ERID-208339

Los Alamos
NATIONAL LABORATORY
EST. 1943
Environmental Programs
P.O. Box 1663, MS M991
Los Alamos, New Mexico 87545
(505) 606-2337/FAX (505) 665-1812

RECEIVED
NOV 2011
NMED Hazardous Waste Bureau

National Nuclear Security Administration
Los Alamos Site Office, MS A316
Environmental Restoration Program
Los Alamos, New Mexico 87544
(505) 667-4255/FAX (505) 606-2132

Date: NOV 29 2011
Refer To: EP2011-0405

John Kieling, Acting Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

Subject: Inspection and Maintenance of Erosion Controls in the Drainages to the 90s Line Pond at Technical Area 16

Dear Mr. Kieling:

This letter documents the annual inspection and maintenance of erosion controls associated with the drainages entering the 90s Line Pond at Technical Area 16 (TA-16) at Los Alamos National Laboratory (the Laboratory). This letter is submitted annually pursuant to the New Mexico Environment Department's (NMED's) "Approval with Modifications [for the] Supplemental Investigation Work Plan for Consolidated Units 16-007(a)-99 and 16-008(a)-99 at Technical Area 16" dated December 31, 2008.

Four solid waste management units (SWMUs) within Consolidated Unit 16-008(a)-99 were evaluated for inclusion in the Laboratory's National Pollutant Discharge Elimination System (NPDES) Stormwater Individual Permit (NPDES Permit No. NM0030759) and were determined to have no potential to discharge to waters of the United States. However, stormwater from these sites drains to the 90s Line Pond. Best management practices were installed in the two major drainages to the 90s Line Pond on June 8, 2008. They consisted of juniper bales designed to block sediment transport down the drainages into the pond. Wattles were installed in 2009 and 2010 and continue to control sediment transport from a bare slope draining to the 90s Line Pond (Figure 1).

An annual inspection of the erosion controls, conducted in November 2011, revealed that two of the four juniper bale check dams had been damaged from large storm events in the summer of 2011. The check dams were repaired and are in good operating condition (Figures 2–5). No other erosion control maintenance activities were required during the previous 12 months.

If you have any questions, please contact John McCann at (505) 665-1091 (jmccann@lanl.gov) or Woody Woodworth at (505) 665-5820 (lance.woodworth@nnsa.doe.gov).

Sincerely,

B. G. Schappell for MJG

Michael J. Graham, Associate Director
Environmental Programs
Los Alamos National Laboratory

Sincerely,

George J. Rael, Assistant Manager
Environmental Projects Office
Los Alamos Site Office

MG/GR/DM/JM:sm

Cy: (w/enc.)
Neil Weber, San Ildefonso Pueblo
Woody Woodworth, DOE-LASO, MS A316
John McCann, EP-CAP, MS M992
RPF, MS M707 (electronic copy)
Public Reading Room, MS M992 (hard copy)

Cy: (Letter and CD and/or DVD)
Laurie King, EPA Region 6, Dallas, TX
Steve Yanicak, NMED-DOE-OB, MS M894
Sam Loftin, ENV-RCRA, MS K490 (w/ MS Word files on CD)
Don Hickmott, EES-DO, MS D462
William Alexander, EP-BPS, MS M992

Cy: (w/o enc.)
Tom Skibitski, NMED-OB, Santa Fe, NM (date-stamped letter emailed)
Annette Russell, DOE-LASO (date-stamped letter emailed)
Dave McInroy, EP-CAP, MS M992 (date-stamped letter emailed)
Michael J. Graham, ADEP, MS M991 (date-stamped letter emailed)