LA-UR-17-25437

Approved for public release; distribution is unlimited.

Title: Experimental and Numerical Investigation of Temperature and Flow
Distribution Inside a Glovebox Enclosure for a High Accuracy
Coordinate Measurement Machine

Author(s): Spernjak, Dusan
Morgan, Robert Vaughn
Ney, Stephen Andrew
Mejia-Alvarez, Ricardo
Bernardin, John David

Intended for: ASME 2017 Summer Heat Transfer Conference, 2017-07-09/2017-07-12
(Bellevue, Washington, United States)

Issued: 2017-08-09 (rev.1)

Disclaimer:

Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the Los Alamos National Security, LLC for the National Nuclear Security Administration of the U.S. Department of Energy under contract DE-AC52-06NA25396. By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

Experimental and Numerical Investigation of Temperature and Flow Distribution Inside a Glovebox Enclosure for a High Accuracy Coordinate Measurement Machine

AET-1 Thermal and Mechanical Engineering

D. Spernjak, R. Morgan, R. Mejia-Alvarez, J. Bernardin and S. Ney

7/12/2017

UNCLASSIFIED

Coordinate Measuring Machines

- Leitz Infinity Coordinate measuring machine
 - ~1m x ~1m table
 - 3D part measurement
 - Automatable operation Coordinate measuring machines (CMMs)
- Thermal expansion/contraction causes the largest sources of error
 - Parts and CMM
 - Stringent temperature requirements
 - Ensures measurement resolution and repeatability
- Temporal Requirements:
0.3 °C/hr, 0.4°C/day
- Spatial Requirement: 0.1 °C/meter

Leitz Infinity CMM

<http://www.hexagonmi.com>

UNCLASSIFIED

Glove Boxes

- Object or an assembly needs to be separated from the operator and the environment
- Operator safety
- Contamination prevention
- Safety considerations require low airflow
- Pressure negativity relative to the environment
- Internal heat generation
 - Motors and electronics that produce heat
 - Facility with less accurate temperature control than the requirements
 - Closed loop HVAC system in glovebox

<https://www.terrauniversal.com/>

UNCLASSIFIED

Goals

- Verify if spatial and temporal requirements are met
 - Measurements
 - Temperatures: Thermocouples, Thermography
 - Discrete Flow Velocity: Hotwire, Pitot-static Tube
 - Analysis
 - Gradients, distributions, boundary conditions
- Propose modifications to ensure requirements are met

Type T TC

<http://www.omega.com/>

UNCLASSIFIED

Apparatus

- Leitz Infinity CMM, high precision coordinate measurement machine
- Negative Pressure glovebox provides isolation between the operator and the process
- 40 Type T Thermocouples, individually calibrated
 - Stationary thermocouples shown
 - Two external thermocouples

Fixed TC Locations

UNCLASSIFIED

Apparatus

- Volume of Interest (VOI): above granite table to 0.7m
- 3X Thermocouples mounted to 80-20 Al posts travel with table
- Grids of thermocouples used to approximately measure gradients
- Different configurations allow temperature measurements during repeatability tests.

Standard Beam

UNCLASSIFIED

Ambient Temperature

- Somewhat repeatable day-night variation
- Total range ~6°C
- Noticeable difference between upper and lower GB sections
- Internal follows ambient with HVAC off
- HVAC system dramatically improves temperature stability.

Channel Number	Average Temperature (°C)	Standard deviation (°C)
Channel 109	22.61	0.64
Channel 110	22.20	0.64

UNCLASSIFIED

Temporal Stability

- Min/max envelope shows a total variation of less than 0.6°C over 1 day.
- Looking at $\pm 2\sigma$ deviation shows ΔT under 0.2°C for 1hr in VOI
- Requirement is 0.3°C/hr

ΔT Envelope

Standard Deviations

UNCLASSIFIED

CMM Repeatability

- 36 Repeated beam measurements over 5 days
- Large ambient temperature spikes cause local heating
- Repeatability is poor during these periods
- Repeatability is better during more stable temperature periods
- What reduces the effectiveness of the HVAC?

Standard Beam

UNCLASSIFIED

Spatial Gradients

- Gradients calculated above granite table
- Linear fits to data used to smooth local spikes
- Table position affects gradients
- Requirement is 0.1C/m, and is generally not met
- Indicates that fluid temperatures are spatially non-uniform
- Design improvements needed!

Thermal Gradient TC Grid

Flow Distribution Near Table

- Comparison of simulation and hot-wire measurements near grating.
- Hot-wire only measures magnitude
- Good agreement observed in trends.
- Low flow observed around sides of table, with stronger flow toward rear
- Existing diffuser does not produce a uniform flow distribution

Flow Measurements

UNCLASSIFIED

Numerical Methods

- ANSYS CFX
 - thermal and flow characteristics
 - Steady-state, single-phase gas mixture
- Boundary conditions
 - HVAC flow rates (mass flow)
 - heat loads due to CMM motors
 - external heat sources
- Simplifications
 - screw heads, screw holes, cables, cable trays, brackets, and small components were eliminated
 - Grating around the granite table was omitted
- Mesh
 - Tetrahedral mesh adapts to complex geometries while avoiding shape distortion
 - Max edge length 0.1 m
 - Refined in several regions

UNCLASSIFIED

Simulations

- Five HVAC flow rates simulated:
 - 400 scfm, 700 scfm, 1000 scfm, 1200 scfm, and 1500 scfm
- Three heat-loads
 - Motors: 20W, 50W
 - Walls: Some Warm +5°C, All Warm +5°C
 - Inflow Temp: 20°C or 25°C

- Each case (except for one), had an inflow temperature of 25°C

Heat Sources and Inlets/outlets

Motors and diffuser

UNCLASSIFIED

Simulation Results

- Low flow rates are inadequate to maintain temperature uniformity.
- Heat from warm wall sections tends to be redistributed
- Glovebox temperature nears that of the warm wall sections.

GB Temperature

UNCLASSIFIED

Flow Redistribution

- Incoming flow forms a jet in the diffuser
- This jet entrains flow from outside of the diffuser
- Flow is then sent toward the back of the glovebox
- If entrained flow is at a different temperature than incoming flow large gradients occur
- Motors alone have very little effect on the temperature gradients at higher flow rates.

Flow Distributions

UNCLASSIFIED

Proposed Solutions

- Improved diffuser designs can improve the distribution of flow in the GB.
- To reduce costs, vents can be closed in the existing diffuser to eliminate entrainment.
- Smaller openings focus flow into regions needing more cooling.
- Better temperature uniformity is observed in simulations.
- Uniformity can be further improved by redesigned the diffuser to feature flow straightening and conditioning.

Diffuser Modifications

UNCLASSIFIED

Conclusions

- Experiments
 - The ambient temperature remained in 19.7 °C to 25.3 °C (67.5 °F to 77.5 °F)
 - 0.3 °C/hr requirement is met over a 2 day period
 - 0.4 °C/day requirement is generally not satisfied but is very close
 - Spatial gradient of 0.1 °C/m is not generally satisfied
 - CMM repeatability was not satisfactory during large deviations
- Simulations
 - Minimal temperature variation with only motor heat loads
 - Lower sidewall sections dramatically affected GB temperatures
 - Vent covering in the existing diffuser significantly mitigates the adverse effects of warm walls
 - Complete redesign could further improve uniformity

UNCLASSIFIED

Questions?

UNCLASSIFIED

Supplemental Material

UNCLASSIFIED

References

- [1] Leitz Division, Hexagon Metrology, "Acceptance and re-verification tests for coordinate measuring machines. A brief introduction.," Hexagon Metrology GmbH, Wetzlar, Germany, 2010.
- [2] Leitz Division, Hexagon Metrology, "Leitz Specification," Hexagon Metrology GmbH, Wetzlar, Germany, 2014.
- [3] M. M. Dowling, P. M. Griffin, K.-L. Tsui and C. Zhou, "Statistical Issues in Geometric Feature Inspection," Technometrics, vol. 39, no. 1, pp. 3-17, 1997.
- [4] S. D. Phillips, B. Borchardt, T. Doiron and J. Henry, "Properties of free-standing ball," Precision Engineering Division, National Institute of Standards and Technology, vol. 15, no. 1, pp. 16-24, 1993.
- [5] B. Quivey, "HVAC Systems in Nonreactor Nuclear Facilities, UCRL-AR-133352-Rev1," Lawrence Livermore National Laboratory, Livermore, 1999.
- [6] V. J. Corcoran, T. Aslett, A. Aytekin and A. Huyton, "A New Containment Box For Tritium Operations," Fusion Technology, pp. 1321-1326, 1995.
- [7] International Organization for Standardization, "Cleanrooms and associated environments - Part 7: Separative devices (clean air hoods, gloveboxes, isolators and mini-environments). ISO-14644-7.," International Organization for Standardization, Geneva, Switzerland, 2004.
- [8] ANSYS CFX Solver Theory Guide, Release 15.0, Canonsburg, Pennsylvania: ANSYS, Inc., 2013.
- [9] ANSYS CFX Solver Modeling Guide, Release 15.0, Canonsburg, Pennsylvania: ANSYS, Inc., 2013.

UNCLASSIFIED