



Received	Entered	Distributed
4/18/2011	4/19/2011	4/18/2011
EPCCAT		PCM-DO

Prime Contract Management Office
P.O. Box 1663, MS M722
Los Alamos, New Mexico 87545
505-667-1101/Fax 505-665-5552

Date: April 18, 2011
Refer To: PCM-11-081

Contracting Officer
George J. Rael, Contracting Officer Representative
Los Alamos Site Office
National Nuclear Security Administration
37437 West Jemez Road
Los Alamos, NM 87544

Subject: Contract DE-AC52-06NA25396, Response to Issues Relating to Soil and Groundwater Remediation Response

- Reference:**
- 1) Letter from George Rael and Caroline Crooks to Rueben Rafferty and Michael Graham, *Issues Relating to Soil and Groundwater Remediation*, dated August 17, 2010, EPO-7HS-275106.
 - 2) Letter from Rueben Rafferty to George Rael and Caroline Crooks, *Issues Relating to Soil and Groundwater Remediation Response*, dated September 28, 2010, PCM-10-249

Dear Contracting Officer and Mr. Rael:

The attachment to this letter is a response to Item 4 of Reference 2. Item 4 reads as follows:

In November 2007, a LANL response to 2007 NAS Report titled "Plans and Practices for Groundwater Protection at the Los Alamos National Laboratory" was issued. The response to NAS recommendations referred to many ongoing and pending activities. LANS is directed to provide an update to the 2007 LANL response to LASO no later than April 30, 2011.

The attachment provides updated responses to each of the 17 recommendations made by the National Academy of Sciences. If you have any questions, please contact Craig Douglass at (505) 665-2469 (craigd@lanl.gov).

Sincerely,

A handwritten signature in black ink, appearing to read "Steve Shook".

Steve Shook
Prime Contract Chief

SS/ts

Attachment: Updated Summary of Los Alamos National Laboratory Actions to Recommendations by the 2007 National Academy of Sciences Report "Plans and Practices for Groundwater Protection at the Los Alamos National Laboratory"

Cy: P. Cote, LASO-SUP, A316
C. Douglass, ADEP, M992
M. Graham, ADEP, M991
J. Oliver, LASO-BA, A316
IRM-RMMSO
RPF, M707
PCM, M722
ADEP File