FIGURES



Figure 1 Juniper bale check dam in channel draining to 90s Line Pond, November 2012



Figure 2 Juniper bale check dam in channel draining to 90s Line Pond, November 2012



Figure 3 Juniper bale check dam in channel draining to 90s Line Pond, November 2012



Figure 4 Seed, mulch, and straw wattles on bare slope draining to 90s Line Pond, November 2012