

Sandia wetland run-on control and grade-control structure looking southeast, December 5, 2013



Sheet-pile wall 1 looking upstream, September 23, 2014



Sheet-pile wall 2 looking upstream, September 23, 2014



Cascade structure looking downstream, September 23, 2014



Erosion controls at south-entering swale looking southeast with established vegetation and no signs of erosion or rilling taking place, September 23, 2014



Earthen berm erosion control below south-entering swale looking south with established vegetation and no signs of erosion or rilling taking place, September 23, 2014