

LA-UR-19-23550

Approved for public release; distribution is unlimited.

Stormwater Pollution Prevention Plan, TA-03-38 Carpenter's Shop, Los Alamos National Laboratory, Revision 4: LANS Archived 2019 Title:

Author(s): Burgin, Jillian Elizabeth

Intended for: **Environmental Regulatory Document**

Issued: 2019-04-19



STORMWATER POLLUTION PREVENTION PLAN

TA-03-38 Carpenter's Shop

Los Alamos National Laboratory

A requirement of the NPDES MULTI-SECTOR GENERAL PERMIT #NMR053915 (LANS)

for Storm Water Discharges Associated with Industrial Activities

Prepared by:
Los Alamos National Laboratory
Environmental Protection & Compliance Programs
EPC-CP (Water Quality & Storm Water)
PO Box 1663 MS K490
Los Alamos, New Mexico 87545

Revision 4: LANS Archived 2019

TA-03-38 Carpenter's Shop STORMWATER POLLUTION PREVENTION PLAN TABLE OF CONTENTS

TABLE PREFA	E OF CONTENTS ACE	ii iv
SECTION	ON 1: FACILITY DESCRIPTION AND CONTACT INFORMATION	4
1.1	Facility Description and Contact Information	
1.2	Stormwater Pollution Prevention Teams	
1.3	Site Description/Industrial Activities	
1.4	General Location Map	
1.5	Site Map	
1.6	Outfalls	
	ON 2: POTENTIAL POLLUTANT SOURCES	
2.1	Potential Pollutants Associated with Industrial Activity	
2.2	Spills and Leaks	
2.3	Non-Stormwater Discharges Documentation	
2.4	Salt Storage	
2.5	Sampling Data Summary	
	ON 3: STORMWATER CONTROL MEASURES	
3.1	Minimize Exposure	
3.2	Good Housekeeping	
3.3	Maintenance	
3.4	Spill Prevention and Response	
3.5	Erosion and Sediment Controls	
3.6	Management of Runoff	10
3.7	Salt Storage Piles or Piles Containing Salt	10
3.8	Dust Generation and Vehicle Tracking of Industrial Materials	10
3.9	MSGP Sector-Specific Non-Numeric Effluent Limits	11
3.10	Numeric Effluent Limitations Based on Effluent Limitations Guidelines	11
3.11	Water Quality Based Effluent Limitations and Water Quality Standards	11
4.1	Good Housekeeping	12
4.2	Maintenance	12
4.3	Spill Prevention and Response Procedures	12
4.4	Erosion and Sediment Control	12
4.5	Employee Training	12
4.6	Stormwater Monitoring	12
4.6.1	1 Monitoring Schedule	13
4.6.2	2 Substantially Identical Outfalls	14
4.6.3	3 Monitoring Requirements	14
4.6.4	4 Monitoring Results	15
4.6.5	5 Recordkeeping	15

SECTION 5	INSPECTIONS AND CORRECTIVE ACTIONS	17			
5.1 Ro	utine Facility Inspection Procedures	17			
	Quarterly Visual Inspection Procedures				
5.3 Co	Corrective Actions Process				
5.4 Co	nditions Requiring Review to Determine if Modifications Are Necessary	19			
	DOCUMENTATION TO SUPPORT ELIGIBILITY CONSIDERATIONS UNDER OTHER				
FEDERAL L	AWS	20			
6.1 Do	cumentation Regarding Endangered Species	20			
6.2 Do	cumentation Regarding Historic Properties	20			
6.3 Do	cumentation Regarding NEPA Review	21			
SECTION 7	SWPPP CERTIFICATION	22			
SECTION 8	SWPPP MODIFICATIONS	23			
APPENDIX	A: Stormwater Pollution Prevention Team Members APPENDIX				
	nter Pollution Prevention Team Meeting Notes				
,	And other documentation relative to the SWPPP				
APPENDIX					
APPENDIX	C: NOT (11/02/18), NOI and LANS Delegation of Authority Letter				
	D: Non Storm Water Discharge Certification				
	E: SWPPP Amendment Log				
APPENDIX	F: Facility Inspections: Monthly Routine Inspection Form				
	Quarterly Visual Assessment Form				
	Completed Inspection Reports				
APPENDIX	G: Spill Reports				
APPENDIX	· (- /				
APPENDIX	· · · · · · · · · · · · · · · · · · ·	,			
APPENDIX APPENDIX		ıres)			

APPENDIX L: Procedures Referenced in the SWPPP

TA-03-38 Carpenter's Shop STORMWATER POLLUTION PREVENTION PLAN TABLE OF CONTENTS

PREFACE

This Storm Water Pollution Prevention Plan (SWPPP) was developed in accordance with the provisions of the Clean Water Act (33 U.S.C. §§1251 et seq., as amended), and the Multi-Sector General Permit for Storm Water Discharges Associated with Industrial Activity (U.S. EPA, June 2015) issued by the U.S. Environmental Protection Agency (EPA) for the National Pollutant Discharge Elimination System (NPDES) and using the industry specific permit requirements for Sector A–Timber Products, Subsector A4 (Wood Products Facilities not elsewhere classified) as a guide. The applicable stormwater discharge permit is EPA General Permit Registration # NMR053915 (Los Alamos National Security (LANS) (U.S. EPA, June 2015). Contents of the June 4, 2015 Multi-sector General Permit can be viewed at:

https://www.epa.gov/sites/production/files/2015-10/documents/msgp2015 finalpermit.pdf

This SWPPP applies to discharges of stormwater from the operational areas of the TA-03-38 Carpenter's Shop at Los Alamos National Laboratory. Los Alamos National Laboratory (also referred to as LANL or the "Laboratory") is owned by the Department of Energy (DOE), and is operated by Los Alamos National Security, LLC (LANS). Throughout this document, the term "facility" refers to the TA-03-38 Carpenter's Shop and associated areas. The current permit expires at midnight on June 4, 2020.

As the LANS contract ended for LANL MSGP facilities on October 31, 2018, a Notice of Termination (NOT) for permit coverage was filed and is effective as of 11/02/18. A copy of the NOT acknowledgment is located in Appendix C of this SWPPP.

This is the archived and final revision of the SWPPP for LANS.

SECTION 1: FACILITY DESCRIPTION AND CONTACT INFORMATION

1.1 Facility Description and Contact Information

The Carpenter's Shop (CS) is located in the southwestern most portion of Building 0038, which is located in Technical Area 03 (TA-03) at the southeast corner of West Jemez and Pajarito Roads (east of Bikini Atoll Road) within Los Alamos National Laboratory, in Los Alamos County, New Mexico.

Facility Operator: Los Alamos National Security, LLC

PO Box 1663 MS K490 Los Alamos, NM 87545 Phone: 505-667-0666

Facility Contacts: Holly Wheeler, MSGP Compliance Project Lead, EPC-CP

Office: 505-667-1312 Email: hbenson@lanl.gov

Jillian E. Burgin, MSGP SWPPP Inspector,

Deployed Environmental Professional (DEP), CISEC

Office: 505-665-1893 or Cell: 505-309-1914

Email: jburgin@lanl.gov

Other applicable facility data and contact information is provided in the facility NOI, which is located in Appendix C of this SWPPP. The NOI provides the coordinates of the facility and also a link to the online location where this SWPPP can be viewed.

1.2 Stormwater Pollution Prevention Teams

The TA-03-38 CS is part of LANL's Utilities and Infrastructure (UI) Facilities Operations Directorate (FOD) with day-to-day management provided by the Logistics Division Central Shops (LOG-CS); which has established a Stormwater Pollution Prevention Team (PPT) whose members are responsible for assisting the facility manager in developing and revising the facility's SWPPP as well as maintaining control measures and taking corrective actions when required. All PPT members will have access to either a hard copy or an electronic version of this SWPPP. A list of PPT members along with duties and contact information is provided in Appendix A of this SWPPP.

Designation of Pollution Prevention Teams

The Stormwater PPT for the TA-03-38 CS consists of operations and management personnel from the facility, a representative from EPC-CP, and a Deployed Environmental Professional (DEP). The EPC-CP representative is responsible for Laboratory compliance under the National Pollutant Discharge Elimination System (NPDES) permit regulations. The team members are selected on the basis of their familiarity with the activities at the facility and the potential impacts of those activities on stormwater runoff.

The specific duties of individual team members of the PPT are listed below and in Appendix A.

 Pollution Prevention Team Leader: The Pollution Prevention Team Leader is identified in Appendix A of this SWPPP. The Team Leader or designated representative will assist EPC-CP and/or the DEP in performing routine inspections as described in Section 5.2 of this SWPPP. The Team Leader or designated representative will also ensure that the appropriate facility and other LANS personnel receive the training as specified in Section 3.8 of this SWPPP.

- Team Members: Other members of the team are responsible for the implementation of this SWPPP and the required periodic inspections, as described in Section 5 of this SWPPP. In the event of a spill or release, a team member will ensure that prompt cleanup occurs and will incorporate documentation of the spill and cleanup process into the Spill Tracking Table located in Appendix G of this SWPPP. Team members will also be selected to assist/represent the Team Leader in performing routine and visual site inspections.
- EPC-CP Project Lead: Supports the facility and provides guidance associated with implementation of
 the compliance requirements identified in the 2015 MSGP. The EPC-CP Project Leader also acts as
 the institutional point of contact for all interactions with the regulatory authority (EPA) and supervises
 personnel that implement monitoring requirements for the facility.
- DEP: Responsible for SWPPP updates and conducting routine facility inspections and entering corrective actions into the Corrective Action Report (CARs) Database. The DEP is also responsible for tracking and updating the status of corrective actions that cannot be implemented immediately.
- All Members: All PPT members are responsible for being familiar with and implementing this SWPPP and for compliance with the 2015 MSGP.

1.3 Site Description/Industrial Activities

The industrial activities at this site may be classified under <u>Sector A – Timber Products</u>, <u>Subsector A4 – Wood Products Facilities not elsewhere classified</u>. The primary operation of the TA-03-38 CS is to cut and construct wood and plywood materials for a variety of uses around the Laboratory. All wood cutting and fabrication is performed inside the shop which is located in Room 101 of the building.

Outdoor activities at the facility consist of:

- Sternvent Cyclone (wood dust/shaving collection unit) with roll-off bin for wood shaving disposal.
- Material storage racks (fabricated with covers) for wood and finished metals used for carpentry projects.
- Loading dock for fabricated wood, metal materials and associated products.
- Outdoor storage shed (Building 03-2524) for lumber and scaffolding storage.
- Wood for reuse/recycle roll-off bin with cover.

The interior carpenter shop (TA-03-38-101) consists of administrative offices and work areas with table saws, chop saws and wood sanders for cutting and constructing wood products for a variety of uses (primarily repair and installation jobs) at the laboratory. The saws and sanders connect to the outdoor cyclone unit via ducting that suctions wood dust and shavings to the unit. A loading dock is located on the west side of the shop and is used for loading/unloading wood and shop materials into work trucks. Form oil is stored inside a flammable cabinet located on the west dock and is not exposed to stormwater. There are no satellite accumulation areas for hazardous or RCRA waste inside or outside of the building. Roofing chemical products are stored inside in Room 101D, which is adjacent to the carpenter's shop.

Industrial activities and major structures at the facility are shown on the Site Map in Appendix B, Figure B-3.

1.4 General Location Map

The general location map for the facility can be found as Figure B-1 in Appendix B. Figure B-2 provides locations of all receiving waters associated with stormwater discharges from the facility.

1.5 Site Map

A site map is provided in Figure B-3, which illustrates the facility's activities: including property boundaries, structures, impervious surfaces, operational areas as well as information on drainage patterns, stormwater and erosion control structures, potential pollutant sources, and nearby receiving streams.

As required by the 2015 MSGP, the following information specific to the facility is shown either on the site map or with additional information provided in this SWPPP.

- Site Boundaries and Acreage. The site covers approximately 1/3 of an acre (including shop and outdoor yard)
- **Significant Structures and Impervious Surfaces.** The site is 100% impervious, primarily structures and paved lots.
- Direction of Stormwater Flow and Site Drainage. Direction of flow is indicated with arrows.
- Locations of Structural Stormwater Control Measures.
- Locations of all Receiving Waters. In the immediate vicinity of the facility, indicating if any of the waters are Impaired and, if so, whether the waters have TMDLs established for them (see paragraph below this list).
- Locations of all Stormwater Conveyances. This includes all ditches, pipes, and swales.
- Locations of Potential Pollutant Sources.
- Locations of Significant Spills or Leaks.
- Locations of all Stormwater Monitoring Points.
- Locations of Stormwater Inlets and Outfalls. Of which each will require a unique identification code for each outfall (e.g., Outfall #073, etc), indicating if you are treating one or more outfalls as "substantially identical" and an approximate outline of the areas draining to each outfall.
- This facility is not associated with a municipal separate storm sewer system (MS4)
- Areas of designated critical habitat for endangered or threatened species. There are none in the direct vicinity of the facility. An endangered species habitat map (for LANL property) is provided in Appendix B-4.
- There are no non-stormwater discharges at the facility (see certification in Appendix D)
- Locations of the following activities where such activities are exposed to precipitation:
 - o fueling stations (none at this facility)
 - vehicle and equipment maintenance and/or cleaning areas (none at this facility);
 - loading/unloading areas;
 - o locations used for the treatment, storage, or disposal of wastes;
 - liquid storage tanks (none at this facility);
 - processing and storage areas;
 - immediate access roads and rail lines used or traveled by carriers of raw materials, manufactured products, waste material, or by-products used or created by the facility (none at this facility);
 - transfer areas for substances in bulk (none at this facility);
 - machinery; and
 - locations and sources of run-on to your site: there is some run-on from the northwestern side
 of the lower west parking lot and some from the southwest upper lot area at the southern
 boundary of the site.

1.6 Outfalls

Outfall #073: Consists of a circular grated storm drain located on the northwest side of the storage shed (03-2524) in the west lot. Stormwater flows through the wood and metal storage area from the west to the outfall. The discharge runs south from the facility, through TA-03 and daylights east of Building 261.

Outfall #074: Consists of a circular grated storm drain located in the central area of the west parking lot of TA-03-38 and north of the CS. Run-off from the facility drains north to this outfall. The outfall also receives a significant amount of run-on from the north and west sides of building 38 and sheet flow from the west side of the parking area, which is not associated with stormwater discharges from the CS facility. The discharge runs south from the facility, through TA-03 and daylights east of Building 261.

<u>Sampling Station:</u> Samples are collected at an automated sampling station **MSGP07302** which is adjacent to the Sternvent cyclone and wood shaving roll-off bin. The collection tubes for the sampler are on the north side of the cyclone unit and collect stormwater that naturally ponds in the area.

Substantially Identical Outfalls

Outfalls #073 and #074 have been determined to be substantially identical outfalls (SIOs) based on common potential pollutant sources, drainage areas, activities within the drainage areas and general site topography and characteristics. Automated sample collection is impractical at Outfalls #073 and #074 due to heavy vehicle traffic and equipment storage. Outfall #074 also receives a significant amount of drainage from the north parking lot of Building 38, which is from outside of the CS boundary. Representative samples for the facility will be obtained at the automated sampling station **MSGP07302**.

SECTION 2: POTENTIAL POLLUTANT SOURCES

2.1 Potential Pollutants Associated with Industrial Activity

Most industrial activities at the TA-03-38 CS occur indoors so materials are not exposed to stormwater. Potential stormwater pollutants associated with this facility involve materials stored outdoors: primarily finished or scrap wood materials, wood shavings; metals stored on racks; and associated outdoor activities such as loading/unloading materials at the shop bay and vehicle parking. Controls used for each potential pollutant are described in Section 3 of this SWPPP.

Vehicle parking is limited to areas adjacent to the lower west boundary of Building 38. The loading dock is located on the west side of the shop and is primarily used to transport wood and associated work materials to carpenter vehicles for delivery to jobsites throughout the laboratory. The remainder of the lower west parking lot is used for other government vehicle/craft parking and is not exclusive to the CS. The upper west lot is used for general employee parking for Building 38 and other adjacent laboratory buildings.

Activities in the Area exposed to Stormwater:

- **Sternvent Cyclone/wood shavings roll-off bin:** Potential pollutants include: wood dust and shavings that could leach out of roll-off bin into stormwater.
- Wood for reuse/recycle roll-off bin with cover: Potential pollutants include: wood dust and shavings that could leach out of roll-off bin into stormwater.
- **Loading docks:** Potential pollutants include form oil or chemicals being transported by carpenters or roofing products being transported by the adjacent roofing department.
- Material storage racks: Potential pollutants include: metal (rust) and wood materials (shavings/dust) exposed to precipitation. The racks have been fabricated with covers as of February 2016.
- Vehicle parking: Potential pollutants include: the leakage of fuel, oil, or hydraulic fluids.
- **Trash dumpsters**: Potential pollutants include: trash, debris, plastics, food, which can get blown around the parking lot or carried out of the dumpster by birds or other wildlife.

Solid Waste Management Units (SWMUs)

There are no SWMUs or potential release sites (from legacy waste/operations) in the immediate area.

2.2 Spills and Leaks

Past Spills and Leaks

Spills and leaks for the past 3 years (2014-2017) are summarized below and completed spill reports can be found in Appendix G of the SWPPP. Spills and leaks that occurred prior to 2014 will be documented in previous SWPPP revisions.

Date	Description	Outfall(s) Affected
Nov-Dec 2015	A steam condensate line leak occurred south of the outfall and discharged an estimated ~5,500+ gallons of potable steam condensate water into the storm drain over the course of the leak.	Outfall 074

	A 7 & 15 day discharge report was completed by EPC-CP and sent to NMED. This leak was not attributable to activities associated with the TA-3-38, but did cause a non-stormwater discharge to the site and to the outfall.	
Dec 2014	Approximately 3 gallons of concrete washout water were inadvertently discharged outside of the concrete testing lab at Building TA-3-39. The spilled material was collected out of the storm drain with a shop vac and was prevented from being released to Sandia Canyon. The spilled material was not associated with industrial activities occurring at the TA-3-38 Carpenter's Shop.	Outfall 074

Potential Spills and Leaks

Table 1: Areas of Site Where Potential Spills/Leaks Could Occur:

LOCATION	OUTFALLS (see site map)
Loading Dock	074
Stervent Cyclone (with covered wood shaving roll-off bin)	074
Wood reuse/recycle roll-off bin (with cover)	074
Parking Lot	073 & 074
Outdoor Storage Areas	073

In the event of any future spill or leak at any of the facility areas, a spill report, documenting the occurrence and the nature of the spill or leak, will be completed. The spill report will be filed promptly (in Appendix G) upon completion and documentation of the spill clean-up.

The probability of spills or releases at the facility is minimized by the application of good housekeeping procedures and appropriate operational methods. Appropriate response measures for a spill or release of hazardous materials are applied when addressing spills. The specific spill response and cleanup procedures will depend on the nature of the spilled material. Specific response techniques for spills involving all water priority chemicals will be performed as required by section 8.AA.2.2 of the 2015 MSGP. Spill containment and clean-up supplies are maintained within operational areas at the facility.

2.3 Non-Stormwater Discharges Documentation

Except for flows from fire-fighting activities, sources of non-stormwater that are combined with stormwater discharges associated with industrial activity will be identified in the SWPPP.

Non-stormwater discharges are also identified in the "Non-Stormwater Discharge Assessment and Certification" in Appendix D. This form certifies that all stormwater outfalls have been evaluated for the presence of non-stormwater discharges. This form will be updated whenever a change in possible non-stormwater discharge is determined.

There are no NPDES permitted non-stormwater discharges or unpermitted outfalls associated with the facility. Potential sources of non-stormwater discharges at the facility include the testing of fire hydrants in the area. There are no discharges of water from any shop equipment to sewer drains inside the building.

Fire hydrant testing is performed periodically on hydrants servicing laboratory facilities. The closest hydrant to the TA-03-38 CS is located southwest of the facility near a rocked area between Building 38 and adjacent Building 2327 to the south. This hydrant is located outside of the facility boundary and is therefore not considered a source of non-stormwater discharge.

2.4 Salt Storage

No salt storage or piles containing salt are present at the facility. There is no salt storage anticipated for this facility as part of an industrial activity.

2.5 Sampling Data Summary

Sampling of stormwater runoff from the facility will be performed by the EPC-CP, Water Quality and Stormwater Group. Samples will be collected at an automated monitoring station **MSGP07302** located adjacent to the Sternvent cyclone unit. All sampling requirements for the facility are listed in Section 4.6.3 of the SWPPP.

This facility is new to MSGP permit coverage for 2015 and has not been monitored under previous permits. Results from sampling data & Monthly Discharge Monitoring Reports (MDMRs) for the current permit term (MSGP 2015) will be kept on file in Appendix H of this SWPPP.

A sampling data summary of the current permit term is also provided below:

2017

Benchmark Monitoring:

Outfall 073 did not exceeded benchmark parameters.

Impaired Waters Monitoring:

Outfall 073: On 7/18/17 the sample exceeded the New Mexico Water Quality criterion for Copper.

Discontinued Monitoring: n/a

2016

Benchmark Monitoring:

Outfall 073: did not exceeded benchmark parameters.

Impaired Waters Monitoring:

Outfall 073: On 5/15/16 the sample exceeded the New Mexico Water Quality criterion for Copper.

Discontinued Monitoring:

Outfall 073: Impaired waters monitoring was discontinued for Thallium.

SECTION 3: STORMWATER CONTROL MEASURES

3.1 Minimize Exposure

Control measures at the facility are designed to minimize the potential for spills, releases, exposure of materials, or any other events that could adversely affect the quality of water and sediment that may be transported out of the area by stormwater runoff.

Proper material management and storage minimize the potential for exposure of precipitation and runoff to potentially hazardous materials. Containers that could be susceptible to spillage or leakage will be plainly labeled (e.g., "Used Oil," "Spent Solvents," etc.). Most operations and storage areas are located within structures, so that the potential for exposure of stormwater to potential pollutants is limited to the loading area and vehicle parking areas. There is no hazardous material storage or satellite accumulation areas for waste storage on site. All major wood cutting and fabrication activities occur inside.

Specific Structural Controls Description:

- Sternvent Cyclone/wood shavings roll-off bin: wood shavings from shop saws and sanding equipment are kept fully enclosed and stored in the cyclone compartments. When the compartments are full they are emptied into the roll-off bin located directly below the cyclone. The roll-off bin is kept covered except when the cyclone compartments are emptied.
- Roll off bin for scrap wood: the roll-off bin is equipped with a rolling cover and is kept covered when not in use. The bin and its contents are removed for disposal once the bin becomes ~3/4 full.
- Storage Shed and Racks for Wood and Metals: wood and metal materials are either kept enclosed in the facility storage shed (Building 03-2524) or on elevated storage racks outside of the facility. The racks were fabricated with covers in February 2016.
- **Spill Control:** craft vehicles are monitored on a regular basis for leaks and checked during monthly routine inspections. If spills or leaks are found, absorbent materials will be used immediately to contain the leak. The spill procedures listed in Section 3.4 of this SWPPP will also be followed.
- **Flammable cabinet:** Form oil is kept enclosed in a flammable storage cabinet located on the west loading dock. The loading dock area is roofed and the flam cabinet is not exposed to stormwater.
- Lids and Side Enclosures for Trash Dumpsters: trash dumpsters (adjacent to the facility) are normally kept closed when not in use and dumped on a regular basis. Dumpsters will be kept in good condition and will be repaired or replaced if needed by Roads & Grounds.
- Metallox Wattle: is installed around the Sternvent cyclone wood shavings roll-off bin to filter out metal residuals in stormwater runoff.

3.2 Good Housekeeping

Good housekeeping practices specifically applicable to the prevention of stormwater contamination include the following measures:

All site areas exposed to precipitation are walked down during monthly inspections to ensure that the grounds are kept in an orderly condition. The entire site will be inspected for floatable debris, garbage, waste and all other potential pollutants. The area around the cyclone and wood shaving roll-off bin will be inspected and swept as needed to keep wood dust and shavings from leaching into stormwater. The loading and vehicle parking areas will be inspected for leaks or spills and leaking vehicles will be taken off-site for

maintenance. The west parking area will be swept monthly (except when not possible during winter months) to reduce sediment accumulation on site. Spill clean-up procedures will be followed as listed in Section 3.4 of this SWPPP. The trash dumpsters will be dumped on a weekly or as-needed basis by Roads and Grounds.

3.3 Maintenance

Control measures at the facility will be kept in effective operating condition. If control measures need to be replaced or repaired, necessary modifications will be made according to the timelines specified in the Corrective Action requirements of Section 5.4 of this SWPPP. Documentation of corrective actions, maintenance and repair of control measures (BMPs) will be kept on file in Appendix J of the SWPPP. Deficient items identified during monthly or other routine facility inspections will be documented on the inspection forms and must be corrected within the same time frame as noted above.

The PPT Leader is responsible for ensuring that any maintenance or repairs associated with a deficiency or opportunity for improvement, including any regular or scheduled maintenance (such as the removal of debris) are promptly and adequately performed. Any necessary changes to operational procedures or structural features must be implemented in a timely manner before the next rain event.

3.4 Spill Prevention and Response

Spill Prevention consists of: Spills, leaks, or releases that are minimized by the application of good housekeeping procedures, best management practices (BMPs), and engineering and administrative controls. Examples of these measures include storing equipment with drip pans, and inspecting regularly for leaks. Containers that could be susceptible to spillage or leakage will be plainly labeled as to contents (e.g., "Used Oil," "Spent Solvents," etc.) to encourage proper handling and facilitate repaid response if spills or leaks from these containers should occur. Spill cleanup materials will be kept on hand inside the CS in Room 101.

In general, the approach to spill cleanup is to secure the spill area and contact the Operations and Maintenance Coordinator (OMC) and/or the Security and Emergency Operations (SEO)/Emergency Management & Response (EM&R) Team. For incidental releases, absorbents are used to pick up free liquids and the contaminated absorbents are properly disposed with the coordination of a Waste Management Coordinator (WMC).

The SEO or Facility Duty Officer shall report all spills or releases. All uncontrollable spills or releases must be reported to the SEO/EM&R Office or Facility Duty Officer by calling 667-6211 or, after hours, at 667-7080. If fire or explosion is present, or if the potential for such exists, the situation must be reported by dialing 911 from a non-cellular phone or by activating a fire pull box. In the event of a spill, the SEO/EM&R Office will determine appropriate cleanup procedures and will notify the individuals or organizations responsible for completing spill reports or fulfilling regulatory reporting requirements.

Spills are reported to EPC-CP for documentation and reporting purposes. The completion of a spill report (form provided in Appendix G-1) is required in the event of a spill. The spill report will be submitted to EPC-CP personnel and handled according to internal spill record keeping procedures. Spills may be "reportable" (requiring external agency notification) depending on the nature of the spilled material and the location of the release. External agency notification may consist of verbal or written notification to the National Response Center, Environmental Protection Agency Region VI, or the New Mexico Environment Department (NMED). The determination for the type of reporting will be made by the SEO/EM&R Office, FOD, and EPC-CP in accordance with Laboratory and DOE policies and federal and state regulatory reporting requirements. Copies of internal spill reports are maintained by the responsible organization. If an un-reportable spill occurs it will be documented in the spill log in Appendix G.

Additional EPC-CP procedures (documents provided in Appendix L) for spill reporting and response include:

ENV-CP-QP-007, Spill Investigations:

http://int.lanl.gov/training/v-courses/41819/41819.pdf; and

• ENV-DO-QP-101.3, Environmental Reporting Requirements for Releases or Events: http://int.lanl.gov/training/adesh/42415/42415.pdf

3.5 Erosion and Sediment Controls

The entire outside surface region associated with the facility is paved with asphalt and concrete; therefore, erosion and sediment transport from the site is unlikely. Areas to the south and southeast of the facility are stabilized with rock. Sweeping of the west lot at the facility will generally be performed monthly (under the annually submitted Facility Service Request) except during winter months when weather conditions do not permit. Regular sweeping reduces sediment accumulation on site and transport of associated pollutants.

3.6 Management of Runoff

The majority of stormwater runoff from outdoor activity areas at the facility is captured by the grated storm drains (Outfalls #073 & #074), which are located in the lower west lot of Building 38 as described in Section 1.6 of this SWPPP.

All onsite and offsite storm drains at the facility connect to a common storm system and common outfall which daylights into a tributary of Sandia Canyon.

A significant amount of run-on to the facility was occurring from the drainage area adjacent to the concrete walkway at the upper southwest boundary of the facility. This area was stabilized with rock, and an asphalt berm was installed along the edge and corner of the upper parking lot in September 2015. The area will continue to be monitored for run-on issues.

See site map in Figure B-3, Appendix B or Outfall information provided in Sections 1.5 and 4.2 of this SWPPP for more detailed information on drainage patterns and control measures associated with this facility.

3.7 Salt Storage Piles or Piles Containing Salt

No salt storage or piles containing salt are present at the facility. There is no salt storage anticipated for this facility as part of an industrial activity.

3.8 Dust Generation and Vehicle Tracking of Industrial Materials

The entire outside surface region associated with the facility, except for small plots of dirt and grass adjacent to the site on the south boundary, is paved with asphalt and concrete. Other sections of adjacent property on the south side of the facility are stabilized with rock. Therefore, dust generation at the facility is minimal and dust suppression is not required. All wood cutting and fabrication activities occur inside. Wood shavings are suctioned away from inside equipment (saws and sanders) by ductwork connected to the cyclone unit. Wood shavings are stored in the cyclone compartments (until full) and then transferred to the wood-shaving roll off bin located directly under the cyclone. The area around the cyclone will be swept on a regular basis to ensure that shavings do not come into contact with stormwater. The wood shaving roll-off bin is taken off-site for disposal and is kept covered to prevent contents from coming into contact with stormwater. The Environmental Technical Advisor (DEP) PPT member will be responsible for assuring that off-site tracking of raw, final or waste materials are enforced. The PPT Leader is responsible for making sure the outdoor ground areas (especially around the wood shaving roll-off bin) are generally free of dust and wood shavings.

3.9 MSGP Sector-Specific Non-Numeric Effluent Limits

Part 8 of the 2015 MSGP identifies sector-specific requirements for <u>Sector A – Timber Products</u>, <u>Subsector A4-Wood Products Facilities not elsewhere classified</u> in addition to the numeric limits outlined in this Section. The facility must comply with requirements associated with the primary industrial activities described in Section 1.3 of this SWPPP and any co-located industrial activities as defined in Appendix A of the 2015 MSGP. The sector specific requirements only apply to those areas of the facility where the sector-specific activities occur. There are no areas at this facility where chemical formulations are sprayed to provide surface protection; and no stormwater discharges associated with this type of activity. There are no areas at this facility where the spray-down of lumber or wood products takes place.

The following Sector-Specific Non-Numeric Effluent Limits are addressed at this facility:

- Goodhousekeeping: See Sections 3.2 and 4.1 of this SWPPP.
- Drainage Area Site Map: See Sections 1.5 and Appendix B of this SWPPP.
- Inventory of Exposed Materials: See section 2.1 and 3.1 of this SWPPP. This facility does
 not use or store chlorophenolic, creosote, or chromium-copper-arsenic formulations for wood
 surface protection/preserving. There are no known areas of contamination associated with
 these chemicals at the facility.
- Description of Stormwater Management Controls: See Section 3 of this SWPPP.
- Additional Inspection Requirements: This facility does not perform wood surface
 protection and preservation activities. However, routine inspections are conducted monthly
 at the site as described in Section 5.1 of this SWPPP.

3.10 Numeric Effluent Limitations Based on Effluent Limitations Guidelines

The TA-03-38 CS is classified under <u>Sector A-Timber Products</u>, <u>Subsector A4-Wood Products Facilities</u> <u>not elsewhere classified</u> and does not meet the industrial category requirements for effluent monitoring as listed in Part 2.1.3 (*Table 2-1 Applicable Effluent Limitations Guidelines*) of the 2015 MSGP. Benchmark monitoring is performed at the facility as specified in Part 8.A.6 (*Table 8.A.1 Subsector A4.*) of the 2015 MSGP and those requirements and parameters are listed in Section 4.6 of this SWPPP.

3.11 Water Quality Based Effluent Limitations and Water Quality Standards

Impaired Receiving Waters/TMDLs

Impaired waters monitoring is performed annually at the facility as listed in Section 4.6.3 of this SWPPP. The TA-03-38 CS discharges to Sandia Canyon. Certain stream reaches within Sandia Canyon have been identified as impaired waters by the NMED Surface Water Quality Bureau (SWQB). According to the 2014-2016 State of NM Clean Water Act 303b/305b Integrated Report and Final List of Assessed Surface Waters, pollutants causing the impairment are listed as: Gross Alpha, adjusted; Aluminum, PCB in water column; Copper, and Thallium, dissolved. Primary potential pollutant sources have been identified as post development erosion/sedimentation and urban runoff (NMED 2014).

TA-03-38 CS operations do not involve the impaired water pollutants of concern. EPA has not yet approved or established TMDLs for Sandia Canvon.

SECTION 4: SCHEDULES AND PROCEDURES

4.1 Good Housekeeping

All site areas exposed to precipitation will be walked down during monthly inspections to ensure that the grounds are kept in an orderly condition. All areas will be inspected for floatable debris, garbage, waste and all other potential pollutants. Trash and debris will be picked up and disposed of in the trash dumpster(s).

The cyclone wood shaving roll-off-bin (and surrounding area) will be inspected monthly. The bin will be removed from the facility and emptied at the Metal Recycling Facility (MRF) once it becomes ~3/4 full.

The outdoor wood and metal storage areas will be inspected monthly to ensure materials are off the ground on storage racks and otherwise stored properly.

The loading dock, storage shed and vehicles/parking areas will be inspected monthly for signs of spills or leaks and cleaned-up immediately if spills/leaks are found.

The trash dumpsters (adjacent to the facility) will be emptied weekly or as-needed by Roads & Grounds personnel.

Although routine inspections by the DEP and/or EPC-CP are conducted monthly, good housekeeping can be required at any time a deficiency is reported by any facility personnel.

The west parking area will generally be swept monthly (except when not possible during winter months) to reduce sediment accumulation on site.

See also Section 3.2 of this SWPPP.

4.2 Maintenance

All control measures must be maintained in accordance with Section 3.3 of this SWPPP and will be repaired within the timelines required for the 2015 MSGP Corrective Actions Process as noted in Section 5.3 of this SWPPP.

See also Section 3.3 of this SWPPP.

4.3 Spill Prevention and Response Procedures

See Section 3.4 & 4.2 of this SWPPP.

4.4 Erosion and Sediment Control

All outfalls and potentially erodible areas at the facility will be inspected monthly to ensure erosion is not occurring on site or to adjacent areas affected by runoff.

See also Section 3.5 of this SWPPP.

4.5 Employee Training

Employee training is essential to effective implementation of the SWPPP. The goals for the training program are to ensure that employees are more capable of preventing spills, responding safely and effectively to an accident when one occurs, and recognizing situations that could lead to stormwater contamination.

Per section 2.1.2.8 of the 2015 MSGP, training relevant to the SWPPP is required for all operational workers at the facility who work in areas where industrial materials or activities are exposed to stormwater (MSGP sites);

managers and supervisors who are responsible for implementing activities necessary to meet the conditions of this permit (e.g., inspectors, maintenance personnel); and all members of the PPT. Training provided and assigned to these personnel cover both the specific control measures used at the facility; along with monitoring, inspection, planning, reporting, and documentation requirements described in this SWPPP. Training is conducted at least annually.

Training activities are documented in accordance with LANL's Training Standards. In cases where training is formalized enough to require specific curricula and reoccurrence, the training activity will be recorded in LANL's official U-TRAIN database. Informal briefings, such as those included in group safety meetings are not typically recorded in U-TRAIN. Sign-in sheets are used to document attendance and will be kept on file in Appendix I of this SWPPP.

The topics in this SWPPP that are covered in the latest version of LANL's training (ENV-CP-QAPP-MSGP, Stormwater Multi-Sector General Permit for Industrial Activities Program) include the following:

- Overview and goals of the SWPPP;
- Spill response and cleanup procedures, good housekeeping, maintenance requirements, and material management practices to prevent stormwater pollution;
- The location of all controls on the site required by this permit and how they are to be maintained;
- The proper procedures to follow with respect to the permit's pollution prevention requirements; and
- When and how to conduct inspections, record applicable findings, and take corrective actions.

Additional training is provided to the PPT members responsible for design, installation, maintenance, and/or repair of controls (including pollution prevention measures), conducting and documenting monitoring and inspections, and taking and documenting corrective actions. Qualified team members are hired and trained as prescribed in ENV-DO-QP-115, Personnel Training. This initial and annual training includes quality assurance requirements, reporting, inspections, logbook use, health and safety, report preparation, and engineering and design criteria. This training is applicable for the following personnel:

- MSGP SWPPP Inspector: Curricula 10697 ENV-RCRA
- MSGP SWPPP Preparer: Curricula 7814 ENV-RCRA
- MSGP Design Engineer: Curricula 51 ENV-RCRA
- MSGP Visual Assessor: Curricula 10698 ENV-RCRA
- Field Worker Training Requirements: Curricula 131

4.6 Stormwater Monitoring

Analytical monitoring comprised of quarterly benchmark and annual impaired waters monitoring will be performed on stormwater discharges from the site. Monitoring events will be from storm events that result in an actual discharge from the site and that follow the preceding measurable storm event by at least 72 hours (3 days). For runoff from snowmelt, the monitoring will be performed at a time when a measurable discharge from the site occurs.

Monitoring will be conducted according to test procedures approved under 40 CFR Part 136. Runoff samples will be collected by taking a minimum of one grab sample from a discharge, collected within the first 30 minutes of a measurable storm event. If it is not possible to collect the sample within the first 30 minutes of a measurable storm event, the sample will be collected as soon as practicable after the first 30 minutes and documentation will be kept with the SWPPP explaining why it was not possible to take samples within the first 30 minutes.

4.6.1 Monitoring Schedule

For this permit term, monitoring will begin October 1, 2015. Benchmark monitoring will be performed on a

quarterly basis at least once in each of the following 4-month intervals:

- October 1 November 30
- April 1 May 31
- June 1 July 31
- August 1 September 30

Impaired waters monitoring will be performed on an annual basis with a sample collected in the period between April 1 and November 30.

LANL is located in a high elevation, semi-arid climate where the majority of rainfall occurs during a period between July and September. Freezing conditions that would prevent runoff from occurring for extended periods may also occur during the winter months. For these conditions if benchmark monitoring cannot be performed on the quarterly schedule above, monitoring events will be distributed during seasons when precipitation occurs, or when snowmelt results in a measurable discharge from the site. If adverse weather conditions prevent the collection of samples according to the relevant monitoring schedule, a substitute sample will be collected during the next qualifying storm event or as soon as practical.

4.6.2 Substantially Identical Outfalls

Monitoring occurs at automated sampling station **MSGP07302** located adjacent to the Sternvent Cyclone. Discharge from the facility is east to Sandia Canyon (impaired waters), which is a tributary of the Rio Grande located approximately 5 miles east of the facility. Outfall #073 is representative of all stormwater associated with the facility including any discharge occurring at #074. Detailed information on the SIOs is provided in section 1.6 of the SWPPP and in Table 2 below.

Table 2: Substantially Identical Outfalls:

Outfall ID	Outfall Location	Activities/Potential Pollutants	Runoff Coefficient	Control Measures
#073	Grated inlet west of Bldg. 38 and northeast of Bldg. 2524 (storage shed).	Residues from wood or metal stock exposed to stormwater, wood dust, fuel/oil/hydraulic fluid leaks from vehicle parking.	>85%	Wood and metal stock is kept off ground on racks or pallets or in the storage shed Bldg. 2524. Vehicles are constantly monitored for leaks.
#074	Grated inlet west of Bldg. 38 and north of CS facility in parking lot.	Residues from wood or metal stock exposed to stormwater, wood dust/shavings, fuel/oil/hydraulic fluid leaks from vehicle parking.	>85%	Scrap wood is kept in a covered roll-off bin, the cyclone roll-off bin is kept covered when not in use. Loading dock is covered. Vehicles are constantly monitored for leaks.

4.6.3 Monitoring Requirements

Benchmark and impaired waters monitoring will be conducted for this facility as required by the 2015 MSGP. A 2015 MSGP Sampling and Analysis Plan for LANL is provided in Appendix H of this SWPPP. The impaired water pollutants to be sampled can change yearly based on the requirements of the MSGP. The Sampling and Analysis plan will be updated each year.

Table 3 lists the current Summary of Monitoring Requirements and LANL's applicable stormwater monitoring procedures (which also include procedures for gathering storm event data). The monitoring values have been modified to reflect New Mexico facility water quality standards and are based on the lowest water quality standards from the *Standards for Interstate and Intrastate Surface Waters* (as approved on June 5, 2013), 20.6.4.900 NMAC; and as set forth in section 9.6.2.1 of the 2015 MSGP.

Table 3: Summary of Monitoring Requirements:

Monitoring Type	Location	Parameters		Numeric Limitations	Schedule
Benchmark Sector A Timber Products Subsector A4 Wood Products Facilities not elsewhere classified (SIC 2449)	MSGP07302	Chemical Oxygen Demand (COD)	120 mg/L	None	None Quarterly
		Total Suspended Solids (TSS)	100 mg/L		
Impaired Waters	MSGP07302	Aluminum	681 ug/L	None	Annual
vvalers	Sandia Canyon	Gross Alpha, adjusted	15 pci/L		
		Copper	6 ug/L		
		Thallium, dissolved	0.47 ug/L		
		Total Aroclor (PCB in Water Column)	0.2 ug/L		

Procedures (see Appendix L for documents):

- ENV-CP-QP-045, *Installing, Setting up, and Operating ISCO Samplers for the MSGP:* http://int.lanl.gov/training/env-courses/55962/env-cp-qp-045.pdf
- EPC-CP-QP-048, Processing MSGP Stormwater Samples: http://int.lanl.gov/training/adesh/56595/56595.pdf
- EPC-CP-QP-047, Inspecting Stormwater Runoff Samplers and Retrieving Samples for the MSGP: http://int.lanl.gov/training/adesh/56594/56594.pdf
- ENV-CP-QAPP-MSGP, Quality Assurance Project Plan for the Stormwater MSGP: http://int.lanl.gov/training/env-courses/43337/env-cp-qapp-msgp.pdf

4.6.4 Monitoring Results

Monitoring will continue quarterly for benchmark parameters and annually for constituents associated with impaired waters until that constituent is no longer detected in stormwater samples.

If the average of four monitoring values for any parameter does not exceed the benchmark, you have fulfilled your monitoring requirements for that parameter for the permit term.

If the average of the four monitoring values for any parameter exceeds the benchmark (or if prior to completion of 4 quarterly samples, an exceedance of the 4 quarter average is mathematically certain); or if the impaired water constituent exceeds the New Mexico Water Quality criterion, the Pollution Prevention Team and EPC-CP personnel will:

- Review the selection, design, installation, and implementation of control measures to determine if modifications are necessary to meet the effluent limits,
- Implement the necessary modifications within the timeframe specified for corrective action, and
- Continue benchmark or annual monitoring of the constituent (as required by Section 6.2 of the 2015 MSGP).

4.6.5 Recordkeeping

For each monitoring event, except snowmelt monitoring, the following information will be recorded and maintained through field data sheets, LANL database systems, and Discharge Monitoring Records:

- The date, exact place, and time of sampling or measurements;
- The date and duration (in hours) of the rainfall event
- · Rainfall total (in inches) for that rainfall event
- Time (in days) since the previous measurable storm event
- The individual(s) who performed the sampling or measurements;
- The date(s) analyses were performed
- The individual(s) who performed the analyses;
- The analytical techniques or methods used; and
- The results of such analyses.

For snowmelt monitoring, all information except rainfall event durations, totals, and time since previous event will be included. Additionally, all records of monitoring information, including all calibration and maintenance records will be maintained for a minimum period of at least three years from the date the permit expires.

SECTION 5: INSPECTIONS AND CORRECTIVE ACTIONS

5.1 Routine Facility Inspection Procedures

Routine inspections at this facility will be conducted and documented monthly and per ENV-RCRA-QP-022, MSGP Stormwater Corrective Actions: http://int.lanl.gov/training/env-courses/54892/env-rcra-qp-022.pdf (document provided in Appendix L).

At least once each calendar year, the routine inspection will be conducted during a period when a stormwater discharge is occurring. The inspection will be performed by a qualified member of the Stormwater PPT (typically the DEP or EPC-CP Technical Lead). EPC-CP will perform at least one routine inspection per year in order to evaluate corrective action status for the Annual Report requirements.

Routine inspections will evaluate the following areas, at a minimum:

- Areas where industrial materials or activities are exposed to stormwater;
- Areas identified in the SWPPP and those that are potential pollutant sources;
- Areas where spills and leaks have occurred in the last three years;
- Discharge points (Outfalls/SIOs); and
- Control measures used to comply with the effluent limits contained in this permit.

Specific areas of the facility to be inspected include (see descriptions in Section 3.7):

- Raw Steel Handling Storage Areas (none on site)
- Metal Fabricating Areas (none on site)
- Storage Areas for Raw Metal
- Metal Working Fluid Storage Areas (none on site)
- Cleaners and Rinse Water (none on site)
- Lubricating Oil and Hydraulic Fluid Operations (none on site)
- Chemical Storage Areas

During routine inspections the following must be examined and looked out for:

- Industrial materials, residue or trash that may have or could come into contact with stormwater;
- Leaks or spills from industrial equipment, drums, tanks and other containers;
- Offsite tracking of industrial waste or materials, or sediment where vehicles enter or exit the site;
- Tracking or blowing of raw, final or waste materials from areas of no exposure to exposed areas: and
- Control measures needing maintenance, repairs or replacement.

The Stormwater PPT member performing the inspection will document the inspection and will note potential stormwater pollution problems that were encountered on the routine facility inspection form. Any required corrective actions identified during the inspection will be addressed in accordance with Section 5.4 *Corrective Actions Process* of this plan. Facility personnel or the DEP may also perform daily, weekly, or other periodic facility surveys in between monthly routine inspections to further ensure compliance with the

SWPPP. The routine inspection form can be found in Appendix F of this SWPPP and meets the requirements listed in the 2015 MSGP (Section 3.1.2.).

5.2 Quarterly Visual Inspection Procedures

Visual inspections are conducted in accordance with EPC-CP-QP-064, MSGP Stormwater Visual Assessments: http://int.lanl.gov/training/adesh/56595/56595.pdf (document provided in Appendix L).

Once each quarter (April 1-May 31, June 1-July 31, August 1-September 30, October 1-November 30) a sample and visual assessment must be collected and performed at each outfall. The visual assessment will be conducted by a qualified member of the Stormwater PPT (DEP, EPC-CP Technical Lead or designee). The visual assessment must be:

- Of a sample in a clean, clear colorless glass or plastic container and examined in a well-lit area;
- On samples collected within the first 30 minutes of an actual discharge from a storm event or as soon as practical thereafter. Or document why it was not possible to collect the sample within the first 30 minutes (i.e. adverse conditions, not enough flow, etc.)
- Conducted at least 72 hours since the last storm event; or document that the 72 hour period is representative of your local storm events during the sampling period.

The visual assessment will inspect for the following water quality characteristics: color, odor, clarity, floating solids, settled solids, suspended solids foam, oil sheen, and other obvious indicators of stormwater pollution.

Exceptions to visual assessments:

- Document rationale if a visual assessment is unable to be collected in a quarter (no precipitation event or adverse conditions, etc.);
- Perform an additional assessment during the next qualifying storm event if unable to perform in a particular quarter; and
- Perform one quarterly assessment during snow melt discharge (taken during a measurable discharge from the site).

For facilities with significantly identical outfalls, quarterly visual assessments may be performed at only one of the outfalls; provided that you perform visual inspections on a rotating basis at each outfall.

The Stormwater PPT member performing the visual assessment will document potential stormwater pollution problems that were observed during the assessment on the Quarterly Visual Assessment form (Appendix F). Any required corrective actions identified during the assessment will be addressed in accordance with Section 5.4 *Corrective Actions Process* of this plan.

5.3 Corrective Actions Process

When any of the flowing conditions occur or are detected during an inspection, monitoring or any other means, this SWPPP (e.g., sources of pollution; spill and leak procedures; non-stormwater discharges; the selection, design, installation and implementation of control measures) will be reviewed and revised (as appropriate) so that the effluent limits of the 2015 MSGP permit are met and pollutant discharges are minimized:

- An unauthorized release or discharge (e.g., spill, leak, or discharge of non-storm water not authorized by this or another NPDES permit to a water of the U.S.) occurs at the facility;
- A discharge violates a numeric effluent limit;
- Control measures are not stringent enough for the discharge to meet applicable water quality standards or non-numeric effluent limits;
- An inspection identifies that a required control measure was never installed, was installed incorrectly or is not being properly operated or maintained; and

Whenever a visual assessment shows evidence of stormwater pollution.

If the event triggering corrective action is associated with an outfall that is identified as an SIO, the review of the need for action must encompass all related SIOs.

<u>Immediate Actions:</u> If a corrective action is required, immediate steps must be reasonably taken to minimize or prevent discharges from occurring (i.e. spill clean-up, scheduling repairs) until a permanent solution (if needed) can be implemented. Immediate action means all reasonable steps must be taken the same work day or no later than the following work day (when it is too late in the day to take corrective action).

<u>Subsequent Actions:</u> If further corrective actions are required (e.g. installing or making operational a new or modified control, completing repairs, ordering BMPs) they must be completed by the next storm event, if possible or within 14 calendar days (from initial discovery). If it is infeasible to complete corrective actions within 14 days, documentation of why it is infeasible must be provided in the SWPPP. This documentation must also include a timeframe and schedule for completion of the work, which must be completed no later than 45 days (from initial discovery). If time needed to make corrective actions will exceed 45 days, EPA must be notified and provided a justification of why actions will exceed the timeframe.

Upon discovery, required corrective actions will be documented by the DEP (or EPC-CP) and entered into the Corrective Action Database (CARs). The action will be kept open in the database until the issue has been resolved. Documentation of CARS/Maintenance and Repairs of Control Measures (BMPs) will be kept in Appendix J of this SWPPP. Where corrective actions result in changes to procedures or controls documented in this SWPPP, modifications to the SWPPP will be made accordingly within 14 days of completing the corrective action(s).

5.4 Conditions Requiring Review to Determine if Modifications Are Necessary

If any of the following conditions occur, a review of the selection, design, installation, and implementation of control measures will be performed to determine if modifications are necessary to meet the effluent limits in this permit:

- Construction or a change in design, operation, or maintenance at the facility significantly changes the nature of pollutants discharged in stormwater from the facility, or significantly increases the quantity of pollutants discharged; or
- The average of 4 quarterly sampling results exceeds an applicable benchmark. If less than 4 benchmark samples have been taken, but the results are such that an exceedance of the 4 quarter average is mathematically certain (i.e., if the sum of quarterly sample results to date is more than 4 times the benchmark level) this is considered a benchmark exceedance, triggering this review; or
- If an impaired water constituent exceeds the NM Water Quality criterion.

If a review identifies any necessary modifications, they will be performed following the corrective action process identified in Section 5.3 above.

SECTION 6: DOCUMENTATION TO SUPPORT ELIGIBILITY CONSIDERATIONS UNDER OTHER FEDERAL LAWS

6.1 Documentation Regarding Endangered Species

The Los Alamos National Laboratory (LANL) Threatened and Endangered Species Habitat Management Plan (HMP) was prepared to provide for the protection of federally listed threatened and endangered species and their habitats at LANL. The HMP was designed to be a comprehensive landscape-scale management plan that balances the current operations and future development needs of LANL with the habitat requirements of threatened and endangered species. It also facilitates DOE compliance with the Endangered Species Act and related federal regulations. The HMP received concurrence from the U.S. Fish and Wildlife Service (USFWS) and was first implemented in 1999. All changes to the HMP, such as adding new species or changing requirements, are assessed in a new consultation with the USFWS before being implemented. The HMP provides guidance by species for different types of activities allowed without further review by the USFWS.

Currently, the only federally-listed species that have habitat or occur at LANL are the Southwestern Willow Flycatcher (Empidonax trailii extimus), Jemez Mountains Salamander (Plethodon neomexicanus), and Mexican Spotted Owl (Strix occidentalis lucida). Suitable habitats for these species, along with a protective buffer area surrounding the habitats, have been designated as Areas of Environmental Interests (AEIs). An AEI consists of a core area that contains important breeding or wintering habitat for a specific species and a buffer area around the core area. The buffer protects the core area from disturbances that would degrade the value of the core area to the species.

The HMP includes eco-risk analyses which account for any industrial facility's stormwater discharges, allowable non-stormwater discharges, and stormwater discharge-related activities. In addition, the Site-wide Environmental Impact Statement (SWEIS) biological assessment (BA) covered the continuation of Laboratory operations and included outfalls.

As determined by earlier evaluations, stormwater discharges, allowable non-stormwater discharges, and stormwater discharge-related activities from LANL MSGP locations are not likely to adversely affect any species that is federally-listed as endangered or threatened under Criterion D Section iii, the ESA, and will not result in the adverse modification or destruction of habitat that is federally-designated as "critical habitat" under the ESA. New activities are evaluated to determine if they will have an impact to any species. If an activity can be completed within the guidelines of the HMP it can go forward as scheduled; however, if the activity can not comply with the guidelines, the HMP requires that a project-specific BA be prepared for the action and go through the consultation process with the USFWS.

The LANL HMP and other applicable critical habitat documentation can be found in Appendix K of this SWPPP.

6.2 Documentation Regarding Historic Properties

In August, 2015 and December 2008, the Cultural Resources Team (using GPS spatial data as well as conducting visual inspections), reviewed the Laboratory industrial sites (see list below) and their associated outfalls and monitoring stations subject to the 2015 Multi-Sector General Permit (Permit #NMR050000) for effects on historic properties. All of these sites were found to be undertakings of no effect and in compliance with Section 106 of the National Historic Preservation Act (i.e., Criterion B).

- TA-3-22 Power and Steam Plant
- TA-3-38 Metals Fabrication Shop
- TA-3-38 Wood Shop
- TA-3-39 and 102 Metal Shop
- TA-3-66 Sigma Complex

- TA-60 Asphalt Batch Plant
- TA-60-1 Heavy Equipment Yard
- TA-60 Material Recycle Facility
- TA-60 Roads and Grounds
- TA-60-2 Warehouse
- TA-54 Area L
- TA-54 Area G
- TA-54 Maintenance Facility West
- TA-54 RANT

6.3 Documentation Regarding NEPA Review

The Final Site-Wide Environmental Impact Statement for the Operation of Los Alamos National Laboratory (DOE/EIS-0380) was issued in May 2008, and a Record of Decision in September 2008. Stormwater issues and associated pollution prevention requirements and activities at LANL are analyzed in Chapters 4 and 5 of the 2008 Site-Wide EIS. These activities are integrated into environmental reviews on a project-specific level through LANL's Integrated Review Tool (IRT), which incorporates both the Excavation Permit (EX-ID) and Permit Requirements Identification (PR-ID) process. Stormwater issues are identified and pollution prevention activities are implemented during the design and construction phases of all LANL projects, and as part of facility operations, including routine maintenance. LANL staff monitors stormwater pollution prevention compliance at the MSGP sites in accordance with Section 4.6 Stormwater Monitoring of this plan. Corrective actions are taken as necessary as described in Section 5.3 Corrective Actions Process of this plan.

SECTION 7: SWPPP CERTIFICATION

STORMWATER POLLUTION PREVENTION PLAN TA-03-38 Carpenter's Shop

Los Alamos National Laboratory

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Digitally signed by Andrew W Erickson
DN: c=US, o=US, Government, ou=Department of Energy,
ou=Los (Alamos National Laboratory, ou=People,
serialNumber=141880, cn=Andrew W Erickson
Date: 2018.01.2616:1958-07'00'

Date: 1/26/2018

Andrew W. Erickson

Facility Operations Director

Utilities and Institutional Facilities

SECTION 8: SWPPP MODIFICATIONS

The SWPPP will be modified by the PPT and reviewed by the EPC-CP Technical Advisor(s) whenever necessary to address any of the triggering conditions for corrective actions listed in Section 5.4 of this SWPPP to ensure that they do not reoccur; or to reflect changes implemented when a review following the triggering conditions listed in Section 5.4 of this SWPPP indicates that changes to control measures are necessary to meet the effluent limits described in this SWPPP. Changes to this SWPPP document must be made in accordance with the corrective action deadlines defined in Section 5.4 and must be signed and dated in accordance with the signatory requirements listed in Appendix B Subsection 11 (Signatory Requirements) of the 2015 MSGP. A record of amendments to the SWPPP will be tracked in the amendment log located in Appendix E of this SWPPP.

APPENDIX A

Stormwater Pollution Prevention Team Members

Stormwater Pollution Prevention Team Members

Staff Names	Individual Responsibilities
Team/Group Leader: Russell Stone, ESH Manager, Utilities and Institutional Facilities (DESHS-UIS)	Responsible for the management of all environmental, safety, health, and quality programs for the buildings and facilities listed within this Plan. This includes performing oversight and periodic walk downs to ensure implementation of the requirements of the MSGP and this SWPPP including overseeing the assigned duties of other PPT members. The Group Leader is responsible for ensuring that problems noted in inspections are corrected. The Group Leader must also ensure funding is established to cover compliance requirements of the MSGP and this SWPPP.
DEPs: Jillian Burgin (primary), Leonard Sandoval (backup), Utilities and Institutional Facilities (DESHS-UIS)	Responsible for the management of all environmental programs and issues for the buildings and facilities listed within this Plan. The DEP is responsible for training, recordkeeping, and SWPPP revision. The DEP will ensure that all PPT, operations site workers (as appropriate), and applicable supervisors receive annual MSGP and SWPPP training. The DEP will ensure that inspection documents and other required MSGP records relative to the SWPPP are managed in accordance with the permit and established document control procedures and that the SWPPP is kept current. The DEP provides technical and regulatory support to facility personnel regarding implementation of the MSGP and this SWPPP. Lastly, the DEP conducts routine inspections and visual assessments as required by the MSGP. Identified corrective actions from routine inspection are entered into the EPC-CP Corrective Action Report (CAR) database. The DEP is responsible for tracking and updating the status of corrective actions that cannot be implemented immediately.
FOD Manager: Lawrence Chavez, Operations Manager Utilities and Institutional Facilities (UI-DO)	Responsible for managing the operation and maintenance of all aspects of the buildings and facilities listed within this Plan. The Operations Manager shall provide review and ensure coordination with core personnel and the PPT, as appropriate, when tenants within the UI FOD propose a new process or a new site or operation that may be subject to the MSGP.
ENV Core: Holly Wheeler, MSGP Environmental Compliance Programs (EPC-CP)	The MSGP Project Lead is responsible for managing and administering the Multi-Sector General Permit Storm Water Program for all industrial facilities within Los Alamos National Laboratory. The MSGP Project Lead advises and provides guidance to facility personnel on NPDES MSGP regulations/requirements. The MSGP Project Lead also acts as the institutional point of contact for all interactions with the regulatory authority (EPA) and supervises personnel implementing storm water monitoring requirements for the facility.
Facility Staff: Donnie W. Parrett Carpenter Shop Superintendent, Logistics-Central Shops (LOG-CS)	Responsible for day-to-day operations at the facility. Assisting DEPs and EPC with inspections; and implementing, installing and maintaining BMPs at the facility for MSGP compliance. Spill reporting; providing documentation as requested by other team members. Coordinating SWPPP training and briefings as requested by DEP/EPC.

APPENDIX A1

SWPPT Meeting Notes and Other Documentation Relative to the SWPPP

Burgin, Jillian E

From: Wheeler, Holly Lynn

ent: Friday, May 13, 2016 5:15 PM

To: Burgin, Jillian E

Cc: Shendo, Marwin Patrick; Dale, Leslie J

Subject: RE: Will be out checking stormwater samplers today. We are on the standing plan of

the day.

We got a new location ID number for that location on 4/29/2016 in EIM. It may have been moved prior to that time, but it became official at that point. For your purposes, it is still identified as outfall 073.

Hope this helps. Just let me know if you have any further questions.

Thanks, Holly

From: Burgin, Jillian E

Sent: Tuesday, May 03, 2016 1:34 PM

To: Wheeler, Holly Lynn; Shendo, Marwin Patrick

Subject: RE: Will be out checking stormwater samplers today. We are on the standing plan of the day.

Holly/Marwin,

What date was the sampler moved at the Carpenter Shop? I need to note the new location in the SWPPP and date.

ihanks!

From: Wheeler, Holly Lynn

Sent: Tuesday, May 03, 2016 9:20 AM **To:** Parrett, Dana; Chavez, Thomas Page

Cc: Burgin, Jillian E

Subject: Will be out checking stormwater samplers today. We are on the standing plan of the day.

Burgin, Jillian E

rom:

owner-es-deployed@maillist.lanl.gov on behalf of Wheeler, Holly Lynn

<hbenson@lanl.gov>

Sent:

Tuesday, January 19, 2016 8:21 AM

To:

es-deployed@lanl.gov

Cc:

DiSalle, Camillo R

Subject:

New MSGP Permit Tracking Number

All,

LANL's new Permit tracking number for inspections, visual assessments, SWPPPs and other reports is NMR053195

Please ensure that all required compliance documentation regarding the 2015 MSGP contain this number.

Thanks,

Holly Wheeler

APPENDIX B

Site Maps

Figure B-1, Regional Location Map
Figure B-2, General Location Map (Includes nearby surface waters and receiving waters)
Figure B-3, Facility Site Map
Figure B-4, Endangered Species Habitat (within LANL) Map







Figure B-2, General Location Map Location of Nearby Surface Waters and Receiving Waters

7/16/2015

TA-03-38 Carpenter's Shop SWPPP Location of Nearby Receiving Waters



http://gis-arcserver-p/DSA_Rev3/default.aspx







Figure B-4, Endangered Species Habitat (within LANL) Map



APPENDIX C NOT, NOI and LANS Delegation of Authority Letter



U.S. ENVIRONMENTAL PROTECTION AGENCY (EPA) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) EPA's NPDES EREPORTING HELP DESK



11/2/2018

Los Alamos National Security LLC ATTN: Enrique R. Torres PO Box 1663 MS K490 Los Alamos, NM 87545

Facility: Los Alamos National Laboratory PO Box 1663 Los Alamos, NM 87545

NPDES ID: NMR053195

Dear Enrique R. Torres:

Thank you for submitting your Notice of Termination (NOT) form, terminating coverage under the EPA's Stormwater Multi-Sector General Permit. The coverage for the facility listed above which began on 09/03/2015, has been terminated effective midnight of 11/02/2018. By submission of this NOT form, you are certifying that you have reviewed the terms and conditions of the Multi-Sector General Permit and have determined that the facility no longer requires coverage.

If you have questions concerning the stormwater program, please contact:

EPA Region 06

Name: Nasim Jahan Phone: (214) 665-7522

Email: jahan.nasim@epa.gov

If you have any questions regarding this letter, please call the EPA NPDES eReporting Help Desk at 1-877-227-8965 (toll free) or send an email to NPDESeReporting@epa.gov.

EPA NPDES eReporting Help Desk Operated by Avanti Corporation 1200 Pennsylvania Ave., NW Mail Code: 4203M Washington, DC 20460 1-877-227-8965





CAP DISTRICT MD 207 ZE 360V 18 PM 41





ZIP 20004 011E12651159

LOS ALAMOS NATIONAL SECURITY LLC ATTN: ENRIQUE R. TORRES PO BOX 1663 MS K490 LOS ALAMOS, NM 87545

> 87545-



Environment Safety & Health PO Box 1663, MS K491 Los Alamos, New Mexico 87545 (505) 667-4218/Fax (505) 665-3811

MAR 2 2 2016 Date:

Symbol: ADESH-16-045 LA-UR: 16-21721

Locates Action No.: N/A

Stormwater Notice Processing Center Mail Code 4203M, ATTN: 2015 MSGP Reports U.S. EPA 1200 Pennsylvania Avenue, NW Washington, DC 20460

To Whom It May Concern:

Transmittal of the National Pollutant Discharge Elimination System (NPDES) Notice Subject:

of Intent (NOI) For Stormwater Discharges Associated with Industrial Activity under

the Multi-Sector General Permit (MSGP) Tracking No. NMR053195

The purpose of this letter is to transmit a complete/correct NOI for stormwater discharges associated with industrial activity under the MSGP for Los Alamos National Laboratory (LANL) (Enclosure 1) on behalf of Los Alamos National Security LLC. LANS operates LANL for the Department of Energy. Per Section G of the attached NOI, three concurrence letters from the United States Department of Interior, Fish and Wildlife Service are provided in Enclosure 2. While submitting a NOI for coverage under the new 2015 MSGP, LANS experienced significant problems with EPA's Net NPDES eReporting tool, which resulted in the initial submission of a NOI with incomplete outfall attribute data and incorrect information. The details of these issues were provided in a letter sent to Mr. Bret Larsen of EPA Region 6 on October 29, 2015 (ENV-DO-15-0309) (Enclosure 3).

The initial NOI was submitted in the Net eReporting tool on 9/02/2015, which resulted in a follow-up email on 9/03/2015 from NeT@epa.gov stating the NOI requesting coverage for Los Alamos National Laboratory under EPA's 2015 MSGP had been certified and submitted to EPA for review, and assigned NPDES ID NMR053195. Please note, this tracking number has been inserted in Section B of Enclosure 1 to prevent confusion or assignment of an additional tracking number. Authorization to discharge under the 2015 MSGP was sent to LANS on 10/03/2015.

Repeated attempts to update the NOI via the "Change NOI" form have resulted in the same system problems without successful submittal of all required information via NeT. As such, an e-mail request for waiver pursuant to Part 7.1 of the 2015 MSGP was sent to Ms. Nasim Jahan on 2/05/2016. On 2/09/2016 Ms. Jahan responded by indicating "LANL can submit their paper copy."

LANL has 14 industrial sites covering eight (8) sectors, with 74 outfalls (26 monitored outfalls and 48 associated substantially identical outfalls) discharging to five (5) assessment units on the Clean Water Act 303(d) list (impaired waters without an EPA-approved or established TMDL pursuant to Part 6.2.4.1 of the 2015 MSGP). In addition, due to extended frozen conditions in the winter and the semi-arid climate, LANS implements an alternate monitoring period of four (4) two-month monitoring quarters for benchmark values as identified below, in accordance with Part 6.1.6 of the 2015 MSGP. This does not coincide with the four (4) three month monitoring quarters for benchmark values currently in the NetDMR.

April 1 through May 31 June 1 through July 31 August 1 through September 30 October 1 through November 30

To facilitate complete and accurate information in the NeT reporting system, LANS has provided an additional table (Enclosure 4) containing sector-specific information per MSGP site within the 36 square mile facility and listed each site's associated outfalls. The premise for providing this information is to determine whether the NeT tool can prepopulate the electronic Discharge Monitoring Report (DMR) form based on this information without causing inaccuracies or rejected data (non-fillable forms due to unresolvable hard errors). In addition, LANS is concerned that incomplete or incorrect NOI information will perpetuate a recurring prohibitive "domino effect" on subsequent electronic DMR filing and "Change NOI" forms.

LANS respectfully requests consideration of waivers for electronic submittal of MSGP DMRs using the NetDMR system until it is determined whether the attached NOI can be submitted by EPA's Subcontractor into the NeT tool. Once this occurs, LANS can determine how information is populating the NetDMR system and whether it will accept applicable data without causing prohibitive hard errors.

Any additional direction or guidance you may have would be appreciated. Please contact Terrill Lemke of Environmental Protection and Compliance, Compliance Programs (EPC-CP) at (505) 665-2397 if you have any questions regarding this NOI.

Sincerely,

Michael T. Brandt, DrPH, CIH

Associate Director

Environment, Safety & Health

Los Alamos National Security, LLC

Los Alamos National Laboratory

MTB:TWL:HLW/lm

Enclosure: 1. Notice of Intent (NOI) For Stormwater Discharges Associated With Industrial Activity Unde the NPDES Multi-Sector General Permit

2. Concurrence letters from United States Department of Interior, Fish and Wildlife Service

- 3. Multi-Sector General Permit (MSGP) Notice of Intent (NOI) Reporting Pursuant to Part B.12.H
- 4. Industrial Sites and Outfalls by Sector

Cy: Nasim Jahan, USEPA/Region 6, Dallas, TX, (E-File) Bruce Yurdin, NMED/SWQB, Santa Fe, NM, (E-File) Jordan Arnswald, NA-LA, (E-File) Craig S. Leasure, PADOPS, (E-File) William Mairson, PADOPS, (E-File) Michael T. Brandt, ADESH, (E-File) Raeanna Sharp-Geiger, ADESH, (E-File) John P. McCann, EPC-DO, (E-File) Terrill W. Lemke, EPC-CP, (E-File) Holly L. Wheeler, EPC-CP, (E-File) Timothy A. Dolan, LC-ESH, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File) epc-correspondence@lanl.gov

ENCLOSURE 1

Notice of Intent (NOI) For Stormwater Discharges Associated With Industrial Activity Under the NPDES Multi-Sector General Permit

ADESH-16-045

LA-UR-16-21721

Date:	MAR 2 2 2016

NPDES FORM 3510-6



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY WASHINGTON, DC 20460

NOTICE OF INTENT (NOI) FOR STORMWATER DISCHARGES ASSOCIATED WITH INDUSTRIAL ACTIVITY UNDER THE NPDES MULTI-SECTOR GENERAL PERMIT

Form Approved. OMB No. 2040-0004

Submission of this Notice of Intent (NOI) constitutes notice that the operator identified in Section C of this form requests authorization to discharge pursuant to the NPDES Stormwater Multi-Sector General Permit (MSGP) permit number identified in Section B of this form. Submission of this NOI also constitutes notice that the operator identified in Section C of this form meets the eligibility conditions of Part 1.1 of the MSGP for the facility identified in Section D of this form. To obtain authorization, you must submit a complete and accurate NOI form. Discharges are not authorized if your NOI is incomplete or inaccurate or if you were never eligible for permit coverage. Refer to the instructions at the end of this form to complete your NOI.

A. Approval to	Use Paper NOI Form
1. Have you been	granted a waiver from electronic reporting from the EPA Regional Office*?
If yes, check v	which waiver you have been granted, the name of the EPA Regional Office staff person who granted the waiver, and the date of approval:
Waiver gran	
	The owner/operator has issues regarding available computer access or computer capability.
Name of EP	A staff person that granted the waiver: Naslm Jahan Jahan
	val obtained: 02/09/2016
must file this for	equired to obtain approval from the applicable EPA Regional Office prior to using this paper NOI form. If you have not obtained a waiver, you melectronically using the NPDES eReporting Tool (NeT) at

D. Facility Information
1. Facility Name: Los Allamos National Laboratory
2. Facility Address:
Street/Location: POBox 1663
City: Los Alamos State: NM ZiP Code: 87545-
County or Similar Government Subdivision:
3. Latitude/Longitude for the facility:
Latitude: 3 5 8 7 2 7 7 7 N (decimal degrees) Longitude: 1 0 6 3 2 1 1 2 7 N (decimal degrees)
Latitude/Longitude Data Source:
If you used a USGS topographic map, what was the scale?
Horizontal Reference Datum: NAD 27 NAD 83 WGS 84
4. Is your facility located on Indian Country lands? TYES INO
If yes, provide the name of the Indian tribe associated with the area of Indian country (including name of Indian reservation, if applicable):
5. Are you requesting coverage under this NOI as a "federal operator" as defined in Appendix A? YES NO 6. What is the ownership type of the
facility? Federal Facility (U.S. Government) Privately Owned Facility Municipality County Government
☐ Corporation ☐ State Government ☐ Tribal Government ☐ School District
District Mixed Ownership (e.g. Municipal or Water Public/Private) District
7. Estimated area of industrial activity at your facility exposed to stormwater: 131.36 (to the nearest quarter acre)
8. Sector-Specific Information
Identify the 4-digit Standard Industrial Classification (SIC) code or 2-letter Activity Code that best represents the products produced or services rendered for which your facility is primarily engaged, as defined in the MSGP, and the applicable sector and subsector of your primary industrial activity (See Appendix D):
Primary SIC Code: 3 4 4 9 OR Primary Activity Code:
Sector: A A Subsector: A A 1
Identify the applicable sector(s) and subsector(s) of any co-located industrial activity for which you are requesting permit coverage:
Sector: P Subsector: P 1 Sector: K Subsector: K 1 Sector: A Subsector: A 4 Sector: D Subsector: D 1
Sector: O Subsector: O 1 Sector: F Subsector: F 4 Sector: N Subsector: N 2 Sector: Subsector: N 2 Subsector: Subsector: N 2 Subsector: Subsector: N 2 Subsec
If you are a Sector S (Air Transportation) facility, do you anticipate using more than 100,000 gallons of pure glycol in glycol-based deicing fluids and/or 100 tons or more of urea on an average annual basis?
If you are a Sector G (Metal Mining) facility, do you have discharges from waste rock and overburden piles? 🔲 YES 📋 NO
Check the type of ore you mine at your facility: Tungsten Ore Nickel Ore
☐ Mercury Ore ☐ Iron Ore ☐ Platinum Ore ☐ Titanium Ore ☐ Vanadium Ore ☐ Molybdenum ☐ Uranium, Radium, and/or Vanadium Ore
9. Is your facility presently inactive and unstaffed?* 🔲 YES 🗎 NO
* Note that if your facility becomes inactive and unstaffed during the permit term, you must submit an NOI modification to reflect the change.
E. Discharge Information
1. By indicating "Yes" below, I confirm that I understand that the MSGP only authorizes the allowable stormwater discharges in Part 1.1.2 and the allowable non-stormwater discharges listed in Part 1.1.3. Any discharges not expressly authorized in this permit cannot become authorized or shielded from liability under CWA section 402(k) by disclosure to EPA, state, or local authorities after issuance of this permit via any means, including the Notice of Intent (NOI) to be covered by the permit, the Stormwater Pollution Prevention Plan (SWPPP), during an inspection, etc. If any discharges requiring NPDES permit coverage other than the allowable stormwater and non-stormwater discharges listed in Parts 1.1.2 and 1.1.3 will be discharged, they must be covered under another NPDES permit.
2. Federal Effluent Limitation Guidelines
Are you requesting permit coverage for any stormwater discharges subject to effluent limitation guidelines?

40 CFR Part/Subpart	Eligible Discharges	Affected MSGP Sector	New Source Date	Check if Applicable
Part 411, Subpart C	Runoff from material storage piles at cement manufacturing facilities	E	2/20/1974	
Part 418 Subpart A	Runoff from phosphate fertilizer manufacturing facilities that comes into contact with any raw materials, finished product, by-products or waste products (SIC 2874)	С	4/8/1974	
Part 423	Coal pile runoff at steam electric generating facilities	0	11/19/1982 10/8/1974 ¹	
Part 429, Subpart 1	Discharges resulting from spray down or intentional wetting of logs at wet deck storage areas	A	1/26/1981	
Part 436, Subpart B, C, or D	Mine dewatering discharges at crushed stone mines, construction sand and gravel mines, or industrial sand mines	J	N/A	
Part 443, Subpart A	Runoff from asphalt emulsion facilities	D	7/28/1975	•
Part 445, Subparts A & B	Runoff from hazardous waste and non-hazardous waste landfills	K, L	2/2/2000	
Part 449	Runoff containing urea from airfield pavement deicing at existing and new primary airports with 1,000 or more annual non-propeller aircraft departures	s	6/15/2012	0

NSPS promulgated in 1974 were not removed via the 1982 regulation; therefore wastewaters generated by Part 423-applicable sources that were New Sources under the 1974 regulations are subject to the 1974 NSPS.

3. Receiving Waters Information: (Attach a separate list if necessary)

11-4 11 2 44	e stormwater outfalls			
from your facility. Each outfall must be identified by a unique 3-digit ID (e.g., 001, 002). Also provide the latitude and longitude in degrees decimal for each outfall.		Provide the name of the first water of the U.S. that receives stormwater directly from the outfall and/or from the MS4 that the outfall discharges to:	If the receiving water is impaired (on the CWA 303(d) list), list the pollutants that are causing the impairment:	If a TMDL been completed for this receiving waterbody, providing the following information:
Outfall ID	002	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.875797		Polychlorinated Biphenyls (PCBs) Thallium, dissolved	Poliutant(s) for which there is a TMDL:
Longitude	-106.327580			N/A
Outfall ID	004	Two Mile Canyon (Pajarito to headwaters)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID:
Latitude	35.871431		1 003	Poliutant(s) for which there is a TMDL:
Longitude	-106.323832			N/A
If substantia	lly identical to other ou	rifall, list identical outfall ID:		

EPA FORM 3510-6 (Revised 6-2015)

-				
Outfail ID	005	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID:
Latitude	35.873919		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.320746			N/A
If substanti	ally identical to other o	outfall, list identical outfall ID:		<u> </u>
Outfall ID	006	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.874011		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.319858			N/A
if substantio	ally identical to other o	utfall, list identical outfall ID: 005		
Outfall ID	009	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID:
Latitude	35.874843		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.319412			N/A
If substantia	illy identical to other or	utfall, list identical outfall ID:		
Outfall ID	007	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.874014	,	PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
iongitude	-106.319203			N/A
f substantial	lly identical to other ou	tfall, list identical outfall ID: 009		(

Oulfall ID	008	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.874617		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.318925			N/A
It substanti	ally identical to other	outfall, list identical outfall ID: 009		
Outfall ID	010	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.875402		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.320301			N/A
if substantic	ally identical to other	outfall, list identical outfall ID: 009		
Oulfall ID	012	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
latitude	35.875532		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
longitude	-106.320884			N/A
f substantia	liy identical to other o	outfall, list identical outfall ID:		
Outfall ID	011	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
atitude	35.875563		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
		1		N/A
ongitude	-106.320744			_ =

Outfall ID	018	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.872834		Gross Alpha, adjusted PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.317653			N/A
If substanti	ally identical to other	outfall, list identical outfall ID:	×	
Outfall ID	013	Mortandad Canyon (Within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870797		PCBs	Pollutant(s) for which there is a TMDL:
Longitude	-106.317867			N/A
If substantic	ally identical to other	outfall, list Identical outfall ID: 018		
Outfall ID	014	Mortandad Canyon (Within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870890		PCBs	Pollutant(s) for which there is a TMDL:
Longitude	-106.317393		7	N/A
if substantia	lly identical to other o	outfall, list identical outfall ID: 018		
Outfall ID	015	Mortandad Canyon (Within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.871389		PCBs	Pollutant(s) for which there is a TMDL:
longitude	-106.316397			N/A
		I The state of the		

Outfall ID	016	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID:
Latitude	35.872447		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
longitude	-106.316721			N/A
If substanti	ally identical to other	outfall, list identical outfall ID: 018		
Outfall ID	017	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.872599		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.317066			N/A
lf substantic	ally identical to other	outfall, list identical outfall ID: 018		
Outfail ID	019	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
		001)	PCBs Thallium, dissolved	
Latitude	35.872682		Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Latitude Longitude	35.872682 -106.318467	· ·	Thallium, dissolved	
longitude	-106.318467	outfall, list identical outfall ID: 018	Thallium, dissolved	there is a TMDL:
longitude	-106.318467	Sandia Canyon (Sigma Canyon to NPDES outfall	Aluminum, total Copper, dissolved	there is a TMDL:
Longitude If substantia Outfall ID	-106.318467	Sandia Canyon (Sigma	Aluminum, total	there is a TMDL: N/A TMDL Name and ID:
Longitude If substantia	-106.318467 Ally identical to other a	Sandia Canyon (Sigma Canyon to NPDES outfall	Aluminum, total Copper, dissolved Gross Alpha, adjusted PCBs	TMDL Name and ID: N/A Pollutant(s) for which

	Too	Candia Carros (C)		TMDL Name and ID:
Oulfall ID	022	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	N/A
Latitude	35.872661		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.313691			N/A
if substanti	ally identical to other o	outfall, list identical outfall (D:		
Outfall ID	021	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.872514		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.313562			N/A
If substantio	ally identical to other o	utfali, list identical outfall ID: 022		
Outfall ID	023	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.873193		PCBs Thallium, dissolved	Poliutant(s) for which there is a TMDL:
Longitude	-106.313116			N/A
If substantia	illy identical to other or	utfall, list identical outfall ID: 022		
Outfall ID	024	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.873046	,	PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.315069			N/A
if substantia	lly identical to other ou	tfali, list identical outfall ID: ⁰²²		

Outfall ID	025	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted PCBs Thallium, dissolved	TMDL Name and ID:
Latitude	35.872928			Pollutant(s) for which there is a TMDL:
Longitude	-106.315400			N/A
if substanti	ally identical to other	outfall, list identical outfall ID: 022		n 1 le 1
Outfall ID	026	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.872114		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.313105			N/A
lf substantic	ally identical to other	outfall, list identical outfall ID:		
Outfall ID	027	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted PCBs Thallium, dissolved	TMDL Name and ID: N/A
Latitude	35.872401			Pollutant(s) for which there is a TMDL:
longitude	-106.313391		.8:	N/A
f substantic	illy identical to other o	outfall, list identical outfall ID: 026		A. d
Outfall (D	028	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted PCBs Thallium, dissolved	TMDL Name and ID: N/A
		001)		
.atitude	35.872505			Pollutant(s) for which there is a TMDL:
	35.872505 -106.313542			

Outfall ID	029	Sandia Canyon (Sigma Canyon to NPDES outfall	Aluminum, total Copper, dissolved	TMDL Name and ID:
Latitude	35.873969	001)	Gross Alpha, adjusted PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.313281			N/A
If substanti	ally identical to other	outfall, list identical outfall ID:		
Outfail ID	031	Mortandad Canyon (within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.869227		PCBs	Poliutant(s) for which there is a TMDL:
Longitude	-106.305685			N/A
If substantia	ally identical to other o	outfall, list identical outfall ID:		
Outfall ID	030	Mortandad Canyon (within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.869325		PCBs	Pollutant(s) for which there is a TMDL;
Longitude	-106.306926			N/A
if substantia	Illy identical to other o	utfall, list identical outfall ID: 031	<i>K</i>	
Oulfali ID	032	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870741		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longilude	-106.306812			N/A
f substantial	lly identical to other ou	utfall, list identical outfall ID:		

Outfall ID	033	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870712		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.306443			N/A
lf substanti	ally identical to other	outfall, list identical outfall ID: 032		
Outfall ID	034	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870603		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.306055			N/A
if substantic	ally identical to other	outfall, list identical outfall ID: 032	1	
Outfall ID	035	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.870474		PCBs Thallium, dissolved	Poliutant(s) for which there is a TMDL:
Longifude	-106.305432			N/A
lf substantio	illy identical to other o	outfall, list identical outfall ID: 032		
Outfall ID	036	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.867825		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
I		1		N/A
longilude	-106.293388			

Outfall ID	037	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.867859		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.292992			N/A
if substanti	ally identical to other o	outfall, list identical outfall ID: 036		
Outfall ID	039	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.867826		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.291726			N/A
if substantic	ally identical to other o	utfall, list identical outfall ID:		
Ouffall ID	038	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID:
Latitude	35.867855		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longilude	-106.292211			N/A
if substantio	illy identical to other or	utfall, list identical outfall ID: 039		
Outfall ID	040	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.867839	<i></i>	PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.291955			N/A
If substantia	lly identical to other ou	tfall, list identical outfall ID: 039		

Outfall ID	042	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.867047		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.289163			N/A
if substanti	ally Identical to other	outfall, list identical outfall ID:		
Ouffall ID	041	Mortandad Canyon (within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.866377		PCBs	Pollutant(s) for which there is a TMDL:
Longitude	-106.291397	_		N/A
if substantic	ally identical to other	putfall, list identical outfall ID: 042	- Games	I.
Outfall ID	043	Mortandad Canyon (within LANL)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Outfall ID	043 35.866084		•	
			Copper, dissolved Gross Alpha, adjusted	N/A Pollutant(s) for which
Latitude Longitude	35.866084 -106.290165		Copper, dissolved Gross Alpha, adjusted PCBs	N/A Pollutant(s) for which there is a TMDL:
Latitude Longitude	35.866084 -106.290165	LANL)	Copper, dissolved Gross Alpha, adjusted PCBs Aluminum, total Gross Alpha, adjusted	N/A Pollutant(s) for which there is a TMDL:
Latitude Longitude If substantia	35.866084 -106.290165	LANL) Dutfall, list Identical outfall ID: Canada del Buey (within	Copper, dissolved Gross Alpha, adjusted PCBs Aluminum, total	N/A Pollutant(s) for which there is a TMDL: N/A

Outfall ID	044	Canada del Buey (within LANL)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID: N/A
Latitude	35.845868			Pollutant(s) for which there is a TMDL:
Longitude	-106.265279			N/A
If substantia	ally identical to other o	outfall, list identical outfall ID: 047		
Outfall ID	045	Canada del Buey (within LANL)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID: N/A
Latitude	35.845586			Pollutant(s) for which there is a TMDL:
Longifude	-106.265214			N/A
If substantia	lly identical to other o	utfall, list identical outfall ID: 047		
Outfall ID	046	Canada del Buey (within LANL)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID:
Latitude	35.845200		· 655	Pollutant(s) for which there is a TMDL:
Longitude	-106.264844		A 1	N/A
If substantia	lly identical to other ou	rifali, list identical outfali ID: 047		
Outfall ID	048	Canada del Buey (within LANL)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID: N/A
Latitude	35.844590			Pollutant(s) for which there is a TMDL:
Longitude	-106.265044			N/A
If substantial	ly identical to other ou	Ifali, list identical outfall ID: 047		"

Oulfall ID	049	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Lalifude	35.837228			Pollutant(s) for which there is a TMDL:
Longitude	-106.254840			N/A
If substanti	ally identical to other	outfall, list identical outfall ID:		
Oulfall ID	050	Canada del Buey (within LANL)	Aluminum, total Gross Alpha, adjusted PCBs	TMDL Name and ID: N/A
Latitude	35.835746			Pollutant(s) for which there is a TMDL:
Longitude	-106.250832			N/A
if substantio	Lily identical to other	outfall, list identical outfall ID:		
Outfall ID	051	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.830143	_ Delie)	: :	Pollutant(s) for which there is a TMDL:
Longitude	-106.242662			N/A
lf substantic	lly identical to other o	Dutfall, list identical outfall ID:		
Outfall ID	052	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.831852			Pollutant(s) for which there is a TMDL:
		4		N/A
.ongitude	-106.242928			,,,,,

Oulfall ID	053	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID:
Latitude	35.829232			Pollutant(s) for which there is a TMDL:
Longitude	-106.236793			N/A
if substanti	ally identical to other	outfall, list identical outfall ID:		н
Outfall ID	065	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829028			Pollutant(s) for which there is a TMDL:
Longitude	-106.236029			N/A
If substantic	ally identical to other o	outfall, list identical outfall ID: 053		
Ouffail ID	066	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.830185	Delie)		Poliutant(s) for which there is a TMDL:
Longitude	-106.236107			N/A
if substantia	illy identical to other o	utfall, list identical outfall ID: 053		
Outfall ID	069	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID:
Lattivde	35.830285	,		Pollutant(s) for which there is a TMDL:
Longitude	-106.234518		-	N/A
	80 0 0 0 0	uffall, list identical outfall ID:		

Outfall ID	054	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829036			Pollutant(s) for which there is a TMDL:
Longitude	-106.235125			N/A
If substant	ally identical to other	outfall, list identical outfall ID: 069		
Oulfall ID	055	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829173			Pollutant(s) for which there is a TMDL:
Longitude	-106.235121			N/A
if substanti	ally identical to other	outfall, list identical outfall ID: 069		
Outfall ID	056	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829310			Pollutant(s) for which there is a TMDL:
Longitude	-106.236107			N/A
f substantic	lly identical to other (outfall, list identical outfall ID: 069		
Outfall ID	057	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
atitude	35.829440			Poliutant(s) for which there is a TMDL:
	-106.235117			N/A
ongitude				

Outfall ID	058	Pajarito Canyon (within LANL below Arroyo de la	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829573	Delfe)		Pollutant(s) for which there is a TMDL:
Longitude	-106.235112		-	N/A
lf substanti	ally identical to other	outfali, list identical outfali ID: 069		
Outfall ID	059	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.829711			Pollutant(s) for which there is a TMDL:
Longitude	-106.235108		£	N/A
If substantic	Ily identical to other o	Dutfall, list identical outfall ID: 069		
Outfall ID	060	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.830340	2 Delie)		Pollutant(s) for which there is a TMDL:
Longitude	-106.234802	w =		N/A
lf substantia	illy identical to other o	utfall, list identical outfall ID: 069		
Oulfall ID	061	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.830343			Poliutant(s) for which there is a TMDL:
Longitude	-106.234766	ja ki		N/A
		utfall, list identical outfall iD: 069		

Outfall ID	062	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID:
Latitude	35.830344			Pollutant(s) for which there is a TMDL:
Longitude	-106.234725			N/A
if substant	laily identical to other	outfall, list identical outfall ID: 069		
Outfall ID	063	Pajarito Canyon (within LANL below Arroyo de la Delfe)	Aluminum, total PCBs	TMDL Name and ID: N/A
Latitude	35.830342			Pollutant(s) for which there is a TMDL:
Longitude	-106.234692			N/A
If substanti	ally identical to other	outfall, list identical outfall ID: 069		
Outfall ID	064	Pajarito Canyon (within	Aluminum, total	TMDL Name and ID:
Secondario		LANL below Arroyo de la	PCBs	
Latitude	35.830340	LANL below Arroyo de la Delfe)	PCBs	Pollutant(s) for which there is a TMDL:
36	35.830340 -106.234656		PCBs	Poliutant(s) for which
Latitude Longitude	-106.234656		PCBs	Poliutanf(s) for which there is a TMDL:
Latitude Longitude	-106.234656	Pajarito Canyon (within LANL below Arroyo de la	Aluminum, total	Poliutanf(s) for which there is a TMDL:
Latitude Longitude If substantic	-106.234656	Delfe) Duttall, list identical outfall ID: 069 Pajarito Canyon (within	Aluminum, total	Poliutanf(s) for which there is a TMDL: N/A TMDL Name and ID:
Latitude Longitude if substantic	-106.234656 ally identical to other a	Pajarito Canyon (within LANL below Arroyo de la	Aluminum, total	Pollutant(s) for which there is a TMDL: N/A TMDL Name and ID: N/A Pollutant(s) for which

If substantially identical to other outfall, list identical outfall ID: Outfall ID O70 Canada del Buey (within LANL) Canada del Buey (within PCBs Aluminum, total Gross Alpha, adjusted PCBs Pollutant(s) for which there is a TMDL: N/A If substantially identical to other outfall, list identical outfall ID: 072 Outfall ID O71 Canada del Buey (within LANL) Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs TMDL Name and ID: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A					TAIRL Name and the
Latiflude 35.830051 Longitude -106.235103 If substantially identical to other outfall, list identical outfall ID: Canada del Buey (within LANL) Canada del Buey (within LANL) Latiflude 35.832885 Longitude -106.239444 If substantially identical to other outfall, list identical outfall ID: Canada del Buey (within LANL) TMDL Name and ID: N/A TMDL Name and ID: N/A Pollutant(s) for which there is a TMDL: N/A	Outfall ID	068	LANL below Arroyo de la		
tongitude -106.235103	Latitude	35.830051			
Cuffall ID 072 Canada del Buey (within LANL) Latitude 35.832885 Longitude -106.239444 Toutical ID 070 Canada del Buey (within LANL) Council ID 070 Canada del Buey (within LANL) Latitude 35.832404 Longitude -106.240510 Table Name and ID: N/A Pollutant(s) for which there is a TABL: N/A Pollutant(s) for which there is a TABL: N/A Latitude 35.832701 Canada del Buey (within LANL)	Longitude	-106.235103			N/A
Cutfall ID Lafflude 35.832885 Longitude -106.239444 If substantially Identical to other outfall, list Identical outfall ID: Canada del Buey (within LANL) Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs TMDI. Name and ID: N/A Pollutant(s) for which there is a TMDI: N/A Pollutant(s) for which there is a TMDI: N/A If substantially Identical to other outfall, list Identical outfall ID: Canada del Buey (within LANL) If substantially Identical to other outfall, list Identical outfall ID: Outfall ID Outfall ID Or1 Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs TMDI. Name and ID: N/A Pollutant(s) for which there is a TMDI: N/A	If substanti	ally identical to other o	utfall, list identical outfall ID: 069		
Longitude -106.239444 Longitude -106.239444 If substantially identical to other outfall, list identical outfall ID: Outfall ID Outfall ID Canada del Buey (within LANL) Longitude -106.240510 If substantially identical to other outfall, list identical outfall ID: Outfall ID O70 Canada del Buey (within LANL) Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A If substantially identical to other outfall, list identical outfall ID: Outfall ID O71 Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs TMDL Name and ID: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A	Outfall ID	072		Gross Alpha, adjusted	
toutfall ID 070 Canada del Buey (within LANL) N/A Pollutant(s) for which there is a TMDL: N/A	Latitude	35.832885			
Canada del Buey (within LANL) Canada del Buey (within Gross Alpha, adjusted PCBs Aluminum, total Gross Alpha, adjusted PCBs Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A It substantially identical to other outfall, list identical outfall ib: 072 Outfall ID O71 Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs TMDL Name and ID: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A Pollutant(s) for which there is a TMDL: N/A	Longitude	-106.239444			N/A
Carriada del Buey (Within LANL) Solutified Carriada del Buey (Within LANL) Carriada del Buey (Within LANL)	if substantio	ally identical to other o	iuffail, list identical outfail ID:		
tatified 35.832404 Longitude -106.240510 Total Duffall ID Canada del Buey (within LANL) Canada del Buey (within LANL) Aluminum, total Gross Alpha, adjusted PCBs Pollutant(s) for which there is a TMDL: N/A	Outfail ID	070		Gross Alpha, adjusted	
In the substantially identical to other outfall, list identical outfall ID: 072 Outfall ID	Latitude	35.832404		FODS	
Outfall ID Canada del Buey (within LANL) Canada del Buey (within Gross Alpha, adjusted PCBs Aluminum, total Gross Alpha, adjusted PCBs Pollutant(s) for which there is a TMDL: N/A	Longitude	-106.240510			N/A
outfall ID Canada del Buey (Within LANL) Aluminum, total Gross Alpha, adjusted PCBs Pollutant(s) for which there is a TMDL: N/A N/A	If substantio	illy identical to other ou	rifall, list identical outfall ID: 072		
atitude 35.832701 Pollutant(s) for which there is a TMDL: N/A	Outfall ID	071		Gross Alpha, adjusted	
ongitude -105.240994	Latitude	35.832701		. 000	
	Longitude	-106.240994			N/A
substantially identical to other outfall, list identical outfall ID: 072	lf substantia	ly identical to other ou	tfall, list identical outfall ID: 072		

Outfall ID	073	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.874819		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.324283			N/A
if substanti	ally identical to other	outfall, list identical outfall ID:		
Outfall ID	074	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
Latitude	35.875034		PCBs Thallium, dissolved	Pollutant(s) for which there is a TMDL:
Longitude	-106.327328			N/A
lf substantic	illy identical to other c	outfall, list identical outfall ID: 073		
Outfail ID	075	Sandia Canyon (Sigma Canyon to NPDES outfall 001)	Aluminum, total Copper, dissolved Gross Alpha, adjusted	TMDL Name and ID: N/A
	0-0-44-4	7 ***	PCBs	Pollutant(s) for which
Latitude	35.871154		Thallium, dissolved	there is a TMDL:
Latitude Longitude	-106.312940		Thallium, dissolved	
Longitude	-106.312940	outfall, list identical outfall ID:		there is a TMDL:
Longitude	-106.312940	outfall, list identical outfall ID:		there is a TMDL:
Longitude If substantia	-106.312940	outfall, list identical outfall ID:		there is a TMDL:
Longitude If substantia Outfall ID	-106.312940	outfall, list identical outfall ID:		there is a TMDL: N/A TMDL Name and ID: Pollutant(s) for which

4. Provide the following Information about your outfall latitude longitude:
Latitude/Longitude Data Source:
If you used a USGS topographic map, what was the scale?
Horizontal Reference Datum: NAD 27 NAD 83 WGS 84
5. Does your facility discharge into a Muncipal Separate Storm Sewer System (MS4)? YES NO
If yes, provide the name of the MS4 operator, N/A
6. Check if you discharge to any of the waters of the U.S. that are designated by the state or tribal authority under its antidegradation policy as a Tier 2 (or Tier 2.5) water (water quality exceeds levels necessary to support propagation of fish, shellfish, and wildlife and recreation in and on the water) or as a Tier 3 water (Outstanding National Resource Water)? (See Appendix L).
□ Tier 2/2.5. Provide the name(s) of receiving water(s):
☐ Tier 3 (Outstanding National Resource Waters)*
 Note: You are ineligible for coverage if you are a new discharger or new source to waters designated as Tier 3 (outstanding national resource waters) for antidegradation purposes under 40 CFR 131.13(a)(3). If you are subject to benchmark monitoring requirements for a hardness-dependent metal, what is the hardness of your receiving water(s) (see Appendix J) ? 4mg/L)
8. If you are subject to benchmark monitoring requirements for a hardness-dependent metal, does your facility discharge into any saltwater receiving waters? YES INO
9. Does your facility discharge to a federal CERCLA site listed in Appendix P? 🔲 YES 🛮 🔳 NO
If yes, did you notify the EPA Regional Office in advance of filing your NOI, and did the EPA Regional Office determine that you are eligible for permit coverage pursuant to Part 1.1.4.10°? 🔲 YES 📉 NO
Note: If you discharge to a federal CERCLA site listed in Appendix P, you are ineligible for coverage under this permit unless you notify the EPA Regional Office in advance and the EPA Regional Office determines you are eligible coverage under this permit. In determining your eligibility for coverage under this Part, the EPA Regional Office may evaluate whether you have included adequate controls and/or procedures to ensure that your discharges will not lead to reconfarmination of aquatic media at the CERCLA Site such that it will to cause or contribute to an exceedance of a water quality standard.
F. Stormwater Pollution Prevention Plan (SWPPP) Information
1. Has the SWPPP been prepared in advance of filling this NOI, as required? YES NO
2. SWPPP Contact Information:
First Name, Middle Initial, Last Name: Holly L Wheeler r
Professional Title: Environmental Professional
Phone: 5 0 5 - 6 6 7 - 1 3 1 2 Ext.
E-mail: h b e n s o n @ i a n i . g o v
3. SWPPP Availability: Volume of SWPPP are contain information from your SWPPP and the containing of t
Your current SWPPP or certain information from your SWPPP must be made available through one of the following two options. Select one of the options and provide the required information*:
* Note: You are not required to post any confidential business information (CBI) or restricted information (as defined in Appendix A) (such information may be redacted), but you must clearly identify those portions of the SWPPP that are being withheld from public access.
Option 1: Maintain a current copy of your SWPPP on an Internet page (Universal Resource Locator or URL).
Provide the web address URL: eptr.lanl.gov
Option 2: Provide the following information from your SWPPP:
A. Describe your onsite industrial activities exposed to stormwater (e.g., material storage; equipment fueling, maintenance, and cleaning; cutting steel beams), and potential spill and leak areas:

The second secon	
B. List the pollutant(s) or pollutant constituent(s) associated with each industrial activity exposed to stormwater that could be discharge authorized non-stormwater discharges listed in Part 1.1.3:	d in stormwater and ar
C. Describe the control measures you will employ to comply with the non-numeric technology-based effluent limits required in Part 2.1.2 other measures taken to comply with the requirements in Part 2.2 Water Quality-Based Effluent Limitations (see Part 5.2.4):	and Part 8, and any
D. Provide a schedule for good housekeeping and maintenance (see Part 5.2.5.1) and a schedule for all inspections required in Part 4 (s	see Part 5.2.5.2):
	_
G. Endangered Species Protection	
Using the instructions in Appendix E of the MSGP, under which endangered species criterion listed in Part 1.1.4.5 are you eligible for call.	A. 1.
permit (only check 1 box) ?*	verage under mis
DA DB DC DE	
 Note: After you submit your NOI and before your NOI is authorized, EPA may notify you it any additional controls are necessary to ensubave no likely adverse affects on listed species and critical habitat. 	rre your discharges
2. Provide a brief summary of the basis for the criterion selected in Appendix E (e.g., communication with U.S. Fish and Wildlife Service or Fisheries Service to determine no species in action area; implementation of controls approved by EPA and the Services): Direct consultation with the U.S. Fish and Wildlife Service and corresponding development and implementation of a facility-specific Habitat Management P	
3. If you select criterion B, provide the NPDES ID from the other operator's NOI authorized under this permit:	
4. If you select criterion C, you must answer the following questions:	
a. What federally-listed species or designated critical habitat are located in your "action area":	
b. Using the Appendix E worksheet, check which of the following is applicable to your facility and answer any corresponding questions	¢:
I submitted my completed Criterion C Eligibility Form to EPA at least 30 days prior to submitting this NOI and agree to implement and that were determined by EPA to be necessary to ensure that my discharges and/or discharge-related activities will not have likely a listed species and critical habitat.	v additional measures
Date your Criterion C Eligibility Form was sent to EPA:	
Describe any EPA-approved measures you will implement to ensure no likely adverse affects on listed species and critical habitat:	
I submitted my completed Criterion C Eligibility Form to EPA at least 30 days prior to submitting this NOI and have not been notified measures necessary to ensure no likely adverse affects on listed species and critical habitat. Date your Criterion C Eligibility Form was sent to EPA:	of any additional
If you select criterion D or E, you must attach copies of any letters or other communications with the U.S. Fish and Wildlife Service or Nat Service.	ional Marine Fisheries

EPA FORM 3510-6 (Revised 6-2015)

H. Historic Pre	servation									ver the			
YES	□ NO		Indian country lai					or cul	Itural sig	nificance	to an Inc	dian tribe	B\$
2. Using the in under this p	nstructions in Dermit (only	Append	dix F of the MSGP, box)?	under which his	storic propertie	es preserva	tion criterion	listed	d in Part	1.1.4.6 ar	e you eli	gible for	coverage
	⊞в ⊏]c	D										
I. Certification	Information					in the same		3,5					
system, or tho	se persons c	irectly re	this document and properly gathered esponsible for gath ere are significant	ana evaluated herina the inform	t the intormational the info	on submitte	ed. Based on Ibmitted is to	my i	inquiry of	f the per	on or pe	ersons wh	no manage the
First Name, Mi	ddle Initial, L	.ast Nam	e: John			P M	c Can	n	11	Ш	Ш		
Title:	Div	isi	on Lea	der	ШШ	Ш	ШШ						_
Signature:	9	7W						ic.	Date:	03/2	22/2	4018	6
E-mail:	Imc	c a n	n@lani	. g o v	ШЦ	Ш	ШШ		-				-
		1				Charles and							Control of the contro

Instructions for Completing EPA Form 3510-6

Notice of Intent (NOI) for Stormwater Discharges Associated with Industrial Activity Under the NPDES Multi-Sector General Permit

NPDES Form Date (06/15)

This Form Replaces From 3510-6 (09/08)

Form Approved OMB No. 2040-0004

Who Must File an NO! Form

Under section 402(p) of the Clean Water Act (CWA) and regulations at 40 CFR Part 122, stormwater discharges associated with industrial activity are <u>prohibited</u> to waters of the United States unless authorized under a National Pollutant Discharge Elimination System (NPDES) permit. You can obtain coverage under the MSGP by submitting a completed Notice of Intent (NOI) if you are an operator a facility:

- that is located in a jurisdiction where EPA is the permitting authority, listed in Appendix C of the MSGP,
- that discharges stormwater associated with industrial activities, identified in Appendix D of the MSGP.
- that meets the eligibility requirements in Part 1.1 of the permit.
- that has developed a stormwater pollution prevention plan (SWPPP) in accordance with Part 5 of the MSGP; and
- that installs and implements control measures in accordance with Part 2 and Part 8 to meet numeric and non-numeric effluent

Completing the Form

Obtain and read a copy of the 2015 MSGP, viewable at http://water.epa.gov/polwaste/npdes/stormwater/EPA-Multi-Sector-General-Permit-MSGP.cfm. To complete this form, type or print, using uppercase letters, in the appropriate areas only. Please place each character between the marks. Abbreviate if necessary to stay within the number of characters allowed for each item. Use only one space for breaks between words, but not for punctuation marks unless they are needed to clarify your response. Please submit original document with signature in ink - do not send a photocopied signature.

Section A. Approval to Use Paper NOI Form

You must indicate whether you have been granted a waiver from electronic reporting from the EPA Regional Office. Note that you are not authorized to use this paper NOI form unless the EPA Regional Office has approved its use. Where you have obtained approval to use this form, indicate the waiver that you have been granted, the name of the EPA staff person who granted the waiver, and the date that approval was provided.

See http://water.epa.gov/polwaste/nodes/stormwater/Stormwater-Contacts.cfm for a list of EPA Regional Office contacts.

Section B. Permit Information

Provide the master permit number of the permit under which you are applying for coverage (see Appendix C of the general permit for the list of eligible master permit numbers).

You must indicate whether you are a new discharger or a new source (see Appendix A for the definitions). If you are not a new discharger or a new source, you must indicate whether stormwater discharges NPDES permit. If yes, you must provide the unique NPDES ID (i.e., permit tracking number) for the previous permit your facility was covered under.

Section C. Facility Operator Information

Provide the legal name of the person, firm, public organization, or any other entity that operates the facility described in this NOI. An operator of a facility is the legal entity that controls the operation of the facility. Refer to Appendix A of the permit for the definition of "operator". Provide the operator's mailing address, phone number,

and e-mail. Correspondence for the NOI will be sent to this address. Also provide the name and title for the operator point of contact (note that the point of contact name may be the same as the operator name).

If the NOI was prepared by someone other than the certifier (for example, if the NOI was prepared by the facility SWPPP contact or a consultant for the certifier's signature), include the full name, organization, phone number, and email address of the NOI preparer.

Section D. Facility Information

Enter the official or legal name and complete address, including city. state, ZIP code, and county or similar government subdivision of the facility. If the facility lacks a street address, indicate the general location of the facility (e.g., Intersection of State Highways 61 and 34). Complete facility information must be provided for permit coverage to be granted.

Provide the latitude and longitude of your facility in decimal degrees format. The latitude and longitude of your facility can be determined in several different ways, including through the use of global positioning system (GPS) receivers, U.S. Geological Survey (U.S.G.S.) topographic or quadrangle maps. Refer to http://transition.fcc.gov/mb/audio/bickel/DDDMMSSdecimal.html/ for assistance in providing the proper latitude/longitude format. For consistency, EPA requests that measurements be taken from the approximate center of the facility. Specify which method you used to determine latitude and longitude. If a U.S.G.S. topographic map is used, specify the scale of the map used. Enter the horizontal reference datum for your latitude and longitude. The horizontal reference datum used on USGS topographic maps is shown on the bottom left corner of USGS topographic maps; it is also available for GPS receivers.

Indicate whether the facility is on Indian country lands, and if so, provide the name of the Indian tribe associated with the area of Indian country (including name of Indian reservation, if applicable).

Indicate whether you are seeking coverage under this permit as a "federal operator" as defined in Appendix A. Also check the ownership type for the facility (e.g., Federal Facility, Privately Owned Facility, Municipality, County Government, Corporation, State Government, Tribal Government, School District, District, Mixed Ownership [e.g., public/private], Municipal or Water District).

Enter the estimated area of industrial activity at your facility exposed to stormwaterto the nearest quarter acre.

List the four-digit Standard Industrial Classification (SIC) code or two character activity code that best describes the primary industrial activities performed by your facility under which you are required to obtain permit coverage. Your primary industrial activity includes any activities performed on-site which are (1) identified by the facility's primary SIC code and included in the descriptions of 40 CFR 122.26(b)(14)(ii), (iii), (vi), or (viii); or (2) included in the narrative from your facility have been previously covered under another descriptions of 40 CFR 122.26(b) (14) (i), (iv), (v), (vii), or (ix). See Appendix D of the MSGP for a complete list of SIC codes and activities codes covered under the MSGP. Also provide the applicable sector and subsector associated with the SIC code or activity code for your primary industrial activities. For a complete list of sector and subsector codes, see Appendix D of the MSGP.

> If your facility has co-located industrial activities that are not identified as your primary industrial activity, identify the sector and subsector codes that describe these other industrial activities.

Instructions for Completing EPA Form 3510-6

Notice of Intent (NOI) for Stormwater Discharges Associated with Industrial Activity Under the NPDES Multi-Sector General Permit

NPDES Form Date (06/15) This Form Replaces From 3510-6 (09/08)

Form Approved OMB No. 2040-0004

For Sector S facilities (Air Transportation), indicate whether you anticipate that the entire airport facility will use more than 100,000 gallons of pure glycol in glycol-based deicing fluids and/or 100 tons or more of urea on an average annual basis. If so, additional effluent limits and monitoring conditions apply to your discharge (see Part 8.S of the permit).

For Sector G facilities (Metal Mining), check the type of ore(s) mined at the facility.

Indicate whether your facility is currently inactive and unstaffed. Note that if your facility becomes inactive and unstaffed during the permit term, you must submit an NOI modification to reflect the change.

Section E. Discharge Information

You must confirm that you understand that the MSGP only authorizes the allowable stormwater discharges listed in Part 1.1.2 and the allowable non-stormwater discharges listed in Part 1.1.3. Any discharges not expressly authorized under the MSGP are not covered by the MSGP or the permit shield provision of the CWA Section 402(k) and they cannot become authorized or shielded by disclosure to EPA, state, or local authorities via the NOI to be covered by the permit or by any other means (e.g., in the SWPPP or during an inspection). If any discharges requiring NPDES permit coverage other than the allowable stormwater and non-stormwater discharges listed in Parts 1.1.2 and 1.1.3 will be discharged, they must either be eliminated or covered under another NPDES permit.

Depending on your industrial activities, your facility may be subject to federal effluent limitation guidelines which include additional effluent limits and monitoring requirements for your facility. Please review these requirements, described in Part 2.1.3 of the MSGP, and check any appropriate boxes on the NOI form.

You must identify all the outfalls from your facility that discharge stormwater. Each outfall must be assigned a unique 3-digit ID (e.g., 00) 002, 003). You must also provide the latitude and longitude for each outfall from your facility. Indicate whether any outfalls are substantially identical to an outfall already listed, and identify the outfall it is identical to. For each unique outfall you list, you must specify the name of the first water of the U.S. that receives stormwater directly from the outfall and/or from the MS4 that the outfall discharges to. You must specify whether any receiving waters that you discharge to are listed as "impaired" as defined in Appendix A, and the pollutants for which the water is impaired. You must also check identify any Total Maximum Daily Loads (TMDL) that have been completed for any of the waters of the U.S. that you discharge to. You must also provide information about the outfall latitude/longitude, including data source, the scale (if applicable), and the horizontal reference datum. See the instructions in Section D for more information about determining the latitude and longitude.

Identify whether your facility discharges into a Municipal Separate Storm Sewer System (MS4). If yes, provide the name of the MS4 operator. If you are uncertain of the MS4 operator, contact your local government for that information.

Indicate whether discharges from the facility will enter into a water of the U.S that is designated as a Tier 2, Tier 2.5, or Tier 3 water. A list of Tier 2, 2.5, and 3 waters is provided as Appendix L. If the answer is "yes", name all waters designated as Tier 2, Tier 2.5, or Tier 3 to which the facility will discharge. Note that you are ineligible for coverage if you are a new discharger or a new source to waters designated as Tier 3 (outstanding national resource waters) for antidegradation purposes under 40 CFR 131.13(a)(3).

If you are subject to any benchmark monitoring requirements for metals (see the requirements applicable to your Sector(s) in Part 8 of the permit), indicate the hardness for your receiving water(s). See Appendix J of the permit for information about determining waterbody hardness.

If you are subject to benchmark monitoring requirements for hardness-dependent metals you must also answer whether your facility discharges into any saltwater receiving waters.

Indicate whether your facility will discharge to a federal CERCLA site listed in Appendix P. Note that if your facility will discharge into a federal CERCLA site listed in Appendix P, you are not eligible for coverage under this permit unless you notify the EPA Regional Office in advance and the EPA Regional Office authorizes overage under this permit after you have included adequate controls and/or procedures designed to ensure that discharges will not lead to recontamination of aquatic media at the CERCLA site such that your discharge will cause or contribute to an exceedance of a water quality standard.

Section F. Stomwater Poliution Prevention Plan (SWPPP) Information

All facilities eligible for coverage under this permit are required to prepare a SWPPP in advance of filing the NOI, in accordance with Part 5. Indicate whether the SWPPP has been prepared in advance of filing the NOI.

Indicate the contact information (name, phone, and email) for the person who developed the SWPPP for this facility.

You identify how your SWPPP information will be made availal consistent with Part 5.4 and 7.3 of the permit. If you are making your SWPPP publicly available on a web site, check Option 1 and provide the appropriate Internet URL address. If you are not providing a URL, check Option 2 and provide the selected SWPPP information on this NOI form. You may copy and paste this information directly from your SWPPP.

Section G. Endangered Species Protection

Using the instructions in Appendix E, indicate the Part 1.1.4.5 criterion (i.e., A, B, C, D, or E) you are eligible under with regard to the protection of federally listed endangered and threatened species and designated critical habitat. A description of the basis for the criterion selected must also be provided.

If criterion B is selected, provide the NPDES ID (i.e., permit tracking number) for the other operator who has certified their eligibility under this permit. The NPDES ID was assigned when the operator received coverage under this permit.

If criterion C is selected, you must specify the federally-listed species or designated critical habitat that are located in the "action area" of the facility. You must also indicate under which scenario you determined you were eligible to submit your NOI under criterion C using Appendix E, and answer any corresponding questions.

If criterion D or E is selected, attach copies of any communications between you and the U.S. Fish and Wildlife Service and National Marine Fisheries Service to this NOI.

Section H. Historic Preservation

If the project is not located in Indian country lands, indicate whether the project is located on a property of religious or cultural significance to an Indian tribe, and if so, provide the name of the Indian tribe associate with the property. Use the instructions in Appendix F to complete questions on the NOI form regarding historic preservation.

Instructions for Completing EPA Form 3510-6

Notice of Intent (NOI) for Stormwater Discharges Associated with Industrial Activity Under the NPDES Multi-Sector General Permit

NPDES Form Date (06/15) This Form Replaces From 3510-6 (09/08)

Form Approved OMB No. 2040-0004

Section I. Certification

Certification statement and signature (see Section B.11 of Appendix B of the MSGP for more information). Enter certifier's printed name, title and email address. Sign and date the form. (CAUTION: An unsigned or undated NOI form will prevent the granting of permit coverage.) Federal statutes provide for severe penalties for submitting false information on this application form. Federal regulations require this application to be signed as follows:

For a corporation: by a responsible corporate officer, which means: (i) a president, secretary, treasurer, or vice-president of the corporation in charge of a principal business function, or any other person who performs similar policy- or decision-making functions for the corporation, or (ii) the manager of one or more manufacturing, production, or operating facilities, provided, the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations. and initiating and directing other comprehensive measures to assure long-term environmental compliance with environmental laws and regulations; the manager can ensure that the necessary systems are established or actions taken to gather complete and accurate information for permit application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures.

For a partnership or sole proprietorship: By a general partner or the proprietor, respectively; or

For a municipality, state, federal, or other public agency: By either a principal executive officer or ranking elected official. For purposes of this Part, a principal executive officer of a federal agency includes (i) the chief executive officer of the agency, or (ii) a senior executive officer having responsibility for the overall operations of a principal geographic unit of the agency (e.g., Regional Administrator of EPA). Include the name and title of the person signing the form and the date of signing.

An unsigned or undated NOI form will not be considered eligible for permit coverage.

Modifying Your NO!

If you have been granted a waiver from your Regional Office from electronic reporting, and if after submitting your NOI you need to correct or update any fields on this NOI form, you may do so by indicating changes on this same form.

Paperwork Reduction Act Notice

Public reporting burden for this NOI is estimated to average 3.7 hours plus an additional 2 hours for certain respondents required to gathe hardness data. This estimate includes time for reviewing instructions searching existing data sources, gathering and maintaining the datc needed, and completing and reviewing the collection of information An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. Send comments regarding the burden estimate, any other aspect of the collection of information, or suggestions for improving this form, including any suggestions which may increase or reduce this burden to: Director, Collection Strategies Division, U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number on any correspondence. Do not send the completed form to this address.

Submitting Your Form

If you have been granted a waiver from your Regional Office to submit a paper NOI form, you must send your NOI by mail to one of the following addresses:

For Regular U.S. Mail Delivery:

Stormwater Notice Processing Center Mail Code 4203M, ATTN: 2015 MSGP Reports U.S. EPA 1200 Pennsylvania Avenue, NW

1200 Pennsylvania Avenue, NW Washington, DC 20460

For Overnight/Express Mail Delivery:

Stormwater Notice Processing Center William Jefferson Clinton East Building - Room 7420 ATTN: 2015 MSGP Reports U.S. EPA

1201 Constitution Avenue, NW Washington, DC 20004

Visit this website for instructions on how to submit electronically: http://water.epa.gov/polwaste/npdes/stormwater/Stormwater-eNOI-System-for-EPAs-MultiSector-General-Permit.cfm

ENCLOSURE 2

Concurrence Letters From the United States Department of Interior, Fish and Wildlife Service

ADESH-16-045

LA-UR-16-21721

Date: MAR 2 2 2016



United States Department of the Interior

FISH AND WILDLIFE SERVICE

New Mexico Ecological Services Field Office 2105 Osuna NE Albuquerque, New Mexico 87113 Phone: (505) 346-2525 Fax: (505) 346-2542

February 12, 1999

Cons. #2-22-98-J-336 Cons. #2-22-95-J-108

David A. Gurule, Acting Area Manager Department of Energy Albuquerque Operations Office Los Alamos Area Office Los Alamos, New Mexico 87545

Dear Mr. Gurule:

This responds to your letter dated August 6, 1998, requesting our review and concurrence with the Threatened and Endangered Species Habitat Management Plan (HMP) for Los Alamos National Laboratory (LANL). The HMP was prepared by the LANL Ecology Group for the Department of Energy (DOE) as part of the Dual-Axis Radiographic Hydrodynamics Test Facility (DAHRT) Mitigation Action Plan. The U.S. Fish and Wildlife Service (Service) has worked closely with LANL in the development of the HMP. As a result of discussions and meetings following the August 6, 1998, submittal, additional information/clarification was provided via letters, updated Biological Evaluations/HMPs, and e-mail messages, dated September 8, October 20, November 25, and December 9, 1998, and January 4, January 22, and January 29, 1999. The purpose of the HMP is to provide for the protection of threatened and endangered species and their habitats on LANL. The HMP consists of three components that must be used together to assure proper management of the threatened and endangered species: an Overview Document, Site Plans, and Monitoring Plans. It was determined that if all the restrictions and protective measures outlined in the HMP are strictly followed, the implementation of this HMP may affect, but is not likely to adversely affect the Mexican spotted owl (owl), peregrine falcon (falcon), bald eagle (eagle), and southwestern willow flycatcher (flycatcher). The Biological Evaluation (BE) also considered potential impacts on the black-footed ferret, arctic peregrine falcon, and whooping crane. It was determined that there would be no effect on these species because of a lack of habitat.

Property at LANL varies from remote isolation to heavily developed and/or industrialized. The Service agrees, as stated in the Overview document, that a number of activities at LANL have the potential to adversely impact threatened and endangered species. Many of the industrial processes used at LANL have involved hazardous and radioactive materials. These materials as well as remediation of potential release sites may disturb

or reduce population viability of threatened and endangered species. In addition, other potential sources of disturbance or habitat alterations are possible as a result of the residential and commercial development in the LANL area. While the HMP identifies potential sources of adverse effects, this consultation does not necessarily cover all of those impacts. The Service does not anticipate that DOE will be able to plan all of its operations at LANL in accordance with this plan. The direct effects of most actions can be minimized through implementation of the HMP; however, a more thorough assessment is necessary to adequately evaluate the indirect and cumulative impacts of all actions that are funded, authorized, and permitted by DOE, as well as potential impacts from interrelated and interdependent actions. It was agreed (by Service, DOE, and LANL personnel) that consultation concerning ongoing LANL operations would be handled separately from the HMP, under the consultation on the Site-Wide EIS.

The Site Plans identify the particular areas of LANL where operations might impact known occupied or potential habitat for the flycatcher, eagle, falcon, and owl. Suitable habitat for these species, along with protective buffer areas surrounding their habitat, have been designated as Areas of Environmental Interest (AEIs). For the flycatcher, one AEI was established based on an observation of a migrant male flycatcher in 1997. The AEI is located in the Pajarito wetland area and includes the best available riparian habitat. For eagles, one AEI has been identified for wintering habitat that exists along the Rio Grande on the eastern edge of LANL. It is based on the locations of known and potential roost sites. For the falcon, four AEIs have been identified. They consist of the habitat previously identified under the 1985 interagency agreement. These areas are centered on deep canyons on the eastern side of LANL or on adjacent lands. LANL has agreed to implement the recommended management guidelines, which utilize four management zones (A through D) to protect nesting peregrine falcons from disturbance. For the owl, six AEIs have been identified, but only one of these sites is known to be occupied. These AEIs are based on and located in canyons that have been defined as suitable nest/roost habitat.

The AEI management section of each Site Plan provides guidelines for LANL operations to reduce or eliminate threats to each species. The primary threats on LANL property are (1) impacts on habitat quality from LANL operations and (2) disturbance of nesting or roosting birds. The site plans provide information on their location and guidelines for their management. The AEI Site Plans consist of a species description, descriptions of the AEIs for the species, descriptions of current impacts in the AEIs, management plans that describe allowable activities within core and buffer areas under the guidelines of the sites plan and protective measures. Activities discussed in the site plans include day to day activities, such as access into an AEI, as well as long-term projects, such as levels of habitat alteration in the buffer area of an AEI. Restrictions will be implemented on activities that could cause disturbance (people, vehicles and machinery, aircraft, light production, and noise) within occupied AEIs. The location of a potential disturbance activity within the AEI, the occupancy status of the AEI, and the type of activity all affect whether or not an activity is allowable. Habitat alterations are always restricted in core areas, but a limited amount of future development is allowed in currently undeveloped DOE-controlled buffer areas under the guidelines of this site plan as long

as it does not alter habitat in the undeveloped AEI (including light and noise guidelines). The purpose of buffer areas is to protect core areas from undue disturbance or habitat alteration or habitat degradation. Each AEI is specific to the situation or circumstances of the site it covers. According to the HMP, development beyond the cap established for each AEI, or greater than 2 hectares in size, including the developed-area border, requires independent review for ESA compliance.

Varying amounts of development and/or ongoing activities exist in the cores and buffers of each AEI. These developments may include residential, commercial, and light industrial areas, as well as roads and utility corridors. Existing/ongoing activities may include periodic scientific surveys, power line maintenance, recreational use, residential development, ER Program activities, and possible use of a firing site. Potential disturbance may be associated with automobile and truck traffic, construction activities, a live-fire range, explosives testing, and aircraft traffic at the County airport. Ongoing activities in developed areas constitute a baseline condition for the AEIs and are not restricted. New activities including further development within already existing developed areas are not restricted unless they impact undeveloped portions of an AEI core. If a proposed action within a developed area does not meet site plan guidelines, it must be individually reviewed for ESA compliance.

Some activities such as utility corridor maintenance, fuels management, and a limited amount of development are allowed in each AEI (as described in the HMP). The potential impacts of these activities are considered to be insignificant or discountable because they will occur in habitat that has been previously disturbed or is of poor quality due to its size or proximity to already developed areas. It is our understanding (based on the January 22, 1999, e-mail response from Terry Foxx) that the fuels management activities within the owl AEIs will only consist of ongoing and proposed fire protection activities around existing facilities (e.g. thinning around buildings) or those activities that are already covered under the Dome Fire Emergency BA. The other fire management activities mentioned in the HMP will go through the ESH-ID process and further consultation with the Service when a fire management plan is completed in the future.

In general, activities that detrimentally alter habitat in an AEI or would cause unacceptable disturbance to the species inhabiting the AEI are not allowed under the guidelines of a Site Plan. The Site Plans are designed to minimize impacts to threatened and endangered species and their habitat. The protective measures and restrictions outlined in the Site Plans were developed using the best available data, in cooperation with Service biologists.

The U.S. Fish and Wildlife Service concurs with DOE's determination that implementation of LANL's HMP may affect, but is not likely to adversely affect the Mexican spotted owl, American peregrine falcon, bald eagle, and southwestern willow flycatcher based on the protective measures described in the BA and HMP. If all the restrictions and protective measures outlined in the HMP are strictly followed, potential impacts on owls, falcons, eagles, and flycatchers are expected to be insignificant or

discountable for the following reasons: 1) appropriate seasonal restrictions will be implemented to avoid disturbance to potentially breeding flycatchers, peregrines, and owls and wintering eagles; 2) no nest or roost habitat for any listed species will be altered; 3) the total amount of potential foraging habitat that could be impacted within each species home ranges is expected to be insignificant compared to the amount of available foraging habitat throughout the area; 4) monitoring plans have been developed as an integral part of the HMP; and 5) a mechanism for incorporating necessary technical and regulatory changes and updating the HMP has been included (page 32 of the Overview Document).

In future communications regarding this project, please refer to Consultation #2-22-98-1-336. If we can be of further assistance, please contact Carol Torrez of my staff at (505) 346-2525, ext. 115.

Sincerely,

Jennifer Fowler-Propsi

Field Supervisor

cc:

Teralene Foxx, Project Manager, Ecology Group, Los Alamos National Laboratory, P.O. Box 1663, Mail Stop M887, Los Alamos, New Mexico 87545
Elizabeth Withers, U.S. Department of Energy, Los Alamos Area Office, 35th Street, Los Alamos, New Mexico

Field Supervisor, Ecological Services, U.S. Fish and Wildlife Service, Phoenix, Arizona



United States Department of the Interior

FISH AND WILDLIFE SERVICE

New Mexico Ecological Services Field Office 2105 Osuna NE Albuquerque, New Mexico 87113 Phone: (505) 346-2525 Fax: (505) 346-2542

December 9, 2013

Cons. #02ENNM00-2014-I-0014

Geoffrey L. Beausoleil, Acting Manager National Nuclear Security Administration, Los Alamos Field Office Department of Energy Los Alamos, New Mexico 87544

Dear Mr. Beausoleil:

Thank you for your biological assessment entitled, "Biological Assessment of the Effects of Implementing the Jemez Mountains Salamander Site Plan on Federally Listed Threatened and Endangered Species at Los Alamos National Laboratory" (BA); the request for informal consultation and conferencing received on July 25, 2013 and supplemental information supplied in the "Jemez Mountains Salamander (Plethodon neomexicanus) Los Alamos National Laboratory (LANL) Site Plan" (Site Plan); and emails dated November 19 and December 3. 2013. The Department of Energy (DOE) requested concurrence with the determination of effects for the endangered Jemez Mountains salamander (Plethodon neomexicanus) (salamander) pursuant to Section 7(a)(2) of the Endangered Species Act of 1973 (ESA), as amended (16 U.S.C. § 1531 et seq.). Your proposed action consists of implementing the Site Plan, and includes of the incorporation of this Site Plan into LANL's Habitat Management Plan (HMP). The HMP was consulted upon in 1999 (Consultation #2-22-981-336) as the primary mechanism to ensure compliance with the ESA at LANL. The actions described in the Site Plan and analyzed in the BA, and supplemental emails are hereby incorporated by reference. You determined that implementing the Site Plan "may affect, is not likely to adversely affect" the salamander, and includes placing restrictions on certain types of work in areas identified as core habitat for the salamander on LANL property with the purpose of ensuring that effects to the salamander from those actions identified in the Site Plan are insignificant and discountable.

The Site Plan does not include any areas within designated salamander critical habitat, indicating that no critical habitat will be affected. The Site Plan has modeled and field validated the model to identify the areas on LANL property with the highest potential to be occupied by salamanders based on habitat features for the salamander. Each area identified by the modeling is termed "Area of Environmental Interest" (AEI) and consists of a "core area" and a "buffer area". The core area habitat is defined as suitable habitat where the salamander occurs or may occur at LANL. The core area habitat consists of sections of north-facing slope that contain the required

micro-habitat to support salamanders. The buffer area is 328 feet (100 meters) wide extending outward from the edge of the core area. Only the Los Alamos Canyon AEI is known to be occupied based on surveys. Surveys for the salamander are known to have a very low detection rate for occupied areas and DOE has assumed that all AEIs at LANL are occupied at all times by the salamander.

Within the Site Plan, DOE has assessed activities that could cause habitat alteration and includes any action that alters the soil structure, vegetative components necessary to the species, water quality, or hydrology in undeveloped areas of an AEI. If an activity were to take place outside of the AEI the activity will be assessed if it will have effects inside the AEI core. Within the core areas, only activities specified within the Site Plan and those that have no effect in the core areas (e.g. no habitat alterations or effects within the core areas) will be conducted without further consultation with the Service. Habitat alterations also include soil pits for soil samples deeper than 6 inches (15.2 centimeters) using either hand or mechanized augers. Within the Site Plan, DOE is proposing fuels management practices to reduce wildfire risk and maintenance of utility corridors within the AEIs. The likelihood that salamanders may be affected by the actions in the Site Plan is very low. To ensure that effects to the salamander are insignificant and discountable, the Site Plan incorporates the following conservation measures as restrictions to the identified work:

Fuels Management Practices to Reduce Wildfire Risk

- a. Within undeveloped core areas, thinning trees to a level of 80% canopy cover or higher may occur; tree thinning below 80% canopy cover is not part of the action under this consultation.
- b. Large logs on the ground will be left in place and not chipped.
- c. Large trees that are felled will be left as large logs on the ground
- d. When appropriate, smaller trees and understory shrubs that may be thinned will be dispersed and left on-site to aid in soil moisture retention.
- e. In buffer areas, thinning of trees may occur to the current LANL-approved prescription level; clear-cutting will not occur.
- f. Thinning activities will not occur during the rainy season when salamanders are surface active, between July 1 October 31. Thinning activities may occur earlier in October if freezing temperatures are present.
- g. In the unlikely event that a salamander is observed surface active during thinning activities, all activities shall cease, and the Service will be notified.

Utility Corridors

- a. Cutting trees that threaten power lines may occur within 26 feet (8 meters) of either side of an existing utility line at LANL
- b. New utility lines and utility lines requiring clearance of a right-of-way greater than 52 feet (16 meters) total in core habitat is not part of the action under this consultation.

Habitat alterations other than the fuels management practices and utility corridor maintenance described above will not occur in undeveloped core areas under the guidelines of the Site Plan or this consultation. The Service concurs with DOE's determination regarding the salamander for the following reasons:

Within the Site Plan, DOE has placed the above detailed restrictions to ensure that any effects to the salamander and its habitat remain insignificant and discountable. Canopy cover will remain at 80% or greater in undeveloped core areas and fire management actions will occur outside of the salamander surface activity period. Maintaining utility line corridors in areas with existing infrastructure (the utility lines) by removing individual hazard trees is not expected to have any measurable effect on salamanders or their potential habitat. Consequently, we concur that potential effects to the salamander from the proposed action will be insignificant and discountable.

This concludes section 7 consultation regarding the proposed action. If monitoring or other information results in modification or the inability to complete all aspects of the proposed action, consultation should be reinitiated. Please contact the Service if: 1) future surveys detect listed, proposed or candidate species in habitats where they have not been previously observed; 2) the proposed action changes or new information reveals effects of the proposal to listed species that have not been considered in this analysis; or 3) a new species is listed or critical habitat designated that may be affected by the action.

Thank you for your concern for endangered and threatened species and New Mexico's wildlife habitats. In future correspondence regarding this project, please refer to consultation #02ENNM00-2014-I-0014. If you have any questions, please contact Michelle Christman of my staff at (505) 761-4715.

Sincerely,

Wally Murphy Field Supervisor

CC:

Wildlife Biologist, Cuba Ranger District, Cuba, NM (Attn: Ramon Borrego) Director, New Mexico Department of Game and Fish, Santa Fe, New Mexico



United States Department of the Interior



FISH AND WILDLIFE SERVICE

New Mexico Ecological Services Field Office 2105 Osuna Road NE Albuquerque, New Mexico 87113 Telephone 505-346-2525 Fax 505-346-2542 www.fws.gov/southwest/es/newmexico/

August 6, 2015

Cons. # 02ENNM00-2015-I-0538

Kimberly Davis Lebak, Manager Department of Energy National Nuclear Security Administration Los Alamos Field Office Los Alamos, New Mexico 87544

Dear Ms. Lebak:

This responds to your July 9, 2015, cover letter and biological assessment (BA) requesting informal consultation for the addition of the Western distinct population segment of the yellow-billed cuckoo (*Coccyzus americanus occidentalis*) (cuckoo) and the New Mexico meadow jumping mouse (*Zapus hudsonius luteus*) (jumping mouse) to the Los Alamos National Laboratory Habitat Management Plan, Los Alamos, New Mexico. As documented in your BA, which is hereby incorporated by reference, we find that your proposed action will have insignificant and discountable effects to the cuckoo and the jumping mouse. Therefore, the Service concurs with your determination of "may affect, is not likely to adversely affect" for the cuckoo and the jumping mouse.

This concludes section 7 consultation regarding the proposed action. If monitoring or other information results in modification or the inability to complete all aspects of the proposed action, consultation should be reinitiated. Please contact the Service if: 1) future surveys detect listed, proposed or candidate species in habitats where they have not been previously observed; 2) the proposed action changes or new information reveals effects of the proposal to listed species that have not been considered in this analysis; or 3) a new species is listed or critical habitat designated that may be affected by the action.

Thank you for your concern for endangered species and New Mexico's wildlife habitats. If you have any questions, please contact Eric Hein of my staff at the letterhead address or at (505) 761-4735.

Sincerely,

ERIC

HEIN

for Wally Murphy Field Supervisor

cc:

Director, New Mexico Department of Game and Fish, Santa Fe, New Mexico

ENCLOSURE 3

Multi-Sector General Permit (MSGP) Notice of Intent (NOI) Reporting Pursuant to Part B.12.H

ADESH-16-045

LA-UR-16-21721

Date:	MAR 2 2 2016



Environmental Protection Division Environmental Compliance Programs (ENV-CP) PO Box 1663, K490 Los Alamos, New Mexico 87545 (505) 667-0666

Date:

OCT 2 9 2015 Symbol: ENV-DO-15-0309

LA-UR: 15-28383

Locates Action No.: N/A

Mr. Brent Larsen Water Quality Protection Division (6WQ) U.S. Environmental Protection Agency, Region 6 1445 Ross Avenue, Suite 1200 Dallas, TX 75202-2733

Dear Mr. Larsen:

Subject:

National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Notice of Intent (NOI) Reporting Pursuant to Part B.12.H.

In submitting a NOI for coverage under the new NPDES Multi-Sector General Permit, Los Alamos National Security (LANS) experienced significant problems with EPA's NeT NPDES eReporting Tool which resulted in certification of the NOI on September 3 and initial submission of a NOI with incomplete outfall attribute data and incorrect information. During this time LANS staff contacted EPA's NOI Processing Center for support and was given the recommendation to contact Region 6 personnel for further guidance. Per this direction, on September 1, 2015, Terrill Lemke left you a voicemail summarizing the issues and potential impacts of the difficulties experienced with the new electronic reporting system. For additional clarification, the following is a summary of the timeline of events associated with the NOI submission.

- Monday, August 31, 2015
 - o Initiated NOI submission using the NeT NPDES eReporting Tool.

Mr. Brent Larsen ENV-DO-15-0309

-2-

- As data was entered into each data field on the NOI form, the Tool was very slow in processing the data and allowing entry into the next field. This created a significant waiting time.
- Upon reaching the fields on the NOI form where outfall attribute data was entered the Tool began to randomly crash, repeatedly deleting all unsaved data.

Tuesday, September 1, 2015

- o Tool continued to be very slow and randomly crash, repeatedly deleting all unsaved data.
- o For each outfall, when listing the constituents associated with impaired waters, the Tool's auto population feature initially displayed incorrect data which required additional editing and then eventually stopped functioning and caused the Tool to crash.
- Much of the outfall attribute data had to be reentered multiple times before it was possible to successfully save it to the system.
- After each save or Tool crash the eReporting Tool would close the NOI form. The time required for the Tool to repeatedly reopen the form made data entry very time consuming.
- LANS staff contacted the EPA NOI Processing Center on the afternoon of Sept 1 for technical support:
 - NOI Processing Center staff stated that they had been "flooded" with calls over the past week on Tool problems.
 - LANS staff expressed their concern about the length of time being required to enter data and the potential inability to complete the NOI form by the Sept 2 deadline. No solution was available.
 - LANS staff explained the difficulty with entering outfall information for 73 outfalls and NOI Processing Center staff stated that they had received numerous calls on problems with entering outfall data and that some permittees couldn't even enter 20 outfalls.
 - NOI Processing Center staff recommended contacting Regional personnel to notify them of the situation and to seek additional guidance.
- The eReporting Tool went down at approximately 3:30 pm MDT and remained down until after 9 pm MDT. This eliminated the opportunity to input data during normal business hours.

• Wednesday, September 2, 2015

- o Continued decrease in the performance of the eReporting Tool.
 - Increase in the time for the Tool to process information after entry of each item of data.
 - Increased frequency in the Tool crashing.
 - For each outfall, when listing the constituents associated with impaired waters, the form had to be saved after entry of each individual constituent. Entry of more than one constituent without saving would cause the Tool to crash.

Mr. Brent Larsen ENV-DO-15-0309

- 3 -

- With the decreased performance of the eReporting Tool LANS staff contacted the EPA NOI Processing Center for direction and Processing Center staff stated the following:
 - They were aware of the problems with the Tool but could provide no solutions or technical direction.
 - They had been reporting daily to EPA on the problems and EPA was definitely aware of the issues.
 - When asked about taking the Tool down at 3:30 MDT on Sept. 1, staff stated that they thought the programmers may have taken the system down to assess the problems.
 - Stated again that they had received many calls about technical issues with the Tool.
 - The more data that was entered the slower the Tool would get.
 - When asked again about the possibility that LANS may not be able to get all information into the NOI, staff stated that LANS would be able to access the submitted NOI to modify/add data after the 30 day waiting period.
- eReporting Tool went down again at 3:30 pm MDT and did not come back up until after 10 pm MDT, again eliminating the opportunity to input data during normal business hours.
- The LANS NOI with all information except some remaining outfall attribute data was submitted by the Preparer at 10:50 pm MDT.
 - The LANS NOI certification signatory was prepared to certify the NOI at this time but didn't get notification that the NOI was ready for certification until 9:37 am MDT on Sept. 3, almost 11 hours later.
 - The NOI was certified on Sept 3, 2015.

Additionally, the NeT NPDES eReporting Tool did not provide dissolved Thallium as a constituent option, but only allowed the selection of total Thallium as an impaired water pollutant under a "Cause Group" when "Metals (other than Mercury)" was selected from the drop down menu. This resulted in LANS having to enter total Thallium as an impaired water pollutant in error for the following outfalls: 002, 005, 006, 007, 008, 009, 010, 011, 012, 016, 017, 018, 019, and 020. LANS appreciates any assistance you may have relative to the total Thallium vs. dissolved Thallium issue. During a subsequent quality assurance evaluation, LANS staff also determined that total Copper was erroneously entered as an impaired water pollutant for outfall 051 and needs to be deleted from the NOI.

LANS is committed to maintaining compliance with the MSGP requirements. Per Section B.12.H of the MSGP, the LANS NOI will be modified to include the remaining outfall attribute data that could not be included on the initial submission and to delete Copper as an impaired water pollutant for outfall 051. LANS coverage under the 2015 MSGP became effective on October 3, 2015, and with the NOI now accessible, actions to update the NOI have been initiated.

Mr. Brent Larsen ENV-DO-15-0309

-4-

Any additional direction or guidance you may have would be appreciated. Please contact Terrill W. Lemke & (505) 665-2397 of the Environmental Compliance Programs (ENV-CP) if you have any questions.

Sincerely.

Anthony R. Grieggs

Group Leader

Environmental Compliance Programs (ENV-CP)

Los Alamos National Security, LLC

ARG:MTS:TWL:HLW/lm

Cy: Nasim Jahan, USEPA/Region 6, Dallas, TX, (E-File)

Elifa

Bruce Yurdin, NMED/SWQB, Santa Fe, NM, (E-File)

Gene E. Turner, LASO-NS-LP, (E-File)

Jordan Arnswald, LASO-NS-PI, (E-File)

Kirsten Laskey, EM-LA, (E-File)

Craig Leasure, PADOPS, (E-File)

Amy E. De Palma, PADOPS, (E-File)

Michael T. Brandt, ADESH, (E-File)

Raeanna Sharp-Geiger, ADESH, (E-File)

Alison M. Dorries, ENV-DO, (E-File)

Michael T. Saladen, ENV-CP, (E-File)

Terrill W. Lemke, ENV-CP, (E-File)

Holly L. Wheeler, ENV-CP, (E-File)

Timothy A. Dolan, LC-ESH, (E-File)

lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

env-correspondence@lanl.gov

ENCLOSURE 4

Industrial Sites and Outfalls by Sector

ADESH-16-045

LA-UR-16-21721

Date: MAR 2 2 2016

Industrial Sites and Outfalls by Sector

Sector	Industrial Site	Monitored Outfalls	Substantially Identical Outfalls
Α	TA-3-38 Carpenter Shop	073	074
AA	TA-3-38 Metals Fab Shop	002	N/A
AA	TA-3-39 & 102 Metal Shop	004	N/A
AA, F	TA-3-66 Sigma Complex	018	013 014 015 016 017 019
AA, F	TA-3-66 Sigma Complex	020	N/A
Đ	TA-60 Asphalt Batch Plant	043	N/A
K	TA-54 Area G	051	052
K	TA-54 Area G	072	070 071
K	TA-54 Area G	053	065 066
K	TA-54 Area G	069	059 058 057 056 055 054 067 068 060 061 062 063 064
K	TA-54 Area L	050	N/A
к	TA-54 RANT	047	048 046 045 044
N	TA-60 MRF	029	N/A

Sector	Industrial Site	Monitored Outfalls	Substantially Identical Outfalls
0	TA-3-22 Power & Steam Plant	005	006
0	TA-3-22 Power & Steam Plant	009	007 008 010
0	TA-3-22 Power & Steam Plant	012	011
Р	TA-54 MFW	049	N/A
P	TA-60 Roads and Grounds	031	030
Р	TA-60 Roads and Grounds	039	038 040
P	TA-60 Roads and Grounds	036	037
Р	TA-60 Roads and Grounds	032	033 034 035
P	TA-60 Roads and Grounds	042	041
P	TA-60-1 Heavy Equipment Yard	022	021 023 024 025
Р	TA-60-2 Warehouse	026	027 028
Р	TA-60-2 Warehouse	075	N/A

N/A = Not Applicable



Associate Director for ESH ADESH P. O. Box 1663, MS K491 Los Alamos, New Mexico 87545 505-667-4218/Fax 505-665-3811

Date: APR 2 5 2016 Symbol: ADESH-16-053

LAUR: N/A
Locates Action No.: N/A

Mr. Ron Curry, Regional Administrator U.S. Environmental Protection Agency, Region 6 1445 Ross Avenue, Suite 1200 Mail Code: 6RA Dallas, TX 75202-2733

Dear Mr. Curry:

SUBJECT: Notification of Los Alamos National Security, LLC Signatory Officials and Authorized Representatives for NPDES Permits

The purpose of this letter is to provide an update to the U. S. Environmental Protection Agency (EPA) Region 6 on the Los Alamos National Security, LLC (LANS) delegation of authority for signature of documents associated with the various Los Alamos National Laboratory NPDES Permits, pursuant to 40 CFR 122.22(c). This letter supersedes and replaces the signatory authority letters dated July 17, 2013 (EP2013-0147) and August 14, 2013 (ADESH-13-041).

The positions of Associate Director and Deputy Associate Director of Environmental, Safety, and Health (ADESH) Directorate, and Division Leader of the Environmental Protection & Compliance Division (EPC-DO) are hereby identified as LANS's primary signatory officials under 40 CFR 122.22(a) for certifying and signing permit applications (including Notice of Intents (NOIs)) required under the LANL Industrial Point Source Outfall Permit (NPDES Permit No. NM0028355), the NPDES Storm Water Individual Permit (NPDES Permit No. NM0030759), the NPDES Storm Water Construction General Permit, the NPDES Multi-Sector General Permit (ID No. NMR053195), and the NPDES Pesticide General Permit (No. NMG87A041)

The following positions are hereby designated as authorized representatives under 40 CFR 122.22(b) to sign reports, Storm Water Pollution Prevention Plans, Discharge Monitoring Reports, Pesticide Discharge Management Plans, and any other compliance documentation required by the permits:

NPDES Industrial Point Source Outfall Permit (No. NM0028355)

- Positions listed as primary signatory officials above.
- Group Leader of the Environmental Compliance Programs Group.
- Responsible Facility Operations Director (FOD).



NPDES Storm Water Individual Permit (No. NM0030759):

- Positions listed as primary signatory officials above.
- Group Leader of the Environmental Compliance Programs Group.
- The Environmental Remediation Division Leader, Program Director, or Surface Water Program Manager.

NPDES Construction General Permit:

- Positions listed as primary signatory officials above.
- Group Leader of the Environmental Compliance Programs Group.
- Cognizant Project Manager, Construction Manager, or Subcontractor Technical Representative for the regulated construction activity.
- Responsible FOD; Deputy FOD; Operations Manager; or Deployed Environment, Safety, & Health Group Leader responsible for the overall operation of the regulated facility or construction activity.

NPDES Multi-Sector General Permit (ID No. NMR053195)

- Positions listed as primary signatory officials above.
- Group Leader of the Environmental Compliance Programs Group.
- Division Leader, Deputy Division Leader, or Group Leader of the LANL division responsible for the overall operation of the regulated facility or activity.
- Responsible FOD, Deputy FOD, Operations Manager, or Deployed Environment, Safety, & Health Manager responsible for the overall operation of the regulated facility or activity.

NPDES Pesticide General Permit (No. NM687A041)

- Positions listed as primary signatory officials above.
- Group Leader of the Environmental Compliance Programs Group.

Please contact John McCann, Acting Division Leader for the Environmental & Compliance Protection Division, at (505) 667-2211, if you have questions.

Sincerely,

Michael T. Brandt, DrPH, CIH

Associate Director

Environment, Safety & Health

MTB:TWL:MTS/lm

CY: Everett Spencer, USEPA, Region 6, Dallas, TX, (E-File) Brent E. Larsen, USEPA, Region 6, Dallas, TX, (E-File)



Cy (continued):

Gladys Gooden-Jackson, USEPA, Region 6, Dallas, TX, (E-File)

Bruce Yurdin, NMED/SWQB, Santa Fe, NM, (E-File)

Jody M. Pugh, NA-LA, (E-File)

Jordan Arnswald, NA-LA, (E-File)

Kirsten Laskey, EM-LA, (E-File)

David Rhodes, EM-SG, (E-File)

Craig S. Leisure, PADOPS, (E-File)

William R. Mairson, PADOPS, (E-File)

Raeanna Sharp-Geiger, ADESH (E-File)

John McCann, EPC-DO, (E-File)

Anthony R. Grieggs, EPC-CP, (E-File)

Michael T. Saladen, EPC-CP, (E-File)

Terrill W. Lemke, EPC-CP, (E-File)

Jacob W. Meadows, EPC-CP, (E-File)

Marc A. Bailey, EPC-CP, (E-File)

Deborah K. Woitte, LC-ESH, (E-File)

Tim Dolan, LC-ESH, (E-File)

Steve Veenis, ADEM-PO, (E-File)

LASOmailbox@nnsa.doe.gov, (E-File)

Emla.docs@em.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

ADESH Correspondence File, (E-File)

Epc-Correspondence@lanl.gov, (E-File

From: Medina, Louella B

To: Spencer.everett@Epa.gov; larsen.brent@epa.gov; Gooden-Jackson.gladys@epa.gov; Bruce.Yurdin@state.nm.us;

Pugh, Jody M; Arnswald, Jordan; Laskey, Kirsten McKean; Rhodes, David; Leasure, Craig Scott; Mairson, William Raymond; Sharp-Geiger, Raeanna Racine; McCann, John Phillips; Grieggs, Tony; Saladen, Michael Thomas; Lemke, Terrill W; Meadows, Jacob William; Bailey, Marc A; Woitte, Deborah Kay; Dolan, Timothy Aloysius; Veenis, Steve; lasomailbox@nnsa.doe.gov; emla.docs@em.doe.gov; locatesteam; adesh-records@lanl.gov; epc-

correspondence@lanl.gov; Martinez, Saundra; Brandt, Michael Thomas

Subject: ADESH-16-053, Notification of Los Alamos National Security, LLC Signatory Officials and Authorized

Representatives for NPDES Permits

Date: Monday, April 25, 2016 8:23:08 AM

Attachments: ADESH-16-053-R Curry, Notification of Los Alamos National Security, LLC Signatory Officials and Authorized

Representatives for NPDES Permits.pdf

Attached is the final distribution of ADESH-16-053, Notification of Los Alamos National Security, LLC Signatory Officials and Authorized Representatives for NPDES Permits.

USPS Tracking ID: ED442507151US

APPENDIX D

Non-Stormwater Discharge Certification

NON-STOR	NON-STORM WATER DISCHARGE Completed							
ASSESSME	ASSESSMENT AND CERTIFICATION Detail Strong Burgin Title: Detail Burgin Date: 8/20/15							
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Date:	8120 (15		
Date	Outfall Directly	Identify Potential	Method Used to Test	Is Non-Storm	How Often?	Describe Results from Test for		
of	Observed During	Significant Sources	or Evaluate	Water		the Presence of Non-Storm		
Evaluation	the Test (Location)	of Non- Storm Water	Discharge	Present?		Water Discharge		
8/20/15	073,074	NONE	VISUAL	NO	NIA	NONE PRESENT		
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and completed. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. Name & Official Title: Division Bussion, DEP, CISE C. Signature: Date Signed: 8(7015								
Signature:	milia -	Buen	Date Signed:	8/20/15				

APPENDIX E SWPPP Amendment Log

SWPPP AMENDMENT TRACKING LOG

Date	Plan Section	Reason for Amendment	Amendment
August 2015	All	New plan – August 2015	New SWPP plan created for facility (2015 MSGP).
January 2015	All	Annual Update (Rev 0)	Annual update. Added NOI, inspection data Oct-Dec-15, updated control measures, App G spill info, App J c/a's & BMPs, & Site Map. Updated permit #.
January 2016	All	Annual Update for 2017 (Rev 1)	Annual update for 2015 changes.
January 2017	All	Annual Update (Rev 2)	Annual update for 2016 changes.
January 2018	All	Annual Update (Rev 3)	Annual update for 2017 changes.
Mar 2019	All	Annual Update/Archive for LANS.	Change to Revision 4 and archive for LANS.

APPENDIX F

Facility Inspections:

> Kept in LANL Hard Copy TA-3, Building 1437, RM 105AG

Stormwater Industrial Routine Facility Inspection Report

	General Info	rmation					
Facility Name	TA-3-38 Carpenter's Sho	р					
NPDES Tracking No.	NMR050000						
Date of Inspection	10/22/2015 Start/End Time 11:00 a.m. / 11:15 a.m.						
Inspector's Name(s)	Jillian Burgin						
Inspector's Title(s)	DEP/CISEC						
Inspector's Contact Information	Inspector's Contact Information 665-1893						
Inspector's Qualifications	Inspector's Qualifications CISEC (See SWPPP)						
	Weather Info	rmation					
Weather at time of this inspection	?	5000 - 500 -					
☐ Clear ☐ Cloudy ☐ Rain☐ Other:	☐ Sleet ☐ Fog ☐ Sno Temperature: 45						
Have any previously unidentified discharges of pollutants occurred since the last inspection? ☐Yes ☑No If yes, describe: N/A							
Are there any discharges occurrin If yes, describe: Accumulated stor			s evident.				

Control Measures

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them
 below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with
 you during your inspections. This list will ensure that you are inspecting all required control measures at your
 facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	□Yes ☑No	☐ Maintenance ☐ Repair ☐ Replacement	This area has been noted for corrective action to cover racks or put items in storm resistant shelter.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

The annual stormwater inspection was conducted for this site on 9/14/15. Corrective Actions that were documented are as follows:

- 1) Erosion from outside of the fence to the southwest of the facility is causing sedimentation to be deposited onto the site. These repairs were made by Roads & Grounds on 9/30/15. The eroded area was repaired and stabilized with rock and the corner of the west parking lot was bermed with asphalt.
- 2) Metal on the west end of the facility needs to be covered or moved to a storm resistant shelter. Options have been looked at for covering this material. However, all options involve a considerable cost, which is not feasible with the LOG-CS budget at this time. A meeting was held (10/21/15) with ENV-CP personnel to discuss elevating the issue up to the AD level in order to acquire funding. A P2 proposal was also submitted on 10/23/15 for funding request up to 25K.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Covers for the metal and wood storage racks (on the west side of the facility) need to be obtained/fabricated; or materials need to be salvaged or moved into a storm resistant shelter.

Notes

Use this space for any additional notes or observations from the inspection:

Permit coverage under the 2015 MSGP began on October 3, 2015. The automated monitoring station (sampler) #03-0038S has been installed at Outfall #073.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title:	Phil Ron	nero, ESH Manager		
Signature:	Phil	Romer	Date:	10/28/15

Stormwater Industrial Routine Facility Inspection Report

General Information						
Facility Name	TA-3-38 Carpenter's Sho	р				
NPDES Tracking No.	NMR050000					
Date of Inspection	11/24/2015	Start/End Time	1:15-1:25p.m.			
Inspector's Name(s)	Jillian Burgin	digas carrottas 40 d	The state of the s			
Inspector's Title(s)	DEP/CISEC	otherwise and investment	administrative of the first the last the			
Inspector's Contact Information	665-1893	Thirtier L	Share Law and			
Inspector's Qualifications	CISEC (See SWPPP)					
	Weather Info	ormation				
Weather at time of this inspection? ☑ Clear □Cloudy □ Rain □ Sleet □ Fog □ Snow □ High Winds □ Other: Temperature: 51° F						
Have any previously unidentified discharges of pollutants occurred since the last inspection? ☐Yes ☑No If yes, describe: N/A						
Are there any discharges occurring If yes, describe: There is a steam causing some non-stormwater rurn gravel bags but some water is still outfall at the time of inspection.	condensate line leak at the n-on to the site. Repair to t	e southern fenceline he leak is in progre	ss and the area is protected with			

Control Measures

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with you during your inspections. This list will ensure that you are inspecting all required control measures at your facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	⊠Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	□Yes ☑No	☐ Maintenance ☐ Repair ☐ Replacement	This area has been noted for corrective action to cover racks or put items in storm resistant shelter.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair	

Structural Control Measure	Control Measure is Operating Effectively?	Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
		☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater
Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

The metal and wood storage racks were covered with tarps on 11/13/15. However, the tarps have come loose during recent storm events and need to be re-secured to cover the materials.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Permanent covers for the metal and wood storage racks need to be obtained/fabricated; or materials need to be salvaged or moved into a storm resistant shelter.

Notes

Use this space for any additional notes or observations from the inspection:

The tarps are scheduled to be re-secured on 12/7/15 when a crew can be assigned to perform the work. Materials are also in the process of being salvaged and removed from site. A meeting to discuss compliance options is scheduled for Monday, 11/30/15, as covering the area has been determined to be infeasible by LOG-CS Managers.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title:	Phil Rome	rocESH Manager		1	, /
Signature:	Jul	former	Date:	12/	1/15

	Genera	Information				
Facility Name	TA-3-38 Carpenter's Shop					
NPDES Tracking No.	NMR050000		7			
Date of Inspection	12/17/2015	Start/End Time	1:15-1:30p.m.			
Inspector's Name(s)	Jillian Burgin [With E	Bob Aitken, DSESH-ADI	PM]			
Inspector's Title(s)	DEP/CISEC	Terresia de la Caración de la companyo	Contract of Section 1970 to 187, 187, 187			
Inspector's Contact Information	665-1893	to some the state of the state	programa c - 10 - 1 ex-e	_		
Inspector's Qualifications	CISEC (See SWPP)	P) Electronical I	with the Manual A	_		
	Weather	Information .				
Weather at time of this inspection? ☐ Clear ☐ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snow ☐ High Winds ☐ Other: Temperature: 26° F (Some snow and ice present in parking lot and material storage area from recent snow storms).						
Have any previously unidentified discharges of pollutants occurred since the last inspection? □Yes ☑No If yes, describe: N/A (other than discharge listed below)						
Are there any discharges occurring at the time of inspection? Yes No If yes, describe: There is a steam condensate line leak at the southern fenceline of the site boundary, which is causing some non-stormwater run-on to the site. Repair to the leak is in progress and the excavated area is protected with gravel bags. The condensate leak has discharged to the main storm drain (Outfall #073) in the parking lot. A 7 and 15 day leak report has been provided to applicable LANL personnel and NMED.						

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with you during your inspections. This list will ensure that you are inspecting all required control measures at your facility.
- Describe corrective actions initiated, date completed, and note the person that completed the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	✓Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	□Yes ☑No	☐ Maintenance ☐ Repair ☐ Replacement	This area has been noted for corrective action to cover racks or put items in storm resistant shelter.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance	

Structural Contr Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
		☐ Repair ☐ Replacement	and the surface of th

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

The material storage area and racks do not provide sufficient coverage from stormwater as per the requirements of 2.1.2.1 of the 2015 MSGP.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Permanent covers for the metal and wood storage racks need to be obtained/fabricated; or materials need to be

Permanent covers for the metal and wood storage racks need to be obtained/fabricated; or materials need to be salvaged or moved into a storm resistant shelter.

Continue to maintain BMPs (i.e. gravel bags) around the excavated soil pile associated with the steam condensate leak at the southern boundary of the site.

Notes

Use this space for any additional notes or observations from the inspection:

Materials are in process of being salvaged and removed from site. Two storage racks have been painted with Rustoleum and will be fabricated with covers to store the remaining materials. A walk-down of the area was conducted on 12/9/15 with LOG-CS management, the LOG-MSS DEP, and ENV-CP personnel to discuss this path forward.

The steam condensate leak excavation area has become much more extensive than anticipated. It is currently infeasible to continue salvaging materials and working in the area until the leak is repaired.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title:	Phil Romero,	ESH Manager			1000
Signature:	XI	Row	_Date:	12/17	115

General Information					
Facility Name	TA-3-38 Carpenter's Sho	p			
NPDES Tracking No.	NMR053915				
Date of Inspection	1/28/2016	Start/End Time	10:00-10:15 a.m.		
Inspector's Name(s)	Jillian Burgin (with Donni	e Parrett)			
Inspector's Title(s)	DEP/CISEC				
Inspector's Contact Information	665-1893				
Inspector's Qualifications	CISEC (See SWPPP)				
	Weather Info	ormation			
Weather at time of this inspection					
☑ Clear □Cloudy □ Rain	•	ow 🚨 High Winds			
☐ Other: Temperature: 41°					
Have any previously unidentified	discharges of pollutants occ	curred since the last	inspection? □Yes ☑No		
If yes, describe: N/A					
Are there any discharges occurrin	g at the time of inspection?	□Yes ☑No			
If yes, describe: The steam conde	nsate line leak was repaire	ed on 12/23/15.			

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them
 below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with
 you during your inspections. This list will ensure that you are inspecting all required control measures at your
 facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	□Yes ☑No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been moved off site and indoors for storage/repairs and painting. All materials have been covered with tarps.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance Describe any incidents of non-compliance observed and not described above: The material storage racks are in the process of being painted and repaired (with covers); all materials in outdoor storage have been covered with tarps until the racks are completed. Additional Control Measures Describe any additional control measures needed to comply with the permit requirements: Complete painting and covering of material storage racks for storage of outdoor materials. Notes Use this space for any additional notes or observations from the inspection: The annual SWPPP update for this facility was completed on 1/28/2016. The new permit/MSGP tracking # is NMR053915. **CERTIFICATION STATEMENT** "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Print name and title: Phil Romero, ESH Manager Signature:

General Information					
Facility Name	TA-3-38 Carpenter's Sho	p			
NPDES Tracking No.	NMR053915				
Date of Inspection	2/25/2016	Start/End Time	2:15-2:25 p.m.		
Inspector's Name(s)	Jillian Burgin (with Donn	ie Parrett)			
Inspector's Title(s)	DEP/CISEC	AG. DE	40.00		
Inspector's Contact Information	665-1893				
Inspector's Qualifications	CISEC (See SWPPP)		and the second to the second t		
	Weather Info	ormation	a ke Hoody takena haro		
Weather at time of this inspection? ☐ Clear ☐ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snow ☐ High Winds ☐ Other: Temperature: 46 deg. F Have any previously unidentified discharges of pollutants occurred since the last inspection? ☐ Yes ☐ No If yes, describe: N/A					
Are there any discharges occurring If yes, describe: Some snowmelt of		☑Yes □No			

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them
 below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with
 you during your inspections. This list will ensure that you are inspecting all required control measures at your
 facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	⊠Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been painted and covered.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

100	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

The material storage racks have been painted and repaired (with covers); metal materials are currently being stored under the covered racks, remaining materials stored outside of the racks are galvanized. Bins have been constructed to store wooden forms.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Continue to keep materials properly covered/stored. Utilities will need to restabilize the disturbance area where the steam condensate leak was repaired in order to prevent erosion and soil transport onto site.

Notes

Use this space for any additional notes or observations from the inspection:

FSR #149115 was submitted on 2/22/16 for monthly (Mar-Nov) sweeping of the parking lot/yard and housekeeping.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title: Phil Romero, ESH Manager

Signature: Date: \$2/29/16

	Gener	al Information				
Facility Name	Facility Name TA-3-38 Carpenter's Shop					
NPDES Tracking No.	NMR053915					
Date of Inspection	3/29/2016	Start/End Time	9:30-9:50AM			
Inspector's Name(s)	Jillian Burgin, Cliff	Heintschel, Leonard San	doval			
Inspector's Title(s)	DEP/CISEC					
Inspector's Contact Information	665-1893	665-1893				
Inspector's Qualifications						
	Weath	er Information				
Weather at time of this inspection						
	☐ Sleet ☐ Fog	☐ Snow ☐ High Winds				
☐ Other: Temperature: 52 de						
Have any previously unidentified	discharges of polluta	nts occurred since the last	inspection? □Yes ☑No			
If yes, describe: N/A						
Are there any discharges occurring If yes, describe: N/A	Are there any discharges occurring at the time of inspection? □Yes ☑No If yes, describe: N/A					

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with you during your inspections. This list will ensure that you are inspecting all required control measures at your facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been painted and covered.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

There are still some materials in the area that need to be covered or stored indoors:

- 1) Rusted metal "ties" under the concrete blocks SW of the storage shed. These were in bags but the bags have deteriorated.
- 2) Any non-galvanized metal being stored on the south side of the storage shed.
- 3) The yellow metal "posts" being stored on the SW side of storage shed. They are painted but rusting.
- 4) The metal form posts being stored in an uncovered cart on the SW side of the storage shed near the newly constructed wooden storage boxes.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Continue to keep materials properly covered/stored. Utilities will need to restabilize the disturbance area where the steam condensate leak was repaired in order to prevent erosion and soil transport onto site. Gravel bags have currently been installed as temporary BMPs. A w/o and IWD are in process to repaye the area.

	te	

Use this space for any additional notes or observations from the inspection:

FSR #149115 was submitted on 2/22/16 for monthly (Mar-Nov) sweeping of the parking lot/yard and housekeeping.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title:	Phil Romero, ESH Manager		
Signature:	il Come	Date:	3/30/14

	General Inf	ormation			
Facility Name TA-3-38 Carpenter's Shop					
NPDES Tracking No.	NMR053915				
Date of Inspection	4/27/2016	Start/End Time	11:10-11:20AM	9	
Inspector's Name(s)	Leonard Sandoval				
Inspector's Title(s)	DEP/CISEC	- 5%			
Inspector's Contact Information	667-3557 or 231-1235				
Inspector's Qualifications	CISEC (See SWPPP)				
	Weather In	formation	in a superior superior bar		
Weather at time of this inspection ☐ Clear ☐ Partly Cloudy ☐ R ☐ Other: Temperature: 63 dec	ain □ Sleet □ Fog g. F	☐ Snow ☐ High V		⊠No	
Have any previously unidentified of If yes, describe: N/A	discharges of pollutants of	curred since the last	inspection? The res	MNO	
Are there any discharges occurrin If yes, describe: N/A	g at the time of inspection	? □Yes ☑No	F-75 - 27-1		

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with you during your inspections. This list will ensure that you are inspecting all required control measures at your facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been painted and covered.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

	Non-Compliance
l	Describe any incidents of non-compliance observed and not described above:
l	The materials in the storage yard have been covered.
I	
ı	
ı	
l	
l	
l	
I	
L	
	Additional Control Measures
	Describe any additional control measures needed to comply with the permit requirements:
l	Continue to keep materials properly covered/stored. Utilities has repaved and stabilized the disturbance area where
l	the steam condensate leak was repaired.
l	
l	
_	Notes
l	Use this space for any additional notes or observations from the inspection:
l	FSR #149115 was submitted on 2/22/16 for monthly (Mar-Nov) sweeping of the parking lot/yard and housekeeping.
١	Sweeping was performed the same day as the inspection 4/27/16.
l	
l	
l	
	CERTIFICATION STATEMENT
	"I certify under penalty of law that this document and all attachments were prepared under my direction or
	supervision in accordance with a system designed to assure that qualified personnel properly gathered and
	evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or
	those persons directly responsible for gathering the information, the information submitted is, to the best of my
	knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."
	raise information, including the possibility of thie and imprisonment for knowing violations.
	Print name and title: Phil Romero, ESH Manager
	\bigcap
	5/3/15
	Signature:

	General Information					
Facility Name	Pacility Name TA-3-38 Carpenter's Shop					
NPDES Tracking No.	NMR053915					
Date of Inspection	5/25/2016	Start/End Time	1:45-2:00PM			
Inspector's Name(s)	Jillian Burgin, Do	onnie Parrett present				
Inspector's Title(s)	DEP/CISEC					
Inspector's Contact Information	ector's Contact Information 665-1893					
Inspector's Qualifications	Inspector's Qualifications CISEC (See SWPPP)					
	Wea	ather Information				
Have any previously unidentified discharges of pollutants occurred since the last inspection? □Yes ☑No If yes, describe: N/A						
Are there any discharges occurring at the time of inspection? The Modern of the second of yes, describe: N/A						

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them
 below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with
 you during your inspections. This list will ensure that you are inspecting all required control measures at your
 facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been painted and covered.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	¥

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	☑Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A ·
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:
The materials in the storage yard have been covered. Remaining uncovered materials are galvanized metals only.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:
Continue to keep materials properly covered and stored. Continue monthly sweeping.

Notes

Use this space for any additional notes or observations from the inspection:

FSR #149115 was submitted on 2/22/16 for monthly (Mar-Nov) sweeping of the parking lot/yard and housekeeping. The galvanized metal forms currently being stored outdoors will be used for an upcoming project at NNSB. Utilities has repayed and stabilized the disturbance area where the steam condensate leak was repaired. The chain link fence still needs to be replaced. The sampler and Outfall #073 has been relocated to the Sternvent Cyclone and wood dust roll-off bin (as of 4/29/16).

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title: Phil Romero, ESH Manager

Signature: Date: 5/25/16

	General	Information					
Facility Name TA-3-38 Carpenter's Shop							
NPDES Tracking No.	NMR053915	,					
Date of Inspection	6/27/2016	Start/End Time	1:00-1:15 p.m.				
Inspector's Name(s)	Jillian Burgin						
Inspector's Title(s)	DEP/CISEC		. 1				
Inspector's Contact Information	665-1893						
Inspector's Qualifications	CISEC (See SWPPP)	51				
	Weather	Information	Consume de Latrobano				
Weather at time of this inspection ☐ Clear ☐ Partly Cloudy ☐ R ☐ Other: Temperature: ~83 de	ain 🗆 Sleet 🗆 Fog	g 🗆 Snow 🗀 High V	Vinds				
Have any previously unidentified of If yes, describe: N/A Are there any discharges occurring			inspection? □Yes ☑No				
If yes, describe: N/A	g at the time of hispecti	OII; CI I CS MINO					

- Number the structural stormwater control measures identified in your SWPPP on your site map and list them below (add as many control measures as are implemented on-site). Carry a copy of the numbered site map with you during your inspections. This list will ensure that you are inspecting all required control measures at your facility.
- Describe corrective actions initiated, date completed, and note the person that completed the work in the Corrective Action Log.

	Structural Control Measure	Control Measure is Operating Effectively?	If No, In Need of Maintenance, Repair, or Replacement?	Corrective Action Needed and Notes (identify needed maintenance and repairs, or any failed control measures that need replacement)
1	Sternvent Cyclone with wood shaving roll-off bin (covered)	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	N/A
2	Scrap wood roll-off bin	□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	This has been removed from the facility.
3	Wood and metal storage area/racks	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	The racks have been painted and covered.
4	Spill control – loading and parking areas	☑Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	No vehicle spills/leaks observed during inspection.
5		□Yes □No	☐ Maintenance ☐ Repair ☐ Replacement	

Areas of Industrial Materials or Activities exposed to stormwater

Below are some general areas that should be assessed during routine inspections. Customize this list as needed for the specific types of industrial materials or activities at your facility.

	Area/Activity	Inspected?	Controls Adequate (appropriate, effective, and operating)?	Corrective Action Needed and Notes
1	Material loading/unloading and storage areas	☑Yes □No □ N/A	⊠Yes □No	N/A
2	Equipment operations and maintenance areas	□Yes □No ☑ N/A	□Yes □No	N/A
3	Fueling areas	□Yes □No ☑ N/A	□Yes □No	N/A
4	Outdoor vehicle and equipment washing areas	□Yes □No ☑ N/A	□Yes □No	N/A
5	Waste handling and disposal areas	□Yes □No ☑ N/A	□Yes □No	N/A
6	Erodible areas/construction	□Yes □No ☑ N/A	□Yes □No	N/A
7	Non-stormwater/ illicit connections	□Yes □No ☑ N/A	□Yes □No	N/A
8	Salt storage piles or pile containing salt	□Yes □No ☑ N/A	□Yes □No	N/A
9	Dust generation and vehicle tracking	□Yes □No ☑ N/A	□Yes □No	N/A
10	(Other)	□Yes □No □ N/A	□Yes □No	
11	(Other)	□Yes □No □ N/A	□Yes □No	
12	(Other)	□Yes □No □ N/A	□Yes □No	

Non-Compliance

Describe any incidents of non-compliance observed and not described above:

 Hand sweeping needed: There is accumulation of debris around the sampler tubes located on the north side of the Sternvent Cyclone/wood dust bin. There is also an accumulation of trash and debris near the dumpsters and the south side of yard.

CS Yard:

- 2) Cover (move into covered storage): the metal posts being store on top of the grey cart and cinderblocks.
- 3) Cover (move into covered storage): the box of metal ESH-17 signs being store at the SE side of the storage shed. The box is starting to fall apart.
- 4) Cover (re-cover) the wooden and metal posts being stored in the metal cart on the far SE side of yard.

Additional Control Measures

Describe any additional control measures needed to comply with the permit requirements:

Continue to keep materials properly covered and stored. Continue monthly sweeping. Sweeping is scheduled for 6/29/16.

Notes

Use this space for any additional notes or observations from the inspection:

The chain link fence at the southern boundary of the facility has been replaced. A meeting will be scheduled with LOG-HERG and ENV-CP to determine if berming should be implemented in the area as an extra run-on BMP.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name and title: Phil Romero, ESH Manager		
Signature:	Date:	6/30/16

Los Alamos National Lab

Work Order MSGP-56657

MSGP Monitoring Stations Printed 7/27/2016 - 12:30 PM

M	ain	ter	an	ce	De	tai	S

Requested By: Banar, Alethea on 7/27/2016 12:27:00

MSGP Stormwater Procedure: Industrial Routine

Facilty Inspection (EPC-CP-Form-

1020.1) 7/26/2016

Last PM: Project:

Routine Facility

Inspections 7-25-16 (P-MSGP-4982)

Reason: MSGP Routine Facility Inspection

Special Instructions: NMR053195

Target: 7/31/2016 MSGP Program Priority/Type: / New Installation ₩ RG121.9

Department: Utilities and ♣ TA-3-38 Carpenter Shop

Infrastructure

Contact: Banar, Alethea

Phone: 665-0454

asks			7155				
#	Description	Rating	Meas.	Initials	Failed	N/A	Complete
Neath	ner Information						
20	Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F°) in the "Reading" field of this line.	78° Clo	udy, rea	centra.	~	Г	F
Vithin	the Facility Boundary						
40	Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe:	at					
50	If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0)				- Jal		
30	Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0)						T/
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0)						
	Il Inspection needed maintenance and repairs, faile rective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of	d control m	easures tha	nt need rep	lacement	t, or a	description
90	Erosion? (Range: 0 - 0)				7 2	<u></u>	П
100	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)				П	<u></u>	
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)			r gr			Ti-
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0)					[v	
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: -0)	0				<u>r</u>	
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)						

160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)	page.	party.	
100			d	1
	Asphalt Berm [0300503040002] If "Failed", is control measure in need of maintenance, Repair, or			
170	Replacement?	- G	Б	Ti-
	Rip Rap [0300504060001] Control Measure is			
180	operating effectively? (Range: 0 - 0)		1,3	~
	Rip Rap [0300504060001] If "Failed", is control			
190	measure in need of maintenance, Repair, or Replacement?			
190	Replacement?		- 4	100
	Activity exposed to stormwater (identify needed mainteance or a description)	ription of corrective ac	tions in r	elevant
ask c	omment).			
210	Material loading/unloading and storage areas inspected?		_	
10	Area/Activity controls adequate (appropriate,		- sal	15
220	effective, and operating)? (Range: 0 - 0)			
230	Transfer areas for substances in bulk inspected?			
	Area/Activity controls adequate (appropriate,		1	
240	effective, and operating)? (Range: 0 - 0)		Г	
	Produce/chemical storage areas (raw material)			10
250	inspected?		-8	
	Area/Activity controls adequate (appropriate,			Tien, 8
260	effective, and operating)? (Range: 0 - 0)	D. W.L.	1	T
	Liquid tank storage/secondary containment		/	
270	inspected?	<u> </u>		al l
200	Area/Activity controls adequate (appropriate,		-/	
280	effective, and operating)? (Range: 0 - 0)	4		4
290	Industrial processing and finished product storage areas inspected?			TE
	Area/Activity controls adequate (appropriate,	3	- 18	-
300	effective, and operating)? (Range: 0 - 0)		Б	Ti-
	Equipment operation and maintenance areas			
310	inspected?		F	4
	Area/Activity controls adequate (appropriate,		0	
320	effective, and operating)? (Range: 0 - 0)	al —		
330	Fueling areas inspected?			a
	Area/Activity controls adequate (appropriate,		/	
340	effective, and operating)? (Range: 0 - 0)			4
350	Outdoor vehicle and equipment washing areas		-/	_
330	inspected?		<u> </u>	14
360	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
370	Machinery inspected?			. 48
	Area/Activity controls adequate (appropriate,		10	1.4
380	effective, and operating)? (Range: 0 - 0)	E E	F/	
390	Waste handling and disposal areas inspected?		[-	
	Area/Activity controls adequate (appropriate,		28 11	
400	effective, and operating)? (Range: 0 - 0)		T	
410	Erodible areas/construction inspected?f			
	Area/Activity controls adequate (appropriate,			
420	effective, and operating)? (Range: 0 - 0)		F	- 4
	Locations and sources of run-on to the site			
430	inspected?		-6	
140	Area/Activity controls adequate (appropriate,		1 3 0	
140	effective, and operating)? (Range: 0 - 0)	<u>a</u>		-
50	Non-stormwater/illicit connections inspected?	2	V	al
160	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		-/	

470	Salt storage piles or pile containing salt inspected?		
480	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	4_ 16	
490	Dust generation and vehicle tracking inspected?		
500	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		
510	Housekeeping (Industrial materials/residues/trash in contact with stormwater) inspected?	<u> </u>	
520	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	<u></u>	
530	Leaks and spills inspected?		
540	Area/Activity controls adequate (appropriate,		
550	Sector A [03005-] Wood processing, transport or treated wood storage areas inspected?		/
560	Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)?		
Non-C	Compliance		
580	Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0)	*	
A al alias	onal Control Measures		
Additi	Are permit requirements satisfied with existing control measure(s) not associated with any of the above?		
600	(Range: 0 - 0)		
ahor	Report 10/A		
-ub01	No port		
Comp	leted: Failure:		
	The state of the s		
Repor	τ:		
-	1 - 14 - 17 - 17 - 17 - 17 - 17 - 17 - 1		*

			5 200,55 30 21 22

WO ID: 5465	7	Page \(\frac{\frac{1}{2}}{2}\) of \(\frac{1}{2}\)		
Signature (lead inspector):	Delien	- Buzin	Date and Time:_	7/29/14
		CERTIFICATION STAT	EMENT	
accordance with a system Based on my inquiry of th information, the information	designed to assure that e person or persons w on submitted is, to the	ho manage the system, or t	rly gathered and evaluate hose persons directly resp belief, true, accurate, and	d the information submitted. consible for gathering d complete. I am aware that
(Signatory must meet de	finition in Section B.	11.A, eg., FOD, Ops Mgr	, DSESH Group Leader,	EPC Group Leader)
Print name and title:	fhil?	Romens,	Group Le	s n de
Signature:	Pai A	2	Date: 7/29	116

Los Alamos National Lab - ADESH

-Maintenance Details

140

Work Order MSGP-RI-58489

MSGP Routine Inspection Printed 8/29/2016 - 10:05 AM

Requested By: Banar, Alethea on 8/29/2016 10:00:00 AM Taken By: Banar, Alethea Procedure: MSGP Stormwater Industrial Routine Facilty Inspection (EPC-CP-Form-1020.1) Last PM: 7/26/2016		8/29/2016 10:00:00	Target: Priority/Type: Department:			MSGP	.9	ter Shor		
			Infrastructure		TA-3-38 Carpenter Shop Contact: Banar, Alethea Phone: 699-5836					
Reaso	n: Month	nly Routine Facility Insp	ection at TA-3-38	Carpenter Shor	0					
Monit	oring Peri	iod:	Odor:							yu i
Clarity	y:		Settled Solids							
Suspe	ended Sol	ids:								
Specia	al Instruc	tions: NMR053195								
					1.	Insp.	8/29	116	1:15	P
Tasks			7			ny.	010			=
#	Descri	ption		Rating	Meas.	Initials	Failed	N/A	Complete	8
Weatl	her Inform	nation								
20	Weath	be the weather at time of er lookup table. If "Othe otion in task comments of the "Re operature (F°) in the "Re	r" is chosen, provi of this line. Docum	de ent	670	PIC	Б	Fa .		
Within	n the Faci	lity Boundary				W 1511	5 E			
40	Is the f	acility free of new disch ccurred since the last in						Б		
50		illed" has a CAR been p new discharge? (Range		for	- Willy					
60		acility free of discharge inspection? If "Failed"						Б	[Z/	
70	polluta	acility free of evidence onts entering the drainage: (Range: 0 - 0)								
Outfa of cor	II Inspecti	ion needed maintenan ctions in relevant task	ce and repairs, fa	ailed control m	easures th	at need rep	lacement	t, or a de	escription	
90	Monito	ored Outfall [073] Free n? (Range: 0 - 0)						V	TUDO	')
100		red Outfall [073] Flow ing Effectively? (Range		es				F/		
110		ored Outfall [073] Free nts in Discharges and/o :: 0 - 0)		?				Б		
120		intially Identical Outfa ce of Erosion? (Range:								
		intially Identical Outfa ation Devices Operating		ge: 0						

Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)

	ol Measures (identify needed maintenance and repairs, failed control ription of corrective actions in relevant task comments).	measures that need rep	olacment,	or a
160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)			
100	Asphalt Berm [0300503040002] If "Failed", is	4	1.41	
170	control measure in need of maintenance, Repair, or Replacement?		F	12
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)		<u> </u>	
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?		G/	
	Activity exposed to stormwater (identify needed mainteance or a descreement).	ription of corrective ac	tions in re	elevant
210	Material loading/unloading and storage areas inspected?			
220	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
230	Transfer areas for substances in bulk inspected?		3	
240	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			F
250	Produce/chemical storage areas (raw material) inspected?	<u> </u>		~
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
270	Liquid tank storage/secondary containment inspected?		5	Б
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		<u></u>	
290	Industrial processing and finished product storage areas inspected?			V
300	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
310	Equipment operation and maintenance areas inspected?			
320.	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		I	
330	Fueling areas inspected?	and the state of t	[
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			d
350	Outdoor vehicle and equipment washing areas inspected?			T _o l
360	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
370	Machinery inspected?			د ا
380	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		F	
390	Waste handling and disposal areas inspected?			
400	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	La Carte	П	
410	Erodible areas/construction inspected?f			45
420	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
430	Locations and sources of run-on to the site inspected?			
440		· · · · · · · · · · · · · · · · · · ·		1

		ontrois adequate (appi operating)? (Range: 0				
450		illicit connections insp	///		Tal. D	
460		ontrols adequate (approperating)? (Range: 0				/ [
470	Salt storage piles	s or pile containing sal	t inspected?		<u> </u>	
480		ontrols adequate (approperating)? (Range: 0				/ [
490	Dust generation a	and vehicle tracking in	spected?		T ₃ E	
500	effective, and o	ontrols adequate (approperating)? (Range: 0	- 0)			/ [
510	contact with storr	ndustrial materials/resinwater) inspected?				
520		ontrols adequate (approperating)? (Range: 0				
530	Leaks and spills i					
540		ontrols adequate (approperating)? (Range: 0				
550		-] Wood processing, trage areas inspected?				
560		05-] Area/Activity contri fective, and operating		<u> </u>		
580 Addit	ional Control Meas	ements satisfied with a	existing control	were inst	alled F F	
12	around	Sampler		8/17/110.		
Labor						
Labo ı Jillian	r Burgin		Assign 8/31/20		Reg Hrs OT H	rs Other Hrs
Labor	Report					
Comp	oleted:	Failure:			9	
Repo	rt:					
(d						
× ×	Signature / Name		Date	Signature / Namo		Date
	Organica / Harrie	W.1	5414	Signature / Nami		Date

Signature (lead inspector): The Burn Date and Time: 8/29/16, 1:30 P.M.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title: Phil Romens Group LEAder

Signature: Date: 3/27/16

Los Alamos National Lab - ADESH

Work Order MSGP-RI-58816

V laintenance	Details			1 2 1		MSGP R Printed 9/2	Routine Inspection 7/2016 - 1:10 Pl
Requested By	: Banar, Alethea on 9/27/2016 1:04:00 PM	Target: 9/3 Priority/Type: / R	30/2016 Routine		MSGP P	rogram	
Taken By:	Banar, Alethea	Department: Ut				Carpenter Sho	op
Procedure:	MSGP Stormwater	Inf	rastructure				
	Industrial Routine Facilty Inspection			C	ontact: Ba	nar, Alethea	
	(EPC-CP-Form-	0		P	hone: 69	9-5836	
	1020.1)	Uns	4				
Last PM:	7/26/2016		4:	dus			
Project:	Monthly Routine Inspections 9-6-16						
	(P-MSGP-RI-5119)			1:0	000	U.V.	
Reason: MSG	P Stormwater Industrial F	Routine Facility Inspe	ection				
Monitoring Pe	riod:	Odor:					181
Clarity:		Settled Solids:					
Suspended So	lids:						
	ctions: NMR053195						
							24
Special Instruc							
Tasks———	ription		Rating	Meas.	Initials	Failed N/A	Complete
Tasks———	ription		Rating	Meas.	Initials	Failed N/A	Complete
# Desci Weather Information	ription mation ibe the weather at time of		Rating	Meas.	Initials	Failed N/A	Complete
# Desci Weather Information Descrive the second term of the second ter	ription mation ibe the weather at time of the lookup table. If "Other"	is chosen, provide		Meas.	Initials	Failed N/A	Complete
# Describer Information Weather Information Weather Weather Information Weather Information Weather Weather Information Weather Weather Information Weather Weathe	ription mation ibe the weather at time of	is chosen, provide this line, Document		Meas.	Initials	Failed N/A	Complete

have occurred since the last inspection? If "Failed", 40 If "Failed" has a CAR been previously initiated for 50 this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 -60 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" 70 describe: (Range: 0 - 0) Outfall Inspection needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of 90 Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices 100 Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? 110 (Range: 0 - 0) Substantially Identical Outfall [074] Free of 120 Evidence of Erosion? (Range: 0 - 0) 130

	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)			
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)			
Contr	ol Measures (identify needed maintenance and repairs, failed control measures that n	eed rep	lacment,	or a
descr 160	iption of corrective actions in relevant task comments). Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)	Б	Б	
170	Asphalt Berm [0300503040002] If "Failed", is control measure in need of maintenance, Repair, or Replacement?			
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)			<u>-</u>
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?			al
	Activity exposed to stormwater (identify needed mainteance or a description of correc	tive act	ions in r	elevant
task c 210	omment). Material loading/unloading and storage areas inspected?			[]/
220	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
230	Transfer areas for substances in bulk inspected?			
240	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		[·	
250	Produce/chemical storage areas (raw material) inspected?		N	
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
270	Liquid tank storage/secondary containment inspected?	á	- W	al-
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	d		
290	Industrial processing and finished product storage areas inspected?			
300	Area/Activity controls adequate (appropriate, metal on 500 and in 3 effective, and operating)? (Range: 0 - 0)	d /	Cre	HR #0
310	Equipment operation and maintenance areas inspected?	d		Ĭ.
320	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		5/	a a
330	Fueling areas inspected?			J.
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range; 0 - 0)	J.		
350	Outdoor vehicle and equipment washing areas inspected?			
360	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	- 1		
370	Machinery inspected?			V
380	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
390	Waste handling and disposal areas inspected?	ij.	~	aji
400	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
410	Erodible areas/construction inspected?f	ä	1	
420	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Б		

430	Locations and sources of run-on to the site inspected?			4	4	
440	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					
450	Non-stormwater/illicit connections inspected?				13	<u> </u>
430	Area/Activity controls adequate (appropriate,				1	
460	effective, and operating)? (Range: 0 - 0)					
470	Salt storage piles or pile containing salt inspec	ted?				
480	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					
490	Dust generation and vehicle tracking inspected					TV V
500	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			Б	1/	
510	Housekeeping (Industrial materials/residues/tracontact with stormwater) inspected?	ash in				
520	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	×			-	
530	Leaks and spills inspected?					
540	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					
550	Sector A [03005-] Wood processing, transport treated wood storage areas inspected?				4	
560	Sector A [03005-] Area/Activity controls ade (appropriate, effective, and operating)?	quate ————————			nd.	
580	Free of incidents of observed non-compliance associated with any of the above? (Range: 0 -	not 0)			- G	
Addition	Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0)			Б	<u>_</u>	
-1				4		
abor-						
L abor Jillian E	Burgin	Assigned 10/11/2016 / 14	Work Date	Reg Hrs C	OT Hrs	Other Hrs
abor I	Report-					
Comple	eted: Failure:					
Report						
					-	*****
more and a second						

WO ID: MSGP-R1-58816 Page 4 of 4

Signature (lead inspector):	_Date and Time: 9 9 1	
	p.n.	٠.
	1810	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

Print name and title:

Date:

Date:

| Comparison of the print of the

Los Alamos National Lab - ADESH

130

Work Order MSGP-RI-58984

MSGP Routine Inspection Printed 10/27/2016 - 1:22 PM

viainte	enance l	Details ————	TE THE T				State No. 10	
Reque Taken Proce	By:	Banar, Alethea on 10/18/2016 7:32:00 AM Velasquez, W. MSGP Stormwater Industrial Routine Facilty Inspection	Target: Priority/Type: Department:	10/31/2016 / Routine Utilities and Infrastructure			.9 3 Carpenter Sh anar, Alethea	ор
		(EPC-CP-Form- 1020.1)		Insp.	10/31	116		
ast P rojec		7/26/2016 ROUTINE FACILITY INSPECTIONS OCT 2016 (P-MSGP-RI- 5140)			3:00) ~ 3!1	15 p.m.	
Reaso	n: MSGF	Stormwater Industrial	Routine Facility In	spection				
Veath	er at insp	ection:						
pecia	al Instruc	tions: NMR053195						
1 2								
asks					1.0			
#	Dogori	ntion		Dating	Moss	Initials	Failed N/A	Complete
	Descri			Rating	Meas.	iniuais	Failed N/A	Complete
weatr	Weathe descrip	nation the weather at time of the weather at time of the lookup table. If "Other of the lookup table to the lookup table the	r" is chosen, provi of this line. Docum	de ient	50 p	le		-/
		EA. Double		Nagara and American				3
vvitnir 40	Is the f	lity Boundary acility free of new dischaccurred since the last in se:					ББ	<u> </u>
0		iled" has a CAR been p ew discharge? (Range:		for	S_204			
60		acility free of discharge inspection? If "Failed" o						TC/
'O	pollutar	acility free of evidence onts entering the drainages: (Range: 0 - 0)			N Valv	1		
Outfal	II Inspecti	on (needed maintenar			measures t	hat need rep	placement, or a	1
lescri		corrective actions in re		ment)				
90		red Outfall [073] Free n? (Range: 0 - 0)	or Evidence of				ББ	
00		red Outfall [073] Flowing Effectively? (Range:		es				
10		red Outfall [073] Free onts in Discharges and/onts: 0 - 0)		?				[~
20		intially Identical Outfal ce of Erosion? (Range:					6 6	

	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)			
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)			~
	ol Measures (identify needed maintenance and repairs, failed control measures that	need rep	lacment,	ora
	iption of corrective actions in relevant task comments). Asphalt Berm [0300503040002] Control Measure is			
160	operating effectively? (Range: 0 - 0)	3	- id	
170	Asphalt Berm [0300503040002] If "Failed", is control measure in need of maintenance, Repair, or Replacement?		F /	
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)	Б		[/
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?			
	Activity exposed to stormwater (identify needed mainteance or a description of correcomment).	ctive act	ions in r	elevant
lask C	Material loading/unloading and storage areas			
210	inspected? CAN # 993	[/	g	હ
220	Area/Activity controls adequate (appropriate, metal materials need effective, and operating)? (Range: 0-0) to be properly stored)	wer	ed	
230	Transfer areas for substances in bulk inspected?		8	T.
240	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		<u> </u>	
250	Produce/chemical storage areas (raw material) inspected?			[]
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			- La
270	Liquid tank storage/secondary containment inspected?			
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		[J	
290	Industrial processing and finished product storage areas inspected?	9		
300	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		[-	14
310	Equipment operation and maintenance areas inspected?			
320	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Б	F/	
330	Fueling areas inspected?			
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
350	Outdoor vehicle and equipment washing areas inspected?	Б		Б
360	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
370	Machinery inspected?	- 4		
380	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		[/	
390	Waste handling and disposal areas inspected?			
400	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		[/	
410	Erodible areas/construction inspected?f	Til.	[/	ai
420	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		T/	- E

	Locations and sources of run-on to the site inspected?			La	-31	
440	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)	, 112 = 1			F/	Б
450	Non-stormwater/illicit connections inspected?			5 2 9	C	
460	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)	,				
470	Salt storage piles or pile containing salt inspec	cted?				
480	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)	,				
490	Dust generation and vehicle tracking inspecte	d?	ni nazati			- 54
500	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)					
510	Housekeeping (Industrial materials/residues/tr contact with stormwater) inspected?	ash in				TV.
520	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)	,	it Hara ta			Б
530	Leaks and spills inspected?					1
540	Area/Activity controls adequate (appropriate effective, and operating)? (Range: 0 - 0)		S 2 C 2 D III			
550	Sector A [03005-] Wood processing, transport treated wood storage areas inspected?	t or				F
560	Sector A [03005-] Area/Activity controls add (appropriate, effective, and operating)?	equate			[-/	
580	Free of incidents of observed non-compliance associated with any of the above? (Range: 0 -				14	~
580 Additi	associated with any of the above? (Range: 0 - onal Control Measures	0)				<u>r</u>
Additi	associated with any of the above? (Range: 0 -	control				F/
Additi	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the abo (Range: 0 - 0)	control				F/
	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the abo (Range: 0 - 0)	control	Work Date	Reg Hrs (OT Hrs	F
Addition Addition I	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the abo (Range: 0 - 0)	Assigned	Work Date	Reg Hrs (OT Hrs	F
Addition Solution Sol	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0) Burgin	Assigned	Work Date	Reg Hrs (OT Hrs	F
Addition 6000 abor building for the complete com	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0) Burgin Report leted:Failure:	Assigned	Work Date	Reg Hrs	OT Hrs	F
abor- abor- abor dillian I	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0) Burgin Report leted:Failure:	Assigned	Work Date	Reg Hrs (OT Hrs	F
Addition 6	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0) Burgin Report leted:Failure:	Assigned	Work Date	Reg Hrs (OT Hrs	F .
Addition 6000 abor building for the complete com	associated with any of the above? (Range: 0 - onal Control Measures Are permit requirements satisfied with existing measure(s) not associated with any of the about (Range: 0 - 0) Burgin Report leted:Failure:	Assigned	Work Date	Reg Hrs (OT Hrs	

WO ID: MSGP-RI-58984 Page 4 of 4	
Signature (lead inspector):Date and Time: "I confirm the information as recorded is true, accurate and complete."	10/31/16 3:15 p.m.
"I certify under penalty of law that this document and all attachments were prepared under my direct accordance with a system designed to assure that qualified personnel properly gathered and evaluate Based on my inquiry of the person or persons who manage the system, or those persons directly resinformation, the information submitted is, to the best of my knowledge and belief, true, accurate, and there are significant penalties for submitting false information, including the possibility of fine and violations".	ed the information submitted. ponsible for gathering d complete. I am aware that

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title: Russell Stone, DESHS-UES Group Lealer

Signature: Date: 11/3/2016

Work Order MSGP-RI-59121

MSGP Routine Inspection Printed 11/1/2016 - 4:57 PM

Mainte	enance Details	
	dure: MSGP Stormwater Industrial Routine Facilty Inspection (EPC-CP-Form- 1020.1) Target: 11/30/2016 Priority/Type: Normal / Inspection Utilities and Infrastructure	SGP Program និះ RG121.9 ♣ TA-3-38 Carpenter Shop
Last Pi	ini *	Contact:
Projec	Nov 2016 (P-MSGP-RI-	Phone: 4 1:45-10:00 a.M.
Reaso	n: MSGP Stormwater Industrial Routine Facility Inspection	1,45-70.00 413
	er at inspection:	
	il Instructions: NMR053195	
Tasks		
Said	_	
#	Description Rating Mea	s. Initials Failed N/A Complete
Weath	ner Information	
	Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F°) in the "Reading" field of this	
20	line. 40° F	Ltrain To
Within	the Facility Boundary	2002.49
40	Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe:	
50	If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0)	
60	Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0)	
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0)	
Outfali descri	I Inspection (needed maintenance and repairs, failed control measure ption of corrective actions in relevant task comment)	s that need replacement, or a
<u>9</u> 0	Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0)	
100	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)	
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0)	
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	
	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or	
140	Receiving Water? (Range: 0 - 0)	

Contro descri	ol Measures (identify needed maintenance and repairs, failed cor ption of corrective actions in relevant task comments).	itrol measures that ne	ed rep	lacment,	ога
160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)		-1	4	[-/
170	Asphalt Berm [0300503040002] If "Failed", is control measure in need of maintenance, Repair, or Replacement?				
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)		Tac .	П	
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?				
	ctivity exposed to stormwater (identify needed mainteance or a	description of correcti	ve act		
	omment).				o to varit
210	Material loading/unloading and storage areas inspected?		E-1	П	
220	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		-		
230	Transfer areas for substances in bulk inspected?			Q.	
240	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		_		_
240	Produce/chemical storage areas (raw material)		al		4
250	inspected?		-1	(4)	Ti-
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			1	47.
270	Liquid tank storage/secondary containment inspected?		14	Ti-	4
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			~	A
290	Industrial processing and finished product storage areas inspected?		Es.		T
300	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)				
<u>310</u>	Equipment operation and maintenance areas inspected?				[
320	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)				
330	Fueling areas inspected?		4		al
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		al	<u> </u>	
<u>350</u>	Outdoor vehicle and equipment washing areas inspected?			<u> </u>	
<u>360</u>	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		III		
370	Machinery inspected?		24	ы	
380	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)				
390	Waste handling and disposal areas inspected?			-14	
400	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		<u> </u>		<u> </u>
410	Erodible areas/construction inspected?f		W.	34	Tu-
420	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		al.		Al .
430	Locations and sources of run-on to the site inspected?				-
440	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		14		
450	Non-stormwater/illicit connections inspected?		al		al
460	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		П		4

Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) 490 Dust generation and vehicle tracking inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Housekeeping (Industrial materials/residues/trash in contact with stormwater) inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Leaks and spills inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A [03006-1] Wood processing, transport or treated wood storage areas inspected? Sector A [03006-1] Wood processing, transport or treated wood storage areas inspected? Sector A [03006-1] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? 600 (Range: 0 - 0) Labor Labor Labor Completed: Failure: Report:	470	Salt storage piles or pile containing salt inspecte	ed?			al.
490 Dust generation and vehicle tracking inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Housekeeping (Industrial materials/residues/trash in contact with stormwater) inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A (03006-) Wood processing, transport or treated wood storage areas inspected? Sector A (03006-) Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned In Assigned Work Date Reg Hrs OT Hrs Other Hrs Completed: Failure: Report:	480					all'
## defective, and operating)? (Range: 0 - 0) ## Housekeeping (Industrial materials/residues/trash in contact with stormwater) inspected? ## Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) ## Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) ## Sector A [03006-] Wood processing, transport or treated wood storage areas inspected? ## Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? ## Non-Compliance ## Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) ## Additional Control Measures ## Are permit requirements satisfied with existing control measure(s) not associated with any of the above? ## Basigned	490	Dust generation and vehicle tracking inspected?			A B	
Housekeeping (Industrial materials/residues/trash in contact with stormwaler) inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Leaks and spills inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A [03006-] Wood processing, transport or treated wood storage areas inspected? Sector A [03006-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned 11/30/2016 / 14 Labor Report Completed: Failure: Report:	500					
Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) 520 Leaks and spills inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A [03005-] Wrood processing, transport or treated wood storage areas inspected? Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? 600 (Range: 0 - 0) Labor Labor Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hrs Jillian Burgin 11/30/2016 / 14	510	Housekeeping (Industrial materials/residues/tras	h in			
Leaks and spills inspected? Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A [03005-] Wood processing, transport or treated wood storage areas inspected? Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hrs Jillian Burgin 11/30/2016 / 14	520	Area/Activity controls adequate (appropriate,				1
Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0) Sector A [03005-] Wood processing, transport or treated wood storage areas inspected? Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hn Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure: Report:	530					
Sector A [03005-] Wood processing, transport or treated wood storage areas inspected? Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned 11/30/2016 / 14 Labor Report Completed: Failure:	540	Area/Activity controls adequate (appropriate,				al l
Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)? Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hn Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure: Report:	550	Sector A [03005-] Wood processing, transport of	or			<u> </u>
Non-Compliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hrs Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure: Report:	560	(appropriate officially and approximate)	uate			
Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0) Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned Mork Date Reg Hrs OT Hrs Other Hrs Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure:	Non-Cr					
Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Assigned Work Date Reg Hrs OT Hrs Other Hrs Jillian Burgin Labor Report Completed: Failure: Report:		•	ot			
Additional Control Measures Are permit requirements satisfied with existing control measure(s) not associated with any of the above? (Range: 0 - 0) Labor Labor Assigned Work Date Reg Hrs OT Hrs Other Hrs Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure: Report:	580					
Labor Jillian Burgin Assigned Work Date Reg Hrs OT Hrs Other Hrs 11/30/2016 / 14 Labor Report Completed: Failure: Report:		(Range: 0 - 0)				
Jillian Burgin 11/30/2016 / 14 Labor Report Completed: Failure: Report:	Luboi					
Labor Report Completed: Failure: Report:		urgin	11/30/2016 /			r Hrs
Report:		•				
	•					
Signature / Name Date Signature / Name Date	Report:					
Signature / Name Date Signature / Name Date	_					_
Signature / Name Date Signature / Name Date						
Signature / Name Date Signature / Name Date	-					
Signature / Name Date Signature / Name Date						
Date Date		Signature / Name Date		Signature / Name	Date	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name ar	nd title: Russell Store,	GC	DESHS-UITS		77.50
Signature:	Russell Ster		Date:	11/22/2016	

Work Order MSGP-59438

MSGP Monitoring Stations Printed 12/7/2016 - 2:12 PM

Requested: 12/6/2016 3:51:06 PM Procedure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Forn- 102011) Last PM: 7/26/2016 Project: Routine Facility Inspections Dec 2016 (P-MSGP-RI- 5158) Reason: MSGP Stormwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI- 5158) Reason: MSGP Stormwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI- 5158) Reason: MSGP Stormwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI- 5158) Reason: MSGP Stormwater Industrial Routine Facility Inspection Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of i	Maintena	ance Details					
Procedure: MSGP Stomwater Industrial Routine Facility Inspection (EPC-CP-Form-1020.1) Last PM: 7/26/2016 Project: Routine Facility Inspections Dec 2016 (P-MSGP-RI-5188) Project: Routine Facility Inspections Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-51888) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-51888) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-518888) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188888) Reason: MSGP Stomwater Industrial Routine Facility Inspection Dec 2016 (P-MSGP-RI-5188888) Reason: MSGP Stomwater Industrial Routine Facility Inspection In the Weather Industrial Routine Facility Inspection Infrastructure Routine Facility Read Routine Facility Inspection In the Weather Industrial Routine Facility Inspection Infrastructure Industrial Routine Facility Inspection Infrastructure Industrial Routine Facility I	Requeste	ed: 12/6/2016 3:51:06 PM	Target: 1	2/30/2016	MSGD E	Program	
Phone: Project: Routine Facility Inspections Dec 2016 (P-MSGP-RI- 5158) Reason: MSGP Stormwater Industrial Routine Facility Inspection Description: Rating Meas. Initials Failed N/A Complete Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F*) in the "Reading" field of this Iline. Within the Facility Boundary Is the facility fee of evidence of pollutants that have occurred since the last inspection? If "Failed", describe. If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a tescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Doutfall Inspection (re: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form-	Priority/Type: N Department: U	lormal / Inspectio	n 🚓 RG121.	9	ор
Reason: MSGP Stormwater Industrial Routine Facility Inspection Description Reason: MSGP Stormwater Industrial Routine Facility Inspection Odor: Clarity: Settled Solids: Suspended Solids: Suspended Solids: Special Instructions: NMR053195 asks # Description Description Description in task comments of this line. Document the temperature (F*) in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed" describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Frow of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Frow Dissipation Devices Operating Effectively? (Range: 0 - 0)	_ast PM:	7/26/2016					
Precipitation Type: Odor: Clarity: Settled Solids: Suspended Solids: Special Instructions: NMR053195 Asks # Description Rating Meas. Initials Failed N/A Complete Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" of describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a lescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free 20 Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Free 21 Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Free 22 Evidence of Erosion? (Range: 0 - 0)		Dec 2016 (P-MSGP-RI- 5158)	Insp:	12/19/16	e 9:15 a	.M.	
recipitation Type: Odor: clarity: Settled Solids: uspended Solids: pecial Instructions: NMR053195 Basks # Description Rating Meas. Initials Failed N/A Complete Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F*) in the "Reading" field of this line. Within the Facility Boundary Is the facility Fee of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a lescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 0 - 0)	leason:	MSGP Stormwater Industrial R	toutine Facility Insp	ection by t	tolly wheel	ler (Jii	i.an Bur
## Description Rating Meas. Initials Failed N/A Complete							
# Description Rating Meas. Initials Failed N/A Complete Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Nothall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a lescription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	larity:		Settled Solids:				
# Description Rating Meas. Initials Failed N/A Complete Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence o	uspend	ed Solids:					
Weather Information Describe the weather at time of inspection in the Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) State and the describe of the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of	Special Ir	nstructions: NMR053195					
Weather Information Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F°) in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Outfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence	asks						
Describe the weather at time of inspection in the Weather lookup table. If "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a describor of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	#	Description		Rating	Meas. Initials	Failed N/A	Complete
Weather lookup table, if "Other" is chosen, provide description in task comments of this line. Document the temperature (F") in the "Reading" field of this line. Within the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a electric of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	Neather	Information					
Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	,	Weather lookup table. If "Other" description in task comments of the temperature (F°) in the "Rea	is chosen, provide this line. Documen	it	C 23°F		
have occurred since the last inspection? If "Failed", describe: If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Outfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? 10 (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 0 - 0)	Vithin th	e Facility Boundary					
If "Failed" has a CAR been previously initiated for this new discharge? (Range: 0 - 0) Is the facility free of discharge of pollutants at the time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Dutfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence		have occurred since the last insp	ges of pollutants the pection? If "Failed"	nat ,			
time of inspection? If "Failed" describe: (Range: 0 - 0) Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Outfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Evidence of Evidence of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	50			r			
Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "Failed" describe: (Range: 0 - 0) Outfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Evi	t	time of inspection? If "Failed" de	f pollutants at the escribe: (Range: 0 -				_
Outfall Inspection (needed maintenance and repairs, failed control measures that need replacement, or a description of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Evidence of Evidence of Evidence of Evidence Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	ī	s the facility free of evidence of,		Γ,			
Monitored Outfall [073] Free of Evidence of Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)							v /
Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0) Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0	descripti I	on of corrective actions in rele Monitored Outfall [073] Free of	evant task comme	led control meas ent)	sures that need rep	lacement, or a	
Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	ı	Monitored Outfall [073] Flow D					
10 (Range: 0 - 0) Substantially Identical Outfall [074] Free of Evidence of Erosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 30 -0)	T I	Monitored Outfall [073] Free of	Evidence of			Li Li	
20 Evidence of Érosion? (Range: 0 - 0) Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? (Range: 0 - 0)	10 (Range: 0 - 0)					
Dissipation Devices Operating Effectively? (Range: 0 -0)							
	[Dissipation Devices Operating E		0			
	30 <u>-</u> 40	· U)				- <u> </u>	

Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? (Range: 0 - 0)

160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)	П	П	V
	Asphalt Berm [0300503040002] If "Failed", is			
170	control measure in need of maintenance, Repair, or Replacement?			
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)	П	П	
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?	П		П
200	EnviroSoxx w/ MetalLoxx [0300503200003] Control Measure is operating effectively?	П	П	
210	EnviroSoxx w/ MetalLoxx [0300503200003] If "Failed", is control measure in need of maintenance, Repair, or Replacement?	П		
Area/	Activity exposed to stormwater (identify needed mainteance or a description of correct comment).	tive act	tions in r	elevant
230	Material loading/unloading and storage areas inspected?		Б	
240	Area/Activity controls adequate (appropriate, Metal Stored on Scound + on effective, and operating)? (Range: 0 - 0)	5/5	de of	Shed
250	Transfer areas for substances in bulk inspected?			
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Б		
270	Produce/chemical storage areas (raw material) inspected?	Б		
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Б		
290	Liquid tank storage/secondary containment inspected?			
300	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
310	Industrial processing and finished product storage areas inspected?	П	П	
320	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	П		
330	Equipment operation and maintenance areas inspected?			
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	П		
50	Fueling areas inspected?			П
60	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
70	Outdoor vehicle and equipment washing areas inspected?			П
80	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
90	Machinery inspected?		Д	
00	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			П
10	Waste handling and disposal areas inspected?	F		V #
20	Area/Activity controls adequate (appropriate, Reflace dumpster will no start effective, and operating)? (Range: 0 - 0) Remove trash can be cover will	door	· See	CAR 10
130	Erodible areas/construction inspected?f		Е	

Comple Report:	eted: Failure: :					
	Report				(44	-
Jillian B	SUICHT	12/30/2016 / 14				
Labor		Assigned	Work Date	Reg Hrs	OT Hrs	Other Hrs
abor						
620	measures needed. (Range: 0 - 0)				-	
	Are permit requirements satisfied with existing co measure(s)? If "Failed" describe additional contro			_		JB
Non-Co 600	pmpliance Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0)	t				
580	Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)?	ate 				
570	Sector A [03005-] Wood processing, transport or treated wood storage areas inspected?					
560	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					П
550	Leaks and spills inspected?					-
540	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Dec 420	4 CAR #	1018		П
530	Housekeeping (Industrial materials/residues/trash contact with stormwater) inspected?	n in			Г	
520	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			Г		
510	Dust generation and vehicle tracking inspected?					
500	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					
480 490	effective, and operating)? (Range: 0 - 0) Salt storage piles or pile containing salt inspected	12				
470	Non-stormwater/illicit connections inspected? Area/Activity controls adequate (appropriate,					
460	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)				~	
450	Locations and sources of run-on to the site inspected?					
Madual 6	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)					

WO ID: MSGP-59438 Page 4 of 4
Signature (lead inspector): Dlan Burger, CIFC Date and Time: 12/19/16 "I confirm the information as recorded is true, accurate and complete." (w) Holly wheeler) 9:15 and.
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russell Stone GL D8545-UZS
Signatura: Reserved States

Work Order MSGP-RI-59461

MSGP Routine Inspection Printed 1/23/2017 - 11:03 AM

Mainte	nance Details							
	ure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form- 1020.1)	Priority/Type: Norr Department: Utilit	/2017 mal / Inspect ies and istructure	ion	MSGP F		hop	
Last PN					Contact:			
Project		Insp.	1/24/1-	7 @	Phone:	a.m.		
Reason	: 2017 January Inspections				10:30			
Weathe	er at inspection:							
Special	Instructions: NMR053195							
Tasks								
#	Description		Rating	Meas.	Initials	Failed N/	A C	omplete
Weathe	er Information							
	Describe the weather at time of Weather lookup table. If "Other description in task comments o the temperature (F°) in the "Rea	is chosen, provide fthis line. Document						
20	line.	ading field of this	27°F	Clos	du w	п п		
Within	the Facility Boundary			Sre	dy w/	ries		
40	Is the facility free of new dischat have occurred since the last insidescribe:							
50	If "Failed" has a CAR been pr this new discharge? (Range:							
60	Is the facility free of discharge of time of inspection? If "Failed" do 0)							
70	Is the facility free of evidence of pollutants entering the drainage describe: (Range: 0 - 0)							TV.
Outfall descrip	Inspection (needed maintenan- ption of corrective actions in re	levant task comment	control me	asures th	nat need repl	acement, or	а	
90	Monitored Outfall [073] Free of Erosion? (Range: 0 - 0)							
100	Monitored Outfall [073] Flow I Operating Effectively? (Range:	0 - 0)					(m)	
110	Monitored Outfall [073] Free of Pollutants in Discharges and/or (Range: 0 - 0)						i La Roberta	
120	Substantially Identical Outfall Evidence of Erosion? (Range: 0							
130	Substantially Identical Outfall Dissipation Devices Operating E - 0)						/	
140	Substantially Identical Outfall Evidence of Pollutants in Discha Receiving Water? (Range: 0 - 0	arges and/or			A:			-/

Contr	ol Measures (identify needed maintenance and repairs, failed control measures that ne	ed rep	lacment,	or a
descr	iption of corrective actions in relevant task comments).			
160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)	_	_	-/
100	Asphalt Berm [0300503040002] If "Failed", is			
	control measure in need of maintenance, Repair, or			
170	Replacement?	П		
43	Rip Rap [0300504060001] Control Measure is			
180	operating effectively? (Range: 0 - 0)			
	Rip Rap [0300504060001] If "Failed", is control			
7.1	measure in need of maintenance, Repair, or			
190	Replacement?		-	
200	EnviroSoxx w/ MetalLoxx [0300503200003] Control			
200	Measure is operating effectively?			
	EnviroSoxx w/ MetalLoxx [0300503200003] If "Failed", is control measure in need of			
210	maintenance, Repair, or Replacement?			_
		-		
Area/A	Activity exposed to stormwater (identify needed mainteance or a description of correct	ive act	ions in re	elevant
task c	omment).			
230	Material loading/unloading and storage areas inspected?	_	_	
200	Area/Activity controls adequate (appropriate, CAT # 1018 From 12 Police			
240	effective, and operating)? (Range: 0 - 0)		E-/-	
250	Transfer areas for substances in bulk inspected?	÷	<u> </u>	
	Area/Activity controls adequate (appropriate,	1.4		
260	effective, and operating)? (Range: 0 - 0)	П	F1	
-	Product/chemical storage areas (raw material)			
270	inspected?		П	
	Area/Activity controls adequate (appropriate,			-
280	effective, and operating)? (Range: 0 - 0)	П	D-2	Te /
	Liquid tank storage/secondary containment			
290	inspected?	П	V	
	Area/Activity controls adequate (appropriate,			3"
300	effective, and operating)? (Range: 0 - 0)			52
040	Industrial processing and finished product storage			
310	areas inspected?			
320	Area/Activity controls adequate (appropriate,	_	_	_/
320	effective, and operating)? (Range: 0 - 0)		3	
330	Equipment operation and maintenance areas inspected?	_	_	
	Area/Activity controls adequate (appropriate,	口		
340	effective, and operating)? (Range: 0 - 0)	П	r-	_/
350	Fueling areas inspected?	F	Ė-	
	Area/Activity controls adequate (appropriate,	-		
360	effective, and operating)? (Range: 0 - 0)	П	17/	
	Outdoor vehicle and equipment washing areas			
370	inspected?		-	П
	Area/Activity controls adequate (appropriate,			
380	effective, and operating)? (Range: 0 - 0)		اسمنا	
390	Machinery inspected?			
100	Area/Activity controls adequate (appropriate,			1
400	effective, and operating)? (Range: 0 - 0)	Д.		
410	Waste handling and disposal areas inspected?			-
120	Area/Activity controls adequate (appropriate, CAr + 1017 + 1019 from 12/16			_/
420	effective, and operating)? (Range: 0 - 0) Completed 1/a(17.		5.5	1
430	Erodible areas/construction inspected?			~
440	Area/Activity controls adequate (appropriate,	_		_/
440	effective, and operating)? (Range: 0 - 0)			
450	Locations and sources of run-on to the site inspected?	_	_	

460	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		-	
470	Non-stormwater/illicit connections inspected?			
480	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		TC/	П
490	Salt storage piles or pile containing salt inspected?		1	
500	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			П
510	Dust generation and vehicle tracking inspected?			-
520	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	Б	100	/
530	Housekeeping (Industrial materials/residues/trash in contact with stormwater) inspected?			
540	Area/Activity controls adequate (appropriate, CAC # 1017+ 1019 from 12 effective, and operating)? (Range: 0 - 0)	2/16	F-	-/
550	Leaks and spills inspected?			
560	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	П	Ti-	
570	Sector A [03005-] Wood processing, transport or treated wood storage areas inspected?	Б	П	V
580	Sector A [03005-] Area/Activity controls adequate (appropriate, effective, and operating)?	Б	E	
Non-Co	ompliance			
600	Free of incidents of observed non-compliance not associated with any of the above? (Range: 0 - 0)			
Additio	nal Control Measures			
	Are permit requirements satisfied with existing control measure(s)? If "Failed" describe additional control			
620	measures needed. (Range: 0 - 0)		2	
Labor				
Labor		eg Hrs O	T Hrs C	ther Hrs
Burgin,	Jillian 1/31/2017 / 14			
Labor F	Report			
Comple	ted: Failure:			
Report:				
-				
9				

WO ID: MSGP-RI-59461 Page 4 of 4
Signature (lead inspector): Della Pargue C156C Date and Time: 1/24/17 10: 30 a.m.
"I confirm the information as recorded is true, accurate and complete."
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title:
Signature:Date:

Work Order MSGP-RI-59475

MSGP Routine Inspection Printed 2/6/2017 - 3:07 PM

Mainter	nance Details		
and the second	ted: 2/6/2017 2:59:13 PM Targe		MSGP Program
Procedu	had retain Develop Exactly	ty/Type: Normal / Inspection tment: Utilities and Infrastructure	RG121.9 TA-3-38 Carpenter Shop
Last PM	: 12/19/2016	1 - 1 - 1	Contact: Phone:
Project:	RIs Feb 2017 (P-MSGP- RI-5161)	2nsp. 2li5li7 1:00 - 1:1	0 P.M.
	MSGP Stormwater Industrial Routine I		
Weather	rat inspection:		
Special	Instructions: NMR053195		
Tasks			
#	Description	Rating M	eas. Initials Failed N/A Complete
Weathe	r Information		
	Describe the weather at time of inspecti Weather lookup table. If "Other" is chos description in task comments of this line the temperature (F°) in the "Reading" fie	en, provide e. Document	112.0
20	line.	activity to the control of the contr	43° Sung F F
Within t	he Facility Boundary		2
	Is the facility free of new discharges of	ollutants that	
40	have occurred since the last inspection'describe:	If "Failed",	F F F/
	If "Failed" has a CAR been previously	initiated for	
50	this new discharge? (Range: 0 - 0)		
	Is the facility free of discharge of polluta		
60	time of inspection? If "Failed" describe: 0)	(Range: 0 -	
	Is the facility free of evidence of, or the pollutants entering the drainage system		
70	describe: (Range: 0 - 0)		
	nspection (needed maintenance and r tion of corrective actions in relevant to		ires that need replacement, or a
00	Monitored Outfall [073] Free of Eviden	ce of	
90	Erosion? (Range: 0 - 0) Monitored Outfall [073] Flow Dissipation	n Devises	
100	Operating Effectively? (Range: 0 - 0)		
110	Monitored Outfall [073] Free of Eviden Pollutants in Discharges and/or Receivin (Range: 0 - 0)		
120	Substantially Identical Outfall [074] February Evidence of Erosion? (Range: 0 - 0)	ree of	
130	Substantially Identical Outfall [074] F Dissipation Devices Operating Effective - 0)		
140	Substantially Identical Outfall [074] For Evidence of Pollutants in Discharges an Receiving Water? (Range: 0 - 0)		

Control Measures (identify needed maintenance and repairs, failed control measures that need replacment, or a description of corrective actions in relevant task comments).

160	Asphalt Berm [0300503040002] Control Measure is operating effectively? (Range: 0 - 0)	Г	<u> </u>	
470	Asphalt Berm [0300503040002] If "Failed", is control measure in need of maintenance, Repair, or			I I I
170	Replacement?	<u> </u>		
180	Rip Rap [0300504060001] Control Measure is operating effectively? (Range: 0 - 0)	<u>_</u>	<u> </u>	
190	Rip Rap [0300504060001] If "Failed", is control measure in need of maintenance, Repair, or Replacement?	г	/	· -
200	EnviroSoxx w/ MetalLoxx [0300503200003] Control Measure is operating effectively?		- <u> -</u>	
210	EnviroSoxx w/ MetalLoxx [0300503200003] If "Failed", is control measure in need of			
210	maintenance, Repair, or Replacement?	<u>_</u>		<u> </u>
Area/. task c	Activity exposed to stormwater (identify needed mainteance or a descreption comment).	iption of corrective	actions in	relevant
230	Material loading/unloading and storage areas inspected?		. F	rt/
240	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
250	Transfer areas for substances in bulk inspected?		F	Tī-
260	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
270	Product/chemical storage areas (raw material) inspected?			T-/
280	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		г	
290	Liquid tank storage/secondary containment inspected?			
300	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		T-	
310	Industrial processing and finished product storage areas inspected?			[Z/
320	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			[-/
330	Equipment operation and maintenance areas inspected?			<u> </u>
340	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		<u> </u>	T-
350	Fueling areas inspected?			
360	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)		 	·
370	Outdoor vehicle and equipment washing areas inspected?		[]	——————————————————————————————————————
380	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	<u> </u>	17/	
390	Machinery inspected?		<u></u> -	
400	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	···	_ -	
110	Waste handling and disposal areas inspected?		— 	<u> </u>
120	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	——————————————————————————————————————	_	
130	Erodible areas/construction inspected?	— ————————————————————————————————————		
140	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			——————————————————————————————————————
450	Locations and sources of run-on to the site inspected?		 .	. .
460	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)	<u>-</u>	<u> </u>	

Labor		Assigned	Work Date	Reg Hrs OT Hrs Other Hrs
abor				-
				FFF
Additio	Are permit requirements satisfied with existing co measure(s)? If "Failed" describe additional contro measures needed. (Range: 0 - 0)	ol		
600 Additio	Free of incidents of observed non-compliance no associated with any of the above? (Range: 0 - 0)			
Non-Co	ompliance	2		
580	Sector A [03005-] Area/Activity controls adequal (appropriate, effective, and operating)?	uate		
570	Sector A [03005-] Wood processing, transport o treated wood storage areas inspected?	r		
560	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
550	Leaks and spills inspected?			
540	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
530	Housekeeping (Industrial materials/residues/tras contact with stormwater) inspected?	h in		
520	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			
510	Dust generation and vehicle tracking inspected?			
500	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			E E/ E
490	Salt storage piles or pile containing salt inspecte	d?		
480	Area/Activity controls adequate (appropriate, effective, and operating)? (Range: 0 - 0)			/ _

WO ID: MSGP- R1-59475 Page 4 of 4
Signature (lead inspector): Dillen Brugu, CISEC Date and Time: 211517 "I confirm the information as recorded is true, accurate and complete." 1:10 P.M.
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russell Store, GL DESHS-UZS
Signature:

140

Receiving Water? If "No", describe.

Work Order MSGP-RI-59485

MSGP Routine Inspection Printed 3/7/2017 - 11:22 AM

						FILL	eu 3/1/21	017 - 11.22 A
/laintena	nce Details					-	* * * * * * * * * * * * * * * * * * * *	
	d: 3/7/2017 11:13:53 AM : MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form- 1020)	Target: Priority/Type: Department:	3/31/2017 Normal / Inspec Utilities and Infrastructure	tion	MSGP F RG121.9 TA-3-38	9	er Shop	.
ast PM: roject:	12/19/2016 Routine Facility Inspections March 2017 (P-MSGP-RI- 5162)		Drop.	3123	Phone:			
eason:	2017 March Inspections		11:30	-11:0	45 air	u.		
leather a	t inspection:							
pecial In	structions: NMR053195							
asks								
# [Description		Rating	Meas.	Initials	Failed	N/A	Complete
Veather I	nformation							
V d tl	Describe the weather at time of Veather lookup table. If "Other" lescription in task comments of the temperature (F°) in the "Rea ne.	is chosen, provi this line. Docum	ide nent	55°	Clear/u	virds		
ls h	e Facility Boundary s the facility free of new dischar ave occurred since the last inspective:					_	_	5 /
0	If "No" has a CAR been previous new discharge?	usly initiated for	this				<u></u>	
0 <u>ti</u>	s the facility free of discharge of me of inspection? If "No" descr	ibe.					П	T .
р	s the facility free of evidence of, ollutants entering the drainage escribe.		for,			П	Б	3
lescriptio	spection (needed maintenance on of corrective actions in rela nonitored Outfall [073] Free of	evant task com		easures th	nat need rep	lacemen	t, or a	
	rosion? If "No", describe.	- Evidence of					Б	-
<u>00</u> C	Ionitored Outfall [073] Flow Diperating Effectively? If "No", de	escribe.	es				/	W.
10 <u>"I</u>	lonitored Outfall [073] Free of collutants in Discharges and/or No", describe.	Receiving Water	r? If					
	ubstantially Identical Outfall vidence of Erosion? If "No", de						П	
S	ubstantially Identical Outfall issipation Devices Operating E escribe	[074] Flow	ס",			Б		
s	ubstantially Identical Outfall vidence of Pollutants in Discha						-	

Control Measures (identify needed maintenance and repairs, failed control measures that need replacment, or a description of corrective actions in relevant task comments).

160	Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.				
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.				D/
190	EnviroSoxx w/ MetalLoxx [0300503200003] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or		_	_	_/
180	Replacement.				
	Activity exposed to stormwater (identify needed main comment).	teance or a descripti	on of corrective a	actions in r	elevant
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		г	П	
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, and operating)? If "No" describe.	,			E/
220	Product/chemical storage areas (raw material): controls adequate (appropriate, effective, and operating)? If "No" describe.				
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.			-	DA JB
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				5/
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			E/	For OB
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			E/	TWOB
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.				-/
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.		· D	п	
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.				
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.			-/	
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.			-	
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.				
	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No"				
350	describe. Leaks and spills: controls adequate (appropriate,				<u>r</u>
360 370	effective, and operating)? If "No" describe.		—— <u>-</u>		

Free of incidents of observed non-compliance not already identified above? If "No" describe. Additional Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed. Assigned Burgin, Jillian Assigned Work Date Reg Hrs OT Hrs Ott Assigned Work Date Reg Hrs OT Hrs Ott Abor Report Completed: Failure:		treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.
already identified above? If "No" describe. Additional Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed. In Inc. Assigned Burgin, Jillian Assigned 3/31/2017 / 14 Burgen, Jillian Assigned A		npliance
Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed. Labor Burgin, Jillian Assigned 3/31/2017 / 14 Reg Hrs OT Hrs Otl		
measure(s)? If "No" describe additional control measures needed. Labor Burgin, Jillian Mork Date Reg Hrs OT Hrs Otl 3/31/2017 / 14 Assigned Signed		al Control Measures
Labor Burgin, Jillian Assigned 3/31/2017 / 14 Reg Hrs OT Hrs Ottle 3/31/2017 / 14		measure(s)? If "No" describe additional control
Burgin, Jillian 3/31/2017 / 14 abor Report		
abor Report		
Completed: Failure:		eport
1. In 1919 1919 1919 1919 1919 1919 1919 1	_	ed: Failure:
Report:		

WO ID: MSGP-R1-59485 Page 4 of 4	
Name/Z#: Dillian Burgin, 211087	
Signature (lead inspector):	Date and Time: 3123117
"I confirm the information as recorded is true, accurate and complete."	11:45 a.m.
CERTIFICATION STATEMENT	
"I certify under penalty of law that this document and all attachments were prepared accordance with a system designed to assure that qualified personnel properly gather Based on my inquiry of the person or persons who manage the system, or those person information, the information submitted is, to the best of my knowledge and belief, to there are significant penalties for submitting false information, including the possibility violations".	red and evaluated the information submitted. ons directly responsible for gathering ue, accurate, and complete. I am aware that
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH	Group Leader, EPC Group Leader)
Print name and title: Russell Stare GK DES#5-UZS	
Signature:Date:	3/28/2017

description of corrective actions in relevant task comments).

Work Order MSGP-RI-59713

MSGP Routine Inspection Printed 4/5/2017 - 10:06 AM

Mainte	nance Details	*			·		0 11 0/2	10.00746
	sted: 4/4/2017 5:48:14 PM lure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form- 1020)	Priority/Type: Non Department: Utilii	0/2017 mal / Inspec ties and astructure	etion	MSGP F → RG121.9	9	er Sho	p
Last Pl	M : 3/23/2017	5			Contact: Phone:			
	April 2017 (P-MSGP-RI- 5170)	Ina	p. 4	اعروا	7			
Reason	1: 2017 April Inspections	0	. 20 (rue.	7 - 9:40	5	.4.1	
	er at inspection:		(,)0		,	_ Co	,	
Special	Instructions: NMR053195	-	and the second s	**************************************	The CO-COMM REPORTED STATE OF THE PROPERTY AND ADMINISTRATION ADMINISTR			
Tasks							100 mm (100 mm)	
#	Description		Rating	Meas.	Initials	Failed	N/A	Complete
Weathe	er Information							
20	Describe the weather at time of Weather lookup table. If "Othe description in task comments of the temperature (F°) in the "Refine"	r" is chosen, provide of this line. Document	,	15° <	nny	_		
20	line.			10 0	77.61.9		П.	
Within 40	the Facility Boundary Is the facility free of new discharate occurred since the last in describe:	arges of pollutants that spection? If "No",				_	_	5 /
50	If "No" has a CAR been prev new discharge?	iously initiated for this					<u> </u>	
60	Is the facility free of discharge time of inspection? If "No" descriptions of the facility of	rihe					П	[·
70	Is the facility free of evidence of pollutants entering the drainage describe.	of, or the potential for, e system. If "No"					_	
	_	and remains failed						
	Inspection (needed maintenar tion of corrective actions in re			easures tn	iat need repi	acement	, or a	
90	Monitored Outfall [073] Free Erosion? If "No", describe.	of Evidence of				П		~
100	Monitored Outfall [073] Flow Operating Effectively? If "No", o							[-/
110	Monitored Outfall [073] Free of Pollutants in Discharges and/or "No", describe.					_	-	- /
120	Substantially Identical Outfal Evidence of Erosion? If "No", d	I [074] Free of escribe.					<u> </u>	
	Substantially Identical Outfal Dissipation Devices Operating	I [074] Flow					1	
130	describe.	1 507 43 5					「	
140	Substantially Identical Outfal Evidence of Pollutants in Disch Receiving Water? If "No", description	arges and/or				П	П	
Control	Measures (identify needed ma	aintenance and repair	s, failed co	ntrol mea	sures that no	eed repla	cment	or a

160	Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.		Γ	Γ	F
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.				[-
400	EnviroSoxx w/ MetalLoxx [0300503200003] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or				
180	Replacement.			С	_ 「i
task o	Activity exposed to stormwater (identify needed main comment).	iteance or a description of correc	tive ac	tions in r	elevant
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		_		-/
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, and operating)? If "No" describe.			<u></u>	-/
220	Product/chemical storage areas (raw material): controls adequate (appropriate, effective, and operating)? If "No" describe.		- <u></u>		
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.		- <u>- l </u>		
***************************************	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and				
240	operating)? If "No" describe. Equipment operation and maintenance areas: controls adequate (appropriate, effective, and	· · · · · · · · · · · · · · · · · · ·	Г		
250 260	operating)? If "No" describe. Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		<u> </u>	_ <u></u> _	
200	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and			·	
270	operating)? If "No" describe.		<u></u>		
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.				17/
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		Γ.	1	
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.		T.	r	
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.			r	T/
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.		. <u> </u>		
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.		·	<u> </u>	
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.		г		
	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No"		·		
350	describe. Leaks and spills: controls adequate (appropriate,			<u> </u>	<u> </u>
360 370	effective, and operating)? If "No" describe.		<u>F</u>	<u></u>	T.

	Sector A [03005-] Wood processing, transport of treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	or 				
Non-C	ompliance					
390	Free of incidents of observed non-compliance no already identified above? If "No" describe.					
Additio	onal Control Measures	Ya	rd very o	rderly	4 no	. ta
	Are permit requirements satisfied with existing comeasure(s)? If "No" describe additional control	ontrol	rd very o	SUOS.		_
410	measures needed.					
.abor Labor Burgin,		Assigned 4/4/2017 / 1	Work Date	Reg Hrs	OT Hrs	Other Hrs
abor l	Report			1 (8) 11 (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	***************************************	
Compl	eted: Failure:					
Report	:					
			THE WALL CO.			

WOID: MSGP- R1-59713 Page 4 of 4					
Name/Z#: Jillian Bursin, 211081					
Signature (lead inspector):					
CERTIFICATION STATEMENT					
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".					
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)					
Print name and title: Russell Stone & DESHS-UIS					
Signature: Date: 5/4/2017					

Maintenance Details

task comment).

Work Order MSGP-RI-59909

MSGP Routine Inspection Printed 5/3/2017 - 12:56 PM

	dure: MS Ind	/2017 11:12:28 AM GP Stormwater ustrial Routine Facility pection (EPC-CP-Form- 20)	Target: Priority/Type Department:	5/31/2017 Normal / Inspection Utilities and Infrastructure	RG	-3-38 Carpe		hop	
Last P		3/2017	0		Contac Phone	1000			
Projec		utine Facility Inspections y 2017 (P-MSGP-RI-	5	130117	1 110110				
D				1:20-1:30					
		May Inspections	9	1.20- 1.50					
Specia	al Instruc	tions: NMR053195							
Tasks						«			
#	Descri	iption				Meas.	No	N/A	Yes
Weath	ner Inforn								
20	choser	be the weather at time of n, provide description in ta rature (F°) in the "Reading	ask comments	of this line. Document	the	cloudy	_	_	-
		country states destro	g noid of this in	ne.		Ctocky			
AAIGHH		ility Boundary acility free of new dischar	rges of pollutan	ts that have occurred	since the last				
40		tion? If "No", describe:	igoo oi poliatan	to that have occarred	- Inoc the last				
50		o" has a CAR been previo							
60	Is the f	acility free of discharge o	f pollutants at ti	he time of inspection?	If "No"				
	Is the f	acility free of evidence of	, or the potentia	al for, pollutants enteri	ng the		Lil		
70	drainag	ge system. If "No" describ	e.		10.00				
Outfa	II Inspect	ion (needed maintenand	ce and repairs,	, failed control meas	ures that need	d replaceme	ent, or	а	
90	The second second	corrective actions in rel pred Outfall [073] Free o			ihe		Е	Е	[_
	Monito	ored Outfall [073] Flow D							10
100	describ								
110	Receiv	ored Outfall [073] Free or ing Water? If "No", descri	f Evidence of P ibe.	ollutants in Discharge	s and/or	79			[-/
120	Substa describ	antially Identical Outfall be.	[074] Free of E	Evidence of Erosion? I	f "No",		П	-JE	5 5
130	Substa	antially Identical Outfall /ely? If "No", describe.	[074] Flow Dis	sipation Devices Ope	rating		П		
140	Substa and/or	antially Identical Outfall Receiving Water? If "No"	[074] Free of E , describe.	vidence of Pollutants	in Discharges				<u></u>
Contro	ol Measu	res (identify needed ma	intenance and evant task con	repairs, failed contr	ol measures t	hat need re	placm	ent, or	a
160	Aspha	It Berm [0300503040002 be condition & need for Ma	Control Meas	ure is operating effect	tively? If "No"			П	E/
170	Rip Ra	p [0300504060001] Confee condition & need for Ma	trol Measure is	operating effectively?	If "No"			—	E/
180 CONTO	Enviro	Soxx w/ MetalLoxx [030 rely? If "No" describe cond	0503200003] (Control Measure is op	erating	12			
180	Replac	ement.		30 8	V2.				[]

Area/Activity exposed to stormwater (identify needed mainteance or a description of corrective actions in relevant

		1
П	П	
	[V	
		_F
		[-/
	~	
	[V	
Г	П	
Г	П	
п	П	
п	Г	<u> </u>
	<u> </u>	
<u>—</u> —		
п.		<u></u>
п		<u> </u>
П	П	
	1.00	
	П	<u> </u>
П	П	
T Hrs	Oth	er Hrs
<u>_</u>		

WO ID: MOGP-R1-59909 Page 3 of 3
Name/Z#:_ Jilliau Borgin, O11081
Signature (lead inspector):
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russell Stone, GE DESHS-UES
Signature:

┌ Maintenance Details —

task comment).

200

Work Order MSGP-RI-60208

MSGP Routine Inspection Printed 5/26/2017 - 4:30 PM

	ested: 5/26/2017 4:14:25 PM dure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form- 1020)	Target: 6/30/2017 Priority/Type: Normal / Inspection Department: Utilities and Infrastructure	MSGP Program RG121.9 TA-3-38 Carpenter Shop	The state of the s
Last P	M: 4/26/2017		Contact:	
Projec	Routine Facility Inspections June 2017 (P-MSGP-RI- 5187)	Insp. 6/16/11	Phone:	
Reaso	n: 2017 June Inspections		. 6	
Specia	al Instructions: NMR053195			
Tasks				
#	Description		Meas. No N/A Yes	
Weath	ner Information			
	Describe the weather at time of	f inspection. Document the temperature	(F°) in the ~ 84° 50 mg	
20	"Reading" field of this line.		~ 64	
Withir	n the Facility Boundary			
40	Is the facility free of new disch inspection? If "No", describe:	arges of pollutants that have occurred sir	nce the last	
50	_	iously initiated for this new discharge?		and the same of th
60		of pollutants at the time of inspection? If		
60	describe. Is the facility free of evidence of	of, or the potential for, pollutants entering	The	
70	drainage system. If "No" descr			
Outfal	II Inspection (needed maintenal iption of corrective actions in re	nce and repairs, failed control measure	es that need replacement, or a	
90	THE PERSON NAMED OF THE PE	of Evidence of Erosion? If "No", describe		
100		Dissipation Devices Operating Effectively		
110	Monitored Outfall [073] Free Receiving Water? If "No", desc	of Evidence of Pollutants in Discharges a		
120	Substantially Identical Outfa describe.	II [074] Free of Evidence of Erosion? If "I	No",	-
130	Substantially Identical Outfa Effectively? If "No", describe.	II [074] Flow Dissipation Devices Operati		
140	Substantially Identical Outfa and/or Receiving Water? If "No	II [074] Free of Evidence of Pollutants in ", describe.	Discharges	
	ol Measures (identify needed miption of corrective actions in re	aintenance and repairs, failed control	measures that need replacment, or a	The same of the sa
160	Asphalt Berm [030050304000	2] Control Measure is operating effective Maintenance, Repair, or Replacement.	ely? If "No"	
170	Rip Rap [0300504060001] Co	ntrol Measure is operating effectively? If Maintenance, Repair, or Replacement.	"No"	
180		600503200003] Control Measure is operandition & need for Maintenance, Repair,	or	
		(identify pooled polynomia	cription of corrective actions in relevant	

Report:								No. of the last of
Comple	ted:							
abor R	eport-						words and	
Burgin,	Jillian	5/26/2017 / 1						
Labor		Assigned	Work Date	Reg Hrs	OT Hrs	Othe	r Hrs	
abor			A CONTRACTOR OF THE CONTRACTOR				WIND THE STREET	1
- 10	additional control measures fieeded.							
Additio 410	nal Control Measures Are permit requirements satisfied with existing additional control measures needed.	control measure(s)? If "No" describe		_	_	_	
390	describe.				П.			
Non-Co	mpliance Free of incidents of observed non-compliance	not already identifi	ed above? If "No"					
370	Sector A [03005-] Wood processing, transpor controls adequate (appropriate, effective, and	τ or treated wood s operating)? If "No"	torage areas: describe.			Д.		
360	Leaks and spills: controls adequate (appropria describe.						-	1
350	Housekeeping (Industrial materials/residues/tr controls adequate (appropriate, effective, and	operating)? If "No"	describe.	ash clee	line	ree	Jed C	1124
340	Dust generation and vehicle tracking: controls operating)? If "No" describe.							
330	Salt storage piles or pile containing salt: contro and operating)? If "No" describe.				П		П	
320	Non-stormwater/illicit connections: controls ad operating)? If "No" describe.		*					
310	Locations and sources of run-on to the site: coeffective, and operating)? If "No" describe.	ontrols adequate (a	ppropriate,			Г		
300	Erodible areas/construction: controls adequate operating)? If "No" describe.	e (appropriate, effe	ctive, and			Г		
290	Waste handling and disposal areas: controls a operating)? If "No" describe.	adequate (appropri	ate, effective, and			Г		
280	Machinery: controls adequate (appropriate, ef describe.	fective, and operat	ing)? If "No"					
270	Outdoor vehicle and equipment washing area effective, and operating)? If "No" describe.	s: controls adequat	e (appropriate,					
260	Fueling areas: controls adequate (appropriate describe.	, effective, and ope	erating)? If "No"					
250	(appropriate, effective, and operating)? If "No' Equipment operation and maintenance areas: effective, and operating)? If "No" describe.		(appropriate,					
230	effective, and operating)? If "No" describe. Industrial processing and finished product sto	rage areas: control	s adequate					
220	effective, and operating)? If "No" describe. Liquid tank storage/secondary containment: c	ontrols adequate (a	appropriate,	-				
210	and operating)? If "No" describe. Product/chemical storage areas (raw material): controls adequat	e (appropriate,					
	effective, and operating)? If "No" describe. Transfer areas for substances in bulk: controls	s adequate (approp	oriate, effective,					

WO ID: MSGP-R1 - 60208 Page 3 of 3
Name/Z#: Jilian Burgin, 211081
Signature (lead inspector):
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russell Store, GC DESES-UTS
Signature:

Work Order MSGP-RI-60706

MSGP Routine Inspection Printed 7/10/2017 - 11:05 AM

-	ested: 7/10/2017 8:54:14 AM edure: MSGP Stormwater Industria Routine Facility Inspection (EPC-CP-Form-1020) PM: 5/30/2017	, , , , ,	7/31/2017 : Normal / Inspection Utilities and Infrastructure	☐ MSGP Program ☐ RG121.9		ор	
Projec	ct: Routine Facility Inspections July 2017 (P-MSGP-RI-519	9)	7126117	Phone:			
Reaso	on: 2017 July Inspections		4:30 - 4:45 pm	\mathbf{C}			
Speci	ial Instructions: NMR053195						
Fasks							
#	Description			Meas.	No	N/A	Yes
Weat	her Information						
20	Describe the weather at time of "Reading" field of this line.	inspection. Docur	ment the temperature (F°) ir	the 60°p(c	, [
	in the Facility Boundary	-	*.				
	Is the facility free of new discha	rges of pollutants	that have occurred since th	e last			
40	inspection? If "No", describe:						
50	If "No" has a CAR been previous						
60	Is the facility free of discharge of				Д_		
70	Is the facility free of evidence of system. If "No" describe.	, or the potential f	or, pollutants entering the d	rainage 			-
Outfa	Il Inspection (needed maintenan	ce and repairs, fa	ailed control measures tha	at need replacement, o	r a des	scriptio	n of
90	ctive actions in relevant task cor Monitored Outfall [073] Free of		sion? If "No" describe				
100	Monitored Outfall [073] Flow Describe.			No",			
110	Monitored Outfall [073] Free of Water? If "No", describe.	f Evidence of Poll	utants in Discharges and/or	Receiving			F/
120	Substantially Identical Outfall	[074] Free of Evi	dence of Erosion? If "No", d	escribe.			1
130	Substantially Identical Outfall "No", describe.						
140	Substantially Identical Outfall and/or Receiving Water? If "No"		dence of Pollutants in Disch	arges			
Contr	rol Measures (identify needed ma ription of corrective actions in rel	intenance and re	epairs, failed control meas	ures that need replac	ment, c	or a	
160	Asphalt Berm [0300503040002 describe condition & need for M	2] Control Measure	e is operating effectively? If	"No"			
170	Rip Rap [0300504060001] Concondition & need for Maintenance	ce, Repair, or Rep	lacement.	# 100 min man man man man man man man man man ma			
180	EnviroSoxx w/ MetalLoxx [030 "No" describe condition & need	00503200003] Cor for Maintenance, I	ntrol Measure is operating e Repair, or Replacement.	ffectively? If		Д	
Area//	Activity exposed to stormwater (identify needed n	nainteance or a description	on of corrective action	s in rel	evant ta	ask
200	Material loading/unloading and and operating)? If "No" describe		ntrols adequate (appropriate	e, effective,			
210	Transfer areas for substances ir operating)? If "No" describe.						
220	Product/chemical storage areas and operating)? If "No" describe	(raw material): co	ntrols adequate (appropriat	e, effective,		П	5 /

	Liquid tank storage/secondary containment: controls and operating)? If "No" describe.	adequate (appropri	ate, effective,				
240	Industrial processing and finished product storage are effective, and operating)? If "No" describe.	eas: controls adequ	ate (appropriate,		Б		
250	Equipment operation and maintenance areas: control and operating)? If "No" describe.	s adequate (approp	oriate, effective,			Г	
 260	Fueling areas: controls adequate (appropriate, effective describe.	ve, and operating)?	If "No"			~	
 270	Outdoor vehicle and equipment washing areas: control and operating)? If "No" describe.	ols adequate (appro	opriate, effective,				
280	Machinery: controls adequate (appropriate, effective,	and operating)? If "	No" describe.				
290	Waste handling and disposal areas: controls adequate operating)? If "No" describe.						
300	Erodible areas/construction: controls adequate (appro	priate, effective, ar	d operating)? If				
 310	Locations and sources of run-on to the site: controls a and operating)? If "No" describe.	idequate (appropria	te, effective,				
320	Non-stormwater/illicit connections: controls adequate operating)? If "No" describe.	(appropriate, effect	ive, and				
330	Salt storage piles or pile containing salt: controls adec operating)? If "No" describe.	quate (appropriate,	effective, and				
340	Dust generation and vehicle tracking: controls adequate operating)? If "No" describe.						
350	Housekeeping (Industrial materials/residues/trash in cadequate (appropriate, effective, and operating)? If "N	ontact with stormw	ater): controls	Rods "	e fer	celi	~
360	Leaks and spills: controls adequate (appropriate, effectives)	ctive, and operating)? If "No"			Б.	
370	Sector A [03005-] Wood processing, transport or trea adequate (appropriate, effective, and operating)? If "N	ted wood storage a	reas: controls				
Nam C		o describe.				A	-
NOII-C	ompliance Free of incidents of observed non-compliance not alre	ady identified abov	e? If "No"				
390	describe				_		
	describe.						-
Additio	describe. pnal Control Measures Are permit requirements satisfied with existing control additional control measures needed.	measure(s)? If "No	" describe				
Additio	onal Control Measures Are permit requirements satisfied with existing control	measure(s)? If "No	" describe				
Addition 110 abor	onal Control Measures Are permit requirements satisfied with existing control					<u></u>	F
Addition 410 abor-	describe. conal Control Measures Are permit requirements satisfied with existing control additional control measures needed.		" describe	Reg Hrs		<u></u>	F
Addition 410 Abor Burgin,	describe. Donal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian	Assigned		Reg Hrs		<u></u>	[-
Addition 410 abor abor Burgin,	describe. conal Control Measures Are permit requirements satisfied with existing control additional control measures needed.	Assigned		Reg Hrs		<u></u>	F
Addition abor abor Burgin,	describe. Donal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian	Assigned		Reg Hrs		<u></u>	F
Addition 410 abor abor Burgin,	describe. ponal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian Report eted:	Assigned		Reg Hrs		<u></u>	[-
Addition 410 abor abor Burgin,	describe. ponal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian Report eted:	Assigned		Reg Hrs		<u></u>	F
abor abor Burgin,	describe. ponal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian Report eted:	Assigned		Reg Hrs		<u></u>	
Addition 410 abor abor Burgin,	describe. ponal Control Measures Are permit requirements satisfied with existing control additional control measures needed. Jillian Report eted:	Assigned		Reg Hrs		<u></u>	

Name/Z#: Jilian Bursin, 211081

				7/26/17
Signature (lead inspector):	Pouron	CISEC	_Date and Time:_	4:45 RM.

"I confirm the information as recorded is true, accurate and complete."

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title:

| Leader | Lead

Maintenance Details

Work Order MSGP-RI-61005

MSGP Routine Inspection Printed 8/2/2017 - 9:32 AM

	a: 8/2/2017 9:15:10 AW	larget:	8/31/2017	MSGP Progra	m		
Procedur	e: MSGP Stormwater Industrial	Priority/Type:	Normal / Inspection				
	Routine Facility Inspection (EPC-CP-Form-1020)	Department:	Utilities and Infrastructo	ure 🃤 TA-3-38 Carpe	enter Sho	р	
ast PM:	5/30/2017			Contact			
Project:	Routine Facility Inspections August 2017 (P-MSGP-RI-		Insp.	Contact: Phone:			
	5207)		81251	17			
Reason:	MSGP Stormwater Industrial Rou	utine Facility Ins _l		:30 - 9:45	ade	•	
Special Ir	nstructions: NMR053195		·			•	
asks	·				ACADO, Mark I a Samuragan Marko		
#	Description			Meas.	No	N/A	Yes
Weather	Information						
	Describe the weather at time of in "Reading" field of this line.	spection. Docum	nent the temperature (F°) in the 63° Sun	w L		
Within th	ne Facility Boundary)		
	Is the facility free of new discharge	es of pollutants t	hat have occurred since	the last			
	inspection? If "No", describe:	or pondicino i	navo ocoamoa omoc	and last			
50	If "No" has a CAR been previous	sly initiated for th	nis new discharge?				
======= 30 I	Is the facility free of discharge of p			o" describe.			
	Is the facility free of evidence of, of						
	system. If "No" describe.	- The potential it	, politicants entering the				[]
	nspection (needed maintenance		iled control measures	that need replacement,	or a des	criptio	n of
	re actions in relevant task comn						
	Monitored Outfall [073] Free of E						
	Monitored Outfall [073] Flow Dis describe.	sipation Devices	Operating Effectively?	lf "No", 			
	Monitored Outfall [073] Free of E Water? If "No", describe.	Evidence of Pollu	itants in Discharges and	/or Receiving			F
120	Substantially Identical Outfall [0	74] Free of Evic	ence of Erosion? If "No	', describe.		П	T
	Substantially Identical Outfall [0" "No", describe.	74] Flow Dissipa	ation Devices Operating	Effectively? If			
	Substantially Identical Outfall [0	_	ence of Pollutants in Dis	scharges			
140 8	and/or Receiving Water? If "No", o	iescribe.				4	
Control N	Measures (identify needed main on of corrective actions in relev	tenance and re vant task comm	pairs, failed control me ents).	easures that need repla	cment, o	ra	
	Asphalt Berm [0300503040002] describe condition & need for Main	Control Measure ntenance, Repai	is operating effectively'r, or Replacement.	? If "No"			[-/
160 c	Dim Dam [0200504000004] Cambra	Measure is one	erating effectively? If "No	o" describe			
160 <u>c</u>	Rip Rap [0300504060001] Contro condition & need for Maintenance,	Repair, or Repl	acement.				1
160 g	condition & need for Maintenance, EnviroSoxx w/ MetalLoxx [03005 'No" describe condition & need for	Repair, or Repl 503200003] Con	acement. trol Measure is operatin	g effectively? If			
160 c 170 c 180 "	condition & need for Maintenance, EnviroSoxx w/ MetalLoxx [03008 'No" describe condition & need for ivity exposed to stormwater (ide	Repair, or Replements of Replements (Repair, or Replements) Maintenance, Front (Replements)	acement. trol Measure is operatin Repair, or Replacement.		ns in rel	Evant ta	T/ ask
160 c 170 c 180 " Area/Actic	condition & need for Maintenance, EnviroSoxx w/ MetalLoxx [03008 'No" describe condition & need for ivity exposed to stormwater (ident).	Repair, or Repl 503200003] Con Maintenance, F entify needed m	acement. trol Measure is operatin Repair, or Replacement. Painteance or a descrip	otion of corrective action	ns in rel	Evant to	「」「」
170 c 170 c 180 " Area/Acti comment 180 1	condition & need for Maintenance, EnviroSoxx w/ MetalLoxx [03005] 'No" describe condition & need for ivity exposed to stormwater (ide t). Material loading/unloading and storand operating)? If "No" describe.	Repair, or Replemental Repair, or Replemental Replementation of Replementation Re	acement. trol Measure is operatin Repair, or Replacement. rainteance or a descrip trols adequate (appropri	ate, effective,	ns in rel	Evant to	TZ ask
160 c 170 c 180 18	condition & need for Maintenance, EnviroSoxx w/ MetalLoxx [03005] 'No" describe condition & need for ivity exposed to stormwater (ident). Material loading/unloading and stores.	Repair, or Replession of Repair, or Replession of Replessi	acement. trol Measure is operatin Repair, or Replacement. ainteance or a descrip trols adequate (appropri	ate, effective,	ns in rel	Evant to	G ask

I confirm	n the information as recorded is true, accurate and complete.		
	Signature / Name Date Signature / Name		Date
Report:			
Comple	ted:		
Labor R	deport de la consiste deport deport deport deport deport deport deport de la consiste deport deport de la consiste deport de la consiste de la consiste de la consiste deport de la consiste del la consiste de la consiste del la con		
Burgin, .	Jillian <u>8/2/2017 / 1</u>		
Labor	Assigned Work Date	Reg Hrs	OT Hrs Other Hrs
Labor			
410	additional control measures needed.		
Additio	nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" describe		
390	Free of incidents of observed non-compliance not already identified above? If "No" describe.		
370 Non-Co	adequate (appropriate, effective, and operating)? If "No" describe. mpliance		
	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls		
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.		
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.		
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.		
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.		
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.		
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.		
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.		
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		
270 280	and operating)? If "No" describe. Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.		
260	describe. Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective,	98.	
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe. Fueling areas: controls adequate (appropriate, effective, and operating)? If "No"		
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.		
	and operating)? If "No" describe.	•	·

Signature (lead inspector): Orney (15EC) Date and Time: 8/25/17 9:45 a.m.
"I confirm the information as recorded is true, accurate and complete."
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russell Stone, 62 DESHS - UIS
Signature: Date: 9/8/2017

Name/Z#: Jilian Burgin, CFSEC, 211081

Requested: 9/7/2017 12:25:31 PM **Target:**

Maintenance Details

Work Order MSGP-RI-61373

MSGP Routine Inspection Printed 9/7/2017 - 12:40 PM

Reque	ested: 9/7/2017 12:25:31 PM	Target:	9/30/2017	MSC MSC	3P Program		
Proce	dure: MSGP Stormwater Industrial	Priority/Type:	Normal / Inspection				
	Routine Facility Inspection	Department:	Utilities and Infrast		3-38 Carpenter	Shop	
	(EPC-CP-Form-1020)	•					
Last P				Contac	f•		
Projec			Inop. 9/2	Phone:			
	Sept 2017 (P-MSGP-RI-	9	J. 112	- 711 7			
	5219)		17.4	0-12:15	0.44		
Reaso	n: MSGP Stormwater Industrial Re	outine Facility Insi	pection	0-12.15	Pyoc.		
		,	-				
Specia	al Instructions: NMR053195						
Tasks							
#	Description				Meas. N	o N/A	Yes
Wooth	ner Information						
weati				(= 0) :			
20	Describe the weather at time of i "Reading" field of this line.	nspection. Docum	nent the temperature	(F°) in the	-11	-	
20	Reading field of this line.				closely r		
Withir	n the Facility Boundary			N	rinces		
	Is the facility free of new discharge	ges of pollutants t	hat have occurred s	ince the last			
40	inspection? If "No", describe:	ger er penatarite t	nat have becamed t		г	1 0	G /
50	If "No" has a CAR been previo	usly initiated for th	nis new discharge?				/ -
60	Is the facility free of discharge of			f "No" doscribo			
<u> </u>							
70	Is the facility free of evidence of, system. If "No" describe.	or the potential to	or, pollutants enterin	the drainage	-		-/
	System: If the describe.						
Outfal	ll Inspection (needed maintenanc	e and repairs, fa	iled control measu	res that need rep	lacement, or a	descript	ion of
	ctive actions in relevant task com						
90	Monitored Outfall [073] Free of	Evidence of Eros	ion? If "No", describ	e.			
	Monitored Outfall [073] Flow Di	ssipation Devices	Operating Effective	ly? If "No",			
100	describe.					1	
	Monitored Outfall [073] Free of	Evidence of Pollu	itants in Discharges	and/or Receiving			
110	Water? If "No", describe.						
120	Substantially Identical Outfall	[074] Free of Evid	lence of Erosion? If	'No", describe.	Г		T-
	Substantially Identical Outfall	[074] Flow Dissipa	ation Devices Opera	ting Effectively? If			
130	"No", describe.			J			- □
	Substantially Identical Outfall	074] Free of Evid	ence of Pollutants in	Discharges			
140	and/or Receiving Water? If "No",			J			
01	155						
	ol Measures (identify needed mai			I measures that n	eed replacmen	t, or a	
uescri	iption of corrective actions in rele						The state of the s
160	Asphalt Berm [0300503040002] describe condition & need for Ma	Control Measure	s is operating effective	ely? If "No"			/
100							
		OLIVIERSUIRE IS ONE	erating effectively? If	"No" describe			1
170	Rip Rap [0300504060001] Conti				Total Control		
170	condition & need for Maintenance	e, Repair, or Repla	acement.				
	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300	e, Repair, or Replanta 0503200003] Con	acement. trol Measure is oper	ating effectively? I	f		
170 180	condition & need for Maintenance	e, Repair, or Replanta 0503200003] Con	acement. trol Measure is oper	ating effectively? I ent.			
180	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for	e, Repair, or Replant 0503200003] Control Maintenance, F	acement. trol Measure is oper Repair, or Replaceme	ent.		relevant	
180	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Maintenance Activity exposed to stormwater (in	e, Repair, or Replant 0503200003] Control Maintenance, F	acement. trol Measure is oper Repair, or Replaceme	ent.		relevant	task
180 Area/A	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Maintenance Activity exposed to stormwater (ident).	e, Repair, or Repli 0503200003] Con or Maintenance, F dentify needed m	acement. trol Measure is oper Repair, or Replaceme nainteance or a des	ent. cription of correc			task
180 Area/A	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Maintenance Activity exposed to stormwater (in	e, Repair, or Repli 0503200003] Con or Maintenance, F dentify needed m	acement. trol Measure is oper Repair, or Replaceme nainteance or a des	ent. cription of correc		relevant	task
180 Area/A	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Maintenance Activity exposed to stormwater (ident). Material loading/unloading and stand operating)? If "No" describe.	e, Repair, or Repla 0503200003] Con or Maintenance, F dentify needed manage areas: conf	acement. trol Measure is oper Repair, or Replacement ainteance or a des trols adequate (appr	ent. cription of correct opriate, effective,		relevant	task
180 Area/A	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Activity exposed to stormwater (ident). Material loading/unloading and st	e, Repair, or Repla 0503200003] Con or Maintenance, F dentify needed manage areas: conf	acement. trol Measure is oper Repair, or Replacement ainteance or a des trols adequate (appr	ent. cription of correct opriate, effective,		relevant	t task
180 Area/A commo	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need for Maintenance and Secrible Condition & need for Maintenance (in the condition of	e, Repair, or Repla 9503200003] Con or Maintenance, Falentify needed manage areas: contact bulk: controls ade	acement. trol Measure is oper Repair, or Replacement alinteance or a des trols adequate (appropriate,	ent. cription of correct opriate, effective, effective, and		relevant	t task

9/30/2017

	and operating)? If "No" describe.				
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.			[/	
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		г		
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	•			
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				<u> </u>
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.				
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		П.		
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.				
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.				
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.	ş-		<u> </u>	
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.	11		, <u> </u>	
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.			Г	
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.				
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.				[]/
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
Non-Co	ompliance				
390	Free of incidents of observed non-compliance not already identified above? If "No" describe.		-		-
					-
Additio	nal Control Measures				
410	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.		П	П	<u></u>
abor-					CONTRACTOR NOTES
Labor	Assigned Work Date	Dear Une	OT U	041-	
Burgin,		Reg Hrs	OTHrs	Othe	r Hrs
abor R	Report		(1000 x 10	TOTAL THE SECRET SHEET OF THE SECRET SHEET	THE ROTOR CONTROL TO SERVICE SAME
Comple	ted:				
Report:					
	501-R1-61373 Page 7 of 3				
D: W	501-KI-61373 Page 7 of 3				

WO

Name/Z#: Truian Burgin, 211081

Signature (lead inspector):	OPomogue,	CISEC	_Date and Time:_	9/27/17	
"I confirm the information as recorded	is true, accurate and complete."			12:15 p.m.	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with y inquiry of on submitted bmitting false

a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on n the person or persons who manage the system, or those persons directly responsible for gathering information, the informat is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for su information, including the possibility of fine and imprisonment for knowing violations".	in
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)	
Print name and title: Russell Stone, GC DESHS-UZS	
Signature:	

Los Alamos National Lab - ADESH

- Maintenance Details –

Work Order MSGP-RI-61880

MSGP Routine Inspection Printed 11/1/2017 - 8:47 AM

_	lested: 10/31/2017 2:43:12 PM	Target:	11/30/2017	MSGP Progr	am		
Proc	edure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form-1020)		Normal / Inspection Utilities and Infrastructure	♣ RG121.9 ♣ TA-3-38 Carp	enter SI	пор	
Last-			and the same to				
Proje	Routine Facility Inspections Nov 2017 (P-MSGP-RI-5238)	In	F166101 . Qu	Contact: Phone:			
Reas	on: 2017 November Inspections		2:15-2:30 P	M.			
Spec	ial Instructions: NMR053195						
asks							
#	Description			Meas	. No	N/A	Yes
Weat	her Information						
20	Describe the weather at time of in	nenection and do	Sumant the temperature (F°)	630 Pla	7	toward.	_
		ispection and doc	cument the temperature (F*).	65 PI			~
Withi	n the Facility Boundary						
40	Is the facility free of new discharg	jes of pollutants t	hat have occurred since the	ast			
40	inspection? If "Failed" describe.						V
50	If "No" has a CAR been previou						
30	Is the facility free of discharge of						V
7.0	Is the facility free of evidence of,	or the potential fo	r, pollutants entering the dra	nage			
70	system. If "No" describe.						-
iesci 10	Ill Inspection (identify needed mair ription of corrective actions in rele Monitored Outfall [073] Free of Monitored Outfall [073] Flow Dis	vant task comm Evidence of Erosi	ent) on? If "No", describe.			П	V
100	describe.	***		,		V	
110	Monitored Outfall [073] Free of I Water? If "No", describe.						~
120	Substantially Identical Outfall [6	074] Free of Evidence	ence of Erosion? If "No", des	cribe.		Two.	-
130	Substantially Identical Outfall [0 "No", describe.	074] Flow Dissipa	tion Devices Operating Effec	ctively? If		T/	Г
140	Substantially Identical Outfall [0 and/or Receiving Water? If "No", o	074] Free of Evidence describe.	ence of Pollutants in Dischar	ges			5
Contr	ol Measures (identify needed main	tenance and rep	airs, failed control measur	es that need repla	cment.	ora	1.5
ıescr	iption of corrective actions in relev	∕ant task comme	ents).				
60	Asphalt Berm [0300503040002]	Control Measure	is operating effectively? If "N	lo"			
	describe condition & need for Mail Rip Rap [0300504060001] Control	ol Measure is ope	rating effectively? If "No" des	scribe			
70	condition & need for Maintenance	, Repair, or Repla	cement.				
80	EnviroSoxx w/ MetalLoxx [03009] "No" describe condition & need for	503200003] Cont r Maintenance, R	rol Measure is operating effe epair, or Replacement.	ctively? If			
rea/	Activity exposed to stormwater (ide	entify needed ma	ainteance or a description	of corrective action	ns in rel	evant ta	ask
omm	ent).						
00	Material loading/unloading and sto and operating)? If "No" describe.	orage areas: conti	ols adequate (appropriate, e	ffective,		_	_/
	Transfer areas for substances in b	ulk: controls adec	quate (appropriate, effective,	and			
10	operating)? If "No" describe.						
	Product/chemical storage areas /re	aw materially can	trale adaquata (annuni - 1 -	- CC - ali			
	Product/chemical storage areas (rand operating)? If "No" describe.			,			
30	and operating)? If "No" describe. Liquid tank storage/secondary con			,			

	and operating)? If "No" describe.				_
240	Industrial processing and finished product storage areas: controls adequate effective, and operating)? If "No" describe.	(appropriate,			T.
250	Equipment operation and maintenance areas: controls adequate (appropriat and operating)? If "No" describe.	te, effective,			
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "describe.	'No"			
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriand operating)? If "No" describe.	ate, effective,			
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No	" docoribe			
290	Waste handling and disposal areas: controls adequate (appropriate, effective operating)? If "No" describe.				
300	Erodible areas/construction: controls adequate (appropriate, effective, and o "No" describe.	pperating)? If			
310	Locations and sources of run-on to the site: controls adequate (appropriate, and operating)? If "No" describe.	effective,			
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, operating)? If "No" describe.	, and			
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effe operating)? If "No" describe.	ective, and			
340	Dust generation and vehicle tracking: controls adequate (appropriate, effectioperating)? If "No" describe.	ve, and			
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater adequate (appropriate, effective, and operating)? If "No" describe.	r): controls			<u></u>
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? I describe.	f "No"			1
370	Sector A [03005-] Wood processing, transport or treated wood storage area	as: controls			
Non-Co 390	adequate (appropriate, effective, and operating)? If "No" describe. Impliance Free of incidents of observed non-compliance not already identified above? I describe. Inal Control Measures				
Non-Co 390	mpliance Free of incidents of observed non-compliance not already identified above? I describe.				F
Non-Co 390 Addition	Free of incidents of observed non-compliance not already identified above? In describe. The describe describe describe describe. The permit requirements satisfied with existing control measure(s)? If "No" describe des			п	F
Non-Co 390 Addition 110 abor	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned	escribe	Reg Hrs OT	Г	
Non-Co 390 Addition 410	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned	escribe		Г	
Non-Co 390 Addition 110 abor abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	
Non-Co 390 Addition 410 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	
Non-Co 890 Addition 110 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	F-
Non-Co 390 Addition 110 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	F
Non-Co 390 Addition 110 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	F-
Non-Co 390 Addition 410 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	F-
Non-Co 390 Addition 110 abor Burgin, J	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	F-
Non-Co 390 Addition 110 abor Burgin, J Bor Ro Complete Report:	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Assigned World Measures Assigned World Measures needed.	escribe		Г	
Additionabor Burgin, J Complete Report:	Free of incidents of observed non-compliance not already identified above? I describe. nal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" de additional control measures needed. Dillian Assigned 11/11/2017 / 1 eport ted:	escribe rk Date F		Г	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, O	ps Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Russel Store, GL	DESHS-UZS
Signature: Recall Stee	Date: 11/21/2017

Los Alamos National Lab - ADESH

Work Order MSGP-RI-61880

MSGP Routine Inspection

Maint	enance Details	Printed 11/1/2017 - 8:47 Al
Reque	ested: 10/31/2017 2:43:12 PM	☑ MSGP Program 拈 RG121.9
	Routine Facility Inspection Department: Utilities and Infrastructure (EPC-CP-Form-1020)	TA-3-38 Carpenter Shop
Last F Projec	t: Routine Facility Inspections	Contact: Phone:
Reaso	Nov 2017 (P-MSGP-RI-5238) on: 2017 November Inspections al Instructions: NMR053195	
Specia	al Instructions: NMR053195	
asks		
4	Description	
#	Description	Meas. No N/A Yes
	ner Information	11001-1-
20 -	Describe the weather at time of inspection and document the temperature (F°).	16° Cloudy 1 1
Withir	the Facility Boundary	
40	Is the facility free of new discharges of pollutants that have occurred since the last	<u> </u>
40 50	inspection? If "Failed" describe.	
50	If "No" has a CAR been previously initiated for this new discharge?	
60	Is the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection? If "No" described the facility free of discharge of pollutants at the time of inspection?	
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "No" describe.	ge \square
90	Monitored Outfall [073] Free of Evidence of Erosion? If "No", describe.	
100	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? If "No", describe.	
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Rece Water? If "No", describe.	eiving
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If "No", describe	be.
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effective "No", describe.	ely? If
	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges	
140	and/or Receiving Water? If "No", describe.	
Contro descri	ol Measures (identify needed maintenance and repairs, failed control measures ption of corrective actions in relevant task comments).	that need replacment, or a
160	Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" descrict condition & need for Maintenance, Repair, or Replacement.	be G G
180	EnviroSoxx w/ MetalLoxx [0300503200003] Control Measure is operating effective "No" describe condition & need for Maintenance, Repair, or Replacement.	vely? If
Area/A	activity exposed to stormwater (identify needed mainteance or a description of	corrective actions in relevant task
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective and operating)? If "No" describe.	ctive,
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, an operating)? If "No" describe.	d
220	Product/chemical storage areas (raw material): controls adequate (appropriate, effeand operating)? If "No" describe.	ective,
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective	

Liquid tank storage/secondary containment: controls adequate (appropriate, effective,

		<u>and operating)?</u> If "No" describe.	
	240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	280		
	200	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.	
The state of the s	340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.	
AND DESCRIPTION OF THE PERSONS ASSESSMENT	350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.	
	360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.	
-	370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	<u> </u>	sacquate (appropriate, encouve, and operating): If the describe.	
1	Non-Co	mpliance	
	390	Free of incidents of observed non-compliance not already identified above? If "No" describe.	
-	Additio	nal Control Measures	
ĺ	410	Are permit requirements satisfied with existing control measure(s)? If "No" describe	
	410	additional control measures needed.	
ı			
<u></u>			
Г	Labor -		
	Labor		
		Assigned Work Date R	leg Hrs OT Hrs Other Hrs
	Burgin, .	Jillian 11/1/2017 / 1	
L			
Γ-	Labor R	eport	
	Comple	to de	
-	Comple	ted:	
Î	_		
	Report:		
L	. ^	110 0 0 0	
W	O ID:¥	NS6P- RI- 61880 Page 2 of 3	
		T	
Na	me/Z#:	Tillian Burgin CISER 211081	
. 14			
1 14		0 1	
1 14			
			,
	mature (le	ad inspector): Power CTSEC During III	30/17
	gnature (lea	ad inspector):	3017
	gnature (lea	ad inspector):	130/17 1:45 p.m.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.	A, eg., FOD, Ops Mgr, DSESH	I Group Leader, EPC Group I	Leader)
Print name and title: Ressell Store	GL DESHS-UIS		_
Print name and title: Russell Stone Signature: Russ Of Stone	Date	e: 12/21/2017	
			•

Los Alamos National Lab - ADESH

Work Order MSGP-RI-62067

MSGP Routine Inspection Printed 12/4/2017 - 8:33 AM

Main	tenance Details		The second secon	7 111100 12/4/2017 - 0.00 AIVI
	edure: MSGP Stormwater Industrial Routine Facility Inspection (EPC-CP-Form-1020)	Target: 12/31/2017 Priority/Type: Normal / Inspection Department: Utilities and Infrastru	○ MSGP Prog 品 RG121.9 Icture	
	10.20.2011	Insp. Reyon 12/18/17 3:30-4:0		
Tasks				
#	Description		Mea	s. No N/A Yes
20	in the Facility Boundary	spection and document the temperatures of pollutants that have occurred sing	A	sunny
<u>40</u> 50	inspection? If "Failed" describe.	-		
60		sly initiated for this new discharge? collutants at the time of inspection? If "	No!! describe	
70		or the potential for, pollutants entering t		
90 100		Evidence of Erosion? If "No", describe. sipation Devices Operating Effectively	? If "No",	
110	Monitored Outfall [073] Free of E Water? If "No", describe.	vidence of Pollutants in Discharges ar	nd/or Receiving	
120		74] Free of Evidence of Erosion? If "N	o" describe	
130		74] Flow Dissipation Devices Operating		
140	Substantially Identical Outfall [0' and/or Receiving Water? If "No", de	74] Free of Evidence of Pollutants in Describe.	Discharges	
Contro	ol Measures (identify needed maint iption of corrective actions in releva	tenance and repairs, failed control n	neasures that need repl	
160		Control Measure is operating effectively	y? If "No"	
170	Rip Rap [0300504060001] Control condition & need for Maintenance,	Measure is operating effectively? If "N	No" describe	
180	EnviroSoxx w/ MetalLoxx [03005] "No" describe condition & need for	03200003] Control Measure is operati Maintenance, Repair, or Replacement	ng effectively? If	
Area/A	Activity exposed to stormwater (ide ent).	ntify needed mainteance or a descr	iption of corrective acti	ons in relevant task
200	and operating)? If "No" describe.	rage areas: controls adequate (approp		
210	operating)? If "No" describe.	ulk: controls adequate (appropriate, eff		
220	and operating)? If "No" describe.	w material): controls adequate (approp		
230	Liquid tank storage/secondary conta	ainment: controls adequate (appropria	ite, effective,	一方方元

	and operating)? If "No" describe.				
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г	[]	
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.				
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.		<u> </u>		
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.		<u> </u>		
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.				
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.				
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and		<u></u>		
340		,⇒□_	Д.	<u> </u>	
350	operating)? If "No" describe. Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls care adequate (appropriate, effective, and operating)? If "No" describe. (Lean - 0) + (ash by adequate (appropriate, effective, and operating)? If "No" describe.	Samp	ler,	o fe	1
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.				ncen
	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls			li/	
370	adequate (appropriate, effective, and operating)? If "No" describe.				
410	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.				
abor]
Labor	Assigned Work Date Reg Hrs	OT Hrs	Othe	r Hrs	
Burgin, 、					
abor R	eport			***]
Comple	ted:				
Report:					
ΙD: <u>γγ</u>	156P-R1-62067 Page 2 of 3				
ne/Z#:	Tillian Burgin, @ 211081				
-4 /1		. ~	(1)	~ A · · ·	
ature (le	ad inspector): Date and Time: 12/18	117	4:0	opm	_

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory mus	t meet definition in Section B.1	1.A, eg., FOD, Ops Mgr, D	SESH Group Leader, EPC Group I	Leader)
Print name and t	itle: Russell S	tone GL DESH	is- UIS	_
Signature:	Russ Ol Fran		Date: 12/21/2017	
			•	

- Maintenance Details -

Work Order MSGP-RI-62082

MSGP Routine Inspection Printed 1/2/2018 - 5:03 PM

-	ested: 1/2/2018 3:57:09 PM edure: MSGP Stormwater Ind Routine Facility Inspec (EPC-CP-Form-1020) PM: 12/18/2017	, , , , , , , , , , , , , , , , , , , ,	1/31/2018 : Normal / Inspection Utilities and Infrastructure	SGP Program RG121.9 TA-3-38 Carpenter Shop		юр		
Projec		tions -5248)	p. 1/31/18	Contac Phone:				
Reaso	on: 2018 January Inspections		1:15-1:30 pr	4				
Speci	al Instructions: NMR05319	5		with the same of t				
asks.				the factor growing and the second growing the second growing and the second growing growing and the second growing growin				
#	Description				Meas.	No	N/A	Yes
Weat	her Information							
20	Describe the weather at tir	me of inspection and do	ocument the temperature (F	°). 57°	F	Г	Г	Tu
Withi	n the Facility Boundary				Clear,	Su	nne	1
40		ischarges of pollutants	that have occurred since the	e last		_	_	,
50	If "No" has a CAR been		his new discharge?					
60			time of inspection? If "No" of	lescribe		+		
70			or, pollutants entering the dr					
descr	Il Inspection (identify neede iption of corrective actions	d maintenance and re	pairs, failed control meas	ures that r	eed replac	ement,	or a	
90	Monitored Outfall [073] F					_	_	
100			s Operating Effectively? If "I	No",				
110	Monitored Outfall [073] F	ree of Evidence of Poll	utants in Discharges and/or	Receiving				
120	Water? If "No", describe.	utfall [07/1] Eroo of Evic	dence of Erosion? If "No", de			ᅳ	Щ.	
130			ation Devices Operating Eff					
	Substantially Identical Or	utfall [074] Free of Evid	dence of Pollutants in Disch	arges				
140	and/or Receiving Water? If	"No", describe.		-				1
Contro descri	ol Measures (identify neede iption of corrective actions i	d maintenance and re	pairs, failed control meas	ures that n	eed replaci	ment, c	or a	
			e is operating effectively? If	"No"				
160	describe condition & need	for Maintenance, Repai	r, or Replacement.					1
170	condition & need for Mainte	enance, Repair, or Repl				Г	Г	1
180	EnviroSoxx w/ MetalLoxx If "No" describe condition 8	[0300503200003] Cor need for Maintenance	ntrol Measure is operating ef , Repair, or Replacement.	fectively?		Г	Г	
Area/A	Activity exposed to stormwa			n of correc				ask
200	Material loading/unloading and operating)? If "No" des	and storage areas: con	trols adequate (appropriate,	effective,	CAR	F12	18'	_
	Transfer areas for substance	ces in bulk: controls ade	equate (appropriate, effective	e, and	orrer.			
210	operating)? If "No" describe Product/chemical storage a		ntrols adequate (appropriate	offective		Г_	_Г	1
20	and operating)? If "No" des	cribe.	unora anedinare (abbitobuste	, enective,		_	ī	To .
230	Liquid tank storage/second	ary containment: contro	ale adoquato (approprieto e	ffootivo		 -		

240			
	and operating)? If "No" describe. Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		
050	Equipment operation and maintenance areas: controls adequate (appropriate, effective	ve,	
250	and operating)? If "No" describe.		
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		ГГГ
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe		
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	···	
	Erodible areas/construction: controls adequate (appropriate, effective, and operating)	? If	
300	"No" describe. Locations and sources of run-on to the site: controls adequate (appropriate, effective,		
310	and operating)? If "No" describe. Non-stormwater/illicit connections: controls adequate (appropriate, effective, and		
320	operating)? If "No" describe.		
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.		<u> </u>
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.		
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): control adequate (appropriate, effective, and operating)? If "No" describe.	S	
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.		
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: contro adequate (appropriate, effective, and operating)? If "No" describe.	ls	ГГГ
Additio	onal Control Measures Are permit requirements satisfied with existing control measure(s)? If "No" describe		
410	additional control measures needed.		
abor			
	Jillian Assigned Work Date 1/31/2018 / 1 1	Reg Hrs	OT Hrs Other Hrs
Burgin,		Reg Hrs	OT Hrs Other Hrs
Burgin, abor R	Jillian 1/31/2018 / 1	Reg Hrs	OT Hrs Other Hr
Burgin, abor R Comple	Jillian	Reg Hrs	OT Hrs Other Hr
Labor Burgin, abor R Comple Report:	Jillian	Reg Hrs	OT Hrs Other Hr
Burgin, abor R Comple	Jillian	Reg Hrs	OT Hrs Other Hrs
Burgin, abor R Comple Report:	Jillian	Reg Hrs	OT Hrs Other Hrs
Burgin, Bor R Comple Report:	NSGP-RI-62087 Page 1 of 3	Reg Hrs	OT Hrs Other Hrs
Burgin, Bor R Comple Report:	Jillian	Reg Hrs	OT Hrs Other Hrs

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

Target:

- Maintenance Details -

230

Requested: 2/5/2018 3:59:49 PM

Work Order MSGP-62095

MSGP Monitoring Stations Printed 2/5/2018 - 4:16 PM

Request	ed: 2/5/2018 3:59:49 PM	Target:	2/28/2018	🗀 MSGP Pro	gram		
Procedu	re: MSGP Stormwater Industrial	Priority/Type:	: Normal / Inspection	品 RG121.9			
	Routine Facility Inspection (EPC-CP-Form-1020)	Department:	Utilities and Infrastructure	♣ TA-3-38 Ca	rpenter Sh	ор	
Last PM:	: 12/18/2017			Contact:			
Project:	Routine Facility Inspections Feb 2018 (P-MSGP-RI-5250)	. 0.	me. 2123/18	Phone:			
≀eason:	2018 February Inspections		9:30-9:45				
pecial l	Instructions: NMR053195						
asks-							
#	Description			Me	as. No	N/A	Yes
Weather	r Information						
20	Describe the weather at time of in	spection and do				Г	<u></u>
Nithin t	he Facility Boundary		5r	ownest a	lischa	urge	_
	Is the facility free of new discharg	es of pollutants	that have occurred since the	last			
10	inspection? If "Failed" describe.						
50	If "No" has a CAR been previou						
0	Is the facility free of discharge of I						
<u>'0</u>	Is the facility free of evidence of, of system. If "No" describe.	or the potential fo	or, pollutants entering the dra	inage			T/
	nspection (identify needed mair			res that need re	placement,	or a	
descript 90	tion of corrective actions in rele		•				
10	Monitored Outfall [073] Free of I Monitored Outfall [073] Flow Dis						
00	describe.				Г	<u></u>	厂
110	Monitored Outfall [073] Free of It Water? If "No", describe.	=vidence of Polli	utants in Discharges and/or F	Receiving	_	_	
20	Substantially Identical Outfall [6	074] Free of Evid	dence of Erosion? If "No", de	scribe.	— 	÷	-10
30	Substantially Identical Outfall [6"No", describe.					- F	
	Substantially Identical Outfall [0	74] Free of Evid	dence of Pollutants in Discha	rges			
40	and/or Receiving Water? If "No", or			-		厂	
	Measures (identify needed main ion of corrective actions in relev			res that need re	placment, c	or a	
•	Asphalt Berm [0300503040002]		•	No"			
	describe condition & need for Mai				Г		
	Rip Rap [0300504060001] Contro condition & need for Maintenance			scribe	Г	Г	-
	EnviroSoxx w/ MetalLoxx [0300: "No" describe condition & need fo			ectively? If		_	
00	140 describe condition & fleed to	i Maintenance, i	repair, or replacement.				
Area/Act commen	tivity exposed to stormwater (ident).	entify needed n	nainteance or a description	of corrective ac	tions in rel	evant t	ask
	Material loading/unloading and sto and operating)? If "No" describe.	orage areas: con	trols adequate (appropriate,	effective,		厂	
	Transfer areas for substances in boperating)? If "No" describe.	oulk: controls ade	equate (appropriate, effective	, and	Г	Г	1
	Product/chemical storage areas (rand operating)? If "No" describe.	aw material): co	ntrols adequate (appropriate,	effective,			<u></u>

Liquid tank storage/secondary containment: controls adequate (appropriate, effective,

2/28/2018

	and operating)? If "No" describe.				
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				_ 「~
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		П	[/	
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г		F
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				F
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.			厂	[-
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г	Г	
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.			[-/	
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.			~	
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.				L
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.				
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.				
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г	Г	Г
Additio 110	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.		_		F-
abor _abor	Work Date Re	a Hre	OT H	e Oth	er H
abor F	Report				
Comple	eted:				
Report					
		en an ann agus de contraction de la contraction	and the same		
D:	M561-62095 Page 2 of 3				
	M561-62095 Page 2 of 3 Tillian Burgin / 211081				

9:45 AM

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must me	et definition in Section B.11.A, eg., FO	DD, Ops Mgr, DSESH Gro	up Leader, EPC Group Leader)
Print name and title:_	Russell Stone	Desus- uts	
Signature:	Russel Fee	Date <u>:</u>	3/27/2018

- Maintenance Details

Work Order MSGP-RI-62103

MSGP Routine Inspection Printed 3/5/2018 - 11:02 AM

Reques	ted: 3/5/2018 10:56:50 AM	Target: 3/31/2018	MSGP Program
Procedu	ure: MSGP Routine Facility	Priority/Type: Normal / Inspection	류 RG121.9
	Inspection (EPC-CP-Form- 1020.1)	Department: Utilities and Infrastructure	💪 TA-3-38 Carpenter Shop
Last PM	l: 1/31/2018	9.000	Contact:
Project:		O .	Phone:
	March 2018 (P-MSGP-RI- 5251)	Insp. 3/29/18	· none.
Reason	: MSGP Routine Facility Inspection	n 3:15-3:30 pm	
Special	Instructions: NMR053195		
「asks ─			
#	Description		Meas. No N/A Yes
Weathe	r Information		
20	Describe the weather at time of it	spection and document the temperature (F°	530 Ple F F T
Within	the Facility Boundary		
	Is the facility free of new discharg	es of pollutants that have occurred since the	last
40	inspection? If "Failed" describe.		
50		sly initiated for this new discharge?	
60	Is the facility free of discharge of	pollutants at the time of inspection? If "No" d	escribe.
		or the potential for, pollutants entering the dra	•
70	system. If "No" describe.		<u></u>
Outfall	Inspection (identify needed mai	ntenance and repairs, failed control measi	ires that need replacement, or a
•	tion of corrective actions in rele	•	
90		Evidence of Erosion? If "No", describe.	
100	Monitored Outfall [073] Flow Didescribe.	ssipation Devices Operating Effectively? If "N	o", <u> </u>
110	Monitored Outfall [073] Free of Water? If "No", describe.	Evidence of Pollutants in Discharges and/or	Receiving
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If "No", de	escribe.
130	Substantially Identical Outfall ["No", describe.	074] Flow Dissipation Devices Operating Effe	ectively? If
		074] Free of Evidence of Pollutants in Discha	arges
140	and/or Receiving Water? If "No",		
		ntenance and repairs, failed control measu	ıres that need replacment, or a
descrip	tion of corrective actions in rele	•	
160	· · · · · · · · · · · · · · · · · · ·	Control Measure is operating effectively? If 'ntenance, Repair, or Replacement.	No"
100		ol Measure is operating effectively? If "No" de	escribe
170	condition & need for Maintenance		
	EnviroSoxx w/ MetalLoxx [0300	503200003] Control Measure is operating ef	fectively? If
180	"No" describe condition & need for	r Maintenance, Repair, or Replacement. N	ew wattle Ma F F
Area/Ac		entify needed mainteance or a description	n of corrective actions in relevant task
200	,	orage areas: controls adequate (appropriate,	effective,
210		pulk: controls adequate (appropriate, effective	e, and
		raw material): controls adequate (appropriate	e, effective,
220	and operating)? If "No" describe.	,	

230	Liquid tank storage/secondary containment: controls a and operating)? If "No" describe.	adequate (approp	oriate, effective,		П	1-/	П
240	Industrial processing and finished product storage are effective, and operating)? If "No" describe.	as: controls ade	quate (appropriate,			厂	[-/
250	Equipment operation and maintenance areas: controls and operating)? If "No" describe.		-			Г	- /
260	Fueling areas: controls adequate (appropriate, effective describe.	e, and operating)? If "No"			<u> </u>	
270	Outdoor vehicle and equipment washing areas: control and operating)? If "No" describe.	ols adequate (app	oropriate, effective,			<u>「/</u>	
280	Machinery: controls adequate (appropriate, effective, a	and operating)? I	f "No" describe.			Г	「
290	Waste handling and disposal areas: controls adequate operating)? If "No" describe.	e (appropriate, ef	fective, and				<u>「</u>
300	Erodible areas/construction: controls adequate (appro				-		
310	Locations and sources of run-on to the site: controls a and operating)? If "No" describe.	dequate (approp	riate, effective,		П		<u> </u>
320	Non-stormwater/illicit connections: controls adequate operating)? If "No" describe.		П	F/	Г		
330	Salt storage piles or pile containing salt: controls adeq operating)? If "No" describe.	juate (appropriat	e, effective, and		Г	<u> </u>	Г
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.						
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.					г	[~
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.				Г	г	[~
370	Sector A [03005-] Wood processing, transport or trea adequate (appropriate, effective, and operating)? If "N	ted wood storage o" describe.	e areas: controls				
Non-Co	ompliance						
390	Free of incidents of observed non-compliance not alre describe.	ady identified ab	ove? If "No"		_	_	[~
	nal Control Measures						10
410	Are permit requirements satisfied with existing control additional control measures needed.	measure(s)? If "	No" describe			匚_	<u>「</u>
_abor							
Labor		Assigned	Work Date	Reg Hrs	OT Hrs	Othe	r Hrs
Burgin,	Jillian	3/5/2018 / 1					
abor R	Report				antenine a antenin i si i intenincia i con Mili con intenincia.		
Comple	eted:						
Report:							
			,				
The state of the s					Note that I recognise a control they are a control	TOTAL TAXABLE PARAMETER	

WO ID: MSGP- RI- 62103 Page 2 of 3

Name/Z#: Jiwan Bursin 211081

Signature (lead inspector):	DEP (CISECDate and Time:	3/29/18	3:30 p.m.
	Bate and Time:_		

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title:

| Last | Store | Compared Destricts | Date: 4/18/20/7

Maintenance Details

Work Order MSGP-RI-62332

MSGP Routine Inspection Printed 5/1/2018 - 4:01 PM

Request	ted: 5/1/2018 3:59:00 PM	Target:	4/30/2018	MSGP Program			
Procedu	ire: MSGP Routine Facility	Priority/Type:	: / Inspection	器 RG121.9			
	Inspection (EPC-CP-Form-	Department:	Utilities and Infrastructure	🗘 TA-3-38 Carper	ter Sh	ор	
004 DB#	1020.1)						
ast PM				Contact:			
Project:	Routine Facility Inspections April 2018 (P-MSGP-RI-			Phone:			
	5262)	Dr	usp. 4/2/e/18	S			
Reason:	2018 April Inspections		2:45-3:001	on			
Snecial	Instructions: NMR053195						
peciai	illistractions. Mivinoss 195						
asks							
#	Description			Meas.	No	N/A	Yes
Waatha	r Information						
20	Describe the weather at time of ir	spection and do	ocument the temperature (F°). 69° Char/ Surn	_	_	<u> </u>
		ispection and de	beament the temperature (i	Suni	'}		10
Within t	he Facility Boundary	-					
10	Is the facility free of new discharge	es of pollutants	that have occurred since the	e last		_	
40 50	inspection? If "Failed" describe.	.alı i aiti ata al fau t	his servedical area O				
50	If "No" has a CAR been previou						
30	Is the facility free of discharge of		•				
70	Is the facility free of evidence of, system. If "No" describe.	or the potential f	or, pollutants entering the dr	ainage	_	_	-
70	system. If No describe.					-	
	Inspection (identify needed mair			ures that need replac	ement,	or a	
aescrip 90	tion of corrective actions in rele		•			_	
90	Monitored Outfall [073] Free of			1-11			
100	Monitored Outfall [073] Flow Dis describe.	ssipation Device:	s Operating Effectively? If Ir	NO ,	_	_	T.
	Monitored Outfall [073] Free of	Evidence of Poll	utants in Discharges and/or	Receiving			10
110	Water? If "No", describe.	211401100 01 1 011	atanto in Biodiai geo anaior	receiving	Г	Г	-
120	Substantially Identical Outfall [074] Free of Evid	dence of Erosion? If "No", de	escribe.	Г	F	
	Substantially Identical Outfall [
130	"No", describe.				Г	<u> </u>	
	Substantially Identical Outfall [dence of Pollutants in Discha	arges			
140	and/or Receiving Water? If "No",	describe.					
Control	Measures (identify needed mair	ntenance and re	pairs, failed control meas	ures that need replac	ment. c	or a	
	tion of corrective actions in rele				,		
	Asphalt Berm [0300503040002]			"No"			
160	describe condition & need for Mai	-	· · · · · · · · · · · · · · · · · · ·				
170	Rip Rap [0300504060001] Control			escribe			_/
170	condition & need for Maintenance EnviroSoxx w/ MetalLoxx [0300	· · · · · · · · · · · · · · · · · · ·		Yo ative le O. If			10
180	"No" describe condition & need for			rectively? If	_	г	レン
	tivity exposed to stormwater (id	entify needed n	nainteance or a descriptio	n of corrective action			
comme	•	0r000 0r000 5	strolo odoguate (amazanii-t-	effective P.Pe	CA	化址	(33
200	Material loading/unloading and stand operating)? If "No" describe.	orage areas: cor	itrois adequate (appropriate		. [_/	_	_
	Transfer areas for substances in the				10		1
210	operating)? If "No" describe.	Jain. Controls au	oquate (appropriate, eliectiv	c, and	Г	Г	1
	Product/chemical storage areas (raw material): co	ntrols adequate (appropriate	e, effective,			
220	and operating)? If "No" describe.		(sile le cele transfer	· · · · · · · · · · · · · · · · · · ·	$\overline{}$	_	T

230	Liquid tank storage/secondary containment: controls adequate and operating)? If "No" describe.	(appropriate, effective,		Γ		1.
240	Industrial processing and finished product storage areas: contreffective, and operating)? If "No" describe.	ols adequate (appropriate,				ー レ
250	Equipment operation and maintenance areas: controls adequa and operating)? If "No" describe.	te (appropriate, effective,				
260	Fueling areas: controls adequate (appropriate, effective, and o describe.	perating)? If "No"		_ ' _		
270	Outdoor vehicle and equipment washing areas: controls adequand operating)? If "No" describe.	ate (appropriate, effective,				
280	Machinery: controls adequate (appropriate, effective, and operation)	ating)? If "No" describe.		Ė		F
290	Waste handling and disposal areas: controls adequate (appropoperating)? If "No" describe.	riate, effective, and		Г	Г	トレ
300	Erodible areas/construction: controls adequate (appropriate, ef "No" describe.	fective, and operating)? If		Г	Г	[v
310	Locations and sources of run-on to the site: controls adequate and operating)? If "No" describe.	(appropriate, effective,		Г		r.
320	Non-stormwater/illicit connections: controls adequate (appropri operating)? If "No" describe.	ate, effective, and		<u>г</u>	, [_	
330	Salt storage piles or pile containing salt: controls adequate (approperating)? If "No" describe.	propriate, effective, and			[
340	Dust generation and vehicle tracking: controls adequate (appro operating)? If "No" describe.	priate, effective, and	-		Г	
350	Housekeeping (Industrial materials/residues/trash in contact win adequate (appropriate, effective, and operating)? If "No" descril	th stormwater): controls			Г	
360	Leaks and spills: controls adequate (appropriate, effective, and describe.					- -
370	Sector A [03005-] Wood processing, transport or treated wood adequate (appropriate, effective, and operating)? If "No" described as a contract of the contract	storage areas: controls				<u> </u>
	ompliance					10
390	Free of incidents of observed non-compliance not already ident describe.	ified above? If "No"		_	г	[~
						10
410	onal Control Measures Are permit requirements satisfied with existing control measures additional control measures needed.	(s)? If "No" describe		_	Г	[·/
						10
.abor				The second second second		
Labor	Assigne	ed Work Date	Reg Hrs	OT Hrs	Othe	r Hrs
Burgin,	Jillian 4/30/20	18 / 14				
abor F	Report					
Comple	eted:					
Report:						
Торога						

Name/Z#: Julian Bursin /211087	
Signature (lead inspector): Der CISEC Date and Time:	4/26/18
"I confirm the information as recorded is true, accurate and complete."	3:00 pm

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title: Russell Stone GL DESHS-UTS

Signature: Date: 6/14/2018

Work Order MSGP-RI-62581

MSGP Routine Inspection Printed 5/24/2018 - 11:01 AM

- Mainte	enance Details	
	dure: MSGP Routine Facility Priority/Type: Normal / Inspection	3-38 Carpenter Shop
Projec	t: Routine Facility Inspections Contact Phone	:
Specia	5276) on: MSGP Routine Facility Inspection 1:45 - 2:00 pm	
Tasks		
#	Description	Meas. No N/A Yes
	ner Information	0.00
20 Withir	Describe the weather at time of inspection and document the temperature (F°). 19°	Sunny
40	Is the facility free of new discharges of pollutants that have occurred since the last	
<u>40</u> 50	inspection? If "Failed" describe. If "No" has a CAR been previously initiated for this new discharge?	
60	Is the facility free of discharge of pollutants at the time of inspection? If "No" describe.	
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "No" describe.	
Outfal descri	Il Inspection (identify needed maintenance and repairs, failed control measures that ription of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? If "No", describe.	need replacement, or a
100	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? If "No", describe.	
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.	
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If "No", describe.	
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? If "No", describe.	<u></u>
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.	
Contro descri	ol Measures (identify needed maintenance and repairs, failed control measures that r ption of corrective actions in relevant task comments).	need replacment, or a
160	Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	
180	EnviroSoxx w/ MetalLoxx [0300503200004] Control Measure is operating effectively? "No" describe condition & need for Maintenance, Repair, or Replacement.	f
Area/A	activity exposed to stormwater (identify needed mainteance or a description of correctent).	ctive actions in relevant task
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, and operating)? If "No" describe.	
220	Product/chemical storage areas (raw material): controls adequate (appropriate, effective, and operating)? If "No" describe.	

230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.		1	F	
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			Г	F
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		Г	
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			F	
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	г		I	_
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.	÷		Ë	-
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		<u>-</u> -	<u> </u>
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		<u>-</u>	<u> </u>
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		Г	
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		[V	Г
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.				
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		Г	レ
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		г	[/
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		Г	
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		Г	~
Non-Co	ompliance				
390	Free of incidents of observed non-compliance not already identified above? If "No" describe.	г		г	[·
A dditio	onal Control Measures			<u>.</u>	
Additio	Are permit requirements satisfied with existing control measure(s)? If "No" describe				
410	additional control measures needed.			厂.	F
_abor					
Labor	Work Date Reg Hrs	ОТ Н	-Irs	Othe	er Hrs
The Art of Control of Control			—		
abor R	Report	PROPERTY OF THE PARTY OF THE PA			
Comple	eted:				
Report:					

WO ID: MSGP-RI- 62581 Page 2 of 3

Name/Z#: Tillian Bursin /211081

Signature (lead inspector):	Tillian Brussin	-, DEP,	Date and Time: 5 31 LY	2:00 PM
- ,		CI	SEC	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title:	Russell Stone	GL	DESHS-UCS	
Signature:	n OF		Date:	6/14/2018

Los Alamos National Lab - ADESH

- Maintenance Details

Work Order MSGP-RI-62643

MSGP Routine Inspection Printed 6/6/2018 - 12:55 PM

		Target: 6/30/2018 Priority/Type: Normal / Inspection Department: Utilities and Infras	tructure TA-3-38 Carpenter Shop Contact: Phone:
_	,	Insp. 16/2	
Reas	on: 2018 June Inspections	1:15-	1:30
Speci	al Instructions: NMR053195		
Tasks			
#	Description		Meas. No N/A Yes
Weat	her Information		G20
20	Describe the weather at time of it	nspection and document the tempera	ature (F°). Bot Cloudy F F
Withi	n the Facility Boundary		-
40	Is the facility free of new discharg	ges of pollutants that have occurred s	since the last
<u>40</u> 50	inspection? If "Failed" describe.	usly initiated for this new discharge?	
60		pollutants at the time of inspection?	If "No" describe
-	Is the facility free of evidence of,	or the potential for, pollutants enterin	
70	system. If "No" describe.		
Outfa descr	Il Inspection (identify needed main iption of corrective actions in rele	ntenance and repairs, failed contro	ol measures that need replacement, or a
90		Evidence of Erosion? If "No", describ	De. FF
100	Monitored Outfall [073] Flow Disdescribe.	ssipation Devices Operating Effective	ely? If "No",
110	Monitored Outfall [073] Free of Water? If "No", describe.	Evidence of Pollutants in Discharges	and/or Receiving
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If	"No", describe.
130	Substantially Identical Outfall ["No", describe.	074] Flow Dissipation Devices Opera	ating Effectively? If
140	Substantially Identical Outfall [and/or Receiving Water? If "No",	074] Free of Evidence of Pollutants in describe.	n Discharges
Contr descr	ol Measures (identify needed mair iption of corrective actions in rele	ntenance and repairs, failed contro	ol measures that need replacment, or a
160	Asphalt Berm [0300503040002]	Control Measure is operating effective ntenance, Repair, or Replacement.	vely? If "No"
170	condition & need for Maintenance		
180	EnviroSoxx w/ MetalLoxx [0300 "No" describe condition & need fo	503200004] Control Measure is oper r Maintenance, Repair, or Replaceme	rating effectively? If ent.
Area/A	Activity exposed to stormwater (id ent).	entify needed mainteance or a des	scription of corrective actions in relevant task
200	,	orage areas: controls adequate (appr	ropriate, effective,
210	Transfer areas for substances in boperating)? If "No" describe.	oulk: controls adequate (appropriate,	
220	Product/chemical storage areas (rand operating)? If "No" describe.	aw material): controls adequate (app	propriate, effective,

230	Liquid tank storage/secondary containment: controls adeand operating)? If "No" describe.	quate (approp	riate, effective,		П	F/ F
240	Industrial processing and finished product storage areas: effective, and operating)? If "No" describe.	controls adeq	uate (appropriate,		г	ГБ
250	Equipment operation and maintenance areas: controls ac and operating)? If "No" describe.				Г	ГГ
260	Fueling areas: controls adequate (appropriate, effective, a describe.					ГV Г
270	Outdoor vehicle and equipment washing areas: controls a and operating)? If "No" describe.	adequate (app	ropriate, effective,		П	E/
280	Machinery: controls adequate (appropriate, effective, and	operating)? If	"No" describe.			ГБ
290	Waste handling and disposal areas: controls adequate (a operating)? If "No" describe.	ppropriate, eff	ective, and		Г	ГГ
300	Erodible areas/construction: controls adequate (appropria "No" describe.	ate, effective, a	and operating)? If		Г	ГБ
310	Locations and sources of run-on to the site: controls adec and operating)? If "No" describe.	quate (appropr	iate, effective,		Г	ГГ
320	Non-stormwater/illicit connections: controls adequate (approperating)? If "No" describe.	propriate, effec	ctive, and		Г	
330	Salt storage piles or pile containing salt: controls adequat operating)? If "No" describe.	e (appropriate	, effective, and		Г	ГГ
340	Dust generation and vehicle tracking: controls adequate (operating)? If "No" describe.	appropriate, e	ffective, and		П	
350	Housekeeping (Industrial materials/residues/trash in conta adequate (appropriate, effective, and operating)? If "No" of		vater): controls		Г	ГГ
360	Leaks and spills: controls adequate (appropriate, effective describe.	e, and operatin	g)? If "No"		Г	
370	Sector A [03005-] Wood processing, transport or treated adequate (appropriate, effective, and operating)? If "No" of		areas: controls			
Non Co	ompliance					
NOII-CO	Free of incidents of observed non-compliance not already	identified abo	vo2 If "No"			
390	describe.	identified abo	verii ivo		Г	п п
A dditio	nal Cantral Magaziros					
Additio	nal Control Measures Are permit requirements satisfied with existing control measures	ocuro(o)2 If "N	o" doporibo			
410	additional control measures needed.	asure(s)? II N	o describe		工	<u> </u>
.abor						
Labor		ssigned	Work Date	Reg Hrs	OT Hrs	Other Hr
Burgin, abor R		4/2018 / 1			Yes (as an arrange and arrange arrange arrange and arrange	
	eted:					
Report:						
narros carros a criscinas o accordos				Baddida Madisa Luda a specie como se persona		The state of the s

WO ID: MS6P-R1-10264 Fage 2 of 3

Name/Z#: Trutan Bursin, DEP/211081

Signature (lead inspector):	USE C	_Date and Time:	6/29/18
"I confirm the information as recorded is true, accurate and complete."			1:30 PM

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for sinformation, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title:

| Compared to the possibility of fine and imprisonment for knowing violations".

| Compared to the penalties for significant penalties fo

Maintenance Details

Work Order MSGP-RI-62782

MSGP Routine Inspection Printed 7/2/2018 - 5:13 PM

-	M: 5/31/2018 Resulting Facility Inspection (EPC-CP-Form-1020.1) Priority/Type: Normal / Inspection Department: Utilities and Infrastructure Lit: Routine Facility Inspections July 2018 (P-MSGP-RI-5293) Contact Phone:	3-38 Carpenter Shop
Reaso	n: MSGP Routine Facility Inspection 9:45 - 10:00 Am	
Specia	al Instructions: NMR053195	
Tasks		
# Weath	Description ner Information	Meas. No N/A Yes
20	Describe the weather at time of inspection and document the temperature (F°).	Ple
40	In the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed" describe.	
50	If "No" has a CAR been previously initiated for this new discharge?	
60	Is the facility free of discharge of pollutants at the time of inspection? If "No" describe.	
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "No" describe.	
Outfal descri	I Inspection (identify needed maintenance and repairs, failed control measures that n iption of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? If "No", describe.	
	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? If "No",	
100	describe.	
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.	
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If "No", describe.	
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? If "No", describe.	ГГГ
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.	
descri	ol Measures (identify needed maintenance and repairs, failed control measures that n ption of corrective actions in relevant task comments).	eed replacment, or a
	Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No"	
160	describe condition & need for Maintenance, Repair, or Replacement.	
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	
180	EnviroSoxx w/ MetalLoxx [0300503200004] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	f
Area/A	activity exposed to stormwater (identify needed mainteance or a description of correctent).	ctive actions in relevant task
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, and operating)? If "No" describe.	
	Product/chemical storage areas (raw material): controls adequate (appropriate, effective,	
220	and operating)? If "No" describe.	
230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective,	

	and operating)? If "No" describe.				
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		П	П	T-
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г	Г	F
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г		
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г	F	
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		П	Г	C
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.			Г	F
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.		П	Г	F
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г		Г
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.				
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.			П	
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.				
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.				[v
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			П	Г
90 Additio	Free of incidents of observed non-compliance not already identified above? If "No" describe. Inal Control Measures				
110	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.				
abor					
_abor Burgin,	Assigned Work Date Jillian 7/31/2018 / 1	Reg Hrs	OT H	rs Oth	er Hr
abor F	Report				
Comple					
Report:					
Report:	NSGP-R1-62782Page_2 of 3				100000000000000000000000000000000000000

Signature (lead inspector): DEP CISE C Date and Time: 71818

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

230

Work Order MSGP-RI-62866

MSGP Routine Inspection Printed 8/2/2018 - 9:05 AM

Mainte	nance Details	months of the control of the	* White	For all abstracts accommons.
-	ted: 7/17/2018 12:20:02 PM ure: MSGP Routine Facility Inspection (EPC-CP-Form- 1020.1) Target: 8/31/2018 □ MSGP Program RG121.9 Department: Utilities and Infrastructure # TA-3-38 Carpen	ter Sh	ор	
Last Pi	N : 6/29/2018			
Project	Routine Facility Inspections Aug 2018 (P-MSGP-RI-5301) Contact: Phone: 2018 August Inspections II:15 - II:30 Am			
Reasor	: 2018 August Inspections			
Special	Instructions: NMR053195			
Tasks -				The second secon
#	Description Meas.	No	N/A	Yes
Weath	er Information			
20	Describe the weather at time of inspection and document the temperature (F°).		Г	Tu
Within 40	the Facility Boundary Is the facility free of new discharges of pollutants that have occurred since the last inspection? If "Failed" describe.			
50	If "No" has a CAR been previously initiated for this new discharge?			1
50 60	Is the facility free of discharge of pollutants at the time of inspection? If "No" describe.			
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "No" describe.			
descrip 90	Inspection (identify needed maintenance and repairs, failed control measures that need replace ition of corrective actions in relevant task comment) Monitored Outfall [073] Free of Evidence of Erosion? If "No", describe.	шепт, 	Г	
100	Monitored Outfall [073] Flow Dissipation Devices Operating Effectively? If "No", describe.			طاد: <u>اسا</u>
110	Monitored Outfall [073] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.	Г	Г	[·
120	Substantially Identical Outfall [074] Free of Evidence of Erosion? If "No", describe.	Г	Г	TV
130	Substantially Identical Outfall [074] Flow Dissipation Devices Operating Effectively? If "No", describe.			
140	Substantially Identical Outfall [074] Free of Evidence of Pollutants in Discharges and/or Receiving Water? If "No", describe.			
Contro descrip	Measures (identify needed maintenance and repairs, failed control measures that need replacment tion of corrective actions in relevant task comments). Asphalt Berm [0300503040002] Control Measure is operating effectively? If "No"	ient, c	ır a	
160	describe condition & need for Maintenance, Repair, or Replacement.	Г		
170	Rip Rap [0300504060001] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	Г		[]
180	EnviroSoxx w/ MetalLoxx [0300503200004] Control Measure is operating effectively? If "No" describe condition & need for Maintenance, Repair, or Replacement.	厂		<u></u>
Area/Ad comme	ctivity exposed to stormwater (identify needed mainteance or a description of corrective actions nt).	in rel	evant t	ask
200	Material loading/unloading and storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		
210	Transfer areas for substances in bulk: controls adequate (appropriate, effective, and operating)? If "No" describe.	Г		
220	Product/chemical storage areas (raw material): controls adequate (appropriate, effective, and operating)? If "No" describe.		_	

Liquid tank storage/secondary containment: controls adequate (appropriate, effective,

	and operating)? If "No" describe.				
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		·		
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			<u></u>	
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.		 -	 -	
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		г		
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.		Г		
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.			Г	
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.		П	<u></u>	
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.				
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.				
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.				
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.			Г	r
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				
110	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.			Г	F
abor _abor	Assigned Work Date	Reg Hrs	OT Hre	Othe	r H
Burgin, J		ixeg i ii s	OT HIS	- —	
abor Ro Complet Report:				MAAN Inquisit American	
D: <u> </u>	156P-R1-6286 Page 2 of 3			nan e en enneme e manera de m	TRA-S a conference
e/Z#:					
	DEP/				

11:30 And

"I confirm the information as recorded is true, accurate and complete."

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet	definition in Section B.11.A, eg.	., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leade	r)
Print name and title:	Russell Stone	- GL DESKS-Uts	
Signature: Rusa	ell St	Date: 9/29/2018	

- Maintenance Details

Work Order MSGP-RI-63003

MSGP Routine Inspection Printed 9/4/2018 - 3:25 PM

-	ested: 8/22/2018 3:08:00 PM dure: MSGP Routine Facility Inspection (EPC-CP-Form- 1020.1) PM: 7/18/2018	Target: 9/30/2018 Priority/Type: / Inspection Department: Utilities and Infrastructure	☑ MSGP Program 品 RG121.9 ♣ TA-3-38 Carpenter Shop
Projec		9/27/18	Contact: Phone:
	on: 2018 September Inspections al Instructions: NMR053195	3:15-3:30	DM_
Tasks #	Description		Meas. No N/A Yes
Weat	ner Information		Meas. No N/A Yes
20		inspection and document the temperature (F	73°Clas. F F F
Withi	n the Facility Boundary	The second of th	, summer of the second
40		ges of pollutants that have occurred since the	e last
50	If "No" has a CAR been previo	ously initiated for this new discharge?	
60	Is the facility free of discharge o	f pollutants at the time of inspection? If "No" of	lescribe.
70	Is the facility free of evidence of system. If "No" describe.	, or the potential for, pollutants entering the dr	ainage
Outfa descr	Il Inspection (identify needed ma iption of corrective actions in rel	intenance and repairs, failed control meas	ures that need replacement, or a
90		f Evidence of Erosion? If "No", describe.	г г г⁄
100		issipation Devices Operating Effectively? If "N	No",
<u>110</u>	Monitored Outfall [073] Free of Water? If "No", describe.	f Evidence of Pollutants in Discharges and/or	Receiving
120		[074] Free of Evidence of Erosion? If "No", de	
130	"No", describe.	[074] Flow Dissipation Devices Operating Eff	
140	Substantially Identical Outfall and/or Receiving Water? If "No",	[074] Free of Evidence of Pollutants in Discharge describe.	arges
Contr descr	ption of corrective actions in rel		
160	describe condition & need for Ma	Control Measure is operating effectively? If intenance, Repair, or Replacement.	
170	condition & need for Maintenance		
180	"No" describe condition & need f	0503200004] Control Measure is operating et or Maintenance, Repair, or Replacement.	fectively? If
Area/A	Activity exposed to stormwater (ident).	dentify needed mainteance or a descriptio	n of corrective actions in relevant task
200	Material loading/unloading and s and operating)? If "No" describe.	torage areas: controls adequate (appropriate	effective,
210	operating)? If "No" describe.	bulk: controls adequate (appropriate, effective	
220	Product/chemical storage areas and operating)? If "No" describe.	(raw material): controls adequate (appropriate	e, effective,

230	Liquid tank storage/secondary containment: controls ade and operating)? If "No" describe.	equate (appropriate, effective,			П	
240	Industrial processing and finished product storage areas effective, and operating)? If "No" describe.	: controls adequate (appropriate,				<u></u>
250	Equipment operation and maintenance areas: controls a and operating)? If "No" describe.			Г	Г	_
260	Fueling areas: controls adequate (appropriate, effective, describe.				<u></u>	
270	Outdoor vehicle and equipment washing areas: controls and operating)? If "No" describe.	adequate (appropriate, effective,			F	
280	Machinery: controls adequate (appropriate, effective, and	d operating)? If "No" describe.		П	Г	1
290	Waste handling and disposal areas: controls adequate (a operating)? If "No" describe.				Г	「
300	Erodible areas/construction: controls adequate (appropria "No" describe.				П	[]
310	Locations and sources of run-on to the site: controls ade and operating)? If "No" describe.				F	
320	Non-stormwater/illicit connections: controls adequate (ap operating)? If "No" describe.	propriate, effective, and			F-/	
330	Salt storage piles or pile containing salt: controls adequa operating)? If "No" describe.	te (appropriate, effective, and		Г	F-/	
340	Dust generation and vehicle tracking: controls adequate operating)? If "No" describe.	(appropriate, effective, and		П	Г	
350	Housekeeping (Industrial materials/residues/trash in contadequate (appropriate, effective, and operating)? If "No"	tact with stormwater): controls describe.		Г	Г	F~
360	Leaks and spills: controls adequate (appropriate, effective describe.	e, and operating)? If "No"		Г	Г	
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				Г	レ
Non-Co	ompliance					
390	Free of incidents of observed non-compliance not already describe.	y identified above? If "No"			_	[]/
					<u> </u>	1
Addition 410	nal Control Measures Are permit requirements satisfied with existing control me additional control measures needed.	easure(s)? If "No" describe		_	П	E/
Labor				errer ar november (1884). El accidente		
Labor	A	ssigned Work Date	Reg Hrs	OT Hrs	s Othe	er Hrs
Burgin, .	Jillian 9,	/30/2018 / 14				
Labor R	eport				*****	
Comple	ted:					
Report:						
CONTRACTOR BY STOLEN WARRANT AND AND A COM-		MARTINET PROMISE AND A SERVICE	The second contract of the second sec			And the second s

WO ID: MSOP-RI-63003 Page 2 of 3

Name/Z#: Tillian Bursin/211087

Signature (lead inspector): Devision OFP CISE Date and Time: 912718

"I confirm the information as recorded is true, accurate and complete."

3:30PM

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title: Russell Store	GL DESHK-UIS
Signature: Russell Str.	Date: 6/26/2018

Work Order MSGP-RI-63201

MSGP Routine Inspection Printed 10/1/2018 - 12:15 PM

Maint	enan	ce Details						who are a various security of a
-		: 10/1/2018 12:09:29 PM	Target: 10/31/2018	MSGP	Program			
Proce	dure:	MSGP Routine Facility Inspection (EPC-CP-Form- 1020.1)	Priority/Type: Normal / Inspection Department: Utilities and Infrastructure	品 RG121 企 TA-3-3		ter Sh	ор	
Last P	PM:	7/18/2018						
Projec	et:	Routine Facility Inspections Oct. 2018 (P-MSGP-RI-	Inspected:	Contact: Phone:				
		5333)	10 (19118)					
Reaso	n: 2	018 October Inspections	3:00 - 3:15	0 . 4				
Specia	al Ins	tructions: NMR053195	3:00 - 3:13	PAC				
Tasks						and a manufacture with a second control of the second control of t	reda videlpro-ver nessessanos.	
#	De	escription			Meas.	No	N/A	Yes
Weath	her In	formation						
20	De	escribe the weather at time of in	spection and document the temperature (F°)			Г	1	-
Withi	n the	Facility Boundary						
40	ls		es of pollutants that have occurred since the	last			_	-
50		· · · · · · · · · · · · · · · · · · ·	sly initiated for this new discharge?			<u> </u>		
60			pollutants at the time of inspection? If "No" de	escribe.		Ė	i i	Ė
70	Is the facility free of evidence of, or the potential for, pollutants entering the drainage system. If "No" describe.						Г	
Outfo	II Inci	naction /identify panded mair	tenance and repairs, failed control measu	414	dl			
		of corrective actions in rele		ires mai nee	u replace	ement,	or a	
90	Mc	onitored Outfall [073] Free of I	Evidence of Erosion? If "No", describe.			Г		I
100		onitored Outfall [073] Flow Dis scribe.	sipation Devices Operating Effectively? If "No	0",		-		
110		onitored Outfall [073] Free of later? If "No", describe.	Evidence of Pollutants in Discharges and/or F	Receiving				
120	<u>Su</u>	ıbstantially Identical Outfall [074] Free of Evidence of Erosion? If "No", de	scribe		<u> </u>		
130		ibstantially Identical Outfall [6 o", describe.	774] Flow Dissipation Devices Operating Effe	ctively? If				
140		ibstantially Identical Outfall [ud/or Receiving Water? If "No", o	074] Free of Evidence of Pollutants in Discha describe.	rges				
Contr	ol Me	easures (identify needed main	tenance and repairs, failed control measu	res that nee	d replac	nent, c	r a	
descr	-	of corrective actions in rele	•					
160			Control Measure is operating effectively? If "Internance, Repair, or Replacement.	No"		_	_	
170	Rij		ol Measure is operating effectively? If "No" de	escribe			<u></u>	
180	En	viroSoxx w/ MetalLoxx [0300	503200004] Control Measure is operating eff r Maintenance, Repair, or Replacement.	ectively? If				
			entify needed mainteance or a description	of corrective	e action	s in rel	evant t	ask
comm	ent).							
200		aterial loading/unloading and sto d operating)? If "No" describe	orage areas: controls adequate (appropriate,	effective,		_	-	T

Transfer areas for substances in bulk: controls adequate (appropriate, effective, and

Product/chemical storage areas (raw material): controls adequate (appropriate, effective, and operating)? If "No" describe.

210

220

operating)? If "No" describe.

230	Liquid tank storage/secondary containment: controls adequate (appropriate, effective, and operating)? If "No" describe.		Γ	F- F	
240	Industrial processing and finished product storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		<u> </u>		_
250	Equipment operation and maintenance areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			 г	_
260	Fueling areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			<u> </u>	
270	Outdoor vehicle and equipment washing areas: controls adequate (appropriate, effective, and operating)? If "No" describe.			r/ r	
280	Machinery: controls adequate (appropriate, effective, and operating)? If "No" describe.			ĖĖ	_
290	Waste handling and disposal areas: controls adequate (appropriate, effective, and operating)? If "No" describe.		r r	_	
300	Erodible areas/construction: controls adequate (appropriate, effective, and operating)? If "No" describe.			r F	
310	Locations and sources of run-on to the site: controls adequate (appropriate, effective, and operating)? If "No" describe.	-			
320	Non-stormwater/illicit connections: controls adequate (appropriate, effective, and operating)? If "No" describe.				
330	Salt storage piles or pile containing salt: controls adequate (appropriate, effective, and operating)? If "No" describe.				
340	Dust generation and vehicle tracking: controls adequate (appropriate, effective, and operating)? If "No" describe.			r r	_
350	Housekeeping (Industrial materials/residues/trash in contact with stormwater): controls adequate (appropriate, effective, and operating)? If "No" describe.		r r	_	
360	Leaks and spills: controls adequate (appropriate, effective, and operating)? If "No" describe.			_	
370	Sector A [03005-] Wood processing, transport or treated wood storage areas: controls adequate (appropriate, effective, and operating)? If "No" describe.				_
Non-Co	ompliance				_
390	Free of incidents of observed non-compliance not already identified above? If "No" describe.		Jam	г г <u>.</u>	_
					_
Additio	nal Control Measures				
410	Are permit requirements satisfied with existing control measure(s)? If "No" describe additional control measures needed.			<u> </u>	_
_abor					
Labor		eg Hrs	OT Hrs	Other Hr	s
Burgin,	Jillian 10/1/2018 / 1				
abor R	Report				
Comple	eted:				
Report:					

-			minore transferrence consider : Access		

WOID: MSGP-RI-63201 Page 2 of 3

Name/Z#: Dillou Burgin / 211081

Signature (lead inspector): Pour DEP CISE Date and Time: 10 (19118

"I confirm the information as recorded is true, accurate and complete."

3:15 PM

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DESH Group Leader, EPC Group Leader)

Print name and title: Kussell Hones GL

Signature: Date: 12/5/2018



Environmental Protection & Compliance Division Environmental Compliance Programs (EPC-CP)

To/MS: Jillian Burgin, DESHS-CPCS, K481

Thru/MS: Terrill Lemke, EPC-CP, (E-File)

From/MS: Holly Wheeler, EPC-CP, (E-File) Volu

Phone/Fax: 667-1312

Symbol: 0EPC-DO-16-303 Date: 0ET 1 2016

Subject:

National Pollutant Discharge Elimination System (NPDES) Permit No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for April and May of 2016 for the TA-3-38 Metals Fabrication Shop and TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA Forms documenting visual assessments performed during the first quarter of monitoring at the TA-3-38 Metals Fabrication Shop and the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the QVA forms shall be incorporated into your MSGP Storm Water Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of storm water discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, LANS has designated the following MSGP monitoring quarters.

April - May Quarter 1:

Quarter 2: June - July

Quarter 3: August - September Quarter 4: October - November

The attached QVA forms document the following information as required by Part 3.2.2 of the 2015 MSGP and were completed by Environment Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.

Part 3.2.3 of the 2015 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for



personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

TWL:HLW/lm

Enclosures: 1. Quarterly Visual Assessment Forms, First Quarter, 2016 Monitoring Year

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07302	MSGP-53620
TA-3-38 Metals Fab Shop	MSGP00201	MSGP-53592

Cy: Philbert Romero, DESHS-CPCS, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

Los Alamos National Lab

Work Order MSGP-53620

						Ø1 10	IOOI OOOL
				Printed 5/2	MS 2/2016 - 10:	SGP M	lonitoring Station (Duplicate Cop
Main	tenance Details			14.55 (0.55 (0.45 ((- гриодіо Сор
Requ	ested: 4/28/2016 1:01:00 PM	Target:	5/31/2016	MSCD	Drogram		
	edure: MSGP Quarterly Visual	Priority/Type:	520,772	MSGP			
	Assessment (EPC-CP-		Utilities and	♣ TA-3-38		r Sho	n
Last	Form-1021.2) PM: 4/20/2016		Infrastructure	Monitor	ed Outfall	(073)	P
Proje		S X		MSGP0	7301		
rioje	Q1 2016 (P-MSGP-4708)	•					
Reas	on: MSGP Q1 2016 Visual Asses	sment		Contact: Phone:			*
Speci	ial Instructions: NMR053195		9	*			
Tasks)				1		
#	Description		Detine				
1700	20		Control of the Contro	Meas. Initials	Failed	N/A	Complete
The r	esult of this VA applies to assoc	iated SIOs as def	ined in the SWPP	P, where applicabl	e.		
Samp	ole information						
	Document the monitoring Perio	d by using the	mpi				
30	Monitoring Period lookup table		1011				
35	Is visual assessment performed sample? (Use filtered only if un	d on an unfiltered					
-	Document the Date/Time Disch		.)				
	"Reading" field of this line (usin	g mm/dd/yy hh:mm	s leel.	10.11			
40	format).	N. 10	2/15/14	10:16			8
	Document the Date/time sample	e collected in the	11				e ming waters a second
50	"Reading" field of this line (usin format).	g mm/aa/yy nh:mm	5/15/16	10:16		_	
	Document the Date/time sample	e visually assessed	d in				_/_
60	the "Reading" field of this line (a	using mm/dd/yy	5/10/1	10 1361			/
60	hh:mm format).			1001			
	Document the nature of dischar Precipitation Type lookup table.	ge using the	Qn.				20
70	amount (in) in the "Reading" field	d of this line.	rkl	0.15 in			
	Sample collected in first 30 min	utes of discharge?	lf				/
80	"Failed" or unknown, provide re-	ason in comments	of				
50	this line. Previous storm ended >72 hour	o before start of				口.	
	storm? If "Failed", provide reaso	s before start of	this				1
90	line.	The second secon			.not	П	CALAGORIA
Param	eters	KS	2	77	-17		MARIE
110	Is sample colorless? If "Failed",	describe.	Drown		0	_	
5 5 6	Is sample oderless? If "Failed"			Control of the Contro	/		

observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line. Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in 130 comments of this line. Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this 140 150 Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If

	Is sample free of suspended solids? If no, docum observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table. provide description in comments of this line.	nent			
170	is sample foamless after gently shaking? If no describe foam color and location ('on the surface 'in the sample') in the comments of this line.	or or			
180	Is sample devoid of an oil sheen? If no, describe color and thickness (e.g. flecks, globs) in the comments of this line.			75 4 16 16	/
190	is sample free of other obvious indicators of pollution? If no, describe in the comments of this line.				_
QI	Document Name VA signature MSGP Visual Assessment Signature	Туре	Location	NING AND THE COLUMN TO THE STATE OF THE STAT	
abor	Report			O VOLE ON STATEMENT OF E	1000 1000 - 1000
Compl	leted: Failure:		Meter 1:	Meter 2:	
Repor	t:				
12 217					

WO ID: MSGP-53592 Page 3 of 3
Signature (collecting sample):
Signature (conducting visual assessment):
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., EPC Group Leader or designee)
Print name and title: Arthony R. Grieggs, EPC-CP Group Leader
Signature: A R Greege Date: 6/9/2016



memorandum

Environmental Protection & Compliance Division Environmental Compliance Programs (EPC-CP) To/MS: Jillian Burgin, DESHS-UIS,

Thru/MS: Terrill Lemke, EPC-CP, (E-File)

From/MS: Holly Wheeler, EPC-CP, (E-File)

Phone/Fax: 667-1312

Symbol: EPC-DO:17-020

Date: JAN 1 2 2017

Subject: National Pollutant Discharge Elimination System (NPDES) Permit No. NMR053195,

Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for

June and July of 2016 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA Forms documenting visual assessments performed during the second quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the QVA form shall be incorporated into your MSGP Storm Water Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of storm water discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, LANS has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Ouarter 3: August – September Ouarter 4: October - November

The attached QVA forms document the following information as required by Part 3.2.2 of the 2015 MSGP and were completed by Environment Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.

Part 3.2.3 of the 2008 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen



EPC-DO-17-20 Jillian Burgin

conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

TWL:HLW/am

Enclosure: 1. Quarterly Visual Assessment Forms, Second Quarter, 2016 Monitoring Year

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07401	MSGP-54927

Copy: Russell Stone, DESHS-UIS, (E-File)

<u>Adesh-records@lanl.gov</u>, (E-File)

<u>lasomailbox@nnsa.doe.gov</u>, (E-File)

<u>locatesteam@lanl.gov</u>, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

Quarterly Visual Assessment Forms Second Quarter, 2016 Monitoring Year

EPC-DO-17-020

Date:	J	AN 12	2017	

Los Alamos National Lab

130

140

150

comments of this line.

Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this

Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide

description in comments of this line.

Work Order MSGP-54927

X C

MSGP Monitoring Stations

		_							6/2016 - 3:48 F
Vlainte	enance	Details							
Reque	ested By:	Banar, Alethea on	Target:	6/10/2016		MSGP F	Program		
		6/6/2016 3:29:00 PM	Priority/Type:			♣ RG121.			
Proced	dure:	MSGP Quarterly Visual Assessment (EPC-CP-	Department:	Utilities and		A TA-3-38			р
		Form-1021.2)		Infrastructure		Monitore			
Last P	M:	5/24/2016				Substant MSGP0		tical C	outfall (074)
						INSGPU	7401		
Reaso	n: SIO \	/isual Assessment at 074				Contact: Ba Phone: 66		hea	
Specia	al Instruc	tions: NMR053195							
Tasks									
. #	Descr	iption		Rating	Meas.	Initials	Failed	N/A	Complete
The re	esult of th	nis VA applies to associ	ated SIOs as de	efined in the S	WPPP, whe	re applicabl	e.		
Sampl	le inform	ation			- /				
04043		nent the monitoring Period	by using the		June		-	-	1
30		ring Period lookup table.			_Jul	4			
35		al assessment performed e? (Use filtered only if unfi				0	П		E
		nent the Date/Time Discha			addi				
100		ng" field of this line (using	mm/dd/yy hh:m	ım	ago116			V	192.00
40	format				14:30			L	
		nent the Date/time sample ng" field of this line (using			06/01/16				
50	format		, minudary y mism		14:30		Г	Г	R
		ent the Date/time sample		ed in					
00		eading" field of this line (u	sing mm/dd/yy		040110	No.	_		-
60		format).	zo using the		12,09			, il	
		nent the nature of discharg tation Type lookup table.			Δ				
70		t (in) in the "Reading" field			Raino	24"		Г	
		e collected in first 30 minu				Fe .			
90	"Failed	" or unknown, provide rea	ason in comment	ts of				-	-
80	uns im	 							
Param			. accommon		medin	M			
110		ple colorless? If "Failed",			Braw	v			
		ple oderless? If "Failed", o ation using the Odor look		r" is					
		from the lookup table, pr			o				
120		ents of this line.			Petroleu	w	N.	Г	
		ple clear? If "Failed", docu			Csecla	box report)			
		he Clarity lookup table. If		n					
	II OIII th	e lookup table, provide de	escription in						

160	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	Fine	&	ā	G
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line.	Might Foum	Æ.	_[i	[al
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line.	while			V
190	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line.				₹.
Jomp	leted: Failure:				
Repor		The Court Drown	ه ۲/۰۵۰	an to	
Repor	Potroleum odar is believed to h	are come from of a contract of	amilion of	Tallas	Con-
Repor	Petroleum odar is believed to he selvice situated over stormdown Sample did not exhibit a Sheen is		and C	at of Solo	Con .

WO ID: WSCO P-54927 Page 3 of 3
Signature (collecting sample): Date and Time: No 07 14 11:48
Signature (conducting visual assessment): Date and Time: 06/07/16 11'40
CERTIFICATION STATEMENT
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
(Signatory must meet definition in Section B.11.A, eg., FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
Print name and title: Anthony R. Griegge, EPC-CP Group Leader
Signature: AN GNEGGES Date: 9/14/2016



Environmental Protection & Compliance Division

To: Jillian Burgin, DESHS-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File)

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 17-362

Date:

SEP 1 4 2017

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for April and May of 2017 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA Forms documenting visual assessments performed during the first quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Storm Water Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of storm water discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Los Alamos National Security (LANS) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information as required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.



The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVA completed by EPC-CP representatives contained in Enclosure 1.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Anthony R. Grieggs, EPC-CP Group Leader Los Alamos National Laboratory

Manager Signature

Part 3.2.3 of the 2015 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

EPC-DO: 17-362 Jillian Burgin

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07302	MSGP-54677
TA-3-38 Carpenter Shop	MSGP07401	MSGP-60154

TWL/HLW: am

Enclosure(s):

1. Quarterly Visual Assessment Forms Requiring a Certification Statement Signature, First Quarter, 2017 Monitoring Year

Copy: Russell Stone, DESHS-UIS, (E-File)

Adesh-records@lanl.gov, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

Quarterly Visual Assessment Forms Requiring a Certification Statement Signature First Quarter, 2017 Monitoring Year

EPC-DO: 17-362

SEP 1 4 2017

Date:		

Work Order MSGP-54677

MSGP Monitoring Stations Printed 7/6/2017 - 1:37 PM (Duplicate Copy)

i	۷	ı	a	i	n	ŧ١	e	n	a	r	ì	c	e	D	6	ta	i	ls
•		۰	-				~		40	۰	u	v	~	Shaper .	~	**	10	-

Requested: 3/9/2017 11:02:00 AM

Procedure: MSGP Quarterly Visual Assessment (EPC Sig)

(EPC-CP-Form-1021.02 2)

Last PM: 6/2/2016

Project: Visual Assessments 4-1-17

(P-MSGP-5156)

Reason: MSGP Quarterly Visual Assessment

Target:5/31/2017■ MSGP ProgramPriority/Type:Normal / Inspection➡ RG121.9

Department: Utilities and Infrastructure

♣ RG121.9 ♣ TA-3-38 Carpenter Shop ♠ Monitored Outfall (073)

MSGP07302

Contact: Phone:

Tasks					
#	Description	Meas.	No	N/A	Yes
The re	sult of this VA applies to associated SIOs as defined in the SWPPP, where applicable.				
Sampl	e information				
30	Document the monitoring Period by using the Monitoring Period lookup table.	April/May	128		
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)	only filtered avail.	(X		d
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	5/9/17 16:52			C'
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	5/9/17 16:52	-8		
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	5/10/17 10:05am		S.	E.
70	Document the nature of discharge using the Precipitation Type lookup table. Document the amount (in) in the "Reading" field of this line.	rain/hail 0.42 in.	ند		
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide reason in comments of this line.		.4		TO!
Parame	eters				
110	Is sample colorless? If "Failed", describe.	tan	THE STATE OF	La.	
120	Is sample oderless? If "Failed", document observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				C
130	Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.		al		G.
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	Coarse	TK.	d	
150	Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.		, si		
160	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.			T.	
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)				
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line. (Range: 0 - 0)		al	[4]	
190	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line. (Range: 0 - 0)				

Labor Report

Completed: 5/10/2017 10:15:00 AM

Alothe Bang	5/10/2017	Signature / Name	
I confirm the information as recorde		signature / Name ete.	Date
	CERTIFICATION S	TATEMENT	
"I certify under penalty of law that this do a system designed to assure that qualified	ocument and all attachments wer I personnel properly gathered and	d evaluated the information submitted	d. Based on my inquiry of
the person or persons who manage the sy is, to the best of my knowledge and belied information, including the possibility of f	stem, or those persons directly ref, true, accurate, and complete. I	am aware that there are significant p	
the person or persons who manage the sy is, to the best of my knowledge and belie	stem, or those persons directly ref, true, accurate, and complete. I fine and imprisonment for knowi	am aware that there are significant pang violations".	enalties for submitting false
the person or persons who manage the sy is, to the best of my knowledge and belied information, including the possibility of f	stem, or those persons directly ref, true, accurate, and complete. I fine and imprisonment for knowing tion B.11.A, eg. FOD, Ops Mgr	am aware that there are significant pang violations".	enalties for submitting false

160

170

180

description in comments of this line.

Is sample foamless after gently shaking? If "Failed" describe foam color and location

Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks,

('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)

Work Order MSGP-60154

MSGP Monitoring Stations Printed 9/7/2017 - 11:01 AM

Maint	enance	Details							
Reque Taken Proce	By:	Wheeler-Benson, Holly on 5/22/2017 6:57:00 PM Wheeler-Benson, Holly MSGP Quarterly Visual Assessment (EPC Sig) (EPC-CP-Form-1021.02 2)		5/31/2017 Normal / Inspection Utilities and Infrastructure	品 RC	SGP Program 3121.9 -3-38 Carpen onitored Outfa bstantially Ide SGP07401	ter Sho		(074)
Last P Projec	4-1-17 (P-MSGP-5166)								
Reaso	n: MSGI	P Quarterly Visual Assessm	ent (EPC Sig)						
Specia	al Instruc	tions: NMR053195							
☑ Atta	ach								
Tasks							- 32		
#	Descri	ption				Meas.	No	N/A	Yes
The re	esult of th	nis VA applies to associate	ed SIOs as defi	ned in the SWPPP, where a	pplicab	le.			
Samp	le inform	ation							
30	Docum	ent the monitoring Period b	y using the Mon	itoring Period lookup table.		April/May	iol.	24	
25			n an unfiltered sa	ample? (Use filtered only if u	nfiltered				
35	unavai	lable.)				05/19/17 at	int.	24	
40		ent the Date/Time Dischard /yy hh:mm format).	e began in the "	Reading" field of this line (us	ing	apx. 10:55 hours.		d	TW.
50		ent the Date/time sample c /yy hh:mm format).	ollected in the "F	Reading" field of this line (usi	ng	05/19/17 at apx. 10:55 hours.			16/
60		ent the Date/time sample v mm/dd/yy hh:mm format).	isually assessed	in the "Reading" field of this	line	05/19/17 at 13:25 hours.		100	G/
70		ent the nature of discharge ent the amount (in) in the "I				Snow melt 0.17"			13/
80		e collected in first 30 minute in comments of this line.	s of discharge?	If "Failed" or unknown, provid	de		155	V	TO S
Param	neters								
110	is sam	ole colorless? If "Failed", de	scribe.	•## •##			r di	124	
120	"other"	is chosen from the lookup t	able, provide de	tion using the Odor lookup ta scription in comments of this	line.		id.	<u> </u>	[6]
130				using the Clarity lookup table scription in comments of this			-31	20	16/
140		ole free of floating solids? If nts of this line.	"Failed", describ	e if raw or waste material(s)	in the				100
150	Solids I			ent observation using the Set okup table, provide description			F3		TO/
	ls samp	ole free of suspended solids		cument observation using the				м 7	

1	globs) in the comments of this line. (Range: 0 - 0)			
190	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line. (Range: 0 - 0)	J	GJ.	N/
Labor F	Report			
Comple	eted: 5/19/2017 1:25:00 PM			
Report	5/22/2017 - 118432: Holly Wheeler			
1/2	Signature / Name 5/22/2017 Signature / Name Signature / Name		Dete	
I confirm	n the information as recorded is true, accurate and complete.		Date	
	CERTIFICATION STATEMENT			
a system det the person of is, to the bes	der penalty of law that this document and all attachments were prepared under my direction or supsigned to assure that qualified personnel properly gathered and evaluated the information submitted repersons who manage the system, or those persons directly responsible for gathering information, at of my knowledge and belief, true, accurate, and complete. I am aware that there are significant procluding the possibility of fine and imprisonment for knowing violations.	d. Based of the information	on my in	quiry of submitted
(Signatory	must meet definition in Section B.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Grou	up Leade	r)	
Print name a	and title: Anthony R. Grieggs, EPC-CP Group Leader			
Signature:	(See signature on file) Date:			



memorandum

Environmental Protection & Compliance Division

To: Jillian Burgin, DESHS-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File)

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 17-363

Date:

SEP 1 3 2017

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for June and July of 2017 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA Forms documenting visual assessments performed during the second quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Storm Water Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of storm water discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Los Alamos National Security (LANS) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information as required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.



The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVA completed by EPC-CP representatives contained in Enclosure 1.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Anthony R. Grieggs, EPC-CP Group Leader Los Alamos National Laboratory

Manager Signature

Part 3.2.3 of the 2015 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

Work Order MSGP-59935

MSGP Monitoring Stations Printed 9/5/2017 - 4:57 PM

Maintenance Details

Requested: 5/15/2017 12:52:00 PM

Procedure: MSGP Quarterly Visual

Assessment (EPC Sig)

(EPC-CP-Form-1021.02 2)

Last PM: 5/1/2017

Project: Visual Assessments 6-1-17

(P-MSGP-5173)

Reason: MSGP Quarterly Visual Assessment

Target: 7/31/2017 Priority/Type: / Inspection

Department: Utilities and Infrastructure

♣ TA-3-38 Carpenter Shop ♠ Monitored Outfall (073)

▲ MSGP07302

Contact: Phone:

Tasks			11-4		
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable.				
Samp	le information				
30	Document the monitoring Period by using the Monitoring Period lookup table.	Jun-July	4		
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)	Filtered only available	IX.		
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/18/17 18:06	al	, di	
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/18/17 18:06	Tol.	ed.	C.
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/20/17 9:10			
70	Document the nature of discharge using the Precipitation Type lookup table. Document the amount (in) in the "Reading" field of this line.	rain, 0.29 in	10	4	ď
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide reason in comments of this line.			w)	
Paran	neters				
110	Is sample colorless? If "Failed", describe.	light tan	EK.		-3
120	Is sample oderless? If "Failed", document observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				
130	Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.				
150	Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.		A		[e/
160	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.		ارا		E.
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)		di	.3)	
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line. (Range: 0 - 0)		- N	<u>p</u>	
190	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line. (Range: 0 - 0)				

Labor Report

Completed: 7/20/2017 9:10:00 AM

Signature / Name	7/20/2017	Signature / Name	
I confirm the information as record		ete.	Date
	CERTIFICATION S	TATEMENT	
"I certify under penalty of law that this ca system designed to assure that qualified	ed personnel properly gathered and	d evaluated the information submitted	d. Based on my inquiry of
the person or persons who manage the s is, to the best of my knowledge and beli information, including the possibility of	ef, true, accurate, and complete. I	am aware that there are significant pe	
is, to the best of my knowledge and beli information, including the possibility of	ef, true, accurate, and complete. I fine and imprisonment for knowi	am aware that there are significant pand in graph of the significa	enalties for submitting false
is, to the best of my knowledge and beli information, including the possibility of (Signatory must meet definition in Sec	ef, true, accurate, and complete. I fine and imprisonment for knowi	am aware that there are significant pand in graph of the significa	enalties for submitting false

EPC-DO: 17-363 Jillian Burgin

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07302	MSGP-59935
TA-3-38 Carpenter Shop	MSGP07401	MSGP-60290
TA-3-38 Carpenter Shop	MSGP07302	MSGP-60907
TA-3-38 Carpenter Shop	MSGP07401	MSGP-60908

TWL/HLW: am

Enclosure(s):

1. Quarterly Visual Assessment Forms Requiring a Certification Statement Signature, First Quarter, 2017 Monitoring Year

Copy: Russell Stone, DESHS-UIS, (E-File)

Adesh-records@lanl.gov, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

Quarterly Visual Assessment Forms Requiring a
Certification Statement Signature
Second Quarter, 2017 Monitoring Year

EPC-DO: 17-363

Date:				
Duto.				

Work Order MSGP-60290

MSGP Monitoring Stations Printed 9/5/2017 - 5:00 PM (Duplicate Copy)

I	M	la	in	to	na	n	6	n	eta	ile	6
ı	196	10		ILC	110	1101		1.7	e la	803	9

Requested: 5/30/2017 11:28:00 AM

Procedure: MSGP Quarterly Visual

Assessment (EPC Sig)

(EPC-CP-Form-1021.02 2)

Last PM: 5/31/2017

Project: SIO Visual Assessments

6/1/17 (P-MSGP-5188)

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Special Instructions: NMR053195

Target: 7/31/2017 MSGP Program Priority/Type: Normal / Inspection

Department: Utilities and Infrastructure

ឝ្ឋិ RG121.9

ATA-3-38 Carpenter Shop Monitored Outfall (073)

Substantially Identical Outfall (074)

₼ MSGP07401

Contact: Phone:

Tasks					
#	Description	Meas.	No	N/A	Yes
The r	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable.				
Samp	le information				
30	Document the monitoring Period by using the Monitoring Period lookup table.	Jun- Jul	4		16/
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)				
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	6/26/17 12:50			[6/
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).			П	[·
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	6/26/17 13:05	Г	<u> </u>	1
70	Document the nature of discharge using the Precipitation Type lookup table. Document the amount (in) in the "Reading" field of this line.	Rain 0.5in	al		10/
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide reason in comments of this line.		-24	- I	E.
Paran	neters				
110	Is sample colorless? If "Failed", describe.		-	.8	
120	Is sample oderless? If "Failed", document observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.		à	Б	
130	Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	Slightly	IX.		
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	Fine			[6/
150	Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				E/
160	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	Fine	ix.		
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)				[*
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line. (Range: 0 - 0)				[6/
190	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line. (Range: 0 - 0)	-	Tal.	141	C/
					The state of the s

Labor Report

Completed: 6/26/2017 1:05:00 PM			
Report: Alethea Banar		Waster Administration (View)	- spraying
A WAL Bon ~ Signature / Name I confirm the information as recorded is to	7/5/2017 Date true, accurate and comp	Signature / Name	Date
	CERTIFICATION	STATEMENT	
"I certify under penalty of law that this docume a system designed to assure that qualified perso the person or persons who manage the system, is, to the best of my knowledge and belief, true information, including the possibility of fine an	onnel properly gathered as or those persons directly: e, accurate, and complete.	nd evaluated the information submitted responsible for gathering information, a I am aware that there are significant pe	Based on my inquiry of the information submitted
(Signatory must meet definition in Section B	3.11.A, eg. FOD, Ops Mg	r, DSESH Group Leader, EPC Grou	p Leader)
Print name and title: Anthony R. Grieggs.	EPC-CP Group Leader		
Signature: (See signature on file)	r	Date:	

Work Order MSGP-60907

MSGP Monitoring Stations Printed 9/5/2017 - 4:59 PM

Maintenance Details

Requested By: Banar, Alethea on

7/27/2017 9:04:00 AM

Target: 7/31/2017 Priority/Type: / Inspection

Taken By: Procedure:

Banar, Alethea

Department: Utilities and Infrastructure MSGP Quarterly Visual

Assessment (EPC Sig) (EPC-CP-Form-1021.02

2)

Last PM:

7/26/2017

Project:

Visual Assessments 6-1-

17 (P-MSGP-5173)

Monitored Outfall (073) **№** MSGP07302

♣ TA-3-38 Carpenter Shop

MSGP Program

品 RG121.9

Contact: Banar, Alethea Phone: 699-5836

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

asks					
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable	e.			
Samp	le information				
30	Document the monitoring Period by using the Monitoring Period lookup table.	June-July	ad.	40	
5	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)				6
10	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 10:54 MST			
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 10:54 MST		Г	
0	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 12:15 MDT	al		
0	Document the nature of discharge using the Precipitation Type lookup table. Document the amount (in) in the "Reading" field of this line.	rain 0.99in			
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide reason in comments of this line.				
aram	eters				
10	Is sample colorless? If "Failed", describe.	light tan		4	
20	Is sample oderless? If "Failed", document observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				
30	Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	cloudy	[X		
40	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	vegetation	(X		, di
50	Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				
60	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	fine	[X		-
70	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)				
80	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line. (Range: 0 - 0)			П	W.
90	Is sample free of other obvious indicators of pollution? If "Failed", describe in the comments of this line. (Range: 0 - 0)			Б	

Labor Report		
Completed: 7/26/2017 12:15:00	PM	
Report: Alethea Banar		
AldtlBonor	7/27/2017	
Signature / Name I confirm the information as reco	Date Signature / Name orded is true, accurate and complete.	Date
	CERTIFICATION STATEMENT	
I certify under penalty of law that this	s document and all attachments were prepared under my direction of	or supervision in accordance with
system designed to assure that quality the person or persons who manage the s, to the best of my knowledge and be	s document and all attachments were prepared under my direction of the direction of the direction of the directly properly gathered and evaluated the information subsystem, or those persons directly responsible for gathering information, true, accurate, and complete. I am aware that there are significant fine and imprisonment for knowing violations.	mitted. Based on my inquiry of ation, the information submitted
system designed to assure that qualified person or persons who manage the s, to the best of my knowledge and be information, including the possibility of	Tied personnel properly gathered and evaluated the information sub- system, or those persons directly responsible for gathering informa- lief, true, accurate, and complete. I am aware that there are signification.	mitted. Based on my inquiry of ation, the information submitted cant penalties for submitting false
system designed to assure that qualify the person or persons who manage the state of my knowledge and be nformation, including the possibility of	Tied personnel properly gathered and evaluated the information subsystem, or those persons directly responsible for gathering informatief, true, accurate, and complete. I am aware that there are significant fine and imprisonment for knowing violations". ection B.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC	mitted. Based on my inquiry of ation, the information submitted cant penalties for submitting false

Work Order MSGP-60908

MSGP Monitoring Stations Printed 9/5/2017 - 5:00 PM

Maintenance Details

Requested By: Banar, Alethea on

7/27/2017 9:14:00 AM

Target: 7/31/2017

MSGP Program 品 RG121.9

Taken By:

Banar, Alethea

Priority/Type: / Inspection

Department: Utilities and Infrastructure

A TA-3-38 Carpenter Shop

Procedure:

MSGP Quarterly Visual Assessment (EPC Sig)

Monitored Outfall (073) Substantially Identical Outfall (074)

(EPC-CP-Form-1021.02 2)

Last PM:

7/26/2017

Project:

SIO Visual Assessments

6/1/17 (P-MSGP-5188)

Contact: Banar, Alethea Phone: 699-5836

₼ MSGP07401

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Special Instructions: NMR053195

Tasks					110
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable	е.			
Samp	le information				
30	Document the monitoring Period by using the Monitoring Period lookup table.	June-July	4	46	
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)		ul		
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 10:50 MST			
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 10:50 MST	3		
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/26/17 12:00 MDT		Γa.	
70	Document the nature of discharge using the Precipitation Type lookup table. Document the amount (in) in the "Reading" field of this line.	rain 0.99in		ā	
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide reason in comments of this line.		4		
Param	eters				340W
110	Is sample colorless? If "Failed", describe.	light tan			
120	Is sample oderless? If "Failed", document observation using the Odor lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.			à	W
130	Is sample clear? If "Failed", document observation using the Clarity lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	cloudy	(X	, d	
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	vegetation	IX.		
150	Is sample free of settled solids? If "Failed", document observation using the Settled Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.				E.
160	Is sample free of suspended solids? If "Failed", document observation using the Suspended Solids lookup table. If "other" is chosen from the lookup table, provide description in comments of this line.	fine	IX.		Ta .
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location ('on the surface' or 'in the sample') in the comments of this line. (Range: 0 - 0)		-4		TV.
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs) in the comments of this line. (Range: 0 - 0)		, d		W
				-6	

	Is sample free of other obv comments of this line. (Rar	ous indicators of pollution? If "Fai ge: 0 - 0)	led", describe in the	
Labor	Report			
Comp	leted: 7/26/2017 12:00:00 PM	1		
Repor	t: Alethea Banar		19000a. 1	·
	Aboll w/LBomn	7/27/2017		
l confi	Signature / Name rm the information as record	Date led is true, accurate and comple	Signature / Name ete.	Date
system d e person , to the b	esigned to assure that qualifie or persons who manage the s est of my knowledge and beli	d personnel properly gathered and ystem, or those persons directly re	re prepared under my direction or sup- d evaluated the information submitted esponsible for gathering information, am aware that there are significant pe- ng violations".	l. Based on my inquiry of the information submitted
Torritatio				enalties for submitting fals
	y must meet definition in Sec	tion B.11.A, eg. FOD, Ops Mgr	, DSESH Group Leader, EPC Grou	-
ignatory		ction B.11.A, eg. FOD, Ops Mgr	, DSESH Group Leader, EPC Grou	-



Environmental Protection & Compliance Division

To: Jillian Burgin, DESHS-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File)

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 17-528

Date:

JAN 1 2 2018

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Form for August and September of 2017 for the TA-3-38 Carpenter Shop

Please find attached a completed MSGP QVA form documenting a visual assessment performed during the third quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA form shall be incorporated into your MSGP Stormwater Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of stormwater discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Los Alamos National Security (LANS) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA form documents the following information required by Part 3.2.2 of the 2015 MSGP and was completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.



The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVA completed by an EPC-CP representative contained in Enclosure 1.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Taunia S. Van Valkenburg, EPC-CP Group Leader

Los Alamos National Security, LLC

Manager Signature

1/12/18 Date

Part 3.2.3 of the 2015 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

Facility Name	Sampling Station	Work Order #		
TA-3-38 Carpenter Shop	MSGP07401	MSGP-61114		

TWL/HLW: am

Enclosure(s): 1) Quarterly Visual Assessment Forms, Third Quarter, 2017 Monitoring Year

Copy: Russell Stone, DESHS-UIS, (E-File)

Adesh-records@lanl.gov, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

Quarterly Visual Assessment Forms
Third Quarter, 2017 Monitoring Year

EPC-DO: 17-528

JAN 1 2 2018

Date:	 			

Work Order MSGP-61114

MSGP Monitoring Stations Printed 10/17/2017 - 4:47 PM

١	Λ	ai	in	t	er	าล	n	се	D	ef	ta	il	ls
---	---	----	----	---	----	----	---	----	---	----	----	----	----

Requested By: Banar, Alethea on

8/9/2017 2:05:00 PM

9/30/2017 Target: Priority/Type: / Inspection

Department: Utilities and Infrastructure

MSGP Program

Taken By:

Banar, Alethea

品 RG121.9 A TA-3-38 Carpenter Shop

MSGP Quarterly Visual Procedure: Assessment (EPC Sig)

Monitored Outfall (073) Substantially Identical Outfall (074)

(EPC-CP-Form-1021.2 3)

MSGP07401

8/17/2017

Last PM: Project:

SIO Visual Assessments 8/1/17 (P-MSGP-5209)

Contact: Banar, Alethea Phone: 699-5836

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Special Instructions: NMR053195

Tasks					
#	Description	Meas.	No	N/A	Yes
The re	sult of this VA applies to associated SIOs as defined in the SWPPP, where applicable				
Sampl	e information				
30	Document the monitoring Period (e.g., Apr-May)	Aug-Sep	3		1
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)		_اتاك		14
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/23/17, 11:25	П	<u> E</u>	
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/23/17, 1312			1
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/23/17, 1312	П	П	TV.
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	Rain, 0.22"			10
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				14
Param	eters	-			
110	Is sample colorless? If "Failed", describe.			Г	1
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)			Б	1
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).				1
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.			JE	
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	course	TX.		
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).				
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., on the surface or 'in the sample').			Га	
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).		Lit.		
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.				V

Labor Report

Completed: 8/23/2017 1:12:00 PM

Report: Antonio Trujillo

8/28/2017

| Signature / Name | Date | Signature / Name | Date |
| Confirm the information as recorded is true, accurate and complete.

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)

Print name and title: _____ Anthony R. Grieggs, EPC-CP Group Leader

Signature: _____ (See signature on file) _____ Date: _____



Environmental Protection & Compliance Division

To: Jillian Burgin, DESHS-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File)

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 17-548

Date:

JAN 1 2 2018

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for October and November of 2017 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA forms documenting visual assessments performed during the fourth quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Stormwater Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of stormwater discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Los Alamos National Security, LLC (LANS) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.



EPC-DO: 17-548 Jillian Burgin

The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVAs completed by EPC-CP representatives contained in Enclosure 1.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

<u>Taunia S. Van Valkenburg, EPC-CP Group Leader</u> Los Alamos National Security, LLC

Manager Signature

Date

Part 3.2.3 of the 2015 MSGP allows the facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility-specific SWPPP.

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07302	MSGP-61113
TA-3-38 Carpenter Shop	MSGP07401	MSGP-61674

EPC-DO: 17-548 Jillian Burgin

TWL/HLW: am

Enclosure(s): 1) Quarterly Visual Assessment Forms, Fourth Quarter, 2017 Monitoring Year

Copy: Russell Stone, DESHS-UIS, (E-File)

Adesh-records@lanl.gov, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

Quarterly Visual Assessment Forms Fourth Quarter, 2017 Monitoring Year

EPC-DO: 17-548

JAN 1 2 2018

Date: _____

Work Order MSGP-61113

MSGP Monitoring Stations Printed 12/13/2017 - 10:30 AM (Duplicate Copy)

V	aint	en:	anı	9	Dei	tails	
w	ann		alis	-		Lalia	

Requested By: Banar, Alethea on

8/9/2017 2:04:00 PM

Taken By: Procedure:

MSGP Quarterly Visual

Assessment (EPC Sig) (EPC-CP-Form-1021.2

3)

Last PM:

8/9/2017

Project:

Visual Assessments 10/1/17 (P-MSGP-5229)

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Banar, Alethea

Target:

Department: Utilities and Infrastructure

11/30/2017

Priority/Type: / Inspection

MSGP Program 品 RG121.9

♣ TA-3-38 Carpenter Shop Monitored Outfall (073)

№ MSGP07302

Contact: Banar, Alethea Phone: 699-5836

asks					
#	Description	Meas.	No	N/A	Yes
The re	sult of this VA applies to associated SIOs as defined in the SWPPP, where applicable				
Samp	le information				
30	Document the monitoring Period (e.g., Apr-May)	Oct-Nov	2		1
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)				
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 13:45			1
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 13:45			
30	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 15:45			
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	Rain, 0.92"			TV.
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				N.
Param	eters				
110	Is sample colorless? If "Failed", describe.		E		1
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)			±	W
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).				1
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	fine	[X		П
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	course	1X		
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).	fine	1X		
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g.,'on the surface' or 'in the sample').	g			1
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).		_ 🔟	Б	1
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.	Q1			

Labor Report

Completed: 10/4/2017 3:45:00 PM

Report: Antonio Trujillo

10/12/2017

Mullo			
¶gnature Name I confirm the information as recorded is tru	Date ue, accurate and com	Signature / Name	Date
	CERTIFICATION	ISTATEMENT	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory m	ust meet definition in Section B.11.A	, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Group	Leader
Print name an	d title: <u>Taunia Van Valkenburg, El</u>	PC-CP Group Leader	
Signature:	(See signature on file)	Date:	

Work Order MSGP-61674

Phone: 699-5836

MSGP Monitoring Stations Printed 12/8/2017 - 4:02 PM

Maintenance	Details			
	Banar, Alethea on 10/10/2017 9:18:00 AM	Target: Priority/Type:	11/30/2017 / Inspection	실 MSGP Program 品 RG121.9
Taken By: Procedure:	Banar, Alethea MSGP Quarterly Visual Assessment (EPC Sig) (EPC-CP-Form-1021.2 3)	Department:	Utilities and Infrastructure	♣ TA-3-38 Carpenter Shop ♣ Monitored Outfall (073) Substantially Identical Outfall (074) ♣ MSGP07401
Last PM: Project:	10/4/2017 SIO Visual Assessments			Contact: Banar, Alethea

10/1/17 (P-MSGP-5230) Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Special Instructions: NMR053195

asks					
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable				
Samp	le information				
30	Document the monitoring Period (e.g., Apr-May)	Oct-Nov			1
35	Is visual assessment performed on an unfiltered sample? (Use filtered only if unfiltered unavailable.)			_D	1
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 1500			
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 1500			W
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/4/17, 1500	П	П	IV.
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	rain, 0.92"			14
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				1
Paran	neters				
110	Is sample colorless? If "Failed", describe.				10
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)				TW.
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).		Г		1
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	fine	IX.		
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	fine	1X		П
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).	fine	IX.		
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., on the surface or 'in the sample').				TV.
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).	10			V
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.	-			1

La	bor	Re	port
----	-----	----	------

Completed: 10/4/2017 3:00:00 AM

Report: Antonio Trujillo

	10/17/2017		
(Lundla			
1 juyure			
\ Signature // Name	Date	Signature / Name	Date
I confirm the information as recorded	is true, accurate and com-	olete.	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory m	ust meet definition in Section B.	.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Grou	p Leader)
Print name an	d title: <u>Taunia Van Valkenbur</u>	g, EPC-CP Group Leader	
Signatura	(See cignature on file)	Dotor	

There were no MSGP Quarterly Visual Assessments performed for the TA-03-38 Carpenter's Shop for the first quarter of 2018.



Environmental Protection & Compliance Division

To: Jillian Burgin, DESHS-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File)

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 18-338 OCT 0 5 2018

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for June and July of 2018 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA forms documenting visual assessments performed during the second quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Stormwater Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of stormwater discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Los Alamos National Security, LLC (LANS) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.



EPC-DO: 18-338 Jillian Burgin

The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVAs completed by EPC-CP representatives contained in Attachment 1.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

<u>Taunia S. Van Valkenburg, EPC-CP Group Leader</u> Los Alamos National Laboratory

Manager Signature

Date

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP Permit.

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07302	MSGP-62278
TA-3-38 Carpenter Shop	MSGP07401	MSGP-62793
TA-3-38 Carpenter Shop	MSGP07401	MSGP-62860

TWL/HLW: jdm

Attachment: 1) Quarterly Visual Assessment Forms, Second Quarter, 2018 Monitoring Year

Copy: Russell Stone, DESHS-UIS, (E-File)

Adesh-records@lanl.gov, (E-File)
lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ATTACHMENT 1

Quarterly Visual Assessment Forms Second Quarter, 2018 Monitoring Year

EPC-DO: 18-338

Date:	OCT 0 5 2018
Date:	

Maintenance Details

Work Order MSGP-62278

MSGP Monitoring Stations Printed 8/29/2018 - 9:32 AM

Last PM: Project:	ed: 6/20/2018 4:09:00 PM re: MSGP Quarterly Visual Assessment (EPC-CP-Form- 1021.2) 4/2/2018 Visual Assessments 6/1/18		7/31/2018 Normal / Inspection Utilities and Infrastructure	-∰ RG12 -∰ TA-3-	38 Carpent ored Outfal			
•	(P-MSGP-5279) MSGP Quarterly Visual Assessm	nent		Contact: Phone:				
asks								
#	Description				Meas.	No	N/A	Yes
The resu	ılt of this VA applies to associat	ed SIOs as defi	ned in the SWPPP, where	applicable.				
	information		,					
	Document the monitoring Period (e.g., Apr-May)			June-july	г		V
	Document the Date/Time Discharmm/dd/yy hh:mm format).		'Reading" field of this line (ι	using	7/17/18, 1117			V
501	Document the Date/time sample omm/dd/yy hh:mm format).				7/17/18, 1117			V
30 (Document the Date/time sample value (using mm/dd/yy hh:mm format).				7/17/18, 1217			V
<u>'0</u> (Document the nature of discharge (in) in the "Reading" field of this lin	ne.			rain, 0.71"	Γ		V
	Sample collected in first 30 minute reason.	es of discharge?	If "Failed" or unknown, pro-	vide a				V
aramete	ers							
	Is sample colorless? If "Failed", de							~
20 s	Is sample oderless? If "Failed", pr solvent, petroleum/gas)	ovide descriptior	ı (e.g. musty, sewage, sulfu	r, sour,				V
	Is sample clear? If "Failed", provid					Г		~
	Is sample free of floating solids? In comments of this line.	f "Failed", describ	pe if raw or waste material(s) in the		Г		V
	Is sample free of settled solids? If				fine	[X		
	Is sample free of suspended solid				fine	TX.		
<u>70 (</u>	Is sample foamless after gently sh (e.g.,'on the surface' or 'in the sam	ple').				Г		V
	Is sample devoid of an oil sheen? globs).	If "Failed", descr	tibe color and thickness (e.g	g. flecks,		_	_	12
	ls sample free of other obvious inc	licators of polluti	on? If "Failed", describe.				+	1

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory must meet definition in Section B.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader
Print name and title: Taunia Van Valkenburg, EPC-CP Group Leader
Signature: (See signature on file) Date:

Work Order MSGP-62793

MSGP Monitoring Stations Printed 8/29/2018 - 12:51 PM

Requested By: Banar, Alethea on

7/9/2018 9:42:00 AM

Priority/Type: / Inspection Banar, Alethea **Department:** Utilities and Infrastructure

Target:

7/31/2018

MSGP Quarterly Visual

Assessment (EPC-CP-

Form-1021.2)

Last PM: 7/5/2018

Taken By:

Procedure:

Project:

SIO Visual Assessments 6/1/18 (P-MSGP-5280)

Reason: MSGP Quarterly Visual Assessment

Special Instructions: NMR053195

🗎 MSGP Program ₽ RG121.9

♣ TA-3-38 Carpenter Shop Monitored Outfall (073)

Substantially Identical Outfall (074)

MSGP07401

Contact: Banar, Alethea Phone: 699-5836

asks					
#	Description	Meas.	No	N/A	Yes
The r	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable.				
Samp	le information				
30	Document the monitoring Period (e.g., Apr-May)	June-	-	-	ww.
50	Document the Montoling Period (e.g., Apr-May) Document the Date/Time Discharge began in the "Reading" field of this line (using	July			
40	mm/dd/yy hh:mm format).	7/5/18, 1215	г	Г	12
	Document the Date/time sample collected in the "Reading" field of this line (using				1.5
-0	mm/dd/yy hh:mm format).	7/5/18,			
50	Comments: A grab sample was collected	1348			V
50	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/5/18, 1348	Г	Г	V
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	rain, 0.07			1
30	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				V
aran	neters				
110	Is sample colorless? If "Failed", describe.		Г	г	1
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)				12
30	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).		T		1
40	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	raw	r)X		
50	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	course	IX.		
60	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).		F		1
70	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., on the surface or 'in the sample').				- IV
80	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).				1
90	Is sample free of other obvious indicators of pollution? If "Failed", describe.		-		10

Labor Report

Completed: 7/5/2018 1:48:00 PM

Report: Antonio Trujillo

7/11/2018

M/MM.			
Signature / Name I confirm the information as recorded is	Date true, accurate and complete	Signature / Name	Date
	CERTIFICATION STA	ATEMENT	
"I certify under penalty of law that this docum- a system designed to assure that qualified pers- the person or persons who manage the system, is, to the best of my knowledge and belief, true information, including the possibility of fine an	sonnel properly gathered and e , or those persons directly resp e, accurate, and complete. I ar	evaluated the information submitted. Exponsible for gathering information, the maware that there are significant pena	Based on my inquiry of e information submitted
(Signatory must meet definition in Section E	B.11.A, eg. FOD, Ops Mgr, D	OSESH Group Leader, EPC Group	Leader)
Print name and title: <u>Taunia Van Valkenbu</u>	urg, EPC-CP Group Leader		
Signature: (See signature on file)	Date	::	

Work Order MSGP-62860

MSGP Monitoring Stations Printed 8/29/2018 - 12:52 PM

Maintenance	Details	

Requested By: Wheeler-Benson, Holly

on 7/17/2018 10:15:00

A N //

Wheeler-Benson, Holly

Taken By: Procedure:

MSGP Quarterly Visual

Assessment (EPC-CP-

Form-1021.2) 7/5/2018

Last PM: Project:

SIO Visual Assessments

6/1/18 (P-MSGP-5280)

Reason: MSGP Quarterly Visual Assessment

Special Instructions: NMR053195

Target: 7/31/2018

Priority/Type: / Inspection

Department: Utilities and Infrastructure

MSGP Program

RG121.9

TA-3-38 Carpenter Shop
Monitored Outfall (073)

Substantially Identical Outfall (074)

MSGP07401

Contact: Wheeler-Benson, Holly

Phone: 667-1312

Tasks					***************************************
#	Description	Meas.	No	N/A	Yes
The r	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable	·.			
Samp	ole information				
30	Document the monitoring Period (e.g., Apr-May)	June/July		Г	V
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/13/18 13:55	Г	Г	V
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/13/18 14:22		Г	V
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	7/13/18 14:24	Г	Г	IV.
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	Rain 0.21"	Г	Г	V
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				~
Paran	neters				- Indiana
110	Is sample colorless? If "Failed", describe.	light tan	TX.	_	
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)		r		TV
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).	slightly cloudy	[X		
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.		Г	Г	V
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	fine	IX.	T	
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).	fine	IX.	Г	
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., 'on the surface' or 'in the sample').		Г	Г	TV.
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).		Г	Г	V
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.			Ī	V

Labor Report

Completed: 7/13/2018 2:22:00 PM

Report: Grab sample

Holly Wheeler			i
Signature / Name I confirm the information as recorded	7/23/2018 Date d is true, accurate and compl	Signature / Name	Date
	CERTIFICATION S	STATEMENT	
"I certify under penalty of law that this doc a system designed to assure that qualified paths as a system or persons who manage the syst is, to the best of my knowledge and belief, information, including the possibility of fir	personnel properly gathered an tem, or those persons directly r true, accurate, and complete. l	d evaluated the information submitted responsible for gathering information, to am aware that there are significant pe	l. Based on my inquiry of the information submitted
Signatory must meet definition in Section	on B.11.A, eg. FOD, Ops Mgr	r, DSESH Group Leader, EPC Group	p Leader)
Print name and title: <u>Taunia Van Valk</u> e	enburg, EPC-CP Group Leader	<u></u>	
Signature:(See signature on file)		oate:	



To: Jillian Burgin, DESH-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File) The San

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 18-387 Date: DEC 1 2 2018

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for August and September of 2018 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA forms documenting visual assessments performed during the third quarter of monitoring at the TA-3-38 Carpenter Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Stormwater Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of stormwater discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Triad National Security, LLC (Triad) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.

The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVAs completed by an EPC-CP representative contained in Attachment 1.



EPC-DO: 18-387 Jillian Burgin

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

<u>Taunia S. Van Valkenburg, EPC-CP Group Leader</u> Los Alamos National Laboratory

Manager Signature

112/18 Date

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP.

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07401	MSGP-63060
TA-3-38 Carpenter Shop	MSGP07302	MSGP-63084

TWL/HLW:jdm

Attachment(s): Attachment 1 Quarterly Visual Assessment Forms, Third Quarter, 2018
Monitoring Year



EPC-DO: 18-387 Jillian Burgin

Copy: Michael Hazen, ALDESHQSS, mhazen@lanl.gov, (E-File)

Terrill Lemke, EPC-CP, tlemke@lanl.gov, (E-File)

William Mairson, ALDESHQSS, wrmairson@lanl.gov, (E-File)

Russell Stone, DESH-UIS, <u>rdstone@lanl.gov</u>, (E-File) Enrique Torres, EPC-DO, <u>etorres@lanl.gov</u>, (E-File)

Taunia Van Valkenburg, EPC-CP, tauniav@lanl.gov, (E-File)

Adesh-records@lanl.gov, (E-File) lasomailbox@nnsa.doe.gov, (E-File) locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)



ATTACHMENT 1

Quarterly Visual Assessment Forms Third Quarter, 2018 Monitoring Year

EPC-DO: 18-387

DEC 1 2 2018

Date:

Work Order MSGP-63060

MSGP Monitoring Stations Printed 10/11/2018 - 4:26 PM

Maintenance	Details	 W. C.

Requested By: Wheeler-Benson, Holly

on 8/6/2018 2:56:00 PM

Taken By:

Wheeler-Benson, Holly

Procedure: MSGP Quarterly Visual

Assessment (EPC-CP-

Form-1021.2)

Last PM:

8/3/2018

Project:

MSGP Quarterly Visual 8/1/2018 (P-MSGP-

5315)

Reason: MSGP Quarterly Visual Assessment (EPC Sig)

Special Instructions: NMR053195

Target: 9/30/2018 Priority/Type: / Inspection

Department: Utilities and Infrastructure

MSGP Program 品 RG121.9

♣ TA-3-38 Carpenter Shop Monitored Outfall (073)

Substantially Identical Outfall (074)

№ MSGP07401

Contact: Wheeler-Benson, Holly

Phone: 667-1312

Tasks					
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable.				
Samp	le information				
30	Document the monitoring Period (e.g., Apr-May)	Aug- Sept	Г		r/
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/3/18, 1240	Г		V
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/3/18, 1240			V
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	8/3/18, 1358			V
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	rain, 0.13"			~
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.				V
Param	neters				
110	Is sample colorless? If "Failed", describe.	Dark Brown	J.X		П
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)				V
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).	cloudy	X		
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.		Г	П	1
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	course	TX.		Г
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).	fine	130	Г	
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., on the surface' or 'in the sample').		Г	Г	TV.
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).			Г	1
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.				~

Labor Report

Completed: 8/3/2018 1:58:00 PM

Report: Antonio Trujillo

A A	8/9/2018		
Millo			
Signature / Name	Date	Signature / Name	Date
I confirm the information as recorded	I is true, accurate and com	plete.	Dato

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

(Signatory m	nust meet definition in Section B.11.A, eg	g. FOD, Ops Mgr, DESH Group Lea	der, EPC Group Leader)
Print name ar	nd title: <u>Taunia Van Valkenburg, EPC</u> -	CP Group Leader	
Signature:	(See signature on file)	Date	

Work Order MSGP-63084

MSGP Monitoring Stations Printed 10/11/2018 - 4:25 PM (Duplicate Copy)

/lainte	nance l	Details					and the state of the state of the state of		
Reques	ted By:	Dale, Leslie on 8/16/2018 3:15:00 PM	Target: Priority/Type:	9/30/2018 / Inspection	🗎 MS0 ௬ RG1	GP Program			
aken E Procedi	ure:	Dale, Leslie MSGP Quarterly Visual Assessment (EPC-CP- Form-1021.2) 8/16/2018		Utilities and Infrastructure	♣ TA-3 ♣ Mon	RG121.9 A-3-38 Carpenter Shop Monitored Outfall (073) ISGP07302		•	
roject:		MSGP Quarterly Visual 8/1/2018 (P-MSGP- 5315)			Contact Phone:	t: Dale, Lesli	e		
Reason	: MSGF	^o Quarterly Visual Assessn	nent (EPC-CP Si	g)					
asks					many pages a second or has second as the sec			MARIE E E E E MARIE MARIE	
#	Descri					Meas.	No	N/A	Yes
	inform		ed SIOs as defi	ned in the SWPPP, where a	applicable	•			
0		ent the monitoring Period				Aug-Sept			1
0	mm/dd	/yy hh:mm format).		'Reading" field of this line (u		8/16/18, 1240			V
0	mm/dd	/yy hh:mm format).		Reading" field of this line (us		8/16/18, 1240			V
0	(using	mm/dd/yy hh:mm format).		d in the "Reading" field of this		8/16/18, 1340			V
0	<u>(in) in t</u>	he "Reading" field of this lir	ne.	vmelt). Document the TOTAI		rain, 0.56"			V
0	Sample reason		es of discharge?	If "Failed" or unknown, prov	ide a				V
arame	ters					Dark			
10	Is samp	ole colorless? If "Failed", de	escribe.			Brown	130		
20	ls samp solvent	ole oderless? If "Failed", pr , petroleum/gas)	ovide description	ı (e.g. musty, sewage, sulfur	sour,		Г	Г	V
30	Is samp	ole clear? If "Failed", provid	le description (e.	g., slightly cloudy, cloudy, op	aque).	opaque	130		
40		ole free of floating solids? Into of this line.	f "Failed", descrit	be if raw or waste material(s) in the	raw	TX.		
50				e description (e.g., fine, cours		course	TX.		
30				ovide description (e.g., fine, o		fine	[X		
70	(e.g.,'or	the surface' or 'in the sam	nple').	" describe foam color and lo			Г		V
30	globs).			ibe color and thickness (e.g.	flecks,				V
90	Is samp	ole free of other obvious inc	licators of pollution	on? If "Failed", describe.					V
ıbor R	eport				THE STATE OF THE S				
omple	ted: <u>8/1</u>	6/2018 1:40:00 AM							
eport:	Antonio	Trujillo	8/20/2018						

Signature / Name I confirm the information as recorded	Date is true, accurate and comp	Signature / Name lete.	Date
	CERTIFICATION	STATEMENT	
"I certify under penalty of law that this do accordance with a system designed to assi Based on my inquiry of the person or persinformation, the information submitted is, there are significant penalties for submittiviolations".	ure that qualified personnel sons who manage the syster , to the best of my knowled;	properly gathered and evaluated the in, or those persons directly responsible and belief, true, accurate, and comp	information submitted. le for gathering plete. I am aware that
(Signatory must meet definition in Sect	tion B.11.A, eg. FOD, Ops	Mgr, DESH Group Leader, EPC G	roup Leader)
Print name and title: <u>Taunia Van Val</u>	kenburg, EPC-CP Group Le	eader	

Signature: (See signature on file) Date:



To: Jillian Burgin, DESH-UIS, B274

Thru: Terrill Lemke, EPC-CP, (E-File) Wo fr

From: Holly Wheeler, EPC-CP, (E-File)

Phone: 505-667-1312 Symbol: EPC-DO: 18-465

DEC 1 2 2018

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Quarterly Visual Assessment (QVA) Forms for October and November of 2018 for the TA-3-38 Carpenter Shop

Please find attached completed MSGP QVA forms documenting visual assessments performed during the fourth quarter of monitoring at the TA-3-38 Carpenters Shop. Per Parts 3.2.2 and 5.5 of the 2015 MSGP, the signed certification statement and associated QVA forms shall be incorporated into your MSGP Stormwater Pollution Prevention Plan (SWPPP).

Part 3.2.1 of the 2015 MSGP requires the visual assessment of stormwater discharge samples collected from each outfall once each quarter for the entire permit term. Part 3.2.3 allows facilities that are located in an area with a semi-arid climate and/or in an area where freezing conditions exist for an extended period to distribute the quarterly visual assessments during seasons when precipitation runoff occurs. Accordingly, Triad National Security, LLC (Triad) has designated the following MSGP monitoring quarters.

Quarter 1: April – May Quarter 2: June – July

Quarter 3: August – September Quarter 4: October - November

The attached QVA forms document the following information required by Part 3.2.2 of the 2015 MSGP and were completed by Environmental Compliance Programs (EPC-CP) personnel.

- Sample location;
- Sample collection date and time, and visual assessment date and time for each sample;
- Personnel collecting the sample and performing the visual assessment, and their signatures;
- Nature of the discharge (i.e., runoff or snowmelt);
- Results of observations of the stormwater discharge;
- Probable sources of any observed stormwater contamination (if applicable);
- If applicable, why it was not possible to take a sample within the first 30 minutes of the storm event.

The EPC-CP Group Leader has signed the certification statement to meet the duly authorized signatory requirements for the QVAs contained in Attachment 1.



EPC-DO: 18-465 Jillian Burgin

> I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Taunia Van Valkenburg, EPC-CP Group Leader Los Alamos National Laboratory

Manager Signature 12/12/18

Date

Please contact Holly Wheeler at 667-1312 (hbenson@lanl.gov) if you have questions regarding the QVA documentation. Thank you for your assistance in meeting the requirements of the Laboratory's NPDES 2015 MSGP.

Facility Name	Sampling Station	Work Order #
TA-3-38 Carpenter Shop	MSGP07401	MSGP-63134
TA-3-38 Carpenter Shop	MSGP07302	MSGP-63319

TWL/HLW:jdm

Attachment(s): Attachment 1 Quarterly Visual Assessment Forms, Fourth Quarter, 2018 Monitoring Year



Copy: Michael Hazen, ALDESHQSS, mhazen@lanl.gov, (E-File)

Terrill Lemke, EPC-CP, tlemke@lanl.gov, (E-File)

William Mairson, ALDESHQSS, wrmairson@lanl.gov, (E-File)

Russell Stone, DESH-UIS, <u>rdstone@lanl.gov</u>, (E-File) Enrique Torres, EPC-DO, <u>etorres@lanl.gov</u>, (E-File)

Taunia Van Valkenburg, EPC-CP, tauniav@lanl.gov, (E-File)

Adesh-records@lanl.gov, (E-File)
lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)



ATTACHMENT 1

Quarterly Visual Assessment Forms Fourth Quarter, 2018 Monitoring Year

EPC-DO: 18-465

Date: ______

Los Alamos National Lab - ADESH

Signature / Name

Work Order MSGP-63134

MSGP Monitoring Stations Printed 11/8/2018 - 11:50 AM

Procedure: MSGP Quarterly Visual Assessment (EPC-CP-Form- 1021.2) Last PM: 8/3/2018 Priority/Type: / Inspection Department: Utilities and Infrastructure Department: Utilities and Infrastructure Sulphysical Sulphysical Priority/Type: / Inspection Department: Utilities and Infrastructure Sulphysical Sulphysical Priority/Type: / Inspection Sulphys						ISGP Program G121.9 A-3-38 Carpenter Shop onitored Outfall (073) ubstantially Identical Outfall (074) SGP07401				
	n: MSGP Quarterly Visual Assessm I Instructions: NMR053195	nent		Contact Phone:	:					
asks										
#	Description				Meas.	No	N/A	Yes		
	sult of this VA applies to associat	ed SIOs as defir	ned in the SWPPP, where	applicable.						
-	e information	0 00				FARMACIES*	Northead C			
30	Document the Monitoring Period (Danding!! field of their line (oct-nov					
4 0	Document the Date/Time Discharg mm/dd/yy hh:mm format).	ge began in the	Reading field of this line (u	sing	10/9/18 11:08	_		1		
	Document the Date/time sample of	collected in the "F	Reading" field of this line (us	ing	10/9/18					
50	mm/dd/yy hh:mm format).		`		11:08			V		
60	Document the Date/time sample v	isually assessed	in the "Reading" field of thi	s line	10/9/18	National	National			
60	(using mm/dd/yy hh:mm format).	/a.a	Decision Aller TOTA		11:08					
70	Document the nature of discharge (in) in the "Reading" field of this lir		meit). Document the TOTA	_ amount	rain .13	г				
	Sample collected in first 30 minute		If "Failed" or unknown, prov	ide a						
80	reason.							V		
Param	eters									
110	Is sample colorless? If "Failed", de	escribe.			blackish	130	Г	Г		
	Is sample oderless? If "Failed", pro		(e.g. musty, sewage, sulfur	, sour,						
120	solvent, petroleum/gas)				musty	[X				
130	Is sample clear? If "Failed", provid				cloudy	[X		厂		
140	Is sample free of floating solids? If comments of this line.	"Failed", describ	e if raw or waste material(s) in the		-	-	12/		
150	Is sample free of settled solids? If	"Failed" provide	description (e.g. fine cour	se)	coarse	rM*				
160	Is sample free of suspended solids							[V		
	Is sample foamless after gently sh	aking? If "Failed"								
170	(e.g., on the surface or in the same	ple').						1		
180	Is sample devoid of an oil sheen? globs).	If "Failed", descri	ibe color and thickness (e.g	. flecks,		-	-	900 F		
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.						_	15/		
	10 Sample free of other obvious life		on. In Falled , describe.							
abor F	Report									
	•									
	eted: 10/9/2018 11:08:00 AM									
Report	:: Marwin Shendo									
	. ^									

Date

Signature / Name

Date

	CERT	TIFICATION STATEMENT	
accordance with a system Based on my inquiry of th information, the informati	designed to assure that quality e person or persons who man on submitted is, to the best of	nage the system, or those persons ding of my knowledge and belief, true, acc	d evaluated the information submitted.
(Signatory must meet de	efinition in Section B.11.A, o	eg. FOD, Ops Mgr, DESH Group	Leader, EPC Group Leader)
Print name and title:	Taunia Van Valkenburg, EPC	C-CP Group Leader	
Signature: (See sig	nature on file)	Date:	

I confirm the information as recorded is true, accurate and complete.

Los Alamos National Lab - ADESH

Work Order MSGP-63319

MSGP Monitoring Stations Printed 11/8/2018 - 11:49 AM

Maintenance Details

Requested By: Banar, Alethea on

10/24/2018 8:44:00 AM

Taken By:

Banar, Alethea

Procedure:

MSGP Quarterly Visual

Assessment (EPC-CP-

Form-1021.2)

Last PM:

10/23/2018

Project:

MSGP Quarterly Visuals 10/1/2018 (P-MSGP-

5335)

Reason: MSGP Quarterly Visual Assessment

11/30/2018

Priority/Type: / Inspection

Target:

Department: Utilities and Infrastructure

MSGP Program ₽ RG121.9

♣ TA-3-38 Carpenter Shop Monitored Outfall (073)

№ MSGP07302

Contact: Banar, Alethea Phone: 699-5836

Гasks					
#	Description	Meas.	No	N/A	Yes
The re	esult of this VA applies to associated SIOs as defined in the SWPPP, where applicable	e.			
Samp	le information				
30	Document the monitoring Period (e.g., Apr-May)	Oct-Nov			~
40	Document the Date/Time Discharge began in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/23/18, 0815		Г	V
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/23/18, 0815	П	Г	V
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).	10/23/18, 0915	П	Г	~
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.	rain, 1.25"	Г	Г	~
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.		Г	Г	~
Param	neters	-			
		light			
110	Is sample colorless? If "Failed", describe.	brown	120		
120	Is sample oderless? If "Failed", provide description (e.g. musty, sewage, sulfur, sour, solvent, petroleum/gas)				10/
130	Is sample clear? If "Failed", provide description (e.g., slightly cloudy, cloudy, opaque).	cloudy	TX.	П	Г
140	Is sample free of floating solids? If "Failed", describe if raw or waste material(s) in the comments of this line.	raw	[]		Г
150	Is sample free of settled solids? If "Failed", provide description (e.g., fine, course).	fine	1X	Г	
160	Is sample free of suspended solids? If "Failed", provide description (e.g., fine, course).	fine	1X	П	
170	Is sample foamless after gently shaking? If "Failed" describe foam color and location (e.g., 'on the surface' or 'in the sample').				
180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks, globs).		Г	Г	V
190	Is sample free of other obvious indicators of pollution? If "Failed", describe.				1

Labor Report

Completed: 10/23/2018 9:15:00 AM

Report: Antonio Trujillo

10/25/2018

\$ignature / Name I confirm the information as recorded is	Date true, accurate and com	Signature / Name plete.	Date
	CERTIFICATION	STATEMENT	
"I certify under penalty of law that this docu accordance with a system designed to assure Based on my inquiry of the person or person information, the information submitted is, to there are significant penalties for submitting violations".	e that qualified personne ns who manage the syste o the best of my knowle	el properly gathered and evaluated the in em, or those persons directly responsible dge and belief, true, accurate, and compl	formation submitted. for gathering lete. I am aware that
(Signatory must meet definition in Section	on B.11.A, eg. FOD, Op	s Mgr, DESH Group Leader, EPC Gr	oup Leader)
Print name and title: Taunia Van Valke	enburg, EPC-CP Group I	Leader	_

Signature: (See signature on file) Date:



Permit Information (* indicates form required data)

Holly

2015 NPDES Multi-Sector General Permit For Stormwater Discharges Associated With Industrial Activity (MSGP) Forms

United States Environmental Protection Agency 1200 Pennsylvania Ave, NW Washington, DC 20460

5056671312

What action would you like to	o take? *			
New Industrial Stormwater A	Annual Report			
Please select the NPDES ID co	rresponding to the facility for which you would li	ke to submit an Annual Report and click the	Submit button.	
NPDES ID *				
NMR053195: LOS ALAMOS N	IATIONAL LABORATORY			
Confirm NPDES ID: NMR05	53195: LOS ALAMOS NATIONAL LABORATORY *			
Facility Information				
Facility Name				
Los Alamos National Lal	boratory			
Street				
PO Box 1663				
Supplemental address				
MS K490				
City	Sta	te	Zip Code	
Los Alamos	Ne	ew Mexico	87545	
First Name	Middle Name	Last Name	Telephone Number	

Wheeler

Summary of past year's inspections, assessments, and corrective actions

1. Provide a summary of your past year's routine facility inspection documentation (see Part 3.1.2 of the permit). In addition, if you are an operator of an airport facility (Sector S) that is subject to the airport effluent
limitations guidelines, and are complying with the MSGP Part 8.S.8.1 effluent limitation through the use of non-urea-containing deicers, provide a statement certifying that you do not use airfield pavement deicers
containing urea (e.g., "I certify that [name of airport] is in compliance with the effluent limitation guideline for airfield pavement deicing by not using airfield pavement deicers that contain urea."). [Note: Operators of airport
facilities that are complying with Part 8.S.8.1 by meeting the numeric effluent limitation for ammonia do not need to include this statement.] *

Los Alamos National Laboratory (LANL), operated by Los Alamos National Security, LLC (LANS), consists of 14 active industrial sites that operate under 8 different Sectors (A, D, F, K, N, O, P, and AA). All 14 active sites were inspected according the schedules identified in the site-specific SWPPs. The 26 sites that qualify for a conditional exclusion for no exposure were inspected between December 1st and 22nd, 2016. A total of 198 inspections and/or evaluations resulting in corrective actions were conducted at a total of 40 sites as follows:

TA-3-22 Power and Steam Plant -20; TA-3-29 Indoor TSD and Machine Shop -1; TA-3-30 Warehouse -2; TA-3-34-Metal Shop -1; TA-3-38 Carpenter Shop -13; TA-3-38 Metals Fab Shop -16; TA-3-39 and 102 Metal Shop -7; TA-3-40, Room 1315 Machine Shop -1; TA-3-66 Sigma Facility -7; TA-3-2206 Warehouse -1; TA-9-28 Heavy Equipment Maintenance -1; TA-14-23 Burn Cage -1; TA-15-313 Machine Shop -1; TA-33-113 Machine Shop -1; TA-33-113 Machine Shop -1; TA-33-113 Machine Shop -1; TA-33-113 Machine Shop -1; TA-35-125 Machine Shop -1; TA-48-8 Machine Shop -1; TA-48-8 Machine Shop -1; TA-53-2 Machine Shop -1; TA-53-2 Machine Shop -1; TA-53-2 Machine Shop -1; TA-53-16 Machine Shop -1; TA-53-16 Machine Shop -1; TA-54-38 Indoor TSD -1; TA-54 Area TA-54-38 Machine Shop -1; TA-54-

า	Drovido a cummary o	f valir nact vaar's	auartorly vicual	assessment documentation	(coo Dart 2.2.2 of the por	mit) *
Z .	. FLOVIGE a Sulfillial V O	i vuui nasi veai s	dual telly visual	assessment adcamentation	DEE FALLOZZZ OF THE DELI	(111L)

A total of 668 visual assessments were completed at 66 different outfalls. Evidence of an oil sheen was observed in four samples: Outfall 021 on 11/04/2016, Outfall 024 on 09/07/2016 and 11/04/2016, and Outfall 052
on 05/02/2016. No other evidence of pollutants were observed.

3. For any four-sample (minimum) average benchmark monitoring exceedance, if after reviewing the selection, design, installation and implementation of your control measures and considering whether any modifications are necessary to meet the effluent limits in the permit, you determine that no further pollutant reductions are technologically available and economically practicable and achievable in light of best industry practice, provide your rationale for why you believe no further reductions are achievable (see Part 6.2.1.2 of the permit). Enter "NA" if not applicable. *

F, F y y y	регине (
N/A		

4. Provide a summary of your past year's corrective action documentation (See Part 4.4 of the permit). (Note: If corrective action is not yet completed at the time of submission of this annual report, you must describe the status of any outstanding corrective action(s).) Also describe any incidents of noncompliance in the past year or currently ongoing, or if none, provide a statement that you are in compliance with the permit. *

A total of 198 inspections and/or evaluations resulting in corrective actions were conducted at a total of 40 sites with the following total count of conditions observed:

Unauthorized Release or Discharge – 24; Control Measures Needing Maintenance, Repairs, or Replacement – 48; Additional Control Measures Needed – 2; Control Measures Inadequate to Meet Non-Numeric Effluent Limitations – 63; Incidents of Noncompliance [New Mexico Water Quality Standard (NM WQS) Exceedances – 23; Incidents of Noncompliance: Average Exceeds or is Average Exceeds or is Mathematically Certain to Exceed Benchmark Value – 6; Average Exceeds or is Mathematically Certain to Exceed Benchmark Value – 23.

At this time, there are only 2 outstanding corrective actions, both identified on December 19, 2016 and proposed for completion by February 2, 2017.

Regarding incidents of noncompliance, 28 monitored constituents from different outfalls exceeded an individual New Mexico Water Quality Standard (NM WQS). In addition, 9 monitored quarterly benchmark constituent value exceedances occurred where the benchmark value was modified to reflect a NM WQS per Section 9.6.2.1. Corrective actions to address these exceedances have been completed.

EPC-DO: 17-084: LA-UR-17-20556

Certification Information

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. 40 CFR 122.22



Permit Information (* indicates form required data)

Holly

2015 NPDES Multi-Sector General Permit For Stormwater Discharges Associated With Industrial Activity (MSGP) Forms

United States Environmental Protection Agency 1200 Pennsylvania Ave, NW Washington, DC 20460

5056671312

What action would you like to	o take? *			
New Industrial Stormwater A	Annual Report			
Please select the NPDES ID co	rresponding to the facility for which you would li	ke to submit an Annual Report and click the	Submit button.	
NPDES ID *				
NMR053195: LOS ALAMOS N	IATIONAL LABORATORY			
Confirm NPDES ID: NMR05	53195: LOS ALAMOS NATIONAL LABORATORY *			
Facility Information				
Facility Name				
Los Alamos National Lal	boratory			
Street				
PO Box 1663				
Supplemental address				
MS K490				
City	Sta	te	Zip Code	
Los Alamos	Ne	ew Mexico	87545	
First Name	Middle Name	Last Name	Telephone Number	

Wheeler

Summary of past year's inspections, assessments, and corrective actions

1. Provide a summary of your past year's routine facility inspection documentation (see Part 3.1.2 of the permit). In addition, if you are an operator of an airport facility (Sector S) that is subject to the airport effluent limitations guidelines, and are complying with the MSGP Part 8.S.8.1 effluent limitation through the use of non-urea-containing deicers, provide a statement certifying that you do not use airfield pavement deicers containing urea (e.g., "I certify that [name of airport] is in compliance with the effluent limitation guideline for airfield pavement deicing by not using airfield pavement deicers that contain urea."). [Note: Operators of airport facilities that are complying with Part 8.S.8.1 by meeting the numeric effluent limitation for ammonia do not need to include this statement.] *

Los Alamos National Laboratory (LANL), operated by Los Alamos National Security, LLC (LANS), consists of 13 active industrial sites that operate under 8 different Sectors (A, D, F, K, N, O, P, and AA). All 13 active sites were inspected according the schedules identified in the site-specific Stormwater Pollution Prevention Plans (SWPPPs). The 35 sites that qualify for a conditional exclusion for no exposure and one inactive site were inspected between December 1st and 22nd, 2017. A total of 153 inspections were conducted at 49 facilities. A count of corrective actions by facility are as follows:

TA-3-Power and Steam Plant – 27; TA-3-32 Metal Shop – 2; TA-3-38 Metal Shop – 6; TA-3-38 Metals Fab Shop – 18; TA-3-39 and 102 Metal Shop – 12; TA-3-66 Sigma Facility – 23; TA-9-28 Heavy Equipment Maintenance – 1; TA-15-313 Machine Shop – 2; TA-35-125 Machine Shop – 1; TA-46-31 Machine Shop – 1; TA-50-69 WCRRF – 3; TA-53-2 Machine Shop – 3; TA-53-16 Machine Shop – 1; TA-53-26 Machine Shop – 1; TA-54 Area L – 9; TA-54 Area G – 15; TA-54 Maintenance Facility West – 4; TA-54 RANT – 6; TA-60 Asphalt Batch Plant – 8; TA-60 MRF – 17; TA-60 Roads and Grounds – 45; TA-60-1 Heavy Equipment Yard – 28; TA-60-2 Warehouse – 20; TA-63 Transuranic Waste Facility – 1.

2. Provide a summary of your past year's quarterly visual assessment documentation (see Part 3.2.2 of the permit) *

A total of 529 visual assessments were completed at 70 different outfalls. Evidence of an oil sheen was observed in two samples: Outfall 024 and Outfall 028 on 04/04/2017. No other evidence of pollutants were observed.
observed.

3. For any four-sample (minimum) average benchmark monitoring exceedance, if after reviewing the selection, design, installation and implementation of your control measures and considering whether any modifications are necessary to meet the effluent limits in the permit, you determine that no further pollutant reductions are technologically available and economically practicable and achievable in light of best industry practice, provide your rationale for why you believe no further reductions are achievable (see Part 6.2.1.2 of the permit). Enter "NA" if not applicable. *

N/A		

4. Provide a summary of your past year's corrective action documentation (See Part 4.4 of the permit). (Note: If corrective action is not yet completed at the time of submission of this annual report, you must describe the status of any outstanding corrective action(s).) Also describe any incidents of noncompliance in the past year or currently ongoing, or if none, provide a statement that you are in compliance with the permit. *

A total of 153 inspections were conducted at 49 facilities, with the following total count of conditions observed:

SWPPP Non-conformance – 2; Unauthorized Release or Discharge – 48; Control Measures Needing Maintenance, Repairs, or Replacement – 50; Additional Control Measures Needed – 1; Control Measures Inadequate to Meet Non-Numeric Effluent Limitations – 78; Incidents of Noncompliance (Effluent Limitation Guidelines Exceedances) – 1; Incidents of Noncompliance (New Mexico Water Quality (NM WQS) Exceedances] – 32; Incidents of Noncompliance (Average Exceeds or is Mathematically Certain to Exceed Benchmark Value Modified to Reflect a NM WQS per Section 9.6.2.1) – 15; Average Exceeds or is Mathematically Certain to Exceed Benchmark Value – 27.

At the time of annual report submission, there is only one outstanding corrective action, identified on December 21, 2017, and scheduled to be completed by February 1, 2018. Regarding incidents of noncompliance, 32 monitored constituents from different outfalls exceeded an individual NM WQS; 15 monitored quarterly benchmark constituent exceedances occurred where the benchmark value was modified to reflect a NM WQS per Section 9.6.2.1; and one effluent limitation guideline exceedance occurred. Corrective actions to address these exceedances have been completed. LA-UR-18-20566.

Certification Information

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. 40 CFR 122.22

APPENDIX G

Spill Reports

RELEASE / DISCHARGE NOTIFICATION

Permit Number: NM0028355

LOS ALAMOS NATIONAL LABORATORY LA-UR-

15-29396

2016

NPDES or Operational Spill/Release Release ID Number: ER Spill/Release Indicate with "X" in appropriate box. 416 Other Spill/Release Responsible Facility/User Group: UI-DO Contact Person: Andrew Erickson NA Pager #: Phone #: 667-4222 NA Cell Phone #: Release/Discharge Location: During a site observation, a steam condensate leak at Los Alamos National Laboratory by the southwest corner of Technical Area 3, Building 38 was confirmed TA: 3 to have reached the storm drain on 12/2/2015. An initial site visit on the afternoon of 12/1 raised suspicion about the potential for the steam condensate to reach the **Building:** 38 storm drain. Cool morning temperatures the morning of 12/2 helped confirm the presence of the steam condensate in the storm drain. The steam condensate is leaking at a rate of approximately 1 gallon every three to five minutes, depending on facility demand. The leak is occurring on a paved surface and is entering a storm drain that is connected to Sandia Canyon. The steam condensate appears to be comingling with the water from the leak that was reported in Release Report #383 (corrective actions associated with the discovery of the source of the water Release Report #383 are ongoing, its source appears to be potable water). The leak was originally minimal and was confined to wetting the paved surface in the immediate vicinity of the leak. The steam condensate discharged prior to it reaching the storm drain has been documented and will be included in the Quarterly Discharge Report covering the period of October 1, 2015 through December 31, 2015. Portions of TA-3-38 are also covered under the NPDES Multi Sector General Permit. If the release/discharge is associated with a NPDES Outfall, Potential Release Site (PRS) or Solid Waste Management Unit (SWMU), indicate the site/unit number and its relationship to the release/discharge: NPDES Outfall: PRS: SWMU: ✓ PRS/SWMU Number: 3-013(a) Indicate with "X" in appropriate box(es). Relationship of the Discharge to a SWMU or PRS: The storm drain system around TA-3-38 is SWMU 03-013(a), the outfall for the storm drain system by TA-3-38 is SWMU 03-052(f). Stormwater IP Site S-SMA-0.25 is within the drainage area. The release does not appear to have adversely affected the SWMUs or IP site. Discharge 12/2/2015 ~8:00 a.m. Discharge 12/2/2015 ~8:00 a.m. 12/23/2015 Morning Discharge Occurred: Discovered: Stopped: Date & Time Date & Time Date & Time 12/15/2015 Morning Cleanup Cleanup 12/23/2015 Afternoon Started: Completed: Date & Time Date & Time Material(s) Released / Discharged: Steam Condensate Release/Discharge Mitigation Method: Repairs to the steam condensate line were completed on 12/23/2015. **Weather Conditions:** Mostly Sunny Duration of Release/ Est. Volume released,in Est. Volume Recovered, ~3.500 0 Discharge, in DAYS: gallons in gallons.

If the release/discharge reached a watercourse, describe the estimated surface area affected, presence of release/discharge now in the watercourse, and the media the release/discharge was detected in: The steam condensate has flowed to Sandia Canyon, but erosion was not observed. Depth to Groundwater, in FT, if known: ~1,000 Distance to Nearest Drinking Water Well, in FT, if known: ~22,000 Well ID# PM-3 24-HOUR RELEASE / DISCHARGE NOTIFICATIONS **Contact Person** Phone Fax Date & Time (or Comment) EPA: Gladys Gooden-Jackson 214-665-7494 12/9/2015 7 Day Report NMED/SWQB: Erin Trujillo 827-0418 12/2/2015 Verbal NMED/GWQB: Gerald Knutson 827-2996 827-2965 12/2/2015 Verbal NMED/HRMB: Ruth Horowitz 476-6025 12/2/2015 Verbal NMED/DOE-OB: Steve Yanicak 672-0448 661-4958 12/2/2015 Verbal ENV-CP: Jake Meadows 606-0185 665-9344 DOE: Gene Turner 667-5794 505-665-4872 12/2/2015 Electronic OTHER: Arturo Duran 665-7772 12/9/2015 7 Day Report OTHER: LANS, LLC staff provided verbal notification to NMED-GWQB, HWB, SWQB, and NMED/DOE Oversight Comments: Bureau on 12/2/2015, within 24 hours of confirming the steam condensate reached the storm drain. Form Completed By: Jake Meadows 7 DAY RELEASE / DISCHARGE ACTIONS 7 Day Notice 🗹 7 Day Notice Date: 12/9/2015 7 Day Notice By: Jake Meadows Mark "X" when done Comments: Additional information may be provided in the 15 Day report. 15 DAY RELEASE / DISCHARGE ACTIONS 15 day Follow-up Due: 12/16/2015 15-day Follow-Up By: Jake Meadows At a site visit on 12/15/2015, the condensate was no longer discharging to the storm drain. Excavations have Comments: commenced in support of identifying and repairing the leak(s). Additional information, along with a request for closure may be provided following completion of repairs. CLOSURE REQUEST: Repairs to the condensate line were completed on 12/23/2015. All corrective actions have been completed, LANS, LLC requests administrative closure of Release Report #416 pursuant to 20.6.2.1203 NMAC. NMED 30 DAY APPROVAL / DISAPPROVAL NMED 30 Day Response Date: 1/4/2016 Comments:

Arturo Duran
Office of Los Alamos Site Operations
Department of Energy
Los Alamos, New Mexico 87544
(505) 665-7772

Alison Dorries, ENV Division Director Los Alamos National Security, LLC. Los Alamos National Laboratory P.O. Box 1663, MS K404 Los Alamos, New Mexico 87544 (505) 667-2211

RELEASE / DISCHARGE NOTIFICATION

Permit Number: NM0028355

LOS ALAMOS NATIONAL LABORATORY LA-UR-

15-29396

Calendar Year

NPDES or Operational Spill/Release Release ID Number: ER Spill/Release Indicate with "X" in appropriate box. 416 Other Spill/Release Responsible Facility/User Group: UI-DO Contact Person: Andrew Erickson NA Pager #: Phone #: 667-4222 Cell Phone #: NA Release/Discharge Location: During a site observation, a steam condensate leak at Los Alamos National Laboratory by the southwest corner of Technical Area 3, Building 38 was confirmed TA: 3 to have reached the storm drain on 12/2/2015. An initial site visit on the afternoon of Building: 12/1 raised suspicion about the potential for the steam condensate to reach the 38 storm drain. Cool morning temperatures the morning of 12/2 helped confirm the presence of the steam condensate in the storm drain. The steam condensate is leaking at a rate of approximately 1 gallon every three to five minutes, depending on facility demand. The leak is occurring on a paved surface and is entering a storm drain that is connected to Sandia Canyon. The steam condensate appears to be comingling with the water from the leak that was reported in Release Report #383 (corrective actions associated with the discovery of the source of the water Release Report #383 are ongoing, its source appears to be potable water). The leak was originally minimal and was confined to wetting the paved surface in the immediate vicinity of the leak. The steam condensate discharged prior to it reaching the storm drain has been documented and will be included in the Quarterly Discharge Report covering the period of October 1, 2015 through December 31, 2015. Portions of TA-3-38 are also covered under the NPDES Multi Sector General Permit. If the release/discharge is associated with a NPDES Outfall, Potential Release Site (PRS) or Solid Waste Management Unit (SWMU), indicate the site/unit number and its relationship to the release/discharge: NPDES Outfall: PRS: SWMU: ✔ PRS/SWMU Number: 3-013(a) Indicate with "X" in appropriate box(es). Relationship of the Discharge to a SWMU or PRS: The storm drain system around TA-3-38 is SWMU 03-013(a), the outfall for the storm drain system by TA-3-38 is SWMU 03-052(f). Stormwater IP Site S-SMA-0.25 is within the drainage area. The release does not appear to have adversely affected the SWMUs or IP site. Discharge 12/2/2015 ~8:00 a.m. Discharge 12/2/2015 ~8:00 a.m. Discharge Ongoing Occurred: Discovered: Stopped: Date & Time Date & Time Date & Time Cleanup Ongoing Cleanup Ongoing Started: Completed: Date & Time Date & Time Material(s) Released / Discharged: Steam Condensate Release/Discharge Mitigation Method: The steam condensate line will be excavated and repaired as soon as practicable. Weather Conditions: Mostly Sunny **Duration of Release/** Est. Volume released,in Est. Volume Recovered. ~3.500 ٥ Discharge, in DAYS:

gallons:

in gallons.

If the release/discharge reached a watercourse, describe the estimated surface area affected, presence of release/discharge now in the watercourse, and the media the release/discharge was detected in:

Depth to Gro	oundwat	er, in FT, if known:	~1,000			
Distance to N	Nearest i	Orinking Water Well, in FT,	if known:	~22,000	Well ID#	PM-3
		24-HOUR RELEA	SE / DISCHA	RGE NOTIFICA	ATIONS	
		Contact Person	Phone	Fax		Time (or Comment
	EPA:	Gladys Gooden-Jackson	214-665-7494		12/9/2015	7 Day Report
NMED/	SWQB:	Erin Trujillo	827-0418		12/2/2015	Verbal
NMED/	GWQB:	Gerald Knutson	827-2996	827-2965	12/2/2015	Verbal
NMED/	HRMB:	Ruth Horowitz	476-6025		12/2/2015	Verbal
NMED/DO	DE-OB:	Steve Yanicak	672-0448	661-4958	12/2/2015	Verbal
EI	NV-CP:	Jake Meadows	606-0185	665-9344		
	DOE:	Gene Turner	667-5794	505-665-4872	12/2/2015	Electronic
	THER:	Arturo Duran	665-7772		12/9/2015	7 Day Report
0						
o	THER:	LC staff provided verbal notion 12/2/2015, within 24 hours	fication to NMED-C s of confirming the	GWQB, HWB, SWQ steam condensate r	B, and NMED	/DOE Oversight torm drain.
	LANS, I Bureau	LC staff provided verbal notion 12/2/2015, within 24 hours	fication to NMED-C s of confirming the	GWQB, HWB, SWQI steam condensate r	B, and NMED reached the si	/DOE Oversight torm drain.
O omments:	LANS, I Bureau	Jake Meadows	s of confirming the	GWQB, HWB, SWQ steam condensate r	reached the s	/DOE Oversight torm drain.
O omments:	LANS, I Bureau eted By:	Jake Meadows 7 DAY RELE 7 Day Notice Date:	s of confirming the	steam condensate r	reached the si	/DOE Oversight torm drain.
Omments: Orm Comple 7 Day N Mark "X" v	LANS, I Bureau eted By:	Jake Meadows 7 DAY RELE 7 Day Notice Date:	EASE / DISCH	IARGE ACTION 7 Day Not	reached the si	torm drain.
Omments: Orm Comple 7 Day N Mark "X" v	LANS, I Bureau eted By:	Jake Meadows 7 DAY RELE 7 Day Notice Date: e. al information may be provide	EASE / DISCH 12/9/2015 ed in the 15 Day re	IARGE ACTION 7 Day Not	reached the si	torm drain.
orm Comple 7 Day N Mark "X" v	LANS, L Bureau eted By: Notice when don Addition	Jake Meadows 7 DAY RELE 7 Day Notice Date: e. al information may be provide 15 DAY RELE	EASE / DISCH 12/9/2015 ed in the 15 Day re	IARGE ACTION 7 Day Not	VS VS	torm drain.
Onomments: 7 Day North Tark "X" womments: 15 day Folicomments:	LANS, L Bureau eted By: Notice when don Addition At a site commer	Jake Meadows 7 DAY RELE 7 Day Notice Date: e. al information may be provide 15 DAY RELE	EASE / DISCH 12/9/2015 ed in the 15 Day re EASE / DISCH densate was no lonand repairing the le	JARGE ACTION 7 Day Not port. HARGE ACTION 15-day Follow- ger discharging to the sak(s) Additional in	VS -Up By: Jak	te Meadows e Meadows
Orm Comple 7 Day N Mark "X" v Omments:	LANS, L Bureau eted By: Notice when don Addition At a site commer	Jake Meadows 7 DAY RELE 7 Day Notice Date: e. al information may be provide 15 DAY RELE 12/16/2015 visit on 12/15/2015, the concided in support of identifying a may be provided following contacts.	EASE / DISCH 12/9/2015 ed in the 15 Day re EASE / DISCH densate was no lon and repairing the lean mpletion of repairs	IARGE ACTION 7 Day Not port. HARGE ACTION 15-day Follow- ger discharging to the tak(s). Additional into	VS Up By: Jak ne storm drair formation, alo	te Meadows e Meadows
Onomments: 7 Day North Tark "X" womments: 15 day Folicomments:	ELANS, L Bureau Sted By: Notice (when don Addition Addition At a site commerciosure r	Jake Meadows 7 DAY RELE 7 Day Notice Date: e. al information may be provide 15 DAY RELE 12/16/2015 visit on 12/15/2015, the conceed in support of identifying anay be provided following column.	EASE / DISCH 12/9/2015 ed in the 15 Day re EASE / DISCH densate was no lonand repairing the lempletion of repairs	IARGE ACTION 7 Day Not port. HARGE ACTION 15-day Follow- ger discharging to the tak(s). Additional into	VS Up By: Jak ne storm drair formation, alo	te Meadows e Meadows

Arturo Duran
Office of Los Alamos Site Operations
Department of Energy
Los Alamos, New Mexico 87544
(505) 665-7772

Alison Dorries, ENV Division Director Los Alamos National Security, LLC. Los Alamos National Laboratory P.O. Box 1663, MS K404 Los Alamos, New Mexico 87544 (505) 667-2211

RELEASE / DISCHARGE NOTIFICATION

Permit Number: NM0028355

LOS ALAMOS NATIONAL LABORATORY LA-UR-

15-29396

Calendar Year

NPDES or Operational Spill/Release Release ID Number: ER Spill/Release Indicate with "X" in appropriate box. 416 Other Spill/Release Responsible Facility/User Group: UI-DO Contact Person: Andrew Erickson NA Pager #: Phone #: 667-4222 Cell Phone #: NA Release/Discharge Location: During a site observation, a steam condensate leak at Los Alamos National TA: Laboratory by the southwest corner of Technical Area 3, Building 38 was confirmed 3 to have reached the storm drain on 12/2/2015. An initial site visit on the afternoon of 12/1 raised suspicion about the potential for the steam condensate to reach the **Building:** 38 storm drain. Cool morning temperatures the morning of 12/2 helped confirm the presence of the steam condensate in the storm drain. The steam condensate is leaking at a rate of approximately 1 gallon every three to five minutes, depending on facility demand. The leak is occurring on a paved surface and is entering a storm drain that is connected to Sandia Canyon. The steam condensate appears to be comingling with the water from the leak that was reported in Release Report #383 (corrective actions associated with the discovery of the source of the water Release Report #383 are ongoing, its source appears to be potable water). The leak was originally minimal and was confined to wetting the paved surface in the immediate vicinity of the leak. The steam condensate discharged prior to it reaching the storm drain has been documented and will be included in the Quarterly Discharge Report covering the period of October 1, 2015 through December 31, 2015. Portions of TA-3-38 are also covered under the NPDES Multi Sector General Permit. If the release/discharge is associated with a NPDES Outfall, Potential Release Site (PRS) or Solid Waste Management Unit (SWMU), indicate the site/unit number and its relationship to the release/discharge: NPDES Outfall: PRS: SWMU: ✓ PRS/SWMU Number: 3-013(a) Indicate with "X" in appropriate box(es) Relationship of the Discharge to a SWMU or PRS: The storm drain system around TA-3-38 is SWMU 03-013(a), the outfall for the storm drain system by TA-3-38 is SWMU 03-052(f). Stormwater IP Site S-SMA-0.25 is within the drainage area. The release does not appear to have adversely affected the SWMUs or IP site. Discharge 12/2/2015 ~8:00 a.m. Discharge 12/2/2015 ~8:00 a.m. Discharge Ongoing Occurred: Discovered: Stopped: Date & Time Date & Time Date & Time Cleanup Ongoing Cleanup Ongoing Started: Completed: Date & Time Date & Time Material(s) Released / Discharged: Steam Condensate Release/Discharge Mitigation Method: The steam condensate line will be excavated and repaired as soon as practicable. Weather Conditions: Mostly Sunny Duration of Release/ Est. Volume released,in Est. Volume Recovered, ~7 ~2.000 0 Discharge, in DAYS:

gallons:

in gallons.

If the release/discharge reached a watercourse, describe the estimated surface area affected, presence of release/discharge now in the watercourse, and the media the release/discharge was detected in: The steam condensate has flowed to Sandia Canyon, but erosion was not observed. Depth to Groundwater, in FT, if known: ~1,000 Distance to Nearest Drinking Water Well, in FT, if known: ~22,000 Well ID# PM-3 24-HOUR RELEASE / DISCHARGE NOTIFICATIONS **Contact Person** Phone Fax Date & Time (or Comment) EPA: Gladys Gooden-Jackson 214-665-7494 12/9/2015 7 Day Report NMED/SWQB: Erin Trujillo 827-0418 12/2/2015 Verbal NMED/GWQB: Gerald Knutson 827-2996 827-2965 12/2/2015 Verbal NMED/HRMB: Ruth Horowitz 476-6025 12/2/2015 Verbal NMED/DOE-OB: Steve Yanicak 672-0448 661-4958 Verbal 12/2/2015 ENV-CP: Jake Meadows 606-0185 665-9344 DOE: Gene Turner 667-5794 505-665-4872 12/2/2015 Electronic OTHER: Arturo Duran 665-7772 12/9/2015 7 Day Report OTHER: Comments: LANS, LLC staff provided verbal notification to NMED-GWQB, HWB, SWQB, and NMED/DOE Oversight Bureau on 12/2/2015, within 24 hours of confirming the steam condensate reached the storm drain. Form Completed By: Jake Meadows 7 DAY RELEASE / DISCHARGE ACTIONS 7 Day Notice 7 Day Notice Date: 12/9/2015 7 Day Notice By: Jake Meadows Mark "X" when done. Comments: Additional information may be provided in the 15 Day report. 15 DAY RELEASE / DISCHARGE ACTIONS 15 day Follow-up Due: 12/17/2015 15-day Follow-Up By: Jake Meadows Comments: NMED 30 DAY APPROVAL / DISAPPROVAL

Arturo Duran
Office of Los Alamos Site Operations
Department of Energy
Los Alamos, New Mexico 87544
(505) 665-7772

1/4/2016

Alison Dorries, ENV Division Director Los Alamos National Security, LLC. Los Alamos National Laboratory P.O. Box 1663, MS K404 Los Alamos, New Mexico 87544 (505) 667-2211

NMED 30 Day Response Date:

Comments:

APPENDIX H

Stormwater Monitoring Records and Results/MDMRs (Current Permit)

Permitted Facility: TA-3-38 Carpenter Shop

Section 4.6.3 Monitoring Requirements

Outfall: 073 (3-CS-1)

Monitoring Requirement	Industrial Sector	Assessment Unit	Analyte	Filtered/ Unfiltered	Regulatory Standard	Units	Regulatory Standard Type	Regulatory Standard Reference
Impaired Waters	-	NM-9000.A_047	Total Aroclors	UF	0.2	ug/L	2007 EPA R6 MQL	20.6.4.900 NMAC Subpart J/ 20.6.4.12 NMAC Subpart E
Impaired Waters	-	NM-9000.A_047	Al	F10u ¹	681	ug/L	NM 2010 Aquatic Chronic 60 mg	20.6.4.900 NMAC Subpart I
Impaired Waters	-	NM-9000.A_047	Cu	F ²	6	ug/L	NM 2010 Aquatic Chronic 60 mg	20.6.4.900 NMAC Subpart I
Impaired Waters	-	NM-9000.A_047	TI	F	0.47	ug/L	NM 2010 Aquatic Chronic 60 mg	20.6.4.900 NMAC Subpart I
Impaired Waters	-	NM-9000.A_047	Adjusted Gross Alpha	UF	15	pCi/L	NM 2010 Livestock Watering	20.6.4.900 NMAC Subpart J
Quarterly Benchmark	Α	-	COD	UF	120	mg/L	MSGP QBM 2015	NMR053195 Sect 9.6.2.1
Quarterly Benchmark	Α	-	TSS	UF	100	mg/L	MSGP QBM 2015	NMR053195 Sect 9.6.2.1

¹F10u – 10 μm filter

Section 2.5 Sampling Data Summary

CY 2016

Insufficient volume was collected in 2016 to analyze for all parameters. No data are available for Total Aroclors, Al, Adjusted Gross Alpha, and TSS.

Monitored Outfall	Discontinue	Monitoring		Co	ntinue Monitoring		
	Average of four monitoring values did not exceed benchmark; quarterly monitoring	Impaired water constituent was not detected in storm water discharge; annual monitoring	Fewer than four quarterly samples have been collected in current sequence. Average concentration is not mathematically	Average concentration mathematically certain to exceed benchmark.	Average of four quarterly monitoring values exceeded benchmark.	Impaired water constituent was detected, but did not exceed New Mexico Water Quality criterion.	Impaired water constituent exceeded New Mexico Water Quality criterion.

 $^{^2\}text{F}$ - 0.45 μm filter

	discontinued per	discontinued per	certain to exceed				
	Section 6.2.1.2	Section 6.2.4.1.	benchmark.				
073	_	TI	COD	_	_	_	Cu

CY 2017

Insufficient volume was collected in 2017 to analyze for all parameters. No data are available for Total Aroclors, and Adjusted Gross Alpha.

Monitored Outfall	Discontinue	Monitoring		Co	ntinue Monitoring		
	Average of four monitoring values did not exceed benchmark; quarterly monitoring discontinued per Section 6.2.1.2	Impaired water constituent was not detected in storm water discharge; annual monitoring discontinued per Section 6.2.4.1.	Fewer than four quarterly samples have been collected in current sequence. Average concentration is not mathematically certain to exceed benchmark.	Average concentration mathematically certain to exceed benchmark.	Average of four quarterly monitoring values exceeded benchmark.	Impaired water constituent was detected, but did not exceed New Mexico Water Quality criterion.	Impaired water constituent exceeded New Mexico Water Quality criterion.
073	_	_	COD, TSS	_	_	Al	Cu

CY 2018

Monitored Outfall	Discontinue	Monitoring		Co	ntinue Monitoring		
	Average of four monitoring values did not exceed benchmark; quarterly monitoring discontinued per Section 6.2.1.2	Impaired water constituent was not detected in storm water discharge; annual monitoring discontinued per Section 6.2.4.1.	Fewer than four quarterly samples have been collected in current sequence. Average concentration is not mathematically certain to exceed benchmark.	Average concentration mathematically certain to exceed benchmark.	Average of four quarterly monitoring values exceeded benchmark.	Impaired water constituent was detected, but did not exceed New Mexico Water Quality criterion.	Impaired water constituent exceeded New Mexico Water Quality criterion.
073	_	Total Aroclor	COD, TSS	_	_	Al, Adjusted Gross Alpha	Cu

Section 4.7 Monitoring

Outfall: 074

Monitoring Requirement	Industrial Sector	Assessment Unit	Analyte	Filtered/ Unfiltered	Regulatory Standard	Units	Regulatory Standard Type	Regulatory Standard Reference
Impaired Waters	-	NM-9000.A_047	Total Aroclor	UF	0.2	ug/L	2007 EPA R6 MQL	20.6.4.900 NMAC Subpart J/ 20.6.4.12 NMAC Subpart E
Impaired Waters	-	NM-9000.A_047	Al	F10u ¹	1010	ug/L	NM 2010 Aquatic Chronic 80 mg	20.6.4.900 NMAC Subpart I
Impaired Waters	-	NM-9000.A_047	Cu	F ²	7	ug/L	NM 2010 Aquatic Chronic 80 mg	20.6.4.900 NMAC Subpart I
Impaired Waters	-	NM-9000.A_047	Temp	UF	24	°C	NM 2010 Aquatic Chronic	20.6.4.900 NMAC Subpart H (2)
Quarterly Benchmark	Α	-	COD	UF	120	mg/L	MSGP QBM 2015	NMR050013 Sect 9.6.2.1
Quarterly Benchmark	А	-	TSS	UF	100	mg/L	MSGP QBM 2015	NMR050013 Sect 9.6.2.1

¹F10u – 10 μm filter

 $^{^2\}text{F}$ - 0.45 μm filter



Environmental Protection & Compliance Division Los Alamos National Laboratory PO Box 1663, K491 Los Alamos, New Mexico 87545 (505) 667-2211

SFP 2 5 2017

Date:

Symbol: EPC-DO: 17-401

LA-UR: 17-28621

Locates Action No.: N/A

U.S. EPA Region 6 NPDES Stormwater Program (WQ-PP) 1445 Ross Avenue, Suite 1200 Dallas, TX 75202-2733

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Industrial Discharge Monitoring Reports (MDMRs) for July 26 and 29, 2017

To whom it may concern:

Enclosed are Los Alamos National Laboratory's MDMRs (Enclosure 1) for July 26 and 29, 2017 as required under MSGP Permit Tracking No. NMR053195. These reports are being submitted on behalf of Los Alamos National Security, LLC and contain analytical results for impaired waters and quarterly benchmark monitoring at outfalls 012, 020, 031, 039 and 073.

Please contact Holly Wheeler at (505) 667-1312 or Terrill Lemke at (505) 665-2397 if you have questions regarding these MDMRs.

Sincerely,

Anthony R. Grieggs Group Leader

Male Solda h

USEPA MSGP Reports

EPC-DO: 17-401

ARG/TWL/HLW: am

Enclosure(s): 1): NPDES Permit Tracking No. NMR053195, MDMRs for July 26 and 29, 2017

Copy: Helen Nguyen, EPA Region 6, Dallas TX (E-File)

Nasim Jahan, EPA Region 6, Dallas TX (E-File)

Michelle Hunter, NMED/GWQB, Santa Fe, NM (E-File)

Shelly Lemon, NMED/SWQB, Santa Fe, NM (E-File)

Karen Armijo, NA-LA, (E-File)

Arturo Duran, EM-SG, (E-File)

David Rhodes, EM-SG, (E-File)

Craig S. Leasure, PADOPS, (E-File)

William R. Mairson, PADOPS, (E-File)

Michael T. Brandt, ADESH, (E-File)

Raeanna Sharp-Geiger, ADESH, (E-File)

Bruce Robinson, ADEM-PO, (E-File)

Andrew Erickson, UI-DO, (E-File)

Clifford Kirkland, STO-DO, (E-File)

Stephanie Archuleta, DESHF-DO, (E-File)

Theresa Cull, DESHS-DO, (E-File)

Russel Stone, DESHS-UIS, (E-File)

Garry Schramm, DESHF-STO, (E-File)

Jillian Burgin, DESHS-UIS, (E-File)

Marc Gallegos, DESHF-STO, (E-File)

Courtney Perkins, DESHF-STO, (E-File)

Terrill W. Lemke, EPC-CP, (E-File)

Holly L. Wheeler, EPC-CP, (E-File)

Leslie J. Dale, EPC-CP, (E-File)

Ellena I. Martinez, EPC-CP, (E-File)

Adesh-records@lanl.gov, (E-File)

lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

NPDES Permit Tracking No. NMR053195, MDMRs for July 26 and 29, 2017

EPC-DO: 17-401

LA-UR-17-28621

Date: _____ SEP 2 5 2017

NPDES FORM 6100-29



United States Environmental Protection Agency Washington, DC 20460 MSGP Industrial Discharge Monitoring Report (DMR) Form

Form Approved. OMB No. 2040-0004

A. Approval to User Paper DMR Form 1. Have you been granted a waiver from electronic reporting from EPA Regional Office*? X YES NO If yes, check which waiver you have been granted, the name of the EPA Regional Office staff person who granted the waiver, and the date of approval: The owner/operator's headquarters is physically located in a geographic area (i.e., ZIP code or census tract) that is identified as under-served for broadband Internet access in the most recent report from the Federal Communications Commission. The owner/operator has issues regarding available computer access or computer capability. **Everett Spencer** Name of EPA staff person that granted the waiver: 06/17/2016 Date approval obtained: * Note: You are required to obtain approval from the applicable EPA Regional Office prior to using this paper DMR form. If you have not obtained a waiver, you must file this form electronically using the NetDMR at http://www.epa.gov/netdmr/ B. Permit Information NMR053195 1. NPDES ID: 2. Reason(s) for Submission (Check all that apply): X Submitting monitoring data (Fill in all Sections). Reporting no discharge for all outfalls for this monitoring period (Fill in Sections A, B, C, D, E.1, and G). Reporting that your site status has changed to inactive and unstaffed (Fill in Sections A, B, C, D, and F and include date of status change in comment field Reporting that your site status has changed to active (Fill in all Sections and include date of status change in comment field in Section F.4). Reporting that no further pollutant reductions are achievable for all outfalls and for all pollutants via Part 6.2.1.2 of the MSGP (Fill in Sections A, B, C, D, C. Facility Operator Information 1. Operator Information Los Alamos National Security, LLC Operator Name: Mailing Address: P.O. Box 1663, MS K490 Street: 87545 City: Los Alamos NM ZIP Code: State: 505 667 0666 Phone: E-mail: grieggst@lanl.gov 2. DMR Preparer (Complete if DMR was prepared by someone other than the certifier): Holly L. Wheeler First Name, Middle Initial, Last Name: **EPC-CP** Organization: 505 667 1312 Phone: E-mail: hbenson@lanl.gov

D. Facility Inform	ation
1. Facility Name:	Los Alamos National Laboratory
2. Facility Address:	
Street/Location	Bikini Atoll Rd. SM30 K490
City:	Los Alamos State: NM ZIP Code: 87545 -
County or Similar Govern	ment Subdivision: Los Alamos
E. Discharge Info	irmation
1. Identify monitoring per	Check here if proposing alternative monitoring periods due to irregular stormwater runoff. Identify alternative monitoring schedule and indicate for which alternative monitoring period you are reporting monitoring data:
Quarter 1 (January 1 -	- March 31) Quarter 1: From 04 / 01 To 05 / 31
Quarter 2 (April 1 – Ju	ine 30) X Quarter 2: From 06 / 01 To 07 / 31
Quarter 3 (July 1 – Sep	ptember 30)
Quarter 4 (October 1	- December 31) Quarter 4: From [10] / [01] To [11] / [30]
2. Are you required to mor freshwater?	nitor for cadmium, copper, chromium, lead, nickel, silver, or zinc in X Yes (Skip to 3) No (Skip to 4)
3. What is the hardness le	vel of the receiving water?57
4. Does your facility discha	arge into any saltwater receiving waters? Yes X No

F. Monitori	F. Monitoring Information		No	Note: Make additional copies of this form as necessary.	of this form as	s necess	ary.			
1. Nature of Discharge:	×	ainfall (Com	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	nelt					
. Duration of	2.a. Duration of the rainfall event (hours): 0	ırs): 0	2.b. Rainfall a	2.b. Rainfall amount (inches): 1.0 2.c. $^{-1}$	Time since previo	us measura	2.c. Time since previous measurable storm event (days): 8			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.d. Monitoring Type QBM, ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant reductions achievable?
012	Substantially identical to outfall:		_	Adjusted Gross Alpha	31.1	pCi/L		07/26/2017		
012	Substantially identical to outfall:		_	Aluminum, total recoverable	709	ng/L		07/26/2017		
012	Substantially identical to outfall.		_	Copper, dissolved	2.08	ng/L		07/26/2017		
012	Substantially identical to outfall.		QBM	Iron, total	989	ng/L		07/26/2017		
011	X Substantially identical to outfall: 012									

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

 $^{4.\} Comment\ and/or\ Explanation\ of\ Any\ Violations\ (Reference\ all\ attachments\ here)$

Rainfall duration = 0.50 hours. Rainfall amount = 0.99 inches.

^{012:} The impaired water pollutant Adjusted Gross Alpha exceeds the New Mexico water quality standard. The impaired water pollutant total recoverable Aluminum exceeds the New Mexico water quality standard. Aroclor, total (I) - NODI B. Thallium, dissolved (I) - NODI B.

F. Monitori	F. Monitoring Information		NC	Note: Make additional copies of this form as necessary.	of this form as	s necessé	ary.			
1. Nature of Discharge:	×	Rainfall (Corr	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.) Snowmelt	melt					
2.a. Duration of	2.a. Duration of the rainfall event (hours): (ours): 0	2.b. Rainfall a	2.b. Rainfall amount (inches): 1,0 2.c.	Time since previou	us measura	2.c. Time since previous measurable storm event (days): 8			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.d. Monitoring Type QBM, ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant reductions achievable?
020	Substantially identical to ouffall:	la l	QBM	Aluminum, total recoverable	BQL		50.0 ug/L	07/26/2017		
020	Substantially identical to ouffall:	П	MBD	Iron, total	ND		33.0 ug/L	07/26/2017		
020	Substantially identical to outfall:		QBM	Nitrate plus Nitrite Nitrogen	0.150	mg/L		07/26/2017		

* (QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 0.50 hours. Rainfall amount = 0.99 inches.

020: The average of four monitoring values for total recoverable Aluminum does not exceed the benchmark value, therefore quarterly monitoring will be discontinued per Part 6.2.1.2. The average of four monitoring values for total Iron does not exceed the benchmark value, therefore quarterly monitoring will be discontinued per Part 6.2.1.2. The average of four monitoring values for Nitrate plus Nitrate Nitrogen does not exceed the benchmark value, therefore quarterly monitoring will be discontinued per Part 6.2.1.2. Adjusted Gross Alpha (I) - NODI B. Aroclor, total (I) - NODI B. Thallium, dissolved (I) - NODI B. Aluminum, total recoverable (I) - NODI B.

	3	
ì	5	
	_	
	_)
	g	7
	ζ	3

		•••	lo er ant ons ble?		
		1,1 2.c. Time since previous measurable storm event (days): 18	3.k. N furthe polluta reducti achieval		
y.	.2.c.)		Exceedance 3.k. No due to further natural pollutant background reductions pollutant achievable?		
			3.i. Collection Date 07/26/2017		
			3.h. Results Description		
s necess			3.g. Units	ng/L	
Note: Make additional copies of this form as necessary.			3.f. Quality or Concentration	11.8	
			3.e. Parameter	Copper, dissolved	
ote: Make	2.a., 2.b., & amount (inc		м ⁱ	Cop	
No	X Rainfall (Complete line items 2.a., 2.b., & 2.c.)	irs): 1 2.b. Rainfall amount (inches):	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	_	
			3.c. Check if No Discharge		
F. Monitoring Information		ıfall ev	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	X Substantially identical to outfall: 031
F. Monitorin	1. Nature of Discharge:		3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	031	030

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 0.58 hours. Rainfall amount = 1.10 inches.

^{031:} The impaired water pollutant dissolved Copper exceeds the New Mexico water quality standard. Aroclor, total (I) - NODI B.

			3.k. No further pollutant reductions achievable?						
			3.j. Exceedance due to natural background pollutant levels						
			3.i. Collection Date	07/26/2017	07/26/2017	07/26/2017	07/26/2017		
ary.	ill (Complete line items 2.a., 2.b., & 2.c.) 1 2.b. Rainfall amount (inches):	able storm event (days): 644	3.h. Results Description				0.600 ug/L		
s necess		ous measur	3.g. Units	pCi/L	ng/L	ng/L			
of this form a		Time since previo	3.f. Quality or Concentration	409	16100	6.55	QN		
Note: Make additional copies of this form as necessary.		1.1	3.e. Parameter	Adjusted Gross Alpha	Aluminum, total recoverable	Copper, dissolved	Thallium, dissolved		
N		2.b. Rainfall	3.d. Monitoring Type QBM, ELG, S/T, I, O*	_	1	1	1		
		rs): 1	3.c. Check if No Discharge						×
F. Monitoring Information	×	2.a. Duration of the rainfall event (hours):	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	X Substantially identical to outfall: 039	X Substantially identical to outfall: 039			
F. Monitorin	1. Nature of Discharge:	2.a. Duration of t	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	039	039	039	039	038	040

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

039: The impaired water pollutant Adjusted Gross Alpha exceeds the New Mexico water quality standard. The impaired water pollutant total recoverable Aluminum exceeds the New Mexico water quality standard.

		$2.c.$ Time since previous measurable storm event (days): $oldsymbol{1}$	3.k. No further pollutant reductions achievable?				
	Rainfall (Complete line items 2.a., 2.b., & 2.c.)		3.j. Exceedance due to natural background pollutant levels				
			3.i. Collection Date	07/26/2017	07/26/2017	07/26/2017	
ary.			3.h. Results Description			18.1 mg/L	
s necess		ous measur	3.g. Units	ng/L	mg/L		
of this form a		Time since previc	3.f. Quality or Concentration	85	80.5	BQL	
Note: Make additional copies of this form as necessary.		2.b. Rainfall amount (inches): 1,0 2.c.	3.e. Parameter	Aluminum, total recoverable	Chemical Oxygen Demand (COD)	Total Suspended Solids (TSS)	
Ž		2.b. Rainfall	3.d. Monitoring Type QBM, ELG, S/T, I, O*	ı	WBO	WBÒ	
Seattle Seattle		ırs): 0	3.c. Check if No Discharge				
F. Monitoring Information	×	2.a. Duration of the rainfall event (hours): 0	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	Usubstantially identical to outfall:	Substantially identical to outfall:	X Substantially identical to outfall: 073
F. Monitorir	1. Nature of Discharge:	2.a. Duration of	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	073	073	073	074

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here) Rainfall duration = 0.50 hours. Rainfall amount = 0.99 inches.

^{073:} Copper, dissolved (I) - NODI 9. Thallium, dissolved (I) - NODI B.

C	3
20	5
E	;
a	3
C	J
¥	-
Cortifica	J
ā	j
C)
18	i

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information, the information, the information submitted is, to the beast of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

First Name, Middle Initial, Last Name: Anthony

R Grieggs

EPC-CP Group Leader

Title:

EPC-CP Group I

Date 09125120+7

Signature:

grieggst@lanl.gov

E-mail:

NPDES FORM 6100-29



United States Environmental Protection Agency Washington, DC 20460 MSGP Industrial Discharge Monitoring Report (DMR) Form

Form Approved. OMB No. 2040-0004

A. Approval to Us	ser Paper DMR Form	
1. Have you been granted	a waiver from electronic reporting from EPA Regional Office*? X YES NO ver you have been granted, the name of the EPA Regional Office staff person who granted the	a waiver, and the date of approval.
Waiver granted:	The owner/operator's headquarters is physically located in a geographic area (i.e., ZIP code under-served for broadband Internet access in the most recent report from the Federal Cor	or census tract) that is identified as
X	·	
Name of EPA staff perso	on that granted the waiver: Everett Spencer	
Date approval obtained	d: 06/17/2016	
	ilred to obtain approval from the applicable EPA Regional Office prior to using this ou must file this form electronically using the NetDMR at http://www.epa.gov/netd	
B. Permit Informa	ation	
1. NPDES ID:	NMR053195	
2. Reason(s) for Submission	on (Check all that apply):	
X Submitting monitori	ng data (Fill in all Sections).	
Reporting no discha	rge for all outfalls for this monitoring period (Fill in Sections A, B, C, D, E.1, and G).	
Reporting that your in Section F.4).	site status has changed to inactive and unstaffed (Fill in Sections A, B, C, D, and F and includ	e date of status change in comment field
Reporting that your	site status has changed to active (Fill in all Sections and include date of status change in con	nment field in Section F.4).
Reporting that no fu and G).	rther pollutant reductions are achievable for all outfalls and for all pollutants via Part 6.2.1.2	of the MSGP (Fill in Sections A, B, C, D,
C. Facility Operat	tor Information	
1. Operator Information	n	
Operator Name:	Los Alamos National Security, LLC	
Mailing Address:		
Street:	P.O. Box 1663, MS K490	
City:	Los Alamos State: NM	ZIP Code: 87545 -
Phone:	505 667 0666	
E-mail:	grieggst@lanl.gov	
2. DMR Preparer (Comp	plete if DMR was prepared by someone other than the certifier):	
First Name, Middle Initial,	Last Name: Holly L. Wheeler	-
Organization:	EPC-CP	_
Phone:	505 667 1312 Ext.	
E-mail:	hbenson@lanl.gov	_

D. Facility Inform	nation		
Facility Name: Facility Address:	Los Alamos National Laboratory		
Street/Location	Bikini Atoll Rd. SM30 K490	2	
City:	Los Alamos	State: NM	ZIP Code: 87545 -
County or Similar Govern	nment Subdivision: Los Alamos		
E. Discharge Info	ormation		
1. Identify monitoring pe	Check here if proposing alternative monitoring alternative monitoring schedule and indicate monitoring data:		
Quarter 1 (January 1	- March 31) Quarter 1: From 04 / 01 To	05 / 31	
Quarter 2 (April 1 – Ju	une 30) X Quarter 2: From 06 / 01 To	07 / 31	
Quarter 3 (July 1 – Se	ptember 30) Quarter 3: From 08 / 01 To	09 / 30	
Quarter 4 (October 1	- December 31) Quarter 4: From 10 / 01 To	11 / 30	
2. Are you required to mor freshwater?	nitor for cadmium, copper, chromium, lead, nickel, silver, or zinc in	X Yes (Skip	to 3) No (Skip to 4)
3. What is the hardness le	evel of the receiving water?57		
4. Does your facility discha	arge into any saltwater receiving waters? Yes	No	

EPA FORM 6100-29

F. Monitorii	F. Monitoring Information		N	Note: Make additional copies of this form as necessary.	of this form as	necess	ary.			
1. Nature of Discharge:	×	Rainfall (Con	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.) Snowmelt	melt				:	
2.a. Duration of	2.a. Duration of the rainfall event (hours): ${f 1}$	ours): 1	2.b. Rainfall	2.b. Rainfall amount (inches): 0,4 2.c. 1	Time since previou	us measura	0.4 2.c. Time since previous measurable storm event (days): 3			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.d. Monitoring Type QBM, ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant I reductions achievable?
031	Substantially identical to outfall:		-	Adjusted Gross Alpha	3.46	pCi/L		07/29/2017		
031	Substantially identical to outfall:		_	Aluminum, total recoverable	1060	ng/L		07/29/2017		
030	X Substantially identical to outfall: 031									

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.08 hours. Rainfall amount = 0.35 inches.

^{031:} Aroclor, total (I) - NODI B. Copper, dissolved (I) - NODI 9.

G. Certification

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information, the information, the information, the information submitted. Is not the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

First Name, Middle Initial, Last Name: Anthony

R Grieggs

EPC-CP Group Leader

Title:

Date 09.125.12017

E-mail:

Signature:

grieggst@lanl.gov



Environmental Protection & Compliance Division Los Alamos National Laboratory PO Box 1663, K491 Los Alamos, New Mexico 87545 (505) 667-2211

OCT 2 7 2017

Symbol:

Date:

EPC-DO: 17-448

LA-UR:

17-29659

Locates Action No.: N/A

U.S. EPA Region 6 NPDES Stormwater Program (WQ-PP) 1445 Ross Avenue, Suite 1200 Dallas, TX 75202-2733

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Industrial "No Discharge" Monitoring Report (MDMR) for the Third Quarter (August 1 – September 30, 2017)

To whom it may concern:

Enclosed is Los Alamos National Laboratory's "no discharge" MDMR (Enclosure 1) for the third quarter (August 1, through September 30, 2017), as required under MSGP Permit Tracking No. NMR053195. This report is being submitted on behalf of Los Alamos National Security, LLC.

Please contact Holly Wheeler at (505) 667-1312 or Terrill Lemke at (505) 665-2397 if you have questions regarding this MDMR.

Sincerely,

Taunia S. Van Valkenburg

Group Leader

TSV:TWL:HLW/am

USEPA MSGP Report EPC-DO: 17-448

Enclosure(s): 1) NPDES Permit Tracking No. NMR053195, "No Discharge" MDMR for the Third

Quarter (August 1 – September 30, 2017)

Copy: Helen Nguyen, EPA Region 6, Dallas TX (E-File)

Nasim Jahan, EPA Region 6, Dallas TX (E-File)

Michelle Hunter, NMED/GWQB, Santa Fe, NM (E-File)

Shelly Lemon, NMED/SWQB, Santa Fe, NM (E-File)

Karen Armijo, NA-LA, (E-File)

Arturo Duran, EM-SG, (E-File)

David Rhodes, EM-SG, (E-File)

Craig S. Leasure, PADOPS, (E-File)

William R. Mairson, PADOPS, (E-File)

Michael T. Brandt, ADESH, (E-File)

Raeanna Sharp-Geiger, ADESH, (E-File)

Bruce Robinson, ADEM-PO, (E-File)

Stephanie Archuleta, DESHF-DO, (E-File)

Theresa Cull, DESHS-DO, (E-File)

Andrew Erickson, UI-DO, (E-File)

Clifford Kirkland, STO-DO, (E-File)

Stephanie Griego, EWMO-DO, (E-File)

Russel Stone, DESHS-UIS, (E-File)

Garry Schramm, DESHF-STO, (E-File)

Robert Stokes, DESHS-EWMS, (E-File)

Jillian Burgin, DESHS-UIS, (E-File)

Leonard Sandoval, DESHS-UIS, (E-File)

Marc Gallegos, DESHF-STO, (E-File)

Courtney Perkins, DESHF-STO, (E-File)

Terrill W. Lemke, EPC-CP, (E-File)

Holly L. Wheeler, EPC-CP, (E-File)

Leslie J. Dale, EPC-CP, (E-File)

Ellena I. Martinez, EPC-DP, (E-File)

Adesh-records@lanl.gov, (E-File)

lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

NPDES Permit Tracking No. NMR053195, "No Discharge" MDMR for the Third Quarter (August 1 – September 30, 2017)

EPC-DO: 17-448

LA-UR-17-29659

OCT 2 7 2017

Date:

NPDES FORM 6100-29



United States Environmental Protection Agency Washington, DC 20460 MSGP Industrial Discharge Monitoring Report (DMR) Form

Form Approved. OMB No. 2040-0004

A. Approval to User Paper DMR Form 1. Have you been granted a waiver from electronic reporting from EPA Regional Office*? X YES NO If yes, check which waiver you have been granted, the name of the EPA Regional Office staff person who granted the waiver, and the date of approval: The owner/operator's headquarters is physically located in a geographic area (i.e., ZIP code or census tract) that is identified as under-served for broadband Internet access in the most recent report from the Federal Communications Commission. The owner/operator has issues regarding available computer access or computer capability. Everett Spencer Name of EPA staff person that granted the waiver: 06/17/2016 Date approval obtained: * Note: You are required to obtain approval from the applicable EPA Regional Office prior to using this paper DMR form. If you have not obtained a waiver, you must file this form electronically using the NetDMR at http://www.epa.gov/netomr/ **B.** Permit Information NMR053195 1. NPDES ID: 2. Reason(s) for Submission (Check all that apply): Submitting monitoring data (Fill in all Sections). Reporting no discharge for all outfalls for this monitoring period (Fill in Sections A, B, C, D, E.1, and G). Reporting that your site status has changed to inactive and unstaffed (Fill in Sections A, B, C, D, and F and include date of status change in comment field in Section F.4). Reporting that your site status has changed to active (Fill in all Sections and include date of status change in comment field in Section F.4). Reporting that no further pollutant reductions are achievable for all outfalls and for all pollutants via Part 6.2.1.2 of the MSGP (FIII in Sections A, B, C, D, C. Facility Operator Information 1. Operator Information Los Alamos National Security, LLC Operator Name: Mailing Address: P.O. Box 1663, MS K490 Street: NM ZIP Code: 87545 Los Alamos City: State: 505 667 0666 Phone: E-mail: tauniav@lanl.gov 2. DMR Preparer (Complete if DMR was prepared by someone other than the certifier): Holly L. Wheeler First Name, Middle Initial, Last Name: EPC-CP Organization: 505 667 1312 Ext. Phone:

hbenson@lanl.gov

E-mail:

D. Facility Inform	ation
1. Facility Name:	Los Alamos National Laboratory
2. Facility Address:	
Street/Location	Bikini Atoll Rd. SM30 K490
City:	Los Alamos State: NM ZIP Code: 87545 -
County or Similar Govern	nent Subdivision: Los Alamos
E. Discharge Info	rmation
1. Identify monitoring per	od: Check here if proposing alternative monitoring periods due to irregular stormwater runoff. Identify alternative monitoring schedule and indicate for which alternative monitoring period you are reporting monitoring data:
Quarter 1 (January 1 -	1041 / 1011 1051 / 1211
Quarter 2 (April 1 – Ju	e 30) Quarter 2: From 06 / 01 To 07 / 31
Quarter 3 (July 1 - Sep	tember 30) X Quarter 3: From 08 / 01 To 09 / 30
Quarter 4 (October 1	December 31) Quarter 4: From [10] / [01] To [11] / [30]
2. Are you required to mon freshwater?	tor for cadmium, copper, chromium, lead, nickel, silver, or zinc in X Yes (Skip to 3) No (Skip to 4)
3. What is the hardness le	el of the receiving water? 57
4. Does your facility discha	rge into any saltwater receiving waters? Yes X No

EPA FORM 6100-29 Page 2 of 7

F. Monitorii	F. Monitoring Information		No	Note: Make additional copies of this form as necessary.	of this form as	s necessa	Iry.			
1. Nature of Discharge:		ainfall (Com	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	melt					
2.a. Duration of	2.a. Duration of the rainfall event (hours):	ırs):	2.b. Rainfall a	2.b. Rainfall amount (inches):	Time since previo	us measura	2.c. Time since previous measurable storm event (days):			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.a. Outfall ID 3.b. Check if Any (list the same 3- digit outfalls dentified on the Identical to Other NOI form)	3.c. Check if No Discharge	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	Exceedance 3.k. No further natural pollutant pollutant achievable?
005	Substantially identical to outfall:	×								

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

002: NODI C

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

			Exceedance 3.k. No due to further natural pollutant background reductions pollutant achievable?		
			3.i. Collection due backg polluler		
y.		2.c. Time since previous measurable storm event (days):	3.i. Co		
is necessa		ous measurat	3.g. Units		
of this form a	melt	Time since previ	3.f. Quality or Concentration		
Note: Make additional copies of this form as necessary.	.a., 2.b., & 2.c.)	2.b. Rainfall amount (inches):	3.e. Parameter		
No	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall a	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*		
	ainfall (Comp	rs):	3.c. Check if No Discharge	×	
g Information		2.a. Duration of the rainfall event (hours):	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to ouffall:	X Substantially identical to ourfall: 012
F. Monitoring Information	1. Nature of Discharge:	2.a. Duration of th	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	012	011

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

F. Monitori	F. Monitoring Information		N	Note: Make additional copies	onal copies of this form as necessary.	s necessa	lry.			
1. Nature of Discharge:		Rainfall (Con	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	/melt					
2.a. Duration of	2.a. Duration of the rainfall event (hours):	ours):	2.b. Rainfall a	2.b. Rainfall amount (inches):	Time since previo	us measura	2.c. Time since previous measurable storm event (days):			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed		3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant reductions achievable?
036	Substantially identical to outfall:	X								
037	X Substantially identical to outfall: 036	×								

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

			Exceedance 3.k. No due to further natural pollutant background reductions pollutant levels		
			3.j. Exceedance due to natural background pollutant		
			3.i. Collection Date		
ary.		2.c. Time since previous measurable storm event (days):	3.h. Results Description		
s necess		ous measur	3.g. Units		
tional copies of this form as necessary.	vmelt	Time since previ	3.f. Quality or Concentration		
Note: Make additional copies	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall amount (inches):	3.e. Parameter		
Ž	plete line items	2.b. Rainfall	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, 1, O*		
	ainfall (Com	ırs):	3.c. Check if No Discharge	×	
F. Monitoring Information		2.a. Duration of the rainfall event (hours):	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	X Substantially identical to outfall. 073
F. Monitorin	1. Nature of Discharge:	2.a. Duration of t	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	073	074

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information, the information, the information submitted and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information, the information and imprisonment for knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Taunia First Name, Middle Initial, Last Name:

Van Valkenburg S

EPC-CP Group Leader

Title:

T/08/12/01 Date

E-mail:

Signature:

tauniáv@lanl.go



Environmental Protection & Compliance Division Los Alamos National Laboratory PO Box 1663, K491 Los Alamos, New Mexico 87545 (505) 667-2211

DEC 0 7 2017

Date:

Symbol: EPC-DO: 17-518

LA-UR: 17-31023

Locates Action No.: N/A

U.S. EPA Region 6 NPDES Stormwater Program (WO-PP) 1445 Ross Avenue, Suite 1200 Dallas, TX 75202-2733

Subject: National Pollutant Discharge Elimination System (NPDES) Permit Tracking No. NMR053195, Multi-Sector General Permit (MSGP) Industrial Discharge Monitoring Report (MDMR) for October 04, 2017

To whom it may concern:

Enclosed is Los Alamos National Laboratory's MDMR (Enclosure 1) for October 04, 2017 as required under MSGP Permit Tracking No. NMR053195. This report is being submitted on behalf of Los Alamos National Security, LLC and contains analytical results for quarterly benchmark monitoring at outfalls 002, 005, 017, 020, 047, 050, 051, 069, and 073.

Please contact Holly Wheeler at (505) 667-1312 or Terrill Lemke at (505) 665-2397 if you have questions regarding this MDMR.

Sincerely,

Taunia S. Van Valkenburg

Group Leader

TSV/TWL/HLW: am

Enclosure(s): 1) NPDES Permit Tracking No. NMR053195, MDMR for October 04, 2017

Copy: Helen Nguyen, EPA Region 6, Dallas TX (E-File)

Nasim Jahan, EPA Region 6, Dallas TX (E-File)

Michelle Hunter, NMED/GWQB, Santa Fe, NM (E-File)

Shelly Lemon, NMED/SWQB, Santa Fe, NM (E-File)

Karen Armijo, NA-LA, (E-File)

Arturo Duran, EM-SG, (E-File)

David Rhodes, EM-SG, (E-File)

Craig Leasure, PADOPS, (E-File)

William Mairson, PADOPS, (E-File)

Michael Brandt, ADESH, (E-File)

Raeanna Sharp-Geiger, ADESH, (E-File)

Bruce Robinson, ADEM-PO, (E-File)

Stephanie Archuleta, DESHF-DO, (E-File)

Theresa Cull, DESHS-DO, (E-File)

Stephanie Griego, EWMO-DO, (E-File)

Clifford Kirkland, STO-DO, (E-File)

Andrew Erickson, UI-DO, (E-File)

Robert Stokes, DESHS-EWMS, (E-File)

Garry Schramm, DESHF-STO, (E-File)

Russel Stone, DESHS-UIS, (E-File)

Victoria Baca, DESHS-EWMS, (E-File)

Marc Gallegos, DESHF-STO, (E-File)

Jillian Burgin, DESHS-UIS, (E-File)

Terrill Lemke, EPC-CP, (E-File)

Holly Wheeler, EPC-CP, (E-File)

Leslie Dale, EPC-CP, (E-File)

Ellena Martinez, EPC-CP, (E-File)

Adesh-records@lanl.gov, (E-File)

lasomailbox@nnsa.doe.gov, (E-File)

locatesteam@lanl.gov, (E-File)

epc-correspondence@lanl.gov, (E-File)

ENCLOSURE 1

NPDES Permit Tracking No. NMR053195, MDMR for October 04, 2017

EPC-DO: 17-518

LA-UR-17-31023

DEC 0 7 2017

Date:

NPDES FORM 6100-29



United States Environmental Protection Agency Washington, DC 20460 MSGP Industrial Discharge Monitoring Report (DMR) Form

Form Approved. OMB No. 2040-0004

A. Approval to	User Paper DMR Form					
		orting from EPA Regional Office*? X YES No Note name of the EPA Regional Office staff person wh		he waiver	and the date of any	vroval:
Waiver granted:	The owner/operator's head	quarters is physically located in a geographic area I Internet access in the most recent report from th	(i.e., ZIP co	de or censu	s tract) that is iden	
		ues regarding available computer access or compu			ons commission.	
Name of EPA staff;	person that granted the waiver:	Everett Spencer		•		
Date approval obta	ained: 06/17/2016					_
* Note: You are robtained a walve B. Permit Info	er, you must file this form elec	om the applicable EPA Regional Office prior to tronically using the NetDMR at http://www.e	o using thi pa.gov/net	s paper DN tdmr/	1R form. If you h	ave not
1. NPDES ID:	NMR053195					
2. Reason(s) for Subm	nission (Check all that apply):					
X Submitting moni	itoring data (Fill in all Sections).					
Reporting no dis	charge for all outfalls for this mon	nitoring period (Fill in Sections A, B, C, D, E.1, and C	G).			
Reporting that y in Section F.4).	our site status has changed to ina	active and unstaffed (Fill in Sections A, B, C, D, and	F and inclu	ide date of s	tatus change in co	mment field
Reporting that y	our site status has changed to act	tive (Fill in all Sections and include date of status c	hange in co	mment field	I in Section F.4).	
		achievable for all outfalls and for all pollutants via				A, B, C, D,
C. Facility Ope	rator Information					
1. Operator Informa	tion				NA - HO HUNOVANA	
Operator Name:	Los Alamos Natio	onal Security, LLC		_		
Mailing Address:						
Street:	P.O. Box 1663, M	S K490				
City:	Los Alamos	State:	NM	ZIP Code:	87545 -	
Phone:	505 667 0666					
E-mail:	tauniav@lanl.gov	,				
2. DMR Preparer (Co	omplete if DMR was prepared	by someone other than the certifier):				
First Name, Middle Initi	ial, Last Name: Holly L. V	Vheeler		_		
Organization:	EPC-CP					
Phone:	505 667 1312	Ext				
E-mail:	hbenson@lanl.g	jov				

D. Facility Inform	ation	V 17 - 20 - 10 - 10 - 10 - 10 - 10 - 10 - 10			
1. Facility Name:	Los Alamos National Labora	atory			
2. Facility Address:					
Street/Location	Bikini Atoll Rd. SM30 K490				
City:	Los Alamos	State:	NM	ZIP Code:	87545 -
County or Similar Govern	ment Subdivision: Los Alamos				
E. Discharge Info	rmation				
1. Identify monitoring per	iod: Check here if proposing al alternative monitoring schemonitoring data:	ternative monitoring periods du edule and indicate for which alt	e to irregular ernative mon	stormwater itoring perio	runoff. Identify od you are reporting
Quarter 1 (January 1 -	March 31) Quarter 1: From 04	1 / <mark>01</mark> _{To} 05 /	[31]		
Quarter 2 (April 1 - Jur	ne 30) Quarter 2: From 06	5 / 01 To 07 /	31		
Quarter 3 (July 1 – Sep	otember 30) Quarter 3: From 08	3 / 01 To 09 /	/ [30]		
Quarter 4 (October 1 -	December 31) X Quarter 4: From 10) / 01 _{To} 11 /	/ [30]		
2. Are you required to monifreshwater?	itor for cadmlum, copper, chromium, lead, nicke	f, silver, or zinc in	Yes (Skip t	o 3) [No (Skip to 4)
3. What is the hardness lev	rel of the receiving water?				
4. Does your facility discha	rge into any saltwater receiving waters?	Yes X No			

F. Monitorii	F. Monitoring Information		N	Note: Make additional copies of this form as necessary	of this form as	3 necess	N			
1. Nature of Discharge:	×	lainfall (Con	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	melt					
2.a. Duration of	2.a. Duration of the rainfall event (hours): 2	urs): 2	2.b. Rainfall (2.b. Rainfall amount (inches): 0,9 2.c.	Time since previo	us measura	2.c. Time since previous measurable storm event (days): $oldsymbol{4}$			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.d. Monitoring Type QBM, ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background r pollutant a levels	3.k. No further pollutant reductions achievable?
005	Substantially identical to outfall:		QBM	lron, total	1520	ng/L		10/04/2017		
005	Substantially identical to outfall:		QBM	Nitrate plus Nitrite Nitrogen	0.271	mg/L		10/04/2017		
005	Substantially identical to outfall:		QBM	Zinc, dissolved	137	ng/L		10/04/2017		

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here) Rainfall duration = 1.75 hours. Rainfall amount = 0.92 inches.

^{002:} Adjusted Gross Alpha (I) - NODI 9. Aluminum, total recoverable (I) - NODI 9. Aroclor, total (I) - NODI B. Copper, dissolved (I) - NODI 9. Thallium, dissolved (I) - NODI B.

	05				
			3.k. No further pollutant reductions achievable?		
			3.j. Exceedance due to further natural pollutant background reductions ploutant achievable?		
			3.i. Collection Date	10/04/2017	
Ne		0.9 2.c. Time since previous measurable storm event (days): 4	3.h. Results Description		
s necess		ous measure	3.g. Units	ng/L	
of this form a	melt	owiner. c. Time since previo	3.f. Quality or Concentration	2830	
Note: Make additional copies of this form as necessary	2.a., 2.b., & 2.c.)	2.b. Rainfall amount (inches): 0,9 2.c.	3.e. Parameter	Iron, total	
N	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall a	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	QBM	
	lainfall (Com	Kaimfaii (Com ours): 2	3.c. Check if No Discharge		
F. Monitoring Information	×	2.a. Duration of the rainfall event (hours): 2	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to ourfall:	X Substantially identical to outfall: 005
F. Monitorin	1. Nature of Discharge:	2.a. Duration of t	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	005	900

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.75 hours. Rainfall amount = 0.92 inches.

005: Adjusted Gross Alpha (I) - NODI 9. Aluminum, total recoverable (I) - NODI 9. Aroclor, total (I) - NODI B. Copper, dissolved (I) - NODI 9. Thallium, dissolved (I) - NODI B.

		3.k. No further pollutant reductions achievable?								
		3.j. Exceedance due to natural background pollutant levels								
		3.i. Collection Date	10/04/2017	10/04/2017	10/04/2017	10/04/2017	10/04/2017			
ary.	2.c. Time since previous measurable storm event (days): 4	3.h. Results Description								
IS necess	ous measura	3.g. Units	ng/L	ng/L	ng/L	mg/L	ng/L			
of this form a	Time since previ	3.f. Quality or Concentration	72400	68.9	83100	0.0923	246			
Note: Make additional copies of this form as necessary. Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall amount (inches): 0.9 2.c.	3.e. Parameter	Aluminum, total recoverable	Copper, dissolved	Iron, total	Nitrate plus Nitrite Nitrogen	Zinc, dissolved			
nplete line items	2.b. Rainfall	3.d. Monitoring Type QBM, ELG, S/T, I, O*	QBM	QBM	QBM	WBQ.	QBM			
ainfall (Con	urs): 2	3.c. Check if No Discharge								
X	2.a. Duration of the rainfall event (hours):	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	X Substantially identical to outfall: 017	X Substantially identical to outfall: 017	X Substantially identical to outfall: 017				
1. Nature of Discharge:	2.a. Duration of t	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	017	017	017	017	017	013	014	015

X Substantially identical to outfall: 017
019

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.75 hours. Rainfall amount = 0.92 inches.

017: The average concentration of total recoverable Aluminum is mathematically certain to exceed the benchmark value. The average concentration of dissolved Copper is mathematically certain to exceed the benchmark value. The average of four monitoring values for Nitrate plus Nitrite Nitrogen does not exceed the benchmark value, therefore quarterly monitoring will be discontinued per Part 6.2.1.2. The average of four monitoring values for dissolved Zinc exceeds the benchmark value. Adjusted Gross Alpha (I) - NODI 9. Aroclor, total (I) - NODI 9. Copper, dissolved (I) - NODI 9.

ge: X rainfall event b. Check if An Outfalls are Substantially outfalls Listed Substantially iden	F. Monitoring Information Note: Make additional copies of this form as necessary	X Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a. Duration of the rainfall event (hours): 2 2.b. Rainfall amount (inches): 0.9 2.c. Time since previous measurable storm event (days): 4	3.a. Outfall ID 3.b. Check if Any 3.c. 3.d. (list the same 3- Outfalls are digit outfalls blackarded on the Identical to Other Nol form) 3.a. Outfalls 1.sted 3.b. Check if Amonitoring 3.c. 3.d. 3.c. 3.d. Amonitoring 3.c. 3.d. 3.f. Quality or digit outfalls are digit outfalls on the Identical to Other Outfalls Listed Amonitoring 3.e. Parameter Concentration outfall Listed Amonitoring 3.e. No Parameter Concentration outfall Listed Amonitoring 3.e. Parameter Concentration outfall Listed Amonitoring 3.e. No Parameter Concentration outfall Listed Amonitoring 3.e. No Parameter Concent	Substantially identical QBM Zinc, dissolved 173 ug/L
B S F S S S S S S S S S S S S S S S S S	on	X Rainfall (Comp	LAJ Kainfall (Convent (hours): 2		identical

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.75 hours. Rainfall amount = 0.92 inches.

020: The average concentration of dissolved Zinc is mathematically certain to exceed the benchmark value. Adjusted Gross Alpha (I) - NODI B. Aluminum, total recoverable (I) - NODI 9. Aroclor, total (I) - NODI B. Copper, dissolved (QBM) - NODI B. Copper, dissolved (I) - NODI B. Thallium, dissolved (I) - NODI B. Nitrate plus Nitrite Nitrogen (QBM) - NODI B.

. Monitorii	F. Monitoring Information		No	Note: Make additional copies of this form as necessary.	of this form as) necesse	31.			
1. Nature of Discharge:	×	Rainfall (Con	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	melt					
Juration of	2.a. Duration of the rainfall event (hours): 2	urs): 2	2.b. Rainfall a	2.b. Rainfall amount (inches): 0.8 2.c.	Time since previou	us measura	2.c. Time since previous measurable storm event (days): 4			
3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.d. Monitoring Type QBM, ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant reductions achievable?
047	Substantially identical to outfall:		QBM	Magnesium, total	0.37	mg/L		10/04/2017		
046	X Substantially identical to outfall: 047									
045	X Substantially identical to outfall: 047									
048	X Substantially identical to outfall: 047									
044	X Substantially identical to outfall: 047									

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.83 hours. Rainfall amount = 0.78 inches.

^{047:} The average concentration of total Magnesium is mathematically certain to exceed the benchmark value. Adjusted Gross Alpha (I) - NODI B. Aluminum, total recoverable (I) - NODI B. Arsenic, dissolved (QBM) - NODI B. Chemical Oxygen Demand (COD) (QBM) - NODI B. Chemical Oxygen Demand (COD) (QBM) - NODI B. Chemical Oxygen Demand (COD) (QBM) - NODI B. Chemical QBM) - NODI B. Lead, dissolved (QBM) - NODI B.

F. Monitoring Information	ıtion		N	Note: Make additional copies of this form as necessary.	of this form as	s necessa	ary.			
×		infall (Com	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.) Snowmelt	melt					
Ş	2.a. Duration of the rainfall event (hours): 2	rs): 2	2.b. Rainfall a	2.b. Rainfall amount (inches): 0,8 2.c.	Time since previo	us measura	2.c. Time since previous measurable storm event (days): 4			
	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	3.c. Check if No Discharge	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.j. Exceedance 3.k. No due to further natural pollutant background reductions pollutant achievable?
	Substantially identical outfall:		QBM	Chemical Oxygen Demand (COD)	QN		8.95 mg/L	10/04/2017		
	Substantially identical outfall:		QBM	Magnesium, total	1.32	mg/L		10/04/2017		

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.83 hours. Rainfall amount = 0.78 inches.

050: The average concentration of total Magnesium is mathematically certain to exceed the benchmark value. Adjusted Gross Alpha (I) - NODI 9. Aluminum, total recoverable (I) - NODI B. Aroclor, total (I) - NODI B. Aroclor, total (I) - NODI B. Aroclor, total (QBM) - NODI B. Aroclor, total (QBM) - NODI B. Aroclor, total (QBM) - NODI B. Selenium, total (QBM) - NODI B. Silver, dissolved (QBM) - NODI B. Mercury, total (QBM) - NODI B. Selenium, total (QBM) - NODI B. Silver, dissolved (QBM) - NODI B.

(272					
			3.k. No further pollutant reductions achievable?		
			3.j. Exceedance due to natural background pollurant		
			3.i. Collection Date	10/05/2017	
N.		0.3 2.c. Time since previous measurable storm event (days): 6	3.h. Results Description	8.95 mg/L	
s necessa		ous measura	3.9. Units		
of this form a	melt	Time since previc	3.f. Quality or Concentration	QN	
te: Make additional copies	達	3.e. Parameter	Chemical Oxygen Demand (COD)		
No.	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall a	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	МВО	
	ainfall (Com	nours): 2	3.c. Check if No Discharge		
F. Monitoring Information	×	2.a. Duration of the rainfall event (hours): 2	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	X Substantially identical to outfall: 051
F. Monitorin	1. Nature of Discharge:	2.a. Duration of t	3.a. Outfall ID (list the same 3- digit outfalls identified on the NOI form)	051	052

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 2.50 hours. Rainfall amount = 0.34 inches.

051: Aluminum, total recoverable (I) - NODI 9. The average of four monitoring values for Chemical Oxygen Demand does not exceed the benchmark value, therefore quarterly monitoring will be discontinued per Part 6.2.1.2. Ammonia, total (QBM) - NODI B. Arsenic, dissolved (QBM) - NODI B. Cadmium, dissolved (QBM) - NODI B. Cadmium, dissolved (QBM) - NODI B. Lead, dissolved (QBM) - NODI B. Arsenic (QBM) - NODI B. Lead, dissolved (QBM) - NODI B.

			3.K. No further pollutant reductions achievable?								
			3.j. Exceedance due to natural repollutant ac pollutant ac levels								
			3.i. Collection bate	10/04/2017	10/04/2017						
arv.		2.c. Time since previous measurable storm event (days): 4	3.h. Results Description	8.95 mg/L							
S necess		ous measura	3.g. Units		mg/L						
of this form a	melt	Time since previo	3.f. Quality or Concentration	Q	0.223						
Note: Make additional copies of this form as necessary.	2.a., 2.b., & 2.c.) Snowmelt	2.b. Rainfall amount (inches): 0.3 2.c.	3.e. Parameter	Chemical Oxygen Demand (COD)	Magnesium, total		16.				
No	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.b. Rainfall a	3.d. Monitoring Type QBM, ELG, S/T, I, O*	QBM	QBM						
	ainfall (Com	rs): 2	3.c. Check if No Discharge								
F. Monitoring Information	×	2.a. Duration of the rainfall event (hours): 2	3.b. Check if Any Outfalls are Substantially Identical to Other Outfalls Listed	Substantially identical to outfall:	Substantially identical to outfall:	X Substantially identical to outfall: 069	X Substantially identical to ouffall: 069	X Substantially identical to outfall: 069			
F. Monitorir	1. Nature of Discharge:	2.a. Duration of	3.a. Outfall ID (list the same 3. digit outfalls identified on the NOI form)	690	690	020	058	057	056	055	054

	2					
X Substantially identical to outfall: 069						
067	890	090	061	062	063	064

4. Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 2.50 hours. Rainfall amount = 0.34 inches.

069: Aluminum, total recoverable (I) - NODI 9. Ammonia, total (QBM) - NODI B. Aroclor, total (I) - NODI B. Arsenic, dissolved (QBM) - NODI B. Cadmium, dissolved (QBM) - NODI B. Cyanide, total (QBM) - NODI B. Lead, dissolved (QBM) - NODI B. Mercury, total (QBM) - NODI B. Silver, dissolved (QBM) - NODI B.

F. Monitoring Information		No	Note: Make additional copies of this form as necessary.	of this form a	s necess	ary.			
	infall (Corr	Rainfall (Complete line items 2.a., 2.b., & 2.c.)	2.a., 2.b., & 2.c.)	melt					
	2.a. Duration of the rainfall event (hours): 2	2.b. Rainfall a	2.b. Rainfall amount (inches): 0.9 2.c.	Time since previo	us measura	2.c. Time since previous measurable storm event (days): 4			• • •
	3.c. Check if No Discharge	3.c. 3.d. Check if Monitoring No Type QBM, Discharge ELG, S/T, I, O*	3.e. Parameter	3.f. Quality or Concentration	3.g. Units	3.h. Results Description	3.i. Collection Date	3.j. Exceedance due to natural background pollutant levels	3.k. No further pollutant reductions achievable?
		МВО	Chemical Oxygen Demand (COD)	QN		8.95 mg/L	10/04/2017		
X Substantially identical to outfall: 073									

^{* (}QBM) - Quarterly benchmark monitoring; (ELG) - Annual effluent limitations guidelines monitoring; (S/T) - State- or tribal-specific monitoring; (I) - Impaired waters monitoring; (O) - Other monitoring as required by EPA

^{4.} Comment and/or Explanation of Any Violations (Reference all attachments here)

Rainfall duration = 1.75 hours. Rainfall amount = 0.92 inches.

0
tio
H
\simeq
=
rtifica
Ö
U

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information, the information, the information, including the possibility of fine and imprisonment for knowing violations.

Taunia First Name, Middle Initial, Last Name:

Van Valkenburg

S

EPC-CP Group Leader

Signature:

Title:

7702130127 Date

tauniav@lanl.gov

E-mail:



Signature/Review/Coordination Sheet

This form is to accompany all documents requiring review, approval, or signature by the Laboratory Director or Designee.

Today's Date 6/12/2018	Deadline Date 6/30/2018	Is this a re	sponse to an action item	? Yes 🗖	No 🗵
From: Holly Wheeler		Call for	· Pick-up		
Organization: EPC-CP		Name:	Celina Huerta	Phone:	7-0666
		TTGITTO.	Comma Haorta	T HOHE.	7 0000
Title: Identify docume	nt, briefly describing subject matter.				
ESHID-603048 (LA-UR Multi-Sector General Per 2018) Monitoring.	18-25255): National Pollutant Discharge rmit (MSGP) Industrial "No Discharge" N	Elimination Monitoring Re	System (NPDES) Permit Treports (MDMRs) for First Q	racking No. Nourter (April	MR053195, 1 - May 31,
Summary/Detail					
industrial sites quarterly every quarter to EPA ide	or General Permit (Permit Tracking #NMI (every two months between April and No ntifying outfalls that did not discharge du April 1 - May 31). This report is due 30 o	vember) duri ring that perio	ng the calendar year. MDM od. Attached are the "No D	IRs must be si ischarge" MD	ubmitted
-	f Laboratory Director or Designee: file to Adesh-records@lanl.gov				
PAD Endorsement					
Name (print)	Signature		D	ate	
Craig S. Leasure, P	PADOPS \\A				
AD Endorsement	ADDIO O(I)				
Name (print)	Signature		D	ate	
. ,	\	΄.Λ			
William R. Mairson		4			
		are complete ple	ease return to Group Office Admin		ture process
1. Name (print) Enrique Torres, E	Signature	1	D	ate	
2. Name (print)	Signature	<i>T</i> \	D	ate	
Taunia S. Van Valkenb					
3. Name (print)	Signature		D	ate	
Terrill W. Lemke,	EPC-CP	Du	tha	6/14/1	's
4. Name (print) Holly L. Wheeler,	Signature	11.19	(a)	ate	2219
5. Name (print)	Signature	J W	D	ate	-010

Please ensure appropriate PAD/AD/Division coordination and review prior to submittal to the Director's Office. Form 1824 (8/12)

2018Q1MSGPNODI

Permit_id,permitted_feature_id,limit_set_txt,mped_txt,form_nodi_cd,comment_txt
NMR053195,002,11,2018-05-31,C,LA-UR-18-25255
NMR053195,009,01,2018-05-31,C,LA-UR-18-25255
NMR053195,012,01,2018-05-31,C,LA-UR-18-25255
NMR053195,043,D1,2018-05-31,C,LA-UR-18-25255
NMR053195,073,A4,2018-05-31,C,LA-UR-18-25255

DMR Copy of Record

Permit

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Major:

No

Permittee Address: PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

002

External Outfall

Discharge:

002-11

Fabricated Metal Products, except Coating

Report Dates & Status

Monitoring Period:

From 04/01/18 to 05/31/18

DMR Due Date:

07/31/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

FOIM NODI.	-										
Parameter	Monitoring Location Season # Param. NODI			Quantity or Loading	Quality or Concentration			# of Ex.	Frequency of Analysis	Sample Type	
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3	Value 3	Units			
01045 Iron, total [as Fe] 01090 Zinc, dissolved [as Zn]	1 - Effluent Gross			Sample							
		0		Permit Req			1000 MAXIMUM	28 - ug/L	01/60 - Once Every 2 N	1/60 - Once Every 2 Months	onths GR - GRAB
				Value NOD			C - No Discharge			,	
				Sample			•				
	1 - Effluent Gross	0	2	Permit Req		<=	76 MAXIMUM 28 - ug/L	01/60 - Once Every 2 Monti	ns GR - GRAB		
				Value NOD			C - No Discharge	_		•	
01104 Aluminum, total recoverable	1 - Effluent Gross		571	Sample							
		0		Permit Req		<=	681 MAXIMUM 28 - ug/L		01/60 - Once Every 2 Months	s GR - GRAB	
				Value NOD			C - No Discharge			-	
51450 Nitrite Plus Nitrate Total	1 - Effluent Gross	0		Sample							
				Permit Req		<=	0.68 MAXIMUM 19 - mg/L		01/60 - Once Ever	1/60 - Once Every 2 Months	2 Months GR - GRAB
				Value NOD			C - No Discharge			,	

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-25255

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User:

leslie@lanl.gov Leslie Dale

Name: E-Mail:

leslie@lanl.gov

Date/Time:

2018-06-14 15:40 (Time Zone: -05:00)

Report Last Signed By

User: Name: E-Mail: **TERRILLLEMKE** Terrill Lemke

tlemke@lanl.gov

Date/Time: 2018-06-14 15:43 (Time Zone: -05:00)

DMR Copy of Record

Permit Permit #:

Major:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location: PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

009

No

External Outfall

Discharge:

Permittee Address:

009-01

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period:

Considerations for Form Completion

From 04/01/18 to 05/31/18

DMR Due Date:

07/31/18

Status:

NetDMR Validated

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

Parameter Code Name	Monitoring Location	Season	# Param, NODI		Quantity or Loading Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Quality or Concentratio Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3		Units	# of Ex.	Frequency of Analysis	Sample Type
				Sample							
01045 Iron, total [as Fe]	1 - Effluent Gross	0	-	Permit Req.			1000 MAXIMUM		/L 01/60 - Once Every 2 Mo		hs GR-GRAB
				Value NOD			C - No Discharge				

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-25255

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail:

leslie@lanl.gov

Date/Time: 2018-06-14 15:40 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE Name: Terrill Lemke E-Mail: tlemke@lanl.gov

Date/Time: 2018-06-14 15:43 (Time Zone: -05:00)

rd

DMR Copy of	of Reco
Permit	
Permit #:	NM

NMR053195

Permittee: LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Los Alamos, NM 87545

012-01

Facility:

LOS ALAMOS NATIONAL LABORATORY PO BOX 1663

Facility Location: MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

Major:

012

No

External Outfall

Discharge:

Permittee Address:

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period: From 04/01/18 to 05/31/18 DMR Due Date: 07/31/18 Status:

NetDMR Validated

of Ex.

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI: **Parameter**

Code Name 01045 Iron, total [as Fe] 1 - Effluent Gross Sample

Quantity or Loading Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3

Quality or Concentration

Value 3 Units 1000 MAXIMUM 28 - ug/L

C - No Discharge

01/60 - Once Every 2 Months GR - GRAB

Frequency of Analysis Sample Type

Permit Reg.

Value NODI

Monitoring Location Season # Param, NODI

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-25255

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-06-14 15:40 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE Name: Terrill Lemke E-Mail: tlemke@lanl.gov

Date/Time: 2018-06-14 15:43 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

External Outfall

Permittee:

Permittee Address:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location: PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

043

No

Discharge:

043-D1

Asphalt Paving and Roofing Materials and Lubricant Manufacturing

Report Dates & Status

Monitoring Period: From 04/01/18 to 05/31/18

DMR Due Date:

07/31/18

Status:

NetDMR Validated

of Ex.

Units

Considerations for Form Completion

00530 Solids, total suspended 1 - Effluent Gross

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

Code

Parameter Monitoring Location Season # Param. NOD! Name

Sample

Quantity or Loading Quality or Concentration Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3

100 MAXIMUM 19 - mg/L

Frequency of Analysis Sample Type

01/60 - Once Every 2 Months GR - GRAB

C - No Discharge

Value 3

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-25255

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User:

leslie@lanl.gov

Name:

Leslie Dale

E-Mail:

leslie@lanl.gov

Date/Time:

2018-06-14 15:40 (Time Zone: -05:00)

Permit Req.

Value NODI

Report Last Signed By

User:

E-Mail:

TERRILLI EMKE

Name:

Terrill Lemke tlemke@lani.gov

Date/Time:

2018-06-14 15:43 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

Permittee:

Permittee Address:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663

Los Alamos, NM 87545

Facility Location:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

073

No

External Outfall

Discharge:

073-A4

Hardwood Dimension and Flooring Mills?

Report Dates & Status

Monitoring Period: From

From 04/01/18 to 05/31/18

DMR Due Date:

07/31/18

Status:

Facility:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

I OIIII II	ODI.											
	Parameter	Monitoring Location	oring Location Season # Param. NODI			Quantity or Loading	Quantity or Loading Quality or Concentration			# of Ex.	Frequency of Analysis	Sample Type
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units			
					Sample							
00530 So	ids, total suspended	1 - Effluent Gross	0		Permit Req.		<=	100 MAXIMUM	19 - mg/L	. 0	1/60 - Once Every 2 Months	GR - GRAB
					Value NODI			C - No Discharge)			
					Sample							
81017 Ch	emical Oxygen Demand [COD]	1 - Effluent Gross	0	-22	Permit Req.		≼=	120 MAXIMUM	19 - mg/L	. 0	1/60 - Once Every 2 Months	GR - GRAB
					Value NODI			C - No Discharge				

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-25255

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User:

leslie@lanl.gov

Name:

Leslie Dale

E-Mail: leslie@lanl.gov
Date/Time: 2018-06-14 15

2018-06-14 15:40 (Time Zone: -05:00)

Report Last Signed By

User: Name: TERRILLLEMKE

Name: Terrill Lemke
E-Mail: tlemke@lanl.gov

Date/Time:

2018-06-14 15:43 (Time Zone: -05:00)



Signature/Review/Coordination Sheet

This form is to accompany all documents requiring review, approval, or signature by the Laboratory Director or Designee.

Today's Date	Deadline Date		Is this a re	esponse to an action it	em? Yes	No 🗷
8/27/2018	9/19/20	018				
From: Holly Wheeler			Call fo			- 0
Organization: EPC-CP			Name:	Joline Martinez	Phone:	7-0666
Title: Identify docume	nt, briefly describi	ng subject matter.				
				s System (NPDES) Permiss (MDMRs) for Second (
Summary/Detail						
Per the 2015 Multi-Sector industrial sites at monitor quarterly monitoring mureceived. Attached are to	red outfalls quarterl st be electronically	y (every two months b submitted in EPA's ele	etween Apr ectronic repo	il and November) during rting system (NetDMR)	the calendar ye: 30 days after va	ar. Data from lidated data is
ACTION requested o	of Laboratory Dire	ector or Designee:				
Other Action: Send pdf	file to Adesh-record	ls@lanl.gov				
PAD Endorsement						
Name (print)		Signature			Date	
Craig S. Leasure, I	DADODS	k `	NA			
	FADOFS		11,			
AD Endorsement Name (print)		Signature			Date	
, ,		()	IN			
William R. Mairson		N	17			
Coordinated With When	signatures on the COOF		are complete p	lease return to Group Office Ac		nature process.
1. Name (print)		Signature	14		Date	
Enrique Torres, I	EPC-DO	1	VA .			
2. Name (print)		Signature	6		Date	
Taunia S. Van Valken	hura EDC CD	1	VA			
3. Name (print)	ourg, ErC-Cr	Signature	711		Date	
Terrill W. Lemke	, EPC-CP	- Line	Du	He	10/5/	*
4. Name (print)		Signature	0.1	0	Date	
Holly L. Wheeler	· FPC-CP	Hall	CIFN	Leel	9/7/2	216
5. Name (print)	, 11 0-01	Signature	7		Date	-,0
4			\bigcup			

Please ensure appropriate PAD/AD/Division coordination and review prior to submittal to the Director's Office.

Form 1824 (8/12)

2018Q2MSGPData

```
Permit id, permitted feature id, limit set txt, mped txt, form nodi cd, parameter cd, moni
toring location cd, season num, quant 1 nodi cd, quant 1 qualifier txt, quant 1 sample_n
um,quant 1 effluent num,quant 2 nodi cd,quant 2 qualifier txt,quant 2 sample num,qua
nt 2 effluent num, quant uom cd, conc 1 nodi cd, conc 1 qualifier txt, conc 1 sample num
,conc_1_effluent_num,conc_2_nodi_cd,conc_2_qualifier_txt,conc_2_sample_num,conc_2_ef
fluent_num,conc_3_nodi_cd,conc_3_qualifier_txt,conc_3_sample_num,conc_3_effluent_num
,conc uom cd,excursions num,freq analysis cd,sample type cd,param nodi cd,comment tx
NMR053195,002,11,2018-07-31,,01090,1,0,,,,,,,,,,,,,,,,,,,285.0,,28,1,01/60,GR,,LA-U
R-18-28316. The average concentration of Zn is mathematically certain to exceed the
benchmark value.
NMR053195,005,01,2018-07-31,,01045,1,0,,,,,,,,,,,,,,,,,,,,171.0,,28,0,01/60,GR,,LA-U
NMR053195,009,01,2018-07-31,,01045,1,0,,,,,,,,,,,,,,,,,,1800.0,,28,1,01/60,GR,,LA-
UR-18-28316
NMR053195,012,01,2018-07-31,,01045,1,0,,,,,,,,,,,,,,,,,,804.0,,28,0,01/60,GR,,LA-U
R-18-28316
NMR053195,020,11,2018-07-31,,01040,1,0,,,,,,,,,,,,,,,,,,,28,,01/60,GR,B,LA-UR-18-
28316
NMR053195,020,11,2018-07-31,,01045,1,0,,,,,,,,,,,,,,,,,,,,28,,01/60,GR,B,
{\tt NMR053195,020,11,2018-07-31,,01090,1,0,,,,,,,,,,,,,,,,,161.0,,28,1,01/60,GR,,}
NMR053195,020,11,2018-07-31,,01104,1,0,,,,,,,,,,,,,,,,,,,,,,,28,,01/60,GR,B,
NMR053195,020,11,2018-07-31,,51450,1,0,,,,,,,,,,,,,,,,,,,,,,,19,,01/60,GR,B,
NMR053195,073,A4,2018-07-31,,00530,1,0,,,,,,,,,,,,,,,,,188.0,,19,1,01/60,GR,,LA-U
R-18-28316
```

Permit

Permit #: NMR053195 Permittee: LOS ALAMOS NATIONAL LABORATORY

No Major:

Permittee Address: PO Box 1663 Los Alamos, NM 87545

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

Facility:

PO BOX 1663 LOS ALAMOS, NM 87545

Permitted Feature:

002

External Outfall

Discharge:

002-11

Report Dates & Status

Monitoring Period: From 06/01/18 to 07/31/18

Fabricated Metal Products, except Coating

DMR Due Date: 09/30/18 Status: **NetDMR Validated**

Considerations for Form Completion

Principal Executive Officer

First Name: Title: Telephone:

No Data Indicator (NODI)

Last Name:

Form NODI:

Parameter	Monitoring Location	on Season	# Param. NODI		Quantity or Loading	Quality or C	oncentration	# of Ex.	Frequency of Analysis	Sample Typ
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1	Qualifier 2 Value 2 Qualifier 3	Value 3	Units		
				Sample		=	1330	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
01045 Iron, total [as Fe]	1 - Effluent Gross	0	-	Permit Req		<=	1000 MAXIMUM	28 - ug/L 1	01/60 - Once Every 2 Months	GR - GRAB
				Value NOD						
				Sample		=	285	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
01090 Zinc, dissolved [as Zn]	1 - Effluent Gross	0	**	Permit Req		<=	76 MAXIMUM	28 - ug/L 1	01/60 - Once Every 2 Months	GR - GRAB
				Value NOD						
				Sample		=	1550	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
01104 Aluminum, total recoverable	1 - Effluent Gross	0	ii.	Permit Req		<=	681 MAXIMUM	28 - ug/L 1	01/60 - Once Every 2 Months	GR - GRAB
				Value NOD						
				Sample						
1450 Nitrite Plus Nitrate Total	1 - Effluent Gross	0		Permit Req		<=	0,68 MAXIMUM	19 - mg/L	01/60 - Once Every 2 Months	GR - GRAB
				Value NOD			B - Below Detection Limit/No Detection	-	,	

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Manhadania				
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
01045	Iron, total [as Fe]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes

Comments

LA-UR-18-28316. The average concentration of Zn is mathematically certain to exceed the benchmark value.

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-09-13 14:34 (Time Zone: -05:00)

Report Last Signed By

User: saladen@lanl.gov Name: Michael Saladen E-Mail: saladen@lanl.gov Date/Time: 2018-09-13 14:52 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location: PC

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

005

No

External Outfall

Discharge:

Permittee Address:

005-O1

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period:

From 06/01/18 to 07/31/18

DMR Due Date:

09/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name:

No Data Indicator (NODI)

Form NODI:

TOTAL NODE.										
Parameter	Monitoring Location	n Season	# Param. NOD		Quantity or Loading	Quality or Concentration	on	# of I	Ex. Frequency of Analysis	Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1	1 Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units		
				Sample			171	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
01045 Iron, total [as Fe]	1 - Effluent Gross	0		Permit Req.		<=	1000 MAXIMUN	VI 28 - ug/L 0	01/60 - Once Every 2 Months	GR - GRAB
				Value NODI						

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-28316

Attachments

No attachments.

E-Mail:

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov
Name: Leslie Dale

leslie@lanl.gov

Date/Time: 2018-08-30 15:10 (Time Zone: -05:00)

Report Last Signed By

 User:
 TERRILLEMKE

 Name:
 Terrill
 Lemke

 E-Mail:
 tlemke@lanl.gov

Date/Time: 2018-08-30 16:18 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

External Outfall

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Facility:

LOS ALAMOS NATIONAL LABORATORY

No

Considerations for Form Completion

Permittee Address:

PO Box 1663 Los Alamos, NM 87545

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

009

Discharge:

009-O1

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period:

From 06/01/18 to 07/31/18

DMR Due Date:

09/30/18

Status:

NetDMR Validated

of Ex.

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

Monitoring Location Season # Param. NODI **Parameter** Code Name

Quantity or Loading Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3

Quality or Concentration

Value 3 Units 28 - ug/L

01/60 - Once Every 2 Months GR - GRAB

Frequency of Analysis

X 01045 Iron, total [as Fe] 1 - Effluent Gross

Sample Permit Req. Value NODI 1800 1000 MAXIMUM 28 - ug/L 1

01/60 - Once Every 2 Months GR - GRAB

Sample Type

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Manitarian Laurtina	The state of the s			
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
01045	Iron, total [as Fe]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-28316

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-08-30 15:10 (Time Zone: -05:00)

Report Last Signed By

User: **TERRILLLEMKE** Name: Terrill Lemke F-Mail: tlemke@lanl.gov

Date/Time: 2018-08-30 16:18 (Time Zone: -05:00)

Permit

Permit #: Major: NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

Facility:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663 Los Alamos, NM 87545

Ly Location. PO Bo

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

012

No

External Outfall

Discharge:

012-01

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period:

From 06/01/18 to 07/31/18

DMR Due Date:

09/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

Parameter	Monitoring Location	n Season	# Param. NODI		Quantity or Loading	Quality or Concentration	n	#	of Ex.	Frequency of Analysis	Sample Type
Code Name					Qualifler 1 Value 1 Qualifier 2 Value 2 Units Qualifier	r 1 Value 1 Qualifier 2 Value 2 Qualifier 3	Value 3	Units			
			*	Sample			804	28 - ug/L	C	01/60 - Once Every 2 Months	GR - GRAB
01045 Iron, total [as Fe]	1 - Effluent Gross	0	110 5	Permit Req.		<=	1000 MAXIMU	M 28 - ug/L 0	C	01/60 - Once Every 2 Months	GR - GRAB
				Value NODI							

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-28316

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User:

leslie@lanl.gov

Name:

Leslie Dale

E-Mail:

leslie@lanl.gov

Date/Time:

2018-08-30 15:10 (Time Zone: -05:00)

Report Last Signed By

User:

TERRILLLEMKE

Name:

Terrill Lemke

E-Mail:

tlemke@lanl.gov

Date/Time:

2018-08-30 16:18 (Time Zone: -05:00)

Permit

Permit #: Major:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

No

Permittee Address: PO Box 1663

Los Alamos, NM 87545

Facility Location:

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663

MS K490 LOS ALAMOS, NM 87545

Permitted Feature:

020

External Outfall

Discharge:

020-11

Fabricated Metal Products, except Coating

Report Dates & Status

Monitoring Period:

From 06/01/18 to 07/31/18

DMR Due Date:

09/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name: No Data Indicator (NODI)

Form NODI:

	Parameter	Monitoring Location	n Season i	Param. NODI		Quantity or Loading Quality or C	oncentration	# of Ex	. Frequency of Analysis	Sample Type
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units		
					Sample					
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	**	Permit Req	<=	6 MAXIMUM	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
					Value NOD		B - Below Detection Limit/No Detection			
					Sample					
01045	Iron, total [as Fe]	1 - Effluent Gross	0	-	Permit Req	<=	1000 MAXIMUM	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
					Value NOD		B - Below Detection Limit/No Detection	- A		
					Sample		161	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
X 01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	0	**	Permit Req	<=	76 MAXIMUM	28 - ug/L 1	01/60 - Once Every 2 Months	GR - GRAB
					Value NODI					
					Sample					
01104	Aluminum, total recoverable	1 - Effluent Gross	0	2.2	Permit Req	<=	681 MAXIMUM	28 - ug/L	01/60 - Once Every 2 Months	GR - GRAB
					Value NODI		B - Below Detection Limit/No Detection			
					Sample					
51450	Nitrite Plus Nitrate Total	1 - Effluent Gross	0	**	Permit Req.	<=	0.68 MAXIMUM	19 - mg/L	01/60 - Once Every 2 Months	GR - GRAB
					Value NODI		B - Below Detection Limit/No Detection			

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type, **Edit Check Errors**

	Parameter	Manitaging Laustine	e.u.			
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-28316

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User.

leslie@lanl.gov

Name:

Leslie Dale

E-Mail:

leslie@lanl.gov

Date/Time:

2018-08-30 15:10 (Time Zone: -05:00)

Report Last Signed By

User:

TERRILLLEMKE

Name:

Terrill Lemke

E-Mail:

tlemke@lanl.gov

Date/Time:

2018-08-30 16:18 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

No

PO Box 1663

Los Alamos, NM 87545

Facility Location:

LOS ALAMOS NATIONAL LABORATORY

on: PO B

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

073

External Outfall

Discharge:

Permittee Address:

073-A4

Hardwood Dimension and Flooring Mills?

Report Dates & Status

Monitoring Period:

From 06/01/18 to 07/31/18

DMR Due Date:

09/30/18

Status:

Facility:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

FOIII NODI.											
Parameter	Monitoring Location	n Seasor	# Param. NOD	1 = 2	Quantity or Loading	Quality or Con	centration	# o	Ex. F	requency of Analysis	Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qu	alifier 1 Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units			
				Sample			188	19 - mg/L	01/6	0 - Once Every 2 Months	GR - GRAB
X ₀₀₅₃₀ Solids, total suspended	1 - Effluent Gross	0	55	Permit Rec		<=	100 MAXIMUM	19 - mg/L 1	01/6	0 - Once Every 2 Months	GR - GRAB
Ta .				Value NOD	1						
		120		Sample							
81017 Chemical Oxygen Demand [C	COD] 1 - Effluent Gross	0		Permit Rec	10	<=		19 - mg/L	01/6	60 - Once Every 2 Months	GR - GRAB
				Value NOD	1		F - Insufficient Flow for Sampling				

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Etold	Туре		
Code	Name	monitoring Location	Field		Description	Acknowledge
00530	Solids, total suspended	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-28316

Attachments

No attachments: Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

 User:
 leslie@lanl.gov

 Name:
 Leslie
 Dale

 E-Mail:
 leslie@lanl.gov

Date/Time: 2018-08-30 15:10 (Time Zone: -05:00)

Report Last Signed By

 User:
 TERRILLLEMKE

 Name:
 Terrill
 Lemke

 E-Mail:
 tlemke@lanl.gov

Date/Time: 2018-08-30 16:18 (Time Zone: -05:00)



Signature/Review/Coordination Sheet

	any all documents requirin	g review, appro	Jvai, or sig	mature by the Laborato	Director or	Designee.
Today's Date 11/02/2018	Deadline Date N/A		s this a re	sponse to an action ite	em? Yes 🗖	No 🗵
From: Holly Wheeler			Call for	Pick-up		
Organization: EPC-CF			Name:	Joline Martinez	Phone:	7-0666
-	ent, briefly describing subje					
	R-18-29971): National Pollut					
30, 2018) Monitoring.	ermit (MSGP) Industrial Disc	marge Monitori	ng Keports	(MDMRs) for Third Qu	arter (August 1	- September
Summary/Detail						
industrial sites at monitor quarterly monitoring mu	or General Permit (Permit Trored outfalls quarterly (every ast be electronically submitte for third quarter monitoring	two months bet d in EPA's elect	ween April	and November) during	the calendar yea	r. Data from
	of Laboratory Director or file to Adesh-records@lanl.	•				
ALD Endorsement						
Name (print)	Signati	ıre	d		Date	
Michael Hazen, AL	DESHQSS	~ }	A			
	signatures on the COORDINATE	WITH 2 thru 5 are	complete ple	ase return to Group Office Ad	min for further sign	ature process
1. Name (print)	Signati				Date	
Enrique Torres, I		4.7	10			
2. Name (print)	Signati	ıre (N	14		Date	
" -			. 10 -		Date	
Taunia S. Van Valken		/)/#		5.	
3. Name (print)	Signati			000	Date	,
Terrill W. Lemke	, EPC-CP	mu	2	el m	142/18	8
4. Name (print)	Signate	ire (1 1/1		Date	_
Holly L. Wheeler		Lullor	elksti		LCVI	2010
5. Name (print)	Signate	re	7 - 0/3		Date \	VO
lanca august augustude	te-PAD/AD/Division coordin		DELL'A GERGERAL SERVICE.	1 20 11 21 5	1 00	

AUD

Permit id, permitted feature id, limit set txt, mped txt, form nodi cd, parameter cd, monitoring location cd, season nu m,quant 1 nodi cd,quant 1 qualifier txt,quant 1 sample num,quant 1 effluent num,quant 2 nodi cd,quant 2 qual ifier txt,quant 2 sample num,quant 2 effluent num,quant uom cd.conc 1 nodi cd.conc 1 qualifier txt.conc 1 sa mple num,conc 1 effluent num,conc 2 nodi cd,conc 2 qualifier txt,conc 2 sample num,conc 2 effluent num,con c_3_nodi_cd,conc_3_qualifier_txt,conc_3_sample_num,conc_3_effluent_num,conc_uom_cd,excursions_num,freq_anal ysis cd, sample type cd, param nodi cd, comment txt NMR053195,002,11,2018-09-30,,01045,1,0,,,,,,,212.0,,28,0,01/60,GR,,LA-UR-18-29971. NMR053195,002,11,2018-09-30,,01090,1,0,,,,,,,,,78.0,,28,1,01/60,GR, NMR053195,002,11,2018-09-30,,01104,1,0,,,,,,,243.0,,28,0,01/60,GR, NMR053195,002,11,2018-09-30,,51450,1,0,,,,,,19,,01/60,GR,B, NMR053195,005,O1,2018-09-30,,01045,1,0,,,,,,,367.0,,28,0,01/60,GR,,LA-UR-18-29971. NMR053195,009,O1,2018-09-30,,01045,1,0,,,,,,,365.0,,28,0,01/60,GR,,LA-UR-18-29971. NMR053195,012,O1,2018-09-30,,01045,1,0,,,,,,,616.0,,28,0,01/60,GR,,LA-UR-18-29971. The average of four monitoring values for Fe does not exceed the benchmark value therefore quarterly monitoring will be discontinued per Part 6.2.1.2. NMR053195,020,11,2018-09-30,,01040,1,0,,,,,,28,,01/60,GR,B,LA-UR-18-29971. The average concentration of Zn is mathematically certain to exceed the benchmark value. NMR053195,020,11,2018-09-30,,01045,1,0,,,,,,,28,,01/60,GR,B, NMR053195,020,11,2018-09-30,,01090,1,0,,,,,,,203.0,,28,1,01/60,GR, NMR053195,020,11,2018-09-30,,01104,1,0,,,,,,28,,01/60,GR,B, NMR053195,020,11,2018-09-30,,51450,1,0,,,,,,19,,01/60,GR,B, NMR053195,073,A4,2018-09-30,,00530,1,0,,,,,,174.0,,19,1,01/60,GR,,LA-UR-18-29971.

NMR053195,073,A4,2018-09-30,,81017,1,0,,,,,,,,,,,202.0,,19,1,01/60,GR,

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

No

External Outfall

Discharge:

002-11

Fabricated Metal Products, except Coating

Report Dates & Status

Monitoring Period:

From 08/01/18 to 09/30/18

DMR Due Date:

11/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

FOITH NODI.	*								
Parameter	Monitoring Locatio	n Season	# Param. NODI		Quantity or Loading	Quality or Co	ncentration	# of E	Ex. Frequency of Analysis Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3	Value 3	Units	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
0.045				Sample			212	28 - ug/L	01/60 - Once Every 2 Months GR - GRAB
01045 Iron, total [as Fe]	1 - Effluent Gross	0	-	Permit Req		<=	1000 MAXIMUM	28 - ug/L 0	01/60 - Once Every 2 Months GR - GRAB
				Value NOD					
V				Sample			78	28 - ug/L	01/60 - Once Every 2 Months GR - GRAB
X ₀₁₀₉₀ Zinc, dissolved [as Zn]	1 - Effluent Gross	0	-	Permit Req		<=	76 MAXIMUM	28 - ug/L 1	01/60 - Once Every 2 Months GR - GRAB
				Value NOD					
04404				Sample			243	28 - ug/L	01/60 - Once Every 2 Months GR - GRAB
01104 Aluminum, total recoverable	1 - Effluent Gross	0	**	Permit Req		<=	681 MAXIMUM	28 - ug/L 0	01/60 - Once Every 2 Months GR - GRAB
				Value NOD					
51450 Nitrite Plus Nitrate Total	4 500 10			Sample					
5 1450 Millile Plus Nitrate Total	1 - Effluent Gross	0	·	Permit Req		<=	0,68 MAXIMUM	19 - mg/L	01/60 - Once Every 2 Months GR - GRAB
				Value NOD			B - Below Detection Limit/No Detection		

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type. **Edit Check Errors**

	Parameter					
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29971

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: Name: leslie@lanl.gov Leslie Dale

E-Mail:

leslie@lanl.gov Date/Time:

Report Last Signed By User:

TERRILLLEMKE

2018-10-22 12:50 (Time Zone: -05:00)

Name: E-Mail: Terrill Lemke

tlemke@lanl.gov

Date/Time: 2018-10-22 12:53 (Time Zone: -05:00)

Permit	
Permit	#:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Facility:

LOS ALAMOS NATIONAL LABORATORY

Major:

No

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility Location:

PO BOX 1663

MS K490 LOS ALAMOS, NM 87545

Permitted Feature:

005

External Outfall

Discharge:

005-O1

Steam Electric Generating Facilities

Report Dates & Status

Monitoring Period:

From 08/01/18 to 09/30/18

DMR Due Date:

11/30/18

Status:

NetDMR Validated

Principal Executive Officer

Considerations for Form Completion

First Name:

Title:

Telephone:

Last Name:

No Data Indicator (NODI)

Form NODI:

Parameter	Monitoring Location	n Season	# Param. NOD		Quantity or Loading	Quality or Cond	centratio	n		# of Ex.	Frequency of Analysis	Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Qualifier 1 Value 1 Qualifier 2 Value 2 Q	ualifier 3	Value 3	Units			
				Sample				367	28 - ug/L	(01/60 - Once Every 2 Months	GR - GRAB
01045 Iron, total [as Fe]	1 - Effluent Gross	0		Permit Req.		<=	=	1000 MAXIMUN	/ 28 - ug/L	0 (01/60 - Once Every 2 Months	GR - GRAB
				Value NODI								

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

4

Edit Check Errors

No errors.

Comments

LA-UR-18-29971.

Attachments No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: Name:

leslie@lanl.gov Leslie Dale

E-Mail:

leslie@lanl.gov

Date/Time:

2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: Name:

TERRILLLEMKE

E-Mail:

Terrill Lemke

Date/Time:

tlemke@lanl.gov

2018-10-22 12:53 (Time Zone: -05:00)

DMR Copy of Record Permit Permit #: NMR053195 Permittee: LOS ALAMOS NATIONAL LABORATORY Facility: LOS ALAMOS NATIONAL LABORATORY Major: No PO Box 1663 Permittee Address: **Facility Location:** PO BOX 1663 Los Alamos, NM 87545 MS K490 LOS ALAMOS, NM 87545 Permitted Feature: 009 Discharge: 009-01 External Outfall Steam Electric Generating Facilities Report Dates & Status From 08/01/18 to 09/30/18 DMR Due Date: **Monitoring Period:** 11/30/18 Status: NetDMR Validated Considerations for Form Completion Principal Executive Officer First Name: Title: Telephone: Last Name: No Data Indicator (NODI) Form NODI: **Parameter** Monitoring Location Season # Param, NODI **Quantity or Loading Quality or Concentration** # of Ex. Frequency of Analysis Sample Type Code Name Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3 Value 3 Units Sample 365 28 - ug/L 01/60 - Once Every 2 Months GR - GRAB 01045 Iron, total [as Fe] 1 - Effluent Gross Permit Reg. <= 1000 MAXIMUM 28 - ug/L 0 01/60 - Once Every 2 Months GR - GRAB Value NODI Submission Note If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type. **Edit Check Errors** No errors. Comments LA-UR-18-29971. Attachments No attachments. Report Last Saved By LOS ALAMOS NATIONAL LABORATORY User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov Date/Time: 2018-10-22 12:50 (Time Zone: -05:00) Report Last Signed By User: TERRILLLEMKE Name: Terrill Lemke 5 E-Mail: tiemke@lanl.gov Date/Time: 2018-10-22 12:53 (Time Zone: -05:00)

Permi	t
Permi	t #:

Major:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Steam Electric Generating Facilities

Facility:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663 Los Alamos, NM 87545 Facility Location:

PO BOX 1663 MS K490

Permitted Feature:

012

No

External Outfall

Discharge:

012-01

LOS ALAMOS, NM 87545

Report Dates & Status

Monitoring Period:

From 08/01/18 to 09/30/18

DMR Due Date:

11/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name: Title:

Telephone:

Quality or Concentration

No Data Indicator (NODI)

Form NODI: Parar

Code

meter	Monitoring Location	Season #	Param. NODI
Name			

Sample Permit Reg.

Quantity or Loading Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3

Value 3 Units 616 28 - ug/L 1000 MAXIMUM 28 - ug/L 0

01/60 - Once Every 2 Months GR - GRAB 01/60 - Once Every 2 Months GR - GRAB

Frequency of Analysis

Sample Type

01045 Iron, total [as Fe] 1 - Effluent Gross

Value NODI

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-29971. The average of four monitoring values for Fe does not exceed the benchmark value therefore quarterly monitoring will be discontinued per Part 6.2.1.2.

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: Name:

E-Mail:

E-Mail:

leslie@lanl.gov Leslie Dale

leslie@lanl.gov

Date/Time:

2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: Name: **TERRILLLEMKE**

Terrill Lemke

tlemke@lanl.gov

Date/Time:

2018-10-22 12:53 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

No

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility Location:

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

020

External Outfall

Discharge:

020-11

Fabricated Metal Products, except Coating

Report Dates & Status

Monitoring Period:

From 08/01/18 to 09/30/18

DMR Due Date:

11/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

	Parameter	Monitoring Location	Season	# Param. NODI		Quantity or Loading	Quality or C	oncentration		# of Ex.	Frequency of Analysis	Sample Type
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value	1 Qualifier 2 Value 2 Qualifier 3	Value 3	Units			170
					Sample							
1040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	-	Permit Req.		<=	6 MAXIMUM	28 - ug/L	C	1/60 - Once Every 2 Months	GR - GRAB
					Value NODI			B - Below Detection Limit/No Detection				
					Sample							
1045	Iron, total [as Fe]	1 - Effluent Gross	0	1000	Permit Req.		<=	1000 MAXIMUM	28 - ug/L	C	11/60 - Once Every 2 Months	GR - GRAB
					Value NODI			B - Below Detection Limit/No Detection	_			
_					Sample			203	28 - ug/L	0	11/60 - Once Every 2 Months	GR - GRAB
(01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	0	1.575	Permit Req.		<=	76 MAXIMUM	28 - ug/L	1 0	11/60 - Once Every 2 Months	GR - GRAB
					Value NODI							
					Sample							
1104	Aluminum, total recoverable	1 - Effluent Gross	0	-	Permit Req.		<=	681 MAXIMUM	28 - ug/L	0	1/60 - Once Every 2 Months	GR - GRAB
					Value NODI			B - Below Detection Limit/No Detection				
					Sample							
1450	Nitrite Plus Nitrate Total	1 - Effluent Gross	0	2.00	Permit Req.		<=	0.68 MAXIMUM	19 - mg/L	0	1/60 - Once Every 2 Months	GR - GRAB
					Value NODI			B - Below Detection Limit/No Detection				

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Market day				
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
01090	Zinc, dissolved [as Zn]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29971. The average concentration of Zn is mathematically certain to exceed the benchmark value.

Attachments

No attachments,

Date/Time

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: **TERRILLLEMKE**

Name: Terrill Lemke E-Mail: tlemke@lanl.gov

8

2018-10-22 12:53 (Time Zone: -05-00)

Permit Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Facility:

LOS ALAMOS NATIONAL LABORATORY

Major:

No

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility Location:

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

073

External Outfall

Discharge:

073-A4

Hardwood Dimension and Flooring Mills?

Report Dates & Status

Monitoring Period:

From 08/01/18 to 09/30/18

DMR Due Date:

11/30/18

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

Parameter	Monitoring Locatio	n Season	# Param: NODI		Quantity or Loading	Quality or Cor	ncentratio	1	# (of Ex.	Frequency of Analysis	Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Q	Qualifier 1 Value 1 Qualifier 2 Value 2	Qualifier 3	Value 3	Units			
				Sample				174	19 - mg/L	0	1/60 - Once Every 2 Months	GR - GRAB
X 00530 Solids, total suspended	1 - Effluent Gross	0		Permit Req.			<=	100 MAXIMUM	19 - mg/L 1	0	1/60 - Once Every 2 Months	GR - GRAB
				Value NODI								
W.				Sample				202	19 - mg/L	0	1/60 - Once Every 2 Months	GR - GRAB
X 81017 Chemical Oxygen Demand [COD]	1 - Effluent Gross	0	-	Permit Req.			<=	120 MAXIMUM	19 - mg/L 1	0	11/60 - Once Every 2 Months	GR - GRAB
				Value NODI								

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Marshart P. Com		Туре		
Code	Name	Monitoring Location	Field		Description	Acknowledge
81017	Chemical Oxygen Demand [COD]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes
00530	30 Solids, total suspended 1 - Effluent Gross		Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes

Comments

LA-UR-18-29971

Attachments

Date/Time:

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE Name: Terrill Lemke E-Mail: tlemke@lanl.gov

10

2018-10-22 12:53 (Time Zone: -05:00)



Signature/Review/Coordination Sheet

	any all documents requiring r	eview, approval, or sig	gnature by the Laboratory D	irector or Designee.
Today's Date	Deadline Date N/A	Is this a re	esponse to an action item?	Yes No 🗵
11/02/2018 From: Holly Wheeler	IV/A	☐ Call fo		
Organization: EPC-CF	ı	Name:	Joline Martinez	Phone: 7-0666
Organization. Bro or		ivanie.	Jointe Martinez	Priorie. 7-0000
Title: Identify docume	ent, briefly describing subject	matter.		
Multi-Sector General Pe	R-18-29972): National Pollutan ermit (MSGP) Industrial Discha	t Discharge Elimination urge Monitoring Reports	System (NPDES) Permit Tra s (MDMRs) for 2018 Annual	cking No. NMR053195 Monitoring.
Summary/Detail				
Per the 2015 Multi-Sect monitored annually. The all 2018 impaired waters	or General Permit (Permit Trace results must be submitted to Es monitoring data.	king #NMR053195), LAPA in the MSGP NetDI	ANL is required to report resu MR database. Attached are the	.lts for parameters MDMRs transmitting
ACTION requested of	of Laboratory Director or D	esignee:		
Other Action: Send pdf	file to Adesh-records@lanl.go	V		
				3
				10
		3		
ALD Endorsement				
Name (print)	Signature	د	Da	ite .
		Λ\ 7.4.	50	
Michael Hazen, AL				
	signatures on the COORDINATED V		ease return to Group Office Admin for	or further signature process.
1. Name (print)	Signature	, /	Da	ite
Enrique Torres, I	EPC-DO	V(N)	_	
2. Name (print)	Signature	19/17	Da	ite
m 1 0 2 2 2 2 2		111	1	¥
Taunia S. Van Valken 3. Name (print)		N	<u> </u>	1-
3. Name (print)	Signature		Da	ite
Terrill W. Lemke	, EPC-CP	Muss	dep	11/2/18
4. Name (print)	Signature	" USDINA	Da	ite /
Holly L. Wheeler		/ MOKUM	W Mill	11/02/2018
5. Name (print)	Signature		Da	te
llagge angura appropria	to PAD/AD/Bivision coordinat			N.C.

Please ensure appropriate PAD/AD/Bivision coordination and review prior to submittal to the Director's Office. Form 1824 (8/12)

```
Permit id, permitted feature id, limit set txt, mped txt, form nodi cd, parameter cd, monitoring location cd, season nu
 m,quant_1_nodi_cd,quant_1_qualifier txt,quant 1 sample num,quant 1 effluent num,quant 2 nodi cd,quant 2 qual
ifier txt,quant 2 sample num,quant 2 effluent num,quant uom cd,conc 1 nodi cd,conc 1 qualifier txt,conc 1 sa
mple num,conc 1 effluent num,conc 2 nodi cd,conc 2 qualifier txt,conc 2 sample num,conc 2 effluent num,con
c 3 nodi cd,conc 3 qualifier txt,conc 3 sample num,conc 3 effluent num,conc uom cd,excursions num,freq anal
ysis cd, sample type cd, param nodi cd, comment txt
NMR053195,002,IW,2018-11-30,,01040,1,0,,,,,,,40.0,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al exceeded the New Mexico Water Quality Standard.
NMR053195,002,IW,2018-11-30,,01057,1,0,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,002,IW,2018-11-30,,01104,1,0,,,,,,,,,,,1550.0,,28,1,01/YR,GR,
NMR053195,002,IW,2018-11-30,,39516,1,0,,,,,,28,,01/YR,GR,B,
NMR053195,002,IW,2018-11-30,,51931,1,0,,,,,,,,,,8.05,,17,0,01/YR,GR,
NMR053195,005,IW,2018-11-30,,01040,1,0,,,,,,37.8,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,005,IW,2018-11-30,,01057,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,005,IW,2018-11-30,,01104,1,0,,,,,,3280.0,,28,1,01/YR,GR,
NMR053195,005,IW,2018-11-30,,39516,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,005,IW,2018-11-30,,51931,1,0,,,,,,,,25.3,,17,1,01/YR,GR,
NMR053195,009,IW,2018-11-30,,01040,1,0,,,,,,,40.4,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al exceeded the New Mexico Water Quality Standard.
NMR053195,009,IW,2018-11-30,,01057,1,0,,,,,,,,28,,01/YR,GR,B,
NMR053195,009,IW,2018-11-30,,01104,1,0,,,,,,,,725.0,,28,1,01/YR,GR,
NMR053195,009,IW,2018-11-30,,39516,1,0,,,,,,28,,01/YR,GR,B,
NMR053195,009,IW,2018-11-30,,51931,1,0,,,,,,,,,,,10.6,,17,0,01/YR,GR,
NMR053195,012,IW,2018-11-30,,01040,1,0,,,,,,3.56,,28,0,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,012,IW,2018-11-30,,01057,1,0,,,,,,,28,,01/YR,GR,B,
NMR053195,012,IW,2018-11-30,,01104,1,0,,,,,,907.0,,28,1,01/YR,GR,
NMR053195,012,IW,2018-11-30,,39516,1,0,,,,,,,28,,01/YR,GR,B,
NMR053195,012,IW,2018-11-30,,51931,1,0,,,,,,,,,,18.4,,17,1,01/YR,GR,
NMR053195,017,IW,2018-11-30,,01040,1,0,,,,,,,25.7,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al exceeded the New Mexico Water Quality Standard. The impaired water pollutant total Aroclor was
not detected in stormwater discharge from this outfall therefore annual monitoring will be discontinued per Part 6.2.4.1.
NMR053195,017,IW,2018-11-30,01057,1,0,......28,01/YR,GR,B,
NMR053195,017,IW,2018-11-30,,01104,1,0,,,,,,,,,,,,,,787.0,,28,1,01/YR,GR,
NMR053195,017,IW,2018-11-30,,39516,1,0,,,,,,,,,,,,<,0.0343,,28,0,01/YR,GR,
NMR053195,017,IW,2018-11-30,,51931,1,0,,,,,,5.49,,17,0,01/YR,GR,
NMR053195,020,IW,2018-11-30,,01040,1,0,,,,,,13.0,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutant Cu exceeded the New Mexico Water Quality Standard.
NMR053195,020,IW,2018-11-30,,01057,1,0,,,,,,,,28,,01/YR,GR,B,
NMR053195,020,IW,2018-11-30,,01104,1,0,,,,,,,301.0,,28,0,01/YR,GR,
NMR053195,020,IW,2018-11-30,,39516,1,0,,,,,,28,,01/YR,GR,B,
NMR053195,020,IW,2018-11-30,,51931,1,0,,,,,,,,,,,17,,01/YR,GR,B,
NMR053195,022,IW,2018-11-30,,01040,1,0,,,,,,,30.1,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al exceeded the New Mexico Water Quality Standard.
NMR053195,022,IW,2018-11-30,,01057,1,0,,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,022,IW,2018-11-30,,01104,1,0,,,,,,,,,,,,2370.0,,28,1,01/YR,GR,,
NMR053195,022,IW,2018-11-30,,39516,1,0,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,022,IW,2018-11-30,,51931,1,0,,,,,,,,,,,,11.7,,17,0,01/YR,GR,
NMR053195,026,IW,2018-11-30,,01040,1,0,,,,,,34.4,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutant Cu exceeded the New Mexico Water Quality Standard.
NMR053195,026,IW,2018-11-30,,01057,1,0,,,,,,,,28,,01/YR,GR,B,
NMR053195,026,IW,2018-11-30,,01104,1,0,,,,,,291.0,,28,0,01/YR,GR,
```

```
NMR053195,026,IW,2018-11-30,,39516,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,026,IW,2018-11-30,,51931,1,0,,,,,,,,,,17,,01/YR,GR,B,
NMR053195,029,IW,2018-11-30,,01040,1,0,,,,,,,41.3,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,029,IW,2018-11-30,,01057,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,029,IW,2018-11-30,,01104,1,0,,,,,,319.0,,28,0,01/YR,GR,
NMR053195,029,IW,2018-11-30,,39516,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,029,IW,2018-11-30,,51931,1,0,,,,,,,52.0,,17,1,01/YR,GR,
NMR053195,031,IW,2018-11-30,,01040,1,0,,,,,,,54.2,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutant Cu exceeded the New Mexico Water Quality Standard.
NMR053195,031,IW,2018-11-30,,01104,1,0,,,,,,,,28,,01/YR,GR,F,
NMR053195,031,IW,2018-11-30,,39516,1,0,,,,,,,28,,01/YR,GR,B,
NMR053195,031,IW,2018-11-30,,51931,1,0,,,,,,,,,,,,,17,,01/YR,GR,F,
NMR053195,032,IW,2018-11-30,,01040,1,0,,,,,,18.6,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,032,IW,2018-11-30,,01057,1,0,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,032,IW,2018-11-30,,01104,1,0,,,,,,1800.0,,28,1,01/YR,GR,
NMR053195,032,IW,2018-11-30,,39516,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,032,IW,2018-11-30,,51931,1,0,,,,,,,,,,,31.7,,17,1,01/YR,GR,
NMR053195,039,IW,2018-11-30,,01040,1,0,,,,,,,3.11,,28,0,01/YR,GR,,LA-UR-18-29972.
NMR053195,039,IW,2018-11-30,,01057,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,039,IW,2018-11-30,,01104,1,0,,,,,,,28,,01/YR,GR,F,
NMR053195,039,IW,2018-11-30,,39516,1,0,,,,,,,28,,01/YR,GR,B,
NMR053195,039,IW,2018-11-30,,51931,1,0,,,,,,17,,01/YR,GR,F,
NMR053195,042,IW,2018-11-30,,01040,I,0,,,,,,,9.06,,28,I,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,042,IW,2018-11-30,,01057,1,0,,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,042,IW,2018-11-30,,01104,1,0,,,,,,,,,,,2610.0,,28,1,01/YR,GR,
NMR053195,042,IW,2018-11-30,,39516,1,0,,,,,,,,,28,,01/YR,GR,B,
NMR053195,042,IW,2018-11-30,,51931,1,0,,,,,,,,,33.5,,17,1,01/YR,GR,
NMR053195,073,IW,2018-11-30,,01040,1,0,,,,,,17.1,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu and Al exceeded the New Mexico Water Quality Standard. The impaired water pollutant total Aroclor was
not detected in stormwater discharge from this outfall therefore annual monitoring will be discontinued per Part 6.2.4.1.
NMR053195,073,IW,2018-11-30,,01057,1,0,,,,,,,,28,,01/YR,GR,B,
NMR053195,073,IW,2018-11-30,,01104,1,0,,,,,,,,,,,1090.0,,28,1,01/YR,GR,,
NMR053195,073,IW,2018-11-30,,39516,1,0,,,,,,,,,,,,<,0.167,,28,0,01/YR,GR,,
NMR053195,073,IW,2018-11-30,,51931,1,0,,,,,,,5.89,,17,0,01/YR,GR,
NMR053195,075,IW,2018-11-30,,01040,1,0,,,,,,,99.9,,28,1,01/YR,GR,,LA-UR-18-29972. The impaired water
pollutants Cu Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.
NMR053195,075,IW,2018-11-30,,01057,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,075,IW,2018-11-30,,01104,1,0,,,,,,,,,,,,,,,,7590.0,,28,1,01/YR,GR,
NMR053195,075,IW,2018-11-30,,39516,1,0,,,,,,,,,,,28,,01/YR,GR,B,
NMR053195,075,IW,2018-11-30,51931,1,0,,,,,,,,,,90.7,,17,1,01/YR,GR,
```

Permit

Major:

NMR053195 Permit #:

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility Location:

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

002

No

External Outfall

Discharge:

002-IW

Impaired Water

Report Dates & Status

Monitoring Period: From 12/01/17 to 11/30/18 DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:

1 01111	NODI.										
	Parameter	Monitoring Location	Seasor	n # Param. NODI		Quantity or Loading	Quality or 0	Concentration	# of	Ex. Frequency of Analy	sis Sample Type
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1	Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units		
					Sample			40	28 - ug/L	01/YR - Annual	GR - GRAB
X 0104	O Copper, dissolved [as Cu]	1 - Effluent Gross	0	1.00	Permit Rec		<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
					Value NOD	i e					
					Sample						
01057	Thallium, dissolved [as TI]	1 - Effluent Gross	0	300	Permit Rec		<=	0,47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
					Value NOD	l		B - Below Detection Limit/No Detection			
					Sample			1550	28 - ug/L	01/YR - Annual	GR - GRAB
X 0110	Aluminum, total recoverable	1 - Effluent Gross	0	-	Permit Rec		<=	681 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
					Value NOD	I .					
					Sample						
39516	Polychlorinated biphenyls (PCBs	i] 1 - Effluent Gross	0	: ** :	Permit Rec	· ·	<=	0.2 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
					Value NOD	ſ		B - Below Detection Limit/No Detection			
					Sample			8.05	17 - pCi/L	01/YR - Annual	GR - GRAB
51931	Alpha. gross adjusted	1 - Effluent Gross	0	-	Permit Rec		<=	15 MAXIMUM	17 - pCi/L 0	01/YR - Annual	GR - GRAB
					Value NOC	I .					

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Marine I and		Туре		
Code	Name	Monitoring Location	Field		Description	Acknowledge
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (E π or Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Al exceeded the New Mexico Water Quality Standard.

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE

Name: Terrill Lemke E-Mail: tlemke@lanl.gov

Date/Time 2018-10-22 12:53 (Time Zone: -05:00)

Permit

Major:

NMR053195 Permit #:

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Νo

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663 Facility Location:

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

005

External Outfall

Discharge:

005-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name:

No Data Indicator (NODI)

Form NODI:

FOITH NODI.										
Parameter	Monitoring Location	n Season	# Param. NOD!		Quantity or Loading	Quality or C	oncentration	# of	Ex. Frequency of Analysis	s Sample Ty
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1	Value 1 Qualifier 2 Value 2 Qualifier :	3 Value 3	Units		
				Sample			37.8	28 - ug/L	01/YR - Annual	GR - GRAI
X 01040 Copper, dissolved [as Cu]	1 - Effluent Gross	0	1020	Permit Req		<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAI
0 (040 0-ppm)				Value NOD						
				Sample						
01057 Thallium, dissolved [as TI]	1 - Effluent Gross	0	100	Permit Req		<=	0.47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRA
				Value NOD			B - Below Detection Limit/No Detection			
				Sample			3280	28 - ug/L	01/YR - Annual	GR - GRA
X 01104 Aluminum, total recoverable	1 - Effluent Gross	0	-	Permit Req		<=	681 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRA
7 01104				Value NOD						
				Sample						
39516 Polychlorinated biphenyls [PCBs]	1 - Effluent Gross	0		Permit Reg		<=	0.2 MAXIMUM	26 - ug/L	01/YR - Annual	GR - GRAE
				Value NOD			B - Below Detection Limit/No Detection			
				Sample			25.3	17 - pCi/L	01/YR - Annual	GR - GRAI
X 51931 Alpha, gross adjusted	1 - Effluent Gross	0	÷.	Permit Req		<=	15 MAXIMUM	17 - pCi/L 1	01/YR - Annual	GR - GRAI
7 3 (80) · · · · · · · · · · · · · · · · · · ·				Value NOD						

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Fleid	Туре	Description	Acknowledge
Code	Name	moturoring Cocanon	redu	()\$0	2001,0101	
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Εποτ Code: 1)	Yes
51931	Alpha, gross adjusted	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard

tlemke@lanl.gov

Attachments

No attachments.

E-Mail:

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Name: Leslie Dale E-Mail: leslie@lanl.gov Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE Terrill Lemke Name:

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

009

No

External Outfall

Discharge:

009-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name: No Data Indicator (NODI)

Form NODI:						# AF E	x. Frequency of Analysis	Sample Type
Parameter	Monitoring Location	n Season # Param. N	DI	district or mountain	or Concentration	Units	V' I territorist' de sassiti de	Addition 13 be
Code Name				Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier	Nor 3 Value 3	28 - ug/L	01/YR - Annual	GR - GRAB
X 01040 Copper, dissolved [as Cu]	1 - Effluent Gross	0 -	Sample Permit Red Value NO		6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
01057 Thallium, dissolved [as TI]	1 - Effluent Gross	0	Sample Permit Re		0,47 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
			Value NO		725	28 - ug/L 28 - ug/L 1	01/YR - Annual 01/YR - Annual	GR - GRAB GR - GRAB
X 01104 Aluminum, total recoverable	1 - Effluent Gross	0 -	Permit Re Value NO		681 MAXIMUM	20 - ug/L 1	0	
39516 Polychlorinated biphenyls [PCBs] 1 - Effluent Gross	0 -	Sample Permit Re		0,2 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
			Value NOI Sample		10.6 15 MAXIMUM	17 - pCi/L 17 - pCi/L 0	01/YR - Annual 01/YR - Annual	GR - GRAB GR - GRAB
51931 Alpha. gross adjusted	1 - Effluent Gross	0 -	Permit Re Value NO		19 INDMITALING	17 - poi/L 0	STITE ZUITAGE	J., J.

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge	
Code	Name					Von	
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes Yes	
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	Soft The provided sample value is outside the permit limit (Error Code: 1)		

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Al exceeded the New Mexico Water Quality Standard.

Attachments

No attachments

Date/Time:

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail: 2018-10-22 12:50 (Time Zone: -05:00) Date/Time: Report Last Signed By

TERRILLLEMKE User: Terrill Lemke Name: 6 E-Mail: tlemke@lanl.gov 2018-10-22 12:53 (Time Zone: -05:00)

Permit

Major:

Permit #: NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

Facility:

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

External Outfall

No

Discharge:

012-IW Impaired Water

PO Box 1663

Los Alamos, NM 87545

Report Dates & Status

Monitoring Period: From 12/01/17 to 11/30/18 DMR Due Date:

Permittee Address:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form N	NODI:									
	Parameter	Monitoring Location	n Season	# Param. NODI		Quantity or Loading Quality or	Concentration	# of E	c. Frequency of Analysis	Sample Type
Code	Name					Qualifier 1 Value 1 Qualifler 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier	3 Value 3	Units		
					Sample		3.56	28 - ug/L	01/YR - Annual	GR - GRAB
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	-	Permit Req	<=	6 MAXIMUM	28 - ug/L 0	01/YR - Annual	GR - GRAB
					Value NOD					
					Sample					
01057	Thallium, dissolved [as TI]	1 - Effluent Gross	0	-	Permit Req	<=	0.47 MAXIMUM	26 - ug/L	01/YR - Annual	GR - GRAB
0,00,			-		Value NOD		B - Below Detection Limit/No Detection			
					Sample		907	28 - ug/L	01/YR - Annual	GR - GRAB
V	Aluminum, total recoverable	1 - Effluent Gross	Λ	200	Permit Req	<=	681 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
A 01104	Albininani, total recoverable	1 - Enideni Gross	Ü		Value NOD			•		
					Sample					
00.510	S I II I I I I I I I I I I I I I I I I	4	0			<=	0.2 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
39516	Polychlorinated biphenyls [PCBs]	1 - Emuent Gross	0	90.7	Permit Req		B - Below Detection Limit/No Detection	zo ugrz	O II I I I I I I I I I I I I I I I I I	0.1. 0.0.0
					Value NOD		18.4	17 - pCi/L	01/YR - Annual	GR - GRAB
					Sample					
X 5193 ²	1 Alpha, gross adjusted	1 - Effluent Gross	0	S#4.5	Permit Req	<=	15 MAXIMUM	17 - pCi/L 1	01/YR - Annual	GR - GRAB
					Value NOD					

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name	Monitoring Location	rield			
51931	Alpha, gross adjusted	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutants Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User leslie@lant.gov Name: Leslie Dale E-Mail: leslie@lanl.gov

Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User: TERRILLLEMKE Name: Terrill Lemke 7 E-Mail: tlemke@lanl.gov Date/Time: 2018-10-22 12:53 (Time Zone: -05:00)

Permit

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Facility:

LOS ALAMOS NATIONAL LABORATORY

Major:

No

Permittee Address:

PO Box 1663

Facility Location: Los Alamos, NM 87545

PO BOX 1663 MS K490

Permitted Feature:

External Outfall

Discharge:

017-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

LOS ALAMOS, NM 87545

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NO	DI:						# of I	Ex. Frequency of Analys	ie Sample Typ
	Parameter	Monitoring Location	on Season	# Param, NOD!		Quantity or Loading Quality or Concentration		x. Frequency of Analys	sia dampie Typ
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3 Value 3	Units		
					Sample	25 7	28 - ug/L	01/YR - Annual	GR - GRAB
V Co	opper, dissolved [as Cu]	1 - Effluent Gross	Ω		Permit Req	<= 6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
A 01040 CO	ipper, dissolved [as Cd]	1 - Elitaetit O1005	•		Value NOD				
					Sample				
		. =				<= 0.47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
01057 Th	allium, dissolved [as TI]	1 - Effluent Gross	0		Permit Req	D. D. L. Datastin Lies/No Debatic	_		
					Value NOD	787	28 - ug/L	01/YR - Annual	GR - GRAB
					Sample	The state of the s		01/YR - Annual	GR - GRAB
X 01104 Alu	urninum, total recoverable	1 - Effluent Gross	0	_	Permit Req	<= 681 MAXIMUM	28 - ug/L 1	VI/TN - Almuai	ON CIVID
					Value NOD				
					Sample	< 0.0343	28 - ug/L	01/YR - Annual	GR - GRAB
39516 Po	olychlorinated biphenyls [PCB:	sl 1 - Effluent Gross	0		Permit Req	<= 0.2 MAXIMUM	28 - ug/L 0	01/YR - Annual	GR - GRAB
50576	syomoniated Expression (Value NOD				
					Sample	5.49	17 - ρCi/L	01/YR - Annual	GR - GRAB
#4004 AV		1 Efficient Conso	0		Permit Reg	<= 15 MAXIMUM	17 - pCi/L 0	01/YR - Annual	GR - GRAB
51931 Alp	pha. gross adjusted	1 - Effluent Gross	U	#					
					Value NOD				

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Code	Parameter Name	Monitoring Location	Field	Туре	Description	Acknowledge
01104 01040	Aluminum, total recoverable Copper, dissolved [as Cu]	1 - Effluent Gross 1 - Effluent Gross	Quality or Concentration Sample Value 3 Quality or Concentration Sample Value 3		The provided sample value is outside the permit limit. (Error Code: 1) The provided sample value is outside the permit limit. (Error Code: 1)	Yes Yes

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Al exceeded the New Mexico Water Quality Standard. The impaired water pollutant total Aroclor was not detected in stormwater discharge from this outfall therefore annual monitoring will be discontinued per Part 6.2.4.1.

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail:

Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

TERRILLLEMKE User: Terrill Lemke Name: tlemke@lanl.gov E-Mail:

2018-10-22 12:53 (Time Zone: -05:00) Date/Time:

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

020

No

External Outfall

Discharge:

020-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name:

No Data Indicator (NODI) Form NODE

Form I	NODI:					Quality or Loading Quality or Co	- contestion	# of F	x Frequency of Analys	is Sample Type
	Parameter	Monitoring Location	n Season	# Param. NOD		quantity of coasing		Units	A Treduction of Attack	io campio type
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier 3	Value 3	28 - ug/L	01/YR - Annual	GR - GRAB
X 01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	-	Sample Permit Req Value NOD			28 - ug/L 1	01/YR - Annual	GR - GRAB
01057	Thallium, dissolved [as TI]	1 - Effluent Gross	0)##E	Sample Permit Rec Value NOD		B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
01104	Aluminum, total recoverable	1 - Effluent Gross	0		Sample Permit Rec Value NOD		• • •	28 - ug/L 28 - ug/L 0	01/YR - Annual 01/YR - Annual	GR - GRAB
39516	Polychlorinated biphenyls [PCBs]	1 - Effluent Gross	0	S#4	Sample Permit Red Value NOD		0.2 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
51931	Alpha, gross adjusted	1 - Effluent Gross	0	**	Sample Permit Red Value NOE		15 MAXIMUM B - Below Detection Limit/No Detection	17 - pCi/L	01/YR - Annual	GR - GRAB

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row. Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Lan one	DI Eli Oi O					
	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name	Monttoring Location				
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutant Cu exceeded the New Mexico Water Quality Standard

Attachments

No attachments.

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail:

2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User:

Terrill Lemke Name: tlemke@lanl.gov E-Mail:

2018-10-22 12:53 (Time Zone: -05:00) Date/Time:

Permit

Major:

Permit #: NMR053195

LOS ALAMOS NATIONAL LABORATORY Permittee:

Permittee Address:

Los Alamos, NM 87545

PO Box 1663

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663 Facility Location:

MS K490

LOS ALAMOS, NM 87545

17 - pCi/L 0

01/YR - Annual

GR - GRAB

Permitted Feature:

022

No

External Outfall

Discharge:

022-IW

Impaired Water

Report Dates & Status

Monitoring Period: From 12/01/17 to 11/30/18 DMR Due Date:

Sample

Permit Reg. Value NODI 01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

1 - Effluent Gross

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

15 MAXIMUM

No Data Indicator (NODI)

Form NODI:

Parameter	Monitoring Location	n Season	# Param NODI		Quantity or Loading Quality or	Concentration	# of l	Ex. Frequency of Analysis	s Sample Type
Code Name	monitoring Ecocotic				Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifie	er 3 Value 3	Units		
Odde				Sample		30, 1	28 - ug/L	01/YR - Annual	GR - GRAB
X 01040 Copper, dissolved [as Cu]	1 - Effluent Gross	0		Permit Req	<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
01040				Value NOD					
				Sample		0.47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
01057 Thallium, dissolved [as TI]	1 - Effluent Gross	0	-	Permit Req	<=	4,1		UITTN - Attitudal	OK-OIMB
				Value NOD		B - Below Detection Limit/No Detection			00 0010
				Sample		2370	28 - ug/L	01/YR - Annual	GR - GRAB
X 01104 Aluminum, total recoverable	1 - Effluent Gross	0	**	Permit Req	<=	681 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
				Value NOD					
				Sample					
39516 Polychlorinated biphenyls [PCBs	1 - Effluent Gross	0	24	Permit Rec	<=	0.2 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
				Value NOD		B - Below Detection Limit/No Detection	1		
				Sample		11.7	17 - pCi/L	01/YR - Annual	GR - GRAB

Submission Note

51931 Alpha, gross adjusted

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type

Edit Check Errors

	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name					
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes

Comments

LA-UR-18-29972, The impaired water pollutants Cu and Al exceeded the New Mexico Water Quality Standard.

Attachments

No attachments.

Date/Time:

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User: leslie@lanl.gov Leslie Dale Name: E-Mail: leslie@lanl.gov

Date/Time: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

TERRILLLEMKE User:

Terrill Lemke Name: tlemke@lani.gov E-Mail:

2018-10-22 12:53 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

No

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility:

Facility Location:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

026

External Outfall

Discharge:

026-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name:

Title:

Telephone:

Last Name:

No Data Indicator (NODI)

Form NODI:

Form I	NODI:								-44	of Ex. Frequency of Analy	sis Samole Type
	Parameter	Monitoring Locatio	n Season	# Param. NODI		departed of discipling		oncentration		of Ex (todaylog of same)	
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qu			Units	01/YR - Annual	GR - GRAB
0000					Sample			- 10.	28 - ug/L		
V	Conner dispolyed (ac Cul	1 - Effluent Gross	n	(155)	Permit Req	<=	:	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
∧ 01040	Copper, dissolved [as Cu]	1 - Ellident Oloda	Ü		Value NOD						
					Sample					01/YR - Annual	GR - GRAB
01057	Thallium, dissolved [as TI]	1 - Effluent Gross	0	164	Permit Req	<=			28 - ug/L	01/TR - Affilial	GK - GKAD
01007	mamam, dissilves (as 14)				Value NOD			B - Below Detection Limit/No Detection			
					Sample			291	28 - ug/L	01/YR - Annual	GR - GRAB
		. ===				<=	=	681 MAXIMUM	28 - ug/L 0	01/YR - Annual	GR - GRAB
01104	Aluminum, total recoverable	1 - Effluent Gross	0	**	Permit Req						
					Value NOD						
					Sample				20/	01/YR - Annual	GR - GRAB
39516	Polychlorinated biphenyls [PCBs	s] 1 - Effluent Gross	0	***	Permit Req	<=		7 - 11 - 11 - 11	28 - ug/L	OTTR - Annual	OK - OKAB
00010		•			Value NOD			B - Below Detection Limit/No Detection			
					Sample						00 0040
51931	Alpha, gross adjusted	1 - Effluent Gross	0	** :	Permit Reg	<=	=	15 MAXIMUM =	17 - pCi/L	01/YR - Annual	GR - GRAB
31831	Vibila, 81000 aglasted		-		Value NOD			B - Below Detection Limit/No Detection			

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Cede	Name	mointoining cocation	·			
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutant Cu exceeded the New Mexico Water Quality Standard.

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lan1.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail:

2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User:

Terrill Lemke Name: E-Mail: tlemke@lanl.gov

2018-10-22 12:53 (Time Zone: -05:00) Date/Time:

Permit

Major:

Permit #: NMR053195

No

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663 Facility Location:

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

029

External Outfall

Discharge:

029-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

....

Form NODI:						0 -111		# 051	Ex. Frequency of Analys	is Sample Tv
Parameter	Monitoring Location	n Season	# Param. NODI		Quantity or Loading		oncentration		Lx. I requency of many	als cumple ()
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Va	alue 1 Qualifier 2 Value 2 Qualifier		Units		00.001
				Sample			1110	28 - ug/L	01/YR - Annual	GR - GRA
X ₀₁₀₄₀ Copper, dissolved [as Cu]	1 - Effluent Gross	0	44	Permit Req		<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRA
01040 Sopper; disserved (as ear				Value NOD						
				Sample					040/8 4	GR - GRAI
1057 Thallium, dissolved [as TI]	1 - Effluent Gross	0	22	Permit Req		<=	-,,	28 - ug/L	01/YR - Annual	GR - GRA
				Value NOD			B - Below Detection Limit/No Detection			
				Sample			319	28 - ug/L	01/YR - Annual	GR - GRA
01104 Aluminum, total recoverable	1 - Effluent Gross	0	**	Permit Req		<=	681 MAXIMUM	28 - ug/L 0	01/YR - Annual	GR - GRA
				Value NOD						
				Sample						
39516 Polychlorinated biphenyls [PCBs]	1 - Effluent Gross	0		Permit Req		<=		28 - ug/L	01/YR - Annual	GR - GRAI
				Value NOD			B - Below Detection Limit/No Detection			
				Sample			52	17 - pCi/L	01/YR - Annual	GR - GRAI
V Alaba annu adiustod	1 - Effluent Gross	0		Permit Reg		<=	15 MAXIMUM	17 - pCi/L 1	01/YR - Annual	GR - GRAI
X 51931 Alpha, gross adjusted	i - Lindelli Gloss	•	57%	Value NOD						

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row; Units, Number of Excursions, Frequency of Analysis, and Sample Type,

Edit Check Errors

Code	Parameter Name	Monitoring Location	Field	Туре	Description	Acknowledge
51931	Alpha, gross adjusted Copper, dissolved [as Cu]	1 - Effluent Gross 1 - Effluent Gross	Quality or Concentration Sample Value 3 Quality or Concentration Sample Value 3		The provided sample value is outside the permit limit, (Error Code: 1) The provided sample value is outside the permit limit, (Error Code: 1)	Yes Yes

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.

Attachments

E-Mail:

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail:

2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User:

Name: Terrill Lemke 12 tiemke@lanl.gov

2018-10-22 12:53 (Time Zone: -05:00)

Date/Time:

Permit

Major:

Permit #:

NMR053195

Permittee:

Permittee Address:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

031

No

External Outfall

Discharge:

031-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form N								oncentration	# of Fx	x. Frequency of Analysis	Sample Type
	Parameter	Monitoring Location	n Season #	Param NOD		Quantity of codding			Units	. Hogonoy or many	
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value	2 Qualmer 3	54.2	28 - ug/L	01/YR - Annual	GR - GRAB
X 01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	500	Sample Permit Req Value NOD		<=	0.12	28 - ug/L 1	01/YR - Annual	GR - GRAB
01104	Aluminum, total recoverable	1 - Effluent Gross	0		Sample Permit Req Value NOD		<=	1699 MAXIMUM F - Insufficient Flow for Sampling	28 - ug/L	01/YR - Annual	GR - GRAB
39516	Polychlorinated biphenyls [PCBs]	1 - Effluent Gross	0	**	Sample Permit Req Value NOD		<=	0.2 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
51931	Alpha, gross adjusted	1 - Effluent Gross	0	er.	Sample Permit Red Value NOD		<=	15 MAXIMUM F - Insufficient Flow for Sampling	17 - pCi/L	01/YR - Annual	GR - GRAB

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Edit Che						
	Parameter	Monitoring Location	Field	Type	Description	Acknowledge
Code	Name	Morntoning Education				
01040 Copper, dissolved [as Cu]		1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutant Cu exceeded the New Mexico Water Quality Standard.

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name:

leslie@lanl.gov E-Mail: 2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User: Terrill Lemke Name:

tlemke@lanl.gov E-Mail: 2018-10-22 12:53 (Time Zone: -05:00) Date/Time:

Permit

Major:

Permit #:

NMR053195

No

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility: Facility Location: LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

032

External Outfall

Discharge:

032-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name:

Title:

Telephone:

Status:

Last Name:

No Data Indicator (NODI)

Form N	IODI:								# of E	x. Frequency of Analysis	s Sample Type
	Parameter	Monitoring Location	Season	# Param NODI		Quantity or Loading		Concentration Value 3	Units	z i requency of rinoryon	
Code	Name		٠,			Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifi	tier 2 Value 2 Qualmer		28 - ug/L	01/YR - Annual	GR - GRAB
X 01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	*:	Sample Permit Req		<=		28 - ug/L 1	01/YR - Annual	GR - GRAB
	Thallium, dissolved [as TI]	1 - Effluent Gross	0	20	Value NOD Sample Permit Req		<=	5 II 145 - TILLY 5	28 - ug/L	01/YR - Annual	GR - GRAB
01057	maillum, dissolved [as 11]	1 - Ellidelit Gloss	Ü		Value NOD Sample			7000	28 - ug/L 28 - ug/L 1	01/YR - Annual 01/YR - Annual	GR - GRAB GR - GRAB
X 011 04	Aluminum, total recoverable	1 - Effluent Gross	0	. 5 3	Value NOD		<=	OST MAZINOW	220, 49.2		
39516	Polychlorinated biphenyls [PCBs	s] 1 - Effluent Gross	0		Sample Permit Rec Value NOD		<=	0.2 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
X 51931	Alpha, gross adjusted	1 - Effluent Gross	0	-	Sample Permit Rec		<=	31_7 15 MAXIMUM	17 - pCi/L 17 - pCi/L 1	01/YR - Annual 01/YR - Annual	GR - GRAB GR - GRAB
					Value NOD						

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Edit Ched	CK Ellors					
Parameter		Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name	Monitoring Education				
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
		1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes
51931	Alpha, gross adjusted	1 - Ellidelli Gloss			The provided sample value is outside the permit limit. (Error Code: 1)	Yes
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is obtaine the permit limit (Error code. 1)	. 55

LA-UR-18-29972. The impaired water pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

User:

leslie@lanl.gov

Name: E-Mail: Leslie Dale leslie@lanl.gov

Date/Time:

2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

User:

TERRILLLEMKE

Name: E-Mail:

Date/Time:

Terrill Lemke

tlemke@lanl.gov

2018-10-22 12:53 (Time Zone: -05:00)

Permit

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Major:

No

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

External Outfall

Discharge:

039-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:	⇒)									of Ex. Frequency of Analysis	Campio Time
Parameter	Monitor	ring Location	Season #	Param. NODI		Quantity or Loading		Concentration		Of Ex. Frequency of Analysis	s sentition table
Code Name						Qualifier 1 Value 1 Qualifier 2 Value 2 Units	Qualifier 1 Value 1 Qualifler 2 Value 2 Qualifie	3 Value 3	Units		
Code					Sample			3 11	28 - ug/L	01/YR - Annua!	GR - GRAB
01040 Copper, dissolved [as Cu]	1 - Efflue	ent Gross	0	2	Permit Req.		<=	6 MAXIMUM	28 - ug/L 0	01/YR - Annual	GR - GRAB
01057 Thallium, dissolved [as Ti]	1 - Efflu	ent Gross	0	×	Sample Permit Req. Value NODI		<=	0.47 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
01104 Aluminum, total recoverable	e 1 - Efflu	ent Gross	0		Sample Permit Req. Value NODI		<=	681 MAXIMUM F - Insufficient Flow for Sampling	28 - ug/L	01/YR - Annual	GR - GRAB
39516 Polychlorinated biphenyls [PCBs] 1 - Efflu	ent Gross	0	ar i	Sample Permit Req Value NOD		<=	0.2 MAXIMUM B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
51931 Alpha, gross adjusted	1 - Efflu	ent Gross	0	##D	Sample Permit Req Value NOD		<=	15 MAXIMUM F - Insufficient Flow for Sampling	17 - pCi/L	01/YR - Annual	GR - GRAB

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

LA-UR-18-29972.

Attachments

No attachments.

Date/Time:

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail:

2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User: Terrill Lemke

Name: tlemke@lanl.gov E-Mail:

2018-10-22 12:53 (Time Zone: -05:00)

Permit

Major:

Permit #:

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

Permittee Address:

PO Box 1663

Los Alamos, NM 87545

Facility Location:

Facility:

LOS ALAMOS NATIONAL LABORATORY

PO BOX 1663

MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

042 External Outfall

No

Discharge:

042-IW

Impaired Water

Report Dates & Status

From 12/01/17 to 11/30/18 **Monitoring Period:**

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NODI:									er. Francisco e S Amelia	i- Cample Tune
Parameter	Monitoring Location	on Season	# Param, NOD		Quantity or Loading		oncentration		Ex. Frequency of Analys	sis Sample Type
Code Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifi	er 1 Value 1 Qualifier 2 Value 2 Qualifier 3		Units		
				Sample				28 - ug/L	01/YR - Annual	GR - GRAB
X 01040 Copper, dissolved [as Cu]	1 - Effluent Gross	0	0.55	Permit Reg		<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
01040 copper, dissolved [as odj	1 Elitaciii Gioco	•		Value NOD						
				Sample						
01057 Thallium, dissolved [as TI]	1 - Effluent Gross	0	(94)	Permit Req		<=	0,47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
O 1007 Tribillatin, 0/200/fed (do 1/1)				Value NOD			B - Below Detection Limit/No Detection			
				Sample			2610	28 - ug/L	01/YR - Annual	GR - GRAB
V	4. Eff	0	1942	Permit Req		<=	681 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
X 01104 Aluminum, total recoverable	1 - Effluent Gross	U						the state of the s		
				Value NOD						
				Sample			0.2 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
39516 Polychlorinated biphenyls [PCI	Bs] 1 - Effluent Gross	0	**	Permit Rec		<=		20 - ug/L	OTT TO THINGS	011 0111
				Value NOD	l		B - Below Detection Limit/No Detection		040/5 41	CD CDAR
				Sample			33.5	17 - pCi/L	01/YR - Annual	GR - GRAB
X 51931 Alpha, gross adjusted	1 - Effluent Gross	0		Permit Rec	,	<=	15 MAXIMUM	17 - pCi/L 1	01/YR - Annual	GR - GRAB
V 2/83/ Lubrier, 8:000 galactes				Value NOD	1					

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row. Units, Number of Excursions, Frequency of Analysis, and Sample Type, **Edit Check Errors**

Parameter						
Code	Name	Monitoring Location	Field	Туре	Description	Acknowledge
51931	Alpha, gross adjusted	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01040	Copper, dissolved (as Cu)	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

LA-UR-18-29972. The impaired water pollutants Cu and Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.

Attachments

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: E-Mail: leslie@lanl.gov

2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

Name:

E-Mail:

TERRILLLEMKE User:

Terrill Lemke

tlemke@lanl.gov

2018-10-22 12:53 (Time Zone: -05:00) Date/Time:

Permit

NMR053195 Permit #:

Major:

No

LOS ALAMOS NATIONAL LABORATORY Permittee:

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

073

External Outfall

Discharge:

073-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

2018-10-22 12:53 (Time Zone: -05:00)

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form NO	ODI:							# -4 F	. Frequency of Analysis	Sample Type
	Parameter	Monitoring Location	Season	Param, NODI		Quality of Educing	Concentration		. Frequency of Analysis	s Sample Type
Code	Name					Qualifier 1 Value 1 Qualifler 2 Value 2 Units Qualifier 1 Value 1 Qualifier 2 Value 2 Qualifier		Units		00.0040
Code	IVANIC				Sample			28 - ug/L	01/YR - Annual	GR - GRAB
X 01040 C	Copper, dissolved [as Cu] 1	1 - Effluent Gross	0		Permit Req	<=	6 MAXIMUM	28 - ug/L 1	01/YR - Annual	GR - GRAB
		1 - Ellidelit Gloss			Value NODI					
	Thallium, dissolved [as TI]		0		Sample	<a< td=""><td>0.47 MAXIMUM</td><td>28 - ug/L</td><td>01/YR - Annual</td><td>GR - GRAB</td></a<>	0.47 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
01057 T		1 - Effluent Gross			Permit Req		B - Below Detection Limit/No Detection	•		
					Value NOD			28 - ug/L	01/YR - Annual	GR - GRAB
	Aluminum, total recoverable		0		Sample			28 - ug/L 1	01/YR - Annual	GR - GRAB
X 01104 A		1 - Effluent Gross			Permit Req	<=	681 MAXIMUM 28 - ug	20 - ug/L 1	Olivin-Allindar Cit-Cit	010.0
201104					Value NOD				242/5	OD CDAD
					Sample	<	0,167	28 - ug/L	01/YR - Annual	GR - GRAB
39516 F	Polychlorinated biphenyls [PCBs]	1 - Effluent Gross	0	Permit Req		<=	0,2 MAXIMUM	28 - ug/L 0	01/YR - Annual GR -	GR - GRAB
39310 F		j i Emaam order								
	Alpha, gross adjusted		0	40	Sample		5.89	17 - pCi/L	01/YR - Annual	GR - GRAB
51931 A		4 550				<=	15 MAXIMUM 17	17 - pCi/L 0	01/YR - Annual	GR - GRAB
		1 - Effluent Gross			Permit Req					
					Value NOD					

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name	monitoring Education				
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

LA-UR-18-29972. The impaired water pollutants Cu and Al exceeded the New Mexico Water Quality Standard. The impaired water pollutant total Aroclor was not detected in stormwater discharge from this outfall therefore annual monitoring will be discontinued per Part 6.2.4.1

Attachments

Date/Time:

Date/Time:

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail: 2018-10-22 12:50 (Time Zone: -05:00)

Report Last Signed By

TERRILLLEMKE User: Terrill Lemke Name: tlemke@lanl.gov E-Mail:

DMR Copy of Record

Permit

Major:

Permit #:

No

NMR053195

Permittee:

LOS ALAMOS NATIONAL LABORATORY

PO Box 1663 Permittee Address:

Los Alamos, NM 87545

Facility:

LOS ALAMOS NATIONAL LABORATORY

Facility Location:

PO BOX 1663 MS K490

LOS ALAMOS, NM 87545

Permitted Feature:

075

External Outfall

Discharge:

075-IW

Impaired Water

Report Dates & Status

Monitoring Period:

From 12/01/17 to 11/30/18

DMR Due Date:

01/31/19

Status:

NetDMR Validated

Considerations for Form Completion

Yearly based upon the alternate monitoring season of April 1 through November 30.

Principal Executive Officer

First Name: Last Name:

Title:

Telephone:

No Data Indicator (NODI)

Form N	IODI:								44 - 5 5**	x. Frequency of Analysis	e Comple Tune
	Parameter	Monitoring Location	Season	# Param. NODI		Quantity or Loading		oncentration	Units	x. Prequency or Analysis	a aguibio ilibo
Code	Name					Qualifier 1 Value 1 Qualifier 2 Value 2 Units Qualifier 1 Value 1 Qualifier	ifler 2 Value 2 Qualifler	99.9	28 - ug/L	01/YR - Annual	GR - GRAB
					Sample		<=		28 - ug/L 1	01/YR - Annual	GR - GRAB
X 01040	Copper, dissolved [as Cu]	1 - Effluent Gross	0	***	Permit Req						
					Value NOO Sample						
01057	Thallium, dissolved [as TI]	1 - Effluent Gross	0	440	Permit Req		<=	•	28 - ug/L	01/YR - Annual	GR - GRAB
01007	mamam, dissorted fae m	, ==			Value NOD			B - Below Detection Limit/No Detection	28 - ug/L	01/YR - Annual	GR - GRAB
					Sample		<=		28 - ug/L 28 - ug/L 1	01/YR - Annual	GR - GRAB
X 01104	Aluminum, total recoverable	1 - Effluent Gross	0	300	Permit Req		-	GO I MICKINION	20, 09.2	•	
					Value NOD Sample						
20546	Polychlorinated biphenyls [PCBs]	1 1 - Effluent Gross	0	-	Permit Rec		<=	0.2 MAXIMUM	28 - ug/L	01/YR - Annual	GR - GRAB
39516	Polychiolinated diphenyls [FGBs]	T - Emelon Cross	Ŭ		Value NOD			B - Below Detection Limit/No Detection		A1045 A	OR CRAP
					Sample			90.7	17 - pCi/L 17 - pCi/L 1	01/YR - Annual 01/YR - Annual	GR - GRAB GR - GRAB
X 51931	Alpha, gross adjusted	1 - Effluent Gross	0	-	Permit Rec		<=	15 MAXIMUM	17 - poi/L 1	01/TK - Alliteal	SIX SIVE
,					Value NOD						

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Luit Oilot						
	Parameter	Monitoring Location	Field	Туре	Description	Acknowledge
Code	Name	Mothitorara English				V
01040	Copper, dissolved [as Cu]	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
	Alpha, gross adjusted	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
51931			, and the second	Soft	The provided sample value is outside the permit limit, (Error Code: 1)	Yes
01104	Aluminum, total recoverable	1 - Effluent Gross	Quality or Concentration Sample Value 3	Son	The provided sample value is oddided the politicalities (2000)	

Comments

LA-UR-18-29972. The impaired water pollutants Cu Al and Adjusted Gross Alpha exceeded the New Mexico Water Quality Standard.

Attachments

E-Mail:

Date/Time:

No attachments

Report Last Saved By

LOS ALAMOS NATIONAL LABORATORY

leslie@lanl.gov User: Leslie Dale Name: leslie@lanl.gov E-Mail: 2018-10-22 12:50 (Time Zone: -05:00) Date/Time:

Report Last Signed By

TERRILLLEMKE User: Name:

Terrill Lemke

18

tlemke@lanl.gov 2018-10-22 12:53 (Time Zone: -05:00)

APPENDIX I

Records of Employee Training Related to the SWPPP

Los Alamos

National Laboratory

Training Course Information/Roster

Co	urse Title	SWPPP TI	taining T	A-3-38 CS	Course No.	Session No		w Course?
Co	urse Dates	1115117	Time 1:00 pv	0	Class Location	Cost/Persor		Yes No. (if any)
Ins	tructor	Bursin	Training Specialist		3-38-20 Z# 211081	Vendor		Consumer
Spo	onsoring Orga		No. Attendees	Requirement Level C		.		
L	ANLI)ESHS	2	Lab-Wide	Division	Group	Compliano	e-based n/Requirement
Des	urse scription/ mments	Annual	SWPPP	Training	TA-3-3	se Car		
	ırse Category	,		(F) Profession Spe	ecific & Technical	□(L) Off-site Trainii	ng
		ent/Supervisory D	evelopment	(H) Safety			I) Environmenta	ıl
	(C) Facility/Sit	e Specific n (Org. or Benefits		(I) Health) On-the-job	
		cesses & Procedu	•	(J) Employee Dev	•	LJ(P) Emergency R	esponse
	ining Method	Live			Distance Learnin	g	Self Study	Test
		STUDEN	T ROSTER (Comp	lete all requested inf	ormation or use	N/A if not app	olicable)	1
	Z Number	1		formation, i.e., Socia	al Security Numb		wed Mail Stop	Group
		Name (Last, Fire Signature	st, M.I.)			Work Pkg	Phone	Employer
	999888	Doe, John Q.			460700/	M352	E538	CIC-13
					H233/	K123	5-2284	Butler
1	241393	Sisheros	Allen A		1		P298	206-05
	1	,	7777700		1		695-4686	LANS
2	176542	Ponell		,	1		P298	A
	176,390	10118+	1 Opril	W-	/		6-1776	LANL
3					/			
4					1			
					1			
5					/			
			•		/			
6					/			
7					/			
					/			
8					1			
					/			
9		-			1			
10					1			
					1			
11					1			
12					1			
					/			

For additional names, go to Form 1651con.



Storm Water Multi-Sector General Permit (MSGP) for Industrial Facilities

TA-3-38 Carpenter Shop (CS)

2017 SWPPP Training





TA-3-38 CS SWPPP- MSGP Permit

- The MSGP is a National Pollutant Discharge Elimination System (NPDES) Permit associated with the Clean Water Act (CWA) of 1973
 - Regulates storm water discharges from industrial facilities/activities
 - Objective is to minimize pollutants to surface waters
 - Requires implementation of a Stormwater Pollution Prevention Plan (SWPPP)
 - A new permit (with no.) is issued approx. every 5 years
 - 2015 MSGP #NMR053915 (LANS)
 - Link to 2015 MSGP: https://www.epa.gov/sites/production/files/2015-10/documents/msgp2015 finalpermit.pdf





TA-3-38 CS SWPPP – LANL Facilities

LANL MSGP Regulated Facilities:

- Metals Fab Shop TA-03-38: Sector AA (Fabricated Metal Products)
- Carpenter Shop TA-03-38: Sector A (Timber Products)
- Asphalt Batch Plant TA-60-233: Sector D (Asphalt Paving)
- Metal Recycling Facility (MRF) TA-60-311: Sector N (Scrap Recycling)
- Roads & Grounds TA-60-250: Sector P (Land Transportation/Warehousing)
- Power Plant TA-03-1790: Sector O (Steam Electric Generating)
- Heavy Equipment TA-60-01: Sector P (Land Transportation/Warehousing)
- Salvage Yard TA-60-02: Sector P (Land Transportation/Warehousing)
- TA-3-39 & 102 Sector AA (Fabricated Metal Products)
- Sigma Complex Foundry TA-03-66: Sector AA & F (Fabricated & Primary Metals)
- TA-54 TA-54-Area G, Area L & Rant: Sector K (Hazardous Waste TSDF)
- Maint. Facility West TA-54-Area L: Sector P (Land Transportation/Warehousing)





TA-3-38 CS SWPPP - Team Members

- TA-3-38 Carpenter Shop SWPPP Team:
 - Donnie Parrett, Shop Superintendent, LOG-Central Shops
 - Jillian Burgin, Deployed Environmental Professional (DEP)
 - Russell Stone, ESH Manager DSESH-UIS
 - Holly Wheeler, MSGP Compliance Lead, EPC-CP
 - See Facility Managers
- Facility Managers/FOD
 - Jim Farmer, Maintenance Manager, LOG-MSS
 - John Merhege, Logistics Division Leader
 - Andrew Erickson, UI FOD





TA-3-38 CS SWPPP –Control Measures (BMPs)

 Run-On Control: The south and west boundary of the site is stabilized with rock and paving to provide run-on control from the west parking lot.







TA-3-38 CS SWPPP – Control Measures (BMPs)

 <u>Covered Metal/Material Storage</u>: Covered storage racks, rolloff bins, enclosed storage sheds, and flam cabinets minimize storm water contact with materials and pollutants.











TA-3-38 CS SWPPP - Control Measures (BMPs)



- Good House-Keeping Practices: Covered and enclosed trash bins minimize debris on site. Monthly sweeping of the west lot removes accumulated dust and reduces pollutants.
- YOU can help reduce trash as well: keep truck beds clean, properly dispose of food trash and cigarette butts, keep dumpsters closed. Recycle water bottles, cans, plastic bags, etc..









TA-3-38 CS SWPPP - Spill Reporting

Report

a Spill



Know where spill kits are located.

Report spills immediately to your supervisor.

Additional contacts are provided in the LOG-MSS Guidance:



SEO (EM&R):

Los Alamos National Laboratory - LOG-MSS Guidance

Do you know who to call in the event of a spill/leak?



Spills and leaks from vehicles, equipment and laboratory operations can accidentally occur. Oil, fuel, hydraulic fluids and other chemicals, once spilled or leaked to the environment are pollutants that require immediate clean-up and spill reporting. It is important to prevent pollutants from entering into a watercourse or storm drain and from coming into contact with storm water. If you have the ability and materials to contain a spill (i.e. spill kit—absorbent pads, booms, etc.) you may do so in order to prevent migration of the spilled material until additional help arrives. You are still required to report the spill and should be aware of who to contact.

The appropriate spill contact should be listed in your Integrated Work Document (IWD). This can vary from your PIC to the Security & Emergency Operations Center (SEO), also known as EM&R, to your site access control office. The name and contact information for your Waste Management Coordinator (WMC) should also be listed in the IWD.

When in doubt, contact the SEO. They will respond, assess the situation, determine further actions required and will contact appropriate personnel. The Environmental Protection & Compliance (EPC-CP) group will also be contacted. EPC-CP will ensure a Spill Report is completed to document the spill. If the pollutant has reached a watercourse or storm drain, EPC-CP is responsible for reporting the spill to the state environment department - NMED and EPA.

A WMC will ensure that waste from a spill clean-up is properly managed and disposed. The LOG-MSS or FOD Deployed Environmental Professional (DEP) can help coordinate spill response and clean-up activities and can complete the Spill Report form.

-Jillian Burgin, Deployed Environmental Professional for LOG-MSS



TA-3-38 CS SWPPP - Sampler & Outfalls



Sampler(s)

- Automated collection during storm events
- Monitoring for pollutants
 - Benchmark (sector specific limits)
 - Impaired Waters (receiving water)
 - Sandia Canyon

Storm Drains (Outfalls)

- Sample/discharge points (automated & visual)
- Evaluated during inspections
- Each numbered for site map
- 2 Outfalls on site, Outfalls 073 & 074
- 1 Monitored: Outfall 073













TA-3-38 CS SWPPP – Sampling (Monitoring)

- There are two types of monitoring:
 - Benchmark (Quarterly)
 - Monitors for sectorspecific pollutants (i.e. metals)
 - Impaired Waters (Annual)
 - Monitors for pollutants associated with receiving water limits or impairments.

Sampling parameters for TA-3-38 CS

Monitoring Type	Location	Parameters	Numeric Limitations	Schedule		
<u>Benchmark</u>	Sampler: MSGP07302 Outfall #073	Chemical Oxygen Demand (COD)	120 mg/L	Quarterly		
Subsector A Timber Products	Sandia Canyon					
Subsector A4 Wood	,	Total Suspended Solids (TSS)				
Products not elsewhere classified (SIC 2449)			100 mg/L			
Impaired	Sampler:	Aluminum	681 ug/L	Annual		
Waters	MSGP07302 Outfall #073 Sandia	Gross Alpha, adjusted	15 pCi/L			
	Canyon	Copper	6 ug/L			
		Thallium, dissolved	0.47 ug/L			
		PCB in Water Column	0.00064 ug/L			





TA-3-38 CS SWPPP - Inspections

Monthly Routine Inspections

- Performed by DEP and facility rep, annual with EPC-CP
 - Check for non-compliance issues/identify corrective actions
 - (i.e. housekeeping, uncovered materials, spills/pollutant discharge, BMP integrity)

Quarterly Visual Inspections

- Performed during a storm event each quarter at each outfall (if possible)
 - Storm water sample collected in a clean, clear glass
 - Storm water sample evaluated for potential pollutants
 - (i.e. odor, oil sheen, suspended particles)
 - Additional BMPs may be required if pollutants are evident

Additional Reporting Requirements

- Annual reporting to EPA for corrective action status
- Quarterly Discharge Monitoring Report (DMR) for sample results
- Spill reporting to EPC-CP and potentially NMED if reportable



TA-3-38 CS SWPPP - Corrective Actions



MSGP Corrective Action Process

- Once identified immediate reporting to appropriate facility personnel
- Entered into CARs database/main-con. for EPC-CP reporting/tracking
- Specific deadlines for completion:
 - Same day or next day if identified late in the day or after regular business hours (quick fixes)
 - 14 days (order parts, schedule labor) >must provide schedule to EPC-CP
 - 45 days maximum (temporary BMPs required in the meantime)
 - >45 days: Report to EPC-CP for EPA is required (schedule must be provided for completion). EPA must approve schedule.
- FSRs with cost codes may be required
- Anyone can report not just inspector or EPC-CP
- Exceedances from sampling can trigger corrective actions, applicable to the same deadlines as noted above.



TA-3-38 CS SWPPP – Documentation



- Required Documentation for SWPP Plan
 - Site Maps
 - Facility Specific
 - Receiving Waters
 - Endangered Species
 - Completed Inspection Forms & Templates
 - Annual Reporting Data
 - Notice of Intent (NOI) to EPA
 - Non-Storm Water Discharge Certification
 - Spill Tracking Table
 - Amendment Log
 - Sampling Results
 - Training Records
 - Critical Habitat Documentation/Historic Properties/NEPA
 - Procedures Referenced in the SWPPP



TA-3-38 CS SWPPP – Location & Contacts



- A hard copy of the SWPP Plan is kept in DEP office and/or at facility.
- The SWPP Plan is updated annually and can be found online on the public reading room at:
 - http://permalink.lanl.gov/object/tr?what=info:lanl-repo/lareport/LA-UR-17-20933

Environmental Contacts:

- > Jillian Burgin, DESHS-UIS, DEP: 665-1893
- Leonard Sandova, DESHS-UIS, DEP: 231-1235
- Russell Stone, DESHS-UIS, ESH Mgr.: 606-0017
 - Holly Wheeler, EPC-CP: 667-1312



attenders aveilent,
through the
for-Div.

Agenda

Logistics Division Craft All Hands

Tuesday, May 3, 2016.8 - 10 am and Wednesday, May 4, 2016.1 - 3 pm

- John Merhege, Logistics Division Leader
- Orlando Griego, Craft Safety Representative 5 minutes
- Evacuation
- Directors Video
- Larry Simmons, Principal Associate Director of Capital Projects (PADCAP) 15 minutes
- Kim Cassara, Associate Director for Project Management (ADPM) 5 minutes
- Craft Wellness 20 minutes
- Orlando Griego, Craft Safety Representative
- Jamie Aslin and Cynthia Sandin of Occupational Safety and Health-Occupational Health (HO-HSO)
- 2. Multi-Sector General Permit (MSGP) 10 minutes
- Terrill Lemke of Environmental Protection and Compliance Compliance Programs (EPC-CP)
- 3. Radiological Control Awareness 10 minutes
- Phil Romero of Deployed Environmental, Safety and Health Services -- Construction, Projects and Craft Support (DESHS-CPCS)
- 4. Materials of Trade Training 15 minutes
- Phil Romero/Jillian Burgin of Deployed Environmental , Safety and Health Services Construction, Projects and Craft Support (DESHS-CPCS)
- 5. Fall Protection Training 20 minutes
- Safety & Hygiene (OSH-ISH) Randy Sandoval and Thomas Crespin of Occupational Safety and Health-Industrial



Storm Water Multi-Sector General Permit Compliance

Terrill Lemke
Environmental Protection & Compliance



Water Quality History

- Cuyahoga River,Ohio
- 40 years ago...
 - Two-thirds of
 America's lakes,
 rivers and coastal
 waters were unsafe
 for fishing and
 swimming.





Operated by Los

Water Quality Facts & History

- Approximately 117 million people one in three Americans get drinking water from systems relying in part on streams, rivers or lakes.
- Annually approximately 1.2 trillion gallons of household, restaurant, and industrial sewage is dumped into US waters.
- 1 cup of oil can put a sheen on 1 surface acre of water.
- 1970 Environmental Protection Agency founded
- 1973 Clean Water Act
 - Restore and maintain quality of America's waters
 - Establish water quality laws & permits





Multi-Sector General Permit

- EPA water quality permit
- Objective: minimize the discharge of pollutants to surface waters
- Regulates industrial activity (Not only at LANL!)
- At LANL:
 - Machine Shops
 - Asphalt Batch Plant
 - Power Plant
 - Material Recycling Facility
 - Roads & Grounds

- Heavy Equipment Shop
- TA-60 Warehouse
- TA-54
- Sigma Facility (TA-3-66)
- Carpenter Shop (TA-3-38)







Why Do We Care?

- Federal law
- Protect the environment
- Protect the reputation of LANL
- Potential fines & penalties
 - Los Alamos County (Bayo Canyon WWTP) \$6000
 - Santa Fe Airport \$4000
 - Walmart \$7 million





How Does This Impact You?

- MSGP facilities have specific:
 - Engineering controls
 - Administrative controls
 - Plans & procedures
- Be aware of controls and requirements







How Does This Impact You?

- Primary work related MSGP issues:
 - Housekeeping
 - Spills
 - Metal use/storage
- Think about how your work impacts storm water
- Your work affects MSGP compliance!










Conclusion

- MSGP compliance must be part of your job!
 - Plan for it
 - Think about how your material & activities can affect storm water runoff





APPENDIX J

Corrective Action Reports Documentation of Repairs and Maintenance of Control Measures

CAR # MSGP Facility Desc	Inspection Date	Specific Location	Inspector Name	Finding Category	Finding Category Description If Other	Problem Description	Inspection Type	Inspection Type Description If Other	Corrective Action Description	SIO	SIO Affected	Provide Action Taken at Affected SIOs	Swppp Modify	CA Initiate Date	CA Complete Date	Completed		EPA Notified Date (For ≥ 45 days)
1298 TA-3-38 Carpenter Shop	1/31/18	Southwest Corner of Storage Yard	BURGIN JILLIAN E	Control measures not properly operated or maintained	-	Tarp was totally torn off of the stack of metal posts at the southwest corner of the storage yard.	Routine facility inspection	-	Cover metal posts.	N	-	-	N	2/1/2018 8:00	2/1/2018 16:00	Y	CAR reported at time of inspection. The posts were recovered on 2/1/18.	-
TA-3-38 Carpenter Shop	12/18/17	Along the fence line, dock and near the sampler at TA-3-38 Carpenter's Shop	WHEELER HOLLY L	Control measures inadequate to meet non- numeric effluent limitations	-	At the TA-3-38 Carpenter's Shop, there was trash by the sampler, dock and along the fenceline.	Routine facility inspection	-	Pick up the trash within the facility boundry at TA-3-38 Carpenter's Shop.		-	-	N	12/19/2017 0:00	12/19/2017 0:00	Y	Pick up the trash within the facility boundry at TA-3-38 Carpenter's Shop. *Cleaned up 12/19/17.	-
1160 TA-3-38 Carpenter Shop	8/28/17	Outfall 073 at the TA-3- 38 Carpenter Shop		Impaired water quality exceedance		Discharge from outfall 073 at the TA-3-38 Carpenter Shop (41.8 ug/L) exceeded the New Mexico water quality standard for dissolved Copper (6.0 ug/L). This occurred during the storm event on 07/18/2017.	Impaired waters monitoring		Facility personnel need to evaluate potential pollutant sources of dissolved Copper and implement additional controls to ensure discharge of this pollutant source in stormwater is minimized.	N			Y	8/28/2017 15:45	8/29/2017 0:00	Y	Facility personnel must immediately take action to minimize off site discharge of the dissolved Copper at outfall 073. Implementation of all follow-up actions must be completed within 14 days (if additional action is needed). If finalization of corrective action(s) exceeds 14 days, documentation of why it is infeasible to complete the corrective action within the 14 day timeframe must be provided along with a schedule for completion. If a SWPPP modification is required as a result of this exceedance it must be implemented within 14 days of completing corrective action work. *8/28/17: sample results are from 7/18/17. The facility parking lot was swept on 7/26/17. in addition, metal materials that were on the ground south of the outfall	
TA-3-38 Carpenter Shop	7/27/17	Drums on West Side of Metal Storage Yard	BURGIN JILLIAN E	Control measures not properly operated or maintained	-	There are a couple rusted drums just to the south of the stairway labeled 'Forming Material?. One is open, doesn't have a bung and has some misc. trash.	Other (describe) :	EPC Sampler Check	Replace rusted drums with new drums or containers or properly cover materials.	N	-	-	N	7/27/2017 0:00	8/18/2017 0:00	Y	Corrective action reported by EPC on 7/27/17 p.m. The drums were removed from the yard on 8/18/17.	-
1153 TA-3-38 Carpenter Shop	7/27/17	SW Corner of Metal Storage Yard	BURGIN JILLIAN E	Control measures not properly operated or maintained	-	The tarp covering the stack of metal posts at the SW side of the yard has come off.	Other (describe) :	EPC Sampler Check	Resecure tarp over metal posts.	N	-	-	N	7/27/2017 0:00	8/18/2017 0:00	Y	Corrective action reported by EPC on 7/27/17 p.m. Completed 8/18/17.	-

1149 TA-3-38 Carpenter	7/26/17 Southeast BURGIN Fenceline JILLIAN E	Control - measures not	Metal rods lying on the ground Routine facility and trash accumulation in inspection	Remove metal rods and Clean up trash in area.	- - N	7/26/2017 0:00 8/7/2017 0:00 Y	Notified facility personnel on 7/27/17. Materials had been
Shop	Near Green Metal Storage Cabinet	properly operated or maintained	area.				removed by 8/7/17.
1126 TA-3-38 Carpenter Shop	6/16/17 SE Side of the Facility at Fenceline	Control - measures not properly operated or maintained	Trash has accumulated at the SE area of the facility at the fenceline.	Clean up and dispose of N trash.	N	6/16/2017 0:00 6/22/2017 0:00 Y	CAR reported to facility personnel the day of inspection. C/A was completed by 6/22/17.
TA-3-38 Carpenter Shop	12/19/16 West end WHEELER of the TA-3- HOLLY L 38 Carpenter's Shop by the metal storage racks.	Control - measures inadequate to meet non-numeric effluent limitations	At the TA-3-38 Carpenter's Shop, there was a can of trash present that was not covered.	Empty the can of trash into N a covered dumpster or find a lit for the trash can and cover it.	- N	12/19/2016 0:00 1/11/2017 0:00 Y	Empty the can of trash into a covered dumpster or find a lit for the trash can and cover it. *Roads & Grounds removed the trash can. 1/11/17.
1018 TA-3-38 Carpenter Shop	12/19/16 On the south side of the shed, under the shed and on the metal rack at t he SW corner of TA-3-38 Carpenter's Shop site.	Control - measures inadequate to meet non-numeric effluent limitations	At the TA-3-38 Carpenter's Shop, metal is stored on the ground as the rack is too full to hold it on the SW corner of the site. In addition, there is uncovered metal stored in half PVC pipe racks on the south side of the shed. Metal is also stored on the ground under the shed and is sticking out.	Pick up the metal stored on the ground and put it on the covered rack. Cover the metal on the south side of the shed. Determine if the metal stored under the shed is still usable. If not, recycle or dispose of it. If it is determined to be usable, cover it.	N	12/19/2016 0:00 1/18/2017 0:00 Y	Pick up the metal stored on the ground and put it on the covered rack. Cover the metal on the south side of the shed. Determine if the metal stored under the shed is still usable. If not, recycle or dispose of it. If it is determined to be usable, cover it. *Metal has been removed, 1/18/17.
1017 TA-3-38 Carpenter Shop	12/19/16 NE corner of the TA-3-38 Carpenter's Shop Site	Control - measures inadequate to meet non-numeric effluent limitations	At the TA-3-38 Carpenter's Shop, two dumpsters had issues. One was not covered and the other did not have a side panel.	Ensure that the dumpsters are covered and trash is enclosed. Either order a new side panel or replace the dumpster with one that has side covers and a top cover.	N	12/19/2016 0:00 1/11/2017 0:00 Y	Ensure that the dumpsters are covered and trash is enclosed. Either order a new side panel or replace the dumpster with one that has side covers and a top cover. *Roads & Grounds replaced side panel on dumpster. 01/11/17.
993 TA-3-38 Carpenter Shop	10/31/16 Storage BURGIN Yard JILLIAN E	Control - measures not properly operated or maintained	Improperly stored and uncovered metal materials were present in storage yard: near fenceline and on top of covered boxes.	Cover/properly store metal N materials.	- N	10/31/2016 0:00 11/4/2016 0:00 Y	Corrective action reported at the time of inspection.
975 TA-3-38 Carpenter Shop	9/29/16 Materials BURGIN Storage JILLIAN E Yard	Control - measures not properly operated or maintained	Metal materials were uncovered and lying on the ground in three areas: 1) Between storage shed & fenceline. 2) North side of storage shed. 3) On west side of lot near storage racks.	Place metals into covered N racks or storage.	- N	9/29/2016 0:00 10/3/2016 0:00 Y	The Carpenter Shop Manager - was informed and corrective action should be taken immediately.

		1			_		1						
935 TA-3-38	7/14/16 Outfall 073		Other	Impaired water Discharge from outfall 073 at	Other (describe):		The facility must	N	 Υ	7/14/2016 0:00	7/26/2016 0:00	Y	N/A -
Carpenter	at the TA-3-	HOLLY L	(describe):	quality standard the TA-3-38 Carpenter Shop		monitoring	immediately take action to						
Shop	38			exceedance exceeded the New Mexico			minimize off site discharge						
	Carpenter			water quality standard for			of the dissolved Copper at						
	Shop			dissolved Copper. This			outfall 073 followed by						
				occurred during the storm			implementation of specific						
				event on 5/15/2016.			follow-up actions within 14						
							days (if additional action is						
							needed). If finalization of						
							corrective action(s)						
							exceeds 14 days,						
							documentation of why it is						
							infeasible to complete the						
							corrective action within the						
							14 day timeframe must be						
							provided along with a						
							schedule for completion.						
							Since outfall 073 has a						
							substantially identical						
							outfall (SIO), the facility						
							must assess the need for						
							corrective action at that						
							SIO also (i.e., outfall 074).						
							SWPPP modifications						
							required as a result of this						
							exceedance must be						
							implemented within 14						
921 TA-3-38	6/27/16 Sternvent	BURGIN	Control	- There is an accumulation of	Routine facility	-	Hand sweeping is needed	N	 N	6/27/2016 0:00	6/29/2016 0:00	Y	Corrective action has been -
Carpenter	Cyclone/Sa	JILLIAN E	measures not	debris around the sampler	inspection		in the areas listed above.						completed.
Shop	mpler		properly	tubes located on the north			Requested this be						
			operated or	side of the Sternvent Cyclone			performed during regular						
			maintained	and wood dust bin. There is			sweeping of the west lot						
				also an accumulation of trash			scheduled for 6/29/16.						
				and debris near the dumpster	s								
				and the south side of the yard									
920 TA-3-38	6/27/16 Storage	BURGIN	Control	- Uncovered metal/materials	Routine facility	-	Cover materials listed	N	 N	6/27/2016 0:00	6/29/2016 0:00	Y	Corrective actions have been -
Carpenter	Yard	JILLIAN E	measures not		inspection		above (or move into			., ,	., .,		completed.
Shop			properly	1) Metal posts stored on top of			covered storage).						
00			operated or	the grey carts and									
			maintained	cinderblocks.									
			airtuirieu	2) Box of metal ESH-17 signs									
				being stored at the SE side of									
				_									
				the storage shed.									
				3) Wooden/metal posts beng									
				stored in metal cart on the far									
				SE side of yard.		<u> </u>	1						

895 TA-3-38	3/29/16	Material	BURGIN	Control	Additional materials need to	Routine facility	-	The following items need	N		N	3/29/2016 0:00	4/6/2016 0:00 Y	Newly constructed enclosed -
Carpenter Shop		Storage Yard	JILLIAN E	measures inadequate to meet non- numeric effluent limitations	be covered or moved into enclosed storage.	inspection		to be covered or moved into enclosed storage: 1)Rusting metal ties (stored under the concrete blocks SW of the storage building) 2)Any non-galvanized metal being stored south o the storage building 3)The yellow metal ?posts? on the SW side of the storage building. They are painted but rusting in spots. 4)The form posts (?) in the uncovered cart on the far SW side of the yard (south of the new storage boxes)						wooden boxes have been made by the carpenter shop to store additional materials in the outdoor yard. The materials needing proper storage (listed above) are scheduled to be moved on Friday 4/1/16.
884 TA-3-38 Carpenter Shop	2/25/16	South Boundary at Steam Condensat Line Repair Area		Control measures not properly operated or maintained	The steam condensate repair area needs to be stabilized.	Site walk down.	-	The area that was excavated to repair the steam condensate line at the southern boundary of the facility needs to be stabilized by UI. The plans are to pave the area and restore rock to the slope as needed.	N N		N	2/25/2016 0:00	3/1/2016 0:00 Y	Gravel bags have been installed - as temporary BMPs at the soil disturbance boundary.
854 TA-3-38 Carpenter Shop	11/24/15	Southern Boundary of Facility	BURGIN JILLIAN E	Unauthorized release or discharge	There is a steam condensate line leak on the southern boundary of the facility. Wate from the leak is discharging to the northern/primary storm drain (Outfall #74) of the parking lot, which is within the MSGP site boundary.		Leak was identified (for repair) by EX-ID request.	Gravel bags have been placed around the area where the leak is originating to prevent erosion and sediment transport onto the MSGP site.	N	-	N	11/24/2015 0:00	12/23/2015 0:00 Y	The leak is in the process of being repaired. A 7 & 15 day release report has been completed by ENV-CP to LANL and NMED. The area has been fenced off for safety. Repairs were completed on 12/23/15.
848 TA-3-38 Carpenter Shop	11/24/15	Material Storage Area	BURGIN JILLIAN E	Control measures not properly operated or maintained	The tarps covering the material storage racks have come loose in recent storm events.	Routine facility inspection	-	Resecure tarps to adequately cover the material storage racks.	N		N	11/24/2015 0:00	12/8/2015 0:00 Y	The tarps are scheduled to be resecured on 12/7/15 when crews can be available to perform the work. A meeting to discuss future compliance options for this issue is scheduled for 11/30/15. Salvaging of some of the materials is also in process of being scheduled. 12/08/15: It has been determined by LOG-CS staff that tarps are not feasible BMPs to cover the material storage racks. Much of the material is in the process of being salvaged and the remaining racks will be painted with rustoleum and fabricated with covers.

CERTIFICATION FOR CORRECTIVE ACTIONS

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Printed Nan	ne: Russell Ston	<u>e</u>	Title:	UI ESH Manager 4
Signature:	Russell Stone	Digitally signed by Russell Stone DN: cn=Russell Stone, o=DSESH-UI, ou=ADESH, email=rdstone@lanl.gov, c=US Date: 2018.02.09 10:19:05 -07'00'	_ Date: _	

CAR # MSGP Facility Ins Desc	spection Date Specific Inspector Location Name	Finding Finding Other	Troblem Sescription inspection in	spection Corrective Action Description rpe Other	SIO SIO	Provide Action Taken at Swp; cted Affected SIOs Mod		CA Complete Date Completed CA Da		CA Status Desc	EPA Notified (Finding Finding modified modified date
1398 TA-3-38 Carpenter Shop	10/2/2018 8:00 Outfall 073 at WHEELER the TA-3-38 HOLLY L Carpenter Shop	Desc Impaired water - quality exceedance	Discharge from outfall 073 at the TA-3-38 Impaired Carpenter Shop exceeded the New Mexico waters water quality standard for total monitoring recoverable Aluminum discharged during the storm event on 8/16/2018 was 1090 ug/l and the water quality standard is 681 ug/l.	Personnel shall evaluate potential pollutant sources of total recoverable Aluminum and implement additional controls to ensure discharge of this pollutant source in stormwater is minimized.	Y	74 Since outfall 073 is associated Y with substantially identical outfall (50) 074, facility personnel must also assess the need for corrective action at outfall 074 and document how the corrective action was appropriate for both, document why the exceedance would not affect this outfall, or document additional corrective action taken specific to this outfall. Changing out Mettalox Wattle and sweeping around wood bin is an applicable BMP for both outfalls.	10/3/2018 13:0	0 10/12/2018 15:00 Y -	r a c s s	Facility personnel shall evaluate potential pollutant sources of total recoverable Aluminum and implemen additional controls to ensure discharge of this pollutant source in stormwater is minimized. Evaluated site on 10/3/18 and requested Metallow. Wattle be changed out and area swept around wood shavings bin Work was completed by Roads & Grounds on 10/12/18.		118432 10/2/201816.29	118432 10/2/2018 16:29	оу 211081 <i>ининининини</i>
1388 TA-3-38 Carpenter Shop	8/30/2018 16:18 Outfall 073 at WHEELER the TA-3-38 HOLLY L Carpenter Shop	Impaired water - quality exceedance	Discharge from outfall 073 at the TA-3-38 Impaired Carpenter Shop exceeded the New Mexico waters water quality standard for dissolved monitoring Copper. The concentration of dissolved topper discharged during the storm event on 7/17/2018 was 17.1 ug/L and the water quality standard is 6 ug/L.	Personnel shall evaluate potential pollutant sources of dissolved Copper and implement additional controls to ensure discharge of this pollutant source in stormwater is minimized. Facility personnel must immediately take action to minimize off site discharge of dissolved Copper at outfall 073. *Sweeping of the west lot at 5M-38 Carpenter's Shop was performed on 7/30/18 which post dates this exceedance.		74 Since outfall 073 is associated Y with substantially identical outfall (50) 074, facility personnel must also assess the need for corrective action at outfall 074 and document how the corrective action was appropriate for both, document why the exceedance would not affect this outfall, or document additional corrective action at then specific to this outfall. "Sweeping of the west lot includes the area around Outfall 074 as well as 073.	8/31/2018 8:0	00 8/31/2018 9:00 Y -	F C C S S F F E C C C S S S T F C C C C C C C C C C C C C C C C C C	Facility personnel shall evaluate potential pollutant sources of dissolved Copper and implement additional controls to ensure discharge of this pollutant source in stormwater is minimized. If inalization of corrective action(s) exceeds 14 days, documentation of why it is infeasible to complete the corrective action within the 14 day timeframe must be provided along with a schedule for completion. SWPPP modifications required as a result of this exceedance, if needed, must be implemented within 14 days of completing corrective action work.		118432 8/30/201817:53	118432 8/30/2018 17:53	211081 9/6/2018 9:51
1331 TA-3-38 Carpenter Shop	4/26/2018 15:00 Metal Storage BURGIN Yard JILLIAN E	Control - measures not properly operated or maintained	Metal posts are uncovered at SW corner of Routine - yard and a bundle of rebar is on the facility ground.	Properly cover/store metal materials.	N -	- N	-	5/15/2018 13:00 Y -	ş Ç	Reported to facility personnel the same day of inspection. The shop is planning to make a covered storage container for the posts. They retarped the posts in the meantime.		211081 4/26/2018 16:53	211081 4/26/2018 16:53	211081 5/16/2018 11:50
1298 TA-3-38 Carpenter Shop	1/31/2018 13:30 Southwest BURGIN Corner of JILLIAN E Storage Yard	Control - measures not properly operated or maintained	Tarp was totally torn off of the stack of Routine metal posts at the southwest corner of the facility storage yard.	Cover metal posts.	N -	- N	2/1/2018 8:0	00 2/1/2018 16:00 Y -		CAR reported at time of inspection. The posts were recovered on 2/1/18.	-	211081 1/31/2018 16:32	211081 1/31/2018 16:32	211081 2/6/2018 15:58

CERTIFICATION FOR CORRECTIVE ACTIONS

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Printed Name: Russell Stone	Title: GC OCSH-UIS
Signature: Swall to	Date:

Appendix K

Critical Habitat Documentation for LANL

K-1, Threatened and Endangered Species Habitat Management Plan (HMP) for LANL

K-2, U.S. Fish & Wildlife Concurrence (Biological Assessment of Jemez Mtn Salamander Site Plan)

K-3, TA-3 and TA-60 IPac Trust Resource Report

K-1, Threatened and Endangered Species Habitat Management Plan (HMP) for LANL

LA-UR-14-21863 Approved for public release; distribution is unlimited.

Title: Threatened and Endangered Species
Habitat Management Plan for
Los Alamos National Laboratory

Author(s): Environmental Protection Division

Resources Management Team

Intended for: Reference purposes

Date: March 2014



Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the Los Alamos National Security, LLC for the National Nuclear Security Administration of the U.S. Department of Energy under contract DE-AC52-06NA25396. By acceptance of this article, the publisher recognizes that the U.S. Government retains a nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

Contents

A (CRONY	'MS	vii
I.		CATENED AND ENDANGERED SPECIES HABITAT MANAGEMENT PLAN CRAL OVERVIEW	1
	1.0 I	NTRODUCTION	1
	2.0 I	ROLE OF SITE PLANS IN THE HMP	1
	3.0 I	DESCRIPTION OF AREAS OF ENVIRONMENTAL INTEREST	1
	3.1	Definition and Role of Developed Areas in AEI Management	1
	3.2	General Description of Buffer Areas and Allowable Buffer Area Development	2
	3.3	Emergency Actions	3
	4.0	MPLEMENTATION OF SITE PLANS	3
	4.1	Roles and Responsibilities	3
	4.2	If an Activity Does Not Meet Site Plan Guidelines	4
	4.3	Dissemination of Information	5
	5.0	CHANGES IN THE HMP SINCE IMPLEMENTION	5
	6.0 I	DATA MANAGEMENT	5
II.		OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE MEXICAN SPOTTE	
		SPECIES DESCRIPTION—MEXICAN SPOTTED OWL	
	1.1	Status	
	1.2	General Biology	
	1.3	Threats	
		MPACT OF HUMAN ACTIVITIES	
	2.1	Introduction	
	2.2	Impacts on Habitat Quality	
		2.2.1 Development	
		2.2.2 Ecological Risk 2.2.3 Disturbance	
		2.2.3.1 Pedestrians and Vehicles	
		2.2.3.2 Aircraft	
		2.2.3.3 Explosives	
		2.2.3.4 Other Sources of Noise	
	3.0	AEI GENERAL DESCRIPTION FOR MEXICAN SPOTTED OWL	
	3.1	Method for Identifying a Mexican Spotted Owl AEI	12
	3.2	Location and Number of Mexican Spotted Owl AEIs	12
	4.0	AEI MANAGEMENT	12
	4.1	Overview	12
	4.2	Definition and Role of Occupancy in AEI Management	13

Threatened and Endangered Species Habitat Management Plan

4.3	Introduction to AEI Management Guidelines	13
4.4	Definition of and Restrictions on Habitat Alterations	14
	4.4.1 Definition of Habitat Alterations	14
	4.4.2 Fuels Management Practices to Reduce Wildfire Risk	14
	4.4.3 Utility Corridors	15
	4.4.4 Restrictions on Habitat Alterations	15
4.5	Definition of and Restrictions on Disturbance Activities	15
	4.5.1 Definitions of Disturbance Activities	
	4.5.2 Activity Table	
4.6		
5.0	LEVELS OF DEVELOPMENT IN AEI CORE AND BUFFERS	
5.1	Allowable Habitat Alteration in the Buffer Areas	19
	A OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE SOUTHWESTERN	
	LOW FLYCATCHER	
	SPECIES DESCRIPTION—SOUTHWESTERN WILLOW FLYCATCHER	
1.1	Status	
1.2	General Biology	
1.3	Threats	
2.0	IMPACT OF HUMAN ACTIVITIES	
2.1	Introduction	21
2.2	Impacts on Habitat Quality	21
	2.2.1 Development	21
	2.2.2 Ecological Risk	22
	2.2.2.1 Ecorisk Assessment	
	2.2.3 Disturbance	
	2.2.3.1 Pedestrians and Vehicles	
	2.2.3.3 Explosives	
	2.2.3.4 Other Sources of Noise	23
2.0	2.2.3.5 Artificially Produced LightAEI GENERAL DESCRIPTION FOR SOUTHWESTERN WILLOW FLYCATCHER	
3.1	Method for Identifying the Southwestern Willow Flycatcher AEI	
3.2	Location of the Southwestern Willow Flycatcher AEI	
	AEI MANAGEMENT	
4.1	Overview	
4.2	Definition and Role of Occupancy in AEI Management	
4.3	Introduction to AEI Management Guidelines	
4.4	Definition of and Restrictions on Habitat Alterations	
	4.4.1 Definition of Habitat Alterations	
	4.4.2 Fuels Management Practices to Reduce Wildfire Risk	2.5

Threatened and Endangered Species Habitat Management Plan

	4.4.3 Utility Corridors	25
	4.4.4 Restrictions on Habitat Alterations	26
4.	5 Definition of and Restrictions on Disturbance Activities	26
	4.5.1 Definition of Disturbance Activities	26
	4.5.2 Activity Table	27
4.	6 Protective Measures	28
5.0	SOUTHWESTERN WILLOW FLYCATCHER AEI DESCRIPTION	29
5.	1 Pajarito Canyon Southwestern Willow Flycatcher AEI	29
	5.1.1 Allowable Habitat Alteration in the Buffer Area	29
	EA OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE JEMEZ MOUNT	
	AMANDER	
1.0	SPECIES DESCRIPTION—JEMEZ MOUNTAINS SALAMANDER	
1.		
1.	<i>E</i> ,	
1.		
2.0	IMPACT OF HUMAN ACTIVITIES	
2.		
2.	2 Impacts on Habitat Quality	30
	2.2.1 Development	
	2.2.2 Pedestrians and Vehicles	
2	2.2.3 Severe Wildland Fire and Wildfire Suppression	
2.	r	31
	2.3.1 Disease 31	2.1
3.0	2.3.2 Destruction of Individual Salamanders	
3.0		
3.		
4.0	AEI MANAGEMENT	
4.0		
4.	1 2	
4.		
4.	1	
4.		
4.		
4.		
	4.7.1 Definition of Habitat Alterations	
	4.7.2 Fuels Management Practices to Reduce Wildfire Risk	
	4.7.3 Utility Corridors	
	T. /.T INCSUICTIONS ON TRADITAL ANCIALIONS	

Threatened and Endangered Species Habitat Management Plan

	CES CITED36
APPENDIX	K41
Figure	
Figure 1. P	rocess flowchart for determining site plan requirements
Tables	
Table 1.	Restrictions on Activities in Undeveloped Occupied Mexican Spotted Owl AEIs 18
Table 2.	Restrictions on Activities in Undeveloped Occupied Southwestern Willow Flycatcher AEI
Table A-1.	The percentage of each food type found in Mexican Spotted Owl food remains at LANL
Table A-2.	Preliminary light measurements in ftc for Mexican Spotted Owl site plan

ACRONYMS

AEI Area of Environmental Interest

BA biological assessment

Bd Batrachochytrium dendrobatidis

BSL-3 Biosafety Level 3

COPCs chemicals of potential concern

DARHT Dual-Axis Radiographic Hydrodynamic Test (Facility)

dB Decibel

DDT (dichloro-diphenyl-trichloroethane)

DOE U.S. Department of Energy

EPA Environmental Protection Agency

ESA Endangered Species Act of 1973

fc foot candles

FR Federal Register

GIS geographic information system

HMP Threatened and Endangered Species Habitat Management Plan

HVAC heating, ventilation, and air conditioning

LANL Los Alamos National Laboratory

NEPA National Environmental Policy Act

NMED New Mexico Environment Department

NPDES National Pollutant Discharge Eliminations System

PCBs polychlorinated biphenyls

PR-ID Permits and Requirements Identification

SME subject matter expert

USFWS U.S. Fish and Wildlife Service

I. THREATENED AND ENDANGERED SPECIES HABITAT MANAGEMENT PLAN GENERAL OVERVIEW

1.0 INTRODUCTION

Los Alamos National Laboratory's (LANL) Threatened and Endangered Species Habitat Management Plan (HMP) was prepared to fulfill a commitment made in the U.S. Department of Energy's (DOE) "Final Environmental Impact Statement for the Dual-Axis Radiographic Hydrodynamic Test Facility Mitigation Action Plan" (DOE 1996). The HMP received concurrence from the U.S. Fish and Wildlife Service (USFWS) in 1999 (USFWS consultation numbers 2-22-98-I-336 and 2-22-95-I-108). In this 2014 update, we retained the management guidelines from the 1999 HMP for listed species, updated some descriptive information, and added the Jemez Mountains salamander (*Plethodon neomexicanus*), which was federally listed in September 2013 (USFWS consultation number 02ENNM00-2014-I-0014).

2.0 ROLE OF SITE PLANS IN THE HMP

The purpose of the HMP is to provide a management strategy for the protection of threatened and endangered species and their habitats on LANL property. The HMP consists of site plans for federally listed threatened or endangered species with a moderate or high probability of occurring at LANL. The following federally listed threatened or endangered species currently have site plans at LANL: Mexican Spotted Owl (*Strix occidentalis lucida*), Southwestern Willow Flycatcher (*Empidonax trailii extimus*), and the Jemez Mountains salamander. Site plans provide guidance to ensure that LANL operations do not adversely affect threatened or endangered species or their habitats.

3.0 DESCRIPTION OF AREAS OF ENVIRONMENTAL INTEREST

Suitable habitats for federally listed threatened and endangered species have been designated as Areas of Environmental Interest (AEIs). AEIs are geographical units at LANL that are managed for the protection of federally listed species and consist of core habitat areas and buffer areas. The purpose of the core habitat is to protect areas essential for the existence of the specific threatened or endangered species. This includes the appropriate habitat type for breeding, prey availability, and micro-climate conditions. The purpose of buffer areas is to protect core areas from undue disturbance and habitat degradation.

Site plans identify restrictions on activities within the AEIs. Allowable activities are activities that the USFWS has reviewed and provided concurrence that these activities are not likely to adversely affect federally listed species. Activities discussed in site plans include day-to-day activities causing disturbance (hereafter referred to as "disturbance activities"), such as access into an AEI, and long-term impacts, such as habitat alteration.

3.1 Definition and Role of Developed Areas in AEI Management

Summary: Habitat alteration is not restricted in developed areas unless it impacts undeveloped core areas of an AEI (e.g., noise and light impacts on a core area). Current ongoing disturbance activities are not restricted in developed areas. Disturbance activities not currently ongoing are

restricted when impacts occur to undeveloped core areas of an AEI that are occupied by a threatened or endangered species.

Developed areas include all building structures, paved roads, improved gravel roads, paved and unpaved parking lots, and firing sites. The extent of developed areas in each AEI was determined using two methods. First, LANL geographic information system (GIS) analysts placed a 15 m (49 ft) border around all buildings and parking lots. For paved and improved gravel roads, the developed area was defined as the area to a roadside fence, if one exists within 9 m (30 ft) of the road, or 5 m (15 ft) on each side of the road, if there is no fence within 9 m (30 ft). If an area of highly fragmented habitat was enclosed by roads, a security fence, or connected buildings, that area was also classified as developed. Developed areas at firing sites were defined as a circle with a 91-m (300-ft) radius from the most centrally located firing pad. Second, LANL GIS analysts overlaid scanned orthophotos onto a map of the Los Alamos area and digitized all areas that appeared developed. These two information sources were overlaid and combined, so that areas classified as developed by either method were considered developed in final maps and analyses. Some areas were confirmed by ground surveys, such as the firing sites. Developed areas are contained in the HMP GIS database.

Developed areas are located in the core and/or buffer of some AEIs. However, developed areas do not constitute suitable habitat for federally listed species. Current ongoing activities in developed areas constitute a baseline condition for the AEIs and are not restricted. New activities including further development within already existing developed areas are not restricted unless they impact undeveloped portions of an AEI core. For example, if light or noise from a new office building in a developed area were to raise levels in an undeveloped core area, those light and noise levels would be subject to the guidelines on habitat alterations. If a proposed action within a developed area does not meet site plan guidelines, it must be individually reviewed for compliance with the Endangered Species Act of 1973 (ESA).

Building a new structure or clearing land within a previously designated developed area in an AEI core does not add to the size of the developed area. New structures in core areas will not be given any developed-area border unless they are individually reviewed for ESA compliance.

Development occurring in the developed area in an AEI buffer can be given a 15 m (49 ft) developed-area border at the discretion of the project leader or facility manager. To expand the size of a developed area in a buffer based on new developments, please contact a LANL biological resources subject matter expert (SME) (http://int.lanl.gov/environment/bio/controls/index.shtml).

3.2 General Description of Buffer Areas and Allowable Buffer Area Development

Summary: Limited future development is allowed in the currently undeveloped DOE-controlled buffer area under the guidelines of this HMP as long as it does not alter habitat in the undeveloped AEI core (including light and noise guidelines). Development beyond the cap established for each AEI, or greater than 2 ha (5 ac) in size including the developed-area border, requires independent review for ESA compliance.

The purpose of buffer areas is to protect core areas from undue disturbance or habitat degradation. The current levels of development in buffer and core areas represent baseline conditions for this

HMP. No further development is allowed in the core area under the guidelines of this HMP. A limited amount of development is allowed in buffer areas. Under the guidelines of this HMP, individual development projects are limited to 2 ha (5 ac) in size, including a 15 m (49 ft) developed-area border around structures and a 5 m (15 ft) developed-area border around paved and improved gravel roads. Projects greater than 2 ha (5 ac) in area require individual review for ESA compliance (see exceptions for fuels management activities and utility corridor maintenance). New development projects in AEI buffer areas must be reported to LANL biological resources SMEs for tracking (http://int.lanl.gov/environment/bio/controls/index.shtml). Descriptions of each of the AEIs give the total area in each buffer area available for development.

3.3 Emergency Actions

Summary: Contact DOE and LANL biological resources SMEs as soon as possible.

If safety and/or property is immediately threatened by something occurring within an AEI (for example, wildfire, water line breakage, etc.) managers may activate emergency actions. Contact a LANL biological resources SME (http://int.lanl.gov/environment/bio/controls/index.shtml), the Environmental Stewardship Group (1-505-665-8855), or the DOE Los Alamos Field Office (Field Office; 1-505-667-6819) as soon as possible. If the emergency occurs outside of regular business hours, contact the Emergency Management Office (1-505-667-6211). This office will then communicate with the appropriate LANL and DOE Field Office personnel.

4.0 IMPLEMENTATION OF SITE PLANS

4.1 Roles and Responsibilities

Summary: LANL's facility managers and operational staff are responsible for ensuring that activities are reviewed for compliance with all applicable site plans. Figure 1 illustrates the process for utilizing site plans. If activities follow approved guidance, there is no requirement for additional ESA regulatory compliance. However, additional National Environmental Policy Act (NEPA), cultural resources, wetlands, or other regulatory compliance actions may be required.

If an activity or project occurs outside of all LANL AEIs and will not impact habitat within an AEI, it does not have to be reviewed for ESA compliance, unless it is a large project. Projects that are larger than 2 ha (5 ac) or cost more than \$5 million require an individual ESA compliance review, even if they are not located within an AEI.

LANL's facility managers are responsible for determining if operations within their geographic and/or programmatic area of responsibility comply with the guidelines in these site plans. Submission of a Permits and Requirements Identification (PR-ID) for a new or modified project is required under Program Description 400 (LANL 2013) and allows managers to identify the requirements within their project area. Deployed environmental professionals and core LANL biological resources SMEs are available to support facility managers. If activities follow site plan guidelines, they do not require any additional ESA regulatory compliance action. However, NEPA, cultural resources, wetlands, or other regulatory compliance actions are not addressed in site plans and additional compliance actions may be required. It is the responsibility of the project leader or facility management staff to ensure that all requirements are satisfied. If you have

questions, contact biological, cultural, NEPA, or other environmental SMEs. Contacts can be found at http://int.lanl.gov/environment/compliance/ier/index.shtml.

A single facility may have one or more AEIs within its boundary and the AEIs may be for different species. Some AEIs overlap. In areas where overlap occurs, project managers must follow the guidelines for AEIs of all involved species.




Figure 1. Process flowchart for determining site plan requirements.

4.2 If an Activity Does Not Meet Site Plan Guidelines

Summary: Activities or projects that do not meet all applicable site plan guidelines must be evaluated individually for compliance with the ESA.

If a project reviewer determines that an activity or project cannot meet the guidelines in applicable site plans, LANL biological resources SMEs evaluate that activity individually for compliance with the ESA. Results of the evaluation of potential impacts allow LANL biological resources SMEs to make recommendations to the DOE Field Office Biological Resources Program Manager

regarding the need for USFWS consultation. An evaluation may result in 1) a DOE Field Office determination that there is no possibility of adverse effects and the activity can proceed, 2) a DOE Field Office suggestion for modifications of the action to avoid adverse effects so that it can proceed, or 3) a DOE Field Office decision to prepare a biological assessment (BA) for the activity and submit it to the USFWS for concurrence. Fieldwork and preparation of a BA can take a few months with an additional 2 to 12 months for DOE Field Office review and then final USFWS concurrence.

4.3 Dissemination of Information

Although information about threatened and endangered species is not classified, it is considered sensitive information. It is in the best interest of threatened and endangered species to restrict specific knowledge about their locations. Habitat locations of threatened and endangered species are not considered sensitive.

5.0 CHANGES IN THE HMP SINCE IMPLEMENTION

The HMP received concurrence from USFWS and was first implemented in 1999. Since that time, both the Peregrine Falcon (*Falco peregrinus*) and the Bald Eagle (*Haliaeetus leucocephalus*) have been delisted. Site plans for those species have been removed from LANL's HMP. Both species are protected at LANL under the Migratory Bird Treaty Act, and the Bald Eagle is also protected under the Bald and Golden Eagle Protection Act.

The black-footed ferret (*Mustela nigripes*) is federally listed as endangered. However, no sightings of black-footed ferrets have been reported in Los Alamos County for more than 50 years. In addition, no large prairie dog towns, which are prime habitat for black-footed ferrets, have been observed on DOE property around LANL. Therefore, there is no site plan for this species.

In 2005, the USFWS concurred with DOE's proposal for new Mexican Spotted Owl habitat boundaries based on a revised analysis of Mexican Spotted Owl habitat quality within DOE property around LANL (USFWS consultation number22420-2006-I-0010).

In 2012, the USFWS concurred with DOE's proposal to modify the habitat boundaries for the Los Alamos Canyon Mexican Spotted Owl AEI due to changes from the fire response activities after the Las Conchas wildfire (USFWS consultation number 02ENNM00-2012-IE-0088).

In 2013, the USFWS concurred with the DOE's new site plan for the Jemez Mountains salamander and its addition to LANL's HMP (USFWS consultation number 02ENNM00-2014-I-0014).

6.0 DATA MANAGEMENT

The data used in the implementation of the HMP is stored in a GIS database at LANL.

II. AREA OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE MEXICAN SPOTTED OWL

1.0 SPECIES DESCRIPTION—MEXICAN SPOTTED OWL

1.1 Status

In 1993, the USFWS determined the Mexican Spotted Owl to be a threatened species under the authority of the ESA, as amended (58 Federal Register [FR] 14248). In 1995, the USFWS released its final recovery plan for the owl (USFWS 1995), which was revised in 2012 (USFWS 2012). The USFWS most recently designated critical habitat for Mexican Spotted Owl in 2004 (69 FR 53181).

1.2 General Biology

The Mexican Spotted Owl is found in northern Arizona, southeastern Utah, and southwestern Colorado south through New Mexico, west Texas, and into Mexico. It is the only subspecies of Spotted Owl recognized in New Mexico (USFWS 1995).

The Mexican Spotted Owl generally inhabits mixed conifer and ponderosa pine (*Pinus ponderosa*; Lawson & C. Lawson) - Gambel oak (*Quercus gambelli*; Nutt.) forests in mountains and canyons. High canopy closure, high stand diversity, multilayered canopy resulting from an uneven-aged stand, large, mature trees, downed logs, snags, and stand decadence as indicated by the presence of mistletoe are characteristic of Mexican Spotted Owl habitat. Some owls have been found in second-growth forests (i.e., younger forests that have been logged); however, these areas were found to contain characteristics typical of old-growth forests. Mexican Spotted Owls in the Jemez Mountains seem to prefer cliff faces in canyons for their nest sites (Johnson and Johnson 1985). The recovery plan for the Mexican Spotted Owl recommends that mixed conifer and pine-oak woodland types on slopes greater than 40 percent be protected for the conservation of this owl.

A mated pair of adult Spotted Owls may use the same home range and general nesting areas throughout their lives. A pair of owls requires approximately 800 ha (1,976 ac) of suitable nesting and foraging habitat to ensure reproductive success. Incubation is carried out by the female. The incubation period is approximately 30 days, and most eggs hatch by the end of May. Most owlets fledge in June, 34 to 36 days after hatching (USFWS 1995). The owlets are "semi-independent" by late August or early September, although juvenile begging calls have been heard as late as September 30. Young are fully independent by early October. The non-breeding season runs from September 1 through February 28. Although seasonal movements vary among owls, most adults remain within their summer home ranges throughout the year.

The diet of Mexican Spotted Owls nesting in canyons consists primarily of woodrats (*Neotoma* spp.) and mice (*Peromyscus* spp.) with lesser amounts of rabbits, birds, reptiles, and arthropods (Willey 2013). The relative abundance of prey types in Mexican Spotted Owl pellets collected at LANL are listed in Table A-1 in the Appendix. Ganey and Balda (1994) found core areas of individuals (i.e., where owls spent 60 percent of their time) averaged 134 ha (331 ac), and core areas for pairs averaged 160 ha (395 ac).

1.3 Threats

The Mexican Spotted Owl was listed as threatened because of destruction and modification of habitat caused by timber harvest and fires, increased predation on owls associated with habitat fragmentation, and a lack of adequate protective regulations.

2.0 IMPACT OF HUMAN ACTIVITIES

2.1 Introduction

The primary threats to Mexican Spotted Owls on DOE property around LANL property are 1) impacts to habitat quality from LANL operations and 2) disturbance of nesting owls. This section provides a review and summary of scientific knowledge of the effects of various types of human activities on the Mexican Spotted Owl and provides an overview of the current levels of activities at LANL.

2.2 Impacts on Habitat Quality

2.2.1 Development

The type of habitat used by Mexican Spotted Owls, late seral stage forests with large trees, are usually not found in large quantities near developed areas or near areas that have had recent agricultural or forest product extraction land uses. Therefore, Mexican Spotted Owls are generally not found near developments. Whether it is the development itself or a lack of suitable habitat that discourages colonization of these areas by Mexican Spotted Owls is unknown.

Areas of LANL vary from remote undeveloped areas to heavily developed and/or industrialized facilities. Most LANL facilities are situated atop mesas, primarily in the northern and western portion of the DOE property. LANL is bounded by developed residential, industrial, and retail areas along its northern boundary (the town of Los Alamos) and by residential and retail development along a portion of its eastern boundary (the town of White Rock). Three major paved roads traverse LANL from northeast to southwest. Sandia, Pajarito, and Los Alamos canyons have paved roads within AEIs, and several AEIs have dirt roads along at least a portion of the canyon bottom. AEIs containing paved or dirt roads in the canyon bottoms have not been occupied at LANL (Hathcock et al. 2010).

2.2.2 Ecological Risk

There is no specific information on the impact of chemicals on the Mexican Spotted Owl, although experience with other raptor species suggests that exposure to polychlorinated biphenyls (PCBs), dichloro-diphenyl-trichloroethane (DDT) and its derivatives, and other organophosphate or organochlorine pesticides would probably be harmful. Exposure to other chemicals could also be harmful (Cain 1988).

LANL completed three ecological risk assessments that included the Mexican Spotted Owl between 1997 and 2009. The ecological risk assessment process involves using computer modeling to assess potential effects to animals from chemicals of potential concern (COPCs) that have been detected in the environment. All of the following ecological risk assessments concluded that, on average, no appreciable impact is expected to Mexican Spotted Owls from COPCs (Gallegos et al. 1997; Gonzales et al. 2004; Gonzales et al. 2009).

2.2.3 Disturbance

2.2.3.1 Pedestrians and Vehicles

Based on work with other raptors, LANL biological resources SMEs assume that Mexican Spotted Owls would likely be disturbed by the approach of either pedestrians or vehicles. At an equal distance, pedestrians are frequently more disturbing to raptors than vehicles (Grubb and King 1991). Brown and Stevens (1997) reported that during surveys in Grand Canyon National Park, 22 times more Bald Eagles were found in canyon reaches with low human recreational use compared to reaches with moderate to high human recreational use. Human activity 100 m (328 ft) from Bald Eagle nests in Alaska caused clear and consistent changes in behavior of breeding eagles (Steidl and Anthony 2000).

Swarthout and Steidl (2001) found that both juvenile and adult roosting Mexican Spotted Owls were unlikely to alter their behavior in the presence of a single hiker at distances greater than 55 m (180 ft). Swarthout and Steidl (2003) concluded that cumulative effects of high levels of short-duration recreational hiking near Mexican Spotted Owl nests may be detrimental.

Many canyon bottoms and mesa tops at LANL have dirt roads traversing them. Most of these roads are gated. However, these roads are accessible to LANL employees and some of them are accessible to the public on foot or by bike. LANL biological resources SMEs have found that AEIs are occupied less often if there is recreational access into a canyon (Hathcock et al. 2010).

2.2.3.2 Aircraft

Ground-based disturbances appear to impact raptor reproductive success more than aerial disturbances (Grubb and King 1991). Grubb and Bowerman (1997) concluded that an exclusion of aircraft within 600 m (1,968 ft) of Bald Eagle nest sites would limit Bald Eagle response frequency to 19 percent.

Delaney et al. (1999) found for Mexican Spotted Owls that chainsaws consistently elicited higher response rates than helicopters at similar distances. Owl flush rates did not differ between nesting and non-nesting seasons. No owls flushed when noise stimuli (helicopter or chainsaws) were at distances greater than 105 m (344 ft). Distance was generally a better predictor of owl response to helicopter overflights than sound level.

LANL is restricted airspace, and planes infrequently fly less than 609 m (2,000 ft) above ground level. The County of Los Alamos operates an airport along the northern edge of LANL. The airport is located on the southern rim of Pueblo Canyon. Most flights approach and depart to the east of the airport, over the Rio Grande.

2.2.3.3 Explosives

There is no specific information on the reaction of Mexican Spotted Owls to explosives detonation currently available. Explosive blasts set off 120 to 140 m (393 to 459 ft) from active Prairie Falcon (*Falco mexicanus*) nests caused perched Prairie Falcons to flush from perches 79 percent of the time, and, in 26 percent of the cases, caused incubating Prairie Falcons to flush from nests. Measured sound levels at aerie entrances during blasts ranged from 129 to 141 decibel (dB) (Holthuijzen et al. 1990). Explosives blasting for dam construction 560 to 1,000 m (1,837 to 3,280 ft) from active Prairie Falcon nests caused a change in behavior 26 percent of the time, and

birds flushed in 17 percent of all cases. No incubating birds flushed (Holthuijzen et al. 1990). Brown et al. (1999) found little activity change in roosting or nesting Bald Eagles and no population-level impacts from weapons detonations at the Aberdeen Proving Ground. Holthuijzen et al. (1990) found that a 167-g (5.89-oz) charge of Kinestik produced noise levels between 138 and 141 dB at 100 m (328 ft), and that a 500-g (17.6-oz) charge of TNT produced noise levels between 144 and 146 dB at 100 m (328 ft). A 20-kg (44-lb) charge of TNT produced noise levels that measured 163 dB at 100 m (328 ft) (Paakkonen 1991).

Measurements of noise levels during explosives testing were conducted at three locations at LANL using quantities of high explosives ranging from 4.5 to 67.5 kg (10 to 148 lb) of TNT during six shots. Noise levels increased during the test from a background level of 31 dB(A)¹ to a range between 64 and 71 dB(A) during shots at a distance of 1.8 km (1.1 mi). At a distance of 4.3 km (2.67 mi), noise levels rose from a background range of 35 to 64 dB(A) to a range of 60 to 63 dB(A) (Vigil 1995). At a distance of 6.7 km (4.16 mi), noise levels rose from a background range of 38 to 51 dB(A) to a range of 60 to 71 dB(A) (Burns 1995). LANL biological resources SMEs estimated that the noise from a shot at the Dual-Axis Radiographic Hydrodynamic Test (DARHT) Facility would be 150 dB(A) at the source and 80 dB(A) at 400 m (1,312 ft) (Keller and Risberg 1995). LANL biological resources SMEs found that Mexican Spotted Owl AEIs located within the explosives testing buffer area were occupied more frequently than AEIs in other locations (Hathcock et al. 2010). This is likely due to the strict access control in explosives areas which limit human activity and development in the canyon bottoms.

2.2.3.4 Other Sources of Noise

Major noise-producing activities at LANL include automobile and truck traffic and noise associated with office buildings, construction activities, a live-fire range, and explosives testing. Also, there is noise associated with aircraft traffic at the Los Alamos County airport. Construction and maintenance activities involved with operations at LANL are fairly common. In addition, implementation of the 2005 Compliance Order on Consent (NMED 2005) issued by the New Mexico Environmental Department (NMED) has resulted in an increased frequency of drilling groundwater monitoring wells in protected habitat at LANL. Also, forest fuels management operations use chainsaws, chippers, and other noise-generating equipment. The 2010 National Pollutant Discharge Elimination System (NPDES) Individual Permit (EPA 2010) issued by the Environmental Protection Agency (EPA) requires sediment control features such as berms and small rock check dams to be installed at various sites with stormwater runoff; these are sometimes installed in protected habitat. LANL biological resources SMEs conducted a study of noise levels in canyons and found that the primary sources of noise exceeding 55 dB(A) were cars and trucks. Readings taken near flowing water were up to 11 dB(A) higher than readings taken elsewhere. The average dB(A) in canyons near paved roads ranged from 41 to 62, with maximum values ranging from 62 to 74. Away from paved roads 1.6 km (1 mi) or more, average dB(A) in canyons ranged from 37 to 50, with all but one average below 45. Maximum dB(A) away from paved roads ranged from 38 to 76 [76 dB(A) was measured during a thunder clap] (Huchton et al. 1997).

_

¹ Sound can be measured as decibels (dB), C-weighted dB [dB(C)], or A-weighted dB [dB(A)]. The dB(A) measurement best resembles the response of the human ear by filtering out lower and higher frequency sound not normally heard by the human ear.

Noise measurements were conducted by LANL biological resources SMEs at the Los Alamos County airport and in Bayo and Pueblo canyons, including the Los Alamos County Sewage Treatment Facility, in December 1997. Sound levels near the airport runway during the maximum use time (6:30 to 7:30 am) had background values averaging 54 dB(A). Noise during plane arrivals ranged from 47 to 63 dB(A). No measurements were collected during plane take-off. Sound measurements conducted in the bottoms of Pueblo and Bayo canyons ranged from 37 to 40 dB(A) in most areas of the canyon. At the sewage treatment facility parking lot during a working day, the average dB(A) during a three-minute period was 46 (range 45 to 49). At the intersection of the road going into Pueblo Canyon with State Road 502, the average dB(A) during a three-minute period was 60 (range 41 to 70).

LANL biological resources SMEs conducted sound measurements at successive distances from an industrial area near a canyon rim, into the canyon, and to the opposite rim, using a C-weighted decibel scale (Keller and Foxx 1997). Measurements of noise levels using the C-weighted decibel scale are greater than if measured using A-weighted decibels. The average background noise on the mesa was 65.8 dB(C) [with a range of 43–81 dB(C)]. The average background noise in the canyon bottom was 62.3 dB(C) [with a range of 54–78 dB(C)]. The average background noise at the bottom of the north-facing slope was 53.8 dB(C) [with a range of 48–64 dB(C)]. Measurements were taken mid-day.

LANL biological resources SMEs measured sound levels from various pieces of construction equipment used at project sites at LANL over 5-minute intervals at distances of 6 to 31 m (20 to 100 ft) (Knight and Vrooman 1999). Average values ranged from 58.5 dB(A) to 80.9 dB(A). Peak values ranged from 75.7 to 155.4 dB(A). Additional data were collected by other LANL operators on specific pieces of construction equipment and on the Security Computer Complex construction site fence perimeter at Technical Area 3 before and during construction (Knight and Vrooman 1999). The average noise levels before construction began was 56.6 dB(A), and the average during construction was 82.1 dB(A).

LANL biological resources SMEs conducted a series of sound measurements at LANL to investigate background noise levels around AEIs (Vrooman et al. 2000). Background noise levels were significantly higher in daytime than in nighttime. AEIs with greater than 10 percent developed area in their buffers had significantly higher levels of background noise than undeveloped AEIs. Mean background sound levels were 51.3 dB(A) in developed AEIs and 39.6 dB(A) in undeveloped AEIs. The LANL biological resources project review process uses the individual AEI background measurements from Vrooman et al. (2000) to screen project activities for increases more than 6 dB(A) above background.

LANL biological resources SMEs took sound level measurements of heavy equipment use associated with concrete recycling on Sigma Mesa at LANL in 2004 (Hansen 2004). At this location, background noise levels at two different locations were 55.2 and 58.8 dB(A). Operation of a dump truck hauling and dumping concrete increased noise levels above background by a mean of 22.7 dB(A) at 30 m (98 ft) and 2.4 dB(A) at 80 m (262 ft). Additional sound level measurements were taken in the same general area on Sigma Mesa in 2005 as part of a BA for the operation of an asphalt batch plant (Hansen 2005). Measurements were taken on the north rim of Mortandad Canyon (south of the asphalt batch plant at distances of approximately 30 to 122 m (100 to 400 ft), at the bottom of Mortandad Canyon, approximately 183 to 244 m (600 to 800 ft) from the asphalt

batch plant, and on the south rim of Mortandad Canyon approximately 305 m (1,000 ft) from the asphalt batch plant. Background noise levels at the various locations ranged from 41.1 to 48.7 dB(A). The only locations with increases greater than 3 dB(A) during operation of the asphalt batch plant were the locations on the north rim of Mortandad Canyon, within 122 m (400 ft) of the asphalt batch plant. Noise from the operation of the asphalt batch plant was not detected in the bottom of Mortandad Canyon or on the south rim.

LANL biological resources SMEs took sound level measurements around the LANL Biosafety Level 3 (BSL-3) Laboratory with the heating, ventilation, and air conditioning (HVAC) system on and with it off (Hansen 2009). The area to the north of the BSL-3 is developed, the area to the south is not. Background noise levels north of the facility ranged from 53.6 to 57.6 dB(A). Background noise levels south of the facility ranged from 41.6 to 49.7 dB(A). Noise from the HVAC system was detected at 25 m (82 ft) from the facility on both sides, but was not detected at 81 m (266 ft) on the north side, or at 107 m (351 ft) on the south side.

Overall, these studies appear to show that areas adjacent to or within developed areas or paved roads are likely to have daytime average background noise levels between 45 and 63 dB(A). Less disturbed areas are likely to have average background noise levels between 37 and 50 dB(A).

2.2.3.5 Artificially Produced Light

There is no information available on the effects of artificially produced light on Mexican Spotted Owls. Under the Los Alamos County Code, commercial site development plans are reviewed to ensure that lighting serves the intended use of the site while minimizing adverse impacts to adjacent residential property (Section 16-276). Section 16-276 of the County Code includes light source measurement limitations by zoning district. The code allows off-site light to be 0.5 foot candles (fc) in residential areas. By comparison, full moonlight measures 0.1 fc, and a crescent moon was measured at 0.01 fc. Table A-2 in the Appendix presents preliminary light measurements in fc.

Preliminary surveys were conducted for light levels within Los Alamos Canyon at the Omega Reactor (Keller and Foxx 1997). The Omega Reactor was brightly lit for purposes of security; therefore, total light intensity was greater than the average street lighting. Measurements were conducted at a light pole with an open parking lot at the reactor as the source. Trees did not obscure the area. Using the relationship of light intensity reducing as a square of the distance, calculations using the field data indicated that at 30 m (98 ft) from the source the light levels would be equivalent or nearly equivalent to full moonlight.

3.0 AEI GENERAL DESCRIPTION FOR MEXICAN SPOTTED OWL

An AEI consists of two areas—a core and a buffer. The core of the habitat is defined as suitable canyon habitat from rim to rim and 100 m (328 ft) out from the top of the canyon rim. The buffer area is 400 m (1,312 ft) wide extending outward from the edge of the core area. Although adult Mexican Spotted Owls may be found within their home range anytime throughout the year, the primary threat from disturbance to the owls is during the breeding season when owl pairs are tied to their nest sites. Therefore, management of disturbance in Mexican Spotted Owl AEIs is concentrated on the breeding season.

3.1 Method for Identifying a Mexican Spotted Owl AEI

The original location of each Mexican Spotted Owl AEI was identified using a habitat model developed by Johnson (1998) that classified nesting and roosting habitat for Mexican Spotted Owls using topographic characteristics and vegetative diversity. LANL biological resources SMEs compared the results from the Johnson (1998) model to a different model identifying slopes >40 percent in mixed conifer and ponderosa pine cover types at LANL. Areas identified from the Johnson (1998) model application to LANL that were over five contiguous 30 × 30 m (97 × 98 ft) pixels in size, were above 1,980 m (6,496 ft) in elevation, and that had mixed conifer or ponderosa pine forest cover, were considered suitable Mexican Spotted Owl habitat. Where suitable habitat was identified, AEI core area boundaries were established to include the canyons and 100 m (328 ft) outward from the canyon rims.

A new Mexican Spotted Owl habitat model was developed and refined for application on LANL following the Cerro Grande wildfire (Hathcock and Haarmann 2008). This model incorporated finer-scale vegetation characteristics into the Mexican Spotted Owl habitat quality assessment. This model was used to redelineate the boundaries of the Mexican Spotted Owl AEIs at LANL in 2005 following wildfire, drought, and a regional bark beetle outbreak (USFWS consultation number 22420-2006-I-0010).

The new core boundaries were delineated with an area approximately 0.4 km (0.25 mi) from the edge of the nearest suitable habitat, up and down canyon. Core boundaries were established along readily recognizable geologic features or anthropogenic features in the terrain wherever possible to facilitate the ease of identification of core boundaries when in the field.

3.2 Location and Number of Mexican Spotted Owl AEIs

There are currently five Mexican Spotted Owl AEIs on LANL, each encompassing one or more canyons. In general, the AEI cores are centered in canyons on the western side of LANL. The canyons with AEIs are Cañon de Valle, Water, Pajarito, Los Alamos, Sandia, Mortandad, and Three-Mile. AEI boundaries are maintained in the LANL biological resources program GIS database.

4.0 AEI MANAGEMENT

4.1 Overview

This AEI management section provides guidelines for LANL operations to reduce or eliminate the threats to Mexican Spotted Owls from 1) habitat alterations that reduce habitat quality and 2) disturbance of breeding or potentially breeding owls. Habitat alterations are considered for all AEIs and for both core and buffer areas. Disturbance activities to owls are considered only for occupied AEIs and only for impacts on core areas. Developed areas (see Part I, Section 3.1) that have ongoing baseline levels of activities and are not suitable habitat for Mexican Spotted Owls have different restrictions than undeveloped core or buffer areas. Therefore, the location of the disturbance activity within the AEI, the occupancy status of the AEI, and the type of activity all affect whether or not the activity is allowable. AEIs for different species may overlap, and an activity must meet the guidelines of all applicable site plans to be allowable.

4.2 Definition and Role of Occupancy in AEI Management

Summary: The occupancy status of an AEI affects what disturbance activities are allowable in different areas (core, buffer, developed) of the AEI. All Mexican Spotted Owl AEIs are considered occupied during March 1 through August 31 or until surveys show the AEI to be unoccupied. See the Activity Table (Table 1, Section 4.5.2) for restrictions on occupied undeveloped core and buffer areas, and Part I, Section 3.1 for restrictions on developed areas.

Occupancy simply refers to whether or not an AEI is occupied during a species' period of sensitivity. For Mexican Spotted Owls, LANL is primarily concerned with protecting the owls from disturbance during the breeding season. Because individuals may colonize suitable habitat, all Mexican Spotted Owl AEIs are treated as though they are occupied from March 1 through August 31 or until surveys show an AEI to be unoccupied. Mexican Spotted Owl surveys are conducted from late March through June. In general, surveys in areas with ongoing or proposed projects are completed by May 15. If a nest is located during surveys, then the AEI can be treated as unoccupied except for the area within a 400 m (1,312 ft) radius of the nest site. Because owls are not as sensitive to disturbance during the non-breeding season, Mexican Spotted Owl AEIs are treated as unoccupied from September 1 to February 28.

The occupancy status of an AEI affects what activities are allowable in the AEI. Although activities causing habitat alterations are restricted in all AEIs, disturbance activities are restricted only in occupied AEIs. The Activity Table (Table 1, Section 4.5.2) provides dates and levels of allowable disturbance activities within occupied Mexican Spotted Owl AEIs under the guidelines of this site plan. Contact a LANL biological resources SME to find out the current occupancy status of an AEI (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.3 Introduction to AEI Management Guidelines

Summary: The habitat alterations section and the activities section give the guidelines for habitat alteration and disturbance activities, respectively, for Mexican Spotted Owl AEIs. The flow chart (see Figure 1) provides a quick reference to determine what, if any, guidelines need to be consulted for a specific activity. Protective measures give management practices that should be applied when working or considering work in AEIs. LANL biological resources SMEs are available to answer questions and provide advice (http://int.lanl.gov/environment/bio/controls/index.shtml).

Sections 4.4 and 4.5 provide the guidelines for habitat alterations and allowable activities in AEI core and buffer areas. Section 4.4 describes what and where habitat alterations are allowed under the guidelines of this site plan. Section 4.5 describes what, when, and where disturbance activities are allowed in occupied AEIs under the guidelines of this site plan. If an activity does not meet the restrictions given in the guidelines, the activity must be individually reviewed for ESA compliance. This site plan only provides guidelines for Mexican Spotted Owl AEIs. If an activity is desired in an area with overlapping AEIs, all applicable site plans must be consulted. AEI maps show the location of all AEIs in an area. Section 4.6 describes management practices that should be applied when working or considering work in an AEI. LANL biological resources SMEs are available to answer questions and provide advice (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.4 Definition of and Restrictions on Habitat Alterations

4.4.1 Definition of Habitat Alterations

Habitat alteration includes any action that alters the soil structure, vegetative components necessary to the species, prey quality and quantity, water quality, hydrology, or noise or light levels in undeveloped areas of an AEI. Long-term means the alteration lasts for more than one year. For physical disturbances, in general, any activity that can be accomplished by one person with a hand tool is generally not considered habitat alteration; any activity that requires mechanized equipment on a landscape is habitat alteration. An actual activity may take place outside of the AEI and will be considered habitat alteration if consequences of the activity have effects inside the AEI core.

The habitat components most important to Mexican Spotted Owls include vegetative structure, food quality and quantity, and disturbance levels, including noise and light. The forest structure within a canyon designated as a Mexican Spotted Owl AEI is important because it provides roost sites and a suitable habitat for nesting and foraging. Trees along the canyon rim are used for foraging and territorial calling, and they shelter the canyon interior from light and noise disturbances.

A long-term change in light or noise levels within the undeveloped core of an AEI is considered to be a habitat alteration if it increases average noise levels by ≥ 6 dB(A) during any portion of the 24-hour day, or it increases average light levels by ≥ 0.05 fc at night. Changes in noise and light levels are measured at the core area boundary if the source is outside the core area, or at 10 m (33 ft) from the source if the source is inside the undeveloped core area. Impacts of changes in developed areas on undeveloped cores are measured at the developed area boundary if it is within the core, or at the core area boundary if the developed area is outside of the core.

4.4.2 Fuels Management Practices to Reduce Wildfire Risk

The recovery plan for the Mexican Spotted Owl lists stand-replacing wildfires as a primary threat to their habitat and encourages land managers to reduce fuel levels and abate fire risks in ways compatible with owl presence on the landscape (USFWS 1995). Within undeveloped core areas, on slopes >40 percent, in the bottoms of steep canyons, and within 30 m (100 ft) of a canyon rim, thinning of trees <22 cm (9 in) diameter at breast height, treatment of fuels, and prescribed and natural prescribed fires are allowed. Exceptions allowing trees >22 cm (9 in) to be thinned within 30 m (100 ft) of buildings are granted to protect facilities. Large logs (>30 cm [11.8 in] midpoint diameter) and snags should be retained. Thinning within core areas not meeting the characteristics listed above, and in buffer areas, may include trees of any size to achieve 8 m (25 ft) spacing between tree crowns. However, clear cutting is not allowed in undeveloped core areas.

For health and safety reasons, any trees within 30 m (100 ft) of buildings, but outside a developed area, may be thinned to achieve 8 m (25 ft) spacing between crowns. Habitat alterations including thinning are not restricted in developed areas. However, LANL biological resources SMEs encourage the retention of trees and snags along canyon rims if the rim is in a developed area. Because of the extreme fire danger associated with firing sites and the potential impact of a fire on Mexican Spotted Owl habitat, firing sites and burn areas are treated separately for the purposes of fuels management. Trees within 380 m (1,246 ft) of firing sites and burn areas in both core and

buffer areas may be thinned to a 15 m (49 ft) spacing between trees everywhere except on slopes >40 percent or in the bottoms of steep canyons. Any tree over 22 cm (9 in) diameter at breast height within 380 m (1,246 ft) of a firing site may be delimbed to a height of 2 m (6 ft) to help prevent crown fires.

In historically occupied core areas, fuels treatment may not exceed 10 percent of the undeveloped core area and is not allowed within 400 m (1,312 ft) of nesting areas. In occupied core areas, forest management activities must take place during the nonbreeding season (September 1 to February 28) (USFWS 1995). Fuels management activities that are allowable in core areas have to be reported to LANL biological resources SMEs for tracking.

4.4.3 Utility Corridors

Habitat alterations such as cutting down trees that threaten power lines are allowed within 8 m (26 ft) of either side of an existing utility line in all areas of an AEI (Trujillo and Racinez 1995). New utility lines and utility lines requiring clearance of a right-of-way greater than 16 m (52 ft) total must be individually reviewed for ESA compliance. Disturbance activities must follow the guidelines given in the Activities Table (Table 1, Section 4.5.2) for occupied AEIs.

4.4.4 Restrictions on Habitat Alterations

Summary: Habitat alterations other than fuels management practices and utility corridor maintenance are not allowed in undeveloped core areas. Habitat alterations in buffer areas are restricted to 2 ha (5 ac) per project, with a maximum cap on development in the buffer for each AEI. Habitat alterations other than fuels management and utility corridor maintenance must be reported to LANL biological resources SMEs for tracking (http://int.lanl.gov/environment/bio/controls/index.shtml).

Habitat alterations other than the fuels management practices and utility corridor maintenance described above are not allowed in undeveloped core areas under the guidelines of this site plan. If a project or activity is planned that would alter habitat in an undeveloped core area, it must be individually evaluated for ESA compliance. Habitat alterations in undeveloped buffer areas other than the fuels management activities and utility corridor maintenance described above are restricted to 2 ha (5 ac) in area per project and are subject to other restrictions including light and noise effects in the core (see Section 2.2.3). Projects in the buffer over 2 ha (5 ac) in size will require individual ESA compliance review.

Habitat alterations in a buffer area other than the fuels management and utility corridor maintenance described above must be reported to LANL's biological resources SMEs for tracking (http://int.lanl.gov/environment/bio/controls/index.shtml). There is a cumulative maximum area that can be developed in each AEI's buffer. Once that cumulative area is reached, all habitat alterations in a buffer will require individual ESA reviews for compliance.

4.5 Definition of and Restrictions on Disturbance Activities

4.5.1 Definitions of Disturbance Activities

LANL biological resources SMEs considered six categories of activities that might cause disturbance in an AEI. Most of the categories were first identified in the document "Peregrine

Falcon Habitat Management in the National Forests of New Mexico," prepared for the United States Forest Service (Johnson 1994). LANL biological resources SMEs added explosives detonation, other light production, and other noise production to provide the most comprehensive list of activities possible, thereby reducing the need for individual review of activities for ESA compliance. The categories of activities are people, vehicles, aircraft, other light production, other noise production, and explosives detonation. LANL biological resources SMEs have defined low, medium, and high levels of impact for these activities except for explosives detonation. Activity levels for explosives detonation have been designed to follow the guidelines agreed upon by LANL, DOE, and USFWS in the DARHT BA (Keller and Risberg 1995). Restrictions on explosives detonation are described in the definition of the activity, but are not included in the Activity Table (Table 1, Section 4.5.2). These six categories of activities are restricted only in AEIs that are classified as occupied.

People—includes any entry of people into an AEI on foot.

- Low impact is the presence of three or fewer people per project and duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of people or the duration criteria.
- High impact is the exceedance of both the number of people and the duration criteria.

Vehicles—includes the entry of any two-axle highway vehicle, all-terrain vehicle, or motorized machinery into an AEI by any route other than a paved road or an improved gravel road.

- Low impact is the presence of two or fewer vehicles per project and duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of vehicles or the duration criteria.
- High impact is the exceedance of both the number of vehicles and the duration criteria.

Aircraft—includes the operation of any aircraft below an elevation of 600 m (2,000 ft) above the highest ground level in the local vicinity.

- Low impact is the presence of one single-engine airplane and the duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of aircraft or the duration criteria.
- High impact is the exceedance of both the number of aircraft and the duration criteria.

Any use of helicopters, jet airplanes, and propeller airplanes with two or more engines is classified as medium impact or above, depending on duration.

Other Light Production—includes any activity not previously listed that causes additional light to occur in an AEI core area. For example, plans for construction of a new building at the edge of a developed area may call for lighting at night to facilitate nighttime work that impacts an undeveloped core area.

- Low impact is the increase of light intensity by ≤ 0.05 fc and a duration of one night or less per project per breeding season.
- Medium impact is the exceedance of either the intensity or duration criteria.
- High impact is the exceedance of both the intensity and duration criteria.

Measurements for increases in light are taken at the AEI core area boundary closest to the light source if the source is outside the core and at 10 m (33 ft) from the source if the source is inside the core. Light measurements for developed areas are taken at the edge of the developed area if the developed area is within an AEI core or at the closest core boundary if the developed area is outside of an AEI core.

Other Noise Production—includes any activity not previously listed except for explosives detonation that causes additional noise to occur in an AEI. For example, operation of machinery creates noise.

- Low impact is increasing noise levels in an AEI core by 6 dB(A) or less for one day or less per project per breeding season.
- Medium impact is the exceedance of either the level or the duration criteria.
- High impact is the exceedance of both the level and the duration criteria.

Measurements for increases in noise are taken at the AEI core boundary closest to the noise source if the source is outside the core and at 10 m (33 ft) from the source if the source is inside the core. Noise measurements for developed areas are taken at the edge of the developed area if the developed area is within an AEI core or at the closest core boundary if the developed area is outside of an AEI core.

Explosives Detonation—includes the use of high explosives for any purpose. LANL biological resources SMEs did not define low, medium, and high levels of this activity because of the difficulty of determining levels for a shot before actually doing the shot. For the purpose of explosives detonation near Mexican Spotted Owl AEIs, occupied habitat is defined as the area within 400 m (1,312 ft) of the current year's nest/roost sites or the previous year's nest site if a current site has not been identified. No explosives detonation will take place within 400 m (1,312 ft) of nest/roost sites in occupied habitat between March 1 and August 31. Explosives detonation at night at sites within 400 to 800 m (1,312 to 2,624 ft) of a nest site in occupied habitat is restricted to once a month from March 1 and August 31. There are no restrictions on daytime explosives testing between 400 and 800 m (1,312 to 2,624 ft). There are no restrictions between September 1 and February 28 or in unoccupied habitat. Explosives detonation adjacent to AEIs that have not previously been recorded by LANL as occupied will have no restrictions unless surveys detect Mexican Spotted Owls. Explosives tests not allowed under the guidelines of this site plan must be individually reviewed for ESA compliance.

4.5.2 Activity Table

The dates shown in the Activity Table (Table 1) are the dates between which the activity in the row is restricted under the guidelines of this site plan. All AEIs are considered occupied from March 1 to August 31 or until surveys show an AEI to be unoccupied. If owls are detected, AEIs

are considered occupied until August 31 within 400 m (1,312 ft) of the nest site. Consult with LANL biological resources SMEs to find out occupancy status of AEIs and what locations are within 400 m (1,312 ft) of nest sites (http://int.lanl.gov/environment/bio/controls/index.shtml).

Table 1. Restrictions on Activities in Undeveloped Occupied Mexican Spotted Owl AEIs

		Core	Buffer	
People				
	Low	No Restrictions*	No Restrictions	
	Medium	March 1 to August 31	No Restrictions	
	High	March 1 to August 31	No Restrictions	
Vehicles				
	Low	No Restrictions	No Restrictions	
	Medium	March 1 to August 31	No Restrictions	
	High	March 1 to August 31	No Restrictions	
Aircraft				
	Low	March 1 to August 31	No Restrictions	
	Medium	March 1 to August 31	March 1 to May 15	
	High	March 1 to August 31	March 1 to August 31	
Other Light Produc	tion			
	Low	March 1 to August 31	No Restrictions**	
	Medium	March 1 to August 31	No Restrictions**	
	High	March 1 to August 31	No Restrictions**	
Other Noise Produc	ction			
	Low	March 1 to August 31	No Restrictions**	
	Medium	March 1 to August 31	No Restrictions**	
	High	March 1 to August 31	No Restrictions**	
Explosives Detonate	ion (see text in Se	ection 4.5.1)		

^{*}Entry is restricted in core areas that are occupied within 400 m (1,312 ft) of the nest site from March 1 to August 31. If the current nest has not been located, entry is restricted within 400 m (1,312 ft) of the previous year's nest site.

4.6 Protective Measures

Summary: This section provides a list of management practices to apply in Mexican Spotted Owl AEIs.

- Timing of projects must take into account that projects in core areas or projects that violate restrictions for occupied buffer areas must stop on February 28 each year until occupancy status of the AEI is determined.
- Every reasonable effort should be made to reduce the noise from explosives testing within 800 m (2,624 ft) of occupied habitat. Methods to reduce noise could include contained shots, noise shields in the direction of AEI cores, etc. For night shots, every reasonable effort should be made to limit the amount of light directed into AEI core areas.

^{**}Noise or light production in the buffer is restricted if the activity would violate core area restrictions on noise or light.

- Put signs on dirt roads and trails leading into AEIs labeling them as restricted access areas and providing a number to contact for access restrictions.
- Keep disturbance and noise to a minimum.
- Avoid unnecessary disturbance to vegetation (e.g., excessive parking areas or equipment storage areas, off-road travel, materials storage areas, crossing of streams or washes).
- Avoid removal of vegetation along drainage systems and stream channels.
- Avoid all vegetation removals not absolutely necessary.
- Appropriate erosion and runoff controls should be employed to reduce soil loss. The controls must be put in place and periodically checked throughout the life of projects.
- All exposed soils must be revegetated as soon as feasible after construction to minimize erosion.
- In the Los Alamos Canyon AEI, development should be focused away from undeveloped areas on the western end of the AEI.

5.0 LEVELS OF DEVELOPMENT IN AEI CORE AND BUFFERS

5.1 Allowable Habitat Alteration in the Buffer Areas

The following quantifications of development and guidance for allowable habitat alteration in buffer areas were published and consulted on in the 1999 version of the HMP. Most AEIs changed in dimensions during the 2005 redelination of the habitats, and many have experienced additional development. Development in buffer habitat was not addressed during the 2005 consultation. Many projects were reviewed and received USFWS concurrence between 1999 and 2014.

LANL biological resources SMEs have provided the current development status for each of the AEIs at the end of each paragraph. The percent developed numbers were derived with the original size of the AEIs.

Cañon de Valle—In 1999, 16.3 ha (40.3 ac, 2.9 percent) of the core was developed and 52.2 ha (129 ac, 6.8 percent) of the DOE-controlled buffer was developed. For this AEI, it was recommended that only an additional 25.30 ha (62.5 ac) of the AEI buffer be developed. The 1999 HMP stated that once this cap is reached or a large-scale project is proposed, additional consultation with USFWS would be required. By 2011, 28 ha (69.2 ac) of the core and 84 ha (207.5 ac) of the buffer had been developed.

Pajarito—In 1999, there were 6.7 ha (16.5 ac, 5.5 percent) of the core developed and 75.1 ha (186.5 ac, 16.7percent) developed in the buffer. LANL biological resources SMEs recommended only an additional 35 ha (86.4 ac) of the buffer be developed before additional USFWS consultations take place. The 1999 HMP stated that once the cap is reached or a single large-scale project is proposed, additional consultation would be required. By 2011, 27 ha (66.7 ac) of the core and 89 ha (220 ac) of the buffer had been developed.

Los Alamos—In 1999, there were 77.16 ha (190 ac) of the core developed and 167.2 ha (413.1 ac) developed in the buffer. For this AEI, LANL biological resources SMEs recommended only an

additional 28.6 ha (70.6 ac, 5.9 percent) of the DOE-owned buffer be developed before additional USFWS consultations take place.

Because this AEI is so heavily developed, additional development was restricted to a few selected areas within the buffer. Development outside of these areas requires individual review for ESA compliance. A large percentage of this AEI was removed in the 2005 and 2013 BAs. By 2011, 94 ha (232.2 ac) of the core and 181 ha (447.3 ac) of the buffer had been developed.

Sandia-Mortandad—In 1999, 98.4 ha (243.2 ac) of this AEI on DOE lands were developed, including 29 ha (71.7 ac, 10.7 percent) of the core and 75.1 ha (185.6 ac, 16.7 percent) of the buffer. For this AEI, LANL biological resources SMEs recommended only an additional 38.1 ha (94.1 ac) of the buffer be developed before additional USFWS consultations take place. Once this cap is reached or a single large-scale project is proposed, additional consultation will be required. By 2011, 45 ha (111.2 ac) of the core and 83 ha (205.1 ac) of the buffer had been developed.

Three Mile—In 1999, 25.3 ha (62.5 ac) of this AEI on DOE lands were developed, including 3.8 ha (9.4 ac, 2.8percent) of the core and 21.5 ha (51.1 ac, 7.3 percent) of the buffer. For this AEI, LANL biological resources SMEs recommended only 64.3 ha (158.8 ac) additional area of buffer be developed before additional USFWS consultations take place. Once this cap is reached or a single large-scale project is proposed, additional consultation will be required. By 2011, 12 ha (29.6 ac) of the core and 37 ha (91.4 ac) of the buffer had been developed.

III. AREA OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE SOUTHWESTERN WILLOW FLYCATCHER

1.0 SPECIES DESCRIPTION—SOUTHWESTERN WILLOW FLYCATCHER

1.1 Status

In 1995, the USFWS designated the Southwestern Willow Flycatcher as a federally endangered species (60 FR 10693). The USFWS most recently designated critical habitat for the Southwestern Willow Flycatcher in 2005 (70 FR 60885). The most recent recovery plan was published for Southwestern Willow Flycatcher in 2002 (USFWS 2002).

1.2 General Biology

The Southwestern Willow Flycatcher is one of four subspecies of the Willow Flycatcher. The historic range of the Southwestern Willow Flycatcher included Arizona, California, Colorado, New Mexico, Texas, Utah, and Mexico. Currently, this flycatcher breeds in riparian habitats from southern California to Arizona and New Mexico, plus southern Colorado, Utah, Nevada, and far western Texas. In winter it is found in southern Mexico, Central America, and northern South America (USFWS 2002).

Southwestern Willow Flycatchers are present in New Mexico from early May through mid-September and breed from late May through late July (Finch and Kelly 1999; USFWS 2002; Yong and Finch 1997). The flycatcher's nesting cycle is approximately 28 days. Three or four eggs are laid at one-day intervals, and incubation begins when the clutch is complete. The female incubates eggs for approximately 12 days, and the young fledge about 13 days after hatching.

Southwestern Willow Flycatchers typically raise one brood per year (USFWS 2002). Because arrival dates vary, northbound migrant Willow Flycatchers (of all subspecies) pass through areas where Southwestern Willow Flycatchers have already begun nesting. Similarly, southbound migrants (of all subspecies) in late July and August may occur where Southwestern Willow Flycatchers are still breeding. Therefore, it is only during a short period of the breeding season (approximately June 15 through July 20) that one can assume that a Willow Flycatcher seen within Southwestern Willow Flycatcher range is probably of that subspecies (USFWS 2002).

The Southwestern Willow Flycatcher only nests along rivers, streams, and other wetlands. It is found in close association with dense stands of willows (*Salix* spp.), arrowweed (*Pluchea* spp.), buttonbush (*Cephalanthus* spp.), tamarisk (*Tamarix* spp.), Russian olive (*Eleagnus angustifolia* L.), and other riparian vegetation, often with a scattered overstory of cottonwood (*Populus* spp.) (USFWS 2002). The size of vegetation patches or habitat mosaics used by Southwestern Willow Flycatchers varies considerably and ranges from as small as 0.8 ha (1.9 ac) to several hundred hectares (Hatten and Paradzick 2003). The Southwestern Willow Flycatcher nests in thickets of trees and shrubs approximately 2 to 15 m (6 to 49 ft) tall, with a high percentage of canopy cover and dense foliage from 0 to 4 m (0 to 13 ft) above ground. Regardless of the plant species composition or height, occupied sites always have dense vegetation in the patch interior (Allison et al. 2003; USFWS 2002).

The Southwestern Willow Flycatcher is an insectivore. It forages within and occasionally above dense riparian vegetation, taking insects on the wing and gleaning them from foliage. The flycatcher's prey includes flies, bees, wasps, ants, beetles, moths, butterflies, grasshoppers, crickets, dragonflies, damselflies, and spiders (Durst et al. 2008; Wiesenborn and Heydon 2007).

1.3 Threats

The current population of Southwestern Willow Flycatchers in the United States is estimated at 1,214 territories (Durst et al. 2006). The distribution of breeding groups is highly fragmented, with groups often separated by considerable distances. This subspecies has suffered declines attributed to extensive loss of its cottonwood-willow habitat and to poor productivity resulting from brood parasitism by Brown-headed Cowbirds (*Molothrus ater*) (USFWS 2002).

2.0 IMPACT OF HUMAN ACTIVITIES

2.1 Introduction

The primary threats to the Southwestern Willow Flycatcher on LANL property are 1) impacts on habitat quality from LANL operations and 2) disturbance of nesting flycatchers. This section includes a review and summary of the known effects of various types of human activities to the Southwestern Willow Flycatcher and an overview of the current levels of activities at LANL within species habitat.

2.2 Impacts on Habitat Quality

2.2.1 Development

Throughout the Southwest, riparian habitats are rare and tend to be small and separated by vast expanses of arid lands. The Southwestern Willow Flycatcher has experienced extensive loss and

modification of its habitat resulting from urban and agricultural development, water diversion and impoundment, channelization of waterways, livestock grazing, off-road vehicle and other recreational uses, and hydrological changes resulting from these and other land uses (USFWS 2002). River and stream impoundments, groundwater pumping, and overuse of riparian areas have altered as much as 90 percent of the Southwestern Willow Flycatcher's habitat (USFWS 2002). Loss of cottonwood-willow riparian forests has had widespread impact on the distribution and abundance of bird species associated with that forest. Development itself may be tolerated if the habitat is left intact.

Because watercourses at LANL tend to be intermittent to ephemeral, riparian habitat is uncommon. There has been extensive degradation of the riparian zone along the Rio Grande caused by feral cattle grazing and flood control operations of Cochiti Lake. There are other riparian/wetland areas on LANL associated with canyon bottoms, the most significant one being Pajarito wetlands in the lower end of Pajarito Canyon. A major paved road traverses the wetlands area in Pajarito Canyon.

2.2.2 Ecological Risk

There is no specific information on the impact of chemicals on Southwestern Willow Flycatcher.

2.2.2.1 Ecorisk Assessment

LANL completed two ecological risk assessments that included the Southwestern Willow Flycatcher between 1997 and 2009. The ecological risk assessment process involves using computer modeling to assess potential effects to animals from COPCs that have been detected in the environment. The ecological risk assessments concluded that, in general, there is a small potential for effects to Southwestern Willow Flycatcher from COPCs (Gonzales et al. 1998; Gonzales et al. 2009).

An ecotoxicological risk assessment for the Southwestern Willow Flycatcher, centered on the Pajarito wetlands, found that between 7 and 16 percent of 100 hypothetical nest sites examined had hazard indices >1.0 and <10.0, depending on the foraging scenario (Gonzales et al. 1998). This indicates a small potential for impacts from chemicals. The primary chemicals driving the risk scenario were pentachlorophenol, aluminum, radium-226, calcium, and thorium-228. Aluminum, radium, and thorium are naturally occurring substances in northern New Mexico.

2.2.3 Disturbance

2.2.3.1 Pedestrians and Vehicles

There is no specific information on the reactions of Southwestern Willow Flycatchers to pedestrians and vehicles available. The recovery plan for the Southwestern Willow Flycatcher recommends providing protected areas, reducing unpredictable activities providing visual barriers, and reducing noise disturbance (USFWS 2002).

2.2.3.2 Aircraft

There is no specific information on the reaction of Southwestern Willow Flycatchers to aircraft available.

LANL lies within restricted airspace and planes infrequently fly less than 609 m (2,000 ft) above ground level. The County of Los Alamos operates an airport along the northern edge of LANL. The airport is located on the southern rim of Pueblo Canyon. Most flights approach and depart to the east of the airport, over the Rio Grande.

2.2.3.3 Explosives

There is no specific information on the reaction of Southwestern Willow Flycatchers to explosives detonation available. The Southwestern Willow Flycatcher AEI is not located close to any explosives testing sites at LANL.

2.2.3.4 Other Sources of Noise

LANL biological resources SMEs do not have good information on the effects of noise, including machinery operation, on Southwestern Willow Flycatchers. However, Southwestern Willow Flycatchers are probably not as sensitive to disturbance as some other threatened or endangered species (USFWS 2002). For a description of noise levels at LANL, see Part I, Section 2.2.3.

2.2.3.5 Artificially Produced Light

There is no information on the effects of artificially produced light on Southwestern Willow Flycatchers available. Under the Los Alamos County Code, commercial site development plans are reviewed to ensure that lighting serves the intended use of the site while minimizing adverse impacts to adjacent residential property (Section 16-276). Section 16-276 of the County Code includes light source measurement limitations by zoning district. The code allows off-site light to be 0.5 fc in residential areas. By comparison, full moonlight measures 0.1 fc, and a crescent moon was measured at 0.01 fc.

3.0 AEI GENERAL DESCRIPTION FOR SOUTHWESTERN WILLOW FLYCATCHER

The AEI consists of two types of areas—core and buffer. Core areas represent wetland areas with suitable vegetation for nesting, primarily dense willows. The buffer area is the area within 100 m (328 ft) of core areas. The Southwestern Willow Flycatcher AEI on LANL consists of two separate core areas. For purposes of this site plan, both core areas and associated buffers are considered one AEI unit.

3.1 Method for Identifying the Southwestern Willow Flycatcher AEI

The core areas were defined by the presence of riparian habitat and suitable wetland vegetation. These areas were identified in 1994 during a survey of wetlands at LANL and mapped using a global positioning system receiver. Wetlands without stands of dense willows at least 2 m (7 ft) tall and 30 m (98 ft) wide were not included in the AEI. The buffer area is the area within 100 m (328 ft) of the core areas.

3.2 Location of the Southwestern Willow Flycatcher AEI

LANL has one AEI for Southwestern Willow Flycatcher. It is composed of two core areas with associated buffers. The AEI core areas are located in the bottom of Pajarito Canyon, on the eastern side of LANL adjacent to Pajarito Road and State Road 4. The boundaries of the Southwestern

Willow Flycatcher AEI are maintained in the biological resources program GIS database at LANL.

4.0 AEI MANAGEMENT

4.1 Overview

This AEI management section provides guidelines for LANL operations to reduce or eliminate the threats to the Southwestern Willow Flycatcher from 1) habitat alterations that reduce habitat quality and 2) disturbance of breeding or potentially breeding flycatchers. Habitat alterations are considered for all AEIs and for both core and buffer areas. Disturbance activities to flycatchers are considered only for occupied AEIs and only for impacts on core areas. Developed areas (see Part I, Section 2.3) with ongoing baseline levels of activities and are not suitable habitat for Southwestern Willow Flycatchers have different restrictions than undeveloped core or buffer areas. Therefore, the location of the disturbance activity within the AEI, the occupancy status of the AEI, and the type of activity all affect whether or not the activity is allowable. AEIs for different species may overlap, and an activity must meet the guidelines of all applicable site plans to be allowable. Protective measures are described as management practices that should be followed when working in AEIs.

4.2 Definition and Role of Occupancy in AEI Management

Summary: The occupancy status of an AEI affects what disturbance activities are allowable in different areas (core, buffer, developed) of the AEI. The Southwestern Willow Flycatcher AEI is considered occupied during May 15 through September 15 or until the surveys show the AEI to be unoccupied. See the Activity Table (Table 2, Section 4.5.2) for restrictions on occupied undeveloped core and buffer areas, and Part I, Section 2.3 for restrictions on developed areas.

Occupancy simply refers to whether or not an AEI is occupied during a species' period of sensitivity. For Southwestern Willow Flycatchers, LANL biological resources SMEs are primarily concerned with protecting the birds from disturbance during the breeding season. Because individuals may colonize suitable habitat, the Southwestern Willow Flycatcher AEI is treated as though it is occupied from May 15 through September 15 or until surveys show an AEI to be unoccupied. Southwestern Willow Flycatcher surveys are conducted during May, June, and July. Because Southwestern Willow Flycatchers migrate south for the winter, the AEI is treated as unoccupied from September 16 to May 14.

The occupancy status of an AEI affects what activities are allowable in the AEI. Although activities causing habitat alterations are always restricted, disturbance activities are restricted only in occupied AEIs. Table 2 provides dates and levels of disturbance activities allowable in the occupied Southwestern Willow Flycatcher AEI under the guidelines of this site plan. The dates in Table 2 indicate the time period during which the activity is restricted. Contact a LANL biological resources SME to find out the current occupancy status of an AEI (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.3 Introduction to AEI Management Guidelines

Summary: The habitat alterations section (Section 4.4) and the activities section (Section 4.5) gives the guidelines for habitat alteration and disturbance activities, respectively, for the

Southwestern Willow Flycatcher AEI. The flow chart (see Figure 1) provides a quick reference to determine what, if any, guidelines need to be consulted for a specific activity. Protective measures give management practices that should be applied when working or considering work in AEIs. LANL biological resources SMEs are available to answer questions and provide advice (http://int.lanl.gov/environment/bio/controls/index.shtml).

Sections 4.4 and 4.5 provide the guidelines for habitat alterations and allowable activities in AEI core and buffer areas. The flow chart (see Figure 1) provides a quick reference that should be used to determine whether a project or activity will affect an AEI and what sections of the site plan need to be consulted. The section on habitat alterations (Section 4.4) describes what and where habitat alterations are allowed under the guidelines of this site plan. The section and table on allowable activities (Section 4.5 and Table 2) describe what, when, and where disturbance activities are allowed in occupied AEIs under the guidelines of this site plan. If an activity does not meet the restrictions given in the guidelines, the activity must be individually reviewed for ESA compliance. This site plan only provides guidelines for the Southwestern Willow Flycatcher AEI. If an activity is desired in an area with overlapping AEIs, all applicable site plans must be consulted. Section 4.6 describes management practices that should be applied when working or considering work in an AEI. LANL biological resources SMEs are available to help interpret site plans and answer questions (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.4 Definition of and Restrictions on Habitat Alterations

4.4.1 Definition of Habitat Alterations

Habitat alteration includes any action that alters over the long-term the soil structure, vegetative components necessary to the species, prey quality and quantity, water quality, hydrology, or noise or light levels in undeveloped areas of an AEI. Long-term means the alteration lasts for more than one year. Habitat alteration includes any activity that removes vegetative components important to the Southwestern Willow Flycatcher (primarily trees and shrubs). An actual activity may take place outside of the AEI and will be considered habitat alteration if consequences of the activity have effects inside the AEI core.

The habitat components most important to flycatchers include vegetative structure, food quality and quantity, and disturbance levels, including noise and light. The thickets of certain trees and shrubs along wetlands are important because they provide roost sites and a suitable habitat for nesting and foraging.

4.4.2 Fuels Management Practices to Reduce Wildfire Risk

Thinning within undeveloped buffer areas may include trees of any size to achieve 7.6 m (25 ft) spacing between tree crowns. However, clear cutting is not allowed in undeveloped buffer areas. No fuels management practices are allowed in core areas. Habitat alterations including thinning are not restricted in developed areas. All fuels management activities in developed and buffer areas must follow the guidelines in the Activity Table (Table 2, Section 4.5.2) if the AEI is occupied.

4.4.3 Utility Corridors

Habitat alterations such as cutting down trees that threaten power lines are allowed within 8 m (26 ft) of either side of an existing utility line in all areas of an AEI (Trujillo and Racinez 1995).

New utility lines and utility lines requiring clearance of a right-of-way greater than 16 m (52 ft) total must be individually reviewed for ESA compliance. Disturbance activities must follow the guidelines given in the Activities Table for occupied AEIs.

4.4.4 Restrictions on Habitat Alterations

Summary: Habitat alterations other than the utility corridor maintenance described above are not allowed in undeveloped core areas under the guidelines of this site plan. Habitat alteration in buffers is limited. If a project or activity is planned that would alter habitat in an undeveloped core area, it must be individually evaluated for ESA compliance. Habitat alterations in a buffer area other than fuels management activities or utility corridor maintenance must be reported to a LANL biological resources SME for tracking (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.5 Definition of and Restrictions on Disturbance Activities

4.5.1 Definition of Disturbance Activities

LANL biological resources SMEs considered five categories of activities that might cause disturbance in an AEI. Most of the categories were first identified in the document "Peregrine Falcon Habitat Management in the National Forests of New Mexico" prepared for the U.S. Forest Service (Johnson 1994). Other light production and other noise production were included to provide the most comprehensive list of activities possible, reducing the need for individual review of activities for ESA compliance. The categories of activities are people, vehicles, aircraft, other light production, and other noise production. The impact of explosives detonation on this species is not considered here because there are no explosives testing sites within 2 km (1.25 mi) of potential nesting habitat. Low, medium, and high levels of impact for these activities are considered here. The following categories of activities are restricted only in AEIs that are classified as occupied.

People—includes any entry of people into an AEI on foot.

- Low impact is the presence of three or fewer people per project and duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of people or the duration criteria.
- High impact is the exceedance of both the number of people and the duration criteria.

Vehicles—includes the entry of any two-axle highway vehicle, all-terrain vehicle, or motorized machinery into an AEI by any route other than a paved road or an improved gravel road.

- Low impact is the presence of two or fewer vehicles per project and duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of vehicles or the duration criteria.
- High impact is the exceedance of both the number of vehicles and the duration criteria.

Aircraft—includes the operation of any aircraft below an elevation of 600 m (2,000 ft) above the highest ground level in the local vicinity.

- Low impact is the presence of one single-engine airplane and duration of one day or less during a breeding season.
- Medium impact is the exceedance of either the number of aircraft or the duration criteria.
- High impact is the exceedance of both the number of aircraft and the duration criteria.

Any use of helicopters, jet airplanes, and propeller airplanes with two or more engines is classified as medium impact or above, depending on duration.

Other Light Production—includes any activity not previously listed that causes additional light to occur in an AEI core area (e.g., plans for construction of a new building at the edge of a developed area may call for lighting at night to facilitate nighttime work that impacts an undeveloped core area).

- Low impact is the increase of light intensity by up to 0.05 fc and a duration of one night or less per project per breeding season.
- Medium impact is the exceedance of either the intensity or duration criteria.
- High impact is the exceedance of both the intensity and duration criteria.

Measurements for increases in light are taken at the AEI core area boundary closest to the light source, if the source is outside the core, and at 10 m (33 ft) from the source if the source is inside the core. Light measurements for developed areas are taken at the edge of the developed area if the developed area is within an AEI core, or at the closest core boundary, if the developed area is outside of an AEI core.

Other Noise Production—includes any activity not previously listed except for explosives detonation that causes additional noise to occur in an AEI. For example, operation of machinery causes noise.

- Low impact is increasing noise levels in an AEI core by 6 dB(A) or less for one day or less per project per breeding season.
- Medium impact is the exceedance of either the level or the duration criteria.
- High impact is the exceedance of both the level and the duration criteria.

Measurements for increases in noise are taken at the AEI core boundary closest to the noise source if the source is outside the core, and at 10 m (33 ft) from the source if the source is inside the core. Noise measurements for developed areas are taken at the edge of the developed area if the developed area is within an AEI core, or at the closest core boundary if the developed area is outside of an AEI core.

4.5.2 Activity Table

Disturbance activities are of concern only when Southwestern Willow Flycatchers occupy an AEI. The AEI is always considered occupied between May 15 and September 15, or until surveys show the AEI to be unoccupied. The Southwestern Willow Flycatcher AEI is always considered unoccupied between September 16 and May 14, when flycatchers have migrated for the winter.

For occupancy status of an AEI after completion of surveys, contact a LANL biological resources SME (http://int.lanl.gov/environment/bio/controls/index.shtml).

Table 2. Restrictions on Activities in Undeveloped Occupied Southwestern Willow Flycatcher AEI

	Core	Buffer
Restrictions on Occupied Habitat		
People		
Low	No Restrictions	No Restrictions
Medium	May 15 to August 15	No Restrictions
High	May 15 to September 15	No Restrictions
Vehicles		
Low	May 15 to September 15	No Restrictions
Medium	May 15 to September 15	No Restrictions
High	May 15 to September 15	No Restrictions
Aircraft		
Low	No Restrictions	No Restrictions
Medium	May 15 to August 15	May 15 to August 15
High	May 15 to September 15	May 15 to August 15
Other Light/Noise Production		
Low	May 15 to September 15	No Restrictions*
Medium	May 15 to September 15	No Restrictions*
High	May 15 to September 15	No Restrictions*

^{*}Noise or light production in the buffer is restricted if the activity would violate core area restriction on noise or light.

4.6 Protective Measures

Summary: This section provides a list of management practices to apply in the AEI.

- No wetland vegetation will be removed outside of developed areas.
- Appropriate erosion and runoff controls should be employed to reduce soil loss.
- Avoid unnecessary disturbance to vegetation (e.g., excessive parking areas or equipment storage areas, off-road travel, materials storage areas, crossing of streams or washes).
- Avoid removal of vegetation along drainage systems and stream channels.
- Avoid all vegetation removals not absolutely necessary.
- Appropriate erosion controls must be put in place and periodically checked throughout the life of any projects.
- All exposed soils must be revegetated as soon as feasible after disturbance to minimize erosion.

5.0 SOUTHWESTERN WILLOW FLYCATCHER AEI DESCRIPTION

5.1 Pajarito Canyon Southwestern Willow Flycatcher AEI

5.1.1 Allowable Habitat Alteration in the Buffer Area

Since the purpose of the buffer area is to help maintain the core area as suitable Southwestern Willow Flycatcher habitat, habitat alteration in the buffer area will be extremely limited. There are two areas in which restrictions on habitat alteration are relaxed.

- 1. The mesa top of Mesita del Buey. This mesa top can be developed as long as restrictions on impacts to the core area are met.
- 2. Pajarito Road within the AEI. Mowing of upland vegetation is allowed up to 5 m (15 ft) from Pajarito Road, or to the fence, if the fence is within 9 m (30 ft). Vegetation must cover the roadsides to prevent sediment runoff, so mowed plants should be at least 5 cm (2 in) high. LANL biological resources SMEs encourage the growth of willow throughout the AEI—even the area along Pajarito Road—to enhance habitat. If, within this area, it is absolutely necessary to remove new willow growth (i.e., to improve visibility for human safety), LANL biological resources SMEs recommend that only willows at or above the level of the roadway surface be mowed.

IV. AREA OF ENVIRONMENTAL INTEREST SITE PLAN FOR THE JEMEZ MOUNTAINS SALAMANDER

1.0 SPECIES DESCRIPTION—JEMEZ MOUNTAINS SALAMANDER

1.1 Status

The Jemez Mountains Salamander (*Plethodon neomexicanus*) was listed in New Mexico as endangered under the Wildlife Conservation Act of New Mexico in 2006 (NMDGF 2006). In September 2012 the USFWS proposed the Jemez Mountains Salamander as endangered under the ESA (FR 2012) and the final listing as endangered was on 10 September 2013 (FR 2013a)

1.2 General Biology

The Jemez Mountains Salamander is endemic to the Jemez Mountains of north-central New Mexico and is found in Los Alamos, Rio Arriba, and Sandoval counties (Stebbins and Riemer 1950). It is one of two endemic plethodontid salamanders that occur in New Mexico. It occurs predominantly at elevations between 2,130 to 3,430 m (6,988 to 11,254 ft) in mixed-conifer forest with greater than 50 percent canopy cover consisting mainly of Douglas fir (*Pseudotsuga menziesii* [Mirb.] Franco), blue spruce (*Picea pungens* Engelm.), Engelmann spruce (*Picea engelmannii* Parry ex Engelm.), white fir (*Abies concolor* [Gord. & Glend.] Lindl. ex Hildebr.), limber pine (*Pinus flexilis* James), ponderosa pine, and quaking aspen (*Populus tremuloides* Michx.). The ground surface in forest areas has (a) moderate to high volumes of large fallen trees and other woody debris, especially coniferous logs at least 25 cm (10 in) in diameter, particularly Douglas fir, which are in contact with the soil in varying stages of decay from freshly fallen to nearly fully decomposed; or (b) structural features, such as rocks, bark, and moss mats that provide

the species with food and cover. Underground habitat in forest or meadow areas contains interstitial spaces provided by (a) igneous rock with fractures or loose rocky soils, (b) rotted tree root channels, or (c) burrows of rodents or large invertebrates (Degenhardt et al. 1996; FR 2013b).

Plethodontid salamanders, which lack both lungs and gills, breathe through the mucous membranes in their mouth and throat and through their moist skin. The Jemez Mountains Salamander is completely terrestrial and does not use standing surface water for any life stage (FR 2012). Present in its habitat year-round, the Jemez Mountains Salamander spends most of its life underground, but can be found on the surface when conditions are warm and wet, approximately July through October. During this time, the Jemez Mountains Salamander can be found under rocks, bark, and moss mats and inside and under logs (Ramotnik 1986, Everett 2003). The Jemez Mountains Salamander eats invertebrates, including ants, mites, and beetles, and is thought to lay its eggs underground (FR 2013b).

1.3 Threats

Principal threats to habitat include historical fire exclusion and suppression and severe wildland fires; forest composition and structure conversions; post-fire rehabilitation; forest and fire management; roads, trails, and habitat fragmentation; recreation; and disease (FR 2012).

2.0 IMPACT OF HUMAN ACTIVITIES

2.1 Introduction

Primary threats to the Jemez Mountains Salamander on LANL property are impacts to habitat quality or destruction of individual salamanders caused by LANL or Los Alamos County operations. Forested LANL property is also subject to impacts from severe wildland fire and wildfire suppression.

2.2 Impacts on Habitat Quality

2.2.1 Development

Property at LANL varies from remote isolated land to heavily developed and/or industrialized. Most of the large developed areas at LANL are found on mesa tops, generally in the northern and western portion of LANL. The areas of Jemez Mountains Salamander habitat currently most impacted by development occur in Los Alamos Canyon. There is a secondary paved road (West Road) in the bottom of the canyon that exits the canyon on the north-facing slope through Jemez Mountains Salamander habitat. The canyon bottom also contains a recreational ice rink operated by Los Alamos County on an inholding owned by Los Alamos County. Development that reduces the occurrence of primary constituent elements of Jemez Mountains Salamander in core habitat would likely have a negative impact on the species.

2.2.2 Pedestrians and Vehicles

Many canyon bottoms and mesa tops at LANL have dirt roads traversing them. Most of these roads are gated; however, many of these roads are accessible to LANL employees and the public on foot or by bike. Some areas, such as Los Alamos Canyon, are frequently used by hikers and dog owners on active and historic trails which traverse the canyon, through Jemez Mountains

Salamander habitat in places. Maintenance of roads and trails in the habitat may have a negative impact on the species.

2.2.3 Severe Wildland Fire and Wildfire Suppression

Stand-replacing wildfires significantly change forest composition and structure, and reduce canopy cover. Even ground wildfires may reduce the volume of fallen logs and large woody debris. Large areas of historic Jemez Mountains Salamander habitat have been impacted by stand-replacing wildfires associated with current forest stocking conditions, drought, and high temperatures (FR 2012). Forested habitats on LANL are also subject to severe wildland fires. To mitigate wildfire risks, some areas of LANL have been treated for fuels reduction and creation of fuel breaks both pre-emptively and during active wildfire suppression. Both wildfires and wildfire suppression activities can negatively impact the primary constituent elements of Jemez Mountains Salamander core habitat.

2.3 Impacts on Individual Salamanders

2.3.1 Disease

The amphibian pathogenic fungus *Batrachochytrium dendrobatidis* (Bd) was found in a wild-caught Jemez Mountains Salamander in 2003 (Cummer et al. 2005) on the east side of the species' range and again in another Jemez Mountains Salamander in 2010 on the west side of the species' range (FR 2012). Bd causes the disease chytridiomycosis, whereby the Bd fungus attacks keratin in amphibians. In adult amphibians, keratin primarily occurs in the skin. The symptoms of chytridiomycosis can include sloughing of skin, lethargy, morbidity, and death. Chytridiomycosis has been linked with worldwide amphibian declines, die-offs, and extinctions, possibly in association with climate change (Pounds et al. 2006). Chytridiomycosis may be a threat to the Jemez Mountains Salamander because this disease is a threat to many other species of amphibians and the pathogen has been detected in the Jemez Mountains Salamander (FR 2012).

As part of a cooperative study with the New Mexico Department of Game and Fish between 2007 and 2013, various amphibian species including the canyon tree frog (*Hyla arenicolor*), western chorus frog (*Pseudacris triseriata*), Woodhouse's toad (*Anaxyrus woodhousii*), tiger salamander (*Ambystoma tigrinum*), and Jemez Mountains Salamander were tested for Bd infection at LANL. To date, all sampling has been negative for Bd infection (Fresquez et al. 2013).

2.3.2 Destruction of Individual Salamanders

During periods of the year when Jemez Mountains Salamander are on the soil surface, when conditions are warm and wet (generally July to October), they are vulnerable to injury and mortality from soil-disturbing activities, including operation of heavy equipment in core habitat. They also are at risk to be found and collected by people.

3.0 AEI GENERAL DESCRIPTION FOR JEMEZ MOUNTAINS SALAMANDER

The AEI consists of two areas, a core area and a buffer area. The core habitat is defined as suitable habitat where the Jemez Mountains Salamander occurs or may occur at LANL. The core habitat consists of sections of north-facing slope that contain the required micro-habitat to support Jemez

Mountains Salamander. The buffer area is 100 m (328 ft) wide extending outward from the edge of the core area.

3.1 Method for Identifying a Jemez Mountains Salamander AEI

The first step in identifying potential Jemez Mountains Salamander at LANL was to use a GIS to model habitat. Early modeling efforts by Hathcock (2008) identified areas of potential habitat and that model was further refined. The following parameters were modeled in the GIS:

• Elevation: 7,000 ft (2,150 m) and above

• Slope: Greater than 20 degrees

• Aspect: north-facing +/- 20 degrees

• Land cover: Mixed conifer

• Land use: Undeveloped

• Modeled habitat is only selected if it is greater than five contiguous 30×30 m (98×98 ft) pixels in size

Once this habitat layer was developed, a second layer was modeled that examined the level of shade in the habitat, also known as an illumination index. Since the Jemez Mountains Salamander needs cool moist conditions, an illumination index model would further highlight areas where this habitat type may occur or further reinforce the areas selected by the GIS modeling. The illumination index describes the amount and extent of solar radiation reaching the Earth's surface at a given point. This takes into account the topography that may cast shadows. The illumination model was developed using the 5 m (16 ft) resolution digital elevation model hillshade and using the Surface toolbox in ArcToolbox (Environmental Science Research Institute, Redlands, California) using the highest height of the sun on June 21 at 1:00 pm, altitude of 74.4 and Azimuth of 178.4, when the sun would be at its maximum height. These procedures were based on work done by Reilly et al. (2009).

Once this modeling was complete, LANL biological resources SMEs performed field validation to verify the suitability of the modeled habitat. The goal was to verify that mixed conifer was still the dominant cover class in the selected area. The GIS analysis used data from a landcover map created by McKown et al. (2003). There have been changes in habitat since this landcover map was published from fire and extreme drought effects. Since LANL is on the extreme edge of Jemez Mountains Salamander lower elevational range, a key component in this part of its range is soil moisture content. During field validation, evidence of a moist mixed conifer habitat versus a dry mixed conifer habitat was noted. One of the key indicators used to delimit areas of moist versus dry mixed conifer during the field validation was the presence of white fir (Evans et al. 2011) combined with a high canopy cover.

Field validation of the model occurred in May 2013, or decisions were based on earlier field visits to the sites from other projects. Each field validation consisted of LANL biological resources SMEs walking down all of the modeled habitat polygons to look for the presence of indictor features. If a polygon of modeled habitat contained white fir, indicating a moist wet conifer type habitat, a high canopy closure, and other signs of high habitat quality such as dead logs, moss or

other areas that could be used as cover by the Jemez Mountains Salamander, then the polygon was marked for retention in the final core habitat. Polygons that did not contain the necessary habitat requirements were omitted.

After the field validation was complete, the final core habitat boundaries that LANL would recognize were hand digitized using ArcGIS (Environmental Science Research Institute, Redlands, California) by LANL biological resources SMEs in and around the validated modeled polygon and areas between polygons if appropriate. The final identified core habitat at LANL occurs on the north-facing slopes of canyons. Toward the rim of the canyon the core boundaries end where the mixed conifer ends. In the canyon bottoms the core boundary extends to the edge of the stream channel. The upstream and downstream core boundaries end where the mixed conifer ends. A buffer habitat was extended around the core to a distance of 100 m (328 ft) outward. The LANL Fenton Hill satellite facility in the Jemez Mountains off of New Mexico Highway 126 is on land leased to DOE by the Santa Fe National Forest. The entire footprint is considered to be developed core habitat for the Jemez Mountains Salamander, since proposed critical habitat is adjacent to the facility.

3.2 Location and Number of Jemez Mountains Salamander AEIs

The identified Jemez Mountains Salamander core habitats were grouped by canyon system into AEIs, which contain contiguous and noncontiguous habitat areas. The largest contiguous section of habitat at LANL is in Los Alamos Canyon. There are two noncontiguous areas of habitat in Two-mile Canyon, four in Pajarito Canyon, one contiguous area in Cañon de Valle, and the entire Fenton Hill facility.

4.0 AEI MANAGEMENT

4.1 Overview

This AEI management section provides guidelines for LANL operations to reduce or eliminate the threats to the Jemez Mountains Salamander from habitat alterations that reduce habitat quality. Habitat alterations are considered for all AEIs and for both core and buffer areas. Developed areas that have ongoing baseline levels of activities and are not suitable habitat for Jemez Mountains Salamander have different restrictions than undeveloped core or buffer areas. AEIs for different species may overlap, and an activity must meet the guidelines of all applicable site plans to be allowable. Protective measures are described as management practices that should be followed when working in AEIs.

4.2 Definition and Role of Occupancy in AEI Management

Occupancy simply refers to whether or not an AEI is occupied by the Jemez Mountains Salamander. The Los Alamos Canyon AEI is known to be occupied based on past surveys. Surveys for the Jemez Mountains Salamander are known to have a very low detection rate for occupied areas, so at LANL all AEIs are assumed to be occupied at all times. If needed, site-specific surveys will be conducted by federally permitted LANL biological resources SMEs.

4.3 Definition and Role of Developed Areas in AEI Management

Developed areas include all building structures, paved roads, improved gravel roads, and paved and unpaved parking lots. The majority of Jemez Mountains Salamander core habitat is in undeveloped areas, except for the satellite facility at Fenton Hill and a small amount of habitat in Los Alamos Canyon where West Road crosses the habitat. Generally, developed areas will not have restrictions; however, some of the undeveloped sections within the footprint of Fenton Hill may have restrictions because they may contain Jemez Mountains Salamanders when they move to the surface between July and October. Any project that occurs within developed core habitat will be evaluated by LANL biological resources SMEs for ESA compliance.

4.4 General Description of Core and Buffer Areas and Allowable Area Development

The purpose of buffer areas is to protect core areas from habitat degradation. The current levels of development in buffer and core areas represent baseline conditions for this site plan. No further development is allowed in the core area under the guidelines of this site plan. Any development in a buffer area will be reviewed by LANL biological resources SMEs to ensure that there are no impacts to the core habitat.

4.5 Emergency Actions

If safety and/or property are immediately threatened by something occurring within an AEI (for example, wildfire, water line breakage, etc.) please contact a LANL biological resources SME (1-505-665-3366) as soon as possible. If the emergency occurs outside of regular business hours, contact the Emergency Management Office (1-505-667-6211). This office will then communicate with the appropriate LANL personnel.

4.6 Introduction to AEI Management Guidelines

Section 4.7 provides the guidelines for habitat alterations and allowable activities in AEI core and buffer areas. It describes what and where habitat alterations are allowed under the guidelines of this site plan. If an activity does not meet the restrictions given in the guidelines, the activity must be individually reviewed for ESA compliance. This site plan only provides guidelines for the Jemez Mountains Salamander AEIs. If an activity is desired in an area with overlapping AEIs, all applicable site plans must be consulted. AEI maps show the location of all AEIs in an area. LANL biological resources SMEs are always available to help interpret site plans and answer questions (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.7 Definition of and Restrictions on Habitat Alterations

4.7.1 Definition of Habitat Alterations

Habitat alteration includes any action that alters the soil structure, vegetative components necessary to the species, water quality, or hydrology in undeveloped areas of an AEI. An actual activity may take place outside of the AEI and will be considered habitat alteration if consequences of the activity have effects inside the AEI core. Habitat alterations would also include soil pits for soil samples deeper than 15 cm (6 in) using either hand or mechanized augers. Any activity that might disturb the soil will need to be reviewed by LANL biological resources SMEs.

The habitat components most important to the Jemez Mountains Salamander include soil structure and vegetative structure. The forest structure within an area designated as a Jemez Mountains Salamander AEI is important because it provides the necessary moist, cool microclimate.

4.7.2 Fuels Management Practices to Reduce Wildfire Risk

One of the primary threats to the Jemez Mountains Salamander is wildfire (FR 2012), but they also require habitat with a high canopy cover which makes fuels reduction challenging. Within undeveloped core areas, thinning trees to a level of 80 percent canopy cover or higher is approved. Trees may not be thinned below 80 percent canopy cover without further ESA review by LANL biological resources SMEs. Large logs on the ground should be left in place and not chipped. Understory thinning that does not reduce total canopy cover below 80 percent is permitted. Large trees that are felled should be left as large logs on the ground. Smaller trees and understory shrubs that may be thinned should be dispersed and left on-site to aid in soil moisture retention. Thinning activities should not occur during the rainy season between July to October (or when freezing temperatures begin, whichever comes first) when the Jemez Mountains Salamander is found on the surface.

In buffer areas, thinning of trees can occur to the current LANL-approved prescription level (LAAO 2000). LANL biological resources SMEs are available to provide guidance and mark trees for thinning (http://int.lanl.gov/environment/bio/controls/index.shtml).

4.7.3 Utility Corridors

Habitat alterations such as cutting down trees that threaten power lines are allowed within 8 m (26 ft) of either side of an existing electrical utility line at LANL under existing guidelines and engineering controls (Hathcock 2013). This level is approved in all areas of an AEI. New utility lines and utility lines requiring clearance of a right-of-way greater than 16 m (52 ft) total in core habitat must be individually reviewed for ESA compliance.

4.7.4 Restrictions on Habitat Alterations

Habitat alterations other than the fuels management practices and utility corridor maintenance described above are not allowed in undeveloped core areas under the guidelines of this site plan. If a project or activity is planned that would alter habitat in an undeveloped core area, it must be individually evaluated for ESA compliance. Habitat alterations in buffer areas must be reviewed by LANL biological resources SMEs to ensure that there are no impacts to core habitat.

REFERENCES CITED

- Allison, L.J., C.E. Paradzick, J.W. Rourke, and T.D. McCarthey. 2003. A characterization of vegetation in nesting and non-nesting plots for southwestern willow flycatchers in central Arizona. In *Ecology and Conservation of the Willow Flycatcher* (eds) M.K. Sogge, B.E. Kus, S.J. Sferra & M.J. Whitfield. Studies In Avian Biology: Cooper Ornithological Society.
- Brown, B.T., G.S. Mills, C. Powels, W.A. Russell, G.D. Therres, and J.J. Pottie. 1999. The influence of weapons-testing noise on bald eagle behavior. Journal of Raptor Research 33:227–32.
- Brown, B.T. and L.E. Stevens. 1997. Winter bald eagle distribution is inversely correlated with human activity along the Colorado River, Arizona. Journal of Raptor Research 31:7–10.
- Burns, M.J. 1995. White Rock noise measurements during PHERMEX tests, 11 March 1995. Los Alamos National Laboratory Memorandum DX-DO:DARHT-95-31 and 35.
- Cain, B.W. 1988. The impact of environmental contaminants on Southwestern USA raptors. *Proceedings of the Southwest Raptor Management Symposium and Workshop* (ed) by R.L. Glinski, B.G. Pendleton, M.B. Moss, M.N. LeFranc Jr., B.A. Millsap & S.W. Hoffman, 348–54. Tucson, AZ, USA, May 21–24, 1986: National Wildlife Federation, Washington, D.C., USA.
- Cummer, M. R., D. E. Green, and E. M. O'Neill. 2005. Aquatic chytrid pathogen detected in terrestrial plethodontid salamander. Herpetological Review 36(3):248–249.
- Degenhardt, W.G., C.W. Painter, and A.H. Price. 1996. Amphibians and Reptiles of New Mexico. University of New Mexico Press, Albuquerque, New Mexico.
- Delaney, D.K., T.G. Grubb, P. Beier, L.L. Pater, and M.H. Reiser. 1999. Effects of helicopter noise on Mexican spotted owls. Journal of Wildlife Management 63:60–76.
- Department of Energy (DOE). 1996. Dual-Axis Radiographic Hydrodynamic Test Facility final environmental impact statement mitigation action plan. DOE/EIS-0228.
- Durst, S.L., M.K. Sogge, H.C. English, S.O. Williams, B.E. Kus, and S.J. Sferra. 2006. Southwestern Willow Flycatcher breeding site and territory summary 2005. USGS Southwest Biological Science Center report to the U.S. Bureau of Reclamation.
- Durst, S.L., T.C. Theimer, E.H. Paxton, and M.K. Sogge. 2008. Age, habitat, and yearly variation in the diet of a generalist insectivore, the southwestern willow flycatcher. Condor 110:514–25.
- Environmental Protection Agency (EPA). 2010. National Pollutant Discharge Elimination System Storm Water Individual Permit number NM0030759.

- Evans, A.M., R.G. Everett, S.L. Stephens, and J.A. Youtz. 2011. Comprehensive Fuels Treatment Practices Guide for Mixed Conifer Forests: California, Central and Southern Rockies, and the Southwest. Forest Guild 106pp.
- Everett, E. 2003. Habitat Characterization and Environmental Influences of the Jemez Mountains Salamander (*Plethodon neomexicanus*). M.S. Thesis, New Mexico State University, Las Cruces, New Mexico, 55pp.
- Federal Register. 2012. September 12, 2012. Endangered and Threatened Wildlife and Plants; Proposed Endangered Status for the Jemez Mountains Salamander and Proposed Designation of Critical Habitat. Proposed Rule 77(177):56482-56513.
- Federal Register. 2013a. September 10, 2013. Endangered and Threatened Wildlife and Plants; Determination of Endangered Species Status for Jemez Mountains Salamander (*Plethodon neomexicanus*) Throughout Its Range. 78(175):55600-55627.
- Federal Register. 2013b. February 12, 2013. Endangered and Threatened Wildlife and Plants; Endangered Status and Designation of Critical Habitat for the Jemez Mountains Salamander. Proposed rule; reopening of comment period 78(29):9876-9882.
- Finch, D.M. and J.F. Kelly. 1999. Status and migration of the southwestern willow flycatcher in New Mexico. In *Rio Grande Ecosystems: Linking Land, Water, and People: Toward a Sustainable Future for the Middle Rio Grande Basin* (ed) D.M. Finch, J.C. Whitney, J.F. Kelly & S.R. Loftin, 197–203, Albuquerque, New Mexico.
- Fresquez, P.R., C. Hathcock, D. Keller, and J. Fair. 2013. "Foodstuffs and Biota Monitoring", in Environmental Report 2012. Los Alamos National Laboratory report LA-UR-13-27065.
- Gallegos, A., G. Gonzales, K. Bennett, and L. Pratt. 1997. Preliminary Risk Assessment of the Mexican Spotted Owl under a Spatially-weighted Foraging Regime at the Los Alamos National Laboratory. LANL report LA-13259-MS.
- Gonzales, G., R. Ryti, P. Newell, A. Gallegos, and S. Sherwood. 2004. Modeled Ecological Risk to the Deer Mouse, Mexican Spotted Owl, and Western Bluebird at the Los Alamos National Laboratory using ECORSK.7. LANL report LA-14118.
- Gonzales, G., P. Gallegos, A. Gallegos, and K. Bennett. 2009. Site-wide Application of ECORSK.9 at the Los Alamos National Laboratory. LANL report LA-UR-09-02833.
- Ganey, J.L. and R.P. Balda. 1994. Habitat selection by Mexican spotted owls in northern Arizona. Auk 111:162–69.
- Gonzales, G.J., A.F. Gallegos, K.D. Bennett, M.A. Mullen, and T.S. Foxx. 1998. Preliminary Risk Assessment of the Southwestern Willow Flycatcher (*Empidonax traillii extimus*) at the Los Alamos National Laboratory. Los Alamos National Laboratory report LA-13508MS.

- Grubb, T.G. and W.W. Bowerman. 1997. Variations in breeding bald eagle responses to jets, light planes, and helicopters. Journal of Raptor Research 31:213–22.
- Grubb, T.G. and R.M. King. 1991. Assessing human disturbance of breeding bald eagles with classification tree models. Journal of Wildlife Management 55:500–11.
- Hansen, L.A. 2004. Sigma Mesa Construction Debris Recycling Project. Los Alamos National Laboratory Memorandum RRES/Ecol-04-0049.
- Hansen, L.A. 2005. A Biological Assessment of the Potential Effects of the Operation of an Asphalt Batch Plant and a Rock Crusher at Sigma Mesa on Federally Listed Threatened and Endangered Species. Los Alamos National Laboratory report LA-CP-05-0293.
- Hansen, L.A. 2009. Sound studies of the Biosafety Level 3 (BSL-3) Laboratory at TA-3, Building 1076. Los Alamos National Laboratory report LA-UR-09-05482.
- Hathcock, C.D. and T.K. Haarmann. 2008. Development of a predictive model for habitat of the Mexican spotted owl in Northern New Mexico. Southwestern Naturalist 53:34–38.
- Hathcock, C. D. 2008. The Status of the Jemez Mountains Salamander (*Plethodon neomexicanus*) at Los Alamos National Laboratory, 2008. Los Alamos National Laboratory Report LA-UR-08-0826.
- Hathcock, C.D., L.A. Hansen, and D.C. Keller. 2010. Occupancy of habitats by Mexican spotted owl in relation to explosives noise and recreational access at Los Alamos National Laboratory. Western Birds 41:102–06.
- Hathcock, C. D. 2013. Email from C. D. Hathcock to S. Martinez on June 20, 2013, Los Alamos National Laboratory communication.
- Hatten, J.R. and C.E. Paradzick. 2003. A multiscaled model of southwestern willow flycatcher breeding habitat. Journal of Wildlife Management 67:774–88.
- Holthuijzen, A.M.A., W.G. Eastland, A.R. Ansell, M.N. Kochert, R.D. Williams, and L.S. Young. 1990. Effects of blasting on behavior and productivity of nesting prairie falcons. Wildlife Society Bulletin 18:270–81.
- Huchton, K., S.W. Koch, and R.J. Robinson. 1997. An analysis of background noise in selected canyons of Los Alamos County. Los Alamos National Laboratory report LA-13372-MS.
- Johnson, J.A. and T.H. Johnson. 1985. Timber type model of spotted owl habitat in northern New Mexico. New Mexico Department of Game and Fish report, Santa Fe, New Mexico.
- Johnson, T.H. 1994. Peregrine falcon habitat management in national forests of New Mexico. USDA Forest Service unpublished report.

- Johnson, T.H. 1998. Topographic-Landsat model of suitable spotted owl habitat around Los Alamos National Laboratory. Los Alamos National Laboratory unpublished report.
- Keller, D.C. and T.S. Foxx. 1997. Biological assessment for threatened and endangered species at the DP Road Tract land transfer. Los Alamos National Laboratory unpublished report.
- Keller, D.C. and D. Risberg. 1995. Biological and floodplain/wetland assessment for the Dual-Axis Radiographic Hydrodynamics Test Facility (DARHT). Los Alamos National Laboratory report LA-UR-95-647.
- Knight, J.L. and S.S. Vrooman. 1999. A study of construction machinery noise levels at Los Alamos National Laboratory. Los Alamos National Laboratory report LA-UR-99-5740.
- Department of Energy, Los Alamos Area Office (LAAO). 2000. Environmental Assessment for the Wildfire Hazard Reduction and Forest Health Improvement Program at Los Alamos National Laboratory, Los Alamos, New Mexico. DOE-EA-1329.
- Los Alamos National Laboratory (LANL). 2013. Environmental Protection. Los Alamos National Laboratory Program Description 400, Revision 2.
- McKown, B., S.W. Koch, R.G. Balice, and P. Neville. 2003. Land Cover Classification Map for the Eastern Jemez Region. Los Alamos National Laboratory report LA-14029.
- New Mexico Department of Game and Fish (NMDGF), April 2006. Threatened and Endangered Species of New Mexico—2006 Draft Biennial Review and Recommendations. Authority: Wildlife Conservation Act (NMSA 17-2-37+B1 through 17-2-46, 1978).
- New Mexico Environment Department (NMED). 2005. Compliance Order on Consent New Mexico Environment Department.
- Paakkonen, R. 1991. Low-frequency noise impulses from explosions. Journal of Low Frequency Noise & Vibration 10:78–82.
- Pounds, J.A., M.R. Bustamante, L.A. Coloma, J.A. Consuegra, M.P.L. Fogden, P.N.Foter, E. La Marca, K.L. Masters, A. Merino-Viteri, R. Puschendorf, S.R. Ron, G.A. Sanchez-Azofeifa, C.J. Still, and B.E. Yound. 2006. Widespread amphibian extinctions from epidemic disease driven by global warming. Nature 439(7073):161-167.
- Ramotnik, C.A. 1986. Status Report: *Plethodon neomexicanus* Jemez Mountains Salamander. U.S. Fish and Wildlife Service Report.
- Reilly, E.C., D. Clayton, R.S. Nauman, D.H. Olson, H.H. Welsh Jr, B. Devlin. 2009. Spatial Model of Optimal Habitat for the Siskiyou Mountains Salamander (*Plethodon stormi*) North of the Siskyou Crest. Chapter 2. In: Olson, D.H., D. Clayton, R.S. Nauman, and H.H. Welsh Jr (Editors). 2009. Conservation of the Siskiyou Mountains Salamander (*Plethodon stormi*). Northwest Fauna 6:1-73.

- Stebbins, R.C., and W.J. Riemer. 1950. A New Species of Plethodontid Salamander from the Jemez Mountains of New Mexico. Copeia 1950(2):73–80.
- Steidl, R.J. and R.G. Anthony. 2000. Experimental effects of human activity on breeding bald eagles. Ecological Applications 10:258–68.
- Swarthout, E.C.H. and R.J. Steidl. 2001. Flush responses of Mexican spotted owls to recreationists. Journal of Wildlife Management 65:312–17.
- Swarthout, E.C.H. and R.J. Steidl. 2003. Experimental effects of hiking on breeding Mexican spotted owls. Conservation Biology 17:307–15.
- Trujillo, C.T. and E. Racinez. 1995. Meeting notes on the 13.8-kV transmission line tree trimming. Los Alamos National Laboratory Memorandum FSS-8-95-114.
- U.S. Fish and Wildlife Service (USFWS). 1995. Recovery plan for the Mexican spotted owl. Albuquerque, New Mexico.
- U.S. Fish and Wildlife Service (USFWS). 2012. Recovery plan for the Mexican Spotted Owl, First Revision. Albuquerque, New Mexico.
- U.S. Fish and Wildlife Service (USFWS). 2002. Southwestern willow flycatcher recovery plan. Albuquerque, New Mexico.
- Vigil, E.A. 1995. Noise measurements at State Road 4 and Bandelier turn-off at State Road 4 during PHERMEX test on March 11, 1995. Los Alamos National Laboratory Memorandum ESH-5:95-11825.
- Vrooman, S.S., S.W. Koch, and J.L. Knight. 2000. Temporal and spatial variation in background noise levels at Los Alamos National Laboratory. Los Alamos National Laboratory report LA-13684-MS.
- Wiesenborn, W.D. and S.L. Heydon. 2007. Diets of breeding southwestern willow flycatchers in different habitats. Wilson Journal of Ornithology 119:547–57.
- Willey, D.W. 2013. Diet of Mexican Spotted Owls in Utah and Arizona. The Wilson Journal of Ornithology 125(4):775-781.
- Yong, W. and D.M. Finch. 1997. Migration of the willow flycatcher along the middle Rio Grande. Wilson Bulletin 109:253–68.

APPENDIX

Table A-1. The percentage of each food type found in Mexican Spotted Owl food remains at LANL

Species	Relative Abundance
Neotoma spp.	26.22
Peromyscus spp.	10.22
Microtus spp.	4.44
Gophers	4.89
Bats	5.78
Chipmunks	0.89
Rabbits	12.89
Shrews	1.33
Small Mammal	1.33
Medium Mammal	1.78
Medium Bird	8.00
Small Bird	4.89
Nocturnal Birds	0.89
Reptiles	4.89
Arthropods	11.56

Table A-2. Preliminary light measurements in ftc for Mexican Spotted Owl site plan

		Distance from Source			
	Source (street light)	5 m	10 m	15 m	20 m
ftc	3.70	2.28	1.20	0.62	0.32

K-2, U.S. Fish & Wildlife Concurrence (Biological Assessment of Jemez Mtn Salamander Site Plan)



United States Department of the Interior

FISH AND WILDLIFE SERVICE

New Mexico Ecological Services Field Office 2105 Osuna NE Albuquerque, New Mexico 87113 Phone: (505) 346-2525 Fax: (505) 346-2542

December 9, 2013

Cons. #02ENNM00-2014-I-0014

Geoffrey L. Beausoleil, Acting Manager National Nuclear Security Administration, Los Alamos Field Office Department of Energy Los Alamos, New Mexico 87544

Dear Mr. Beausoleil:

Thank you for your biological assessment entitled, "Biological Assessment of the Effects of Implementing the Jemez Mountains Salamander Site Plan on Federally Listed Threatened and Endangered Species at Los Alamos National Laboratory" (BA); the request for informal consultation and conferencing received on July 25, 2013 and supplemental information supplied in the "Jemez Mountains Salamander (Plethodon neomexicanus) Los Alamos National Laboratory (LANL) Site Plan" (Site Plan); and emails dated November 19 and December 3, 2013. The Department of Energy (DOE) requested concurrence with the determination of effects for the endangered Jemez Mountains salamander (Plethodon neomexicanus) (salamander) pursuant to Section 7(a)(2) of the Endangered Species Act of 1973 (ESA), as amended (16 U.S.C. § 1531 et seq.). Your proposed action consists of implementing the Site Plan, and includes of the incorporation of this Site Plan into LANL's Habitat Management Plan (HMP). The HMP was consulted upon in 1999 (Consultation #2-22-981-336) as the primary mechanism to ensure compliance with the ESA at LANL. The actions described in the Site Plan and analyzed in the BA, and supplemental emails are hereby incorporated by reference. You determined that implementing the Site Plan "may affect, is not likely to adversely affect" the salamander, and includes placing restrictions on certain types of work in areas identified as core habitat for the salamander on LANL property with the purpose of ensuring that effects to the salamander from those actions identified in the Site Plan are insignificant and discountable.

The Site Plan does not include any areas within designated salamander critical habitat, indicating that no critical habitat will be affected. The Site Plan has modeled and field validated the model to identify the areas on LANL property with the highest potential to be occupied by salamanders based on habitat features for the salamander. Each area identified by the modeling is termed "Area of Environmental Interest" (AEI) and consists of a "core area" and a "buffer area". The core area habitat is defined as suitable habitat where the salamander occurs or may occur at LANL. The core area habitat consists of sections of north-facing slope that contain the required

micro-habitat to support salamanders. The buffer area is 328 feet (100 meters) wide extending outward from the edge of the core area. Only the Los Alamos Canyon AEI is known to be occupied based on surveys. Surveys for the salamander are known to have a very low detection rate for occupied areas and DOE has assumed that all AEIs at LANL are occupied at all times by the salamander.

Within the Site Plan, DOE has assessed activities that could cause habitat alteration and includes any action that alters the soil structure, vegetative components necessary to the species, water quality, or hydrology in undeveloped areas of an AEI. If an activity were to take place outside of the AEI the activity will be assessed if it will have effects inside the AEI core. Within the core areas, only activities specified within the Site Plan and those that have no effect in the core areas (e.g. no habitat alterations or effects within the core areas) will be conducted without further consultation with the Service. Habitat alterations also include soil pits for soil samples deeper than 6 inches (15.2 centimeters) using either hand or mechanized augers. Within the Site Plan, DOE is proposing fuels management practices to reduce wildfire risk and maintenance of utility corridors within the AEIs. The likelihood that salamanders may be affected by the actions in the Site Plan is very low. To ensure that effects to the salamander are insignificant and discountable, the Site Plan incorporates the following conservation measures as restrictions to the identified work:

Fuels Management Practices to Reduce Wildfire Risk

- a. Within undeveloped core areas, thinning trees to a level of 80% canopy cover or higher may occur; tree thinning below 80% canopy cover is not part of the action under this consultation.
- b. Large logs on the ground will be left in place and not chipped.
- c. Large trees that are felled will be left as large logs on the ground
- d. When appropriate, smaller trees and understory shrubs that may be thinned will be dispersed and left on-site to aid in soil moisture retention.
- e. In buffer areas, thinning of trees may occur to the current LANL-approved prescription level; clear-cutting will not occur.
- f. Thinning activities will not occur during the rainy season when salamanders are surface active, between July 1 – October 31. Thinning activities may occur earlier in October if freezing temperatures are present.
- g. In the unlikely event that a salamander is observed surface active during thinning activities, all activities shall cease, and the Service will be notified.

Utility Corridors

- a. Cutting trees that threaten power lines may occur within 26 feet (8 meters) of either side of an existing utility line at LANL
- b. New utility lines and utility lines requiring clearance of a right-of-way greater than 52 feet (16 meters) total in core habitat is not part of the action under this consultation.

Habitat alterations other than the fuels management practices and utility corridor maintenance described above will not occur in undeveloped core areas under the guidelines of the Site Plan or this consultation. The Service concurs with DOE's determination regarding the salamander for the following reasons:

Within the Site Plan, DOE has placed the above detailed restrictions to ensure that any effects to the salamander and its habitat remain insignificant and discountable. Canopy cover will remain at 80% or greater in undeveloped core areas and fire management actions will occur outside of the salamander surface activity period. Maintaining utility line corridors in areas with existing infrastructure (the utility lines) by removing individual hazard trees is not expected to have any measurable effect on salamanders or their potential habitat. Consequently, we concur that potential effects to the salamander from the proposed action will be insignificant and discountable.

This concludes section 7 consultation regarding the proposed action. If monitoring or other information results in modification or the inability to complete all aspects of the proposed action, consultation should be reinitiated. Please contact the Service if: 1) future surveys detect listed, proposed or candidate species in habitats where they have not been previously observed; 2) the proposed action changes or new information reveals effects of the proposal to listed species that have not been considered in this analysis; or 3) a new species is listed or critical habitat designated that may be affected by the action.

Thank you for your concern for endangered and threatened species and New Mexico's wildlife habitats. In future correspondence regarding this project, please refer to consultation #02ENNM00-2014-I-0014. If you have any questions, please contact Michelle Christman of my staff at (505) 761-4715.

Sincerely,

Wally Murphy Field Supervisor

cc:

Wildlife Biologist, Cuba Ranger District, Cuba, NM (Attn: Ramon Borrego) Director, New Mexico Department of Game and Fish, Santa Fe, New Mexico

K-3, TA-3 and TA-60 IPac Trust Resource Report

MSGP

IPaC Trust Resource Report

Generated July 27, 2015 07:29 PM MDT



US Fish & Wildlife Service

IPaC Trust Resource Report



Project Description

NAME

MSGP

PROJECT CODE


LXATM-TI5EJ-BAJEQ-3NC5E-SOGYTE

LOCATION

Los Alamos County, New Mexico

DESCRIPTION

Facilities that discharge to Sandia Canyon within TA-3 and TA-60. Industrial facilities subject to the MSGP. July, 2015.



U.S. Fish & Wildlife Contact Information

Species in this report are managed by:

New Mexico Ecological Services Field Office 2105 Osuna Road Ne Albuquerque, NM 87113-1001 (505) 346-2525

Endangered Species

Proposed, candidate, threatened, and endangered species that are managed by the <u>Endangered Species Program</u> and should be considered as part of an effect analysis for this project.

This unofficial species list is for informational purposes only and does not fulfill the requirements under <u>Section 7</u> of the Endangered Species Act, which states that Federal agencies are required to "request of the Secretary of Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action." This requirement applies to projects which are conducted, permitted or licensed by any Federal agency.

A letter from the local office and a species list which fulfills this requirement can be obtained by returning to this project on the IPaC website and requesting an Official Species List from the regulatory documents section.

Amphibians

Jemez Mountains Salamander Plethodon neomexicanus

Endangered

CRITICAL HABITAT

There is final critical habitat designated for this species.

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=D019

Birds

Mexican Spotted Owl Strix occidentalis lucida

Threatened

CRITICAL HABITAT

There is **final** critical habitat designated for this species.

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B074

Southwestern Willow Flycatcher Empidonax traillii extimus

Endangered

CRITICAL HABITAT

There is final critical habitat designated for this species.

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B094

Yellow-billed Cuckoo Coccyzus americanus

Threatened

CRITICAL HABITAT

There is **proposed** critical habitat designated for this species.

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B06R

Mammals

New Mexico Meadow Jumping Mouse Zapus hudsonius luteus

Endangered

CRITICAL HABITAT

There is **proposed** critical habitat designated for this species.

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=A0BX

Critical Habitats

Potential effects to critical habitat(s) within the project area must be analyzed along with the endangered species themselves.

There is no critical habitat within this project area

Migratory Birds

Birds are protected by the Migratory Bird Treaty Act and the Bald and Golden Eagle Protection Act.

Any activity which results in the take of migratory birds or eagles is prohibited unless authorized by the U.S. Fish and Wildlife Service (1). There are no provisions for allowing the take of migratory birds that are unintentionally killed or injured.

You are responsible for complying with the appropriate regulations for the protection of birds as part of this project. This involves analyzing potential impacts and implementing appropriate conservation measures for all project activities.

Bald Eagle Haliaeetus leucocephalus

Bird of conservation concern

Season: Wintering

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B008

Bendire's Thrasher Toxostoma bendirei

Bird of conservation concern

Season: Breeding

Brewer's Sparrow Spizella breweri

Bird of conservation concern

Season: Migrating

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0HA

Brown-capped Rosy-finch Leucosticte australis

Bird of conservation concern

Season: Wintering

Burrowing Owl Athene cunicularia

Bird of conservation concern

Season: Breeding

Cassin's Finch Carpodacus cassinii

Bird of conservation concern

Year-round

Flammulated Owl Otus flammeolus

Bird of conservation concern

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0DK

Fox Sparrow Passerella iliaca

Bird of conservation concern

Season: Wintering

Golden Eagle Aquila chrysaetos

Bird of conservation concern

Year-round

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0DV

Grace's Warbler Dendroica graciae

Bird of conservation concern

Season: Breeding

Juniper Titmouse Baeolophus ridgwayi

Bird of conservation concern

Year-round

Lewis's Woodpecker Melanerpes lewis

Bird of conservation concern

Year-round

Loggerhead Shrike Lanius Iudovicianus

Bird of conservation concern

Year-round

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0FY

Mountain Plover Charadrius montanus

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B078

Olive-sided Flycatcher Contopus cooperi

Season: Breeding

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0AN

Peregrine Falcon Falco peregrinus

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0FU

Pinyon Jay Gymnorhinus cyanocephalus

Year-round

Prairie Falcon Falco mexicanus

Year-round

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0ER

Swainson's Hawk Buteo swainsoni

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B070

Williamson's Sapsucker Sphyrapicus thyroideus

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0FX

Willow Flycatcher Empidonax traillii

Season: Breeding

https://ecos.fws.gov/speciesProfile/profile/speciesProfile.action?spcode=B0F6

Bird of conservation concern

07/27/2015 07:29

Refuges

Any activity proposed on <u>National Wildlife Refuge</u> lands must undergo a 'Compatibility Determination' conducted by the Refuge. If your project overlaps or otherwise impacts a Refuge, please contact that Refuge to discuss the authorization process.

There are no refuges within this project area

Wetlands

Impacts to <u>NWI wetlands</u> and other aquatic habitats from your project may be subject to regulation under Section 404 of the Clean Water Act, or other State/Federal Statutes.

Project proponents should discuss the relationship of these requirements to their project with the Regulatory Program of the appropriate <u>U.S. Army Corps of Engineers District</u>.

DATA LIMITATIONS

The Service's objective of mapping wetlands and deepwater habitats is to produce reconnaissance level information on the location, type and size of these resources. The maps are prepared from the analysis of high altitude imagery. Wetlands are identified based on vegetation, visible hydrology and geography. A margin of error is inherent in the use of imagery; thus, detailed on-the-ground inspection of any particular site may result in revision of the wetland boundaries or classification established through image analysis.

The accuracy of image interpretation depends on the quality of the imagery, the experience of the image analysts, the amount and quality of the collateral data and the amount of ground truth verification work conducted. Metadata should be consulted to determine the date of the source imagery used and any mapping problems.

Wetlands or other mapped features may have changed since the date of the imagery or field work. There may be occasional differences in polygon boundaries or classifications between the information depicted on the map and the actual conditions on site.

DATA EXCLUSIONS

Certain wetland habitats are excluded from the National mapping program because of the limitations of aerial imagery as the primary data source used to detect wetlands. These habitats include seagrasses or submerged aquatic vegetation that are found in the intertidal and subtidal zones of estuaries and nearshore coastal waters. Some deepwater reef communities (coral or tuberficid worm reefs) have also been excluded from the inventory. These habitats, because of their depth, go undetected by aerial imagery.

DATA PRECAUTIONS

Federal, state, and local regulatory agencies with jurisdiction over wetlands may define and describe wetlands in a different manner than that used in this inventory. There is no attempt, in either the design or products of this inventory, to define the limits of proprietary jurisdiction of any Federal, state, or local government or to establish the geographical scope of the regulatory programs of government agencies. Persons intending to engage in activities involving modifications within or adjacent to wetland areas should seek the advice of appropriate federal, state, or local agencies concerning specified agency regulatory programs and proprietary jurisdictions that may affect such activities.

There are no wetlands identified in this project area

APPENDIX L Procedures Referenced in the SWPPP

ENV-CP-QP-007	Revision: 10
Effective Date: 09/30/15	Next Review Date: 09/30/18



Environment, Safety, Health Directorate

Environmental Protection – Compliance Programs

Quality Procedure

Spill Investigations

Reviewers:

Name:	Organization:	Signature:	Date:
Brian M. Iacona	ENV-CP	Signature on File	08/13/15
Name:	Organization:	Signature:	Date:
Jacob W. Meadows	ENV-CP	Signature on File	08/28/15
Derivative Classifier: 🛛 Unclassified 🔲 DUSA <u>ENVPRO</u>			
Name:	Organization:	Signature:	Date:
Gian A. Bacigalupa	ENV-CP	Signature on File	08/31/15
Approval Signatures:			
Subject Matter Expert:	Organization:	Signature:	Date:
Jacob W. Meadows	ENV-CP, Program Lead	Signature on File	08/31/15
Responsible Line Manager:	Organization:	Signature:	Date:
Michael T. Saladen	ENV-CP, Team Leader	Signature on File	08/31/15
Responsible Line Manager:	Organization:	Signature:	Date:
Anthony R. Grieggs	ENV-CP, Group Leader	Signature on File	09/30/15

This copy is uncontrolled.

Users are responsible for ensuring they work to the latest approved version. To document a required read, Login to <u>UTrain</u>, and go to the Advanced Search.

Spill Investigations	ENV-CP-QP-007	Page 2 of 12
	Revision: 10	Effective Date: 09/30/15

History of Revisions

Document Number [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	12/98	New Document.
1	06/00	Annual review, added Cerro Grande fire hazards
2	07/01	Annual review
3	06/03	Annual review
4	04/04	Annual review, changes to HCPs
5	02/07	Annual review, changes to reflect organizational restructure
6	07/08	Annual review
7	09/10	Biennial Review and revision
8	04/11	Removed prerequisites, added note re: on-call spill reporting.
9	07/13	Biennial review and revision, implemented new procedure format.
10	09/30/15	Biennial review and revision, implemented new procedure format. Controlled the updated LANL ENV-CP Unplanned Release Report.

Spill Investigations

ENV-CP-QP-007 Page 3 of 12

Revision: 10

Effective Date: 09/30/15

Table of Contents

1.0 PURPOSE 2.0 SCOPE 2.1 Hazard review 3.0 RESPONSIBILITIES	4 4 4
2.1 Hazard review	444
3.0 RESPONSIBILITIES	4
	4
3.1 Prerequisites	
4.0 WORK PROCESSES	
4.1 Field Activity	
4.2 Communication	
4.3 Facility Management Work Control Requirements for Field Activities	6
4.4 Facility Management-Specific Access Requirements	6
4.5 Regulatory Spill Reporting	8
5.0 DOCUMENT CONTROL/RECORDS MANAGEMENT	8
6.0 DEFINITIONS	9
7.0 REFERENCES	9
8.0 ATTACHMENTS	
Attachment 1- ENV-CP Release Notification Phone List	
Attachment 2- LANL ENV-CP Unplanned Release Report	

Spill Investigations	ENV-CP-QP-007	Page 4 of 12
_	Revision: 10	Effective Date: 09/30/15

1.0 PURPOSE

This Environmental Protection Division – Compliance Programs Group (ENV-CP) procedure describes processes and implements requirements for spill investigations.

2.0 SCOPE

This procedure applies to all ENV-CP staff and personnel conducting spill investigations.

2.1 HAZARD REVIEW

The work described in this procedure is <u>field work</u> and has a <u>LOW hazard</u> rating as documented by submittal of a completed <u>ENV Low Hazard Verification form</u>.

3.0 RESPONSIBILITIES

The following personnel require training before implementing this procedure:

• ENV-CP staff and contract personnel who perform spill response and investigation.

Annual re-training to this procedure is required. Specific training requirements will be updated as needed.

The training method for this procedure is required reading and on-the-job training (OJT). The OJT is to be conducted by a Team Leader or person designated as Subject Matter Expert (SME) by the ENV-CP Group Leader. This training will be documented in accordance with ENV-DO-QP-115, *Personnel Training*.

Actions specified within this procedure, unless proceeded with "should" or "may," are to be considered mandatory (i.e., "shall", "will", "must").

3.1 Prerequisites

None

4.0 WORK PROCESSES

Responsibility is to assure the immediate mitigation and timely notification of appropriate regulatory organizations in the event of a spill or unplanned discharge that has or may affect the environment. Work requires frequent and unscheduled site visits to any area of the Laboratory during a spill or unplanned release as support staff for the on-scene Security and Emergency Operations (SEO) Incident Commander.

Specific activities associated with Spill Response and Investigation:

- Respond to the spill or unplanned release site;
- Report to the On-Scene SEO Incident Commander and Site Safety Officer;
- Receive site safety requirements;
- Provide decision support;
- Investigate the nature and extent of the spill or unplanned release;

Spill Investigations	ENV-CP-QP-007	Page 5 of 12
	Revision: 10	Effective Date: 09/30/15

- Evaluate the potential environmental impact to water quality;
- Report the occurrence to the regulatory agencies, if necessary; and
- Provide support to mitigation plan and implementation.

4.1 FIELD ACTIVITY

If the spill or unplanned discharge is determined to be a non-emergency event by SEO response, such as a release of potable water, perform the following steps:

Step	Action
1	Perform a site visit in coordination with the Facility
	Operations Director designee.
2	Assess potential environmental damage.
3	Provide mitigation measures and requirements.
4	Document the event.
5	Notify regulatory agencies and DOE, if necessary.
6	Facilitate collection of samples, if necessary.

For emergency response, perform the following steps:

Step	Action
1	Report to on-scene commander and await instructions.
2	Perform a site visit in coordination with SEO.
3	Adhere to access requirements as developed by the SEO Site Safety Officer and Incident Commander.
4	Identify and document the source and cause of the release.
5	Provide notification and written report if necessary.
6	Facilitate collection of samples if necessary and safe to do so.

If sample collection is required, contact the following sampling personnel:

- ENV-CP
 - NPDES outfall
 - Sanitary treatment solids
- WM-SVS
 - Wastes and chemical spills (liquid, solid, hazardous)
- ADEP Environmental Remediation Division
 - Surface water
 - Storm water runoff
 - Groundwater
 - Sediments

Spill Investigations	ENV-CP-QP-007	Page 6 of 12
	Revision: 10	Effective Date: 09/30/15

If WM-SVS will collect the required sample, complete a Request For Analysis (RFA), http://int.lanl.gov/environment/waste/sampling.shtml, to schedule sampling. Specify the analytical suite and turn-around time needed for the sample in the RFA.

4.2 COMMUNICATION

Take a cellular phone that will transmit from the location to be visited. Also take a contact pager to receive messages.

If cellular service is unavailable, use a portable radio set to the appropriate radio frequency.

If in a secure area where cell phone use is prohibited, use the radio. Be sure to have radio checked and authorized for use within secure areas or within the boundaries of the WFO FOD or WX Division. Government-owned cellular phones, with batteries removed, may be brought into the secure area but used only if approval is given by the SEO Incident Commander or FOD or designee. Rules of use for Smartphones and other mobile devices (BlackBerry, iPhones, iPads) can be found on the Computing Communications webpage for mobile devices, http://int.lanl.gov/computing/communications/mobile/index.shtml.

Radio or cellular contact must be established with a designated contact prior to leaving ENV-CP and upon arrival/departure at the site in accordance with <u>ENV-DO-QP-100</u>, <u>General Field Safety</u>.

The Incident Commander can make special communication exceptions.

All photography at LANL must adhere to <u>P217, Controlled Articles</u>.

Wastes generated from activities described in the procedure will be properly characterized, managed, and disposed in accordance with <u>P409, LANL Waste Management</u>, <u>P930-1, LANL Waste Acceptance Criteria</u>, and P403, *Environmental Risk Identification and Management*.

4.3 FACILITY MANAGEMENT WORK CONTROL REQUIREMENTS FOR FIELD ACTIVITIES

Most field activities performed by the ENV-CP spill response personnel are impacted by facility management work control requirements. Requirements vary between the respective Facility Operations Divisions (FODs) and therefore necessitate ENV-CP response personnel to acquire FOD approval for site access in advance of starting work activities. The exception to this is in response to emergency situations as support to SEO staff.

Should work be required to stop/pause, reference P101-18, *Procedure for Pause/Stop Work*, for guidance.

4.4 FACILITY MANAGEMENT-SPECIFIC ACCESS REQUIREMENTS

4.4.1 HIGH EXPLOSIVES AREAS

TA-16 and TA-11 high explosives areas have specific access requirements. Access inside the security gate requires annual site-specific training. Curricula #5243 must be assigned and all the training courses completed before arriving at TA-16. For access, (normal or after hours) contact the WFO FOD to ensure entry requirements are met and the activity is authorized for the Plan of the Day.

Spill Investigations	ENV-CP-QP-007	Page 7 of 12
	Revision: 10	Effective Date: 09/30/15

For access to WFO perimeter gates during normal working hours or after hours, contact TA-15 Access Control at 667-6742 and request permission to enter. A perimeter gate key must be picked up at the TA-15 Access Control office. Note that all outdoor firing will be suspended during entry.

For perimeter gates, prior notification for after-hours entry is also required by SOC. Perform the following steps:

Step	Action	
1	Call SOC Los Alamos at 667-4437.	
2	Identify yourself to the on duty officer or attendant.	
3	Provide the following information: Group, color and make of vehicle (s), which perimeter gate you are entering, and approximate time of arrival and finally, length of stay.	

Failure to notify security personnel in advance could result in a security violation against the visiting Team Member.

Provide notification to SOC Los Alamos at 667-4437 when leaving area.

For access to WX areas required during normal or after working hours, perform the following steps:

- Ensure the required security clearance (Q clearance) is held, and
- Contact the FOD or designee for entry requirements.

4.4.2 CHEMISTRY METALLURGY RESEARCH FACILITY ACCESS

For access to the Chemistry Metallurgy Research Facility, perform the following:

- Must have the required L or Q clearance to pass the security gate.
- If access into any of the buildings is necessary, contact CMR Operations Management or the FOD for an escort.
- If responding to an emergency with SEO, ENV-CP staff will be considered part of the SEO response team, met at the access gate, and escorted to the spill site.

4.4.3 TA-3-66 SIGMA FACILITY ACCESS

For access to the Sigma facility (TA-3-66), perform the following:

- For non-emergency responses, obtain prior site-specific training and authorization or contact the FOD for personnel escort and contact the FOD Deployed Environmental Professional.
- For emergency response with SEO, ENV-CP staff will be considered part of the SEO response team, met at the access gate, and escorted to the spill site. Contact the FOD to ensure they are aware of the incident.

Spill Investigations	ENV-CP-QP-007	Page 8 of 12
_	Revision: 10	Effective Date: 09/30/15

4.5 REGULATORY SPILL REPORTING

If a spill is determined to be a threat to the environment or human health, regulatory and DOE notification may be necessary. Contacts and telephone numbers can be found on Attachment 1, ENV-CP Release Notification Phone List.

If a spill impacts a Solid Waste Management Unit (SWMU) or Area of Concern (AOC), contact ENV-CP and Environmental Remediation (ER) for possible additional notification requirements.

If ENV Division or designated SME personnel determine after a site inspection or verbal notification that a spill is non-reportable to DOE or applicable regulatory agencies, a LANL ENV-CP Unplanned Release Report must be completed (Attachment 2) and submitted to the ENV-CP SME for required documentation.

For ENV Division designated on-call personnel, follow guidance for spill reporting as described in ENV-DO-QP-101, *Environmental Reporting Requirements for Releases or Events*.

NOTE: On-call representatives are required to follow up in writing (email is sufficient) with the spills program lead regarding all releases during their on-call schedule. If no spills are reported in off-work hours, please confirm in writing with the spills program lead at the end of your on-call schedule.

For additional information concerning spill and unplanned discharge determination and notification requirements, contact the ENV-CP Water Quality Permitting and Compliance Team Leader.

5.0 DOCUMENT CONTROL/RECORDS MANAGEMENT

The following records generated as a result of this procedure are to be submitted in accordance with <u>ADESH-AP-006 Records Management Plan</u>.

- Field notebook documentation of the release including:
 - Time and date of the release
 - Time and date of ENV-CP notification
 - Location of the release
 - Source of the release(equipment, etc,)
 - Type of material released
 - Quantity of material released
 - If an impact to a watercourse or Potential Release Site occurred
 - Time release was stopped
 - Any immediate mitigating actions implemented to contain or control the release
- Any written report and verbal notification list generated should the release be deemed reportable.
- LANL ENV-CP Unplanned Release Report (Attachment 2) for non-reportable releases.

Spill Investigations	ENV-CP-QP-007	Page 9 of 12
	Revision: 10	Effective Date: 09/30/15

6.0 DEFINITIONS

AOC: Area of Concern

ER: Environmental Remediation

<u>Field Work</u>: Performance of Laboratory related activities in areas that are removed or isolated from an established populated base of operation (that is, where emergency support and medical assistance is not readily available.)

FOD: Facility Operations Division

NPDES: National Pollutant Discharge Elimination System

OJT: On the job training

PRS: Potential Release Site

SEO: Security and Emergency Operations

SOC Los Alamos: Security contractor for Los Alamos National Laboratory

SWMU: Solid Waste Management Unit

7.0 REFERENCES

None

8.0 ATTACHMENTS

Attachment 1- ENV-CP Release Notification Phone List

Attachment 2- LANL ENV-CP Unplanned Release Report

Spill Investigations	ENV-CP-QP-007	Page 10 of 12
	Revision: 10	Effective Date: 09/30/15

ATTACHMENT 1- ENV-CP RELEASE NOTIFICATION PHONE LIST

Los Alamos National Laboratory ENV-CP

Release notification phone list

August 2015

Los Alamos National Laborato	ry
------------------------------	----

(1)	Security and Emergency Operations	
	Emergency Management (SEO-EM)	667-6211
(2)	ENV-ES Group Office	665-8855
(3)	ENV-CP Group Office	667-0666
(4)	ENV-DO	667-2211
(5)	LANL Central Alarm Station (SOC-LA)	667-7080
	L.A. Fire Department	667-4055

New Mexico Environment Department

See Web address below

(1)	NMED Emergency Hotline (24 hours a day)	827-9329
(2)	NMED Non-Emergency Hotline (During business hours)	476-6000
	NMED Non-Emergency Hotline (Voicemail; 24 hours a day)	1(866) 428-6535
(3)	NMED Surface Water Quality Bureau	827-0187
	Erin Trujillo	827-0418
(4)	NMED Ground Water Quality Bureau	827-2900
	Greg Huey	827-6891
	Steven Huddleson	827-2936
	Gerald Knutson	827-2996
(5)	NMED Hazardous Waste Bureau	476-6000
	Ruth Horowitz	476-6025

U.S Environmental Protection Agency

(1)	US EPA Region 6 Spill Reporting (During business hours)	1(800) 887-6063
	Emergencies- Contact the NRC	1(800) 424-8802
(2)	Gladys Gooden-Jackson	1(214) 655-7494

U.S. Department of Energy

(1) Gene Turner	667-5794

State Emergency Response Commission (SERC) Notification

New Mexico State Police	(505) 827-9300 (During business hours)
(Immediate Notification)	(505) 827-3476 (24 hours a day)

New Mexico Department of Homeland Security and Emergency

Management (Follow-up Notification) (505) 476-9600

National Response Center

U.S. Coast Guard National Response Center	1-800-424-8802

See NRC web address below for report form

Spill Investigations	ENV-CP-QP-007	Page 11 of 12
	Revision: 10	Effective Date: 09/30/15

New Mexico State Police

New Mexico State Police (505)827-9300 (During business hours)

(505) 827-3476 (24 hours a day)

Local Emergency Planning Committee (LEPC) LAPD

Philmont Taylor (505) 663-3511

On Call Environmental Contact for Releases Group Representatives for Notifications to External Agencies

Name	Group	Work	Pager	Cellular	Email address
		Phone		Phone	
Jake Meadows	ENV-CP	606-0185	664-1333	231-0460	jmeadows@lanl.gov
Mike Saladen	ENV-CP	665-6085		699-1284	saladen@lanl.gov
Mark Haagenstad	ENV-CP	665-2014		699-1733	mph@lanl.gov
Tim Zimmerly	ENV-CP	664-0105	664-1237	699-7621	tzimmer@lanl.gov
Terrill Lemke	ENV-CP	665-2397		699-0725	tlemke@lanl.gov

Web addresses:

NMED home page http://www.nmenv.state.nm.us

National Response Center home page http://www.nrc.uscg.mil/Default.aspx

Reportable Quantities web page http://homer.ornl.gov/rg/

Spill Investigations	ENV-CP-QP-007	Page 12 of 12
-	Revision: 10	Effective Date: 09/30/15

ATTACHMENT 2- LANL ENV-CP UNPLANNED RELEASE REPORT

Los Alamos National Laboratory Environmental Compliance Programs (ENV-CP) Unplanned Release Report

Form Completed By: Tel	ephone:		Group:	
Spill Details Spi	ll Owner	(Specify): □LANS, LLC	□Subcontractor:	
Date of Spill/Date Spill Discovered:				
Location:				
Material Spilled:		Anti-freeze/coolant	☐ Gasoline	
☐ Hydraulic Fluid		Steam Condensate Lubricants/oils	□ Other:	
☐ Potable Water ☐ Diesel		Refrigerant Oil		
Volume Spilled:		Waste Volume Ge	enerated:	
Source of Spill:		Hydraulic Line	□ Radiator	
Vehicle ID: Equipment ID:		Potable Water Line Fire Suppression System	☐ Condensate Line ☐ Other:	
Equipment ID.		Fuel Tank	L Ouer.	
			s taken to contain the spill, and steps/spill control eted and describe actions taken to prevent spill	
Did the spill enter or impact any of the		□ Floor Drain, if so please ind	dicate affected facility	
following? (Check as many as apply)				
following? (Check as many as apply) RCRA Treatment Storage Disposal Fac	cility	□ Watercourse/drainage area,	if so please indicate	
following? (Check as many as apply)	cility	□ Watercourse/drainage area,		
following? (Check as many as apply) RCRA Treatment Storage Disposal Fac RCRA Satellite Accumulation Area	cility	□ Watercourse/drainage area,	if so please indicate	
following? (Check as many as apply) RCRA Treatment Storage Disposal Fac RCRA Satellite Accumulation Area		□ Watercourse/drainage area, □ Solid Waste Management U	if so please indicate	
following? (Check as many as apply) RCRA Treatment Storage Disposal Face RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on:	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt	
following? (Check as many as apply) RCRA Treatment Storage Disposal Face RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor	if so please indicate Jnit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area	
following? (Check as many as apply) RCRA Treatment Storage Disposal Face RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on:	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factor RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply)	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factorial RCRA Satellite Accumulation Area RCRA < 90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected:	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other:	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factor RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected:	ing?	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other:	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factorial RCRA Satellite Accumulation Area RCRA < 90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected:	Soil Air Other:	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck If sa	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other: amples were collected, indicate analytical suite:	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factor RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected: None Water Certification	Soil Air Other:	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck If sa	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other: amples were collected, indicate analytical suite:	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factor RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected: None Water Certification I certify that I am knowledgeable about the info	Soil Air Other:	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck If sa	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other: amples were collected, indicate analytical suite:	
following? (Check as many as apply) RCRA Treatment Storage Disposal Factor RCRA Satellite Accumulation Area RCRA <90 Day Storage Area Did the spill occur inside or outside a build Did the spill occur on: (Check as many as apply) Samples Collected: None Water Certification certify that am knowledgeable about the inference of Certifying Official:	Soil Air Other:	□ Watercourse/drainage area, □ Solid Waste Management U □ None □ Inside Concrete Carpeted Floor Tile Wooden floor/deck If sa	if so please indicate Unit/Area of Concern, if so please indicate Outside Asphalt Graveled/Rocky Area Soil/Vegetated Area Other: amples were collected, indicate analytical suite:	

EPC-DO-QP-101	Revision: 3	Los Alamos
Effective Date: 08/07/2017	Next Review Date: 08/07/2020	NATIONAL LABORATORY —— EST. 1943

Environment, Safety, and Health Directorate

Environmental Protection and Compliance Division – Compliance Programs

Quality Procedure

Environmental Reporting Requirements for Releases or Events

Document Owner/Subject Matter Expert:

Name:	Organization:	Signature:	Date:
Brian Iacona	EPC-CP	Signature on File	4-27-17
Derivative Classifier:			
Name:	Organization:	Signature:	Date:

Approval Signatures:

Subject Matter Expert:	Organization:	Signature:	Date:
Brian Iacona	EPC-CP	Signature on File	4-27-17
Responsible Line Manager:	Organization:	Signature:	Date:
Michael Saladen	EPC-CP, Team Leader	Signature on File	7-21-17
Responsible Line Manager:	Organization:	Signature:	Date:
Anthony Grieggs	EPC-CP, Group Leader	Signature on File	8-3-17
Responsible Line Manager	Organization	Signature:	Date:
John Bretzke	EPC-DO, Division Leader	Signature on File	8-7-17

This copy is uncontrolled.

Users are responsible for ensuring they work to the latest approved version. To document a required read, Login to <u>UTrain</u>, and go to the Advanced Search.

Environmental Reporting Requirements	
for Releases or Events	

EPC-DO-QP-101	Page 2 of 23
Revision: 3	Effective Date: 08/07/2017

REVISION HISTORY

Document Number and Revision [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	02/09	New document
1	4/10	Revision and update
ENV-DO-QP-101 R2	6/12	Biennial Review/Revision, new template implemented.
EPC-DO-QP-101 R3	08/07/17	Revision and update. This document replaces ENV-DO-QP-101 R2. New document number reflects organizational name change.

Environmental Reporting Requirements for Releases or Events

EPC-DO-QP-101 Page 3 of 23

Revision: 3 Effective Date: 08/07/2017

Table of Contents

Qualit	ty Pro	cedure	1
Revisi	on Hi	story	2
Table	of Co	ntents	3
1.0	Intro	duction	4
	1.1	Purpose	4
	1.2	Applicability	4
2.0	Preca	autions and Limitations	4
3.0	Respo	onsibilities	4
4.0	Work	Processes	5
	4.1	Responsibility of On-Call Representative	5
	4.2	Follow-Up Reporting	6
	4.3	Summary of Policy Reporting	6
	4.4	Using this Procedure	6
	4.5	Determining if a Release is Reportable under RCRA	7
	4.6	Determining if a Release is Reportable under TSCA	7
	4.7	Determining if a Release is Reportable under the NM Water Quality Act or the CWA	8
		4.7.1 Reporting Requirement for Petroleum Storage Tanks	9
		4.7.2 Additional Reporting Requirements under the NPDES Pesticide General Permit	10
	4.8	Determining if a Release is Reportable under CERCLA or EPCRA	11
		4.8.1 Regulatory Classification of the Released Material	11
	4.9	Determining Release Impacts to Biological or Cultural Resources	13
	4.10	Reporting a Release or Event	13
		4.10.1 Steps to Notify LANL Management and DOE	14
5.0	Reco	rds	15
6.0	Defin	itions and Acronyms	16
	6.1	Definitions	16
7.0	Refer	rences	18
8.0	Attac	hments or Appendices	19
	Attac	hment 1: Emergency Notification Requirements for RCRA	20
	Attac	hment 2. Summary of Emergency Release or Event Reporting Requirements	21

Environmental Reporting Requirements	EPC-DO-QP-101	Page 4 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

1.0 INTRODUCTION

This Environmental Protection and Compliance Division (EPC-DO) procedure describes how to determine whether an unplanned release, spill, fire, or other event needs to be reported under environmental regulations and how to fulfill all immediate reporting requirements (within the first 24 hours). Emergency and abnormal event notification requirements for reporting to Laboratory and DOE management are specified in PD1200, Emergency Management, and P322-4, Performance Improvement from Abnormal Events. Environmental reporting requirements regarding releases or other events are included in this procedure.

1.1 Purpose

This procedure describes the actions that must be performed within the first 24 hours of the release. This procedure does **not** cover the response procedures for "continuous releases" under Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) and Emergency Planning and Community Right-to-Know Act (EPCRA) (see definitions) nor the follow-up notifications and reports.

1.2 Applicability

This procedure applies to EPC-DO on-call representatives and subject matter experts (SMEs) who must respond to any release, spill, or event at the Laboratory that may require immediate notification to local, state or federal regulatory agencies. For notifications to Pueblo Environmental Departments refer to ENV-DO-QP-111, Reporting Environmental Releases to Pueblo Governments.

2.0 PRECAUTIONS AND LIMITATIONS

The work described in this procedure includes field work that does <u>not</u> require an Integrated Work Document (IWD) and is rated as having a **LOW hazard** level.

3.0 RESPONSIBILITIES

The following personnel require training before implementing this procedure:

 EPC managers, designated on-call representatives, and SMEs who may be asked to fulfill immediate reporting requirements during release-related exercises or during actual releases

Annual retraining to this procedure is required. This procedure will be reviewed biennially by all affected personnel and updated as necessary.

Training to this procedure will be by "self-study" (reading) and is documented in accordance with the trainee's organization's procedure for training.

Actions specified within this procedure, unless preceded with "should" or "may", are to be considered mandatory (i.e., "shall", "will", "must").

Environmental Reporting Requirements	EPC-DO-QP-101	Page 5 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

4.0 WORK PROCESSES

Events covered by this procedure include detonation or burns of unstable material, leaking or compromised gas cylinders, puncturing of bulging containers, fires, explosions, chemical or radiological spills, wastewater spills, potable water discharges, and other unplanned releases at the Laboratory.

On a semi-annual basis, EPC-DO will prepare a list of individuals designated as on-call representatives and will designate the week each will be on-call. This list will be distributed to on-call representatives and Laboratory managers including Principal Associate Directorate for Operations (PADOPS), Associate Directorate for Environment, Safety, and Health (ADESH), Associate Directorate for Environmental Management (ADEM), Emergency Operations (SEO-DO), EPC-DO, Environmental Protection and Compliance Division Compliance Programs Group (EPC-CP), and Environmental Protection and Compliance Division Environmental Stewardship Group (EPC-ES). The on-call representative can be reached by pager at 505-664-7722.

4.1 Responsibility of On-Call Representative

The EPC on-call representative is the party primarily responsible for:

- determining if the incident will require immediate notification to external agencies in accordance with LANL, state, and federal regulatory reporting requirements
- notifying EPC Division management of immediate reporting requirements
- if needed, coordinating with other on-call SMEs and the Emergency Operations Center (EOC) to ensure the required notifications for environmental reporting and abnormal events are being addressed for the Laboratory

The EPC on-call representative is not responsible for the following and EOC will make these determinations:

- determining if the Resource Conservation Recovery Act (RCRA) Contingency Plan must be implemented
- if a shock-sensitive material or leaking or compromised gas cylinder constitutes an emergency

However, in order to ensure that the appropriate expertise is available for the affected media, the EPC on-call representative may immediately confer with an SME of the EPC group that has programmatic responsibility. If an SME from the responsible group is able to respond to the event, the <u>remaining steps in this procedure may be passed to that person.</u>

A list of contact numbers for on-call representatives and SMEs for EPC-CP and EPC-ES groups is available in the EPC-CP group office. The EPC-DO and SEO-DO may also be contacted to determine the on-call representative for each group.

Environmental Reporting Requirements	EPC-DO-QP-101	Page 6 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

4.2 Follow-Up Reporting

This procedure describes the initial external notifications (within the first 24 hours) to regulatory agencies. After completion of the steps in this procedure, the EPC group specifically responsible for compliance with the relevant regulations will complete the required notifications and reports, as applicable under the appropriate regulations, according to established procedures.

4.3 Summary of Policy Reporting

The EPC on-call representative and spill response SMEs have the authority and responsibility for deciding when to report an event and for making notifications to regulatory agencies within the applicable regulatory deadlines.

LANL management and Department of Energy Los Alamos Field Office (DOE LAFO) must be informed as soon as possible that a report was or will be made, but their approval is not required prior to the report being made to the regulatory agency. LANL management, with input from EPC SMEs, will determine if an ORPS (Occurrence Reporting Processing System) report or other type of Lessons Learned will be necessary.

NOTE: SEO-DO maintains a current list of on-call LANL managers.

4.4 Using this Procedure

This procedure has seven separate paths (and corresponding sections) to follow for determining if a release or event is reportable. Follow each of these paths to determine if one or more are applicable:

- Resource Conservation and Recovery Act (RCRA)
- Toxic Substances Control Act (TSCA)
- Clean Water Act (CWA), New Mexico Water Quality Act (NMWQA), and New Mexico Water Quality Control Commission (NMWQCC) Regulations
- Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) and Emergency Planning and Community Right-to-Know Act (EPCRA)
- Clean Air Act
- Endangered Species Act
- Bald and Golden Eagle Protection Act
- Migratory Bird Treaty Act
- New Mexico Wildlife Conservation Act
- National Environmental Policy Act
- National Historic Preservation Act
- Native American Graves Protection and Repatriation Act

Environmental Reporting Requirements	EPC-DO-QP-101	Page 7 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

Archaeological Resources Protection Act

Each release needs to be evaluated for all potential reporting requirements. For example, a Reportable Quantity (RQ), defined under CERCLA or EPCRA may not be met, **but the release may be reportable** under RCRA, New Mexico Water Quality Control Commission (NMWQCC), and/or Clean Water Act (CWA) requirements.

NOTE: The 24-hour deadline (immediate in some cases) applies regardless of whether it occurs during business hours, after business hours or on non-business days.

4.5 Determining if a Release is Reportable under RCRA

Follow the flow chart in Attachment 1 to determine if an event is reportable under RCRA regulations.

Under the RCRA permit requirements, the SEO-DO manager determines if the "RCRA Contingency Plan" provisions should be implemented. The EPC on-call representative or an EPC-CP SME performs notifications that may be required.

The SEO-DO Manager will normally attempt to contact the EPC-CP SME for guidance in making this decision. If the EPC-CP SME is successfully contacted, the completion of the remainder of this procedure may be passed on to this individual.

The EPC on-call representative makes the determination that one or more of these conditions occurred through consultation with EPC-CP and appropriate SMEs. 24-hour notification can be made by the EPC on-call representative or by an EPC SME.

The Emergency Operations Center (EOC) manager makes the determination that unstable chemicals, leaking or compromised gas cylinders represent an emergency situation and, typically with EPC-CP, how best to respond. 24-hour notification can be made by the on-call representative or EPC-CP SME.

If a release/event is reportable under RCRA rules, determine if the release/event is reportable under other rules and proceed to the Section 4.10 *Reporting a Release or Event*.

4.6 Determining if a Release is Reportable under TSCA

In practice, only spills of Polychlorinated Biphenyls (PCBs) or PCB-suspect untested mineral oil to the environment (generally outdoors or with the potential to reach the outdoors) are reportable. Spills that are contained indoors are generally not reported.

A discharge of PCBs is reportable to the Environmental Protection Agency (EPA) under TSCA if 1 pound of PCBs by weight is released [40 Code of Federal Regulations (CFR) 761.125(a)(1)]. Notify the EPA regional office and proceed with the immediate clean up requirements noted in 40 CFR 761.125(a)(1) in the shortest possible time after discovery, but in no case later than 24 hours after discovery. Additionally, reporting requirements are triggered if over 270 gallons of untested mineral oil suspected of containing PCBs has been spilled.

Follow the steps in *Determining if a Release is Reportable under CERCLA, EPCRA, or Other Regulations* to determine if the RQ for PCBs has also been exceeded.

Environmental Reporting Requirements	EPC-DO-QP-101	Page 8 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

There are six items containing PCBs that are out of service at the Chemistry and Metallurgy Research (CMR) Building. All other known PCB equipment at the Laboratory has been taken out of service and disposed of in accordance with TSCA regulations.

If a release is reportable under TSCA, continue through the next sections to determine if the release/event is reportable under other rules and proceed to *Reporting a Release or Event* and determine if additional reporting is necessary.

If the spill is ...

equal to or over 1 pound by weight of PCBs (TSCA) or greater than 270 gallons of untested mineral oil suspected of containing PCBs

Then...

Report to the National Response Center (1-800-242-8802) immediately (within 15 minutes of discovery). Additionally, contact EPA Region 6 (Office of Prevention, Pesticides and Toxic Substances Branch) through EPA's 24-hour spill response number 866-372-7745 as soon as possible after discovery but no later than 24 hours after discovery.

4.7 Determining if a Release is Reportable under the NM Water Quality Act or the CWA

20.6.2.1203 New Mexico Administrative Code (NMAC) Reporting

The NM Water Quality Act (NMWQA) does not use Reportable Quantities (as described in the next section). Instead the NM Water Quality Control Commission (NMWQCC) regulations state: "With respect to any discharge from any facility of oil or other water contaminant, in such quantity as may with reasonable probability injure or be detrimental to human health, animal or plant life, or property, or unreasonably interfere with the public welfare or the use of property, notifications (to the New Mexico Environment Department (NMED)) and corrective actions are required."

The above rule requires the use of professional judgment to determine if reporting is required. No quantifiable metric is available to assist in making this determination. The EPC on-call representative or SME has the authority and responsibility to make this determination.

Additionally, unplanned releases of potable water or steam condensate require reporting pursuant to 20.6.2.1203 NMAC if the release is greater than 5,000 gallons, reaches a watercourse, or if the release adversely impacts a Solid Waste Management Unit (SWMU) or Area of Concern (AOC) as directed in the LANL Liquid Discharge Reporting Guidance (Decision Tree), dated March 10, 2009. Contact ADEM to confirm the location and potential impacts to SWMUs or AOCs from any releases that may occur.

Groundwater Discharge Permit Reporting

The Laboratory has four current Groundwater Discharge Permits (DPs) that include notification and reporting requirements in the event of an unpermitted discharge. Spills of **any volume** associated with any of the Groundwater DPs require reporting to NMED pursuant to 20.6.2.1203 NMAC.

Environmental Reporting Requirements	EPC-DO-QP-101	Page 9 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

1. DP-857: Sanitary Waste Water System (SWWS) Plant, Sanitary Effluent Reclamation Facility (SERF), and Sigma Mesa Evaporation Basins. Permit Condition No. 44.

The unauthorized release of untreated and treated sanitary wastewater, reuse wastewater, blended wastewater, and reject wastewater would be subject to reporting under Condition No. 44.

2. DP-1589: Septic Tank/Disposal Systems. Permit Condition No. 23.

The unauthorized release of untreated wastewater, septage, treated wastewater surfacing from failing disposal systems (leach fields), and treated wastewater surfacing from overflowing septic tanks would be subject to reporting under Condition No. 23.

3. DP-1793: Land Application of Treated Groundwater. Permit Condition No. 17.

The unauthorized release of untreated or treated groundwater that does not constitute land application, as defined in EPC-CP-QP-010: Land Application of Groundwater, would be subject to reporting under Condition No. 17.

4. DP-1835: Injection of Treated Groundwater to Class V Underground Injection Control (UIC) Wells. Permit Condition No. 22.

The unauthorized release of treated or untreated groundwater that does not constitute injection into a Class V UIC well, as defined in Discharge Permit DP-1835, would be subject to reporting under Condition No. 22.

Clean Water Act Reporting

Oil discharges (film/sheen/discoloration) to water in stream channels must also be reported to the National Response Center (NRC) immediately (within 15 minutes of discovery) pursuant to 40 CFR §110.6.

National Pollutant Discharge Elimination System (NPDES) Outfall Reporting

The EPC-DO on-call SME must provide notification to the NPDES Outfall Permit Program Lead and/or the EPC-CP Water Quality Team Leader in the event of a leak or unplanned release from an NPDES permitted outfall upon discovery in order to meet applicable reporting requirements.

4.7.1 Reporting Requirement for Petroleum Storage Tanks

As defined in 20.5.7 NMAC, the NMED requires verbal reporting within 24 hours of a petroleum product release from regulated tanks to the NMED Petroleum Storage Tank Bureau (PSTB) when there is:

- any suspected or confirmed release of regulated substances
- evidence of release of regulated substances
- unusual operational conditions (that would cause concern about a release)
- monitoring results that show loss from the system

Environmental Reporting Requirements	EPC-DO-QP-101	Page 10 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

Regulated tanks include those with a capacity between 1,320 gallons and 55,000 gallons. Regulated substances for Aboveground Storage Tanks includes, but is not limited to petroleum and petroleum-based substances comprised of a complex blend of hydrocarbons derived from crude oil through processes of separation, conversion, upgrading and finishing, such as motor fuels (including ethanol-based motor fuels), jet fuels, distillate fuel oils, residual fuel oils, lubricants, petroleum solvents, and used oils.

Notice of any suspected or confirmed release from a storage tank system needs to be completed within 24 hours. Contact the EPC-CP Aboveground Storage Tank (AST) Program Lead and/or the EPC-CP Water Quality Team Leader prior to completing any external notifications. The PSTB can be reached at 476-4397 during business hours and 827-9329 (NMED Emergency Spill Hotline) during non-business hours. A written report describing the spill, release or suspected release and any investigation or follow-up action needs to be submitted to the PSTB within 14 days of the incident.

4.7.2 Additional Reporting Requirements under the NPDES Pesticide General Permit

Adverse incidents require reporting to the EPA under the NPDES Pesticide General Permit (PGP). An adverse incident is defined as an unusual or unexpected incident resulting from pesticide applications that an Operator has observed upon inspection or of which the Operator otherwise becomes aware, in which:

- 1. There is evidence that a person or non-target organism has likely been exposed to a pesticide residue, <u>and</u>
- 2. The person or non-target organism suffered a toxic or adverse effect.

The phrase <u>toxic or adverse effect</u> includes effects that occur within Waters of the United States on non-target plants, fish, or wildlife that are unusual or unexpected (e.g., effects are to organisms not otherwise described on the pesticide product label or otherwise not expected to be present) as a result of exposure to a pesticide residue, and may include:

- Distressed or dead juvenile and small fishes
- Washed up or floating fish
- Fish swimming abnormally or erratically
- Fish lying lethargically at water surface or in shallow water
- Fish that are listless or nonresponsive to disturbance
- Stunting, wilting, or desiccation of non-target submerged or emergent aquatic plants
- Other dead or visibly distressed non-target aquatic organisms (amphibians, turtles, invertebrates, etc.)

The phrase <u>toxic or adverse effects</u> also includes any adverse effects to humans (e.g. skin rashes) or domesticated animals that occur either from direct contact with or as a secondary effect from a discharge (e.g., sickness from consumption of plants or animals containing pesticides) to Waters of the United States that are temporally and spatially related to exposure to a pesticide residue (e.g. vomiting, lethargy).

Environmental Reporting Requirements	EPC-DO-QP-101	Page 11 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

If an Operator observes or otherwise becomes aware of an adverse incident due to pesticide application, the Operator must notify the EPA Incident Reporting contact within 24 hours of the Operator becoming aware of the adverse incident. EPA Incident Reporting Contacts are listed at https://www.epa.gov/npdes/pesticide-permitting.

If an Operator becomes aware of an adverse incident affecting a federally listed threatened or endangered species or its federally designated critical habitat, which may have resulted from a discharge from the Operator's pesticide application, the Operator must immediately (within 15 minutes of discovery) notify the U. S Fish and Wildlife Service. This notification must be made by phone to the contact listed on the EPA's website (https://www.epa.gov/npdes/pesticide-permitting).

4.8 Determining if a Release is Reportable under CERCLA or EPCRA

Under CERCLA or EPCRA, an RQ is the threshold which requires regulatory notification of a release. An RQ is based on the quantity of chemical released within any 24-hour period. CERCLA RQs of hazardous substances are listed in 40 CFR § 302.4. If an RQ is met or exceeded, an immediate (within 15 minutes of discovery) notification must be made to the NRC (1-800-424-8802) pursuant to 40 CFR §302.6. If a release of an airborne radioactive material exceeds an RQ, the EPA Region 6 Health Physicist (Office-(214) 665-8541; Mobile-(214) 755-1530; Home-(972) 937-1900) must also be verbally notified after the NRC notifications have been completed.

A release is reportable under EPCRA if a release of a hazardous or extremely hazardous substance listed in 40 CFR Part 355 Appendices A and B occurs. The chemicals that have not been assigned RQs by the EPA have been given statutory RQs of one pound by Congress. If an RQ established under EPCRA is met or exceeded, an immediate (within 15 minutes of discovery) notification must be made to the Local Emergency Planning Committee (LEPC) community emergency coordinator and to the State Emergency Response Commission (SERC) (see Attachment 2).

The lists of CERCLA hazardous substances and EPCRA extremely hazardous substances are two separate lists that include a number of common substances. However, not all extremely hazardous substances are listed hazardous substances. In some instances, a release of an extremely hazardous substance may be reportable under EPCRA but not reportable under CERCLA.

Releases that occur within a closed space with no emissions to the ambient environment are exempt from EPCRA and CERCLA reporting requirements.

NOTE: Response procedures for "Continuous Releases" are not covered in this procedure.

4.8.1 Regulatory Classification of the Released Material

The on-call EPC SME will determine the regulatory classification of the substance released with respect to the hazard classifications:

Extremely Hazardous Substance (EHS) and/or Hazardous Substance (HS)

Often during the course of an emergency, complete information will not be available regarding type and amount of material released. In this case, best professional judgment must be used to establish the level of confidence associated with the estimates. If the uncertainty is high enough that future

Environmental Reporting Requirements	EPC-DO-QP-101	Page 12 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

estimates may require reporting, it is best to be conservative and report the release following the reporting requirements detailed in Section 4.10 *Reporting a Release or Event*.

After determining the RQ of a released material, the EPC on-call representative or SME will perform the following steps to determine if an RQ has been released.

Step		Action	
1	Obtain an estimate of the quantity and type of material released (e.g. 4 pounds of chlorine gas or 150 curies of tritium).		
2	Compare this quantity against the RQs provided in 40 CFR Table 302.4 and 40 CFR §355, Appendices A and B.		
3	If this is an airborne release of radioactive materials, immediate (within 15 minutes of discovery) reporting to the NRC and the EPA Region 6, Regional Health Physicist is required if the RQ has been exceeded. Note that for radioactive materials, the RQ is provided in activity units (curies or becquerels). Also note that some materials have an RQ value for both chemical exposure (Table 302.4) and for radiological exposure (Appendix B to §302.4). In these cases, the RQ applying to the smallest quantity of material will apply.		
	within 24 hours of the release. This do	radiological dose assessment must also be performed ose assessment should be made by an environmental the on-call individual should contact an EPC health	
	Immediate evaluation – RQ compariso	on (of a radioactive material release)	
	If the release	Then	
	Is equal to or greater than the RQ	Proceed to section 4.10 Reporting a Release or Event.	
	Is less than the RQ	No immediate reporting is required; contact EPC environmental health physicist to complete follow-up dose assessment.	
4	If this is a release of non-rad material, it is reportable if the RQ is exceeded.		
	If the amount released is,	amount released is, Then	
	Equal to or greater than the RQ	Proceed to Section 4.10 Reporting a Release or Event.	
	Less than the RQ	Proceed to Step 5	
5	Continue to re-evaluate the release as new data becomes available. Perform Steps 1 through 4 as necessary.		

Environmental Reporting Requirements	EPC-DO-QP-101	Page 13 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

4.9 Determining Release Impacts to Biological or Cultural Resources

There are laws and regulations related to protection of biological and cultural resources which are applicable to the Laboratory. These laws and regulations include:

- National Environmental Policy Act
- Endangered Species Act
- Bald and Golden Eagle Protection Act
- Migratory Bird Treaty Act
- New Mexico Wildlife Conservation Act
- New Mexico Endangered Species Act
- National Historic Preservation Act
- Native American Graves Protection and Repatriation Act
- Archaeological Resources Protection Act

Reporting of impacts to biological or cultural resources under the preceding federal laws is not specifically defined. However, the EPC on-call SME should utilize the Decision Support Application (DSA) to determine if the release impacted a Biological or Cultural Site. The DSA layer 'Federally Listed Species Habitat' contains Endangered Species habitat boundaries. The DSA 'Cultural Resources-Buffered Sites' layer contains the boundaries of the Cultural Sites (Please note-information contained in these layers is Official Use Only). Notify the respective Biological or Cultural SME within one business day if the release impacted either of these areas. The Biological or Cultural SMEs will handle any additional reporting requirements.

Additionally, if there is a release of contaminants to a wetland or destruction of a wetland, OR if the event could result in the "take" of a threatened or endangered species (i.e., a wildfire), the EPC oncall representative or SME will notify the Biological SME within one business day of the event. The Biological SME will complete any additional reporting requirements.

4.10 Reporting a Release or Event

If a release or event is reportable (as determined by one or more of the previous sections), the Laboratory is required to meet certain reporting requirements. The emergency notification requirements must be followed upon determination that a release or event is reportable.

For informational purposes, a Summary of Emergency Release or Event Reporting Requirements is provided in Attachment 2. This document summarizes the primary statutes and the associated reporting requirements.

Maintain a notebook to record pertinent information about the release and to document the actions taken (see Section 5.0 *Records*).

Any release to the environment that has been determined to be reportable by the EPC on-call representative or SME shall be reported through the LANL management chain in accordance with PD1200, Emergency Management and P322-4, Performance Improvement from Abnormal Events.

Environmental Reporting Requirements	EPC-DO-QP-101	Page 14 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

Los Alamos National Security (LANS) management and DOE shall be notified if a release notification to state or federal regulatory agencies is required. Management approval is not required prior to completing environmental notifications to the regulatory agencies in order to assure that the deadline for reporting is not exceeded.

Perform the following steps immediately after establishing that reporting is required:

Step	Action
1	Compile release information including :
	The source, cause, type and quantity of the release
	Time and duration of the release
	Extent of any protective and corrective actions taken
	 Name, address, and telephone number of the person to contact for further information
	Whether the substance is an HS or EHS
	 Associated health risks and medical attention necessary for exposed individuals
	 If available, information concerning the release of any hazardous and/or mixed waste which may endanger public or private drinking water supplies
	 Assessment of actual or potential hazards to human health or the environment outside the facility
	 If available, estimated quantity and disposition of recovered material that resulted from the incident
	 Precautions to take due to the release/event, including, in the case of fire, those associated with special hazards due to hazardous and/or mixed waste
	 Any other information which may help emergency personnel responding to the incident
	Environmental media impacted from the release
2	Notify LANL management, DOE, and the respective Facilities Operations Division (FOD). Note:
	Management approval is not required prior to completing environmental notifications to the regulatory agencies in order to assure that the deadline for reporting is not exceeded.
3	Provide notification to the regulatory agency as required by the applicable regulation(s) detailed in Sections 4.5 - 4.9. Reference Attachment 2 for a summary of the applicable
	reporting requirements.
4	Notify programmatic SMEs that may be impacted or required to complete follow up reporting.

4.10.1 Steps to Notify LANL Management and DOE

The EPC on-call representative will complete the following steps to provide notification to LANL Management and DOE.

Step	Action
1	Determine that a release to the environment is reportable to state or federal entities as

Environmental Reporting Requirements	EPC-DO-QP-101	Page 15 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

	required under applicable regulations.
	NOTE: Occurrence Reporting and Procession System (ORPS) reporting is a FOD and Responsible Associate Director (RAD) responsibility and commonly they will seek advisement from EPC SMEs.
2	Provide notification to the EPC-CP Water Quality Team Leader, the EPC-CP Group Leader, the EPC-DO Division Leader, and DOE LAFO program contact of the release and the required external notifications.
3	Complete environmental reporting to state and federal agencies in accordance with all applicable regulations.
4	Notify the appropriate program SME that may be impacted or be required to complete following up release reporting.

After all the above notifications have been made, or when requested, the EPC on-call representative or SME will hand off responsibility for additional actions and follow-up to the affected environmental group. (The group that will be responsible will depend on the type and location of the release and the governing regulations or statutes.)

In order to communicate events at LANL which may impact the public and or the environment, EPC staff may provide a courtesy notification to New Mexico Environment Department of events that may not require formal regulatory notification. Examples of such events in the past have been small wild land fires.

5.0 RECORDS

The following records are generated as a result of this procedure and are maintained in accordance with ADESH-AP-006 Records Management Plan and P1020-1, Laboratory Records Management:

- Field documentation of the release, including:
 - Time and date of the release
 - Time, date, and description of notifications
 - Location and source of the release
 - Type of material released
 - Quantity of material released
 - Impacted media
 - Time release was stopped
 - Any immediate mitigation actions taken to contain or control the release
 - Documentation of any verbal notifications
 - Samples taken
- Copies of any written notifications generated

Environmental Reporting Requirements	EPC-DO-QP-101	Page 16 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

- Documentation of any analytical results, and quality assurance of results
- Contingency and / or emergency plan documentation
- Documentation of any RCRA permit non-compliance that threatens human health and environment
- Documentation of treatment of any RCRA unstable chemicals, leaking or compromised gas cylinders

6.0 DEFINITIONS AND ACRONYMS

6.1 Definitions

ADESH – Associate Directorate for Environment, Safety, and Health

ADEM – Associate Directorate for Environmental Management

AOC – Area of Concern

AST – Aboveground Storage Tank

CAA – Clean Air Act

CERCLA – Comprehensive Environmental Response, Compensation, and Liability Act

CMR – Chemistry and Metallurgy Research

CFR – Code of Federal Regulations

Continuous Release – A release is continuous if it "occurs without interruption or abatement or if it is routine, anticipated, intermittent, and incidental to normal operations or treatment processes." The release must also be "stable in quantity and rate," which means that it must be predictable and regular in the amount and rate of emission. The response procedures for continuous releases are not covered by this document. See guidance in Reporting Continuous Releases of Hazardous and Extremely Hazardous Substances under CERCLA and EPCRA.

CWA - Clean Water Act

DOE LAFO – Department of Energy Los Alamos Field Office

DSA – Decision Support Application

Environment – Includes "water, air, land, and the interrelationship which exists among and between water, air, land, and all living things." (40 CFR 355.20)

EOC – Emergency Operations Center

EPA – Environmental Protection Agency

EPC-DO – Environmental Protection and Compliance Division

EPCRA – Emergency Planning and Community Right-to-Know Act

EPC-CP – Environmental Protection and Compliance Division Compliance Programs Group

Environmental Reporting Requirements	EPC-DO-QP-101	Page 17 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

EPC-ES – Environmental Protection and Compliance Division Environmental Stewardship Group

Extremely Hazardous Substance (EHS) – EPCRA establishes emergency reporting requirements for extremely hazardous substances in 40 CFR 355, Appendix A. All of these substances are also CWA and CERCLA "hazardous" substances.

FOD – Facility Operations Director

GWDP-Ground Water Discharge Permit

Hazardous Substance (HS) – These substances are summarized in 40 CFR Part 302. As used in this context, refers to: (1) any elements, compounds, mixtures, solutions, or substances specially designated by EPA under Section 311 of the Clean Water Act (CWA) (40 CFR 116.4); (2) any toxic pollutants listed under Section 307(a) of the CWA; (3) any hazardous substances regulated under Section 311 (b)(2)(A) of the CWA; (4) any listed or characteristic RCRA hazardous waste (40 CFR 261), (5) any hazardous air pollutants listed under Section 112 of the Clean Air Act (CAA); or (6) any imminently hazardous chemical substances or mixtures regulated under Section 7 of the Toxic Substances Control Act (TSCA).

IWD – Integrated Work Document

LANL – Los Alamos National Laboratory

LANS – Los Alamos National Security

LEPC – Local Emergency Planning Committee

NMAC - New Mexico Administrative Code

NMED – New Mexico Environment Department

NMWQA – New Mexico Water Quality Act

NMWQCC – New Mexico Water Quality Control Commission

NPDES – National Pollutant Discharge Elimination System

NRC – National Response Center

ORPS – Occurrence Reporting and Processing System

OSC – On-Scene Commander

PADOPS – Principal Associate Directorate Operations

PCBs – Polychlorinated Biphenyls

PGP – Pesticide General Permit

PST – Petroleum Storage Tank

PSTB – Petroleum Storage Tank Bureau

RAD – Responsible Associate Director

RCRA – Resource Conservation and Recovery Act

Environmental Reporting Requirements	EPC-DO-QP-
for Releases or Events	Revision: 3

EPC-DO-QP-101	Page 18 of 23
Revision: 3	Effective Date: 08/07/2017

Release – Any unpermitted spilling, leaking, pumping, pouring, emitting, emptying, discharging, injecting, escaping, leaching, dumping, or disposing of contaminants into the environment, excluding: (1) emissions from the engine exhaust of any vehicle, (2) certain releases of source, byproduct, or special nuclear material from a nuclear incident, or (3) normal application of fertilizer.

RQ – Reportable Quantity

SARA – Superfund Amendments and Reauthorization Act

SDS – Safety Data Sheet

SERC – State Emergency Response Commission

SERF – Sanitary Effluent Reclamation Facility

SEO-DO –Security and Emergency Operations Division

SME – Subject Matter Expert

SWMU – Solid Waste Management Unit

SWWS - Sanitary Waste Water System

TSCA – Toxic Substances Control Act

UIC – Underground Injection Control

7.0 REFERENCES

The following documents are referenced in this procedure:

- 40 CFR 302, Designation, Reportable Quantities, and Notification
- 40 CFR 261, 264 Subpart D 270.30
- DOE guidance document PCB Spill Response and Notification Requirements
- (EH-231-059/1294), available on the EPC-CP web page
- DOE Office of Environmental Guidance, CERCLA Information Brief, EH-231-001-0490 (April 1990)
- EPA Web Site: http://www.epa.gov/
- EPCRA Information Web Site: http://www.chemicalspill.org/EPCRA-facilities/spill.html
- Federal Register, Volume 67, No. 47, Notices FRL-7172-4, Guidance on the CERCLA Section 101(10)H, Federally Permitted Release Definition for Certain Air Emissions
- PD1200, Emergency Management
- P322-3, Performance Improvement from Abnormal Events
- LANL RCRA Permit No. NM0890010515-1
- LANL NPDES Permit No. NM0028355

Environmental Reporting Requirements	EPC-DO-QP-101	Page 19 of 23
for Releases or Events	Revision: 3	Effective Date: 08/07/2017

- National Response Center (NRC) Web Site: http://www.nrc.uscg.mil/
- NMWQCC Regulations, 20.6.2 NMAC, dated December 1, 2001
- P407, Water Quality
- P1020-1, Laboratory Records Management
- ADESH-AP-006, Records Management Plan

8.0 ATTACHMENTS OR APPENDICES


Attachment 1: Emergency Notification Requirements for RCRA

Attachment 2: Summary of Emergency Release or Event Reporting Requirements

Environmental Reporting Requirements
for Releases or Events

EPC-DO-QP-101	Page 20 of 23
Revision: 3	Effective Date: 08/07/2017

Attachment 1: Emergency Notification Requirements for RCRA



Environmental Reporting Requirements
for Releases or Events

EPC-DO-QP-101	Page 21 of 23
Revision: 3	Effective Date: 08/07/2017

Attachment 2: Summary of Emergency Release or Event Reporting Requirements

NOTE: This is only a guide and does not cover all federal, state, or permit reporting requirements. Refer to the Code of Federal Regulations and the RCRA Permit for more details regarding these regulations.

STATUTE	REGULATIONS	INCIDENT	Immediate Reporting Requirements	Follow Up Reporting Requirements
Clean Water Act	40 CFR §110.6	Oil discharge (film/sheen/discoloration) to water surface or shoreline, or violation of water quality standards.	Immediately (within 15 minutes of discovery) notify the National Response Center.	Follow-up not required.
Clean Water Act	Part III of NPDES Permit No. NM0028355	Leak or unplanned release from an NPDES permitted outfall.	Notify the NPDES Outfall Permit Program Lead and EPC-CP Water Quality Team Leader upon discovery. The program lead or the EPC-CP Water Quality Team Leader will complete initial reporting requirements as required.	Required follow up reporting will be completed by the NPDES Outfall Permit Program Lead and EPC-CP Water Quality Team Leader.
Clean Water Act (CWA)-NPDES Pesticide General Permit	40 CFR §122.28	Adverse incident which includes evidence that a person or non-target organism has been exposed to a pesticide residue or the person or non-target organism suffered a toxic or adverse effect.	Notify the EPA Region 6 Pesticide Permitting contact (214)665-7500 within 24 hours.	Submit a 30 Day Adverse Incident Written Report to the EPA Regional Office.
New Mexico Water Quality Control Commission Regulations (NMWQCC Regulations)	20.6.2.1203 NMAC	Discharge from any facility of oil or other water contaminant, in such quantity as may with reasonable probability injure or be detrimental to human health, animal or plant life, or property, or unreasonably interfere with the public welfare or use of the property.	Notify the New Mexico Environment Department 505-827-9329 within 24 hours.	Submit 7 and 15 Day written follow up Corrective Action Reports (Copy EPA Region 6 on the 7 and 15 Day Reports).

Environmental Reporting Requirement	S
for Releases or Events	

 EPC-DO-QP-101
 Page 22 of 23

 Revision: 3
 Effective Date: 08/07/2017

STATUTE	REGULATIONS	INCIDENT	Immediate Reporting Requirements	Follow Up Reporting Requirements
New Mexico Water Quality Control Commission Regulations (NMWQCC Regulations)	20.6.2.3104 NMAC	Unplanned release of any volume from an activity or facility covered under an active Groundwater DP: DP-857: SWWS Plant, SERF, and Sigma Mesa Evaporation Basins DP-1589: Septic Tank/Disposal Systems DP-1793: Land Application of Treated Groundwater DP-1835: Injection of Treated Groundwater to Class V UIC Wells	Notify the New Mexico Environment Department 505-827-9329 within 24 hours.	Submit 7 and 15 Day written follow up Corrective Action Reports (Copy EPA Region 6 on the 7 and 15 Day Reports)
New Mexico Environmental Improvement Board Regulation	20.5.7 NMAC	A release of a petroleum product from regulated aboveground storage tank.	Contact the EPC-CP AST Program Lead and/or the EPC-CP Water Quality Team Leader prior to completing any external notifications. If required, the Petroleum Storage Tank Bureau (476- 4397) or NMED Emergency Spill Hotline (827-9329) must be contacted within 24 hours.	A written report describing the spill, release or suspected release and any investigation or follow-up action needs to be submitted to the PSTB within 14 days of the incident.
Comprehensive Environmental, Response, Compensation, and Liability Act (CERCLA)	40 CFR §302.6(a)	Hazardous substance (listed in 40 CFR Table 302.4) release (Equal to or greater than an RQ).	Immediately (within 15 minutes of discovery) notify the National Response Center 1-800-424-8802.	Follow-up not required.
Emergency Planning and Community Right- to-Know Act (EPCRA)	40 CFR§ 355.40	Release of an extremely hazardous substance (listed in 40 CFR Part 355 Appendices A and B) or CERCLA hazardous substance (listed in 40 CFR Table 302.4) equal to or greater than RQ.	Immediately (within 15 minutes of discovery) notify the LEPC (505-662-8283) the SERC (505-476-9635). Immediately notify the 911 operator for a release that occurs during transportation or from storage incident to transportation.	A written follow-up emergency notice must be submitted to the LEPC and SERC as soon as practicable after the release.

Environmental	Reporting	Requirements
for Releases or	Events	

 EPC-DO-QP-101
 Page 23 of 23

 Revision: 3
 Effective Date: 08/07/2017

STATUTE	REGULATIONS	INCIDENT	Immediate Reporting Requirements	Follow Up Reporting Requirements
Resource Conservation and Recovery Act (RCRA)	40 CFR 262.34, 263.30, 264.51, 264.56 & .196, 265.51, .56 & .196, 270.14, & .30, 273.17, .37 & .54, 279.43 & .53, 280.50, .52, .53, .60, &.61	Release of hazardous or mixed waste from a permitted unit, interim status, less than 90 day area or a satellite accumulation area which the RCRA Permit Contingency Plan was triggered.	Notify NMED Hazardous Waste Bureau within 24 hours (24 hour emergency phone number: 827-9329; Non-emergency phone number: 476-6000) See Attachment 1 for additional details.	Submit written report to NMED HWB within 5 days.
Clean Air Act/ Radionuclide NESHAP	40 CFR 61, Subpart H	Airborne release of radioactive material in excess of an RQ.	Notify the EPA Region 6 Health Physicist (Office- (214) 665-8541; Mobile- (214) 755-1530; Home – (972) 937-1900) immediately after providing notification to the NRC.	Follow-up not required.
Toxic Substance Control Act (TSCA)	40 CFR 761.120, 761.125	Over 1 pound by weight of PCBs (TSCA) or greater than 270 gallons of untested mineral oil suspected of containing PCBs.	Contact the National Response Center (1-800- 242-8802) and the EPA Region 6 Office of Prevention, Pesticides, and Toxic Substances Branch (1- 866-372-7745) as soon as possible after discovery, but no later than 24 hours after discovery.	Within 24 hours. Follow-up: as required by agency.

ENV-CP-QP-045.1 Effective Date: September 5, Next Review Date: August 5,



2013 2015

Environment, Safety, Health Directorate

Anthony Grieggs

Environmental Protection – Compliance Programs Quality Procedure

ENV-CP Group Leader

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

Reviewers: Name: Organization: Signature: Date: Melanie Lamb ADESH-OIO, QA 8/28/13 Signature on file Specialist **Derivative Classifier:** ☐ Unclassified ☐ DUSA ENVPRO Name: Signature: Date: Organization: Ellena Martinez ADESH-OIO Signature on file 8/28/13 **Approval Signatures:** Subject Matter Expert: Organization: Signature: Date: Holly Wheeler **ENV-CP** Signature on file 8/29/13 Responsible Line Manager: Signature: Organization: Date: Michael Saladen **ENV-CP Team Lead** Signature on file 8/29/13 Responsible Line Manager: Signature: Organization: Date:

CONTROLLED DOCUMENT

9/5/13

This copy is uncontrolled. The controlled copy can be found on the ENV Division Web page.

Users are responsible for ensuring they work to the latest approved version.

Signature on file

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 2 of 26
the MSGP	Effective Date: September 5, 2	2013

History of Revisions

Document Number [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	03/11	New Document.
1	04/13	Biennial Review and Revision
2	09/13	Biennial Review and Revision

No. ENV-CP-QP-045.1

Page 3 of 26

Effective Date: September 5, 2013

Table of Contents

1.0	PUR]	POSE	4
2.0	SCO	PE	4
	2.1	Hazard review	4
3.0	RESI	PONSIBILITIES	4
•••	3.1	Prerequisites	
4.0	DOC	UMENT CONTROL/RECORDS MANAGEMENT	4
5.0	WOF	RK PROCESSES	5
	5.1	Equipment and Tools	
	5.2	ISCO Sampler Installation	6
	5.3	Configuring ISCO 3700 Samplers	7
	5.4	Programming ISCO 3700 Samplers	7
	5.5	Activating ISCO 3700 Samplers	8
	5.6	Configuring ISCO Avalanche Samplers	9
	5.7	Programming ISCO Avalanche Samplers	10
	5.8	Activating ISCO Avalanche Samplers	10
	5.9	Standing Down or Winterizing Samplers	
	5.10	Sampler Reset and Re-initialization After Sample Collection	12
	5.11	Removing a Sampler	12
6.0	REF	ERENCES	12
7.0	DEF	INITIONS	13
8.0	ATT	ACHMENTS	13
	Attac	hment 1- LANL MSGP ISCO Sampler Installation Form 045-1	14
	Attac	hment 2- Wiring Diagram for Avalanche Sampler	15
	Attac	hment 3 – Battery Photovoltaic Connection Wiring	16
	Attac	hment 4 - ISCO 3700 Configuration Settings	18
	Attac	hment 5 – ISCO 3700 Program Sequence	19
	Attac	hment 6 – LANL MSGP ISCO Sampler Activation Form 045-3	22
	Attac	hment 7 – ISCO Avalanche Configuration Settings	23
		hment 8 – ISCO Avalanche Program Sequence	
	Attac	hment 9 – LANL MSGP ISCO Sampler Winter Shut-Down Form 045-5	25
	Attac	hment 10 – LANL MSGP ISCO Sampler Decommission Form 045-6	26

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 4 of 26
the MSGP	Effective Date: September 5,	2013

1.0 PURPOSE

This procedure describes the installation, setup, programming, and operation of Teledyne ISCO Avalanche and Model 3700 full-size portable automated samplers used to collect storm water runoff samples for the Multi-Sector General Permit (MSGP).

2.0 SCOPE

This procedure applies to all ENV-CP technical staff and contractor personnel conducting installation, operation, maintenance and sampling activities at single stage stations used for monitoring under the MSGP.

2.1 HAZARD REVIEW

Hazards in the work described in this procedure are controlled thorough site specific <u>IWDs</u>. The hazard level of the activities in this procedure is <u>moderate</u>.

3.0 RESPONSIBILITIES

The following personnel require training before implementing this procedure:

 This procedure applies to all ENV-CP MSGP storm water compliance personnel conducting installation, operation, maintenance and sampling activities at MSGP single stage monitoring stations.

The training method for this procedure is "self-study" (reading). For ENV-CP staff, this is documented in accordance with ENV-DO-QP-115, *Personnel Training*. Other participating groups may require training documentation pursuant to local procedures.

Actions specified within this procedure, unless proceeded with "should" or "may," are to be considered mandatory (i.e., "shall", "will", "must").

3.1 Prerequisites

Personnel performing this procedure will be familiar with the most current versions of the following procedures and operation manuals:

- ENV-CP MSGP Sampling and Analysis Plan for the current monitoring year
- Manual for Teledyne ISCO Sampler Model 3700.
- Manual for Teledyne ISCO Avalanche refrigerated sampler
- Facility/FOD specific IWDs for the MSGP

4.0 DOCUMENT CONTROL/RECORDS MANAGEMENT

The following records are generated as a result of this procedure and are maintained in accordance with ENV-DO-QP-110, *Records Management Program* with the originals on file at ENV-CP offices:

Completed work orders for:

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 5 of 26
the MSGP	Effective Date: September 5,	2013

- LANL MSGP ISCO Sampler Installation Form 045-1(Attachment 1)
- LANL MSGP ISCO Sampler Activation Form 045-3 (Attachment 6)
- LANL MSGP ISCO Sampler Winter Shutdown 045-5 (Attachment 9)
- LANL MSGP ISCO Sampler Decommission 045-6 (Attachment 10)

5.0 WORK PROCESSES

The discharge of storm water from industrial facilities at Los Alamos National Laboratory (LANL, the Laboratory) is regulated under the National Pollutant Discharge Elimination System (NPDES) *Multi-Sector General Permit for Storm Water Discharges Associated with Industrial Activity* (MSGP). The current MSGP became effective on September 29, 2008 pursuant to 73 FR 56572. The Laboratory's MSGP permit coverage (Permit Tracking No. NMR05GB21) requires storm water quality monitoring to evaluate the overall effectiveness of control measures. ISCO samplers coupled with Model 1640 sampler actuators are used at MSGP Program monitoring stations. Refrigerated (Avalanche) and/or non-refrigerated (Model 3700) samplers may be deployed; and may be configured with multi-battery arrays, solar panels, and surge protectors.

5.1 EQUIPMENT AND TOOLS

Ensure the following equipment is available in the field vehicle:

- Copy of this procedure
- Copy of the appropriate Integrated Work Document(s) (IWDs)
- Charged spare battery(ies)
- Battery voltage tester
- Spare tubing (pump, suction, discharge types, sampler specific)
- Spare sample bottles
- Shovels
- Wooden stakes
- Plastic wire "zip" ties
- Cell phone (only government cell phones with the battery removed are allowed in secure areas)
- Appropriate tools (including insulated tools for electrical work) in tool box
- Issued Work Orders and associated forms
- Necessary access and station keys
- Ziploc® plastic storage bags
- Tape measure
- Sturdy hiking boots or steel toed shoes with soles that grip

The time on the ISCO sampler clock must be verified upon arrival at the site. The ISCO clocks must be set to Mountain Standard Time (MST) at all times, with no daylight saving time adjustment. Cellular phones can be used to verify the time.

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 6 of 26
the MSGP	Effective Date: September 5,	2013

5.2 ISCO SAMPLER INSTALLATION

Step	Action
1	Work Orders are issued for all field operations at individual MSGP monitored outfalls. Obtain the Work Order with the LANL MSGP ISCO Sampler Installation Form 045-1 (Attachment 1). The Work Order specifies the MSGP outfall and target date for the work to be performed. An outfall-specific equipment list with specifications and configuration settings is provided on each Work Order.
2	Deploy the ISCO sampler and charged battery on level ground above the flood plain. Often, large tool/storage boxes (Greenlee TM) are used for equipment protection in the field.
	NOTE: These boxes are locked. Therefore, a key should be obtained prior to accessing them.
	The sampler should be as level as possible to allow effective sample collection. Verify/record the ISCO sampler serial number and the battery tracking number(s) on the Work Order.
3	Install the separate protective battery box for the charged battery (follow manufacturer's instructions).
4	Determine the bottle set configuration from the equipment list on the Work Order.
·	• If a Model 3700 sampler is indicated, install the correct distributor arm (has either "12" or "24" embossed on bottom at outlet).
	• For an Avalanche sampler, attach either the discharge tube guide (single bottle configuration) or the distributor arm (multi-bottle configuration) and the appropriate bottle adapter plate. If an adapter plate is not available, the inside of the sampler may need to be configured by hand (i.e., add form) to prevent bottles from moving around during a sampling event.
	 Install required bottles and retaining devices in the sampler base.
	 Check that the end of the discharge tubing does not extend below the bottom face of the distributor arm (where it could snag the bottle tops and jam as the arm advances through the bottle sequence).
	Remove and place the clean bottle caps in a new Ziploc® plastic bag.
5	Attach a length (in whole foot increments) of 3/8-inch diameter Teflon suction line to the sampler intake line and anchor as needed for the Outfall location. Measure and record (for later programming steps) the tubing length used. Route the sample tubing downslope from the sampler to the intake point so that there is a continuous slope with no valleys that could retain water between sample intervals.
6	Install the actuator:
	Anchor a stake to the channel bottom in the main flow of the outfall discharge.
	• Attach the sampler intake tube and the 1640 liquid level detector (actuator) to the stake.
	• Position the actuator at least ½ inch above the intake tube to ensure there is enough water to submerge the intake when the sampler is activated.
	Connect the actuator to the sampler using the cable connector provided by the manufacturer.
	 If necessary, use a gravel bag to create a small pooling area for the actuator and sampler intake to sit in.
	The actuator height above the channel bottom is established using professional judgment. For example, the intake may be positioned 1 inch or less above the bottom of low-flowing wide channels, but higher than 1 inch in a high-flowing narrow channel.

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 7 of 26
the MSGP	Effective Date: September 5, 2013	

NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.

Connect the sampler to the power source, either a 12 Volt 110 A-h deep cycle lead acid battery or other power source such as a multi-battery array coupled with a solar panel, as appropriate. Record the battery tracking numbers in the equipment list section of the Work Order. (Refer to Attachments 2 and 3 for the wiring diagram for Avalanche sampler installation.)

5.3 CONFIGURING ISCO 3700 SAMPLERS

Step	Action			
1	When a new ISCO 3700 sampler is being installed, configure the sampler in accordance with the steps contained in this section. Follow the project-specific configuration settings as indicated on the Work Order and given in Attachment 4, ISCO 3700 Configuration Settings.			
2	Turn on the sampler by pressing the "On" button.			
3	Press the "Enter/Program" button.			
4	Select "Configuration".			
5	Set the configuration parameters in accordance with the guidance in Attachment 4, ISCO 3700 Configuration Settings. After each selection is made, press the "Enter" button to allow the next configuration parameter to be displayed on the screen.			
6	After the programming is complete, select "Run diagnostics" and press "Enter" to run the system diagnostic test. The diagnostic tests include the following: • RAM and ROM test • LCD test • Pump test ("OFF/ON" number should be between 50 and 200 for a successful test) • Distributor test select "YES" to run test. Test will move the distributor to Position 24 and then return it to Position 1.			
7	Following the diagnostic tests, "Reinitialize Controller" will be displayed. Select "No" and press "Enter." Do not select "Yes." If "Yes" is selected, the sampler will reset a number of configuration and program settings to the factory default values.			
8	To leave the configuration sequence, use the "Exit configuration" and press "Yes" or press the "Enter/Program" key.			

5.4 PROGRAMMING ISCO 3700 SAMPLERS

Si	tep	Action
1		Follow the steps in this process to program a new ISCO or to confirm the program settings are correct for a specific location. Follow the project-specific program settings as indicated on the

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 8 of 26
	Effective Date: September 5, 2013	

	work order and given in Attachment 5, ISCO 3700 Program Sequence.
2	Turn on the sampler by pressing the "ON" button
3	Press the "Enter/Program" button.
4	Select "Program".
5	Set the program parameters in accordance with the guidance on Attachment 5, ISCO 3700 Program Sequence. After each selection is made, press the "Enter" button to allow the next configuration parameter to be displayed on the screen.
6	Set the switch on the actuator to "Latch."
7	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

5.5 ACTIVATING ISCO 3700 SAMPLERS

Step	Action	
1	Follow the steps in this section when a Work Order is received to activate a sampler (generally at the beginning of a field season or at the beginning of the next quarter after the last quarterly monitoring sample was obtained).	
	Note: The MSGP monitoring quarters are as follows	
	April 1 through May 31	
	June 1 through July 31	
	August 1 through September 30, and	
	October 1, through November 30.	
2	Obtain the Work Order with the LANL MSGP Sampler Activation Form 045-3 (Attachment 6). The Work Order specifies the MSGP Outfall and target date for the work to be performed. An Outfall-specific equipment list with specifications and configuration settings is provided on each Work Order.	
	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.	
	If not already installed, install and hook up the charged battery.	
	If a battery is already in place, use the voltage tester to check for minimum voltage of 11.7 volts. If the voltage is lower, replace the battery with a charged battery.	
3	Turn the sampler ON. "Program halted" will be displayed; press the Enter/Program button to enter program/configure sequence.	
4	Check the configuration and programming parameters to ensure they are still correct for the specific installation (see Attachment 4 and 5 for the correct parameters).	
5	Check integrity and condition of sampler tubing, actuator, wiring, etc., to ensure sampler will properly collect a sample.	

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 9 of 26
	Effective Date: September 5, 2013	

6	To test the integrity of the tubing, press "Pump forward" to turn on pump and test for suction at the tubing intake. Press "Stop" to turn off pump.
	If no suction is felt at the intake, check the integrity of the tubing and replace as necessary.
7	To activate the sampler, press "Start sampling" and "Enter" twice.
8	Ensure the sampler indicates "Sampler Inhibited".
9	Complete the responses for the sampler activation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

5.6 CONFIGURING ISCO AVALANCHE SAMPLERS

Step	Action
1	When a new ISCO Avalanche sampler is being installed, configure the sampler in accordance with the steps contained in this section. Follow the project-specific configuration settings as indicated on the work order and given in Attachment 8, ISCO Avalanche Configuration Settings.
2	Turn on the sampler by pressing the "Standby" key.
3	From the main menu, select Other Functions, to access the menus and select options given in Attachment 8.
4	Set the configuration parameters in accordance with the guidance on Attachment 8, ISCO Avalanche Configuration Settings.
5	After the programming is complete, select "Run diagnostics" and press "Enter" to run the system diagnostic test. These include the following: RAM and ROM test Pump test ("ON/OFF" ratio should be between 0.80 and 1.25 for a successful test) Distributor test select "YES" to run test. Test will move the distributor to Position 14 and then return it to Position 1.
6	Following the diagnostic tests, "Reinitialize Controller" will be displayed. Select "No" and press the "Enter" key. (If "Yes" is selected, the sampler will reset a number of configuration and program settings to the factory default values).
7	If a 700 series module (e.g., pH) is to be installed, consult the equipment manufacturer's manual for installation instructions. NOTE: The pH module is only required at the Asphalt Batch Plant.
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 10 of 26
	Effective Date: September 5, 2013	

5.7 PROGRAMMING ISCO AVALANCHE SAMPLERS

Step	Action
1	Follow the steps in this process to program a new ISCO or to confirm the program settings are correct for a specific location and bottle configuration. Follow the project-specific program settings as indicated on the work order and given in Attachment 8, ISCO Avalanche Program Sequence.
2	Turn on the sampler by pressing the "Standby" key.
3	Press the "Program" button.
4	Select the current program to review settings, or choose "Select New Program" to create a new program with different settings.
5	Select the current program to review settings, or choose "Select New Program" to create a new program with different settings.
6	At the prompt "Programming complete, run this program now?", select "Yes" if sampler is scheduled to be active, and "No" if sampler is in stand down.
7	Set switch on actuator to "Latch."
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items within it have been completed.

5.8 ACTIVATING ISCO AVALANCHE SAMPLERS

Step	Action
1	Follow the steps in this section when a Work Order is received to activate a sampler (generally at the beginning of a field season or at the beginning of the next quarter after the last quarterly monitoring sample was obtained).
	Note: The MSGP monitoring quarters are as follows
	 April 1 through May 31 June 1 through July 31 August 1 through September 30, and October 1, through November 30.
2	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.
	If not already installed, install and hook up the charged battery(ies).
	If a battery is already in place, use the voltage tester to check for minimum voltage of 11.7 volts. If the voltage is lower, replace the battery with a charged battery.
3	Turn on sampler power. From the main menu, select "Program" and the "Enter" key to enter programming sequence, and "Other Functions" to enter the configuration settings.
4	Check the programming/configuration parameters to ensure they are still correct for the specific installation – follow the two preceding sections for the steps and see Attachment 7 and 8 for the correct parameters.
5	Check integrity and condition of sampling tubes, actuator, wiring, etc., to ensure sampler

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 11 of 26
	Effective Date: September 5, 2013	

	will properly collect a sample.
6	From the main menu, select "Other Functions" ▶ "Manual Functions" ▶ "Operate Pump" to perform a manual suction test. To test the integrity of the tubing, press "Pump forward" to turn on pump and test for suction at the tubing intake. Press "Stop" to turn off pump. If no suction is felt at the intake, check the integrity of the tubing and replace as necessary.
7	Reset the actuator by toggling the switch to "Reset" then back to "Latch." To activate the sampler, ensure the correct program name is displayed on the main menu and select "Run".
8	Ensure the sampler indicates "Program Disabled".
9	Note: The Avalanche refrigeration system is active any time the controller is powered. This is true for all states (including OFF), except for the time between entering RUN and the completion of the first sample, and when the pump is running. To conserve power, the Avalanche assumes that during this time there is no sample liquid to cool.
10	
	Ensure that all items on the Work Order have been completed.

5.9 STANDING DOWN OR WINTERIZING SAMPLERS

Step	Action
1	Follow the steps in this section when a Work Order is received to turn off ("stand down") a sampler (generally at the end of a field season, which is November 30, or to disable a sampler for a certain time period after a sample was collected). Fill out the LANL MSGP ISCO Sampler Winter Shut-Down Form in Attachment 9.
2	ISCO 3700: Turn off power. ISCO Avalanche: The Avalanche refrigeration system is active any time the controller is powered. This is true for all states (including OFF), except for the time between entering RUN and the completion of the first sample, and when the pump is running. To conserve power, the Avalanche assumes that during this time there is no sample liquid to cool. NOTE: To ensure that the refrigeration system does not activate during an intended stand down, disconnect the sampler from the power source.
3	Remove the battery and return it to the storage compound at TA-64 or other specified location identified by ENV-CP MSGP stormwater compliance personnel. Store cables inside the Greenlee TM box. If the actuator and tubing are not contained within conduit, disconnect these and place them in the box. Close sampler. Avalanche samplers must not be left in place for the winter, and are required to be returned to ENV-CP's storage shed.
4	Ensure that all items on the Work Order have been completed.

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 12 of 26
	Effective Date: September 5,	2013

5.10 SAMPLER RESET AND RE-INITIALIZATION AFTER SAMPLE COLLECTION

Step	Action
1	Follow ENV-CP-QP-047, <i>Inspecting Storm Water Runoff Samplers and Retrieving Samples for the MSGP</i> for collecting samples from an ISCO and installing new bottles so it is ready to collect new samples.
2	After collecting samples and resetting the sampler, follow instructions on sample collection Work Order, the updated sample tracking log or confer with the MSGP Project Lead regarding whether the sampler should be disabled. If sampler is to be deactivated, follow the steps specific to each sampler provided in the preceding section.
	If an ISCO 3700 sampler is to be left activated, reset the actuator by toggling the switch to "Reset" then back to "Latch", and press "Start sampling" and "Enter" twice. Ensure the sampler display indicates "Sampler Inhibited":
	If an ISCO Avalanche sampler is to be left activated, reset the actuator by toggling the switch to "Reset" then back to "Latch." From the main menu, verify the correct program name is displayed and select "Run." Ensure the sampler display indicates "Program Disabled."

5.11 REMOVING A SAMPLER

Step	Action
1	Follow the steps in this process when a Work Order is received to un-install or remove a sampler. Fill out the LANL MSGP ISCO Sampler Decommission Form in Attachment 10.
2	Disconnect all equipment and remove it from the site. Return the equipment to the ENV-CP Storage Shed or other location specified by MSGP storm water compliance personnel.
3	Dispose of all equipment components that contacted samples (tubing, bottles, etc.) as waste according to applicable waste management procedure. For assistance, contact the Waste Management Coordinator for TA-59.
4	Ensure that all items on the Work Order have been completed.

6.0 REFERENCES

ENV-DO-QP-110, Records Management Program

ENV-DO-QP-115, Personnel Training

ENV-CP-QP-047, Inspecting Storm Water Runoff Samplers and Retrieving Samples for the MSGP

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 13 of 26
	Effective Date: September 5, 2013	

7.0 **DEFINITIONS**

ENV-CP: Environmental Protection Division, Compliance Programs Group

<u>Grab Sample:</u> A single sample collected at an NPDES outfall (using approved EPA methods) at a particular time that represents the composition of the storm water at that time and place.

IWD: Integrated Work Document

MSGP: Multi-Sector General Permit

MST: Mountain Standard Time

NPDES: National Pollutant Discharge Elimination System

8.0 ATTACHMENTS

Attachment 1- LANL MSGP ISCO Sampler Installation Form 045-1

Attachment 2- Wiring Diagram for Avalanche Sampler

Attachment 3 – Battery Photovoltaic Connection Wiring

Attachment 4 - ISCO 3700 Configuration Settings

Attachment 5 – ISCO 3700 Program Sequence

Attachment 6 – LANL MSGP ISCO Sampler Activation Form 045-3

Attachment 7 – ISCO Avalanche Configuration Settings

Attachment 8 – ISCO Avalanche Program Sequence

Attachment 9 – LANL MSGP ISCO Sampler Winter Shut-Down Form 045-5

Attachment 10 – LANL MSGP ISCO Sampler Decommission Form 045-6

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1

Page 14 of 26

Effective Date: September 5, 2013

ATTACHMENT 1- LANL MSGP ISCO SAMPLER INSTALLATION FORM 045-1

ENV-QP-045.0				LANL Multi-Se ISCO Sample	0101 00110101					Form 045-1 (3/2011)
Outfall: 54-G-	-4 : 54-P	AD10E		Project ID: P-	MSGP-2443			Wo	ork Order ID:	MSGP-31193
Target Date: 4/	/1/2013				Date:	14 /1 6		Tin	ne:	
					Name/Z#:					
Project: M	ISGP 2013	Sampler Install			Name/Z#:					
Reason: M	1SGP 2013	Sampler Installation	1		Lead Signature:					
					"I confirm t	he informati	on as reco	rded is true,	accurate and	complete."
	Verify the	equipment list b	elow. Make	corrections as rec	uired and fill in	missing i	nformatio	on (e.g., se	erial number	rs).
Equipment		Manufacturer	Model	Serial No.		Specificat	ion		Configuratio	n
Actuator		ISCO	1640	210J01660						
Charge Controller	r	Xantrex	C-12	B20037667						
ISCO 3700 Samp		Teledyne	3700	198H00978		Bottle Set		12c- 1 1L Glass, 11 1L Poly		
ISCO 3700 Samp	0.000	Teledyne	3700	198H00978		Program			Time / Multipl	
ISCO Avalanche	T C T C T C T C T C T C T C T C T C T C	Teledyne	Avalanche	210J00066		Bottle Set Program			14 950 mL Po 1-Part, 14 Bo	
Pb-Acid Battery	Sampler	Teledyne Universal	Avalanche 110 A-h	210J00066 MSGP-110-03	211.07	Voltage			>11.7 V	mes, 930 IIIL
Pb-Acid Battery		Universal	110 A-h	MSGP-110-03		Voltage			> 11.7 V	
Pb-Acid Battery		Universal	110 A-h	MSGP-110-03		Voltage			> 11.7 V	
Solar Panel		SunWize	SW-S85P	11004467						
		ISO	CO Sampler	Tasks			Note: If	'No" provide	correct inform	nation or explanation.
Deploy battery(ie	es) if not liste		•	d serial numbers of ba	attery(ies) installed		□Yes	□No		
Deploy Avalanch	e sampler m	natching serial num	ber listed in e	quipment list above fo	r installation.		□Yes			
Deploy and instal	II pH and Te	mperature Probe li	sted in equipr	ment list above and pro	obe saturation rese	ervior.	□Yes			
		n ENV-QP-045.0 fo		nel, battery configurati	on, and type of sai	mpler	□Yes	1,2,1		
-	•	rding to steps in EN	•	200000000000000000000000000000000000000			□Yes	□No		
Is a Greenlee box	x used?						□Yes	□No		
Are electrical connections secure?				□Yes	□No					
Record battery voltage(s). Voltage(s) > 11.7 V?			□Yes	□No						
Is the sampler ph base, arm)?	nysically con	figured for the type	s and number	r of bottles specified a	bove (i.e., correct o	carousel,	□Yes	□No		
Is the sampler pro	ogrammed o	correctly per ENV-0	QP-045.0 for t	he program / bottle se	t specified above?		□Yes	□No		
Does sampler pa	iss the ISCC	diagnostics test?					□Yes	□No		
Does sample tubi	ing pass su	ction test?					□Yes	□No		
Is sampler ON up	pon departur	e?					□Yes	□No		
Does ISCO displa	ay either "Sa	ampler Inhibited" o	"Program Dis	sabled"?			□Yes	□No		
Has the actuator	switch been	reset to "Latch"?					□Yes	□No		
If any maintenance	ce complete	d, check YES and	describe.				□Yes	□No		
If any follow-on m	naintenance	is required, check	YES and des	cribe.			□Yes	□No		
			LAì	NL PERSONNEL U	ISE ONLY (Initi	als and dat	es)			
Accepted			Te	ech QC				ENV-RCR	A Review	
			_			4		-		


Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1

Page 15 of 26


Effective Date: September 5, 2013

ATTACHMENT 2- WIRING DIAGRAM FOR AVALANCHE SAMPLER



Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 16 of 26
	Effective Date: September 5, 2013	


ATTACHMENT 3 – BATTERY PHOTOVOLTAIC CONNECTION WIRING



Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 17 of 26

Effective Date: September 5, 2013



Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 18 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 4 - ISCO 3700 CONFIGURATION SETTINGS

Parameter	Storm sampling with multiplex, timed delay	Time sampling with multiplex	Flow sampling with multiplex
Time/ Date	[Set to MST]	[Set to MST]	[Set to MST]
Portable/ Refrig	Portable	Portable	Portable
Bottles	12 or 24	12 or 24	12 or 24
Bottle volume	950 ml	1000 ml	1000 ml
Suction line diameter	3/8 inch	3/8 inch	3/8 inch
Suction line type	Teflon	Teflon	Teflon
Suction line length	X feet	X feet	X feet
Liquid detector	Enable	Enable	Enable
Rinse cycles	0	1	1
Enter Head Manually	No	Yes	Yes
Retry	1	1	1
Program mode	Extended	Basic	Basic
Load program	None	N/A	N/A
Save program as	None	N/A	N/A
Take sample at start time	No	N/A	N/A
Take sample at time switch	No	N/A	N/A
Enter intervals in minutes	1 minute	N/A	N/A
Calibrate sampler	Disable	Enable	Enable
Sampling stop/resume	Disable	N/A	N/A
Start time delay	0 minutes	0 minutes	0 minutes
Master slave	No	No	No
Sample upon Disable	No	No	No
Sample upon enable	No	Yes	Yes
Reset sample interval	Yes	Yes	No
Inhibit countdown	Yes	Yes	No
Event marker	Pulse	Pulse	Pulse
At the beginning of:	Purge	Purge	Purge
Purge counts presample counts	150	100	100
Post sample counts	394	1000	1000
Pump counts	[500,000]	[500,000]	[500,000]
Reset pump counter	No	No	No
Pump counts to warning	500,000	500,000	500,000
Program lock	Disable	Disable	Disable
Sampler ID number is:	[leave blank]	[leave blank]	[leave blank]
Run diagnostics	Yes	Yes	Yes
Test distributor	Yes	Yes	Yes
Re-initialize	No	No	No

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 19 of 26

Effective Date: September 5, 2013

ATTACHMENT 5 – ISCO 3700 PROGRAM SEQUENCE

	Storm sampling with
Parameter	multiplex, timed delay
[Switch on	Set to "Latch"
liquid actuator]	
Paced sampling	Storm
Time Mode 1st	X-minute delay
Bottle Group	
Timed Sample	1
Event	
Bottle per	11 or 23
sample event	
Sample volume	950 ml
Bottles	1
available	
2 nd bottle group	Time
2 nd group	1-minute delay
samples	
Sample interval	1 minute
Bottles per	1
sampling event	
Sample per	1
bottle	
Sample volume	950 ml
Enter start time	No

[Programming complete]

	Time sampling with
Parameter	multiplex
[Switch on	Set to "Latch"
liquid actuator]	
Time/Flow	Time
Min/Hr	1 min
Multiplex	Yes
samples	
Bottles/sample	Bottles/ sample
or	
Samples/Bottle	
Number of	12 or 24
bottles	
Sample volume	1000 ml
Suction head	XX Ft
Calibrate sample	No
vol	
Enter start time	No

[Programming complete]

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 20 of 26
	Effective Date: September 5,	2013

Avalanche Program Sequence, cont.

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2-part program			
Two-Part Program						
Part A	N/A	N/A	Yes			
Assign bottle	N/A	N/A	1-X of 4 or 14			
Pacing	N/A	N/A	Uniform time paced			
Time between samples	N/A	N/A	1 minute			
Distribution	N/A	N/A	Sequential			
Bottles per event	N/A	N/A	1			
Switch bottles on	N/A	N/A	Number of samples			
Switch bottles every X samples	N/A	N/	1			
Run continuously	N/A	N/A	No			
Sample volumes dependent on flow?	N/A	N/A	No			
Sample volume	N/A	N/A	Select between 10 ml and full container volume			
Enable programmed	N/A	N/A	None			
Once enabled, stay enabled	N/A	N/A	Yes			
Sample at enable	N/A	N/A	Yes			
Sample at disable	N/A	N/A	No			
Pauses and resumes	N/A	N/A	0			
Part B	N/A	N/A	Yes			
Pacing	N/A		Uniform time paced			
Time between sample events	N/A	N/A	1 minute			
Distribution	N/A	N/A	Sequential			
Bottles per event	N/A	N/A	1			
Switch bottles on	N/A	N/A	Number of samples			
Switch bottles every X samples	N/A	N/A	1			
Run continuously	N/A	N/A	No			
Sample volumes dependent on flow?	N/A	N/A	No			
Sample volume	N/A	N/A	Select between 10 ml and full container volume			
Enable programmed	N/A	N/A	No			

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 21 of 26
	Effective Date: September 5, 2013	

Avalanche Program Sequence, cont.

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2-part program
Once enabled, stay enabled	N/A	N/A	Yes
Sample at disable	N/A	N/A	No
Sample at enable	N/A	N/A	Yes
Once enabled, stay enabled	N/A	N/A	Yes
Pauses and resumes	N/A	N/A	0
Delay to start	N/A	N/A	No
	Reset Samp	ler	
Switch on liquid actuator	Toggle to "Reset" then back to "Latch"	Toggle to "Reset" then back to "Latch"	Toggle to "Reset" then back to "Latch"
Select Program name	Run	Run	Run

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 22 of 26

Effective Date: September 5, 2013

ATTACHMENT 6 – LANL MSGP ISCO SAMPLER ACTIVATION FORM 045-3

ENV-QP-045.0	LANL Multi-Sector General Permit ISCO Sampler Activation Form			Form 045-3 (3/2011)	
Outfall: 3-PSP-5 : E121.9-ISCO 12	Project ID: P	-MSGP-830			Work Order ID: MSGP-12785
Target Date: 4/11/2011		Date:			Time:
Project: MSGP Sampler Activation Q1 2011		Name/Z#:_			
Reason: MSGP Sampler Activation 2011 Q1		Name/Z#:_			
Reason. Moor sample Activation 2011 &1		Lead Signal	ture:		
		"I confirm	n the infor	mation as rec	orded is true, accurate and complete."
Equipment Manufacturer	Model	Serial No.	Spec	ification	Configuration
Actuator ISCO	1640		Actua	ntor Height	
ISCO Sampler 12c Teledyne ISCO	ISCO 3700	198H01553	Bottle	Set	12c- 1 1L Poly
ISCO Sampler 12c Teledyne ISCO	ISCO 3700	198H01553	Progr	am	Time / Multiplex no delay
Pb-Acid Battery			Volta	ge	> 11.7 V
ISCO Sampler Tasks		Note: If	"No" prov	ide correct in	formation or explanation.
Is the ISCO time delta < 1 min (MST)? If no, record adjustn	nent.	□Yes	□No		
Does sampler pass the ISCO diagnostics test?		□Yes	□No		
Are electrical connections secure?		□Yes	□No		
Record battery voltage(s). Is/are voltage(s) > 11.7 V?		□Yes	□No		
Does ISCO display either "Bottle 1 of X afer 1" or "Sampler	Inhibited"?	□Yes	□No		
Is bottle set described above installed?		□Yes	□No		
Is recorded height of actuator above channel bottom correct	it?	□Yes	□No		
If any maintenance completed, check Yes: Describe.		□Yes	□No		
If any follow-on maintenance is required, check Yes: Desc	ribe.	□Yes	□No		
Is sampler ON upon departure?		□Yes	□No		
Additional Notes:					
	ANL PERSONNEL I	USE ONLY (I	nitials and	(dates)	
Accepted	Tech QC	USE ONL! (II	ilitiais and	(dates)	RNV-RCRA Review

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 23 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 7 – ISCO AVALANCHE CONFIGURATION SETTINGS

ISCO Avalanche Configuration Settings

Parameter	All programs				
Maintenance					
Set Clock	[Set to MST]				
Pump Tube Alarm	[1,000,000]				
Reset pump counter	No				
Run diagnostics	Yes				
Re-initialize	No				
Softwa	are Options				
Liquid detector	Liquid detect on				
Target temperature	°C				
Measurement interval	1 minute				
Dual sampler mode	Off				
Bottle full detect	Yes				
Event mark	Every sample				
Duration	3 second pulse at initial purge				
Presample purge counts	100				
Post sample counts	Dependent on head				
Periodic serial output	No				
Interrogator connector power	Alarm dial-outs only				
Manua	al Functions				
Grab Sample	Manual option				
Calibrate volume	Manual option				
Operate pump	Manual option				
Move distributor	Manual option				
Other S	Settings/Misc				
Suction line diameter	3/8 inch				
Suction line type	Teflon				
Program lock	Disable				

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 24 of 26
	Effective Date: September 5, 2	2013

ATTACHMENT 8 – ISCO AVALANCHE PROGRAM SEQUENCE

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2- part program	
	Program			
Program mode	Extended	Extended	Extended	
Program name	COMPOSITE	1-PART (# bottles)	2-PART (# bottles)	
Site description	Station number	Station number	Station number	
Units (length)	ft	ft	ft	
Units (temperature)	°C	°C	°C	
Data storage interval	1 minute	1 minute	1 minute	
Number of bottles	1	4 or 14	4 or 14	
Bottle volume	10000 ml, 4000 ml	2000 ml, 950 ml	2000 ml, 950 ml	
Suction line length	X feet	X feet	X feet	
Enter Head Manually	Yes	Yes	Yes	
Rinse cycles	1	1	1	
Retries	1	1	1	
	One-Pa	rt Program		
Pacing	Uniform time paced	Uniform time paced	N/A	
Time between samples	Every one minute	Every one minute	N/A	
Composite	1 sample	N/A	N/A	
Run continuously	No	N/A	N/A	
Take X sample(s)	1	N/A	N/A	
Distribution	N/A	Sequential	N/A	
Volume	Select between 10 ml and full container volume	Select between 10 ml and full container volume	N/A	
Sample volumes dependent on flow	No	No	N/A	
Enable programmed	None	None	N/A	
Once enabled, stay enabled	Yes	Yes	N/A	
Sample at enable	Yes	Yes	N/A	
Sample at disable	No	No	N/A	
Pauses and resumes	0	0	N/A	
Delay to start	No	No	N/A	

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 25 of 26

Effective Date: September 5, 2013

ATTACHMENT 9 – LANL MSGP ISCO SAMPLER WINTER SHUT-DOWN FORM 045-5

ENV-QP-045.0		LANL Multi-Sector General Permit ISCO Sampler Winter Shutdown Form					Form 045-5 (3/2011)	
Outfall: 3-PSP-5 :	: E121.9-ISCO 12	Project ID: P-MSGP-833				Work Order II	: MSGP-12803	
Target Date: 11/30/2	2011		Da	Date:		Time:		
D MOOD	1000 0 1 . 185 1 01 . 11		Na	ame/Z#:_				
Project: MSGP	ISCO Sampler Winter Shutdow	vn	Na	ame/Z#:				
Reason: MSGP	Sampler Winter Shutdown 201	11	Le	ead Signat	ture:			
				"I confirm	n the inf	ormation as reco	rded is true, accurate	and complete."
Verif	y the equipment list below. N	lake corrections as r	equir	ed and fi	ill in mis	ssing informatio	n (e.g., serial numb	ers).
Equipment	Manufacturer	Model	Ser	rial No.	Spe	ecification	Configuration	
Actuator	ISCO	1640			Acti	uator Height		
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H	101553	Bot	tle Set	12c- 1 1L Poly	
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H	101553	Pro	gram	Time / Multiplex	no delay
Pb-Acid Battery					Volt	tage	> 11.7 V	
	ISCO Sampler Tasks			Note: If	"No" pro	ovide correct info	rmation or explanation	on.
Turn ISCO unit "OFF."				□Yes	□No			
Place caps securely on	bottles in the sample carousel.			□Yes	□No			
Verify equipment list ab	oove.			□Yes	□No			
ISCO 3700 Sampler U	nits							
Disconnect and remove maintenance and storage	e battery. Transport battery to MSG ge.	P stockroom for		□Yes	□No			
Place battery cables so	ecurely inside Greenlee box or ISC	O casing.		□Yes	□No			
Pull up actuator and tub	bing and store in Greenlee box or I	SCO casing.		□Yes	□No			
Avalanche ISCO Sam	pler Units:							
Disconnect and remove maintenance and storage	e batteries. Transport batteries to M ge.	/ISGP stockroom for		□Yes	□No			
Place battery cables se	ecurely inside Greenlee box or ISC	O casing.		□Yes	□No			
Pull up actuator and tub	bing and store inside Greenlee box	or ISCO casing.		□Yes	□No			
Transport Avalanche sa	ampler to MSGP stockroom for ma	intenance and storage.		□Yes	□No			
Additional Notes:								
		LANL PERSONNEL	USE	ONLY (Iı	nitials ar	nd dates)		
Accepted		Tech QC					ENV-RCRA Review	

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1 Page 26 of 26		
	Effective Date: September 5, 2013		

ATTACHMENT 10 - LANL MSGP ISCO SAMPLER DECOMMISSION FORM 045-6

ENV-QP-045.0		LANL Multi-S ISCO Sample	Form 045-6 (3/2011)			
Outfall: 3-PSP-5 : E12	1.9-ISCO 12	Project ID:	P-MSGP-834		Work Order ID: MSGP-12804	
Target Date: 7/27/2011			Date:		Time:	
Project: MSGP Samp	ler Station Decommission	in	Name/Z#:_			
			Name/Z#:_			
Reason: MSGP Samp	ier Decommission		Lead Signal	ture:		
			"I confirm	n the information as reco	orded is true, accurate and complete."	
Verify the	equipment list below. N	Make corrections as	required and fi	ll in missing informati	on (e.g., serial numbers).	
Equipment	Manufacturer	Model	Serial No.	Specification	Configuration	
Actuator	ISCO	1640		Actuator Height		
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H01553	Bottle Set	12c- 1 1L Poly	
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H01553	Program	Time / Multiplex no delay	
Pb-Acid Battery				Voltage	> 11.7 V	
	ISCO Sampler Tasks		Note: If "No" provide correct information or explanation.			
Is equipment list above comple	ete and accurate?		□Yes	□No		
Turn sampler "OFF." Remove	bottles from carousel.		□Yes	□No		
Disconnect and remove batter	y(ies), solar panel, and cab	les (as applicable).	□Yes	□No		
Pull up actuator and tubing. Di	sconnect from sampler unit		□Yes	□No		
Uninstall Greenlee box, as app	olicable.		□Yes	□No		
Transport all removed equipment to the MSGP stockroom for maintenance and storage.		□Yes	□No			
Additional Notes:						
		LANL PERSONNEL	USE ONLY (I	nitials and dates)		
Accepted Tech QC			F 0 7 F		ENV-RCRA Review	

ENV-CP-QP-045.1 Effective Date: September 5, Next Review Date: August 5,



2013 2015

Environment, Safety, Health Directorate

Anthony Grieggs

Environmental Protection – Compliance Programs Quality Procedure

ENV-CP Group Leader

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

Reviewers: Name: Organization: Signature: Date: Melanie Lamb ADESH-OIO, QA 8/28/13 Signature on file Specialist **Derivative Classifier:** ☐ Unclassified ☐ DUSA ENVPRO Name: Signature: Date: Organization: Ellena Martinez ADESH-OIO Signature on file 8/28/13 **Approval Signatures:** Subject Matter Expert: Organization: Signature: Date: Holly Wheeler **ENV-CP** Signature on file 8/29/13 Responsible Line Manager: Signature: Organization: Date: Michael Saladen **ENV-CP Team Lead** Signature on file 8/29/13 Responsible Line Manager: Signature: Organization: Date:

CONTROLLED DOCUMENT

9/5/13

This copy is uncontrolled. The controlled copy can be found on the ENV Division Web page.

Users are responsible for ensuring they work to the latest approved version.

Signature on file

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 2 of 26
	Effective Date: September 5, 2013	

History of Revisions

Document Number [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	03/11	New Document.
1	04/13	Biennial Review and Revision
2	09/13	Biennial Review and Revision

No. ENV-CP-QP-045.1

Page 3 of 26

Effective Date: September 5, 2013

Table of Contents

1.0	PUR]	POSE	4
2.0	SCO	PE	4
	2.1	Hazard review	4
3.0	RESI	PONSIBILITIES	4
•••	3.1	Prerequisites	
4.0	DOC	UMENT CONTROL/RECORDS MANAGEMENT	4
5.0	WOF	RK PROCESSES	5
	5.1	Equipment and Tools	
	5.2	ISCO Sampler Installation	6
	5.3	Configuring ISCO 3700 Samplers	7
	5.4	Programming ISCO 3700 Samplers	7
	5.5	Activating ISCO 3700 Samplers	8
	5.6	Configuring ISCO Avalanche Samplers	9
	5.7	Programming ISCO Avalanche Samplers	10
	5.8	Activating ISCO Avalanche Samplers	10
	5.9	Standing Down or Winterizing Samplers	
	5.10	Sampler Reset and Re-initialization After Sample Collection	12
	5.11	Removing a Sampler	12
6.0	REF	ERENCES	12
7.0	DEF	INITIONS	13
8.0	ATT	ACHMENTS	13
	Attac	hment 1- LANL MSGP ISCO Sampler Installation Form 045-1	14
	Attachment 2- Wiring Diagram for Avalanche Sampler		15
	Attac	hment 3 – Battery Photovoltaic Connection Wiring	16
	Attac	hment 4 - ISCO 3700 Configuration Settings	18
	Attac	hment 5 – ISCO 3700 Program Sequence	19
	Attac	hment 6 – LANL MSGP ISCO Sampler Activation Form 045-3	22
	Attac	hment 7 – ISCO Avalanche Configuration Settings	23
		hment 8 – ISCO Avalanche Program Sequence	
	Attac	hment 9 – LANL MSGP ISCO Sampler Winter Shut-Down Form 045-5	25
	Attac	hment 10 – LANL MSGP ISCO Sampler Decommission Form 045-6	26

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 4 of 26
the MSGP	Effective Date: September 5, 2013	

1.0 PURPOSE

This procedure describes the installation, setup, programming, and operation of Teledyne ISCO Avalanche and Model 3700 full-size portable automated samplers used to collect storm water runoff samples for the Multi-Sector General Permit (MSGP).

2.0 SCOPE

This procedure applies to all ENV-CP technical staff and contractor personnel conducting installation, operation, maintenance and sampling activities at single stage stations used for monitoring under the MSGP.

2.1 HAZARD REVIEW

Hazards in the work described in this procedure are controlled thorough site specific <u>IWDs</u>. The hazard level of the activities in this procedure is <u>moderate</u>.

3.0 RESPONSIBILITIES

The following personnel require training before implementing this procedure:

This procedure applies to all ENV-CP MSGP storm water compliance personnel conducting
installation, operation, maintenance and sampling activities at MSGP single stage monitoring
stations.

The training method for this procedure is "self-study" (reading). For ENV-CP staff, this is documented in accordance with ENV-DO-QP-115, *Personnel Training*. Other participating groups may require training documentation pursuant to local procedures.

Actions specified within this procedure, unless proceeded with "should" or "may," are to be considered mandatory (i.e., "shall", "will", "must").

3.1 Prerequisites

Personnel performing this procedure will be familiar with the most current versions of the following procedures and operation manuals:

- ENV-CP MSGP Sampling and Analysis Plan for the current monitoring year
- Manual for Teledyne ISCO Sampler Model 3700.
- Manual for Teledyne ISCO Avalanche refrigerated sampler
- Facility/FOD specific IWDs for the MSGP

4.0 DOCUMENT CONTROL/RECORDS MANAGEMENT

The following records are generated as a result of this procedure and are maintained in accordance with ENV-DO-QP-110, *Records Management Program* with the originals on file at ENV-CP offices:

Completed work orders for:

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 5 of 26
	Effective Date: September 5, 2013	

- LANL MSGP ISCO Sampler Installation Form 045-1(Attachment 1)
- LANL MSGP ISCO Sampler Activation Form 045-3 (Attachment 6)
- LANL MSGP ISCO Sampler Winter Shutdown 045-5 (Attachment 9)
- LANL MSGP ISCO Sampler Decommission 045-6 (Attachment 10)

5.0 WORK PROCESSES

The discharge of storm water from industrial facilities at Los Alamos National Laboratory (LANL, the Laboratory) is regulated under the National Pollutant Discharge Elimination System (NPDES) *Multi-Sector General Permit for Storm Water Discharges Associated with Industrial Activity* (MSGP). The current MSGP became effective on September 29, 2008 pursuant to 73 FR 56572. The Laboratory's MSGP permit coverage (Permit Tracking No. NMR05GB21) requires storm water quality monitoring to evaluate the overall effectiveness of control measures. ISCO samplers coupled with Model 1640 sampler actuators are used at MSGP Program monitoring stations. Refrigerated (Avalanche) and/or non-refrigerated (Model 3700) samplers may be deployed; and may be configured with multi-battery arrays, solar panels, and surge protectors.

5.1 EQUIPMENT AND TOOLS

Ensure the following equipment is available in the field vehicle:

- Copy of this procedure
- Copy of the appropriate Integrated Work Document(s) (IWDs)
- Charged spare battery(ies)
- Battery voltage tester
- Spare tubing (pump, suction, discharge types, sampler specific)
- Spare sample bottles
- Shovels
- Wooden stakes
- Plastic wire "zip" ties
- Cell phone (only government cell phones with the battery removed are allowed in secure areas)
- Appropriate tools (including insulated tools for electrical work) in tool box
- Issued Work Orders and associated forms
- Necessary access and station keys
- Ziploc® plastic storage bags
- Tape measure
- Sturdy hiking boots or steel toed shoes with soles that grip

The time on the ISCO sampler clock must be verified upon arrival at the site. The ISCO clocks must be set to Mountain Standard Time (MST) at all times, with no daylight saving time adjustment. Cellular phones can be used to verify the time.

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 6 of 26
	Effective Date: September 5, 2013	

5.2 ISCO SAMPLER INSTALLATION

Step	Action
1	Work Orders are issued for all field operations at individual MSGP monitored outfalls. Obtain the Work Order with the LANL MSGP ISCO Sampler Installation Form 045-1 (Attachment 1). The Work Order specifies the MSGP outfall and target date for the work to be performed. An outfall-specific equipment list with specifications and configuration settings is provided on each Work Order.
2	Deploy the ISCO sampler and charged battery on level ground above the flood plain. Often, large tool/storage boxes (Greenlee TM) are used for equipment protection in the field.
	NOTE: These boxes are locked. Therefore, a key should be obtained prior to accessing them.
	The sampler should be as level as possible to allow effective sample collection. Verify/record the ISCO sampler serial number and the battery tracking number(s) on the Work Order.
3	Install the separate protective battery box for the charged battery (follow manufacturer's instructions).
4	Determine the bottle set configuration from the equipment list on the Work Order.
·	• If a Model 3700 sampler is indicated, install the correct distributor arm (has either "12" or "24" embossed on bottom at outlet).
	• For an Avalanche sampler, attach either the discharge tube guide (single bottle configuration) or the distributor arm (multi-bottle configuration) and the appropriate bottle adapter plate. If an adapter plate is not available, the inside of the sampler may need to be configured by hand (i.e., add form) to prevent bottles from moving around during a sampling event.
	 Install required bottles and retaining devices in the sampler base.
	 Check that the end of the discharge tubing does not extend below the bottom face of the distributor arm (where it could snag the bottle tops and jam as the arm advances through the bottle sequence).
	Remove and place the clean bottle caps in a new Ziploc® plastic bag.
5	Attach a length (in whole foot increments) of 3/8-inch diameter Teflon suction line to the sampler intake line and anchor as needed for the Outfall location. Measure and record (for later programming steps) the tubing length used. Route the sample tubing downslope from the sampler to the intake point so that there is a continuous slope with no valleys that could retain water between sample intervals.
6	Install the actuator:
	Anchor a stake to the channel bottom in the main flow of the outfall discharge.
	• Attach the sampler intake tube and the 1640 liquid level detector (actuator) to the stake.
	• Position the actuator at least ½ inch above the intake tube to ensure there is enough water to submerge the intake when the sampler is activated.
	Connect the actuator to the sampler using the cable connector provided by the manufacturer.
	 If necessary, use a gravel bag to create a small pooling area for the actuator and sampler intake to sit in.
	The actuator height above the channel bottom is established using professional judgment. For example, the intake may be positioned 1 inch or less above the bottom of low-flowing wide channels, but higher than 1 inch in a high-flowing narrow channel.

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 7 of 26
the MSGP	Effective Date: September 5, 2013	

NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.

Connect the sampler to the power source, either a 12 Volt 110 A-h deep cycle lead acid battery or other power source such as a multi-battery array coupled with a solar panel, as appropriate. Record the battery tracking numbers in the equipment list section of the Work Order. (Refer to Attachments 2 and 3 for the wiring diagram for Avalanche sampler installation.)

5.3 CONFIGURING ISCO 3700 SAMPLERS

Step	Action
1	When a new ISCO 3700 sampler is being installed, configure the sampler in accordance with the steps contained in this section. Follow the project-specific configuration settings as indicated on the Work Order and given in Attachment 4, ISCO 3700 Configuration Settings.
2	Turn on the sampler by pressing the "On" button.
3	Press the "Enter/Program" button.
4	Select "Configuration".
5	Set the configuration parameters in accordance with the guidance in Attachment 4, ISCO 3700 Configuration Settings. After each selection is made, press the "Enter" button to allow the next configuration parameter to be displayed on the screen.
6	After the programming is complete, select "Run diagnostics" and press "Enter" to run the system diagnostic test. The diagnostic tests include the following: RAM and ROM test LCD test Pump test ("OFF/ON" number should be between 50 and 200 for a successful test) Distributor test select "YES" to run test. Test will move the distributor to Position 24 and then return it to Position 1.
7	Following the diagnostic tests, "Reinitialize Controller" will be displayed. Select "No" and press "Enter." Do not select "Yes." If "Yes" is selected, the sampler will reset a number of configuration and program settings to the factory default values.
8	To leave the configuration sequence, use the "Exit configuration" and press "Yes" or press the "Enter/Program" key.

5.4 PROGRAMMING ISCO 3700 SAMPLERS

Si	tep	Action
1		Follow the steps in this process to program a new ISCO or to confirm the program settings are correct for a specific location. Follow the project-specific program settings as indicated on the

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 8 of 26
the MSGP	Effective Date: September 5, 2013	

	work order and given in Attachment 5, ISCO 3700 Program Sequence.
2	Turn on the sampler by pressing the "ON" button
3	Press the "Enter/Program" button.
4	Select "Program".
5	Set the program parameters in accordance with the guidance on Attachment 5, ISCO 3700 Program Sequence. After each selection is made, press the "Enter" button to allow the next configuration parameter to be displayed on the screen.
6	Set the switch on the actuator to "Latch."
7	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

5.5 ACTIVATING ISCO 3700 SAMPLERS

Step	Action		
1	Follow the steps in this section when a Work Order is received to activate a sampler (generally at the beginning of a field season or at the beginning of the next quarter after the last quarterly monitoring sample was obtained).		
	Note: The MSGP monitoring quarters are as follows		
	April 1 through May 31		
	June 1 through July 31		
	August 1 through September 30, and		
	October 1, through November 30.		
2	Obtain the Work Order with the LANL MSGP Sampler Activation Form 045-3 (Attachmen 6). The Work Order specifies the MSGP Outfall and target date for the work to be performe An Outfall-specific equipment list with specifications and configuration settings is provided each Work Order.		
	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.		
	If not already installed, install and hook up the charged battery.		
	If a battery is already in place, use the voltage tester to check for minimum voltage of 11.7 volts. If the voltage is lower, replace the battery with a charged battery.		
3	Turn the sampler ON. "Program halted" will be displayed; press the Enter/Program button to enter program/configure sequence.		
4	Check the configuration and programming parameters to ensure they are still correct for the specific installation (see Attachment 4 and 5 for the correct parameters).		
5	Check integrity and condition of sampler tubing, actuator, wiring, etc., to ensure sampler will properly collect a sample.		

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 9 of 26
	Effective Date: September 5, 2013	

6	To test the integrity of the tubing, press "Pump forward" to turn on pump and test for suction at the tubing intake. Press "Stop" to turn off pump.
	If no suction is felt at the intake, check the integrity of the tubing and replace as necessary.
7	To activate the sampler, press "Start sampling" and "Enter" twice.
8	Ensure the sampler indicates "Sampler Inhibited".
9	Complete the responses for the sampler activation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

5.6 CONFIGURING ISCO AVALANCHE SAMPLERS

Step	Action
1	When a new ISCO Avalanche sampler is being installed, configure the sampler in accordance with the steps contained in this section. Follow the project-specific configuration settings as indicated on the work order and given in Attachment 8, ISCO Avalanche Configuration Settings.
2	Turn on the sampler by pressing the "Standby" key.
3	From the main menu, select Other Functions, to access the menus and select options given in Attachment 8.
4	Set the configuration parameters in accordance with the guidance on Attachment 8, ISCO Avalanche Configuration Settings.
5	After the programming is complete, select "Run diagnostics" and press "Enter" to run the system diagnostic test. These include the following: RAM and ROM test Pump test ("ON/OFF" ratio should be between 0.80 and 1.25 for a successful test) Distributor test select "YES" to run test. Test will move the distributor to Position 14 and then return it to Position 1.
6	Following the diagnostic tests, "Reinitialize Controller" will be displayed. Select "No" and press the "Enter" key. (If "Yes" is selected, the sampler will reset a number of configuration and program settings to the factory default values).
7	If a 700 series module (e.g., pH) is to be installed, consult the equipment manufacturer's manual for installation instructions. NOTE: The pH module is only required at the Asphalt Batch Plant.
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items contained within it have been completed.

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 10 of 26
	Effective Date: September 5, 2013	

5.7 PROGRAMMING ISCO AVALANCHE SAMPLERS

Step	Action
1	Follow the steps in this process to program a new ISCO or to confirm the program settings are correct for a specific location and bottle configuration. Follow the project-specific program settings as indicated on the work order and given in Attachment 8, ISCO Avalanche Program Sequence.
2	Turn on the sampler by pressing the "Standby" key.
3	Press the "Program" button.
4	Select the current program to review settings, or choose "Select New Program" to create a new program with different settings.
5	Select the current program to review settings, or choose "Select New Program" to create a new program with different settings.
6	At the prompt "Programming complete, run this program now?", select "Yes" if sampler is scheduled to be active, and "No" if sampler is in stand down.
7	Set switch on actuator to "Latch."
8	Complete the responses for the sampler installation tasks listed on the Work Order. Sign and date the Work Order and ensure all items within it have been completed.

5.8 ACTIVATING ISCO AVALANCHE SAMPLERS

Step	Action		
1	Follow the steps in this section when a Work Order is received to activate a sampler (generally at the beginning of a field season or at the beginning of the next quarter after the last quarterly monitoring sample was obtained).		
	Note: The MSGP monitoring quarters are as follows		
	 April 1 through May 31 June 1 through July 31 August 1 through September 30, and October 1, through November 30. 		
2	NOTE: You must be a trained electrical worker and have completed all required courses in Training Plan #2876 to conduct this step.		
	If not already installed, install and hook up the charged battery(ies).		
	If a battery is already in place, use the voltage tester to check for minimum voltage of 11.7 volts. If the voltage is lower, replace the battery with a charged battery.		
3	Turn on sampler power. From the main menu, select "Program" and the "Enter" key to enter programming sequence, and "Other Functions" to enter the configuration settings.		
4	Check the programming/configuration parameters to ensure they are still correct for the specific installation – follow the two preceding sections for the steps and see Attachment 7 and 8 for the correct parameters.		
5	Check integrity and condition of sampling tubes, actuator, wiring, etc., to ensure sampler		

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 11 of 26
	Effective Date: September 5, 2013	

	will properly collect a sample.
6	From the main menu, select "Other Functions" ▶ "Manual Functions" ▶ "Operate Pump" to perform a manual suction test. To test the integrity of the tubing, press "Pump forward" to turn on pump and test for suction at the tubing intake. Press "Stop" to turn off pump. If no suction is felt at the intake, check the integrity of the tubing and replace as necessary.
7	Reset the actuator by toggling the switch to "Reset" then back to "Latch." To activate the sampler, ensure the correct program name is displayed on the main menu and select "Run".
8	Ensure the sampler indicates "Program Disabled".
9	Note: The Avalanche refrigeration system is active any time the controller is powered. This is true for all states (including OFF), except for the time between entering RUN and the completion of the first sample, and when the pump is running. To conserve power, the Avalanche assumes that during this time there is no sample liquid to cool.
10	
	Ensure that all items on the Work Order have been completed.

5.9 STANDING DOWN OR WINTERIZING SAMPLERS

Step	Action
1	Follow the steps in this section when a Work Order is received to turn off ("stand down") a sampler (generally at the end of a field season, which is November 30, or to disable a sampler for a certain time period after a sample was collected). Fill out the LANL MSGP ISCO Sampler Winter Shut-Down Form in Attachment 9.
2	ISCO 3700: Turn off power. ISCO Avalanche: The Avalanche refrigeration system is active any time the controller is powered. This is true for all states (including OFF), except for the time between entering RUN and the completion of the first sample, and when the pump is running. To conserve power, the Avalanche assumes that during this time there is no sample liquid to cool. NOTE: To ensure that the refrigeration system does not activate during an intended stand down, disconnect the sampler from the power source.
3	Remove the battery and return it to the storage compound at TA-64 or other specified location identified by ENV-CP MSGP stormwater compliance personnel. Store cables inside the Greenlee TM box. If the actuator and tubing are not contained within conduit, disconnect these and place them in the box. Close sampler. Avalanche samplers must not be left in place for the winter, and are required to be returned to ENV-CP's storage shed.
4	Ensure that all items on the Work Order have been completed.

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 12 of 26
	Effective Date: September 5, 2013	

5.10 SAMPLER RESET AND RE-INITIALIZATION AFTER SAMPLE COLLECTION

Step	Action
1	Follow ENV-CP-QP-047, <i>Inspecting Storm Water Runoff Samplers and Retrieving Samples for the MSGP</i> for collecting samples from an ISCO and installing new bottles so it is ready to collect new samples.
2	After collecting samples and resetting the sampler, follow instructions on sample collection Work Order, the updated sample tracking log or confer with the MSGP Project Lead regarding whether the sampler should be disabled. If sampler is to be deactivated, follow the steps specific to each sampler provided in the preceding section.
	If an ISCO 3700 sampler is to be left activated, reset the actuator by toggling the switch to "Reset" then back to "Latch", and press "Start sampling" and "Enter" twice. Ensure the sampler display indicates "Sampler Inhibited":
	If an ISCO Avalanche sampler is to be left activated, reset the actuator by toggling the switch to "Reset" then back to "Latch." From the main menu, verify the correct program name is displayed and select "Run." Ensure the sampler display indicates "Program Disabled."

5.11 REMOVING A SAMPLER

Step	Action
1	Follow the steps in this process when a Work Order is received to un-install or remove a sampler. Fill out the LANL MSGP ISCO Sampler Decommission Form in Attachment 10.
2	Disconnect all equipment and remove it from the site. Return the equipment to the ENV-CP Storage Shed or other location specified by MSGP storm water compliance personnel.
3	Dispose of all equipment components that contacted samples (tubing, bottles, etc.) as waste according to applicable waste management procedure. For assistance, contact the Waste Management Coordinator for TA-59.
4	Ensure that all items on the Work Order have been completed.

6.0 REFERENCES

ENV-DO-QP-110, Records Management Program

ENV-DO-QP-115, Personnel Training

ENV-CP-QP-047, Inspecting Storm Water Runoff Samplers and Retrieving Samples for the MSGP

Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 13 of 26
the MSGP	Effective Date: September 5,	2013

7.0 **DEFINITIONS**

ENV-CP: Environmental Protection Division, Compliance Programs Group

<u>Grab Sample:</u> A single sample collected at an NPDES outfall (using approved EPA methods) at a particular time that represents the composition of the storm water at that time and place.

IWD: Integrated Work Document

MSGP: Multi-Sector General Permit

MST: Mountain Standard Time

NPDES: National Pollutant Discharge Elimination System

8.0 ATTACHMENTS

Attachment 1- LANL MSGP ISCO Sampler Installation Form 045-1

Attachment 2- Wiring Diagram for Avalanche Sampler

Attachment 3 – Battery Photovoltaic Connection Wiring

Attachment 4 - ISCO 3700 Configuration Settings

Attachment 5 – ISCO 3700 Program Sequence

Attachment 6 – LANL MSGP ISCO Sampler Activation Form 045-3

Attachment 7 – ISCO Avalanche Configuration Settings

Attachment 8 – ISCO Avalanche Program Sequence

Attachment 9 – LANL MSGP ISCO Sampler Winter Shut-Down Form 045-5

Attachment 10 – LANL MSGP ISCO Sampler Decommission Form 045-6

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1

Page 14 of 26

Effective Date: September 5, 2013

ATTACHMENT 1- LANL MSGP ISCO SAMPLER INSTALLATION FORM 045-1

ENV-QP-045.0			LANL Multi-Sector General Permit ISCO Sampler Installation Form				Form 045-1 (3/2011)			
Outfall: 54-G-4: 54-PAD10E				Project ID: P-MSGP-2443				Work Order ID: MSGP-31193		
Target Date: 4/	1/2013				Date:	14 /1 6		Tin	ne:	
					Name/Z#:					
Project: M	ISGP 2013	Sampler Install			Name/Z#:					
Reason: M	ISGP 2013	Sampler Installation	1		Lead Signature:					
					"I confirm t	he informati	on as reco	rded is true,	accurate and	complete."
	erify the	equipment list b	elow. Make	corrections as rec	uired and fill in	missing i	nformatio	on (e.g., se	erial number	rs).
Equipment		Manufacturer	Model	Serial No.		Specificat	ion		Configuratio	n
Actuator		ISCO	1640	210J01660						
Charge Controller	r	Xantrex	C-12	B20037667						
ISCO 3700 Samp		Teledyne	3700	198H00978		Bottle Set			12c- 1 1L Glass, 11 1L Poly	
ISCO 3700 Samp	0.000	Teledyne	3700	198H00978		Program	The Street		Time / Multiplex no delay	
ISCO Avalanche	10.00 \$ 777	Teledyne	Avalanche	210J00066		Program	Bottle Set		14 950 mL Poly 1-Part, 14 Bottles, 950 mL	
Pb-Acid Battery	Sampler	Teledyne Universal	Avalanche 110 A-h	210J00066 MSGP-110-03	211.07	Voltage			>11.7 V	wes, 930 IIIL
Pb-Acid Battery		Universal	110 A-h	MSGP-110-03		Voltage			>11.7 V	
Pb-Acid Battery		Universal	110 A-h	MSGP-110-03		Voltage			> 11.7 V	
Solar Panel		SunWize	SW-S85P	11004467						
		ISO	CO Sampler	Tasks			Note: If	'No" provide	correct inform	mation or explanation.
Deploy battery(ies) if not listed in equipment list above. Record serial numbers of battery(ies) installed.							□Yes	□No		
Deploy Avalanche sampler matching serial number listed in equipment list above for installation.							□Yes			
Deploy and instal	nent list above and pro	obe saturation rese	ervior.	□Yes						
Refer to the wirin	on, and type of sai	mpler	□Yes	1,2,1						
Is the sampler installed according to steps in ENV-QP-045.0?							□Yes	□No		
Is a Greenlee box used?								□No		
Are electrical connections secure?								□No		
Record battery voltage(s). Voltage(s) > 11.7 V ?							□Yes	□No		
Is the sampler ph base, arm)?	r of bottles specified a	bove (i.e., correct o	carousel,	□Yes	□No					
Is the sampler pro	t specified above?		□Yes	□No						
Does sampler pass the ISCO diagnostics test?							□Yes	□No		
Does sample tubing pass suction test?							□Yes	□No		
Is sampler ON upon departure?							□Yes	□No		
Does ISCO displa			□Yes	□No						
Has the actuator			□Yes	□No						
If any maintenance completed, check YES and describe.							□Yes	□No		
If any follow-on m			□Yes	□No						
LANL PERSONNEL USE ONLY (Initials and dates)										
Accepted			Te	ech QC				ENV-RCR	A Review	
			_			4		-		


Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1

Page 15 of 26


Effective Date: September 5, 2013

ATTACHMENT 2- WIRING DIAGRAM FOR AVALANCHE SAMPLER



Installing, Setting Up, and Operating ISCO Samplers for	No. ENV-CP-QP-045.1	Page 16 of 26	
the MSGP	Effective Date: September 5,	, 2013	


ATTACHMENT 3 – BATTERY PHOTOVOLTAIC CONNECTION WIRING



Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 17 of 26

Effective Date: September 5, 2013



Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 18 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 4 - ISCO 3700 CONFIGURATION SETTINGS

Parameter	Storm sampling with multiplex, timed delay	Time sampling with multiplex	Flow sampling with multiplex
Time/ Date	[Set to MST]	[Set to MST]	[Set to MST]
Portable/ Refrig	Portable	Portable	Portable
Bottles	12 or 24	12 or 24	12 or 24
Bottle volume	950 ml	1000 ml	1000 ml
Suction line diameter	3/8 inch	3/8 inch	3/8 inch
Suction line type	Teflon	Teflon	Teflon
Suction line length	X feet	X feet	X feet
Liquid detector	Enable	Enable	Enable
Rinse cycles	0	1	1
Enter Head Manually	No	Yes	Yes
Retry	1	1	1
Program mode	Extended	Basic	Basic
Load program	None	N/A	N/A
Save program as	None	N/A	N/A
Take sample at start time	No	N/A	N/A
Take sample at time switch	No	N/A	N/A
Enter intervals in minutes	1 minute	N/A	N/A
Calibrate sampler	Disable	Enable	Enable
Sampling stop/resume	Disable	N/A	N/A
Start time delay	0 minutes	0 minutes	0 minutes
Master slave	No	No	No
Sample upon Disable	No	No	No
Sample upon enable	No	Yes	Yes
Reset sample interval	Yes	Yes	No
Inhibit countdown	Yes	Yes	No
Event marker	Pulse	Pulse	Pulse
At the beginning of:	Purge	Purge	Purge
Purge counts presample counts	150	100	100
Post sample counts	394	1000	1000
Pump counts	[500,000]	[500,000]	[500,000]
Reset pump counter	No	No	No
Pump counts to warning	500,000	500,000	500,000
Program lock	Disable	Disable	Disable
Sampler ID number is:	[leave blank]	[leave blank]	[leave blank]
Run diagnostics	Yes	Yes	Yes
Test distributor	Yes	Yes	Yes
Re-initialize	No	No	No

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 19 of 26

Effective Date: September 5, 2013

ATTACHMENT 5 – ISCO 3700 PROGRAM SEQUENCE

	Storm sampling with
Parameter	multiplex, timed delay
[Switch on	Set to "Latch"
liquid actuator]	
Paced sampling	Storm
Time Mode 1st	X-minute delay
Bottle Group	
Timed Sample	1
Event	
Bottle per	11 or 23
sample event	
Sample volume	950 ml
Bottles	1
available	
2 nd bottle group	Time
2 nd group	1-minute delay
samples	
Sample interval	1 minute
Bottles per	1
sampling event	
Sample per	1
bottle	
Sample volume	950 ml
Enter start time	No

[Programming complete]

	Time sampling with
Parameter	multiplex
[Switch on	Set to "Latch"
liquid actuator]	
Time/Flow	Time
Min/Hr	1 min
Multiplex	Yes
samples	
Bottles/sample	Bottles/ sample
or	
Samples/Bottle	
Number of	12 or 24
bottles	
Sample volume	1000 ml
Suction head	XX Ft
Calibrate sample	No
vol	
Enter start time	No

[Programming complete]

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 20 of 26
	Effective Date: September 5, 2013	

Avalanche Program Sequence, cont.

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2-part program		
Two-Part Program					
Part A	N/A	N/A	Yes		
Assign bottle	N/A	N/A	1-X of 4 or 14		
Pacing	N/A	N/A	Uniform time paced		
Time between samples	N/A	N/A	1 minute		
Distribution	N/A	N/A	Sequential		
Bottles per event	N/A	N/A	1		
Switch bottles on	N/A	N/A	Number of samples		
Switch bottles every X samples	N/A	N/	1		
Run continuously	N/A	N/A	No		
Sample volumes dependent on flow?	N/A	N/A	No		
Sample volume	N/A	N/A	Select between 10 ml and full container volume		
Enable programmed	N/A	N/A	None		
Once enabled, stay enabled	N/A	N/A	Yes		
Sample at enable	N/A	N/A	Yes		
Sample at disable	N/A	N/A	No		
Pauses and resumes	N/A	N/A	0		
Part B	N/A	N/A	Yes		
Pacing	N/A		Uniform time paced		
Time between sample events	N/A	N/A	1 minute		
Distribution	N/A	N/A	Sequential		
Bottles per event	N/A	N/A	1		
Switch bottles on	N/A	N/A	Number of samples		
Switch bottles every X samples	N/A	N/A	1		
Run continuously	N/A	N/A	No		
Sample volumes dependent on flow?	N/A	N/A	No		
Sample volume	N/A	N/A	Select between 10 ml and full container volume		
Enable programmed	N/A	N/A	No		

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 21 of 26
	Effective Date: September 5, 2013	

Avalanche Program Sequence, cont.

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2-part program	
Once enabled, stay enabled	N/A	N/A	Yes	
Sample at disable	N/A	N/A	No	
Sample at enable	N/A	N/A	Yes	
Once enabled, stay enabled	N/A	N/A	Yes	
Pauses and resumes	N/A	N/A	0	
Delay to start	N/A	N/A	No	
Reset Sampler				
Switch on liquid actuator	Toggle to "Reset" then back to "Latch"	Toggle to "Reset" then back to "Latch"	Toggle to "Reset" then back to "Latch"	
Select Program name	Run	Run	Run	

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 22 of 26

Effective Date: September 5, 2013

ATTACHMENT 6 – LANL MSGP ISCO SAMPLER ACTIVATION FORM 045-3

NV-QP-045.0 LANL Multi-Sector General Permit ISCO Sampler Activation Form		Form 045-3 (3/2011)			
Outfall: 3-PSP-5 : E121.9-ISCO 12	Project ID: P	-MSGP-830			Work Order ID: MSGP-12785
Target Date: 4/11/2011		Date:			Time:
Project: MSGP Sampler Activation Q1 2011		Name/Z#:_			
Reason: MSGP Sampler Activation 2011 Q1		Name/Z#:_			
Reason. Moor sample Activation 2011 &1		Lead Signal	ture:		
		"I confirm	n the infor	mation as rec	orded is true, accurate and complete."
Equipment Manufacturer	Model	Serial No.	Spec	ification	Configuration
Actuator ISCO	1640		Actua	ntor Height	
ISCO Sampler 12c Teledyne ISCO	ISCO 3700	198H01553	Bottle	Set	12c- 1 1L Poly
ISCO Sampler 12c Teledyne ISCO	ISCO 3700	198H01553	Progr	am	Time / Multiplex no delay
Pb-Acid Battery			Volta	ge	> 11.7 V
ISCO Sampler Tasks		Note: If	"No" prov	ide correct in	formation or explanation.
Is the ISCO time delta < 1 min (MST)? If no, record adjustn	nent.	□Yes	□No		
Does sampler pass the ISCO diagnostics test?		□Yes	□No		
Are electrical connections secure?		□Yes	□No		
Record battery voltage(s). Is/are voltage(s) > 11.7 V?		□Yes	□No		
Does ISCO display either "Bottle 1 of X afer 1" or "Sampler	Inhibited"?	□Yes	□No		
Is bottle set described above installed?		□Yes	□No		
Is recorded height of actuator above channel bottom correct	it?	□Yes	□No		
If any maintenance completed, check Yes: Describe.		□Yes	□No		
If any follow-on maintenance is required, check Yes: Desc	ribe.	□Yes	□No		
Is sampler ON upon departure?		□Yes	□No		
Additional Notes:					
	ANL PERSONNEL I	USE ONLY (I	nitials and	(dates)	
Accepted	Tech QC	USE ONL! (II	ilitiais and	(dates)	RNV-RCRA Review

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 23 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 7 – ISCO AVALANCHE CONFIGURATION SETTINGS

ISCO Avalanche Configuration Settings

Parameter	All programs			
Maintenance				
Set Clock	[Set to MST]			
Pump Tube Alarm	[1,000,000]			
Reset pump counter	No			
Run diagnostics	Yes			
Re-initialize	No			
Softwa	are Options			
Liquid detector	Liquid detect on			
Target temperature	°C			
Measurement interval	1 minute			
Dual sampler mode	Off			
Bottle full detect	Yes			
Event mark	Every sample			
Duration	3 second pulse at initial purge			
Presample purge counts	100			
Post sample counts	Dependent on head			
Periodic serial output	No			
Interrogator connector power	Alarm dial-outs only			
Manua	al Functions			
Grab Sample	Manual option			
Calibrate volume	Manual option			
Operate pump	Manual option			
Move distributor	Manual option			
Other Settings/Misc				
Suction line diameter	3/8 inch			
Suction line type	Teflon			
Program lock	Disable			

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 24 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 8 - ISCO AVALANCHE PROGRAM SEQUENCE

Parameter	Time sampling, single bottle composite sample	Time sampling, 1- part program	Time sampling, 2- part program			
	Program					
Program mode	Extended	Extended	Extended			
Program name	COMPOSITE	1-PART (# bottles)	2-PART (# bottles)			
Site description	Station number	Station number	Station number			
Units (length)	ft	ft	ft			
Units (temperature)	°C	°C	°C			
Data storage interval	1 minute	1 minute	1 minute			
Number of bottles	1	4 or 14	4 or 14			
Bottle volume	10000 ml, 4000 ml	2000 ml, 950 ml	2000 ml, 950 ml			
Suction line length	X feet	X feet	X feet			
Enter Head Manually	Yes	Yes	Yes			
Rinse cycles	1	1	1			
Retries	1	1	1			
	One-Pa	rt Program	1			
Pacing	Uniform time paced	Uniform time paced	N/A			
Time between samples	Every one minute	Every one minute	N/A			
Composite	1 sample	N/A	N/A			
Run continuously	No	N/A	N/A			
Take X sample(s)	1	N/A	N/A			
Distribution	N/A	Sequential	N/A			
Volume	Select between 10 ml and full container volume	Select between 10 ml and full container volume	N/A			
Sample volumes dependent on flow	No	No	N/A			
Enable programmed	None	None	N/A			
Once enabled, stay enabled	Yes	Yes	N/A			
Sample at enable	Yes	Yes	N/A			
Sample at disable	No	No	N/A			
Pauses and resumes	0	0	N/A			
Delay to start	No	No	N/A			

Installing, Setting Up, and Operating ISCO Samplers for the MSGP

No. ENV-CP-QP-045.1 Page 25 of 26

Effective Date: September 5, 2013

ATTACHMENT 9 – LANL MSGP ISCO SAMPLER WINTER SHUT-DOWN FORM 045-5

ENV-QP-045.0		LANL Multi-S ISCO Sampler V						Form 045-5 (3/2011)
Outfall: 3-PSP-5 :	: E121.9-ISCO 12	Project ID: P	-MS	GP-833			Work Order II	: MSGP-12803
Target Date: 11/30/2	2011		Da	ate:			Time:	
D MOOD	1000 0 1 . 185 1 01 . 11		Na	ame/Z#:_				
Project: MSGP	ISCO Sampler Winter Shutdow	vn	Na	ame/Z#:				
Reason: MSGP	Sampler Winter Shutdown 201	11	Le	ead Signat	ture:			
				"I confirm	n the inf	ormation as reco	rded is true, accurate	and complete."
Verif	y the equipment list below. N	lake corrections as r	equir	ed and fi	ill in mis	ssing informatio	n (e.g., serial numb	ers).
Equipment	Manufacturer	Model	Ser	rial No.	Spe	ecification	Configuration	
Actuator	ISCO	1640			Acti	uator Height		
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H	101553	Bot	tle Set	12c- 1 1L Poly	
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H	101553	Pro	gram	Time / Multiplex	no delay
Pb-Acid Battery					Volt	tage	> 11.7 V	
	ISCO Sampler Tasks			Note: If	"No" pro	ovide correct info	rmation or explanation	on.
Turn ISCO unit "OFF."				□Yes	□No			
Place caps securely on	bottles in the sample carousel.			□Yes	□No			
Verify equipment list ab	oove.			□Yes	□No			
ISCO 3700 Sampler U	nits							
Disconnect and remove maintenance and storage	e battery. Transport battery to MSG ge.	P stockroom for		□Yes	□No			
Place battery cables so	ecurely inside Greenlee box or ISC	O casing.		□Yes	□No			
Pull up actuator and tub	bing and store in Greenlee box or I	SCO casing.		□Yes	□No			
Avalanche ISCO Sam	pler Units:							
Disconnect and remove maintenance and storage	e batteries. Transport batteries to M ge.	/ISGP stockroom for		□Yes	□No			
Place battery cables se	ecurely inside Greenlee box or ISC	O casing.		□Yes	□No			
Pull up actuator and tub	bing and store inside Greenlee box	or ISCO casing.		□Yes	□No			
Transport Avalanche sa	ampler to MSGP stockroom for ma	intenance and storage.		□Yes	□No			
Additional Notes:								
		LANL PERSONNEL	USE	ONLY (Iı	nitials ar	nd dates)		
Accepted		Tech QC					ENV-RCRA Review	

Installing, Setting Up, and Operating ISCO Samplers for the MSGP	No. ENV-CP-QP-045.1	Page 26 of 26
	Effective Date: September 5, 2013	

ATTACHMENT 10 - LANL MSGP ISCO SAMPLER DECOMMISSION FORM 045-6

ENV-QP-045.0		LANL Multi-S ISCO Sample			Form 045-6 (3/2011)
Outfall: 3-PSP-5 : E12	1.9-ISCO 12	Project ID:	P-MSGP-834		Work Order ID: MSGP-12804
Target Date: 7/27/2011			Date:		Time:
Project: MSGP Samp	ler Station Decommission	in	Name/Z#:_		
			Name/Z#:_		
Reason: MSGP Samp	ier Decommission		Lead Signal	ture:	
			"I confirm	n the information as reco	orded is true, accurate and complete."
Verify the	equipment list below. N	Make corrections as	required and fi	ll in missing informati	on (e.g., serial numbers).
Equipment	Manufacturer	Model	Serial No.	Specification	Configuration
Actuator	ISCO	1640		Actuator Height	
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H01553	Bottle Set	12c- 1 1L Poly
ISCO Sampler 12c	Teledyne ISCO	ISCO 3700	198H01553	Program	Time / Multiplex no delay
Pb-Acid Battery				Voltage	> 11.7 V
ISCO Sampler Tasks		Note: If	"No" provide correct info	ormation or explanation.	
Is equipment list above comple	ete and accurate?		□Yes	□No	
Turn sampler "OFF." Remove	bottles from carousel.		□Yes	□No	
Disconnect and remove batter	y(ies), solar panel, and cab	les (as applicable).	□Yes	□No	
Pull up actuator and tubing. Di	sconnect from sampler unit		□Yes	□No	
Uninstall Greenlee box, as app	olicable.		□Yes	□No	
Transport all removed equipment storage.	ent to the MSGP stockroom	n for maintenance and	□Yes	□No	
Additional Notes:					
		LANL PERSONNEL	USE ONLY (I	nitials and dates)	
Accepted		Tech QC	F 2 7 F		ENV-RCRA Review

EPC-CP-QP-048	Revision: 3	Los Alamos
Effective Date: 10/05/2017	Next Review Date: 10/05/2020	NATIONAL LABORATORY EST. 1943

Environment, Safety, and Health Directorate Environmental Protection and Compliance—Compliance Programs Quality Procedure

Processing MSGP Stormwater Samples

Document Owner/Subject Matter Expert:				
Name:	Organization:	Signature:	Date:	
Holly L. Wheeler	EPC-CP	Signature on File	10-4-17	
Derivative Classifier: Unclassified or DUSA ENVPRO				
Name:	Organization:	Signature:	Date:	
Ellena Martinez	EPC-CP	Signature on File	10-3-17	
Approval Signatures:				
Subject Matter Expert:	Organization:	Signature:	Date:	
Holly L. Wheeler	EPC-CP	Signature on File	10-4-17	
Responsible Line Manager:	Organization:	Signature:	Date:	
Terrill W. Lemke	EPC-CP Team Leader	Signature on File	10-5-17	
Responsible Line Manager:	Organization:	Signature:	Date:	
Michael Saladen	FPC-CP Group Leader, Acting	Signature on File	10-5-17	

This copy is uncontrolled.

Users are responsible for ensuring they work to the latest approved version. To document a required read, Login to UTrain, and go to the Advanced Search.

Processing MSGP Stormwater	EPC-CP-QP-048	Page 2 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

REVISION HISTORY

Document Number and Revision [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
ENV-RCRA-QP-048, Rev. 0	07/2011	New document
ENV-CP-QP-048, Rev. 1	09/2013	Annual Review and Revision, new format, process change, and new organization name.
EPC-CP-QP-048, Rev. 2	06/05/2017	Review and Revision, new format, and new organization name, clarified steps, updated attachments.
EPC-CP-QP-048 R3	10/05/2017	Updated Sample Collection Log instructions, added step describing evidence of flow, and added section for addressing excess stormwater material.

Processing MSGP Stormwater Samples

EPC-CP-QP-048	Page 3 of 14
Revision: 3	Effective Date: 10/05/2017

Table of Contents

Qual	ity Pr	ocedure	1
	•	History	
		Contents	
1.0	Intro	oduction	4
		Purpose	
	1.2	Scope	
	1.3	•	
2.0	Pred	cautions and Limitations	
3.0		equisite Actions	
	3.1	Planning and Coordination	5
	3.2	Tools and Equipment	5
4.0	Proc	cessing samples	6
	4.1	Preparation for Processing Samples	6
	4.2	Filtering Samples	7
	4.3	Preserving Unfiltered and Filtered Samples	8
	4.4	Handling Excess Stormwater	8
	4.5	Submit Samples for Shipping to Offsite Analytical Laboratory	9
5.0	Trai	ning	. 10
6.0	Reco	ords	. 10
7.0	Defi	nitions and Acronyms	. 10
	7.1	Definitions	. 10
	7.2	Acronyms	. 11
8.0	Refe	erences	. 11
9.0	Atta	chments	. 11
Atta	chme	nt 1: Sample Collection Log/Field Chain of Custody Example	. 12
Atta	chme	nt 2: Sample Container Labels Example	. 13
Atta	chme	nt 3: Chain Of Custody/Analysis Request Example	. 14

Processing MSGP Stormwater	EPC-CP-QP-048	Page 4 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

1.0 INTRODUCTION

Los Alamos National Security, LLC (LANS) through Environmental Protection and Compliance-Compliance Programs (EPC-CP) conducts stormwater monitoring activities required pursuant to the National Pollutant Discharge Elimination System (NPDES), Multi-Sector General Permit (MSGP) at Los Alamos National Laboratory (LANL). The MSGP requires LANL to monitor stormwater runoff from industrial sites relative to potential pollutants.

1.1 Purpose

This procedure describes the process for filtering, preserving and preparing stormwater samples for shipment to an analytical laboratory from monitored outfall locations.

1.2 Scope

This procedure applies to the EPC-CP technical staff and subcontractor personnel (as applicable) who conduct processing and chemical preservation of stormwater samples either in the TA-59-1 Stormwater Laboratory or in the field.

The MSGP Program Lead is the primary person responsible for developing and updating this procedure. EPC-CP personnel will be appointed with responsibility for a subset of sampling stations.

1.3 Applicability

Stormwater samples are collected in the field either with a refrigerated Avalanche® or ISCO 3700 automated sampler, single stage sampler or grab sample. When in-line filtration is not possible, sample filtration along with chemical preservation will be conducted immediately following sample retrieval in the field or in the EPC-CP Stormwater Laboratory (TA-59-01).

Sample collection, submission, and analysis is conducted using EPA and New Mexico Water Quality Control Commission guidelines. Monitoring samples are collected and analyzed according to test procedures approved under Title 40 of the Code of Federal Regulations (40 CFR) Part 136 unless other test procedures have been specified in the MSGP permit. Quantitation limits associated with these test procedures are sufficiently sensitive to meet MSGP permit limits.

2.0 PRECAUTIONS AND LIMITATIONS

Hazards in the work described in this procedure are controlled through site specific Integrated Work Documents (IWDs). The hazard level for the activities in this procedure is **moderate**.

Use only sample containers that are documented to meet or exceed "US EPA Specification and Guidance for Contaminant-Free Sample Container" (Publication 9240.05A, EPA/540/R-93/051, December 1992). Never clean or re-use sample containers. Keep containers in a clean, dry place until a sample is ready for processing and transfer to the appropriate container(s).

Processing MSGP Stormwater	EPC-CP-QP-048	Page 5 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

3.0 PREREQUISITE ACTIONS

3.1 Planning and Coordination

Promptly schedule and complete all stormwater processing to meet the analytical holding time requirements identified in the MSGP Sampling and Analysis Plan or as requested by the MSGP Program Lead.

The MSGP Data Manager will generate Sample Collection Log/Field Chain of Custody (SCL) form(s) at the beginning of the MSGP monitoring season and/or the beginning of each MSGP monitoring quarter. The MSGP Data Manager will generate Chain of Custody/Analysis Request(s) from the Environmental Information Management (EIM) database as stormwater is collected. If the MSGP Data Manager is not available, forms may be obtained from the Sample Management Office (SMO).

3.2 Tools and Equipment

Ensure the following equipment is available:

- Safety glasses with side shields
- Nitrile gloves
- Lab coat
- Eyewash in Stormwater Lab (or portable eyewash in the field)
- Sample Collection Log/Field Chain of Custody Form
- Chain of Custody/Analysis Request
- Copy of the MSGP Sampling and Analysis Plan
- Sample containers (glass and poly bottles)
- Sample container lids
- Acid and base preservatives
- Clean silicon (e.g. Tygon) tubing
- Portable peristaltic pump (e.g. Geopump or equivalent)
- 0.45 micron and/or 0.10 micron cartridge filters (where applicable)
- Paper Towels
- Coolers with ice, Blue Ice[®], or equivalent
- Ball point pen
- Permanent marker
- Chain-of-custody seals/tape
- Copy of this procedure
- Copy of the Integrated Work Documents (IWDs)
- Cell phone (only government cell phones with batteries removed are allowed in secure areas)

Processing MSGP Stormwater	EPC-CP-QP-048	Page 6 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

4.0 PROCESSING SAMPLES

In this procedure, sample collection bottles are the bottles in which the sample was collected in the field. Sample containers are containers into which the original sample may be transferred (as necessary) during processing and shipped to the analytical laboratory.

4.1 Preparation for Processing Samples

- 1. Don nitrile gloves, safety glasses with side shields, and lab coat. Long pants are required and no open toed shoes are allowed. Prior to processing samples, confirm eyewash is operational.
- 2. On the work bench arrange sample collection bottles in order from one MSGP sampling location according to the ISCO carousel number marked on the bottle.

CAUTION

Process only one sample set (i.e., samples listed on one Sample Collection Log/Field Chain of Custody form) at a time to ensure stormwater from different locations is not co-mingled.

- 3. Cross check the Location ID (e.g. MSGP00201) on the sample bottles with the requested analysis for that location on the SCL form (see example in Attachment 1).
- 4. Write the following information on the SCL:
 - Sampler Inspection and Sample Retrieval form (QP-047) identification number (e.g. Work Order: MSGP-xxxx)
 - Date and time the sample was collected in the field (e.g., date/time automated sampler filled sample bottles or a grab sample was taken)
 - pH measurement taken at the time the sample was collected in the field (as necessary)
 - Indicate if evidence of flow was recorded by writing "Y" for Yes or "N" for No
 - Indicate if a visual assessment was performed by writing "Y" for Yes or "N" for No
 - Visual Assessment form (QP-064) identification number (e.g., Visual WO#: MSGPxxxx) if applicable
 - Date and time the visual assessment was performed if applicable
 - Printed name of person collecting the sample
 - Date and time the sample was RETRIEVED
- 5. Ensure the sample container type and chemical preservation type is correct for the analysis requested on the SCL (e.g., 500 ML POLY, HNO3). Note any deviation from the planned sample container volume or type on the SCL.
- 6. Indicate if each sample on the SCL was collected by writing Y for Yes or N for No under "Collected Y/N".

Processing MSGP Stormwater	EPC-CP-QP-048	Page 7 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

- 7. Determine which samples require filtration and chemical preservation as requested on the SCL. Refer to Sections 4.2 and 4.3 as needed. Requirements are also identified in the most current revision of the MSGP Sampling and Analysis Plan.
- 8. Mark on each container lid the 3-digit outfall ID, required analysis, filtration requirement, and preservative requirement."
- 9. Document any other deviations from "As Planned" conditions in the "As Collected" column on the SCL (e.g., change the Field Matrix code from rain (WT) to snowmelt (WM)).

4.2 Filtering Samples

Filter samples if specified on the SCL or if an in-line filter was not used during sample collection.

- 1. Don nitrile gloves and safety glasses with side shields. Long pants are required and no open toed shoes are allowed. Prior to filtering samples, confirm eyewash is operational.
- 2. Ensure the sample container volume and container type (e.g., 1 L GLASS) is correct for the analysis requested on the SCL. Note any deviation from the planned sample container volume or type on the SCL.
- 3. Select the appropriate sized cartridge filter (e.g., 0.10μm or 0.45μm).
- 4. Attach an appropriate amount of silicone tubing to both ends of the cartridge filter. Place the filter upstream of the peristaltic pump to prevent over-pressurization. If the sample contains a significant amount of sediment, a pre-filter of the same size or larger micron capacity may be used.
- 5. For split samples(filtered and unfiltered), turn the sample collection bottle upside down multiple times to ensure all sediment is loose from the bottom of the bottle and move the intake tube up and down through the sample during filtration. A sample collected solely for filtration can be filtered without being homogenized by shaking.
- 6. Replace the filter if flow diminishes, the pump begins to make a grinding sound, or the tubing is forced off the filter by back pressure.
- 7. Add a check mark next to the filtered requirement previously marked on the lid to indicate that filtration has been completed.
- 8. Clean and dry the exterior of sample container and check sample container for leakage and breakage.
- 9. If no further processing is required (e.g., chemical preservation), apply a chain-of-custody seal/tape around the bottle and lid and sign and date the seal/tape.
- 10. Remove filter and tubing when filtration of one sample set (location) has been completed. A new filter must be used with each new sample ID.

Processing MSGP Stormwater	EPC-CP-QP-048	Page 8 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

4.3 Preserving Unfiltered and Filtered Samples

Preservation entails the addition of acid or base to a sample. Acids used include hydrochloric acid (HCl), nitric acid (HNO₃), and sulfuric acid (H_2SO_4). Bases used in preservation include sodium hydroxide (NaOH).

CAUTION

The preservatives are strong acids and bases that can cause severe burns. Extreme care should be taken when using these acids and bases. Review the appropriate Material Safety Data Sheet or Safety Data Sheet for specific guidelines prior to preserving samples.

- 1. Don nitrile gloves, safety glasses with side shields, and a lab coat. Long pants are required and no open toed shoes are allowed. Prior to chemically preserving samples, confirm eyewash is operational.
- 2. Ensure the sample container volume, type, and preservation type is correct for the analysis requested on the SCL or Sampling and Analysis Plan (e.g., 500 ML POLY, HNO₃). Note any deviation from the planned sample container volume or type on the SCL.
- 3. Select the pre-measured preservative size that matches the sample container size.

Note: If you only have one size pre-measured preservative that does not match the sample container size you may need to use more than one. For example, if you have a 1 liter sample container and 500 ml pre-measured preservative vial, you would need to add two preservative vials to the sample container.

Never "split" a larger volume pre-measured vial to preserve a smaller volume container (e.g., do not pipette from a 1 liter pre-measured preservative vial to preserve a 500 mL sample) as error in measurement precision may lead to a risk of violating Department of Transportation shipping requirements.

- 4. Add the preservative (acid or base) to the sample and securely affix the lid to the container.
- 5. Agitate the preserved sample by turning the container upside down two to three times.
- 6. Add a check mark next to the preservation type previously marked on the lid to indicate that preservation has been completed.
- 7. Clean and dry the exterior of sample container and check sample container for leakage and breakage.
- 8. Apply a chain-of-custody seal/tape around the bottle and lid and sign and date the seal/tape.

4.4 Handling Excess Stormwater

All efforts will be made to minimize the amount of stormwater sample brought into the TA-59-1 Stormwater Lab. Field personnel will attempt to retrieve only the volumes needed to fulfill the requested analyses from the current MSGP Sampling and Analysis Plan.

Processing MSGP Stormwater	EPC-CP-QP-048	Page 9 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

If any excess stormwater sample exists after processing has been completed:

- Ensure the container is labeled with the site of origin, date and time sample was collected, and "Return to Site".
- Place the container in the designated storage location in the MSGP Stormwater Lab,
- Return the sample to the site of origin as soon as possible and discharge at the sampler location.

If the excess stormwater has been altered (e.g. tap water or preservative added) contact the Waste Management Coordinator for TA-59-1 for further instruction.

4.5 Submit Samples for Shipping to Offsite Analytical Laboratory

- 1. Deliver completed SCL(s) to the MSGP Data Manager.
- 2. The MSGP Data Manager will process the sample information in the EIM system, capturing any documented deviations from planned conditions (as noted on the SCLs), and generate Chain of Custody/Analysis Request (COC) form(s) and sample container labels to reflect the "as collected" samples (see examples in Attachments 2 and 3).
- 3. In the "Received By" section of the SCL, enter the COC number (e.g., 2017-XXXX).
- 4. Don nitrile gloves and safety glasses.
- 5. Ensure the sample containers are securely sealed and wiped dry.
- 6. Cross check that the Sample ID on the SCL matches the Field Sample ID on the COC.
- 7. Carefully compare the information from the SCL and lid of each container to apply the correct labels to the sample containers.
- 8. Place the sample(s) in the cooler with sufficient Blue Ice® (or equivalent) to maintain the required preservation temperature (≤4° C). Cushioning material (e.g., bubble wrap) may be used to separate containers to avoid breakage during transport.
- 9. Place the SCL(s) and COC(s) in a zip lock type bag, seal, and place in the cooler with samples.
- 10. Transport samples to the Sample Management Office (SMO) using a government vehicle or approved subcontractor vehicle only. Samples may be delivered during SMO business hours, but must be delivered by 2pm for same day shipping. Coordinate with the SMO for delivery during other times or for delivery of samples that have limited holding times.
 - **Note**: If submitting samples to the SMO will be delayed, place sample containers with SCL(s) in the Stormwater Laboratory refrigerator and ensure the refrigerator is locked.
- 11. On the COC, the person submitting the sample(s) will print and sign their name, date, and record the time under "Relinquished By." The SMO personnel accepts the sample(s) by printing and signing their name, dating, and recording the time under "Received By."
- 12. Retain a copy of the signed Chain of Custody/Analysis Request.

Processing MSGP Stormwater	EPC-CP-QP-048	Page 10 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

- 13. On the SCL, the person submitting the sample(s) will enter the data and time under "Relinquished By" that matches the data and time "Relinquished by" on the COC and write the COC/Lab Request# (e.g., 2017-xxxx) under "Received by."
- 14. Ensure the SMO makes a copy of the SCL(s) to accompany the COC and samples. Retain the original SCL(s) for the MSGP program.
- 15. Deliver the copy of the signed COC and original SCL(s) to the MSGP Data Manager.

5.0 TRAINING

The training method for this procedure is "self-study" (reading). The following personnel require training before implementing this procedure:

• EPC-CP technical staff and subcontract or other personnel who process stormwater samples for the MSGP.

Personnel performing this procedure will be familiar with the most current versions of the following procedures and operation manuals:

- EPC-CP MSGP Sampling and Analysis Plan for the current monitoring year
- EPC-CP-QP-047 Inspecting Stormwater Runoff Samplers and Retrieving Samples for the MSGP

6.0 RECORDS

Records generated by this document will be submitted to the ADESH Records Management designated point of contact or document manager in accordance with P1020-1, *Laboratory Records Management* and with ADESH-AP-006, *Records Management Plan*. Below is a list of records generated as a result of implementing this procedure.

- Sample Collection Log/Field Chain of Custody Form
- Copy of the Chain of Custody/Analysis Request
- Copy of log book entry(s) (if a log book is used)
- Other pertinent field or lab notes

7.0 DEFINITIONS AND ACRONYMS

7.1 Definitions

See LANL Definition of Terms.

Processing MSGP Stormwater	EPC-CP-QP-048	Page 11 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

7.2 Acronyms

See LANL Acronym Master List.

40 CFR	Title 40 of the Code of Federal Regulations	
СОС	Chain of Custody/Analysis Request	
EIM	Environmental Information Management	
EPC-CP	Environmental Protection and Compliance – Compliance Programs	
IWD	Integrated Work Document	
LANL	Los Alamos National Laboratory	
LANS	Los Alamos National Security, LLC	
MSGP	Multi-Sector General Permit	
NPDES	National Pollutant Discharge Elimination System	
SCL	Sample Collection Log/Field Chain of Custody	
SMO	Sample Management Office	

8.0 REFERENCES

None

9.0 ATTACHMENTS

Attachment 1: Sample Collection Log/Field Chain of Custody Example

Attachment 2: Sample Container Labels Example

Attachment 3: Chain of Custody/Analysis Request Example

Processing MSGP Stormwater
SamplesEPC-CP-QP-048Page 12 of 14Revision: 3Effective Date: 10/05/2017

ATTACHMENT 1: SAMPLE COLLECTION LOG/FIELD CHAIN OF CUSTODY EXAMPLE

Page 1 of 1

Los Alamos National Laboratory

MSGP Quarter 3

SAMPLE COLLECTION LOG/FIELD CHAIN OF CUSTODY

EVENT ID: 11198

EVENT NAME: MSGP 2017

SAMPLE ID: MSGP-17-131989 WORK ORDER: MSGP-59823

SAMPLE ID:	MSGP-17-131	989		WORK C	ORDER: MSGP-50	1823
	AS PLAN	- 400	OLLECTED		AS PLANNED	AS COLLECTED
Date Collected (MM/DD/YYY):		41	01 17	FIELD MATRI	x :w	
TIME COLLECT! (HH:MM):	ED		:03	MEDIA:		
PRS ID:			1	SAMPLE TEC CODE:	H APS	
LOCATION ID:	MSGP05	301		FIELD PREP:	UF	
LOCATION TYP	E:			FIELD QC TY	PE: REG	
TOP DEPTH:				SAMPLE USA	GE: COMP)
BOTTOM DEPTH	H:			EXCAVATED:		YES / NO / NA
PRIORITY	ORDER	CONTAINER	# PRES	SERVATIVE	COLLECTED Y/N	SPECIAL INSTRUCTIONS
	MSGP- CN(TOTAL)	500 ML POLY	1	NAOH	У	
	MSGP- COD+NH3	500 ML POLY	1 H2	SO4 ICE	У	
	MSGP- Mg+Se+Hg	500 ML POLY	1 H	NO3 ICE	у	
SAMPLE COMM	MENTS:					
LOCATION COI	MMENTS:				McCD 5	90//
FIELD PARAME	TERS:			V	Visual WO# MSGP - 5	
рн <u>6.7</u>	Flow (Evidence)	7	Visual Inspection	su	Visual performed Date/Tim	e 4 3 17 14:36
COLLECTED B	Y (PRINT): Jo	une Doe	Retrieved 1	4/3/17 14:36		
RELINQUISHED (Printed Name) (Signature)			Date/Time	RECEIVED B (Printed Nam (Signature)		Date/Time 4 12 17 15: 10
RELINQUISHED (Printed Name) (Signature)			Date/Time	RECEIVED B (Printed Nam (Signature)	Y	Date/Time

Report Date: 07/21/2017

Processing MSGP Stormwater	EPC-CP-QP-048	Page 13 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

ATTACHMENT 2: SAMPLE CONTAINER LABELS EXAMPLE

Page 1 of 1

Los Alamos National Laboratory				
Sample ID: MSGP-	17-131786			
Container: 500 M	L POLY			1 of 1
Preservative: HN	D3 ICE			
Analysis: NPDES-/	Al-Total Recovera	able	10	
Date/ 0/4/0	1/2017	Time:	16:03	-

Los Alamos Na	tional Labo	ratory
Sample ID: MSGP-17-131787		
Container: 500 ML POLY		1 of 1
Preservative: HNO3 ICE		
Analysis: NPDES-Al-Total Recovers	able	-
Date/ 04/01/2017	Time: 16:	03

Processing MSGP Stormwater	EPC-CP-QP-048	Page 14 of 14
Samples	Revision: 3	Effective Date: 10/05/2017

ATTACHMENT 3: CHAIN OF CUSTODY/ANALYSIS REQUEST EXAMPLE

Page 1 of 1

LANL SMO			Chair	10	f C	cus	to	dy/	/Ar	na	lys	sis	R	e (qu	es	t			4	20	0C/Lab Re 017-1326 Page 1 of 1	7,
Client Contact:	Lab Agreem	Lab Agreement #: Site Name: Los Alamos National Laboratory																					
	Project Num																				Rac	d Screeni	ng Info:
	14 Days - 21 Days - 28 Days -			P-Zn								4									1		ng Limit Ty etection Li
Field Sample ID	Sample Date	Sample Time	Sample Matrix	MSGP-Zn									The second										
MSGP-17-131904	Apr 1 2017	16:03	W	1			T				1			0									
MSGP-17-132187	Apr 1 2017	16:03	W	1			+	1															***************************************
			\(\frac{1}{2}\)							1													
Special Instructions:					**																		4/12/1
Relinquished by Jone Doc Print Name Jane Doc								Received by:								Date/Tin							
Relinquished by:		-Name:		_	Date/Time:				+	Received by: Print Name:													
elinguished by:	Print	Print Name:			Date/Time:				Re	Received by:				9	Print Name:			Date/Tin	10:				

EPC-CP-QP-047	Revision: 2	A		
Effective Date: 09/06/2017	Next Review Date: 09/06/2020	Los Alamos NATIONAL LABORATORY EST. 1943		

Environment, Safety, and Health Directorate

Environmental Protection and Compliance Division – Compliance Programs

Quality Procedure

Inspecting Stormwater Runoff Samplers and Retrieving Samples for the MSGP

Document Owner/Subject Matter Expert:

Name:	Organization:	Signature:	Date:
Holly L. Wheeler	EPC-CP	Signature on File	9-5-17
	Derivative Classifier: Ur	nclassified or 🔀 DUSA ENVPRO	
Name:	Organization:	Signature:	Date:
Ellena I. Martinez	EPC-CP	Signature on File	8-22-17
			·
	Approval	Signatures:	
Subject Matter Expert:	Organization:	Signature:	Date:
Holly L. Wheeler	EPC-CP	Signature on File	9-5-17
Responsible Line Manager:	Organization:	Signature:	Date:
Terrill W. Lemke	EPC-CP Team Leader	Signature on File	9-5-17
Responsible Line Manager:	Organization:	Signature:	Date:
Anthony R Grieggs	FPC-CP Group Leader	Signature on File	9-6-17

This copy is uncontrolled.

Users are responsible for ensuring they work to the latest approved version. To document a required read, Login to <u>UTrain</u>, and go to the Advanced Search.

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 2 of 26
Revision: 2	Effective Date: 09/06/2017

REVISION HISTORY

Document Number and Revision [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
ENV-RCRA-QP-047, Rev. 0	03/11	New Document.
ENV-RCRA-QP-047, Rev. 1	02/13	Annual Review and Revision
EPC-CP-QP-047, Rev. 2	09/06//2017	Review and revision. Updated document to new template and new group name. Clarified steps, modified inspection form EPC-CP-Form-1010, and added crosswalk to electronic form in MC Express. This document replaces ENV-RCRA-QP-047 R1.

Inspecting Storm Water Runoff Samplers & Retrieving Samples for the MSGP

EPC-CP-QP-047	Page 3 of 26
Revision: 2	Effective Date: 09/06/2017

Table of Contents

Qual	ity Pr	ocedur	e	1
Revi	sion F	listory		2
Tabl	e of C	ontents) 	3
1.0	Intro	oductio	1	4
	1.1	Purpos	se	4
	1.2	Scope		4
	1.3	Applic	ability	4
2.0	Prec	autions	and Limitations	4
3.0			e Actions	
	3.1	•	ng and Coordination	
	3.2	Tools	and Equipment	6
4.0	Insp		tormwater samplers and retrieving samples	
	4.1	_	ting the Sampler	
		4.1.1	On Arrival	
		4.1.2	Water Collection Information	8
		4.1.3	Water Retrieval Information	
		4.1.4	On Departure	<u>c</u>
		4.1.5	Equipment Specific Tasks	
		4.1.6	Maintenance Information	11
		4.1.7	Bottle Information	12
	4.2	Retrie	ving Samples	12
	4.3	Compl	eting the Inspection Form	13
4.4	Rem	oving S	tormwater Samples from the field	14
5.0	Trair	ning	·	14
6.0	Reco	ords		15
7.0	Defi	nitions	and Acronyms	15
	7.1	Definit	tions	15
	7.2	Acron	yms	15
8.0	Refe	rences		15
9.0	Atta	chment	·S	16
	Atta	chment	: 1: Screenshot Examples of EPC-CP-Form-1010.02 in MC Express	17
			: 2: Crosswalk of EPC-CP-Form-1010.02 Hard Copy Format to Electronic Format	
	Atta	chment	3: Flow Chart for Sample Retrieval	26

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 4 of 26
Revision: 2	Effective Date: 09/06/2017

1.0 INTRODUCTION

Los Alamos National Security, LLC (LANS) through Environmental Protection and Compliance-Compliance Programs (EPC-CP) conducts stormwater monitoring activities required pursuant to the National Pollutant Discharge Elimination System (NPDES), Multi-Sector General Permit (MSGP) at Los Alamos National Laboratory (LANL). The MSGP requires LANL to monitor stormwater runoff from industrial sites relative to potential pollutants.

1.1 Purpose

This procedure describes the process for inspecting ISCO stormwater samplers and retrieving stormwater runoff samples from monitored outfall locations where LANS conducts stormwater monitoring activities pursuant to the NPDES, MSGP at LANL.

Inspections and sample retrieval conducted under this procedure should be documented using the Maintenance Connection Express™ (MC Express) web application on a tablet or notebook style computer. (In the event of electronic hardware or web application failure, personnel may use a printed hard copy to conduct inspection and sample retrieval.)

1.2 Scope

This procedure applies to the EPC-CP technical staff and subcontractor personnel (as applicable) conducting activities at automated stormwater sampling stations used for monitoring industrial stormwater discharge under the MSGP.

The MSGP Program Lead is the primary person with responsibility for the steps in this procedure. EPC-CP personnel will be appointed with responsibility for a subset of sampling stations.

1.3 Applicability

Stormwater runoff samples are collected at MSGP Program stations either with a refrigerated Avalanche® or ISCO 3700 automated sampler, single stage sampler or grab sample. ISCOs are designed to automatically collect water when the water surface is high enough to trigger a liquid level actuator and fill the sample bottles. Field personnel are required to inspect the sampling station while retrieving water samples during MSGP stormwater monitoring periods and at other intervals determined by the program or as directed by program personnel.

2.0 PRECAUTIONS AND LIMITATIONS

Hazards in the work described in this procedure are controlled thorough site specific Integrated Work Documents (IWDs). The hazard level of the activities in this procedure is **moderate**.

Personnel performing steps in this procedure that involve electrical equipment **MUST** be trained to LANL electrical safety standards as prescribed in the IWD before performing those steps.

Inspections may be discontinued during periods or conditions that make sites dangerous for worker safety or prevent personnel from safely accessing sites (e.g., weather-related events such as flash

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPO	C-CP-QP-047	Page 5 of 26
Rev	vision: 2	Effective Date: XX/XX/2017

floods, flooding, lightning, wildfires, hail, icy roads, deep snow, or LANL operations such as firing shots or burns).

Some terminology varies between the MC Express software and the Maintenance Connection desktop software.

- The "Reading" field in MC Express is the same field as "Reading Final" in Maintenance Connection desktop and "Meas." on a hard copy (printed) work order.
- The "Complete" option in MC Express is the same as a "Yes" answer; the "Failed" option in MC Express is the same as a "No" answer. Maintenance Connection desktop and hard copy (printed) work orders use "Yes" and "No" terminology.

3.0 PREREQUISITE ACTIONS

3.1 Planning and Coordination

- 1. Schedule work to be completed by the target date appearing on the work order(s) or as requested by the MSGP Program Lead if a form is not issued.
- 2. Inform (e.g., by e-mail) Facility contacts, as specified in the IWD, of the schedule for sampler inspection work and locations up to a week (preferred) before but no later than the day before (for minor changes) to be added to the appropriate plan of the day.

Note: For some Facility Operations Divisions (FODs) like the Utilities and Institutional Facilities FOD, MSGP stormwater monitoring activities are on a standing plan of the day. However, this must be requested each year at the beginning of the monitoring season.

- 3. The IWD Part II (2101 Form) addresses specific requirements and training for FODs.
- 4. Obtain any necessary additional paperwork before conducting this work, including IWD's, and excavation permits (as necessary).
- 5. Gather the required equipment (see section below) for the work to be done.
- 6. Using the Safari web browser on a tablet or notebook style computer, navigate to http://express.maintenanceconnection.com and select English from the available dropdown menu.
- 7. Log into the MC Express application using your login credentials.
- 8. Confirm that the work order list displayed in the "My Open Work Orders" section matches your sites (see example in Attachment 1). If work orders are not displayed, click the "Refresh" bar at the bottom of the page. The page will refresh and any work orders issued since you logged in will be loaded to the application. If the work order lists still do not match, contact the MSGP Data Management Team for clarification.
- 9. Ensure that field personnel have access to accurate time measurement at the Site. When at the site, the clock time on the ISCO sampler must be set to Mountain Standard Time at all times, with no daylight saving time adjustment.

Inspecting Storm Water Runoff	
Samplers & Retrieving Samples	
for the MSGP	

EPC-CP-QP-047	Page 6 of 26
Revision: 2	Effective Date: XX/XX/2017

3.2 Tools and Equipment

Ensure the following equipment is available in the field vehicle:

- Safety glasses with side shields
- Sturdy hiking boots or steel toed shoes with soles that grip
- Nitrile gloves
- Cell phone (only government cell phones with batteries removed are allowed in secure areas)
- Copy of this procedure
- Copy of the Integrated Work Documents (IWDs)
- Copy of the MSGP Sampling and Analysis Plan
- Site Map(s) (as needed)
- Current electronic or paper inspection form EPC-CP-Form-1010, MSGP ISCO Sampler Inspection and Sample Retrieval
- Sample Collection Log/Field Chain of Custody (see EPC-CP-QP-048)
- Government issued iPad equipment with Safari web browser and Good™ app.
- Necessary access and station keys
- Charged spare battery(s)
- Battery voltage tester
- Clean spare tubing (pump, suction, discharge types, sampler specific)
- Certified clean replacement sample bottles (glass and poly)
- Spare/replacement sampler parts (liquid level actuator, distributor arm)
- Shovel
- Wooden stakes
- Plastic wire "zip" ties
- Coolers with ice or Blue Ice®
- Paper Towels
- Marker pen (permanent, waterproof)
- Ball point pen
- Zip lock bags
- Chain of custody seals

Inspecting Storm Water Runoff	
Samplers & Retrieving Samples	
for the MSGP	

EPC-CP-QP-047	Page 7 of 26
Revision: 2	Effective Date: XX/XX/2017

0.45 micron filter (where applicable)

4.0 INSPECTING STORMWATER SAMPLERS AND RETRIEVING SAMPLES

Throughout this procedure the field inspector should document comments and notations in the "Reading" field of the associated task line. Any additional comments not documented in a "Reading" field can be entered in in the "Comments" field of the same task line. If the inspector needs more space additional comments can be entered in the "Labor Report Update" field (see Section 4.3) when the work order is updated to "Complete" status.

4.1 Inspecting the Sampler

- 1. If conditions prevent a sampler inspection, document the conditions in the "Labor Report Update" field on the work order and notify the Program Lead or designee within 24 hours. Multiple attempts can be documented on the original inspection work order. If the target date cannot be met, the inspector must contact the MSGP Program Lead no less than 24 hours before target date for guidance.
- In MC Express open the work order issued for the current location by clicking on the
 appropriate line. If needed, use the expand arrow located on the right side of the display to
 expand the work order detail information. The work order will open in the display to the
 work order Summary page.
- 3. Click on the "Tasks" bar to navigate to the work order Tasks page.
- 4. Remove the top cover from the sampler.

4.1.1 On Arrival

5. Item 1: Verify and document the sampler is ON and its condition upon arrival by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes" (see example in Attachment 1). Explain any non-functional status (remember to use the "Reading" field unless more space is needed for comments). A hard copy inspection example is provided in Attachment 2 as a crosswalk to the electronic format.

If a sampler has been inactivated (e.g., sample collection completed) prior to this inspection but continues to appear on the inspection form, change the "N/A" line to "Yes". Subsequent questions regarding this sampler may be left unanswered in this section.

CAUTION

Click the "Save" bar after all entries for a task line have been completed and before proceeding to the next question. Failure to "Save" results in lost data entries.

6. Item 2: Verify and document the ISCO programming displays the following by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 8 of 26
Revision: 2	Effective Date: XX/XX/2017

ISCO 3700 sampler display should indicate "Sampler Inhibited"

OR

Avalanche sampler display should indicate "Program Disabled"

If the display does not indicate these messages, describe the messages (e.g., "Done X samples", "sampler off", etc.). If there is no indication of flow and the sampler triggered due to a non-flow event (e.g., animal, tumbleweed, etc.), describe this. Document any messages from the ISCO display.

- 7. Item 3: Verify and document the sampler is set to the correct Mountain Standard Time +/no more than 1 minute by clicking the expand arrow located on the right side of the task line
 and changing the "Complete" or "Failed" line to "Yes". If the sampler is set incorrectly,
 reprogram for the correct Mountain Standard Time. Describe the work performed and
 correction applied (e.g., "ISCO clock was X minutes slow").
- 8. If the location has more than one sampler complete Steps 5 through 7 for each sampler.
- 9. Don nitrile gloves and safety glasses.
- 10. Remove the center section from the sampler.

4.1.2 Water Collection Information

- 11. Item 4: Document any evidence of storm water flow at the sampling location by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the evidence of flow (e.g. sediment or vegetation movement, erosion, standing water).
 - If the sampler did not trip but there is evidence of flow, document the date and time storm water discharge began from the precipitation report.
 - If the sampler tripped or collected storm water, document the date/time stamp from the sampler if available or from the precipitation report.
- 12. Item 5: Document if any storm water was collected (from either a sampler or by grab sample) by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If any water was collected, complete the Bottle Information section (Item 20). Document if the water is taken by grab sample. Follow the steps in Section 4.2 of this procedure to retrieve samples.
- 13. Item 6: For Avalanche samplers only, verify and document the current refrigerator temperature of the sampler if water was collected by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Record the temperature. If unable to review temperature, check "No" and describe the condition (e.g. dead battery, electrical short).

If no water was collected the field inspector may change the "N/A" line to "Yes".

Inspecting Storm Water Runoff	
Samplers & Retrieving Samples	
for the MSGP	

EPC-CP-QP-047	Page 9 of 26
Revision: 2	Effective Date: XX/XX/2017

14. Item 7: For Avalanche samplers equipped with an ISCO pH and Temp Module, verify and document a pH measurement was taken on the collected water by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Record the pH measurement taken at the time of Bottle 1 as "Average: Minimum:Maximum." If unable to review pH, check "No" and describe the condition (e.g. damaged meter).

If no water was collected the field inspector may change the "N/A" line to "Yes".

4.1.3 Water Retrieval Information

- 15. Item 8: Verify and document whether a sample volume was retrieved (from either a sampler or by grab sample) and taken off site by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If sample volume was retrieved, record the total volume taken off site.
- 16. Item 9: Verify and document whether a visual assessment of the water was performed by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". The MSGP program visual assessment form is not included in this procedure (see EPC-CP-QP-064). Ensure this form is submitted with the sampler inspection form. If the sample was filtered, conduct the visual assessment and document "Filtered sample."

4.1.4 On Departure

- 17. Item 10: Verify all cable and electrical connections are attached and firmly tightened (not loose) upon departure from the site by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".
 - Connections may work loose over time due to temperature changes and if there are dissimilar metals at the connection points. The loose connections can introduce voltage spikes which inherently cause current spikes that may result in blown fuses.
 - If the cables require replacement, connections require tightening, or other maintenance performed, describe the work performed (e.g., "tightened connectors on battery).
 - If maintenance cannot be completed at the time of inspection, then describe the condition (e.g. cables chewed through by animal) and follow-up work needed (e.g., replace cables).
- 18. Item 11: Verify and document power supply function. Use a voltage meter to check the voltage of the battery(s) and record the voltage(s). Change the "Complete" or "Failed" line to "Yes" to indicate if battery voltage is acceptable upon departure from the station (≥11.7 for non-floating charged batteries at ISCO 3700 samplers and ≥11.0 for floating-charged batteries at Avalanche samplers).
 - Check the voltage of the solar panel if access can be gained to the weather protected terminal covers on the back of the panel.

Inspecting Storm Water Runoff	
Samplers & Retrieving Samples	
for the MSGP	

EPC-CP-QP-047	Page 10 of 26
Revision: 2	Effective Date: XX/XX/2017

4.1.5 Equipment Specific Tasks

19. Item 12: Verify and document the sampler passes the diagnostic test by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Directions for running the diagnostics test is provided in ENV-CP-QP-045.

If a sampler has been inactivated (e.g., sample collection completed) prior to this inspection but continues to appear on the inspection form, change the "N/A" line to "Yes" on this task line. Subsequent questions regarding this sampler may be left unanswered in this section.

Warning

The internal pump tubing must be replaced if the pump tubing life has reached or exceeded the preset pump counts. The internal pump tubing life is set 500,000 pump counts for the 3700 and 1,000,000 for the Avalanche.

Only reset the pump counts after replacing the internal tubing.

If maintenance is necessary and can be performed at the time of inspection, describe the work performed. If maintenance cannot be completed at the time of inspection, then describe the condition and follow up with a description of work needed.

If a sampler has been inactivated (e.g., sample collection completed) prior to this inspection but continues to appear on the inspection form, change the "N/A" line to "Yes" on this task line. Subsequent questions regarding this sampler may be left unanswered in this section.

20. Item 13: Verify and document the sample tubing is free or clear of debris by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".

Check the physical condition of the sampler including the actuator and intake line for correct location and height in the channel. The actuator, intake line and strainer (if used) should be placed on the cutting side of the channel to help minimize the possibility of sediment burying the intake line/strainer. Adjust as necessary to capture flow within the channel. The actuator, intake line and strainer must be clear of debris (sediment, pine needles, etc.).

If maintenance (e.g., clearing the tube, reposition tubing intake) is necessary and can be performed at the time of inspection, perform the work and describe. If maintenance cannot be completed at the time of inspection (e.g., can't clear intake tubing and spare intake tubing not on hand to replace) then describe the condition and follow up with description of work needed.

21. Item 14: Verify and document the sample tubing has passed a suction test by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Check the condition of sample tubing and vent tubing.

If maintenance (e.g., replace internal pump tubing) is necessary and can be performed at the time of inspection, perform the work and describe. If maintenance (e.g., replace sampler

Inspecting Storm Water Runoff	
Samplers & Retrieving Samples	
for the MSGP	

EPC-CP-QP-047	Page 11 of 26
Revision: 2	Effective Date: XX/XX/2017

pump) cannot be completed at the time of inspection then describe the condition and follow up with description of work needed.

- 22. Item 15: Verify and document the sampler is ON prior to departing the site by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".
- 23. Item 16: Verify and document the liquid level actuator has been set to "Latch" prior to departing the site by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If the sampler tripped and requires reset of the sampling program, reset the actuator by toggling the switch to "Reset" and then back to "Latch".
- 24. Item 17: Verify and document the ISCO programming displays the following by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".

ISCO 3700 sampler display should indicate "Sampler Inhibited"

OR

Avalanche sampler display should indicate "Program Disabled"

If an error occurs, reconfigure the sampler per EPC-CP-QP-045.

25. If the location has more than one sampler complete Steps 19 through 24 for each sampler.

4.1.6 Maintenance Information

26. Item 18: Verify and document any maintenance completed while on site that is not documented elsewhere on work order by changing the "Complete" or "Failed" line to "Yes". Describe the work performed.

Maintenance items may include (but are not limited to) site clearing, installing new or additional equipment, removing equipment, animal/pest mitigation, problems with equipment location, etc.

If a battery was replaced record the voltage of the new battery and the battery identification number. If the battery does not have an identification number, contact the MSGP Program Manager to have one assigned. Once assigned, the number must be painted or written in a permanent manner on the battery.

27. Item 19: Verify and document any maintenance needed that could not be completed while on site that is not documented elsewhere on work order by changing the "Complete" or "Failed" line to "Yes". Describe any work needed. Refer to EPC-CP-QP-045 for sampler operation and maintenance.

Inspecting Storm Water Runoff		
Samplers & Retrieving Samples		
for the MSGP		

EPC-CP-QP-047	Page 12 of 26
Revision: 2	Effective Date: XX/XX/2017

4.1.7 Bottle Information

- 28. Item 20: Document water collected by clicking the expand arrow located on the right side of each bottle's task line and change the "Complete" or "Failed" line to 'Yes'. Record the following information for each bottle by position number in the carousel.
 - Date (MM/DD/YY or MM-DD-YY) and time the ISCO collected water.
 - Volume of water in the bottle
 - Type of bottle (e.g. G for glass, P for poly)
 - Specific ISCO displayed message, if present

If the sampler(s) did not trigger, change the "N/A" line to 'Yes' for Bottle #1 of each sampler and leave the other Bottle task lines unanswered.

If a sampler has been inactivated (e.g., sample collection completed) prior to this inspection but continues to appear on the inspection form, change the "N/A" line to "Yes" on this task line. Subsequent questions regarding this sampler may be left unanswered in this section.

- 29. If the location has more than one sampler complete Step 28 for each sampler.
- 30. Replace and secure the sampler top cover and secure the sampler shelter (if sampler is in a shelter).

4.2 Retrieving Samples

- 1. Don nitrile gloves and safety glasses.
- 2. Add up the volume of water collected (see flow chart in Attachment 3) and check that the total volume of water in glass and poly matches the required volume for the specific location identified in the MSGP Sampling and Analysis Plan. The volume of water required to complete analytical may vary by monitored location.
 - If sample volume is sufficient to fulfill all analytical requirements, continue with Step 3.
 - If sample volume is sufficient to fulfill part of the analytical requirements, consult the
 prioritization order on the MSGP Sampling and Analysis Plan to determine which
 analytical to fulfill OR contact the MSGP Data Manager, continue with Step 3 but retrieve
 only the volume needed.
 - If the collected sample will NOT fulfill the minimum required volume for any analytical:
 - Record total volume retrieved as "0" in Item 8
 - Complete a Visual Assessment (see EPC-CP-QP-064)
 - Pour out all water on the ground
 - Skip to Step 10 below

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 13 of 26
Revision: 2	Effective Date: XX/XX/2017

CAUTION

ISCO Avalanche samplers are programmed to cool samples to 4°C. If water is collected and the refrigerator temperature reads higher than 6°C, **do not** retrieve samples that require ICE preservation. Refer to the MSGP Sampling and Analysis Plan for preservation requirements.

- 3. Remove filled and partially-filled bottles from the carousel.
- 4. For samples retrieved, immediately place lids onto the sample bottles and securely seal. Place custody seal tape on each bottle.
- 5. Write the date and time collected, Sampler Location number, and the corresponding carousel number on each retrieved sample bottle. Retrieve the sample collection date and time from the ISCO sampler.
- 6. Record total volume retrieved in Item 8.
- 7. Conduct a Visual Assessment (see EPC-CP-QP-064).
- 8. Place retrieved sample bottles in a cooler with blue ice (or equivalent).
- 9. Return any excess water or collected volume that exceeded the amount required to the ground at the location collected.
- 10. Install new certified clean sample bottles in the carousel to replace those bottles that collected stormwater. The number and type of bottles may vary. Ensure bottles match the configuration specified in the MSGP Sampling and Analysis Plan.
- 11. The 0.45 micron filter may also need to be replaced. Consult the most current revision of the Sampling and Analysis Plan for specifics. If the sampler is turned off for the quarter but new certified clean sample bottles and/or the filter have not been replaced, note this as follow-up maintenance required (see Item 19).
- 12. Replace and secure the center section of the sampler.
- 13. Return to steps in Section 4.1.

4.3 Completing the Inspection Form

- 1. When all task lines have been completed, make sure you have clicked the "Save" bar at the bottom of the page.
- 2. Click the "Back" arrow button in the upper left hand corner to exit the work order Tasks page and return to the Work Order Summary page.
- 3. Click the checkered flag in the upper right corner of the work order Summary page.

CAUTION

MC Express automatically changes the work order status to "Closed" and auto-populates the date and time fields.

Inspecting Storm Water Runoff Samplers & Retrieving Samples	EPC-CP-QP-047	Page 14 of 26
for the MSGP	Revision: 2	Effective Date: XX/XX/2017

- 4. Item 21: Click on the expand arrow located on the right side of the "New Status" field and select "Completed" from the available dropdown menu. Ensure the date and time autopopulated are the date and time the inspection was completed.
 - If these fields need to be updated, click the "Date" field to modify it. Make necessary adjustments using the available timestamp application and click "Set" to apply changes.
- 6. Item 22: The inspector must type in his/her name in the "Labor Report Update" field.
 - Any additional notes, observations, or site conditions not documented in a task line "Reading" or "Comments" field can also be documented in the "Labor Report Update" field.
- 7. Scroll down the page to the "Signature" bar and click the expand arrow on the left side of the bar to open the "Signature" field.
- 8. Item 23: Capture an electronic signature by drawing with a finger on the tablet screen. The Lead Inspector is certifying that the information submitted is "true, accurate, and complete" by electronically signing the work order.
 - **Note:** If using MC Express on a desktop screen (not a tablet), the mouse must be used to sign electronically.
- 9. Click on the "Save" bar at the bottom of the page to close the "Signature" field.
- 10. Click on the "Back" button located in the upper left hand corner to return to the "My Open Work Orders" page.
- 11. Once you have completed an inspection, click on the Menu button again, and then click the "Logout" bar. Close the browser. All work will automatically uploaded from the MC Express application to the MC database.

Always log out of MC Express when you have finished work OR if work is interupted.

4.4 REMOVING STORMWATER SAMPLES FROM THE FIELD

- 1. If samples were collected, deliver the samples and corresponding Sample Collection Log/Field Chain of Custody form to the EPC-CP Stormwater Program Laboratory at TA-59-1.
- 2. Sign the Sample Collection Log/Field Chain of Custody and place it with the sample(s) in the refrigerator. Ensure custody seal tape is intact on each sample bottle. Lock the refrigerator to prevent tampering. Refer to EPC-CP-QP-048, *Processing MSGP Stormwater Samples* for instruction on processing samples and submitting samples for shipping to an analytical laboratory.

5.0 TRAINING

The following personnel require training before implementing this procedure:

• EPC-CP technical staff and subcontract or other personnel who inspect automated stormwater samplers and retrieve stormwater samples for the MSGP.

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 15 of 26
Revision: 2	Effective Date: XX/XX/2017

For EPC-CP staff the training method for this procedure is "self-study" (reading). Other participating groups may require training documentation pursuant to local procedures.

Personnel performing this procedure will be familiar with the most current versions of the following procedures and operation manuals:

- EPC-CP MSGP Sampling and Analysis Plan for the current monitoring year
- Manual for Teledyne ISCO Sampler Model 3700
- Manual for Teledyne ISCO Avalanche® sampler
- Manual for Teledyne ISCO 701 pH/Temperature module (if equipped at station)

Personnel performing steps in this procedure that involve electrical equipment **MUST** be trained to LANL electrical safety standards as prescribed in the IWD before performing those steps.

6.0 RECORDS

Records generated by this document will be submitted to the EPC-CP Records Management designated point of contact or document manager in accordance with P1020-1, *Laboratory Records Management* and with ADESH-AP-006, *Records Management Plan*.

Completed ISCO Sampler Inspection and Sample Retrieval form(s)

7.0 DEFINITIONS AND ACRONYMS

7.1 Definitions

See LANL Definition of Terms.

7.2 Acronyms

See LANL Acronym Master List.

EPC-CP	Environmental Protection and Compliance-Compliance Programs
IWD	Integrated Work Document
LANL	Los Alamos National Laboratory
LANS	Los Alamos National Security, LLC
MC Express	Maintenance Connection MC Express web application
MSGP	Multi-Sector General Permit
NPDES	National Pollutant Discharge Elimination System

8.0 REFERENCES

None.

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 16 of 26
Revision: 2	Effective Date: XX/XX/2017

9.0 ATTACHMENTS

Attachment 1: Screenshot Examples of EPC-CP-Form-1010.02 in MC Express


Attachment 2: Crosswalk of EPC-CP-Form-1010.02 Hard Copy Format to Electronic Format Example

Attachment 3: Flow Chart for Sample Retrieval

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 17 of 26
Revision: 2	Effective Date: 09/06/2017


Page 1 of 7



Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 18 of 26
Revision: 2	Effective Date: 09/06/2017

Page 2 of 7



Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 19 of 26
Revision: 2	Effective Date: 09/06/2017

Page 3 of 7






Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 20 of 26
Revision: 2	Effective Date: 09/06/2017


Page 4 of 7



Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 21 of 26				
Revision: 2	Effective Date: 09/06/2017				

Page 5 of 7




Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 22 of 26				
Revision: 2	Effective Date: 09/06/2017				

Attachment 1: Screenshot Examples of EPC-CP-Form-1010.02 in MC Express (cont.)

Page 6 of 7




Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 23 of 26				
Revision: 2	Effective Date: XX/XX/2017				

Attachment 1: Screenshot Examples of EPC-CP-Form-1010.02 in MC Express (cont.)

Page 7 of 7



Inspecting Storm Water R	lunoff
Samplers & Retrieving Sa	mples
for the MSGP	-

EPC-CP-QP-047	Page 24 of 26
Revision: 2	Effective Date: 09/06/2017

Attachment 2: Crosswalk of EPC-CP-Form-1010.02 Hard Copy Format to Electronic Format Page 1 of 2

l ne Alamne	Mational	lah -	ADESH

Work Order MSGP-59941

	\#=:4=		2-4-11-			Printed	8/10/2017 -			ing Station: licate Copy
Γ'	Vlainten	ance L	Jetalis							
	Request	ed By:	Admin, Jane on	Target:	12/31/2017	MSG	P Program			
	_		8/10/2017 11:23:00 AM	Priority/Type:	/ Inspection	₼ RG12	21.9			
	Procedu	ire:	MSGP ISCO Sampler Inspection and Sample Retrieval (EPC-CP-	Department:	Utilities and Infrastructure		38 Carpent ored Outfal P07302		•	
	Last PM		Form-1010.2 2) 7/20/2017							
	Project:		ISCO Inspections wk			Contact:	Admin, Ja	ne		
	Project.		8/7/17 (P-MSGP-5212)			Phone:	123-4567			
	Reason:	Hard (Copy ISCO Sampler Inspe	ction and Sampl	e Retrieval					
Ļ.	Tasks –									
									****	V
	#	Descri	ption				Meas.	No	N/A	Yes
┸	ON ARE	RIVAL								
1	20	ISCO 3	3700 Sampler [210C0143]	7] Is sampler ON	and functioning properly up	on arrival?				
2				7] Does the sam	oler display "Sampler Inhibit	ed'? If No,		_	_	_
4	30		specific message(s).	99 (C E'	- I-II I - I - (MOT) 0 II N -					
3	40	adjustr		[] Is sampler time	e delta < 1 min (MST)? If No	, record				
T	40			015221 Is sampl	er ON and functioning prope	rly upon		-1.0	1.00	
	50	arrival?		o rozzi to campi	or orrana ranodoming prope	пу ароп				
	00				Avalanche display "Progra	m				
	60		ed"? If No, record specific		artima dalta < 1 min (MCT)) If NIo		14	100	
	70		adjustment	101522] IS Sampl	er time delta < 1 min (MST)	II NO,				
	Water C	Collection	on information							
	water C			(but no water co	llected), describe and record	date/time				
4	90	of disc		(but no water oo	ilicotcu), describe una recort	dutertime				
5	100	Is any	water collected? If YES, co	omplete Bottle In	formation section.					
I					was collected, record curren	t				
6	110		ator temperature (C).							
					r was collected, record the p	Н				
7	120	MAXIN		ne sample date/ti	me: AVERAGE: MINIMUM:			H		
Т										
0	1		Information					_	_	_
8	140		ample volume RETRIEVED							-1
9	150		Visual Assessment perfori EPC-CP-TP-064).	ned? If Yes, com	plete the MSGP Visual Ass	essment		П.		
Ť			,					Last		
40	ON DEF									
10	170		ectrical connections secure							
11	180	Record	I voltage of battery(ies) por	wering sampler.	Voltage(s) >/=11.7V?					
\perp	Equipm	ent spe	ecific tasks							
12	200	ISCO 3	3700 Sampler [210C0143]	7] Does the sam	oler pass the ISCO diagnost	ics test?				
13	210	ISCO 3	3700 Sampler [210C0143]	7] Is intake tubing	g free/clear of debris?					
14	220	ISCO 3	3700 Sampler [210C0143]	7] Does sample t	ubing pass suction test?					
15	230	ISCO 3	3700 Sampler [210C0143]	7] Is sampler on	upon departure?					
16	240	ISCO 3	3700 Sampler [210C0143]	7] Has the actuat	or switch been reset to "Late	ch"?				
I				7] Does ISCO dis	splay "Sampler Inhibited" on					
17	250	depart	ure?							

Inspecting Storm Water Runoff Samplers & Retrieving Samples for the MSGP

EPC-CP-QP-047		Page 25 of 26	
	Revision: 2	Effective Date: 09/06/2017	

Attachment 2: Crosswalk of EPC-CP-Form-1010.02 Hard Copy Format to Electronic Format (cont.)

Page 2 of 2


	260	ISCO Avalanche Sampler [210J01522] Does the sampler pass the ISCO diagnostics test?			
	270	ISCO Avalanche Sampler [210J01522] Is intake tubing free/clear of debris?			
	280	ISCO Avalanche Sampler [210J01522] Does sample tubing pass suction test?			
	290	ISCO Avalanche Sampler [210J01522] Is sampler on upon departure?			
	300	ISCO Avalanche Sampler [210001022] Is sampler on upon departure? ISCO Avalanche Sampler [210J01522] Has the actuator switch been reset to "Latch"?	-		-
	300			-11	
	310	ISCO Avalanche Sampler [210J01522] Does Avalanche display "Program Disabled" on departure?			
	Mainten	ance information			
18	330	Is any maintenance not described above completed during inspection? If Yes, describe.		ET.	П
19	340	Is any follow-on maintenance not described above required? If Yes, describe.			
Ι		nformation: IF bottle collected record bottle type (P or G), collection date & time, volume, and/o	or any Is	sco	
20	360	ISCO 3700 Sampler [210C01437] Bottle #1?		100	
Т	370	ISCO 3700 Sampler [210C01437] Bottle #2?			
	380	ISCO 3700 Sampler [210C01437] Bottle #3?			
	390	ISCO 3700 Sampler [210C01437] Bottle #4?			
	400	ISCO 3700 Sampler [210C01437] Bottle #5?			
	410	ISCO 3700 Sampler [210C01437] Bottle #6?			
	420	ISCO 3700 Sampler [210C01437] Bottle #7?			
	430	ISCO 3700 Sampler [210C01437] Bottle #8?			-
	440	ISCO 3700 Sampler [210C01437] Bottle #9?			
	450	ISCO 3700 Sampler [210C01437] Bottle #3?	무		
	460				
		ISCO 3700 Sampler [210C01437] Bottle #11?		ᄪ	
	470	ISCO 3700 Sampler [210C01437] Bottle #12?			
	480	ISCO Avalanche Sampler [210J01522] Bottle #1?			
	490	ISCO Avalanche Sampler [210J01522] Bottle #2?			
	500	ISCO Avalanche Sampler [210J01522] Bottle #3?		-21	
	510	ISCO Avalanche Sampler [210J01522] Bottle #4?			
	Report:	ted: 5/30/2017 4:44:00 PM Jane Admin 5/30/2017 Signature / Name The information as recorded is true, accurate and complete.		Date	
W	D ID:	Pageof			
Day	tor	Time:			
Lea	ad Signati	ıre:			

Inspecting Storm Water Runoff
Samplers & Retrieving Samples
for the MSGP

EPC-CP-QP-047	Page 26 of 26
Revision: 2	Effective Date: 09/06/2017

Attachment 3: Flow Chart for Sample Retrieval

Page 1 of 1



ENV-CP-QAPP-MSGP, R5 Effective Date: 11/04/2013 Next Review Date: 11/04/2015



Environment, Safety, Health Directorate

Environmental Protection Division – Compliance Programs Group

Quality Assurance Project Plan

Stormwater Multi-Sector General Permit for Industrial Activities Program

Reviewers:				
Name:	Organization:	Signature:	Date:	
Melanie Lamb	ADESH-OIO, QA Specialist	Signature on File		
Deriv	ative Classifier: 🔲 Un	classified 🛭 DUSA <u>ENVPRO</u>		
Name:	Organization:	Signature:	Date:	
Ellena Martinez	ADESH-OIO	Signature on File		
Approval Signatures:				
Subject Matter Expert:	Organization:	Signature:	Date:	
Holly Wheeler	ENV-CP	Signature on File		
Responsible Line Manager:	Organization:	Signature:	Date:	
Mike Saladen	ENV-CP, Team Lead	Signature on File		
Responsible Line Manager:	Organization:	Signature:	Date:	
Anthony Grieggs	ENV-CP, Group Leader	Signature on File		

CONTROLLED DOCUMENT

This copy is uncontrolled. The controlled copy can be found on the ENV Division Web page.

Users are responsible for ensuring they work to the latest approved version.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 2 of 40
	Effective Date: 11/04/2013	

History of Revisions

Document Number [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	06/03	New Document
1	12/05	Annual review and revision
2	07/07	Annual review, incorporated organizational restructure changes.
3	07/09	Biennial Review and Revision
4	07/09	Biennial Review and Revision
5	10/13	Biennial Review and Revision. New format implemented.

Effective Date: 11/04/2013

Table of Contents

1.0	QUA:	LITY PROGRAM	5
	1.1	Quality Program Purpose	5
	1.2	Organization	5
	1.3	Responsibilities	6
2.0	PERS	SONNEL DEVELOPMENT	6
	2.1	MSGP Curricula	6
	2.2	MSGP Inspector Qualifications	8
	2.3	MSGP SWPPP Preparer Qualifications	8
	5.4	MSGP Visual Assessor Qualifications	
	5.5	Training Responsibilities	9
3.0	QUA	LITY IMPROVEMENT	10
	3.1	Corrective Actions within ENV-RCRA	10
	3.3	Quality Improvement Responsibilities	10
4.0	DOC	UMENT CONTROL/RECORDS MANAGEMENT	10
	4.1	Program Records	
	4.2	Program Records Responsibilities	11
	4.3	Electronic Media	12
	4.4	Databases	
	4.4	Implementation Responsibilities	13
5.0	PLA	NNING AND PERFORMING WORK	13
	5.1	Work Processes	14
	5.3	Work Performance	14
	5.4	StormWater Pollution Prevention Plan	
	5.5	Inspections	
	5.6	StormWater Monitoring	
	5.7	Discharge Monitoring Reports	
	5.8	Adverse Weather Conditions and Climates with Irregular Stormwater Runoff	
	5.9	Reporting and Recordkeeping	
	5.10	Best Management Practices	
	5.11	Information Management	
	5.12	Responding to Water Quality Exceedances	
	5.13	Instrumentation and Equipment	
6.0		GN	
7.0	PRO	CUREMENT	25
8.0	INSP	ECTION AND ACCEPTANCE TESTING	26
9.0	MAN	AGEMENT ASSESSMENT	26
10.0	INDE	EPENDENT ASSESSMENT	27
11.0	ATT	ACHMENTS	27

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 4 of 40
	Effective Date: 11/04/2013	

Attachment 1- MSGP Program Organization2	8
Attachment 2 – Annual Reporting Form2	9
Attachment 3 – Routine Inspection Form	5
Attachment 4 MSGP Facilities and Storm Water Monitored Outfalls Associated with Industrial	
Activity 2011, Permit NMR05GB213	7
Attachment 5 – Pollutants Under Impaired Waters Monitoring3	8
Attachment 6 – Analytes by Industrial Sector	9
Attachment 7 – References and Guidance Documents4	0

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 5 of 40
	Effective Date: 11/04/2013	

1.0 QUALITY PROGRAM

LANL will comply with the monitoring requirements as specified by the 2008 National Pollutant Discharge Elimination System (NPDES) Stormwater Multi-Sector General Permit for Industrial Activities. Compliance will be demonstrated through the successful implementation of this project plan and applicable procedures.

Los Alamos National Laboratory (the Laboratory) has established a comprehensive stormwater program for its industrial activities. Historically, the Laboratory operated under the NPDES Baseline General Permit and then under the NPDES 1995, 2000, and 2008 Multi-Sector General Permits. The Laboratory submitted its NOI for 2008 coverage in December 2008.

The 2008 MSGP was issued on September 22, 2008 and became effective on September 29, 2008.

The purpose of this project plan is to ensure compliance with the following:

- 2008 NPDES Multi-Sector General Permit (MSGP) and the Clean Water Act (CWA)
- DOE Order 450.1, *Environmental Protection Program*, and DOE Order 5400.5, *Radiation Protection of the Public and Environment*, which establish environmental protection program policies, requirements, and responsibilities

The Environmental Protection, Environmental Compliance Programs (ENV-CP) Water Quality Team has been tasked with overseeing institutional stormwater compliance related activities at the Laboratory.

1.1 QUALITY PROGRAM PURPOSE

This Quality Assurance Project Plan (QAPP) describes the policies and requirements that ensure MSGP activities are conducted in a consistent, agreed-upon manner.

This QA Project Plan describes the policies and requirements that ensure the MSGP processes are conducted in a consistent, agreed-upon manner. Drivers for the quality plan include:

- o DOE Order 414.1C, Quality Assurance
- o SD330, LANL Quality Assurance Program

This QA Project Plan (QAPP), including implementing procedures, is a sub-tier document to the SD330, *LANL Quality Assurance Program*. The following documents provide requirements to ensure that the MSGP Program is operated in accordance with established plans and procedures:

- SD330, LANL Quality Assurance Program
- QA Project Plan for the MSGP (this document)
- Implementing procedures

1.2 ORGANIZATION

ENV-CP is responsible for compliance oversight of the Laboratory's MSGP coverage. The Group is organized by teams under the line management direction of the Group Leader. Teams are crossfunctional and focus on specific Laboratory water quality responsibilities, deliverables, or

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 6 of 40
	Effective Date: 11/04/2013	

products. Teams are guided by Team Leaders who have the responsibility to assure the program is completed and properly implemented.

The Team Leader coordinates the project and reports to the ENV-CP Group Leader. The Project Lead implements program oversight, coordinates contractor efforts (if there are any), and reports to the Team Leader. A QA Specialist is assigned to work for the Team Leader to provide quality assurance assistance, advice, and review. In addition, representatives from other groups may participate and contribute to this team as subject matter experts for project activities. The project organization is shown in Attachment 1.

Applicable regulatory drivers include the following:

- Clean Water Act (CWA)
- 2008 NPDES Multi-Sector General Permit (MSGP)
- DOE Order 450.1, Environmental Protection Program
- DOE Order 5400.5, Radiation Protection of Public and Environment
- P401, Procedure to Identify, Communicate, and Implement Environmental Requirements

1.3 RESPONSIBILITIES

The following table lists specific responsibilities:

Who	What
Group Leader	Assure that qualified staff complies with regulatory requirements associated with the MSGP.
Project Lead	Ensure that MSGP-related activities are performed in accordance with the requirements specified in this plan.
ENV-CP Staff	Perform MSGP-related activities as assigned by the Team Leader or Project Leader

2.0 PERSONNEL DEVELOPMENT

Qualified team members will be hired and trained as prescribed in ENV-DO-QP-115, *Personnel Training*. Minimum training requirements for ENV personnel are described in the ENV Division Qualification Standards. The LANL Human Resources Division maintains documentation of education qualification. Required MSGP qualifications and training plans are listed below.

2.1 MSGP CURRICULA

The MSGP Program requires personnel with the following training requirements:

MSGP Inspectors

Curricula 10697 ENV-RCRA MSGP Inspector
Item 43337 ENV-CP-QAPP-MSGP
Item 54892 ENV-RCRA-QP-022 MSGP Stormwater Corrective Actions

	Stormwater MSG	P for Industrial	Activities	Program
--	----------------	------------------	------------	---------

No. ENV-CP-QAPP-MSGP, R5

Page 7 of 40

Effective Date: 11/04/2013

Item 42415 ENV-DO-QP-101 Environmental Reporting Requirements for Releases or Events

Item 42547 ENV-DO-QP-111 Reporting Environmental Releases to Pueblo Governments

Item 40708 ENV-DO-QP-108 Preparation of External Correspondence for Review and Approval

Item 43172 ENV-DO-QP-112 Coordinating Regulatory Inspections

Item 42891 ENV-DO-QP-113 Tracking Issues and Actions

Item 43805 ENV-DO-QP-114 Logbook Use and Control

Item 45777 ENV-DO-QP-100 General Field Safety

Curricula 131 Field Worker Training Requirements

Item 43562 or 3583 or 16585 CPR/AED: LANL Workplace

Item 3574 or 13264 First Aid

MSGP SWPPP Preparers

Curricula 7814 ENV-RCRA MSGP SWPPP Preparer

Item 43337 ENV-CP-QAPP-MSGP

Item 56593 ENV-RCRA-QP-044 Preparing Storm Water Discharge Monitoring Reports (MDMRs)

for the NPDES Multi-Sector General Permit

Item 40708 ENV-DO-QP-108 External Correspondence

Item 43172 ENV-DO-QP-112 Coordinating Regulatory Inspections

Item 42891 ENV-DO-QP-113 Tracking Issues and Actions

Item 43805 ENV-DO-QP-114 Logbook Use and Control

Item 45777 ENV-DO-QP-100 General Field Safety

Curricula 51 ENV-RCRA Design Engineer

Item 44269, COE Review of LANL Produced Design Documents, AP-341-620

Item 44266, COE System Design Descriptions, AP-341-61

Item 44263, COE Engineering Drawings and Sketches, AP-341-608

Item 44261, COE Calculation, AP-341-605

Item 44258, COE Requirements and Criteria Document, AP-341-602

Item 44257, COE Functions & Requirements Document, AP-341-601

Item 43658, CORE Engineering Overview

Item 55428, COE Management Level Determination, AP-341-502

Item 54168, P342 Engineering Standards

Item 47029, COE LANL Review of Design by External Agencies, AP-341-622

Item 43666, Engineering Design Management

Item 43663, Engineering Technical Baseline

Item 44225, COE Evaluation of Vendor Information, AP-341-701

MSGP Visual Assessors

Curricula 10698 ENV-RCRA MSGP Visual Assessor

Item 43337 ENV-RCRA-QAPP-MSGP

Item 50493 ENV-RCRA-QP-064 MSGP Storm Water Visual Assessments

Item 42415 ENV-DO-QP-101 Environmental Reporting Requirements for Releases or Events

Item 42547 ENV-DO-QP-111 Reporting Environmental Releases to Pueblo Governments.

Item 40708 ENV-DO-QP-108 External Correspondence

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 8 of 40
	Effective Date: 11/04/2013	

Item 43172 ENV-DO-QP-112 Coordinating Regulatory Inspections
Item 42891 ENV-DO-QP-113 Tracking Issues and Actions
Item 43805 ENV-DO-QP-114 Logbook Use and Control
Item 45777 ENV-DO-QP-100 General Field Safety

Curricula 131 Field Worker Training Requirements Item 43562 or 3583 or 16585 CPR/AED: LANL Workplace Item 3574 or 13264 First Aid

2.2 MSGP INSPECTOR QUALIFICATIONS

Inspections:

- Post high school education or experience in engineering or environmental science or a related field; or industrial site field experience involving stormwater pollution prevention.
- 2 years experience of completing MSGP inspections or 1 year MSGP inspection experience with the Certified Inspector of Sediment and Erosion Control (CISEC) certification.
- 6 months knowledge of LANL facility operations.
- Demonstrated ability, as determined by the Multi-Sector General Permit Project Lead and/or Water Quality Team Leader, to successfully and effectively evaluate and identify the following at industrial sites:
 - o Conditions and activities that could impact stormwater quality at the facility.
 - o Inadequate or ineffective BMPs.
 - o Required modification or maintenance of existing BMPs.
 - o Locations requiring new or additional BMPs.
 - o Potential pollutant sources associated with the facility.
 - o Appropriate and correct site stabilization measures.
- Demonstrated ability, as determined by the Multi-Sector General Permit Project Lead and/or Water Quality Team Leader, to evaluate the compliance status of each industrial facility and document identified issues during an inspection.
- Demonstrated ability, as determined by the Multi-Sector General Permit Project Lead and/or Water Quality Team Leader, to properly and effectively complete inspection reports, including the ability to perform the following:
 - o Prepare reports in a clear, concise manner, identifying site conditions and issues.
 - o Write legibly and describe conditions clearly and accurately.
 - o Use proper spelling and grammar.
 - o Complete the MSGP Routine Inspection Report forms accurately.
 - o Accurately enter findings into the Corrective Actions Report database.
- Conduct inspections in a professional manner.
- Be a member of, or contractor supporting, ENV-RCRA or ENV Division.

2.3 MSGP SWPPP PREPARER QUALIFICATIONS

SWPPP Preparation:

One of the 2 criteria below must be satisfied:

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 9 of 40
	Effective Date: 11/04/2013	

- BS degree or experience in engineering, environmental science, or related field, with a
 background involving stormwater pollution prevention and regulatory compliance relating to
 MSGP sites and a 1 year minimum of LANL facility operations knowledge and 1 year
 experience of completing MSGP inspections; or
- Certified Professional in Erosion and Sediment Control (CPESC) or Professional Engineer (PE) with a demonstrated background in stormwater management, sediment and erosion control, and regulatory compliance.

In addition to:

- Demonstrated ability, as determined by the Multi-Sector General Permit Project Lead and/or Water Quality Team Leader, to:
 - Prepare SWPPPs per LANL format and in compliance with NPDES MSGP requirements.
 - o Identify and specify appropriate BMPs and stabilization measures.
 - o Identify potential pollutant sources associated with the facility.
 - o Perform necessary calculations to meet regulatory requirements.
 - o Prepare a site map.
 - o Be a member of, or contractor supporting, ENV-CP or ENV Division.

5.4 MSGP VISUAL ASSESSOR QUALIFICATIONS

Quarterly Visual Assessments:

- Education or experience in engineering, environmental science, or a related field; or industrial site field experience involving stormwater pollution prevention; and
- Completed ENV-RCRA training on how to collect and evaluate visual assessment; and
- Demonstrated ability, as determined by the Multi-Sector General Permit Program Lead and/or Water Quality Team Leader, to:
 - o Collect quarterly visual samples at the designated outfall.
 - o Complete the applicable portions of the MSGP Quarterly Visual Assessment Form.
 - Have working knowledge of the regulatory requirements in Section 4.2 of the MSGP.

5.5 TRAINING RESPONSIBILITIES

All personnel performing MSGP project-related work are required to obtain appropriate training prior to performing work governed by a procedure. Training for all project personnel will be performed and documented in accordance with ENV-DO-QP-115, *Personnel Training*.

The following table lists specific responsibilities regarding training requirements.

Who	What
Group Leader	Ensure project personnel meet all Laboratory training requirements.
Program Lead	Establish and document job descriptions for each position within the MSGP Project.
	Ensure all project personnel have the appropriate level of education,

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5 Page 10 of 40	
	Effective Date: 11/04/2013	

	experience, and training.
--	---------------------------

3.0 QUALITY IMPROVEMENT

The MSGP Project subscribes to the principles of problem prevention and continuous improvement. The Project Lead is committed to evaluating improvement opportunities identified by trending and reporting.

The Project Lead provides verbal and written updates, as needed, to the Team Leader and Group Leader to keep group management apprised of the focus of the MSGP Project activities and to address any shortcomings that may be identified.

3.1 CORRECTIVE ACTIONS WITHIN ENV-RCRA

Corrective actions for all ENV-RCRA programs and projects are initiated, tracked, corrected, and documented according to P330-6 *Nonconformance Reporting*, P322-4 *Laboratory Performance Feedback and Improvement Process*, *SD330*, *Los Alamos National Laboratory Quality Assurance Program*, and Division/Group procedures.

3.3 QUALITY IMPROVEMENT RESPONSIBILITIES

The following table lists specific responsibilities for quality improvement:

Who	What
Project Lead	Monitor program performance and ensure issues are corrected in a timely manner.
ENV-CP Staff	Identify opportunities for process improvement, health and safety enhancement, environmental protection, or other improvements of the program's operations.
	Discuss the identified opportunities with the Project Lead.
	Ensure issues are reported and corrected in a timely manner.

4.0 DOCUMENT CONTROL/RECORDS MANAGEMENT

The program lead, at least one reviewer, and the Group Leader will approve all revisions to this plan. Revisions to the plan will be provided to the QA Specialist. This plan will be reviewed and revised (if necessary) biennially.

This document will be controlled under the organization's document control system (ENV-DO-QP-106, *Document Control*). Controlled copies of ENV documents are located on the Internet: http://int.lanl.gov/orgs/env/rcra/qa.shtml, all other copies are uncontrolled.

Procedures will be developed as necessary and in accordance with ENV-DO-QP-105, *Preparation, Review, and Approval of Procedures*.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 11 of 40
	Effective Date: 11/04/2013	

Phone calls, email, or fax communications will be documented and controlled if the content provides direction or results in decisions.

4.1 PROGRAM RECORDS

The number, type, and detail of all records to be kept will provide sufficient information to allow an individual with equivalent education and training to verify or reconstruct the results. Implementing procedures specify the records, forms, logbook entries, or other information to be kept as documentation of the performance of the procedure.

Records to be kept in the ENV-CP records system include the following:

- Copy of the Multi-Sector General Permit
- Annual Site Compliance Evaluation reports
- Corrective Action Reports
- Reports and certifications required by MSGP
- Records of all data used to complete MSGP Notice of Intent
- Discharge Monitoring Reports

Records to be kept by the Deployed Environmental Professional assigned to the FOD in which the industrial facility resides includes the following:

- Copies of Stormwater Pollution Prevention Plans
- Reports and certifications required by MSGP
- Routine Inspection Forms
- Supporting analytical data reports including Visual Assessment Forms
- Corrective Action Reports
- Discharge Monitoring Reports
 - Annual Site Compliance Evaluation reports

All ENV-CP records will be maintained and available (after the deadline for submittal as given in applicable procedures) for auditing in the records center at ENV-CP (ENV-DO-QP-110, *Records Management*). Records will be archived in compliance with Laboratory and DOE requirements for records retention, storage, and management.

4.2 PROGRAM RECORDS RESPONSIBILITIES

The following table lists specific responsibilities for program records management:

Who	What
Team Leader	Ensure QAPP meets minimum specifications for documentation and records of the SD330, Los Alamos National Laboratory Quality Assurance Program
Program Lead	Conduct annual review of records to ensure compliance with project requirements.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 12 of 40
	Effective Date: 11/04/2013	

4.3 ELECTRONIC MEDIA

The project will utilize electronic means as necessary to maintain data and perform calculations on these data. Electronic means will not however replace paper copies. All records that must be maintained to meet the requirements of the Permit will be kept in hard copy as the official record.

4.4 DATABASES

Analytical data will be maintained in the LANL Water Quality Database (WQDB). Security, verification, and validation of data are maintained in accordance with LANL procedures.

<u>Security</u> -- ENV data will be maintained electronically in a secure manner and will be protected from loss by being maintained as part of an official dataset that is backed up at least weekly.

<u>Verification of data</u> -- All ENV data, either electronic or hardcopy must undergo a verification and validation process that includes the following:

Verification

- Paper deliverables match electronic data that are stored in an official dataset. Paper deliverables include:
 - chain of custody for sample data
 - field log, if applicable, for sample data
 - data packages for analytical data
 - documentation packages for supporting data (e.g., geographic information system)
- All hand-entered data have been verified by a person other than the individual performing the entry
- Electronic uploads of data (e.g., electronic data deliverables) have been spot checked (at least 10%) to ensure the upload performed as expected
- Hard copy supporting information (e.g., data packages, chains of custody, validation reports, etc.) is evaluated for completeness, archived, and available for audit

<u>Validation</u> --analytical data validation is the responsibility of the EP Directorate. The process will include the following:

- Validate that sample and quality assurance/quality control data and information meet contract specifications
- Assign validation flags, as appropriate
- Identify the analytical supplier
- Identify the analytical method

<u>Verification of calculations</u> -- A person other than the person who generated the query will review for accuracy all compliance related calculations performed in a database through queries. This review will be documented and forwarded to the appropriate record series.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 13 of 40
	Effective Date: 11/04/2013	

Spreadsheets:

<u>Backups</u> -- All spreadsheets used to hold data and generate reports to be used in demonstrating compliance will be maintained in a secure location. The preferred location is on the Group server. Spreadsheets will be backed up at least weekly.

<u>Verification of data</u> -- All compliance-related data uploaded into a spreadsheet will be verified to be accurate against the original paper copy. Data that are uploaded through electronic means will undergo a 10% verification. Data that are uploaded through manual means will undergo a 100% verification. Someone other than the data entry person must perform the 100% review. This review will be documented and forwarded to the appropriate record series.

<u>Verification of calculations</u> -- A person other than the person who generated the spreadsheet will review for accuracy all compliance-related calculations performed in a spreadsheet. This review will be documented and forwarded to the appropriate record series. Modifications to the function of these spreadsheets will also be verified in this manner.

<u>Software control</u> -- The integrity of spreadsheets will be ensured by limiting access to these spreadsheets to only trained, authorized personnel. Additionally, at least once per year, the function of the spreadsheets will be verified by hand calculations. Documentation of this review will be forwarded to the appropriate record series.

4.4 IMPLEMENTATION RESPONSIBILITIES

The following table lists specific responsibilities:

Who	What
Program Lead	Regularly assess data integrity methods used by MSGP personnel.

5.0 PLANNING AND PERFORMING WORK

Work conducted under this program ensures compliance with the 2008 Multi-Sector General Permit; the Clean Water Act; and DOE Orders 450.1, *Environmental Protection Program*, and 5400.5, *Radiation Protection of the Public and Environment*.

Work that contributes to achieving the quality specifications of the MSGP deliverables will be planned and documented as described in this document and implementing procedures.

Work will be performed according to applicable plans and implementing procedures. The team leader will provide first line supervision of personnel assigned to project tasks to ensure work is performed to achieve project quality specifications. Before changing a work process that affects the project quality specifications, the team leader will ensure the same level of planning and review as used in the initial project planning steps.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 14 of 40
	Effective Date: 11/04/2013	

5.1 WORK PROCESSES

All work should be regarded as a process. Each process consists of a series of actions and is planned and carried out by qualified workers using specified work processes and equipment under administrative, technical, and environmental controls established by management to achieve an end result. Workers are the best resource of contributing ideas for improving work processes and will be involved in work process design, process evaluation, and providing the feedback necessary for improvement.

All work is planned and performed using the principles of Integrated Safety Management and in compliance with P300, *Integrated Work Management for Work Activities*.

5.3 WORK PERFORMANCE

Management should ensure that the following are clearly identified and conveyed to workers prior to beginning work:

- customer and data requirements for the work and final product;
- acceptance criteria applicable to work and final product;
- hazards associated with the work;
- technical standards applicable to work and final product; and
- safety, administrative, technical, and environmental controls to be employed during the work.

The work processes used to meet the regulatory requirements and the requirements of this plan can be divided as follows:

- Stormwater Pollution Prevention Plans (Multi-Sector General Permit Section 5.0)
- Inspections (Multi-Sector General Permit Section 4.0)
- Monitoring (Multi-Sector General Permit Section 6.0)
- Discharge Monitoring Reports (Multi-Sector General Permit Section 7.1 Reporting Monitoring Data to EPA)
- Best Management Practices (Multi-Sector General Permit Section 2.0 –Control Measures)
 - Reporting and Recordkeeping (Multi-Sector General Permit Section 7.0)

5.4 STORMWATER POLLUTION PREVENTION PLAN

Stormwater Pollution Prevention Plan (SWPPP) development and implementation by the regulated industrial facility is required for MSGP compliance (refer to Section 8.0 of the 2008 MSGP for Sector-Specific Requirements for Industrial Activity and Appendix D, Sectors of Industrial Activity Covered by This Permit). The SWPPP is intended to document the selection, design, and installation of control measures. Additional documentation requirements are intended to document the implementation (including inspection, maintenance, monitoring, and corrective

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 15 of 40
	Effective Date: 11/04/2013	

action) requirements identified in the 2008 MSGP permit. The SWPPP is a written assessment of potential sources of pollutants in stormwater runoff and control measures that will be implemented at the specific industrial facility to minimize the discharge of pollutants in runoff from the site. These control measures include site-specific Best Management Practices (BMPs), inspections, employee training, and reporting. The procedures detailed in the SWPPP must be implemented by the facility and updated as necessary, with a copy of the SWPPP kept on-site.

The SWPPP development process involves evaluating regulated industrial activities and requiring Facility Management support in implementation, improvement, and revision of the Plans.

5.4.1 DISCHARGE MONITORING REPORTS

The Laboratory is required to submit analytical results of stormwater monitoring and to keep the results with the facility specific SWPPP. The Laboratory must certify and submit analytical monitoring results obtained from each facility specific sampling location (i.e., the sampling station located at the monitored outfalls) associated with industrial activity on a Discharge Monitoring Report (DMR) form or use it to report any of the following:

- no discharge for all outfalls for a specific monitoring period;
- the industrial facility status has changed to inactive and unstaffed;
- the facility status has changed to active; or
- no further pollutant reductions are achievable for all outfalls and for all pollutants (see Section 6.2.1.2 of the 2008 MSGP).

5.4.2 ANNUAL SITE COMPLIANCE EVALUATION REPORT

The Laboratory is required to submit an annual report (Attachment 2) to the Environmental Protection Agency (EPA) that includes the findings from the comprehensive site inspection and any corrective action documentation. The documentation must include the following:

- identification of the condition triggering the need for corrective action review;
- date and description of the problem identified;
- summary of the corrective action taken or to be taken;
- notice of whether SWPPP modifications are required as a result of the discovery or corrective action;
- date corrective action was initiated; and
- date corrective action was completed or is expected to be completed.

The following table lists responsibilities:

Who	What
Project Lead	Ensure that SWPPP requirements are performed in accordance with the MSGP.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 16 of 40
	Effective Date: 11/04/2013	

Facility Management Support	Implement SWPPP requirements as recommended by the Project
	Lead.
ENV-CP Staff and Deployed	Assure SWPPP implementation as required by MSGP.
Environmental Professionals	
(DEPs)	
DEPs	Develop, modify, and update SWPPPs and assist facility personnel with SWPPP implementation.

5.5 Inspections

The MSGP requires periodic inspection of industrial processes and maintenance of (BMPs) to assure effectiveness of control measures. The Laboratory has implemented a quarterly or monthly inspection process (depending on the industrial facility) to support this determination. A copy of the Routine Inspection Form is provided in Attachment 3.

5.6 STORMWATER MONITORING

Benchmark stormwater monitoring is the required mechanism for determining the effectiveness of corrective actions and meeting the requirements of the MSGP. Refer to Attachment 4, *MSGP Facilities and Stormwater Monitored Outfalls Associated with Industrial Activity 2011*, for a list of Laboratory sites that have monitoring requirements. Laboratory management has made an investment in time and materials, in addition to a commitment to comply with the 2008 MSGP Permit. All stormwater monitoring is conducted by ENV-CRP personnel. The MSGP Project currently has a network of 23 monitoring stations. Considerations to be used for MSGP stormwater monitoring development decisions will include MSGP requirements, new state water quality standards, Administrative Authority requests, or new permit requirements. Stormwater monitoring will be conducted as specified in the MSGP.

Effluent Limitations stormwater monitoring is required for the following type of facility of LANL:

Regulated	Parameter	Effluent	Monitoring	Sample Type
Activity		Limit	Frequency	
Discharges from asphalt emulsion facilities	Total Suspended Solids	23.0 mg/L daily max. 15.0 mg/L, 30-day avg.	1/year	grab
	pН	6.0-9.0 s.u.	1/year	grab
	Oil and Grease	10.0 mg/L 30-day avg.	1/year	grab

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 17 of 40
	Effective Date: 11/04/2013	

This determination was made in accordance with Section 1.1.2.4 of the MSGP. The TA-60 Asphalt Batch Plant meets the criteria for effluent limitations monitoring in this section. Exceedances of the effluent limits in this table require immediate action. In addition, if follow-up monitoring after corrective actions also exceeds an effluent limit guideline, an Exceedance Report for Numeric Effluent Limits must be submitted to EPA no later than 30 days after lab results have been received and verified.

Impaired Waters stormwater monitoring is required for discharges made to an impaired water. The canyons within and surrounding Los Alamos National Laboratory are declared as Impaired Waters by the New Mexico Environment Department. The pollutants vary from canyon to canyon and are listed in Attachment 5, *Pollutants Under Impaired Waters Monitoring*. The pollutants may be discontinued in subsequent annual monitoring if the concentration is below background levels in stormwater or if the constituent is not detected.

Visual assessments are also required by the MSGP and are an important tool for collecting information to determine the effectiveness of controls in preventing potential contaminants from migrating off Laboratory property. Accordingly, field personnel must conduct visual assessments for stormwater collected at the monitoring stations or discharged through substantially identical outfalls associated with industrial facilities located throughout the Laboratory. Information recorded will document all observations that are required by the MSGP (see ENV-RCRA-QP-064, *Multi-Sector General Permit Storm Water Visual Inspections*).

The Laboratory's MSGP permit requires stormwater quality monitoring to evaluate compliance with water quality standards and evaluation against benchmarks. Parameters sampled at the monitoring stations are selected based on permit requirements and the results of the previous year.

Four stormwater samples per year are required under the 2008 MSGP, but it is not necessary to collect them in consecutive quarters if climatic conditions that prevented quarterly collection are documented (see *Adverse Weather Conditions* in Section 6.1.5 of the MSGP). Sample locations are listed in Attachment 4, *MSGP Facilities and Stormwater Monitored Outfalls Associated with Industrial Activity 2011*, and collection will be conducted in accordance with LANL and NPDES Permit requirements and the current year MSGP Sampling and Analysis Plan.

Stormwater samples are used to demonstrate compliance with water quality standards and requirements to evaluate results against benchmark parameters (Attachments 5 and 6). Any persons involved in the preparation, retrieval, and analysis must maintain positive control of samples at all times until sample disposal. ENV-RCRA personnel will follow guidance in the Associate Directorate for Environmental Programs (ADEP) document ENV-WQH-QP-029, *Creating and Maintaining a Chain of Custody*, as well as, ENV-RCRA-QP-047, *Inspecting Storm Water Runoff Samplers and Retrieving Samples*, and ENV-RCRA-QP-048, *Processing MSGP Storm Water Samples*.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 18 of 40
	Effective Date: 11/04/2013	

Chain of custody is maintained during:

Activity	Responsibility
Sample collection and preparation	All persons (other than analytical personnel) performing sample preparation and collection will be trained to sample collection procedures and must adhere to the chain of custody requirements therein.
Analysis	Analytical laboratories performing sample analysis will maintain sufficient procedures to ensure positive control of samples as specified in the existing Statement of Work.
Storage/ disposal	Analytical laboratories will maintain retained samples and/or sample portions under chain of custody until reanalysis, or ultimate disposal.

The LANL Sample Management Office (SMO) will be the central point for all analytical laboratory selection, evaluations, sample submittal, and data return. The SMO will evaluate potential analytical laboratories, prepare analytical statements of work that include requirements, and arrange contracts with selected laboratories for analysis of all samples. The SMO will accept samples from field collection personnel, process the sample, ship the samples to the off-site analytical laboratories, and receive the data packages from the laboratories.

All analytical data will be received from analytical laboratories in electronic format and uploaded into a database. All received data will be checked for completeness and adherence to contract requirements. After uploading, all data will undergo verification and validation (V&V) for evidence of laboratory contamination, improper analytical method, and other analytical issues which could potentially affect data quality.

Field data collected by sample collection personnel will be verified and validated by the SMO when field personnel deliver samples to the SMO.

If significant V&V issues are identified, results will be forwarded to and discussed with the responsible project leads.

Data issues that result from procedural failures, personnel errors, or other failures to follow requirements will be documented as issues and corrected according to ENV-DO-QP-113, *Tracking Issues and Actions*.

The following table lists responsibilities:

Who	What
Project Lead	Ensure that all project monitoring requirements are performed in accordance with the MSGP.
	Review and update the MSGP Sampling and Analysis Plan annually.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 19 of 40
	Effective Date: 11/04/2013	

	When complete, communicate findings to the team members for implementation. Make appropriate arrangements with the SMO to accept, process, and submit samples to an analytical laboratory for required analyses as specified in the SAP.
MSGP Water Quality Compliance Personnel	 Implement monitoring program as required by the MSGP Project Lead. Conduct stormwater sampling in accordance with the MSGP Sampling and Analysis Plan and applicable procedures. Ensure procedures for sample handling and control during sample preparation and retrieval are followed.
Sample Management Office	 Develop Statements of Work (SOW) for all analytical laboratories that perform analytical work for the MSGP project in accordance with P840-1, Procurement Quality. Ensure analytical laboratories comply with the DOE's SOW. Conduct an annual audit of the laboratory to ensure compliance with the SOW. Approve Statements of Work for analytical laboratories that are contracted to analyze water samples. Approve analytical laboratories that are contracted to analyze water samples for regulatory compliance purposes. Accept samples and submit them to and approved analytical laboratory for analysis. Track progress of samples at the analytical laboratory and resolve issues with sample analysis. Receive data packages from the analytical laboratory and enter data into the database. Provide the MSGP Project Lead with monthly invoice updates. Perform V&V of field data submitted and uploaded from forms when samples are submitted to the SMO.
Operations Integration Office (OIO), Systems Integration (SI)	Perform V&V of data packages uploaded by the SMO or send data packages to a subcontractor company for independent V&V.

5.7 DISCHARGE MONITORING REPORTS

The Laboratory is required to submit analytical results of stormwater monitoring and to keep the results with the specific SWPPP. The Laboratory must submit analytical monitoring results obtained from each monitoring station associated with industrial activity on a MSGP Discharge Monitoring Report (MDMR) form (one form must be submitted for each storm event from which, a sample was collected).

MDMRs shall be written in accordance with ENV-RCRA-QP-044, *Preparing Storm Water Discharge Monitoring Reports (MDMRs) for the NPDES Multi-Sector General Permit.*MDMRs shall be submitted to EPA within 30 calendar days of receiving validated

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 20 of 40
	Effective Date: 11/04/2013	

analytical results. Refer to the DMR language under the SWPPP Section above for additional requirements.

Site analytical requirements are defined by the industrial activity in the MSGP permit. All MSGP analytes applicable to LANL are consistent with the requirements of 40 CFR Part 136, *Guidelines Establishing Test Procedures for the Analysis of Pollutants*.

Sample analytical requirements vary by site depending on the industrial activities performed at the site. Refer to Attachment 5 for a list of analytes by industrial sector. If an insufficient quantity of sample is available, then sample collection will be prioritized at that location for future events. Additional samples may be collected to meet permit requirements.

ENV-RCRA shall refer to the requirements of the 2008 Multi-Sector General Permit, and the most current MSGP Sampling and Analysis Plan to determine the priorities of required analyses.

The following table lists responsibilities:

Who	What
Project Lead	 Ensure implementing procedures for sample analyses are used. Ensure that MDMRs are submitted to EPA and NMED in accordance with the MSGP.
MSGP Water Quality Compliance Personnel	Assure MDMRs are completed and certified as required by the MSGP and have received a full quality assurance review.

5.8 ADVERSE WEATHER CONDITIONS AND CLIMATES WITH IRREGULAR STORMWATER RUNOFF

Section 4.2.3 of the 2008 MSGP allows the industrial facility to take a substitute sample during the next qualifying storm event when adverse weather conditions prevent the collection of samples during a specific quarter. Adverse weather conditions are those that are dangerous or create inaccessibility for personnel, such as local flooding, high winds, or electrical storms, or situations that otherwise make sampling impractical, such as drought or extended frozen conditions. Documentation of the rationale for no visual assessment for the quarter must be included in the facility specific SWPPP.

Since LANL is located in an area where limited rainfall occurs during parts of the year (i.e., in a semi-arid climate) and has periods of freezing conditions, LANL has identified an alternative monitoring period of four quarters as follows for each calendar year.

April 1-May 31

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 21 of 40
	Effective Date: 11/04/2013	

- June 1-July 31
- August 1-September 30
- October 1-November 30

The following table lists specific responsibilities.

Who	What
Project Lead	Ensure that the monitoring schedule is documented in facility specific SWPPPs and provided to EPA on the MDMRs.

5.9 REPORTING AND RECORDKEEPING

All monitoring data shall be collected in accordance with the requirements specified in the 2008 MSGP. LANL will submit monitoring results to EPA within 30 days of receiving validated laboratory results. The address for submittal of monitoring results is as follows.

U.S. Environmental Protection Agency Office of Water, Water Permits Division Mail Code 4203M, ATTN: MSGP Reports 1200 Pennsylvania Avenue, NW Washington, D.C. 20460

LANL shall keep copies of the following documentation for a period of at least 3 years from the date that LANL's coverage under the MSGP expires or is terminated.

- SWPPP (including any modifications made during the term of the 2008 MSGP)
- Additional documentation requirements as identified in Section 5.4 of the MSGP
- All reports and certifications required by the MSGP
- Monitoring data
- Records of all data used to complete the NOI.

The following table lists specific responsibilities:

Who	What
Project Lead	Periodically audit MSGP records to ensure documentation of compliance is being retained.
Deployed Environmental Professionals	Retain records as required by the MSGP for industrial facilities located in their FOD.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 22 of 40
	Effective Date: 11/04/2013	

5.10 BEST MANAGEMENT PRACTICES

It is critical that the Laboratory be able to effectively inspect and maintain the Best Management Practices that have been installed at various locations. Quarterly inspections must be completed and provided to the Project Lead for inclusion into the records system. In addition, the Project Leader conducts a Comprehensive Annual Site Inspection and writes a report to document the status of BMPs and other identified corrective actions. This report is sent to EPA each year. Laboratory management has made an investment in time and materials, in addition to a commitment to minimizing the potential migration of contaminants in stormwater. Report findings are evaluated and in conjunction with facility personnel, BMPs are modified, installed, or removed as necessary.

The following table lists responsibilities.

Who	What
Project Lead	Assist facility personnel and Deployed Environmental Professionals with implementation, inspection, and maintenance of BMPs at MSGP facilities.
Facility Management Support	 Coordinate with Project Lead and provide funding as needed to install, inspect, maintain and implement identified BMPs. Certify the corrective actions identified by the Project Lead and/or facility personnel (or their representatives) for their individual facilities in the Annual Report.

5.11 INFORMATION MANAGEMENT

The Water Quality Database is a database information system designed in part to support the information management (IM) needs of the Laboratory's MSGP. MSGP support includes stormwater discharge monitoring reporting, Geographic Information System (GIS) development, and other IM activities as needed.

The following table lists responsibilities:

Who	What
Project Lead	Coordinate with IM support personnel to meet regulatory requirements.

5.12 RESPONDING TO WATER QUALITY EXCEEDANCES

The identification of a pollutant source(s) contributing to a water quality exceedance will be addressed through the creation of a corrective action that is entered into the Corrective Acton

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 23 of 40
	Effective Date: 11/04/2013	

Report database in accordance with ENV-DO-QP-113, *Tracking Performance Feedback and Actions* and *ENV-RCRA-QP-022*, *MSGP Stormwater Corrective Actions*. Federal stormwater regulations implemented under the Laboratory's MSGP (40 CFR 122, EPA Administered Permit Programs: The National Pollutant Discharge Elimination System) require that corrective action be taken if exceedances of water quality standards or MSGP numeric effluent limits are identified. Corrective actions are typically accomplished by modifying, as appropriate, existing BMPs and SWPPPs.

When a water quality exceedance occurs, the Laboratory will submit the data on the required MDMRs, investigate the occurrence, and document corrective actions.

When an exceedance of the MSGP benchmark parameters is detected, the Project Lead will assure the analytical data is reviewed, notify appropriate SWPPP owners, and recommend and track corrective actions where required.

The following steps lead to corrective actions:

STEP	Action
1	Establish that an analytical result from a location is valid and has exceeded a standard or MSGP benchmark.
2	Evaluate and demonstrate that the analyte is of LANL origin, if possible.
3	Determine the source and assign responsibility for the corrective action.
4	Develop a corrective action plan.

The following table lists responsibilities:

Who	What
Project Lead	 Assure that analytical data is reviewed and accurate. Notify appropriate SWPPP owners, Laboratory management, and Deployed Environmental Professionals. Develop a corrective action plan. Follow up with corrective actions if required. Track corrective actions.
Facility Management and DEP	 Review analytical data with Project Lead and provide input into a possible corrective action necessary to improve water quality where needed. Evaluate and improve BMPs in accordance with site conditions, industry standards, and manufacturer

	Page 24 of 40
Effective Date: 11/04/2013	

recommendations.

5.13 Instrumentation and Equipment

Compliance will be tracked by performing inspections of samplers and other associated equipment, inspecting BMPs, and conducting annual site compliance evaluations. Adequate records will be maintained to demonstrate the operating history of essential instrumentation and equipment.

LANL will properly operate and maintain all systems of monitoring and control and related appurtenances which are installed or used to achieve compliance with the MSGP and the SWPPP. Backup instrumentation and equipment will be timely deployed in the event of equipment failure.

Instrument calibration is essential for documenting the quality of data obtained with the instrument. All technical work that depends upon the accuracy of data will be performed using equipment for which the calibration status and limits of accuracy are known and controlled.

Field team personnel will calibrate and perform maintenance procedures on all monitoring and analytical field instruments to ensure accuracy of measurements and will maintain appropriate records of such activities. All field calibrations will be documented as prescribed by procedures or manufacturer's instructions.

The following table lists specific responsibilities.

Who	What	
Project Lead	Ensure data are collected and equipment is operated and maintained in accordance with project requirements.	
	Provide equipment maintenance and calibration specifications and ensure MSGP Water Quality Compliance Team personnel operate and conduct field activities in accordance with implementing procedures and specific work orders.	

6.0 DESIGN

Design activities will be conducted and reviewed in accordance with PD340, *Conduct of Engineering* and P341, *Engineering Process Manual*.

Design standards under this program include, but are not limited to temporary and permanent BMPs, corrective action measures, and stormwater monitoring support.

Design inputs will be specified and approved on a timely basis for making design decisions. Inputs will contain the level of detail required to permit the performance of design activities correctly.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 25 of 40
	Effective Date: 11/04/2013	

Formal design reviews, including design verifications and evaluation of design changes, will be conducted to ensure that the design input is correctly incorporated into the design output. Changes to design will undergo the same review as the original design.

Verification and validation of the adequacy of designs are conducted before relying on the performance of the design function. Verification and validation are conducted in accordance with implementing procedures.

The following table lists responsibilities.

Who	What
Project Lead	 Provide input to the design process in accordance with appropriate standards, requirements, and implementing procedures.
	 Determine the qualifications required to perform a review of design documents.
	 Identify a resource with skills, knowledge, ability, training, and certifications required to complete the review of the facility engineering design documents.
	Communicate the results of the review to the requestor.
ENV-CP Staff	Review design documents and requests as assigned.
	Inform the Project Lead of concerns regarding the facility engineering designs.

7.0 PROCUREMENT

Items and services required for this process are commercial grade in nature and no special procurement requirements or needs are necessary. All procurements will be made in accordance with P840-1, *Procurement Quality*. For items and all services for which special requirements are necessary, the Project Lead and project members will identify such items or services.

The following table lists responsibilities:

Who	What
Group Leader	Ensure all procurements are conducted in accordance with P840-1.
Project Lead	Recommend to Group Leader contracting items and services. Develop acceptance criteria.
ENV-CP Staff	Identify potential suppliers of products or services necessary to complete work activities that must be procured from outside ENV-RCRA.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 26 of 40
	Effective Date: 11/04/2013	

8.0 INSPECTION AND ACCEPTANCE TESTING

Any materials or services will be inspected and/or tested prior to acceptance for use in this project in accordance with P330-8, *Inspection and Test for Acceptance*. Most supplies used during performance of project activities are commercial grade in nature and require no special acceptance practices or procedures.

The following table lists responsibilities:

Who	What
Group Leader	Ensure procedures for inspection meet SD330, Los Alamos National Laboratory Quality Assurance Program requirements.
Project Lead	Verify that all materials and services meet acceptance criteria.
ENV-CP Staff	Follow established procedures for inspection and acceptance testing.

9.0 MANAGEMENT ASSESSMENT

The ENV-CP Group conducts internal management assessments of projects and programs in accordance with the requirements in P328-3, *Management Assessment* and P328-4, *Management Observation and Verification*. Assessments of the program are documented and filed as records.

When violations of requirements are found during a management assessment, a nonconformance report is initiated in accordance with P330-6, *Nonconformance Reporting* for nonconforming items.

Nonconforming services or processes are tracked and documented in accordance with P322-4, *Issues and Corrective Action Management*.

The following table lists responsibilities:

Who	What
Group Leader	Ensure management self-assessments for the MSGP program are conducted as specified in implementing procedures.
Project Lead	Ensure program management self-assessments are conducted.

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 27 of 40
	Effective Date: 11/04/2013	

10.0 INDEPENDENT ASSESSMENT

Independent assessments are those assessments conducted by organizations external to ENV-RCRA. As required by the SD330, *Los Alamos National Laboratory Quality Assurance Program*, this program may be assessed by outside organizations in accordance with P328-2, *Independent Assessment*.

Periodically audits/assessments will be conducted, with input from the Project Lead identifying one or more areas of the project to be audited.

The following table lists responsibilities:

Who	What
Project Lead	Approve audit schedules.
	Provide input to the QA Specialist as to the content of audit.
	 Review audit reports for factual accuracy. Address all findings and implement corrective actions as appropriate.
QA Specialist	Identify areas to be addressed during internal audits.
	 Contract with the Quality Management Group to perform annual internal audits.
	 Review audit procedures to ensure they meet the requirements in this section.
Team Members	Cooperate with auditors by providing information, data, etc.
	Implement corrective actions as directed by the Project Lead.

11.0 ATTACHMENTS

Attachment 1- MSGP Program Organization

Attachment 2 – Annual Reporting Form

Attachment 3 – Routine Inspection Form

Attachment 4 – MSGP Facilities and Storm Water Monitored Outfalls Associated with Industrial Activity 2011, Permit NMR05GB21


Attachment 5 – Pollutants under Impaired Waters Monitoring

Attachment 6 – Analytes by Industrial Sector

Attachment 7 – References and Guidance Documents

Effective Date: 11/04/2013

ATTACHMENT 1- MSGP PROGRAM ORGANIZATION



^{*}Project Lead acts as liaison and will work directly with Team Leaders for staff assignments.

Stormwater MSGP for Indu	ustrial Activities Progran
--------------------------	----------------------------

No. ENV-CP-QAPP-MSGP, R5

Page 29 of 40

Effective Date: 11/04/2013

ATTACHMENT 2 – ANNUAL REPORTING FORM

	NPDES Permit Tracking No.:
United States Environmental Protection Agency Washington, DC 20460	
Annual Reporting Form	
A. GENERAL INFORMATION	
1. Facility Name:	
2. NPDES Permit Tracking No.:	
3. Facility Physical Address:	
a. Street:	
b. City: c. State: d. Zip Code:	·
4. Lead Inspectors Name: Title: Title:	
Additional Inspectors Name(s):	
5. Contact Person: Title:	
Phone: Ext E-mail: E-mail:	
6. Inspection Date: / / / / / / / / / / / / / / / / / / /	
B. GENERAL INSPECTION FINDINGS	
1. As part of this comprehensive site inspection, did you inspect all potential pollutant sources, including areas where industrial activity may \square YES \square NO	be exposed to stormwater?
If NO, describe why not:	
NOTE: Complete Section C of this form for each industrial activity area inspected and included in your SWPPP or as newly identified in B. may be exposed to stormwater.	2 or B.3 below where pollutants
2. Did this inspection identify any stormwater or non-stormwater outfalls not previously identified in your SWPPP?	
If YES, for each location, describe the sources of those stormwater and non-stormwater discharges and any associated control measures.	res in place:

	NPDES Permit Tracking No.
. Did this inspection identify any sources of stormwater or non-stormwater discharges not previously identified in your SWPPP? 🔲 YE	S NO
If YES, describe these sources of stormwater or non-stormwater pollutants expected to be present in these discharges, and any cor	ntrol measures in place:
Did you review stormwater monitoring data as part of this inspection to identify potential pollutant hot spots?	NA, no monitoring performed
If YES, summarize the findings of that review and describe any additional inspection activities resulting from this review:	
. Describe any evidence of pollutants entering the drainage system or discharging to surface waters, and the condition of and around o	utfalls including flow
dissipation measures to prevent scouring:	ottails, motoding new
Have you taken or do you plan to take any corrective actions, as specified in Part 3 of the permit, since your last annual report submis authorization to discharge under this permit if this is your first annual report), including any corrective actions identified as a result of this permit is permit if this is your first annual report), including any corrective actions identified as a result of the permit is permit if this is your first annual report).	ssion (or since you received his annual comprehensive site
If YES, how many conditions requiring review for correction action as specified in Parts 3.1 and 3.2 were addressed by these corrective actions?	
IOTE: Complete the attached Corrective Action Form (Section D) for each condition identified, including any conditions identified as a	result of this comprehensive

Stormwater MSGP for Industrial Activities Program

Page 30 of 40

No. ENV-CP-QAPP-MSGP, R5 Effective Date: 11/04/2013

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 31 of 40
	Effective Date: 11/04/2013	

			NPD	ES Pe	rmit T	rackir	ng No.:
					Ш		
C. INDUSTRIAL ACTIVITY AREA SPECIFIC FINDINGS						-	
Complete one block for each industrial activity area where pollutants may	be expose	d to stormwater. Copy this page for addition	nal ind	ustrio	l activ	vity e	rose
In reviewing each area, you should consider: Industrial materials, residue, or trash that may have or could come ir Leaks or spills from industrial equipment, drums, tanks, and other co Offsite tracking of industrial or waste materials from areas of no expe Tracking or blowing of raw, final, or waste materials from areas of no	nto contact ontainers;	with stormwater;	iai iiiu	ustria	aun	nty ar	eas.
INDUSTRIAL ACTIVITY AREA:		·					
1. Brief Description:							
Are any control measures in need of maintenance or repair?	☐ YES	□NO					
Have any control measures failed and require replacement?							
Are any additional/revised control measures necessary in this area?	☐ YES	□ NO					
If YES to any of these three questions, provide a description of the problem: Corrective Action Form)		_	the at	tached	ı		
INDUSTRIAL ACTIVITY AREA: 1. Brief Description:							
Are any control measures in need of maintenance or repair? Have any control measures failed and require replacement?	☐ YES	□ NO					
Are any additional/revised c necessary in this area?	YES	□ NO					
If YES to any of these three questions, provide a description of the problem: Corrective Action Form)			n the at	tached	i		
INDUSTRIAL ACTIVITY AREA:							
Brief Description:							
Are any control measures in need of maintenance or repair?	☐ YES	□ NO					
3. Have any control measures failed and require replacement?	☐ YES	□NO					
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□ NO					
If YES to any of these three questions, provide a description of the problem: Corrective Action Form)	(Any neces	ssary corrective actions should be described on	the att	ached			

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 32 of 40
	Effective Date: 11/04/2013	

			NPDE	S Perr	nit Tra	cking	No.:
			Ш	Ш		Ш	
		NOTE: Copy this page and attach	addition	nal pag	es as	neces	sary
INDUSTRIAL ACTIVITY AREA:							
1. Brief Description:							
2. Are any control measures in need of maintenance or repair?	☐ YES	□NO					
3. Have any control measures failed and require replacement?	☐ YES	□NO					
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□NO					
If YES to any of these three questions, provide a description of the Corrective Action Form)	he problem:	(Any necessary corrective actions should be described on the	e attacl	hed			
Corrective Action Form)							
INDUSTRIAL ACTIVITY AREA:							
1. Brief Description:							
1. Diei Description.							
Are any control measures in need of maintenance or repair?	☐ YES	□NO					
Have any control measures failed and require replacement?	YES	□NO					
Are any additional/revised BMPs necessary in this area?	☐ YES	□NO					
If YES to any of these three questions, provide a description of the	he problem:	(Any necessary corrective actions should be described on the	e attac	hed			
Corrective Action Form)							
INDUSTRIAL ACTIVITY AREA:							
1. Brief Description:							
	E V50	FINO					
Are any control measures in need of maintenance or repair? Have any control measures foiled and require replacement?	☐ YES	□ NO					
Have any control measures failed and require replacement? Are any additional/revised BMPs necessary in this area?	☐ YES	□ NO					
If YES to any of these three questions, provide a description of the			e attac	hed			
Corrective Action Form)	problem.	Viny increased y consented actions enough to accompany of the					

Stormwater MSGP for Industrial Activities Program

No. ENV-CP-QAPP-MSGP, R5

Page 33 of 40

Effective Date: 11/04/2013

	NPDE	S Permit	Tracki	ıg No.:
	Ш			
D. CORRECTIVE ACTIONS				
Complete this page for each specific condition requiring a corrective action or a review determining that no corrective at page for additional corrective actions or reviews.	tion is ne	eded. C	Copy th	is
Include both corrective actions that have been initiated or completed since the last annual report, and future corrective actions ned identified in this comprehensive stormwater inspection. Include an update on any outstanding corrective actions that had not been previous annual report.	ded to ad complete	dress pro	oblems time of	your
1. Corrective Action # of for this reporting period.				
2. Is this corrective action:				
☐ An update on a corrective action from a previous annual report; or				
☐ A new corrective action?				
3. Identify the condition(s) triggering the need for this review:				
☐ Unauthorized release or discharge				
☐ Numeric effluent limitation exceedance				
☐ Control measures inadequate to meet applicable water quality standards				
☐ Control measures inadequate to meet non-numeric effluent limitations				
☐ Control measures not properly operated or maintained				
☐ Change in facility operations necessitated change in control measures				
☐ Average benchmark value exceedance				
Other (describe):				
4. Briefly describe the nature of the problem identified:				
5. Date problem identified:				
6. How problem was identified:				
☐ Comprehensive site inspection				
☐ Quarterly visual assessment				
☐ Routine facility inspection				
☐ Benchmark monitoring				
□ Notification by EPA or State or local authorities				
Other (describe):				
7. Description of corrective action(s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modification measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination:	s or repair	s to cont	trol	
8. Did/will this corrective action require modification of your SWPPP?				
9. Date corrective action initiated:				
10. Date correction action completed:	Ш			
11. If corrective action not yet completed, provide the status of corrective action at the time of the comprehensive site inspection an (including timeframes associated with each step) necessary to complete corrective action:	d describe	any ren	naining	steps

N I	IPDES Permit Tracking No.:
E. ANNUAL REPORT CERTIFICATION	
1. Compliance Certification	
Do you certify that your annual inspection has met the requirements of Part 4.2 of the permit, and that, based upon the results of the your knowledge, you are in compliance with the permit? YES NO	nis inspection, to the best of
If NO, summarize why you are not in compliance with the permit:	
2. Annual Report Certification	
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance wassure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or personstem, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge	sons who manage the and belief, true, accurate,
and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impriviolations.	isonment for knowing
Authorized Representative	
Printed Name:	
Signature: Date Signed:	

No. ENV-CP-QAPP-MSGP, R5

Effective Date: 11/04/2013

Page 34 of 40

Stormwater MSGP for Industrial Activities Program

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 35 of 40
	Effective Date: 11/04/2013	

ATTACHMENT 3 – ROUTINE INSPECTION FORM

Name of Facility:				Resnons	ible FOD (Name & Organizatio	n)·
1				-	,	•
Qualified Inspector(s): Others Present:				Inspectio	n type: Quarterly Other	Date of inspection (MM/DD/YYYY):
Others Present:						Time of inspection:
Weather: □ Clear □Cloudy □ F Temperature: ° F	Rain 🗖 S	leet 🛭 Fog	□ s	now 🗖 l	ligh Winds ☐ Other: Is Inspection Being Con	ducted During a Storm Water Discharge? □Yes □No
# Structural Control Measures (BMP)s	Location	Operating Effectively (Yes or No)?	Maint Repa	Need to ain (M), ir (R) or ce (RP)?	Corrective Action Needed ar failed control measures that ne	nd Notes (identify needed maintenance and repairs, or any eed replacement)
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.						
Were additional BMPs or Control Mea						
Were previously identified conditions	s corrected		xt antic	ipated stor	m event? □ Yes □ No If No, o	describe reason:
Area/Activity (Areas of Industrial Materials or Activities Exposed to Storm Water)	Inspected ?	Controls Adequate?	Corre	ctive Actio	n Needed and Notes (List area	letter with comments below)
Material loading/unloading & storage areas Equipment operations & maintenance areas C. Fueling Areas Outdoor vehicle & equipment washing areas Waste Handling & disposal areas F. Erodible areas / construction G. Non-storm water / illicit						

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 36 of 40
	Effective Date: 11/04/2013	

Н.	Salt storage piles or pile			
I.	containing salt Dust generation & vehicle tracking			
Are	the SWPP Plan maintenance, s	schedules and procedures	s being implemented at the facility? Yes No	
We	re any Corrective Actions initia	ted or completed? Yes	□ No Describe:	
			s □ No If Yes, List Number of Corrective Actions Required prrective Action Report database for each listed)	

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 37 of 40
	Effective Date: 11/04/2013	

ATTACHMENT 4 -- MSGP FACILITIES AND STORM WATER MONITORED OUTFALLS ASSOCIATED WITH INDUSTRIAL ACTIVITY 2011, PERMIT NMR05GB21

Location	Permitted Facility	Operation	Activity	Sector	Monitored Outfall	• Canyon
TA-15-185	TA-15-185 PHERMEX	Vehicle Maintenance Shop	Vehicle Maintenance	Р	15-PHRMX- 1	• Water
TA-3-0034	TA-3-0034 Metal Shop	Fabricated Metals	Fabricated Metals	AA	3-MST-1	 Mortandad
TA-3-22	TA-3-22 Power & Steam Plant	Power Plant	Steam Electric Power	0	3-PSP-1 3-PSP-5 3-PSP-8	Sandia
TA-3-38	TA-3-38 Metals Fab Shop	Metal Shop	Fabricated Metals	AA	3-MFS-1	• Sandia
TA-3-39	TA-3-39 & 102 Metal Shop	Metal Shop	Fabricated Metals	AA	3-TS-1	 Pajarito
TA-3-66	TA-3-66 Sigma Complex	Sigma Foundry	Primary Metals	F	3-Sigma-6	• Sandia
TA-54	TA-54 Area G	Area G - South Side	TSD	K	54-G-1	 Pajarito
TA-54	TA-54 Area G	Area G -North Side	TSD	К	54-G-2	 Canada del Buey
TA-54	TA-54 Area G	Area G - South Side	TSD	K	54-G-3	 Pajarito
TA-54	TA-54 Area G	Area G - South Side	TSD	K	54-G-4	 Pajarito
TA-54	TA-54 Area L	Area L	TSD	К	54-L-1	Canada del Buey
TA-54-38	TA-54 RANT	RANT	TSD	К	54-RANT-1	 Canada del Buey
TA-60	TA-60 Asphalt Batch Plant	Asphalt Batch Plant	Asphalt Paving	D	60-ABP-1	 Mortandad
TA-60	TA-60 MRF	Materials Recycling Facility	Scrap Recycling	N	60-MRF-1	• Sandia
TA-60-250	TA-60 Roads and Grounds	Roads & Grounds Facility	Vehicle Maintenance & Storage	Р	60-RG-1	Mortandad
			-	Р	60-RG-3	 Sandia
				Р	60-RG-8	 Sandia
TA-60-1	TA-60-1 Heavy Equipment Yard	Motor pool	Vehicle Maintenance	Р	60-HEY-2	• Sandia
TA-60-2	TA-60-2 Warehouse	Motor pool	Vehicle Maintenance	Р	60-WH-1	• Sandia
TA-9-28	TA-9-28 Heavy Equipment Maintenance	Motor pool	Vehicle Maintenance	Р	9-HEM-1	 Pajarito

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 38 of 40
	Effective Date: 11/04/2013	

ATTACHMENT 5 – POLLUTANTS UNDER IMPAIRED WATERS MONITORING

Permitted Facility	Monitored Outfall	Assessment Unit	Canyon	Pollutant
TA-54 Area G	54-G-2	NM-128.A_00	Canada del Buey (within LANL)	PCBs
TA-54 Area L	54-L-1			Aluminum
TA-54-RANT	54-RANT-1			Gross Alpha
TA-54 Area G	54-G-1	NM-128.A_08	Pajarito Canyon (within LANL	PCBs
TA-54 Area G	54-G-3		below Arroyo de la Delfe)	Aluminum
TA-54 Area G	54-G-4			Copper
				Gross Alpha
TA-15-185 PHERMEX	15-PHRMX-1	NM-128.A_13	Water Canyon (within LANL	PCBs
		_	below Area-A Canyon)	Aluminum
				Gross Alpha
TA-3-39 & 102 Metal Shop	3-TS-1	NM-128.A_15	Two Mile Canyon (Pajarito to	PCBs
			headwaters)	Aluminum
				Gross Alpha
TA-9-28 Heavy Equipment	9-HEM-1	NM-128.A_16	Arroyo de la Delfe (Pajarito	Aluminum
Maintenance			Canyon to headwaters)	Mercury
				Gross Alpha
TA-60 Asphalt Batch Plant	60-ABP-1	NM-9000.A_042	Mortandad Canyon (within	Aluminum
TA-3-0034 Metal Shop	3-MST-1		LANL)	Copper
TA-60 Roads and Grounds	60-RG-1			
				Gross Alpha
		NM-9000.A_047	Sandia Canyon (Sigma Canyon	PCBs
TA-3-38 Metals Fab Shop	3-MFS-1		to NPDES outfall 001)	Aluminum
TA-3-22 Power & Steam Plant	3-PSP-1			Copper
TA-3-22 Power & Steam Plant	3-PSP-5			Gross Alpha
TA-3-22 Power & Steam Plant	3-PSP-8			Mercury
TA-3-66 Sigma Complex	3-Sigma-6			
TA-60-1 Heavy Equipment Yard	60-HEY-2			
TA-60 MRF	60-MRF-1			
TA-60 Roads and Grounds	60-RG-3			
TA-60 Roads and Grounds	60-RG-8			
TA-60-2 Warehouse	60-WH-1			

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 39 of 40
	Effective Date: 11/04/2013	

ATTACHMENT 6 – ANALYTES BY INDUSTRIAL SECTOR

Permitted Facility	Monitored Outfall	Sector	Activity	Analyte	Monitoring Requirement
TA-3-0034 Metal Shop	3-MST-1	AA	Fabricated Metals	Aluminum	Quarterly Benchmark Monitoring (QBM)
TA-3-38 Metals Fab Shop	3-MFS-1			Iron	QBM
TA-3-39 & 102 Metal Shop	3-TS-1			Nitrate plus Nitrite Nitrogen	QBM
				Zinc	QBM
TA-60 Asphalt Batch Plant	60-ABP-1	D	Asphalt Paving	Oil and Grease	Effluent Limitations Guidelines (ELG)
•				pH	ELG
				Total Suspended Solids	QBM and ELG
TA-3-66 Sigma Complex	3-Sigma-6	F	Primary Metals	Copper	QBM
				Zinc	QBM
TA-54 Area G	54-G-1	К	Treatment, Storage or Disposal Facility (TSD)	Ammonia	QBM
TA-54 Area G	54-G-2			Arsenic	QBM
TA-54 Area G	54-G-3			Cadmium	QBM
TA-54 Area G	54-G-4			Chemical Oxygen Demand	QBM
TA-54 Area L	54-L-1			Cyanide	QBM
TA-54 RANT	54-RANT-1			Lead	QBM
				Magnesium	QBM
				Mercury	QBM
				Selenium	QBM
				Silver	QBM
TA-60 MRF	60-MRF-1	N	Scrap Recycling	Aluminum	QBM
				Chemical Oxygen Demand	QBM
				Copper	QBM
				Iron	QBM
				Lead	QBM
				Total Suspended Solids	QBM
				Zinc	QBM
TA-3-22 Power & Steam Plant	3-PSP-1	0	Steam Electric Power	Iron	QBM
	3-PSP-5				
	3-PSP-8				

Stormwater MSGP for Industrial Activities Program	No. ENV-CP-QAPP-MSGP, R5	Page 40 of 40
	Effective Date: 11/04/2013	

ATTACHMENT 7 – REFERENCES AND GUIDANCE DOCUMENTS

- 40 CFR 122, EPA Administered Permit Programs
- 40 CFR 136, Guidelines Establishing Test Procedures for the Analysis of Pollutants.
- Clean Water Act, Title 33 U.S.C. 1251
- DOE O 414.1C, Quality Assurance
- DOE Order 450.1, Environmental Protection Program
- DOE Order 5400.5, Radiation Protection of Public and Environment
- EPA QA/G-4, Guidance for the Data Quality Objectives Process

LANL Documents:

- P322-4, Laboratory Performance, Feedback, and Improvement
- P328-3, Management Assessments
- P328-4, Management Observation and Verification
- P330-6, Nonconformance Reporting
- P330-8, Inspection and Test for Acceptance
- P340, Conduct of Engineering
- P341, Engineering Process Manual
- P401, Procedure to Identify, Communicate, and Implement Environmental Requirements
- P407, Water Quality
- P840-1, Procurement Quality

ENV Documents:

- ENV-DO-QP-105, Preparation, Review, and Approval of Procedures
- ENV-DO-QP-106, Document Control
- ENV-DO-QP-113, Tracking Performance Feedback and Actions
- ENV-DO-QP-115, Personnel Training
- ENV-CP-QP-022, MSGP Storm Water Corrective Actions
- ENV-CP-QP-044, Preparing Storm Water Discharge Monitoring Reports (MDNRs) for NPDES MSGP
- ENV-CP-QP-047, Inspecting Storm Water Runoff Samplers and Retrieving Samples
- ENV-CP-QP-048, Processing MSGP Storm Water Samples
- ENV-CP-QP-064, Multi-Sector General Permit Storm Water Visual Inspections
- ENV-WQH-QP-029, Creating and Maintaining a Chain of Custody
- Surface Water Monitoring Plan, October 2001, Rev. 0.0

ENV-RCRA-QP-022.2

Effective Date: February 28, 2013

Next Review Date: January 28, 2015



Environment, Safety, Health Directorate

Environmental Protection – Water Quality and RCRA Quality Procedure

MSGP Storm Water Corrective Actions

Reviewers:

Name:	Organization:	Signature:	Date:
Melanie Lamb	ENV-QPMO QA Specialist	Signature on file	1/4/13
	Derivative Classific	er: 🛛 Unclassified	
Name:	Organization:	Signature:	Date:
Catherine Hayes	ENV-RCRA	Signature on file	2/8/13
	Approval	Signatures:	
Subject Matter Expert:	Approval Organization:	Signatures:	Date:
Subject Matter Expert: Holly Wheeler		<u> </u>	Date: 1/28/13
	Organization:	Signature:	
Holly Wheeler	Organization: ENV-RCRA	Signature: Signature on file	1/28/13
Holly Wheeler Responsible Line Manager:	Organization: ENV-RCRA Organization:	Signature: Signature on file Signature:	1/28/13 Date:

CONTROLLED DOCUMENT

This copy is uncontrolled. The controlled copy can be found on the ENV Division Web page.

Users are responsible for ensuring they work to the latest approved version.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 2 of 23
	Effective Date: February 28, 2	2013

History of Revisions

Document Number [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
0	08/10	New Document.
1	11/10	Incorporated ENV-RCRA-QP-062 MSGP Routine Inspections into this document.
2	01/13	Biennial revision, new template implemented.

Page 3 of 23

Effective Date: February 28, 2013

Table of Contents

1.0	PUR I	POSE	4
2.0	SCO	PE	4
	2.1	Hazard review	
3.0	RESI	PONSIBILITIES	4
	3.1	Roles and Responsibilities	
	3.2	Prerequisites	6
4.0	DOC	UMENT CONTROL/RECORDS MANAGEMENT	7
5.0	WOR	RK PROCESSES	7
	5.1	Identifying Corrective Actions	
	5.2	Routine Inspections	
	5.3	Comprehensive Inspections	8
	5.4	Spills	9
	5.5	Allowable Non-Storm Water Discharges	9
	5.6	Entering Corrective Actions	10
	5.7	Updating Corrective Actions	12
	5.8	Validating Corrective Actions	12
	5.9	Institutional Performance Feedback and Improvement Tracking System (PFITS)	13
	5.10	Notifications for New and Overdue Corrective Actions	14
6.0	REFI	ERENCES	14
7.0	DEFI	NITIONS	15
8.0	ATT	ACHMENTS	15
		ACHMENT 1- Annual Reporting Form	
		ACHMENT 2- NPDES Multi-Sector General Permit Routine Inspection Form	

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 4 of 23
	Effective Date: February 28, 2	2013

1.0 PURPOSE

This procedure is written to provide requirements for identifying, documenting and entering corrective actions into the ENV-RCRA MSGP Corrective Action Report Findings database.

2.0 SCOPE

Requirements set forth in this document apply to Los Alamos National Laboratory industrial facilities covered by the National Pollutant Discharge Elimination System (NPDES) Storm Water Multi-Sector General Permit (MSGP). This "general permit" requires identification, documentation, tracking and reporting of corrective actions in accordance with sections 2.2.1, 3, 4.1.2, 4.2.2, 4.3.2, 5.0, 5.2, 5.4, 6.2.1, 6.2.1.2, 7.2 and Appendices B and I.

2.1 HAZARD REVIEW

The work described in this procedure is <u>office work only</u> and has a <u>LOW hazard</u> rating as documented by submittal of a completed <u>ENV Low Hazard Verification form</u> to the Quality Assurance Specialist.

3.0 RESPONSIBILITIES

The following personnel require training before implementing this procedure:

- Group and Team Leader
- ENV-RCRA MSGP Storm Water compliance personnel
- Deployed Environmental Professionals (DEPs)
- Other LANL or subcontract personnel identified as being required to conduct storm water assessments as part of their job duties.

In addition to training to this procedure, the following training is also required prior to performing this procedure:

• ENV-RCRA QAPP-MSGP Quality Assurance Project Plan for the Storm Water Multi-Sector General Permit for Industrial Activities

The training method for this procedure is "self-study" (required read). For ENV-RCRA staff, this is documented in accordance with <u>ENV-DO-QP-115</u>, *Personnel Training*. Other participating groups may require training documentation pursuant to local procedures.

Actions specified within this procedure, unless preceded with "should" or "may", are to be considered mandatory (i.e., "shall", "will", "must").

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 5 of 23
	Effective Date: February 28, 2	2013

3.1 ROLES AND RESPONSIBILITIES

3.1.1 ENV-RCRA MSGP STORM WATER TEAM

ENV-RCRA MSGP Storm Water Team members will be fully knowledgeable of the specific regulatory requirements identified in the 2008 MSGP and are responsible for ensuring compliance with these requirements and entering corrective actions. Team members will evaluate corrective actions that the DEPs enter into the ENV-RCRA MSGP Corrective Action Report Findings database and modify them as needed for quality assurance. This team will also periodically review open corrective actions and follow up with the DEPs, ES&H Managers, or Upper Management, as deemed necessary, to ensure close out of the corrective action. The team members will notify upper management of instances of non-compliance with the permit. A team member may also be responsible for responding to the regulatory authority (EPA) regarding identified storm water issues and/or negotiate settlement of any identified issues.

3.1.2 Deployed Environmental Professionals

DEPs will be fully knowledgeable of the site specific Storm Water Pollution Prevention Plan (SWPPP) and corrective action requirements identified in the MSGP for the facilities they are deployed to. In addition, they shall be appropriately trained to meet the job qualifications identified in the *Quality Assurance for Storm Water Multi-Sector General Permit for Industrial Activities Program* (ENV-RCRA-QAPP-MSGP) and shall be familiar with the regulatory requirements identified in the 2008 MSGP. Further, they shall be familiar with facility operations so that potential pollution discharge sources can be determined and corrective actions can be identified.

The DEPs are responsible for identifying and entering corrective actions observed at their industrial facilities into the ENV-RCRA MSGP Corrective Action Report Findings database. They are also responsible for updating corrective actions in a timely manner that cannot be implemented immediately. They will work with the ES&H Manager and ENV-RCRA storm water personnel to ensure identified corrective actions are implemented by overseeing repairs and/or improvements or instituting additional controls. If it is determined that corrective actions are necessary following an assessment, any modification to the control measures must be made before the next storm event if possible, or as soon as practicable following that storm event.

NOTE: These time intervals are not grace periods, but are schedules considered reasonable for documenting your finding(s) and for making repairs and improvements. They are included in the MSGP Permit to ensure that the conditions prompting the need for these repairs and improvements are not allowed to persist indefinitely (see Section 3.3 of the 2008 MSGP). In no instance will the corrective action remain open indefinitely.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 6 of 23
	Effective Date: February 28, 2	2013

3.1.3 ENV-RCRA STORM WATER TEAM LEADER

The ENV-RCRA Storm Water Team Leader is responsible for compliance oversight relative to the 2008 MSGP. The Team Leader will ensure costs needed to implement the regulatory requirements identified in the 2008 MSGP are identified and environmental risks are assessed. Upper management will be notified of these costs or environmental risks, as deemed necessary. In the event there is a dispute regarding the regulatory requirements contained in the MSGP, the Team Leader will make the final determination of the required action. The Team Leader will notify upper management of instances of non-compliance with the permit.

3.1.4 ENV-RCRA GROUP LEADER

The ENV-RCRA Group Leader or designee is responsible for ensuring there is adequate funding to implement the regulatory requirements identified in the 2008 MSGP. The Group Leader also acts as the duly authorized signatory that certifies the reports. The Group Leader will notify upper management of instances of non-compliance with the permit or other identified environmental risk.

3.1.5 ES&H MANAGER

The ES&H manager shall identify funding for their industrial facilities to ensure compliance with the 2008 MSGP. The ES&H Manager is also responsible for ensuring that industrial facilities are complying with the 2008 MSGP permit and notifying upper management of instances of non-compliance with the permit or other identified environmental risk.

3.1.6 FACILITIES OPERATIONS DIRECTOR

The Facilities Operations Director (FOD) provides organizational leadership to ensure that all facility and programmatic activities under their authority are performed in compliance with the 2008 MSGP. The FOD is also responsible for establishing an environmental compliance envelope. It is the FOD's responsibility to maintain trained and qualified Environmental Professionals and Waste Management Coordinators on staff.

3.1.7 Computer Programmer

Maintains and updates the ENV-RCRA MSGP Corrective Action Report Findings database as requested by MSGP storm water personnel.

3.2 Prerequisites

In addition to training to this procedure, the following training is also required prior to performing this procedure:

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 7 of 23
	Effective Date: February 28, 2	2013

• ENV-RCRA QAPP-MSGP, Quality Assurance Project Plan for the Storm water Multi-Sector General Permit for Industrial Activities Program

4.0 DOCUMENT CONTROL/RECORDS MANAGEMENT

The following records generated as a result of this procedure are to be submitted to the designated RM-POC in accordance with ENV-DO-QP-110, *Records Management* and filed in project files.

- MSGP Comprehensive Site Inspection Annual Report
- Completed Routine Inspection Forms
- Electronic records within the ENV-RCRA MSGP Corrective Action Report Findings database.
- Copies of automated e-mail notifications

5.0 WORK PROCESSES

5.1 IDENTIFYING CORRECTIVE ACTIONS

If any of the following conditions occur, the DEP or ENV-RCRA storm water team member must review and revise the selection, design, installation, and implementation of control measures to ensure that the condition is eliminated and will not be repeated in the future:

- An unauthorized release or discharge (e.g., spill, leak, or discharge of non-storm water not authorized by the 2008 MSGP);
- You become aware, or EPA determines, that your control measures are not stringent enough for the discharge to meet applicable water quality standards;
- An inspection or evaluation of the facility by an EPA official and/or local or State entity, determines that modification to the control measures are necessary to meet the nonnumeric effluent limits in the 2008 MSGP;
- You find in the routine facility inspection, quarterly visual assessment, or comprehensive site inspection that the control measures are not being properly operated and maintained;
- Construction or a change in design, operation, or maintenance at the facility significantly changes the nature of pollutants discharged in storm water from the facility, or significantly increases the quantity of pollutants discharged; or
- The average of four quarterly sampling results exceeds an applicable benchmark. If less than four benchmark samples have been taken, but the results are such that an exceedence of the four quarter average is mathematically certain, (i.e., if the sum of quarterly sample results to date is more than four times the benchmark level) this is considered a benchmark exceedence, triggering this review;
- If effluent limitation guidelines are exceeded at the Asphalt Batch Plant (Sector D); or
- If impaired water quality standards are exceeded.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 8 of 23
	Effective Date: February 28, 2	2013

5.2 ROUTINE INSPECTIONS

Routine inspections shall be conducted by the DEP (or a qualified member if the DEP is not trained and qualified) at all areas of the facility where industrial materials or activities are exposed to storm water, and of all storm water control measures used to comply with the effluent limits contained in the 2008 MSGP. Routine inspections shall be conducted at least quarterly; however, some facilities conduct monthly inspections (as specified in the facility specific SWPPP). Routine inspections shall be conducted during periods when the facility is in operation. A certified copy of completed Routine Inspection Forms shall be maintained in the facility's SWPPP.

At least once each calendar year, the routine facility inspections must be conducted during a period when a storm water discharge (either rain or snow) is occurring. The DEP(s) or storm water personnel from ENV-RCRA are responsible for identifying and entering corrective actions observed during the routine inspections into the ENV-RCRA MSGP Corrective Action Report Findings database. The database is set up to allow access for all identified DEPs associated with a particular FOD if the FOD has more than one DEP. Contact a member of the ENV-RCRA storm water team if you do not have access to this database and the FOD has assigned you responsibility for MSGP corrective actions.

NOTE: If the industrial facility is inactive and unstaffed and there are no industrial materials or activities exposed to storm water, routine inspections may not be required. A determination of whether a facility is inactive or unstaffed shall be made in coordination with storm water personnel from ENV-RCRA as there are specific documentation and certification requirements that have to be met prior to discontinuing routine inspections.

5.3 COMPREHENSIVE INSPECTIONS

Qualified ENV-RCRA storm water personnel will conduct one comprehensive inspection of all industrial facilities and those that meet the "no exposure" criteria subject to the 2008 MSGP before September 29th of each year. At least one member of the facility's storm water pollution prevention team shall participate in this inspection. This is usually the DEP.

This inspection must cover all areas of the industrial facility affected by the requirements in the 2008 MSGP including the areas identified in the SWPPP as potential pollutant sources where industrial material or activities are exposed to storm water, areas where control measures are used to comply with the effluent limits, and areas where spills and leaks have occurred in the past 3 years. The inspector must include review of the monitoring data (analytical results from benchmark and impaired waters and visual assessments) collected that calendar year as part of the comprehensive inspection. Inspectors must examine the following at a minimum:

- Industrial materials, residue, or trash that may have or could come into contact with storm water;
- Leaks or spills from industrial equipment, drums, tanks, and other containers;

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 9 of 23
	Effective Date: February 28, 2	2013

- Offsite tracking of industrial or waste materials, or sediment where vehicles enter or exit the site;
- Tracking or blowing of raw, final, or waste materials from areas of no exposure to exposed areas; and
- Control measures needing replacement, maintenance, or repair.
- Storm water controls measures required by the 2008 MSGP must be observed to ensure that they are functioning correctly.

NOTE: The annual comprehensive site inspection may also be used as one of the routine inspections, as long as all components of both types of inspections are included.

ENV-RCRA will then enter all identified corrective actions into the ENV-RCRA MSGP Corrective Action Report Findings database. It is the responsibility of the DEP to update the database to reflect updates to these corrective actions.

Information compiled during the comprehensive inspection is used to complete the Annual Report. This report shall be submitted to EPA (postmarked) within 45 days of the last facility inspection completed in September of each year. For example, if the last facility was inspected (as part of the comprehensive site inspection) on September 22, the report shall be postmarked before or on November 6th. A complete certified copy of the Annual Report shall be maintained in the facility's SWPPP.

5.4 SPILLS

All leaks or spills shall be cleaned up immediately and entered into the ENV-RCRA MSGP Corrective Action Report Findings database. This can be done by either the DEP or an ENV-RCRA MSGP storm water team member. If the spill is immediately cleaned up, and controls are put in place to prevent further leakage, the corrective action can be closed.

5.5 ALLOWABLE NON-STORM WATER DISCHARGES

The following are allowable non-storm water discharges authorized by the 2008 MSGP:

- Discharges from fire-fighting activities;
- Fire hydrant flushing;
- Potable water, including water line flushings;
- Uncontaminated condensate from air conditioners, coolers, and other compressors and from the outside storage of refrigerated gases or liquids;
- Irrigation drainage;
- Landscape watering provided all pesticides, herbicides, and fertilizer have been applied in accordance with the approved labeling;
- Pavement wash waters where no detergents are used and no spills or leaks of toxic or hazardous material have occurred (unless all spilled material has been removed);

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 10 of 23
	Effective Date: February 28, 2	2013

- Routine external building washdown that does not use detergents; and
- Uncontaminated ground water or spring water.

Any person authorized to conduct work at LANL can identify a potential storm water issue. If this occurs, they should contact the DEP or an ENV-RCRA MSGP storm water team member who will determine if a corrective action is needed.

5.6 ENTERING CORRECTIVE ACTIONS

To enter a corrective action into the ENV-RCRA MSGP Corrective Action Report Findings database, perform the following steps:

NOTE: Be clear and concise, use correct grammar and punctuation, and correct any spelling errors. This information will be used to populate a report that will be submitted to the EPA. Therefore, it is critical that all information entered into the ENV-RCRA MSGP Corrective Action Report Findings database is correct and meets these criteria.

Step	Action
1	From this web page:
	http://int.lanl.gov/environment/water/guidance/swmgp.shtml, under the heading "Compliance Tools". Click on the link "MSGP Corrective Action Report Findings Database" Click on "Enter New Corrective Action."
2	 Under the "Corrective Action Header" tab, enter the following: Facility Name by clicking on the "List" tab and selecting a facility. Date Problem was Identified (mm/dd/yyyy) Date of Notification to ENV-RCRA (mm/dd/yyyy) FOD Responsible for CA (Name & Org) by clicking in the box. FOD designations (for example "STO") and the associated name will come up. Just select the appropriate FOD. NOTE: Contact the MSGP Project Leader at 667-1312 or
	hbensen@lanl.gov if the FOD name or organization is incorrect, so this can be corrected.
	 Describe Specific Evaluation Location (for example "Northeast corner of Building TA-3-66") Inspector Z-Number by clicking in the box, which will populate it with your Z number. In most instances, the DEP should be identified as the inspector. Note: If you are entering the CA and are not the DEP, you will have to enter the DEP's Z number or they will not have the ability to update the corrective action.
	Once all of the above information is entered correctly, click "Save" and go

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 11 of 23
	Effective Date: February 28, 2	2013

	to Step 3. All boxes identified with a red asterisk are "required fields" and shall be filled out. Note: The system will automatically assign a Corrective Action Report ID number.
3	Click "Go To Corrective Action Details" in the middle of the screen.
	Under the "Corrective Action Details" tab, enter the following:
	 Identify the condition triggering the need for this review by clicking on the "List" tab and selecting an option or selecting "Other" and entering a description of the condition. Briefly describe the nature of the problem identified during the inspection (e.g., erosion, damage to a BMP, trash, spill, etc.) and the specific evaluation location.
	NOTE: Spills or other emergency situations may identify the need for a corrective action that was not identified during an inspection.
	 How the problem was identified by clicking on the "List" tab and selecting an option or selecting "Other" and entering a description of the problem. Description of the corrective action taken, or to be taken, to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, the basis for that determination. Did/will the corrective action require modification of your SWPPP. Type in "Y" for yes and "N" for no. Date Corrective action was initiated (mm/dd/yyyy) Date corrective action was completed OR expected completion date (mm/dd/yyyy) NOTE: If the corrective action has not been completed, enter an expected completion date. Do not put a date in both locations.
	If the corrective action has not been completed, provide the status of the corrective action and describe any remaining steps (including timeframes associated with each step) necessary to complete the corrective action.
	NOTE: This should only be filled out if the corrective action has not been completed. If the corrective action has been completed, enter "N/A."
	Make sure to hit the "save" tab in the bottom right hand corner so the corrective action information is retained. If you want to enter more corrective actions, go back to the "Corrective Action Header" tab and press the "Enter New Corrective Action" button in the lower left hand corner of the screen (see step #2). Hitting the "Exit" button will cause you to exit from the system.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 12 of 23
	Effective Date: February 28, 2	2013

All boxes identified with a red asterisk are "required fields" and shall be
filled out. If a date is not included or identified as an expected completion
date, ENV-RCRA storm water compliance personnel will enter a
completion date of 30 days after the corrective action was identified.
-

5.7 UPDATING CORRECTIVE ACTIONS

To update a corrective action in the ENV-RCRA MSGP Corrective Action Report Findings database, perform the following steps:

Step	Action
1	From this web page: http://int.lanl.gov/environment/water/guidance/swmgp.shtml , under the heading "Compliance Tools". Click on the link " MSGP Corrective Action Report Findings Database " to access the database and tab down to the corrective action number you want to edit. Click on "Edit."
2	Navigate to the blank that you will be changing and input the updated information. It is anticipated that most changes will occur relative to updating the status of corrective actions. Save all changes to the information. Remember, you should only have a date under "Date corrective action completed OR the "expected to be completion," but not both.

5.8 VALIDATING CORRECTIVE ACTIONS

ENV-RCRA storm water personnel will periodically validate the information contained in the ENV-RCRA MSGP Corrective Action Report Findings database. To validate a corrective action in the ENV-RCRA MSGP Corrective Action Report Findings database, perform the following steps:

Step	Action
1	From this web page:
	http://int.lanl.gov/environment/water/guidance/swmgp.shtml, under the
	heading "Compliance Tools". Click on the link "MSGP Corrective Action
	Report Findings Database" to access the database.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 13 of 23
	Effective Date: February 28, 2	2013

2	Check all entered fields for a corrective action to ensure that all information is clear, correct, and concise. If not, correct the information by navigating to the information that needs to be changed and making the change. Save
	all changes to the information. All information shall be validated before running the final annual report.
3	For ENV-RCRA storm water personnel only, under "status" select "void" if the corrective action is a repeat of a previous corrective action or if it is determined not to be a corrective action. This will delete the corrective action from the annual report.

5.9 INSTITUTIONAL PERFORMANCE FEEDBACK AND IMPROVEMENT TRACKING SYSTEM (PFITS)

PFITS is the institutional performance and tracking system for identified issues. A corrective action that meets any of the following criteria will be entered into the PFITS system, as deemed necessary.

- Corrective action was not completed by the expected completion date entered into the database.
- No action was taken to remedy an identified issue with a control measure within 14 days of discovery or before the next storm event or as soon as practicable following that storm event (Section 3.3 of the 2008 MSGP).
- Repeat corrective actions or trends identified by ENV-RCRA MSGP storm water personnel.
- Conditions requiring immediate action, where failure to take action would result in
 pollutants being released to water of the state or an immediate non-compliance with the
 2008 MSGP.
- Violations identified by the regulatory authority.
- Other issues as deemed necessary by MSGP storm water personnel.

Once every month, ENV-RCRA storm water personnel will evaluate a summary of open corrective actions in the ENV-RCRA MSGP Corrective Action Report Findings database and using the above criteria will determine which corrective actions, if any, should be transferred into PFITS. When the monthly notification of outstanding corrective actions is sent out, evaluate whether any of the outstanding corrective actions meet the above conditions. Send those that do to the Environmental Protection Division's Improvement Management Coordinator (IMC) so that she can enter the information into PFITS. The summary report will contain the following information, at a minimum:

- Date the corrective action was identified;
- Person that identified the corrective action;

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 14 of 23
	Effective Date: February 28, 2	2013

- A description of the nature of the problem identified and what needs to be done to address the corrective action.
- Whether the corrective action was identified internal to LANL or External to LANL.

5.10 NOTIFICATIONS FOR NEW AND OVERDUE CORRECTIVE ACTIONS

When a new corrective action is entered into the ENV-RCRA MSGP Corrective Action Report Findings database, the FOD, ESH&Q Manager, Operations Manager, inspector (usually the DEP) and ENV-RCRA MSGP storm water personnel are notified automatically by e-mail (unless the corrective action is closed the same day it is entered). This will assist the FOD, ESH& Q Managers, Operations Managers and the DEPs with keeping track of new corrective actions.

An automatic e-mail is sent the first of each month notifying the FOD, ESH&Q Manager, Operations Manager and DEPs of all overdue corrective actions for their industrial facilities. The Environmental Protection Division Leader and ENV-RCRA Group Leader receive a web link that contains a bar graph showing corrective actions 30 to 60 days overdue, 60 to 90 days overdue, 90 days to 1 year overdue, and those greater than a year overdue. In addition, they receive a link with summary information on each corrective action overdue sorted by FOD.

6.0 REFERENCES

- Federal Register: Final National Pollutant Discharge Elimination System (NPDES) General Permit for Storm Water Discharges from Industrial Activities. Federal Register: September 29, 2008, Volume 73, Number 189.
- P300, Integrated Work Management
- P315, Conduct of Operations Manual
- PD103, Worker Safety and Health Policy
- <u>SD100, Integrated Safety Management System Description Document with Embedded 10 CFR 851</u> <u>Worker Safety and Health Program</u>
- P101-18, Procedure for Pause/Stop Work
- PD410, Los Alamos National Laboratory Environmental ALARA Program
- P121, Radiation Protection
- ENV-DO QP-106, Document Control
- ENV-DO-QP-115, Personnel Training
- ENV-DO-QP-104, Work Safety Review

In addition to these documents, please read any site specific requirements before proceeding with work.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 15 of 23
	Effective Date: February 28, 2	2013

7.0 **DEFINITIONS**

<u>Best Management Practice (BMP):</u> Schedules of activities, prohibitions of practices, maintenance procedures, and other management practices to prevent or reduce the pollution of "waters of the United States." BMPs also include treatment requirements, operating procedures, and practices to control plant site runoff, spillage or leaks, sludge or waste disposal, or drainage from raw material storage. (40 CFR Part 122.2)

<u>Control Measure:</u> Any BMP or other method (including effluent limitations) used to prevent or reduce the discharge of pollutants to waters of the United States.

CA: Corrective Action

DEP: Deployed Environmental Professional

EPA: Environmental Protection Agency

FOD: Facility Operations Director

MSGP: Multi-Sector General Permit

SWPPP: Storm Water Pollution Prevention Plan

8.0 ATTACHMENTS

Attachment 1- Annual Reporting Form

Attachment 2- NPDES Multi-Sector General Permit Routine Inspection Form

Click here for "Required Read" credit.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 16 of 23	
	Effective Date: February 28, 2013		

ATTACHMENT 1- ANNUAL REPORTING FORM

NPDES Permit Tracking No.:
SEPA United States Environmental Protection Agency Washington, DC 20460
Annual Reporting Form
A. GENERAL INFORMATION
1. Facility Name:
2. NPDES Permit Tracking No.:
3. Facility Physical Address:
a. Street
b. City. c. State: d. Zip Code:
4. Lead Inspectors Name:
Additional Inspectors Name(s):
5. Contact Person:
Phone:
8. Inspection Date:
B. GENERAL INSPECTION FINDINGS
1. As part of this comprehensive site inspection, did you inspect all potential pollutant sources, including areas where industrial activity may be exposed to stormwater?
If NO, describe why not:
NOTE: Complete Section C of this form for each industrial activity area inspected and included in your SWPPP or as newly identified in B.2 or B.3 below where pollutants may be exposed to stormwater.
2. Did this inspection identify any stormwater or non-stormwater outfalls not previously identified in your SWPPP?
If YES, for each location, describe the sources of those stormwater and non-stormwater discharges and any associated control measures in place:

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 17 of 23
	Effective Date: February 28, 2013	

NPDES Permit Tracking No.:
3. Did this inspection identify any sources of stormwater or non-stormwater discharges not previously identified in your SWPPP?
If YES, describe these sources of stormwater or non-stormwater pollutants expected to be present in these discharges, and any control measures in place:
4. Did you review stormwater monitoring data as part of this inspection to identify potential pollutant hot spots?
If YES, summarize the findings of that review and describe any additional inspection activities resulting from this review:
in 1 E.S., Sallinia E.S. of that Color and describe any additional impection addition resulting nonlinear solution.
5. Describe any evidence of pollutants entering the drainage system or discharging to surface waters, and the condition of and around outfalls, including flow dissipation measures to prevent scouring:
6. Have you taken or do you plan to take any corrective actions, as specified in Part 3 of the permit, since your last annual report submission (or since you received
authorization to discharge under this permit if this is your first annual report), including any corrective actions identified as a result of this annual comprehensive site inspection? YES
If YES, how many conditions requiring review for correction action as specified in Parts 3.1 and 3.2 were addressed by these corrective actions?
NOTE: Complete the attached Corrective Action Form (Section D) for each condition identified, including any conditions identified as a result of this comprehensive stormwater inspection.

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 18 of 23	
	Effective Date: February 28, 2013		

NPDES	Permit Ti	racking N	o.:	
I I I				
			_	

C. INDUSTRIAL ACTIVITY AREA SPECIFIC FINDINGS				
Complete one block for each industrial activity area where pollutants may be exposed to stormwater. Copy this page for additional industrial activity areas.				
In reviewing each area, you should consider: Industrial materials, residue, or trash that may have or could come into contact with stormwater; Leaks or spills from industrial equipment, drums, tanks, and other containers; Offsite tracking of industrial or waste materials from areas of no exposure to exposed areas; and				
Tracking or blowing of raw, final, or waste materials from areas of no				
INDUSTRIAL ACTIVITY AREA:				
1. Brief Description:				
2. Are any control measures in need of maintenance or repair?	☐ YES	□NO		
3. Have any control measures failed and require replacement?	☐ YES	□ NO		
4. Are any additional/revised control measures necessary in this area?	☐ YES	□NO		
If YES to any of these three questions, provide a description of the problem: Corrective Action Form)	(Any neces	ssary corrective actions should be described on the attached		
INDUSTRIAL ACTIVITY AREA:				
1. Brief Description;				
1. Brief Description:				
2. Are any control measures in need of maintenance or repair?	☐ YES	□NO		
3. Have any control measures failed and require replacement?	YES	□ NO		
4. Are any additional/revised c necessary in this area?	☐ YES	□ NO		
If YES to any of these three questions, provide a description of the problem:		_		
Corrective Action Form)	(rally lieces	sally corrective actions should be described on the attached		
INDUSTRIAL ACTIVITY AREA:				
Brief Description:				
2. Are any control measures in need of maintenance or repair?	☐ YES	□NO		
3. Have any control measures failed and require replacement?	☐ YES	□NO		
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□NO		
If YES to any of these three questions, provide a description of the problem:	(Any neces	ssary corrective actions should be described on the attached		
Corrective Action Form)				

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 19 of 23
	Effective Date: February 28, 2013	

		NPDI 	ES Permit Ti	racking	No.:	Т
		NOTE: Copy this page and attach ad	Idžional nag	05.057		ean/
INDUSTRIAL ACTIVITY AREA:		NOTE. Copy this page and attach ad	dilonal pag	es es n	reces	sary
1. Brief Description:						
Are any control measures in need of maintenance or repair?	YES	□ио				
3. Have any control measures failed and require replacement?	☐ YES	□NO				
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□ NO				
If YES to any of these three questions, provide a description of the problem: (Any necessary corrective actions should be described on the attached Corrective Action Form)						
INDUSTRIAL ACTIVITY AREA:						
1. Brief Description:						
2. Are any control measures in need of maintenance or repair?	☐ YES	□ NO				
3. Have any control measures failed and require replacement?	☐ YES	□ NO				
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□ NO				
If YES to any of these three questions, provide a description of th Corrective Action Form)	e problem:	(Any necessary corrective actions should be described on the	attached			
INDUSTRIAL ACTIVITY AREA:						
1. Brief Description:						
2. Are any control measures in need of maintenance or repair?	☐ YES	□NO				
3. Have any control measures failed and require replacement?	☐ YES	□NO				
4. Are any additional/revised BMPs necessary in this area?	☐ YES	□NO				
If YES to any of these three questions, provide a description of th Corrective Action Form)			attached			

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2	Page 20 of 23		
	Effective Date: February 28, 2013			

NPD	ES F	Pern	nit T	rac	ckir	1 pr	10.		
1						ı - I			1

Complete this page for each specific condition requiring a corrective action or a review determining that no corrective action is needed. Copy this page for additional corrective actions in seviews. Include both corrective actions that have been initiated or completed since the last annual report, and future corrective actions needed to address problems undersided in this corrective action. The third was not provided in the corrective action in the problem in the corrective action. The third was necessary to complete the corrective actions that had not been completed at the time of your provides. Corrective Action a or or or or or or or	
nage for additional corrective actions for reviews.	D. CORRECTIVE ACTIONS
identified in this comprehensive stormwater inspection. Include an update on any outstanding corrective actions that had not been completed at the time of your previous annual report. 1. Corrective Action #	
2. Is this corrective action: An update on a corrective action from a previous annual report; or An env corrective action? An env corrective action from a previous annual report; or An env corrective action from a previous annual report; or Unauthorized release or discharge Numeric effluent limitation exceedance Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet non-numeric effluent limitations Control measures inadequate to meet non-numeric effluent limitation Control measures inadequate to measures inadequate non-numeric effluent limitation Control measures inadequate to measures inadequ	identified in this comprehensive stormwater inspection. Include an update on any outstanding corrective actions that had not been completed at the time of your
A new corrective action from a previous annual report; or A new corrective action A new corrective action not per completed, provide the status of corrective action not per completed, provide the status of corrective action not per completed, provide the status of corrective action not per completed, provide the status of corrective action not yet completed, provide the status of corrective action not yet completed, provide the status of corrective action not yet completed.	1. Corrective Action # of for this reporting period.
A new corrective action?	2. Is this corrective action:
3. Identify the condition(s) triggering the need for this review: Unauthorized release or discharge Numeric effluent limitation exceedance Control measures inadequate to meet applicable water quality standards Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe): 4. Briefly describe the nature of the problem identified: 5. Date problem identified: Comprehensive site inspection Outsterly visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe): The problem of corrective action (s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination: 9. Didd/will this corrective action require modification of your SWPPP? YES NO 9. Date corrective action initiated: / / / / / / / / /	☐ An update on a corrective action from a previous annual report; or
Unauthorized release or discharge Numeric effluent limitation exceedance Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet non-numeric effluent limitations Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe):	A new corrective action?
Numeric effluent limitation exceedance Control measures inadequate to meet applicable water quality standards Control measures inadequate to meet non-numeric effluent limitations Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe) Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe) Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe) Change in facility operations necessitated change in control measures Change in facility operations necessitated change in control measures Change in facility operations necessitated change in control measures Change in facility operations necessarily operations necessarily operations necessarily operations necessarily necessarily operations necessarily ne	3. Identify the condition(s) triggering the need for this review:
Control measures inadequate to meet applicable water quality standards Control measures and equate to meet non-numeric effluent limitations Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe): 4. Briefly describe the nature of the problem identified: 5. Date problem identified: Comprehensive site inspection Country visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe): 7. Description of corrective action(s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination: 8. Did/will this corrective action require modification of your SWPPP? YES NO 9. Date correction action completed: 10. Date correction action completed: 11. If corrective action not yet completed: 11. If corrective action not yet completed: 11. If corrective action not yet completed: 11. If corrective action not yet completed: 11. If corrective action not yet completed: 11. If corrective action not yet completed, provide the status of corrective action and describe any remaining steps	☐ Unauthorized release or discharge
Control measures inadequate to meet non-numeric effluent limitations Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe): 4. Briefly describe the nature of the problem identified: 5. Date problem identified: Comprehensive site inspection Counterly visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe): 7. Description of corrective action (s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination: 8. Did/will this corrective action require modification of your SWPPP? YES NO S. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 7. Date corrective action initiated: 8. Did/will this corrective action initiated: 9. Did/will this corrective action not yet completed: 9. Did/will this corrective action not yet completed: 9. Did/will this corrective action not yet completed: 9. Did/will this corrective action and describe any remaining steps	☐ Numeric effluent limitation exceedance
Control measures not properly operated or maintained Change in facility operations necessitated change in control measures Average benchmark value exceedance Other (describe);	☐ Control measures inadequate to meet applicable water quality standards
Change in facility operations necessitated change in control measures	☐ Control measures inadequate to meet non-numeric effluent limitations
Average benchmark value exceedance Other (describe):	☐ Control measures not properly operated or maintained
Other (describe):	☐ Change in facility operations necessitated change in control measures
4. Briefly describe the nature of the problem identified: 5. Date problem identified: 6. How problem was identified: Comprehensive site inspection Quarterly visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe): 7. Description of corrective action(s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination: 8. Did/will this corrective action require modification of your SWPPP? YES NO 9. Date corrective action initiated: 7. If corrective action not yet completed: 7. If corrective action not yet completed: 7. If corrective action not yet completed, provide the status of corrective action at the time of the comprehensive site inspection and describe any remaining steps	Average benchmark value exceedance
5. Date problem identified:	Other (describe):
6. How problem was identified: Comprehensive site inspection Quarterly visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe): 7. Description of corrective action(s) taken or to be taken to eliminate or further investigate the problem (e.g., describe modifications or repairs to control measures, analyses to be conducted, etc.) or if no modifications are needed, basis for that determination: 9. Did/will this corrective action require modification of your SWPPP? YES NO 9. Date corrective action initiated: / /	4. Briefly describe the nature of the problem identified:
9. Date corrective action initiated:	6. How problem was identified: Comprehensive site inspection Quarterly visual assessment Routine facility inspection Benchmark monitoring Notification by EPA or State or local authorities Other (describe):
	9. Date corrective action initiated:

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2 Page 21 of 23			
	Effective Date: February 28, 2013			

	NPDES Permit Tracking No.:
E. ANNUAL REPORT CERTIFICATION	
1. Compliance Certification	
Do you certify that your annual inspection has met the requirements of Part 4.2 of the permit, and that, based upon the results your knowledge, you are in compliance with the permit?	of this inspection, to the best of
If NO, summarize why you are not in compliance with the permit:	
2. Annual Report Certification	
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordan assure that qualified personnel properly gathered and evaluated the information submitted. Sased on my inquiry of the person or system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowle and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and violations.	r persons who manage the edge and belief, true, accurate,
violations.	
Authorized Representative Title: Title:	
Signature: Date Signed:	

Title: MSGP Storm Water Corrective Actions	No. ENV-RCRA-QP-022.2 Page 22 of 23		
	Effective Date: February 28, 2013		

ATTACHMENT 2- NPDES MULTI-SECTOR GENERAL PERMIT ROUTINE INSPECTION FORM

Los Alamos National Laboratory ENV-RCRA						NPDES Multi-Sector General Permit Routine Inspection Form (rev. 03/2009) Page 1 of (use additional sheets if necessary)
Name of Facility: Resp			Responsible	e FOD (Name & Organization):		
Qualified Inspector(s): Others Present: Inspection		Inspection t	ype: Quarterly Other	Date of inspection (MM/DD/YYYY):		
						Time of inspection:
Weather: Clear Cloudy Rain Sleet Fog Snow High Winds Other: Temperature: °F Is Inspection Being Conducted During a Storm Water Discharge? Yes No					Water Discharge? □Yes □No	
# Structural Control Measures (BMP)s	Location	Operating Effectively (Yes or No)?	Maintain	Need to (M), Repair place (RP)?	Corrective Action Needed and Note measures that need replacement)	es (identify needed maintenance and repairs, or any failed control
1.						
2.						
3.						
4. 5.					-	
6.						
7.						
8.						
9.					1	
10.						
11.					1	
12						
Were additional BMPs or Control Measures Were previously identified conditions correct					s 🗆 No If No, describe reason:	
Area/Activity (Areas of Industrial Materials or Activities Exposed to Storm Water)	Inspected?	Controls Adequate?	Correcti	ve Action Need	ed and Notes (List area letter with commo	ents below)
Material loading/unloading & storage						
B. Equipment operations & maintenance areas			1			
C. Fueling Areas			1			
D. Outdoor vehicle & equipment washing	—		1			
areas	1					
E. Waste Handling & disposal areas]			
F. Erodible areas / construction						
 G. Non-storm water / illicit connections 						
 H. Salt storage piles or pile containing salt 			1			
 Dust generation & vehicle tracking 						
Are the SWPP Plan maintenance, schedules	and procedure	es being impler	nented at	the facility?	☐ Yes ☐ No	
Were any Corrective Actions initiated or con	Were any Corrective Actions initiated or completed? ☐ Yes ☐ No Describe:					
Are there any conditions requiring Corrective (Note – need a Corrective Action Form for e		Yes □ No I	Yes, Lis	t Number of C	corrective Actions Required	

	Effective Date: February 28, 2013		
			-
Los Alamos National Laboratory ENV-RCRA	Non-Compliance	NPDES Multi-Sector Ger (rev. 03/2009) Certification	neral Permit Inspection Form n Sheet
Describe any incidents of non-compliance and/or need for corrective	action observed and not described above:		
	Additional Control Measures		
Describe any additional control measures needed to comply with the	permit requirements:		
	Notes		
Use this space for any additional notes or observations from the insp	ection:		
Inspector's Signature and date:			
"I certify under penalty of law that this document and all attachmen personnel properly gathered and evaluated the information submitte gathering the information, the information submitted is, to the best false information, including the possibility of fine and imprisonment	ed. Based on my inquiry of the person or persons of my knowledge and belief, true, accurate, and	s who manage the system, or t	those persons directly responsible for
Print name and title:			
Signature	Date		

No. ENV-RCRA-QP-022.2

Page 23 of 23

Title: MSGP Storm Water Corrective Actions

EPC-CP-QP-064	Revision: 0
Effective Date: 10/04/2017	Next Review Date: 10/04/2020

Terrill W. Lemke

Michael T. Saladen

Responsible Line Manager:



Environment, Safety, and Health Directorate Environmental Protection and Compliance-Compliance Programs Quality Procedure

MSGP Stormwater Visual Assessments

Document Owner: Name: Organization: Signature: Date: Holly L. Wheeler EPC-CP Signature on File 10-2-17 **Derivative Classifier:** Unclassified or DUSA ENVPRO Name: Organization: Signature: Date: Ellena I. Martinez EPC-CP Signature on File 10-2-17 **Approval Signatures:** Subject Matter Expert: Organization: Signature: Date: Holly L. Wheeler EPC-CP Signature on File 10-2-17 Responsible Line Manager: Organization: Signature: Date:

EPC-CP Team Leader

EPC-CP Acting Group Leader

Organization:

This copy is uncontrolled.

10-4-17

10-4-17

Date:

Users are responsible for ensuring they work to the latest approved version. To document a required read, Login to UTrain, and go to the Advanced Search.

Signature on File

Signature on File

Signature:

MSGP	Stormwater	Visual
Assess	ments	

EPC-CP-QP-064	Page 2 of 20
Revision: 0	Effective Date: 10/04/2017

REVISION HISTORY

Document Number and Revision [Include revision number, beginning with Revision 0]	Effective Date [Document Control Coordinator inserts effective date]	Description of Changes [List specific changes made since the previous revision]
ENV-RCRA-QP-064, R0	7/09	New document MSGP Storm Water Visual Inspections.
ENV-RCRA -QP-064, R1	3/10	Clarifications and added attachments.
ENV-RCRA -QP-064, R2	2/12	Biennial review/revision
EPC-CP-QP-064, R0	10/04/2017	This document replaces ENV-RCRA-QP-064 R2. Converted into new format, and new organization name, clarified steps, updated attachments.

MSGP Stormwater Visual Assessments

EPC-CP-QP-064Page 3 of 20Revision: 0Effective Date: 10/04/2017

Table of Contents

Qual	ity Proced	ure	1
	-	γ	
		, nts	
1.0		ion	_
		oose	
	-	De	
	•	licability	
2.0		ns and Limitations	
3.0		ite Actions	
	•	ning and Coordination	
		ls and Equipment	
4.0	Visual Ass	sessment of Stormwater	6
		umenting Sample Information	
		essing Parameters	
		pleting the Assessment Form	
		pleting the Certification Statement	
5.0		of Stormwater Pollution	
6.0			
7.0	_		
8.0	Definition	ns and Acronyms	12
		nitions	
		pnyms	
9.0		25	
		ents	
		ent 1: Screenshot Examples of EPC-CP-Form-1021 in MC Express	
		ent 2: Crosswalk of EPC-CP-Form-1021 Hard Copy Format to Electronic Format	
		ent 3: Screenshot Examples of Printing from Maintenance Connection	

MSGP Stormwater Visual	EPC-CP-QP-064	Page 4 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

1.0 INTRODUCTION

Los Alamos National Security, LLC (LANS) through Environmental Protection and Compliance-Compliance Programs (EPC-CP) conducts stormwater monitoring activities required pursuant to the National Pollutant Discharge Elimination System (NPDES), Multi-Sector General Permit (MSGP) at Los Alamos National Laboratory (LANL). The MSGP requires LANL to monitor stormwater runoff from industrial sites relative to potential pollutants.

1.1 Purpose

This procedure describes the process for conducting visual assessments of stormwater from outfall locations monitored under the MSGP for industrial facilities at LANL.

Assessments conducted under this procedure should be documented using the Maintenance Connection Express™ (MC Express) web application. (In the event of electronic hardware or web application failure, personnel may use a printed hard copy to conduct inspection and sample retrieval.)

1.2 Scope

Requirements set forth in this document apply to Los Alamos National Laboratory industrial facilities covered by the MSGP. These facilities include, a warehouse, several metal fabrication areas/shops, a heavy equipment yard, an asphalt batch plant, roads and grounds, a foundry, a power plant, a material recycling facility, a carpenter shop, and several hazardous waste treatment, storage or disposal (TSD) facilities. Inspection waivers may be granted by EPC-CP for adverse weather conditions and unstaffed or inactive sites.

At least once each MSGP monitoring quarter a stormwater sample must be collected from each discharge point covered by the MSGP and site specific SWPPP and visually inspected for water quality characteristics. Stormwater samples can be collected with an automated sampler, single stage sampler, or by taking a grab sample.

1.3 Applicability

This procedure applies to the EPC-CP technical staff and subcontractor personnel (as applicable) who conduct stormwater visual assessments during or after measurable storm events at MSGP outfalls.

Note: A measurable storm event is identified as one what results in an actual discharge from your site that follows the preceding measurable storm event by at least 72 hours (3 days).

2.0 PRECAUTIONS AND LIMITATIONS

Hazards in the work described in this procedure are controlled through site specific Integrated Work Documents (IWDs). The hazard level for the activities described in this procedure is <u>low</u>, however the cumulative hazard rating for activities described in the IWD is <u>moderate</u>.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 5 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Assessments may be discontinued during periods or conditions that make sites dangerous for worker safety or prevent personnel from safely accessing sites (e.g., weather-related events such as flash floods, flooding, lightning, wildfires, hail, icy roads, deep snow, or LANL operations such as firing shots or burns).

Click the "Save" bar after all entries for a task line have been completed and before proceeding to the next question. Failure to "Save" results in lost data entries.

Some terminology varies between the MC Express software and the Maintenance Connection desktop software.

- The "Reading" field in MC Express is the same field as "Reading Final" in Maintenance Connection desktop and "Meas." on a hard copy (printed) work order.
- The "Complete" option in MC Express is the same as a "Yes" answer; the "Failed" option in MC Express is the same as a "No" answer. Maintenance Connection desktop and hard copy (printed) work orders use "Yes" and "No" terminology.

Throughout this procedure the field inspector should document comments and notations in the "Reading" field of the associated task line. Any additional comments not documented in a "Reading" field can be entered in the "Comments" field of the same task line. If the inspector needs more space, additional comments can be entered in the "Labor Report Update" field (see Section 4.3) when the work order is updated to "Complete" status.

3.0 PREREQUISITE ACTIONS

3.1 Planning and Coordination

- 1. Schedule work to be completed by the target date appearing on the work order(s) or as requested by the MSGP Program Lead if a form is not issued.
- 2. Inform (e.g., by e-mail) Facility contacts, as specified in the IWD, of the schedule for inspection work and locations up to a week (preferred) before but no later than the day before (for minor changes) to be added to the appropriate plan of the day.

Note: For some Facility Operations Divisions (FODs) like the Utilities and Institutional Facilities FOD, MSGP stormwater monitoring activities are on a standing plan of the day. However, this must be requested each year at the beginning of the monitoring season.

- 3. The IWD Part II (2101 Form) addresses specific requirements and training for FODs.
- 4. Obtain any necessary additional paperwork before conducting this work, including IWD's, and excavation permits (as necessary).
- 5. Gather the required equipment (see section below) for the work to be done.
- 6. Using the Safari web browser on a tablet or notebook style computer, navigate to http://express.maintenanceconnection.com and select English from the available dropdown menu.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 6 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

- 7. Log into the MC Express application using your login credentials. Contact the MSGP Data Management Team if MC Express generates any message stating the field inspector does not have access.
- 8. Confirm that the work order list displayed in the "My Open Work Orders" section matches your sites. If work orders are not displayed, click the "Refresh" bar at the bottom of the page. The page will refresh and any work orders issued since you logged in will be loaded to the application. If the work order lists still do not match, contact the MSGP Data Management Team for clarification.
- 9. Ensure that field personnel have access to accurate time measurement at the Site. When at the site, the clock time on the ISCO sampler must be set to Mountain Standard Time at all times, with no daylight saving time adjustment.

3.2 Tools and Equipment

Ensure the following equipment is available in the field vehicle:

- Safety glasses with side shields
- Nitrile gloves
- Sturdy hiking boots or steel toed shoes with soles that grip
- Cell phone (only government cell phones with batteries removed are allowed in secure areas)
- Copy of this procedure
- Copy of the Integrated Work Documents (IWDs)
- Copy of the MSGP Sampling and Analysis Plan
- Site Map(s) (as needed)
- Current electronic or paper inspection form EPC-CP-Form-1021, MSGP Stormwater Visual Assessments
- Necessary access and station keys
- Clean replacement sample bottles (clear glass or clear poly)
- Paper Towels

4.0 VISUAL ASSESSMENT OF STORMWATER

1. Take the sample bottle with water out of automated sampler or single stage jar off the ground, or fill a clear sample bottle with a grab sample and wipe off exterior.

Note: If a grab sample is collected it shall be collected during daylight hours in a wide mouth clear glass bottle or plastic container within 30 minutes of discharge from a storm event.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 7 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

- 2. In MC Express, open the work order issued for the current location by clicking on the appropriate line. If needed, use the expand arrow located on the right side of the display to expand the work order detail information. The work order will open in the display to the work order Summary page.
- 3. Click on the "Tasks" bar to navigate to the work order Tasks page. See MC Express screen shot example in Attachment 1 and a hard copy example in Attachment 2.

4.1 Documenting Sample Information

4. **Item 1**: Verify the monitoring period by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the monitoring period (e.g., Apr-May, Jun-Jul, Aug-Sep, Oct-Nov).

Note: If the discharge collected is from a rain event from the previous monitoring period but the visual assessment is made in the following monitoring period, document monitoring period on the inspection to correspond to the period in which the rain event took place.

CAUTION

Click the "Save" bar after all entries for a task line have been completed and before proceeding to the next question. Failure to "Save" results in lost data entries.

Note: Any additional comments not documented in a "Reading" field can be entered in in the "Comments" field of the same task line. If the inspector needs more space additional comments can be entered in the "Labor Report Update" field.

- 5. Item 2: Verify the visual assessment is performed on an unfiltered sample and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If the sample was filtered, conduct the visual assessment and document "Filtered sample".
- 6. Item 3: Verify the date and time stormwater discharge began and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".

Enter the date and time in the following date formats: MM/DD/YY, or MM-DD-YY. Time must be entered in 24-hr format.

Note: If the discharge date/time is not available (e.g. precipitation report) when the visual is performed in the field, leave this Task Line incomplete and complete when the information is available.

7. Item 4: Verify the date and time the sample was collected and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".

Enter the date and time in the following date formats: MM/DD/YY, or MM-DD-YY. Time must be entered in 24-hr format.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 8 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Note: If the collection date/time is not available (e.g. precipitation report) when the visual is performed in the field, leave this Task Line incomplete and complete when the information is available.

- 8. Item 5: Verify the date and time stormwater was visually assessed and document by clicking on the right side of the task line and changing the "Complete" or "Failed" line to "Yes".
 - Enter the date and time in the following date formats: MM/DD/YY, or MM-DD-YY. Time must be entered in 24-hr format.
- 9. Item 6: Verify the nature of the discharge and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the discharge (e.g., rainfall or snowmelt) and the TOTAL amount of precipitation from the event.

Note: If the total amount of precipitation is not available (e.g., precipitation report) when the visual is performed in the field, leave this Task Line incomplete and complete when the information is available.

10. Item 7: Verify the sample was collected in the first 30 minutes of discharge and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If it is not possible to collect the sample within the first 30 minutes of discharge, the sample must be collected as soon as practicable after the first 30 minutes. The field inspector will document the reason a sample could not be collected within the first 30 minutes.

4.2 Assessing Parameters

While conducting the visual examinations, personnel should constantly be attempting to relate any pollutant that is observed in the sample to a pollutant source on the site.

Note if there are any potential sources of pollutants on site. If yes, contact an MSGP representative of EPC-CP and document the following:

- Potential sources;
- Indicate if there are any BMPs on site and evaluate and note effectiveness; and
- If no BMPs, determine if installation could correct future pollutant migration.
- 11. Item 8: Verify the color of the discharge in the sample container and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the color.
- 12. Item 9: Verify any odors detected from sample and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the odor (e.g., musty, sewage, sulfur, sour, solvents, petroleum/gas, etc.).

MSGP Stormwater Visual	EPC-CP-QP-064	Page 9 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

- 13. Item 10: Verify the clarity of the discharge and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe the clarity (e.g., slightly cloudy, cloudy, opaque).
 - Clarity can be described as the depth in which you can look into or through water. For example an individual can see through a clear glass of clean water in daylight. Generally the clarity of the water is a good visual indicator of the purity of water. If the water is poor in clarity there is most likely suspended solids throughout the water.
- 14. Item 11: Verify any floating solids and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Careful examination should determine whether the solids are raw materials (e.g., product used to fabricate something, or ingredients used in a formulation) or waste materials (e.g., shavings, woodchips and sawdust, trash). Describe any floating solids observed.
- 15. Item 12: Verify any settled solids in the sample and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe any settled solids observed (e.g., fine, course).
 - Settled solids may be an indicator of unstable ground cover combined with a high intensity stormwater runoff event.
- 16. Item 13: Verify any suspended solids in the sample and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe any settled solids observed (e.g., fine, course).
 - Most often suspended solids include fine sediment. This may be an indication of an unstable channel that may have eroding banks. Some water appears to be colored because of relatively coarse particulate material in suspension such as sediment.
- 17. Item 14: Verify the sample is free of foam and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Gently shake the sample container. Describe any bubbles in or on the surface of the water and the color of the foam.

CAUTION

Contact the EPC-CP Project Leader for MSGP <u>immediately if it is determined that the foam is</u> caused by a pollutant. Follow-up action is required within 24 hours.

18. Item 15: Verify the sample is devoid of any oil sheen and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". If an oil sheen is present, describe the thickness and consistency (e.g., flecks, globs).

MSGP Stormwater Visual	EPC-CP-QP-064	Page 10 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

CAUTION

Contact the EPC-CP Project Leader for MSGP <u>immediately</u>. Then determine the nature of the discharge (rain, snow, hail), the source of the sheen and if existing BMPs are effective in mitigation of potential pollutants or if a new BMP needs to be installed. Follow-up action is required within 24 hours.

- 19. Item 16: Verify the discharge is free of any other indicators of stormwater pollution not described in any other task line above and document by clicking the expand arrow located on the right side of the task line and changing the "Complete" or "Failed" line to "Yes". Describe any observations.
- 20. When all task lines have been completed, click the "Back" arrow button in the upper left hand corner to exit the work order Tasks page and return to the work order Summary page.

4.3 Completing the Assessment Form

- 1. Ensure the inspection form has been filled out completely including information not available during the field inspection (e.g., date/time of discharge, date/time of sample collection, total precipitation amount).
- 3. Click the checkered flag in the upper right corner of the work order Summary page. MC Express auto-populates the date and time fields.

CAUTION

MC Express automatically changes the work order status to "Closed."

- 4. Item 17: Click on the expand arrow located on the right side of the "New Status" field and select "Completed" from the available dropdown menu.
 - Ensure the "Date" field has the date and time the **form was completed**. The completion date and time may be different from the date and time the visual assessment was performed if precipitation information was added to the form after the on-site field inspection.
 - If these fields need to be updated, click the "Date" field to modify it. Make necessary adjustments using the available timestamp application and click "Set" to apply changes.
- 6. Item 18: The inspector must type in his/her name in the "Labor Report Update" field.
 - Any additional notes, observations, or site conditions not documented in a task line "Reading" or "Comments" field can also be documented in the "Labor Report Update" field.
- 7. Scroll down the page to the "Signature" bar and click the expand arrow on the left side of the bar to open the "Signature" field.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 11 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

8. Item 19: Capture an electronic signature by drawing with a finger on the tablet screen. The Lead Inspector is certifying that the information submitted is "true, accurate, and complete" by electronically signing the work order.

Note: If using MC Express on a desktop screen (not a tablet), the mouse must be used to sign electronically.

- 9. Click on the "Save" bar at the bottom of the page to close the "Signature" field.
- 10. Click on the "Back" button located in the upper left hand corner to return to the "My Open Work Orders" page.
- 11. Once you have completed an inspection, click on the Menu button again, and then click the "Logout" bar. Close the browser. All work will automatically upload from the MC Express application to the MC database.

Always log out of MC Express when you have finished work OR if work is interupted.

4.4 Completing the Certification Statement

- Using the Safari web browser on a desktop computer, navigate to
 http://www.maintenanceconnection.com. Log into the MainConn desktop application using your login credentials.
- 2. Click "Open" in the tool bar at the top of the page to open the MainConn module selections. Click on the "Work Orders" module (see Attachment 3).
- 3. Click on the "Search" tab at the top left of the page and enter the work order number in the "Search Value" field. Click the arrow to the right of the "Search Value" field to open the work order in the right split screen.
- 4. Click on the "Report" tab at the top of the page and click the "Work Order Statement" subtab.
- 5. Click the Tools drop down menu in the top right corner of the page and select "Print" from the options. The print dialog box will open. Select the print options as appropriate for your local printer.
- 6. Item 20: Obtain a printed name and title, signature, and date on the certification statement. The visual assessment form must be certified with a signature from a duly authorized representative of the facility as defined in Appendix B of the MSGP Permit, Section B.11.A (e.g., FOD, Operations Manager, DSESH Group Leader, EPC Group Leader). The duly authorized representative of the facility is certifying the information submitted is "true, accurate, and complete" by signing the form.

EPC-CP will send out completed visual assessment forms at the end of each quarter that will contain a certification statement in the cover memorandum. The duly authorized signatory may sign and date this certification statement rather than the certification line associated with each attached form. However, the memorandum and associated completed forms must remain together.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 12 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

7. Place the completed and signed visual assessment into the facility SWPPP.

5.0 EVIDENCE OF STORMWATER POLLUTION

If stormwater contamination is identified through visual assessment personnel should attempt to identify the pollutant source. Personnel should evaluate whether or not BMPs have already been implemented and evaluate whether or not these are working correctly or need maintenance. A design change could also be incorporated into the stormwater pollution prevention plan to eliminate or minimize the contaminant source from occurring in the future. Personnel should evaluate whether or not additional BMPs should be implemented in the pollution prevention plan to address the observed contaminant.

A clean up of the site should be conducted if the pollutant source is known and well defined. The FOD, ESH Manager, and MSGP representative of EPC-CP should also be contacted and made aware of the situation.

Corrective actions **MUST** be taken if BMPs are not performing effectively. Refer to EPC-CP-QP-022, *MSGP Stormwater Routine Facility Inspections and Corrective Actions*.

6.0 TRAINING

The following personnel require training before implementing this procedure:

• EPC-CP technical staff and subcontract or other personnel who retrieve stormwater samples and conduct visual assessments at automated or single stage stormwater samplers for the MSGP.

For EPC-CP staff the training method for this procedure is "self-study" (reading). Other participating groups may require training documentation pursuant to local procedures.

Personnel performing this procedure will be familiar with the most current versions of the following procedures and operation manuals:

• EPC-CP MSGP Sampling and Analysis Plan for the current monitoring year

7.0 RECORDS

Records generated by this document and signed by the EPC-CP certifier will be submitted to the EPC-CP Records Management designated point of contact or document manager in accordance with P1020-1, Laboratory Records Management and with ADESH-AP-006, Records Management Plan.

• EPC-CP-Form-1021, MSGP Quarterly Visual Assessment

All other MSGP Quarterly Visual Assessment forms generated are forwarded to the duly authorized representative of each facility for submittal to that facility's Records Management designated point of contact or document manager.

8.0 DEFINITIONS AND ACRONYMS

See LANL Definition of Terms.

MSGP Stormwater Visual	EPC-CP-QP-064	Page 13 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

8.1 Definitions

Adverse weather conditions – Weather that prohibits collection of samples such as local flooding, high winds, hurricanes, tornadoes, electrical storms, etc. Could also include drought, extended frozen conditions, etc.

Best Management Practices (BMPs) – Schedules of activities, practices, prohibitions of practices, structures, vegetation, maintenance procedures, and other management practices to prevent or reduce pollution. BMPs can also include treatment requirements, operating procedures, and practices to control facility site runoff, spillage or leaks, sludge or waste disposal, or drainage from raw material storage.

Clarity – Clearness or cleanness of appearance. This includes the visual observation of suspended sediment.

Color – Unpolluted water will be clear and colorless. Color should not be confused with clarity.

Floating solids – Particulate material floating on the surface of the water. Examples include: raw or waste materials and common trash.

Foam – An accumulation of fine frothy bubbles formed in or on the surface of water. A mass of bubbles of air in a matrix of liquid film.

Odor – The property or quality of waters that affects or stimulates the sense of smell. Examples of odors that may be present are burnt oil, petroleum hydrocarbon, sewage, diesel, sulfuric, or detergent odors.

Oil sheen – The presence of rainbow-like colors glistening on the surface of a liquid. The color of oil sheen will vary dependent on thickness and consistency.

Settled solids – Settled particulate material i.e., heavier than water. Examples include sand, gravel, metal turnings, and glass.

Suspended solids – Particulate materials that are floating between the bottom of the sample and the surface of the water.

Unstaffed and Inactive Sites – A facility maintaining certification with the SWPPP that it is inactive and unstaffed and visual examinations are not required.

8.2 Acronyms

See LANL Acronym Master List.

EPC-CP	Environmental Protection and Compliance – Compliance Programs
IWD	Integrated Work Document
LANL	Los Alamos National Laboratory
LANS	Los Alamos National Security, LLC
MC Express	Maintenance Connection MC Express web application
MSGP	Multi-Sector General Permit

MSGP Stormwater Visual	EPC-CP-QP-064	Page 14 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

NPDES	National Pollutant Discharge Elimination System
-------	---

9.0 REFERENCES

P1020-1, Laboratory Records Management

ADESH-AP-006, Records Management Plan

EPC-CP-QP-022, MSGP Stormwater Routine Facility Inspections and Corrective Actions

10.0 ATTACHMENTS

Attachment 1: Screenshot Examples of EPC-CP-Form-1021 in MC Express


Attachment 2: Crosswalk of EPC-CP-Form-1021 Hard Copy Format to Electronic Format

Attachment 3: Screenshot Examples of Printing from Maintenance Connection

MSGP Stormwater Visual	EPC-CP-QP-064	Page 15 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Attachment 1: Screenshot Examples of EPC-CP-Form-1021 in MC Express


Page 1 of 3



MSGP Stormwater Visual	EPC-CP-QP-064	Page 16 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Attachment 1: Screenshot Examples of EPC-CP-Form-1021 in MC Express (cont.)

Page 2 of 3



MSGP Stormwater Visual	EPC-CP-QP-064	Page 17 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Attachment 1: Screenshot Examples of EPC-CP-Form-1021 in MC Express (cont.)

Page 3 of 3

Œ		MC Express		
VORK ORDER: tatus Update	MSGP-142	3		
issue	ed			
New Status	17			
Completed				0
<u>Date</u>				
6/28/2017 0	3:12 PM			
Percent Co	mplete 1	00%		
Labor Repo	rt Update	e 18		
Select Comm	ments to Ad	d		0
Jane Admi	n			
5	Cancel	0	Save	
		MC Express		



MSGP Stormwater Visual	EPC-CP-QP-064	Page 18 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Attachment 2: Crosswalk of EPC-CP-Form-1021 Hard Copy Format to Electronic Format $$\sf Page\ 1\ of\ 2$$

Los Alamos National Lab - ADESH				MSGP	Monitor	3P-142	
Mainton	ance Details		Printed 7	7/12/2017 -	10:57 A	M (Dup	licate Cop
Procedu	ed By: Admin, Jane on	ction and Infrastructure	₽ RG12	8 Carpent red Outfal	er Shop	>	
Last PM							
Reason:	Hard Copy MSGP Visual Assessment Example			Admin, Jai 123-4567	ne		
-Tasks							
#	Description			Meas.	No	N/A	Yes
The res	ult of this VA applies to associated SIOs as defined in t	he SWPPP, where app	olicable.				
-	Information				_	_	_
1 30	Document the monitoring Period (e.g., Apr-May) Is visual assessment performed on an unfiltered sample?	(I lee filtered only if unfi	Itered		- 1	18	
35	unavailable.)	(Ose filtered offly if drift	itered				
40	Document the Date/Time Discharge began in the "Reading mm/dd/yy hh:mm format).						
50	Document the Date/time sample collected in the "Reading" field of this line (using mm/dd/yy hh;mm format).						
60	Document the Date/time sample visually assessed in the "Reading" field of this line (using mm/dd/yy hh:mm format).						
70	Document the nature of discharge (e.g., rain, snowmelt). Document the TOTAL amount (in) in the "Reading" field of this line.						
80	Sample collected in first 30 minutes of discharge? If "Failed" or unknown, provide a reason.						
Parame	ters						
110	Is sample colorless? If "Failed", describe.						
120	Is sample oderless? If "Failed", provide description (e.g. m solvent, petroleum/gas)						
0 130	Is sample clear? If "Failed", provide description (e.g., slight						
1 140	Is sample free of floating solids? If "Failed", describe if raw comments of this line.	or waste material(s) in	n the		П		П
2 150	Is sample free of settled solids? If "Failed", provide descrip	otion (e.g., fine, course)).			Til.	
3 160	Is sample free of suspended solids? If "Failed", provide de						
4 170	Is sample foamless after gently shaking? If "Failed" descril (e.g., on the surface' or 'in the sample').						
5 180	Is sample devoid of an oil sheen? If "Failed", describe color and thickness (e.g. flecks,						
6 190	globs). Is sample free of other obvious indicators of pollution? If "F	Failed" describe			-	-6	+
Labor R		,					
-	ted: 6/28/2017 3:23:00 PM						
0	Jane Admin						
9	Jan Adn 1 6/28/2017						
	Signature / Name Date	Signature /	Name			Date	

MSGP Stormwater Visual	EPC-CP-QP-064	Page 19 of 20
Assessments	Revision: 0	Effective Date: 10/04/2017

Attachment 2: Crosswalk of EPC-CP-Form-1021 Hard Copy Format to Electronic Format (cont.)

Page 2 of 2

	CERTIFICATION STATEMENT
	"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".
	(Signatory must meet definition in Section B.11.A, eg. FOD, Ops Mgr, DSESH Group Leader, EPC Group Leader)
20	Print name and title:
	Signature:Date;

EPC-CP-Form-1021.1 07/2017

MSGP	Stormwater	Visual
Assess	ments	

EPC-CP-QP-064	Page 20 of 20
Revision: 0	Effective Date: 10/04/2017

Attachment 3: Screenshot Examples of Printing from Maintenance Connection

Page 1 of 1

